Agenda **Regular Meeting of the Historic Districts Review Board**
September 8, 2026 at 5:30 PM
Peralta Room
Santa Fe Community Convention Center
201 West Marcy Street

Procedures for Historic Districts Review Board Meeting

Join on Zoom: https://santafenm-gov.zoom.us/j/89124710354

By Phone: 301 715 8592

Webinar ID: 891 2471 0354

The agenda and packet for the meeting will be posted at https://santafenm.portal.civicclerk.com/

1. Call to Order
2. Roll Call
3. Approval of Agenda
4. Approval of Minutes
5. Approval of Findings/Conclusions
   a. 2025-11327-HDRB. **412 Camino Don Miguel (October 28, 2025)**
   b. 2025-11326-HDRB. **127 Duran St (October 28, 2025)**
   c. 2025-11329-HDRB. **826 Camino del Poniente (October 28, 2025)**
   d. 2025-10873-HDRB. **219/219-A Washington Ave (December 9, 2025)**
   e. 2025-11459-HDRB. **912 Don Gaspar Ave (December 9, 2025)**
   f. 2025-11328-HDRB. **433 Calle la Paz (December 9, 2025)**
   g. 2025-11419-HDRB. **1020 Camino San Acacio (December 9, 2025)**
   h. 2025-11325-HDRB. 119 Camino Santiago (December 9, 2025)
   i. 2025-11549-HDRB. **527 Agua Fria St. (December 9, 2025)**
   j. 2025-11700-HDRB. **123 Camino Santiago (January 13, 2026)**

k. 2025-11701-HDRB. **125 Camino Santiago (January 13, 2026)**

6. Matters from the Public

7. Staff Communications

8. Old Business

9. New Business

a. 2026-012916-HDRB. 104 Camino Matías, Downtown & Eastside Historic District, contributing, Bernie Romero, agent for Vicki Montano-Torres, owner proposes to construct a 438 sq. ft. portal to a height of 9'-10" and a 35 sq. ft. addition, replace windows and doors, construct a 5'-0" high yard wall, and install HVAC. An exception is requested to 14-4.6(E)(4)(I)(a) to replace windows and doors on a primary façade, and 14-4.6(E)(2)(II)(b) to construct an addition on a primary façade. (Lani McCulley, ljmcculley@santafenm.gov)

b. 2026-012976-HDRB. 338 Orchard Dr., Downtown & Eastside Historic District. Contributing. Osage Design Studio, agent for Anita Alarid, owner, requests a historic status review with primary facade(s) designation, if applicable, for a residential structure. (Lani McCulley)

c. 2026-012977-HDRB. 527-A Agua Fria St., Westside-Guadalupe Historic District. Contributing. Osage Design Studio, agent for Neirika, LLC, owner, proposes to relocate the garage door opening. An exception is requested to 14-4.6(E)(4)(I)(c) for creating an opening on a primary facade where one does not exist. (Lani McCulley)

d. 2026-012978-HDRB. 719 Gildersleeve St., Don Gaspar Area Historic District. Contributing. Alison Kuller, owner, proposes to replace windows in the residence and casita, construct a 100 sq. ft. addition, and stucco in the color "cottonwood". An exception is requested to 14-4.6(E)(4)(I)(a) for the replacement of historic windows. (Lani McCulley)

10. Discussion Items

11. Matters from the Board

12. Next Meeting:

a. September 22, 2026

13. Adjourn

Persons with disabilities in need of accommodations, contact the City Clerk's office at 955-6521, five (5) working days prior to meeting date.

City of Santa Fe
Historic Districts Review Board
Findings of Fact and Conclusions of Law

Case # 2025-11327-HDRB
Address – 412 Camino Don Miguel
Agent's Name – Gayla Bechtol, AIA
Owner/Applicant's Name – Mark and Jesse O'Brien

THIS MATTER came before the Historic Districts Review Board ("Board") for hearing on October 28, 2025.

BACKGROUND

412 Camino Don Miguel is a two-story single-family residence listed as non-contributing to the Downtown and Eastside Historic District. The historic, adobe part of the house was built in 1947, according to Historic Building Inventories from 1983 and 1992. The non-historic second-story addition was placed there in the early 1980s. The 1992 HBI noted that the original, historic structure is "dominated" by the two-story addition. The property also holds a 2024 guest house in the southwest corner of the property. The property is surrounded by a 6-foot-high coyote fence.

In Case # 2023-6625-HDRB, the Board approved a 101-square-foot addition on the southeast elevation of the main residence, and approved conversion of the carport on the guest house to a garage. The garage was created by retaining the existing adobe walls and roof structure of the carport and adding a new east wall with two windows to enclose it, with a new door opening and window on the south façade. In administrative approvals, the property owners:

- Relocated a canale, shortened the portal on the guesthouse, eliminated a window in the bathroom addition, and replaced rotted wood on the front (south) elevation portal (Case # 2025-9875-ADMIN);

- Added parapets and skylights, relocated one window, deleted one window, and added a new door for mechanical access (Case # 2024-7736-ADMIN);

- Reroofed in modified bitumen in tan color (Case # 2021-4424-ADMIN); and

- Added a 615-square-foot portal to a height of 10'6" on the east elevation, and a yard wall and fence along the driveway (Case # 2005-187).

The Applicant now proposes the following exterior alterations:

1. Remove approximately 85 linear feet of the 6-foot-high coyote fence along the southeastern property line.
2. Construct a yard wall with stepped heights ranging from 4'7" to the maximum allowable height of 5'4" for approximately 85 feet along the southeastern property line. Each step in height is approximately 20 feet in length, creating single horizontal planes of 20 feet

before changing planes.
3. Install a 6-foot-high wood-panel pedestrian gate between the residence and the new yard wall.

FINDINGS OF FACT

After conducting a public hearing and having heard from the Applicant and all interested persons, the Board hereby FINDS, as follows:

1. Land Use Department Staff conducted a preliminary zoning review ("PZR") and determined that the application appears to meet the underlying zoning standards set forth in the Santa Fe City Code ("SFCC").
2. Historic Preservation Division Staff reviewed the application and related materials and information submitted by the Applicant for conformity with applicable SFCC requirements and provided the Board with a written report of its findings ("Staff Report"), which evaluates the factors relevant to the application.
3. Historic Preservation Division Staff Recommendation: Staff recommended approval of the proposed project and found that the application complies with SFCC Sections 14-5.2(D), General Design Standards for all Historic Districts, and 14-5.2(E), Downtown and Eastside Design Standards.
4. The project is subject to the requirements and general design standards set forth in SFCC Section 14-5.2(D), General Design Standards.
5. The property is located in the Downtown and Eastside Historic District and is subject to the district design standards set forth in SFCC Section 14-5.2(E).
6. Under SFCC Sections 14-2.6(B-C), 14-5.2(A)(1), 14-5.2(C)(3)(a-b) and 14-5.2(C)(4), the Board has authority to review, approve, with or without conditions, or deny, all or some of the Applicant's proposed design to assure overall compliance with applicable design standards.
7. The information contained in the Staff Report and exhibits, and the testimony and evidence submitted at the hearing, establishes that all applicable requirements for Board review as herein described have been met.
8. The information contained in the Staff Report and exhibits, and the testimony and evidence submitted at the hearing, establishes that all applicable design criteria have been met.

CONCLUSIONS OF LAW

Under the circumstances and given the evidence and testimony submitted during the hearing, the Board acted upon the application as follows:

1. The Board has the authority to review and approve the application.
2. The Board approves Items # 1-3 as set forth in the application, as recommended by Staff.

IT IS SO ORDERED ON THIS 8th DAY of SEPTEMBER, 2026, BY THE HISTORIC DISTRICTS REVIEW BOARD OF THE CITY OF SANTA FE.

_____ _____
Cecilia Rios, Chair Date

FILED:

_____ _____
Geralyn Cardenas Date
City Clerk

APPROVED AS TO FORM:

_____ _____
Frank Ruybalid Date
Assistant City Attorney

City of Santa Fe
Historic Districts Review Board
Findings of Fact and Conclusions of Law

Case # 2025-011326-HDRB
Address – 127 Duran St.
Agent's Name – Gayla Bechtol, AIA
Owner/Applicant's Name – Jenny Allen and Karen Kalat

THIS MATTER came before the Historic Districts Review Board ("Board") for hearing on October 28, 2025.

BACKGROUND

The house at 127 Duran St. sits approximately 70 feet from Duran Street on a 0.15-acre flag lot created from the property west of it, which is 127 Duran St., Units A and B. The subject house is 1,189 square feet, has a rectangular ground plan and faces north. According to a 2025 Historic Cultural Properties Inventory, the building began as a square footprint, as evident in a 1966 aerial photograph. About 1985, a 406-square-foot addition was added on the east elevation. All windows and doors have been replaced. The HDRB reviewed the historic status on February 11, 2025, Case # 2025-9773-HDRB, and retained the status of the residential structure and an accessory structure on the property as non-contributing to the Westside-Guadalupe Historic District. The Board reviewed the accessory structure for demolition September 9, 2025, Case # 2025-11031-HDRB, and approved its demolition.

The HCPI indicates that a 90-square-foot porch was also installed in the 1980s, but has since been removed. Remnant roofing material from the porch remains on the exterior walls on the east addition. While the original structure was constructed of 12-inch-thick adobe, the 1985 addition was built of concrete block. The windows in the adobe portion of the structure are inset into the wall, where the newer construction windows are not. The windows are a combination of metal, aluminum and vinyl. None of the windows appear to be original to the structure. The HCPI also indicates that the wood doors, one six-panel and the other faux plank, appear not to be original to the structure. The HCPI reads that the lot was once used for farming, and has a remnant acequia, thought to be part of the *Acequia Publica*, across the east edge of the property. In the status review earlier in 2025, the Board designated this wall at the acequia as contributing.

The Applicant proposes the following exterior alterations:

1) Construct a 459-square-foot portal to a height of 9'6" where the residence is 9'8" high. The portal will be on the east elevation and will consist of a Brai roof over wood decking, local pine vigas and columns, and brick-on-sand flooring. The wood will be stained and sealed with natural stain.
2) Replace all windows with aluminum-clad wood windows with simulated divided lites in blue.
3) Install an eyebrow roof over the door on the north elevation at 3'6" deep.
4) Install two skylights, which shall not be publicly visible.

5) Stucco the residence in cementitious "Buckskin" stucco.
6) Re-roof the residence with foam roofing.
7) Construct a 4-foot-high coyote vehicle gate at the street to replace the existing chain link gate.

FINDINGS OF FACT

After conducting a public hearing and having heard from the Applicant and all interested persons, the Board hereby FINDS, as follows:

1. Land Use Department Staff conducted a preliminary zoning review ("PZR") and determined that the Application appears to meet the underlying zoning standards set forth in the Santa Fe City Code ("SFCC").
2. Historic Preservation Division Staff reviewed the application and related materials and information submitted by the Applicant for conformity with applicable SFCC requirements and provided the Board with a written report of its findings ("Staff Report"), which evaluates the factors relevant to the application.
3. Historic Preservation Division Staff Recommendation: Staff recommended approval of the proposed project, and found that the application otherwise complies with SFCC Section 14-5.2(D), General Design Standards for all Historic Districts, and 14-5.2(I), Westside-Guadalupe Historic District Design Standards.
4. The project is subject to the requirements and general design standards set forth in SFCC Section 14-5.2(D), General Design Standards.
5. The property is located in the Westside-Guadalupe Historic District and is subject to the district design standards set forth in SFCC Section 14-5.2(I).
6. Under SFCC Sections 14-2.6(B-C), 14-5.2(A)(1), 14-5.2(C)(3)(a-b), and 14-5.2(C)(4), the Board has authority to review, approve, with or without conditions, or deny, all or some of the Applicant's proposed design to assure overall compliance with applicable design standards.
7. The information contained in the Staff Report and exhibits, and the testimony and evidence submitted at the hearing, establishes that all applicable requirements for Board review as herein described have been met.
8. The information contained in the Staff Report and exhibits, and the testimony and evidence submitted at the hearing, establishes that all applicable design criteria have been met.

CONCLUSIONS OF LAW

Under the circumstances and given the evidence and testimony submitted during the hearing, the Board acted upon the application as follows:

1. The Board has the authority to review and approve the application.
2. The Board approves Items # 1-7 as set forth in the application, as recommended by Staff.

IT IS SO ORDERED ON THIS 8th DAY of SEPTEMBER, 2026, BY THE HISTORIC DISTRICTS REVIEW BOARD OF THE CITY OF SANTA FE.

_____ _____
Cecilia Rios, Chair Date

FILED:

_____ _____
Geralyn Cardenas Date
City Clerk

APPROVED AS TO FORM:

_____ _____
Frank Ruybalid Date
Assistant City Attorney

City of Santa Fe
Historic Districts Review Board
Findings of Fact and Conclusions of Law

Case # 2025-11329-HDRB
Address – 826 Camino del Poniente
Agent's Name – Richard Martinez, Martinez Architecture Studio, P.C.
Owner/Applicant's Name – Larry Colton and John McCoy

THIS MATTER came before the Historic Districts Review Board ("Board") for hearing on October 28, 2025.

BACKGROUND

The residence at 826 Camino del Poniente is a single-family residence listed as contributing to the Downtown and Eastside Historic District. The structure is a simple rectangle in a Territorial Revival style. The south was most likely historically an entrance; however, with the enclosure of the porch, the main entrances are now to the north and the east. According to the 1991 Historic Building Inventory, the structure is believed to have been built in the 1930s, however, it first appeared in the Santa Fe City Directory in 1951. The 2,037-square-foot residence was originally a guest house for the property located at 828 Camino del Poniente and was owned by the author Elizabeth DeHuff. There is evidence that the residence was used as a school sometime before 1991. The north and east elevation architecture is simple and unchanged. On November 14, 2023, the Board reviewed the historic status of the property, upgraded the status of the residence to contributing and assigned the north façade, excluding the windows and doors, as the primary façade. See Case # 2023-7468-HDRB.

On February 13, 2024, Case # 2024-7775-HDRB, the Board approved a 20-item remodel of the property, including (summarized):

East Elevation:
1. 675-square-foot two-car garage addition, separated from the residence by 12 feet.
2. 120-square-foot entry portal addition connecting the garage to the house.

West Elevation:
3. 103-square-foot addition at the southwest corner, 33 feet from the primary facade.

Property:
4. Place a 5'4"-high yard wall west of the driveway connecting to the garage entry gate.
5. Install a 9-foot-high wall with pedestrian gate at the north end, west side of the garage.

The Applicant now asks the Board to approve the following changes to previous Case # 2024-7775-HDRB:

1. Decrease the approved garage from 675 square feet to 516 square feet, and relocate it about 18 inches from the east property line to save several significant trees.
2. Decrease the covered area at the garage to 27 square feet from 51 square feet as a result of the garage size change

3. Enclose a 49-square-foot portion of the new approved portal for heated space, decreasing the portal to 114 square feet.
4. Increase the 103-square-foot addition on the west elevation by 29 square feet for a total addition of 132 square feet.
5. Install a new window on the south elevation.
6. Relocate the yard wall and pedestrian gate to the west to accommodate the reduced garage size and adjusted location.

The design otherwise will remain as previously approved.

FINDINGS OF FACT

After conducting a public hearing and having heard from the Applicant and all interested persons, the Board hereby FINDS, as follows:

1. Land Use Department Staff conducted a preliminary zoning review ("PZR") and determined that the application appears to meet the underlying zoning standards set forth in the Santa Fe City Code ("SFCC").
2. Historic Preservation Division Staff reviewed the application and related materials and information submitted by the Applicant for conformity with applicable SFCC requirements and provided the Board with a written report of its findings ("Staff Report"), which evaluates the factors relevant to the application.
3. Historic Preservation Division Staff Recommendation: Staff recommended approval of the proposed project and found that the application complies with SFCC Section 14-5.2(D), General Design Standards for all Historic Districts, and 14-5.2(E), Downtown and Eastside Design Standards.
4. The project is subject to SFCC Section 14-5.2(C), Regulation of Significant and Contributing Structures.
5. The project is subject to the requirements and general design standards set forth in SFCC Section 14-5.2(D), General Design Standards.
6. The property is located in the Downtown and Eastside Historic District and is subject to the district design standards set forth in SFCC Section 14-5.2(E).
7. Under SFCC Sections 14-2.6(B-C), 14-5.2(A)(1), 14-5.2(C)(2)(a-d & f), 14-5.2(C)(3)(a-b), 14-5.2(C)(4), and 14-5.2(D), the Board has authority to review, approve, with or without conditions, or deny, all or some of the Applicant's proposed design to assure overall compliance with applicable design standards.
8. The information contained in the Staff Report and exhibits, and the testimony and evidence submitted at the hearing, establishes that all applicable requirements for Board review as herein described have been met.
9. The information contained in the Staff Report, and the exhibits, testimony and evidence submitted at the hearing, establishes that all applicable design criteria have been met.

CONCLUSIONS OF LAW

Under the circumstances and given the evidence and testimony submitted during the hearing, the Board acted upon the application as follows:

1. The Board has the authority to review and approve the application.
2. The Board approves Items # 1-6 as set forth in the application, as recommended by Staff.

IT IS SO ORDERED ON THIS 8th DAY of SEPTEMBER, 2026, BY THE HISTORIC DISTRICTS REVIEW BOARD OF THE CITY OF SANTA FE.

_____ _____
Cecilia Rios, Chair Date

FILED:

_____ _____
Geralyn Cardenas Date
City Clerk

APPROVED AS TO FORM:

_____ _____
Frank Ruybalid Date
Assistant City Attorney

City of Santa Fe
Historic Districts Review Board
Findings of Fact and Conclusions of Law

Case # 2025-10873-HDRB
Address – 219 and 219-A Washington Ave.
Agent's Name – Robert D. Evans, L+R Design Services
Owner/Applicant's Name – Dennis Price

THIS MATTER came before the Historic Districts Review Board ("Board") for hearing on December 9, 2025.

BACKGROUND

The professional office building at 219 Washington Ave. is listed as contributing to the Downtown and Eastside Historic District, with the west, street-facing façade designated as primary. The structure, a low, flat-roof building that initially served as a garage, occupies the northwest corner of the former Levi A. Hughes estate. To the north is a concrete walkway leading to the former McKee Office Building, which has been redeveloped into a 27-suite hotel compound. To the south is the lawn of the one-time Levi A. and Christine L. Hughes residence. Constructed between 1930 and 1942, the garage is made of structural clay pentiles, finished with stucco and painted in a buckskin color. The west elevation has been altered with the infill of a door and windows. These include two sets of large, multi-light wood windows that sit on low bulkheads faced with stretcher row brick. The public access to the building is through a ¾"-glass door at the northwest corner. The structure is currently used for commercial business purposes.

October 22, 2019, in Case # 2019-0994-HDRB, the Board upgraded the historic status of this building to contributing, and designated the western, street-facing façade as primary. February 27, 2024, in Case # 2024-7814-HDRB, the Board approved various renovations and alterations to all elevations of the structure, including the creation of openings for new windows on the north façade; the removal of an existing door and placement of a new entrance door in the enlarged opening on the west façade; and enlargement of the door openings, replacement of the doors and placement of new windows on the south and east façades. The Board approved exceptions for these alterations, with the condition that the replacement windows be true divided-lite or simulated divided-lite.

The owner now requests approval for a 640-square-foot, two-story addition to a height of 19'8" at 219 Washington Ave.; and to construct a new 1,580-square-foot, two-story structure at 219-A Washington Ave., to a height of 23 feet east of the existing building at 219 Washington Ave. At this hearing, the Applicant requests Board approval of the following items:

219 Washington Ave:

1) Build a 640-square-foot, two-story addition, comprised of units 4 and 5, on the rear, east elevation of the existing building;

2) Remove a storage room from the east elevation and create a 123-square-foot bathroom for unit 4 in that space;

3) Build a 94-square-foot portal addition connecting the new addition to the existing building;

4) Construct an 89-square-foot exterior stairway on the east elevation of the addition; and

5) Construct a 54-square-foot roof deck on the second floor, north façade.

219-A Washington Ave:

1) Build a new two-story structure with 624 square feet on the ground floor and 718 square feet on the second floor. The style will match the hipped roof, stucco type and color, stone foundation, stone sills and wood posts of the existing building at 215 Washington Ave.;

2) Build a 40-square-foot portal on the west elevation;

3) Build a 105-square-foot portal on the south elevation; and

4) Build a 93-square-foot exterior stairway on the east elevation.

The 640-square-foot addition to the 897-square-foot building at 219 Washington Ave. will expand the footprint of the existing building approximately 71 percent. Also, the maximum allowable height on this streetscape is 20'1", and the new structure at 219-A Washington is proposed to be 23 feet high. The Applicant requests two exceptions:

- To SFCC Section 14-5.2(D)(2)(d) for an addition that exceeds 50 percent of the square footage of the existing footprint; and
- To SFCC Section 14-5.2(D)(9)(c)(ii)(B) for exceeding the restriction on the height of a building with a pitched roof.

FINDINGS OF FACT

After conducting a public hearing and having heard from the Applicant and all interested persons, the Board hereby FINDS, as follows:

1. Land Use Department Staff conducted a preliminary zoning review ("PZR") and determined that the application appears to meet the underlying zoning standards set forth in the Santa Fe City Code ("SFCC").
2. Historic Preservation Division Staff reviewed the application and related materials and information submitted by the Applicant for conformity with applicable SFCC requirements and provided the Board with a written report of its findings ("Staff Report"), which evaluates the factors relevant to the application.
3. Historic Preservation Division Staff Recommendation: Staff recommended approval of the proposed project and found that all the exception criteria have been met and that the application complied with SFCC Section 14-5.2(D), General Design Standards for all Historic Districts, and 14-5.2(E), Downtown and Eastside Design Standards.
4. The project is subject to SFCC Section 14-5.2(C), Regulation of Significant and Contributing Structures.
5. The project is subject to the requirements and general design standards set forth in SFCC Section 14-5.2(D), General Design Standards.
6. The property is located in the Downtown and Eastside Historic District and is subject to the district design standards set forth in SFCC Section 14-5.2(E).

7. Under SFCC Sections 14-2.6(B-C), 14-5.2(A)(1), 14-5.2(C)(2)(a-d & f), 14-5.2(C)(3)(a-b), 14-5.2(C)(4), and 14-5.2(D), the Board has authority to review, approve, with or without conditions, or deny, all or some of the Applicant's proposed design to assure overall compliance with applicable design standards.

Addition Exceeding 50 Percent:

8. The Applicant proposes to construct a 640-square-foot addition to an existing historic, contributing structure which is 897 square feet. The addition is more than 50 percent of the square footage of the existing structure.
9. Under SFCC Section 14-5.2(D)(2)(d), an addition shall not exceed 50 percent of the square footage of the existing footprint. The Staff determined that an exception to SFCC Section 14-5.2(D)(2)(d) would be required for approval of this addition, and the Applicant requested an exception.
10. To obtain this exception, the Applicant was required to conclusively demonstrate that the three exception criteria set forth in SFCC Section 14-5.2(C)(5)(b) have been met.
11. Based on the information set forth in the Staff Report, and the exhibits, evidence and testimony presented at the hearing, the Board agrees with Staff's finding that the Applicant has conclusively demonstrated that all exception criteria have been met:
    a. Pursuant to SFCC Section 14-5.2(C)(5)(b)(i), the Board finds that granting the exception would not damage the character of the district, because the proposed new construction is located in the rear of the property and will be minimally visible from the street or adjacent properties;
    b. Pursuant to SFCC Section 14-5.2(C)(5)(b)(ii), the Board finds that the exception is required to prevent a hardship to the Applicant or an injury to the public welfare, because the structure at 219 Washington Ave. is presently vacant, in need of maintenance, and the addition will aid in the development of rental units and full usage of this underutilized structure; and
    c. Pursuant to SFCC Section 14-5.2(C)(5)(b)(iii), the Board finds that granting the exception would strengthen the unique heterogeneous character of the City by providing a full range of design options to ensure that residents can continue to reside within the Historic Districts, because the new construction proposed will infill underutilized space in a manner that is harmonious with the existing structures at 219 and 215 Washington Ave.
12. The Board finds that the Applicant has conclusively demonstrated that all of the exception criteria have been met for expansion of the structure's footprint in excess of 50 percent.

Construction in Excess of Height Restriction:

13. The Applicant proposes to construct a new two-story structure with a pitched, hipped roof to a height 23 feet where the maximum allowable height is 20'1".
14. Under SFCC Section 14-5.2(D)(9)(c)(ii)(B), the ridge height of a proposed building with a pitched roof shall not be in excess of two feet of the average of the ridge height of the other pitched roofs in the streetscape. Staff determined that an exception to SFCC Section 14-5.2(D)(9)(c)(ii)(B) would be required for approval of the application, and the Applicant requested this exception.

15. To obtain an exception, the Applicant was required to conclusively demonstrate that the six exception criteria set forth in SFCC Section 14-5.2(C)(5)(c) have been met.
16. Based on the information set forth in the Staff Report, and the exhibits, evidence and testimony presented at the hearing, the Board agrees with Staff's finding that the Applicant has conclusively demonstrated that all exception criteria have been met:
    a. Pursuant to SFCC Section 14-5.2(C)(5)(c)(i), the Board finds that granting the exception would not damage the character of the streetscape, because the location of the proposed structure at 219-A Washington Ave. is set back from the street, behind 219 Washington Ave. and is mostly concealed from public view, and the Planning and Zoning requirements allow a height of 26'6";
    b. Pursuant to SFCC Section 14-5.2(C)(5)(c)(ii), the Board finds that the exception is required to prevent a hardship to the Applicant or an injury to the public welfare, because the site plan is tightly configured on the lot, leaving no room for expansion of the first floor, a second floor is required, and the additional height is necessary to create a hipped roof harmonious with that at 215 Washington Ave.;
    c. Pursuant to SFCC Section 14-5.2(C)(5)(c)(iii), the Board finds that granting the exception would strengthen the unique heterogeneous character of the City by providing a full range of design options to ensure that residents can continue to reside within the Historic Districts, because the tight configuration at 219 Washington Ave. makes expansion of the existing structure impossible and a two-story accessory structure with hipped roof expands the utility of the space to facilitate its full usage;
    d. Pursuant to SFCC Section 14-5.2(C)(5)(c)(iv), the Board finds that there are special conditions or circumstances that are peculiar to the land or structure involved that are not applicable to other lands or structures in the related streetscape: there is no space adjacent to the existing building at 219 Washington Ave. for expansion of that building, and the parking lot to the rear is larger than necessary and can accommodate an accessory structure;
    e. Pursuant to SFCC Section 14-5.2(C)(5)(c)(v), the Board finds that the special conditions or circumstances are not the result of the actions of the Applicant due to special conditions and circumstances: the entire property was at one time part of a historic estate and the two buildings were dedicated to different uses long before the Applicant took control of them, and there was previously no incentive to reunite them for a single purpose; and
    f. Pursuant to SFCC Section 14-5.2(C)(5)(c)(vi), the Board finds that granting the exception would provide the least negative impact with respect to the purposes set forth in SFCC Section 14-5.2(A)(1) because the proposed building at 219-A Washington Ave. will be sandwiched between two other two-story buildings, at a location that has minimal public visibility, and will have a negligible impact on the streetscape.
17. The Board finds that the Applicant has conclusively demonstrated that all of the exception criteria have been met with respect to the exception for exceeding the height restriction.

18. The information contained in the Staff Report and exhibits, and the testimony and evidence submitted at the hearing, establishes that all applicable requirements for Board

review as herein described have been met.

19. The information contained in the Staff Report and exhibits, and the testimony and evidence submitted at the hearing, establishes that all applicable design criteria have been met.

CONCLUSIONS OF LAW

Under the circumstances and given the evidence and testimony submitted during the hearing, the Board acted upon the application as follows:

1. The Board has the authority to review and approve the application.
2. The Board approves Items # 1-5 for 219 Washington Ave. as set forth in the application, as recommended by Staff.
3. The Board grants the exception requested in the application for 219 Washington Ave.
4. The Board approves Items # 1-4 for 219-A Washington Ave. as set forth in the application, as recommended by Staff.
5. The Board grants the exception requested in the application for 219-A Washington Ave.

IT IS SO ORDERED ON THIS 8th DAY of SEPTEMBER, 2026, BY THE HISTORIC DISTRICTS REVIEW BOARD OF THE CITY OF SANTA FE.

_____ _____
Cecilia Rios, Chair Date

FILED:

_____ _____
Geralyn Cardenas Date
City Clerk

APPROVED AS TO FORM:

_____ _____
Frank Ruybalid Date
Assistant City Attorney

City of Santa Fe
Historic Districts Review Board
Findings of Fact and Conclusions of Law

Case # 2025-11459-HDRB
Address – 912 Don Gaspar Ave.
Agent's Name – Positive Energy Solar
Owner/Applicant's Name – Moises Zamora

THIS MATTER came before the Historic Districts Review Board ("Board") for hearing on December 9, 2025.

BACKGROUND

The single-family residence at 912 Don Gaspar Ave. is a significant structure in the Don Gaspar Area Historic District. The approximately 2,000-square-foot residence was constructed by 1930 in a bungalow style with a hipped roof. It has a moderate level of remodeling with a porch enclosed in the 1950s on the south end of the rear, western elevation. The roof is hipped with asphalt shingles and an overhang with and exposed rafters. The building is constructed of red brick atop a smooth-cut stone foundation. The front portal features columns with chamfered plinths atop brick buttresses and a low wall.

On this streetscape there is a mix of stone walls, picket fences, and metal, wrought iron and chain-link fencing. There is a combination of Spanish Pueblo Revival, Territorial Revival, and Victorian style residences set back from the street with landscaped yards between the street and the residences. Many roofs are pitched, and there is a combination of wall colors from a yellow tan to medium brown stuccos. The property owners were permitted to re-roof the residence in-kind with shingle roofing per an administrative approval in Case # 2019-1037-ADMIN.

The Applicant proposes the following exterior alterations:

1. Install publicly visible solar collectors on the south and west elevations of the roof. The panels will be flat against the pitch of the roof. Nine panels will be installed on the west elevation roof, and nine panels will be installed on the south elevation roof.

The west elevation is the rear of the house and is publicly visible from West Houghton Street. The south elevation is publicly visible from Don Gaspar Avenue. The proposed solar panels on the south elevation have been set back from the front of the building to mitigate the impact on the streetscape. An exception is requested to Santa Fe City Code Section 14-5.2(D)(3)(b) for addition of publicly visible rooftop appurtenances.

FINDINGS OF FACT

After conducting a public hearing and having heard from the Applicant and all interested persons, the Board hereby FINDS, as follows:

1. Land Use Department Staff conducted a preliminary zoning review ("PZR") and determined that the application appears to meet the underlying zoning standards set forth in the Santa Fe City Code ("SFCC").
2. Historic Preservation Division Staff reviewed the application and related materials and information submitted by the Applicant for conformity with applicable SFCC requirements and provided the Board with a written report of its findings ("Staff Report"), which evaluates the factors relevant to the application.
3. Historic Preservation Division Staff Recommendation: The Staff recommended a finding that the exception criteria to SFCC Section 14-5.2(D)(3)(b) had not been met and recommended denial for a proposal to add publicly visible rooftop appurtenances. Staff recommended denial of the application as it does not comply with SFCC Sections 14-5.2(D), General Design Standards for all Historic Districts, and 14-5.2(H), Don Gaspar Area Historic District Design Standards.
4. The project is subject to SFCC Section 14-5.2(C), Regulation of Significant and Contributing Structures.
5. The project is subject to the requirements and general design standards set forth in SFCC Section 14-5.2(D), General Design Standards.
6. The property is located in the Don Gaspar Area Historic District and is subject to the district design standards set forth in SFCC Section 14-5.2(H).
7. Under SFCC Sections 14-2.6(B-C), 14-5.2(A)(1), 14-5.2(C)(2)(a-d & f), 14-5.2(C)(3)(a-b), 14-5.2(C)(4), and 14-5.2(D), the Board has authority to review, approve, with or without conditions, or deny, all or some of the Applicant's proposed design to assure overall compliance with applicable design standards.
8. SFCC Section 14-5.2(D)(3)(b) prohibits the addition of publicly visible rooftop appurtenances, including solar collectors or other mechanical equipment, on significant and landmark structures.
9. The Applicant proposes to install publicly visible solar collector panels on a significant structure. The Staff determined that an exception to SFCC Section 14-5.2(D)(3)(b) would be required for approval of the application, and the Applicant requested an exception.
10. To obtain an exception, the Applicant was required to conclusively demonstrate that the three exception criteria set forth in SFCC Section 14-5.2(C)(5)(b) have been met.
11. Based on the information set forth in the Staff Report, and the exhibits, evidence and testimony presented at the hearing, the Board agrees with Staff's finding that the Applicant has conclusively demonstrated that all exception criteria have been met:
    a. Pursuant to SFCC Section 14-5.2(C)(5)(b)(i), the Board finds that granting the exception would not damage the character of the district, because in the Don Gaspar Area Historic District the use of solar and other energy collecting and conserving strategies is encouraged, per SFCC Section 14-5.2(H)(1)(c), and these collectors will be integrated into the pitch of the roof, as required by SFCC Section 14-5.2(H)(1)(c)(IV);
    b. Pursuant to SFCC Section 14-5.2(C)(5)(b)(ii), the Board finds that the exception is required to prevent a hardship to the Applicant or an injury to the public welfare because the Applicant has no means to add solar collectors without them being publicly visible, and the addition of a solar energy component to the house

helps to meet the City's objective of carbon neutrality, as expressed in City Resolution # 2014-85; and

c. Pursuant to SFCC Section 14-5.2(C)(5)(b)(iii), the Board finds that granting the exception would strengthen the unique heterogeneous character of the City by providing a full range of design options to ensure that residents can continue to reside within the Historic Districts, because in the long term this solar energy component will reduce the owner/occupant's utility costs and reduce the house's greenhouse gas emissions.

12. The Board finds that the Applicant has conclusively demonstrated that all of the exception criteria have been met.
13. The information contained in the Staff Report and exhibits, and the testimony and evidence submitted at the hearing, establishes that all applicable requirements for Board review as herein described have been met.
14. The information contained in the Staff Report, and the exhibits, testimony and evidence submitted at the hearing, establishes that all applicable design criteria have been met.

CONCLUSIONS OF LAW

Under the circumstances and given the evidence and testimony submitted during the hearing, the Board acted upon the application as follows:

1. The Board has the authority to review and approve the application.
2. Board approves Item # 1 as set forth in the application.
3. The Board grants the exception to SFCC Section 14-5.2(D)(3)(b), as requested in the application.

IT IS SO ORDERED ON THIS 8th DAY of SEPTEMBER, 2026, BY THE HISTORIC DISTRICTS REVIEW BOARD OF THE CITY OF SANTA FE.

_____ _____
Cecilia Rios, Chair Date

FILED:

_____ _____
Geralyn Cardenas Date
City Clerk

APPROVED AS TO FORM:

_____ _____
Frank Ruybalid Date
Assistant City Attorney

City of Santa Fe
Historic Districts Review Board
Findings of Fact and Conclusions of Law

Case # 2025-11328-HDRB
Address – 433 Calle la Paz
Agent's Name – Richard Martinez, Martinez Architecture Studio, P.C.
Owner/Applicant's Name – The John C Gregory Revocable Trust and The Pamela S Austin Revocable Trust

THIS MATTER came before the Historic Districts Review Board ("Board") for hearing on December 9, 2025.

BACKGROUND

The 1,358-square-foot single-family residence at 433 Calle la Paz is listed as contributing to the Downtown and Eastside Historic District. The original portion of the home was built of adobe sometime between 1912 and 1930, with four subsequent expansions, all of which were added before 1970. The residence is a vernacular interpretation of Territorial Style with Pueblo Revival influence in the additions to the historic footprint. The property contains a main residence, a casita, and a freestanding single vehicle garage with yard walls along each street and some wood fencing.

The main entrance of the residence is on the north, which is its only primary façade. The residence retains its original fenestrations with mostly two-over-one wood windows, except one six-over-one, wood-clad and one one-over-one vinyl window. The doors are wood, except for one metal door on the east elevation. Character-defining elements of the main residence include the original core, original fenestrations fitted with two-over-one wood windows, and the brick cornice. The Applicant provided an assessment of the windows and doors throughout the residence, done by Ra Patterson, RPA & Associates, LLC. There is a combination of historic and non-historic windows and doors in various stages of wear.

The 264-square-foot west-facing garage was constructed before 1958 of hollow, clay-tile blocks in a Spanish Pueblo Revival style, and has a contributing status. The west-facing vehicle door is a double-chevron wood overhead door in a natural color with blue trim that matches the blue of the roof overhang. The west façade is the garage's only primary façade. The 564-square-foot casita is listed as non-contributing to the historic district. It was constructed in the early 1980s with frame construction that seems to encompass an older structure on its south end.

There are 70-inch-tall yard walls along both Calle la Paz and Camino Manzano, which were constructed after 1983. The yard wall on Camino Manzano starts at the south corner of the lot and runs to the edge of the guest house. Closer to the guest house is a wooden pedestrian gate topped with a header. At the south end of the guest house starts a 72-inch plank fence that runs for about five to 10 feet before ending in a wire fence that is damaged by the overgrown foliage that clings to it.

In Case # 2025-10839-HDRB the Board maintained the main residential structure's contributing status and designated the north as its primary façade, excluding the portal, which appears to be new. The Board also designated the garage as contributing with the west as its primary facade, and designated the guesthouse and yard walls as non-contributing due to their modernity.

The Applicant proposes the following exterior alterations:

Main Residence:

1. Replace all windows and replace east-elevation door. An exception is requested to Santa Fe City Code Section 14-5.2(D)(5)(a)(i) to replace historic windows on the primary, north façade. The windows will be replaced with double-pane wood windows with divided lites, and sizes to match the existing windows.
2. Replace vigas and beams on the north portal with identical viga posts and beams to remove deteriorated and painted wood.
3. Install wood railings to span the side of the existing portal.
4. Install exterior stairs with iron handrails on the north side of the northern portal.
5. Construct a 210-square-foot portal to a height of 10'6" on the east of the main residence. The portal will have a stucco and wood slat cover.

Garage:

1. Refinish the garage vehicle and pedestrian doors.

Casita:

1. Construct a 148-square-foot portal to a height of 11'7" on the west elevation. The portal will be Spanish Pueblo in style with a stucco parapet, square columns, and double corbels below a wood header.
2. Replace windows and doors. All the windows on the casita are non-historic from 1987 to 2015. The windows will be replaced with divided lite grid, double-pane wood windows.
3. Install an overhang on the south elevation.

Property:

1. Construct a 5-foot-high coyote fence on the Camino Manzano or east side of the casita to replace the wood slat and metal wire fencing there currently.
2. Construct a 5-foot-high coyote fence on the north property line with a pedestrian gate on the west between the fence and the garage.
3. Remove interior courtyard walkways and install a water fountain.

FINDINGS OF FACT

After conducting a public hearing and having heard from the Applicant and all interested persons, the Board hereby FINDS, as follows:

1. Land Use Department Staff conducted a preliminary zoning review ("PZR") and determined that the application appears to meet the underlying zoning standards set forth in the Santa Fe City Code ("SFCC").

2. Historic Preservation Division Staff reviewed the application and related materials and information submitted by the Applicant for conformity with applicable SFCC requirements and provided the Board with a written report of its findings ("Staff Report"), which evaluates the factors relevant to the application.
3. Historic Preservation Division Staff Recommendation: Staff found that the exception criteria had been met and recommended approval of the exception to SFCC Section 14-5.2(D)(5)(a)(i) to replace historic windows on a primary facade. Otherwise, the Staff recommended approval of the other elements of the application, as they comply with SFCC Sections 14-5.2(D), General Design Standards for all Historic Districts, and 14-5.2 (E), Downtown and Eastside Historic District Design Standards.
4. The project is subject to SFCC Section 14-5.2(C), Regulation of Significant and Contributing Structures.
5. The project is subject to the requirements and general design standards set forth in SFCC Section 14-5.2(D), General Design Standards.
6. The property is located in the Downtown and Eastside Historic District and is subject to the district design standards set forth in SFCC Section 14-5.2(E).
7. Under SFCC Sections 14-2.6(B-C), 14-5.2(A)(1), 14-5.2(C)(2)(a-d & f), 14-5.2(C)(3)(a-b), 14-5.2(C)(4), and 14-5.2(D), the Board has authority to review, approve, with or without conditions, or deny, all or some of the Applicant's proposed design to assure overall compliance with applicable design standards.
8. Under SFCC Section 14-5.2(D)(5)(a)(i), historic windows on the primary façades of contributing structures shall be repaired or restored wherever possible.
9. The Applicant proposes to replace historic windows (H and J) on the north, primary façade of the main residence. The Staff determined that an exception to SFCC Section 14-5.2(D)(5)(a)(i) would be required for approval of the application, and the Applicant requested an exception.
10. To obtain an exception, the Applicant was required to conclusively demonstrate that the three exception criteria set forth in SFCC Section 14-5.2(C)(5)(b) have been met.
11. Based on the information set forth in the Staff Report and exhibits, and the evidence and testimony presented at the hearing, the Board agrees with the Staff's finding that the Applicant has conclusively demonstrated that all exception criteria have been met:
    a. Pursuant to SFCC Section 14-5.2(C)(5)(b)(i), the Board finds that granting the exception would not damage the character of the district, because the replacement windows will be in-kind, and will duplicate the size, style and material of the originals, consistently with SFCC Section 14-5.2(D)(5)(a)(i);
    b. Pursuant to SFCC Section 14-5.2(C)(5)(b)(ii), the Board finds that the exception is required to prevent a hardship to the Applicant or an injury to the public welfare because, according to a window assessment by a qualified window assessment professional, water penetration is damaging the adobe, the windows must be removed to properly flash the openings to stop the water penetration, but the window jambs cannot be removed without destroying them, making the windows unrestorable; and
    c. Pursuant to SFCC Section 14-5.2(C)(5)(b)(iii), the Board finds that granting the exception would strengthen the unique heterogeneous character of the City by providing a full range of design options to ensure that residents can continue to reside within the Historic Districts because replacement of these windows will

increase the lifespan of a habitable, historic house by stopping its structural deterioration due to seepage of moisture at the windows.

12. The Board finds that the Applicant has conclusively demonstrated that all of the exception criteria have been met with respect to replacement of the historic windows on the primary façade of the main residence.
13. The Board determined that an exception is not necessary for replacement of these windows and door:
    a. Residence, window I, north, primary façade: The evidence shows that this window is not historic;
    b. Residence, windows A, C, D, E and F, west, south and east façades: The evidence shows that these windows are not historic, and they are not on primary façades;
    c. Residence, window B, west façade, and window G, east façade: The evidence shows that these windows are historic, but they are non-restorable and they are not on primary façades;
    d. Residence, door # 1, east façade: The evidence shows that this door is not historic and it is not on a primary façade;
    e. Garage: The Applicant seeks approval to refinish, not to replace, the window and doors on this contributing structure, which does not require an exception; and
    f. Casita: This structure is non-contributing and the evidence shows that all windows and doors on it are non-historic.
14. The information contained in the Staff Report and exhibits, and the testimony and evidence submitted at the hearing, establishes that all applicable requirements for Board review as herein described have been met.
15. The information contained in the Staff Report and exhibits, and the testimony and evidence submitted at the hearing, establishes that all applicable design criteria have been met.

CONCLUSIONS OF LAW

Under the circumstances and given the evidence and testimony submitted during the hearing, the Board acted upon the application as follows:

1. The Board has the authority to review and approve the application.
2. The Board approves Items # 1-5 with respect to the main residence, as set forth in the application.
3. The Board grants the exception requested in the application for replacement of the historic windows on the primary façade of the main residence.
4. The Board approves Item # 1 with respect to the garage on the property, as set forth in the application.
5. The Board approves Items # 1-3 with respect to the casita on the property, as set forth in the application.
6. The Board approves Items # 1-3 with respect to the property perimeter and courtyard, as set forth in the application and as recommended by Staff.

IT IS SO ORDERED ON THIS 8th DAY of SEPTEMBER, 2026, BY THE

HISTORIC DISTRICTS REVIEW BOARD OF THE CITY OF SANTA FE.

_____ _____
Cecilia Rios, Chair Date

FILED:

_____ _____
Geralyn Cardenas Date
City Clerk

APPROVED AS TO FORM:

_____ _____
Frank Ruybalid Date
Assistant City Attorney

City of Santa Fe
Historic Districts Review Board
Findings of Fact and Conclusions of Law

Case # 2025-11419-HDRB
Address – 1020 Camino San Acacio
Agent's Name – Henry Avila, Conron & Woods, Architects
Owner/Applicant's Name – Zelma R. Long and Phillip K. Freese

THIS MATTER came before the Historic Districts Review Board ("Board") for hearing on December 9, 2025.

BACKGROUND

The single-family residence located at 1020 Camino San Acacio is designated as non-contributing to the Downtown and Eastside Historic District. The Santa Fe County Tax Parcel Map records the property as being built on a 0.14-acre lot in 1992, comprised of 1,705 square feet of roofed area. The property was constructed in the Spanish Pueblo Revival design style as seen by the flat roof, rounded parapets and divided-lite windows. The Camino San Acacio streetscape can be described as single-family residences consisting of Spanish-Pueblo Revival and Territorial design style structures with some eclectic structures in the area. Many of the structures were built in the 1950s to 1960s, and new development took place into the early 2000s. The general area is in the juniper-piñon scrubland with some varying degrees in terrain elevation sloping down to the north and rising to the south.

January 8, 2008, in Case # H-08-003, the Board approved the proposed 15-foot by 5-foot vehicle gate and a stucco retaining wall at a maximum of 1.5 feet above the highest grade with the condition that the vehicle gate be open in design with fewer vertical elements, that the stucco corner radius match that of the existing house, and that the small stone structure be retained unless proof of non-historic date is verified by staff. In February, 2012, in Case # 2012-0022-ADMIN, the Staff approved a lot line adjustment and consolidation at 1020 and 1030 Camino San Acacio.

At this hearing, the Applicant requests Board approval of the following item:

New construction of a 740-square-foot detached garage in the Spanish Pueblo Revival style, to a height of 14'6" where the maximum allowable height is 15'10".

FINDINGS OF FACT

After conducting a public hearing and having heard from the Applicant and all interested persons, the Board hereby FINDS, as follows:

1. Land Use Department Staff conducted a preliminary zoning review ("PZR") and determined that the application appears to meet the underlying zoning standards set forth in the Santa Fe City Code ("SFCC").

2. Historic Preservation Division Staff reviewed the application and related materials and information submitted by the Applicant for conformity with applicable SFCC requirements and provided the Board with a written report of its findings ("Staff Report"), which evaluates the factors relevant to the application.
3. Historic Preservation Division Staff Recommendation: Staff recommended approval of the proposed project and found that the application complied with SFCC Section 14-5.2 (D), General Design Standards for all Historic Districts, and 14-5.2(E), Downtown and Eastside Design Standards.
4. The project is subject to the requirements and general design standards set forth in SFCC Section 14-5.2(D), General Design Standards.
5. The property is located in the Downtown and Eastside Historic District and is subject to the district design standards set forth in SFCC Section 14-5.2(E).
6. Under SFCC Sections 14-2.6(B-C), 14-5.2(A)(1), 14-5.2(C)(3)(a-b), and 14-5.2(C)(4), the Board has authority to review, approve, with or without conditions, or deny, all or some of the Applicant's proposed design to assure overall compliance with applicable design standards.
7. The information contained in the Staff Report and exhibits, and the testimony and evidence submitted at the hearing, establishes that all applicable requirements for Board review as herein described have been met.
8. The information contained in the Staff Report, and the exhibits, testimony and evidence submitted at the hearing, establishes that all applicable design criteria have been met.

CONCLUSIONS OF LAW

Under the circumstances and given the evidence and testimony submitted during the hearing, the Board acted upon the application as follows:

1. The Board has the authority to review and approve the application.
2. The Board approves Item # 1 as set forth in the application, as recommended by Staff.

IT IS SO ORDERED ON THIS 8th DAY of SEPTEMBER, 2026, BY THE HISTORIC DISTRICTS REVIEW BOARD OF THE CITY OF SANTA FE.

_____ _____
Cecilia Rios, Chair Date

FILED:

_____ _____
Geralyn Cardenas Date
City Clerk

APPROVED AS TO FORM:

_____ _____
Frank Ruybalid Date
Assistant City Attorney

City of Santa Fe
Historic Districts Review Board
Findings of Fact and Conclusions of Law

Case # 2025-11325-HDRB
Address – 119 Camino Santiago
Agent's Name – John A. Padilla, AIA
Owner/Applicant's Name – Dominic J. Serna

THIS MATTER came before the Historic Districts Review Board ("Board") for hearing on December 9, 2025.

BACKGROUND

Plaza del Monte, formerly the Plaza del Monte Retirement Compound, is an approximately six-acre, "L"-shaped subdivision bounded by Bishops Lodge Road on the east and Old Taos Highway on the west. The earliest plans by architects Kenneth Clark and Phillippe Register in the late 1950s are for the buildings on the eastern part of the development, and were Spanish-Pueblo Revival in style. However, when Register solely took over the project in the 1960s, his designs evolved into contemporary flat-roof structures with the use of canales, viga-roof portales, and carport elements. In the mid-1960s, Camino Santiago was extended, and development at the western end of the development began.

The property at 119 Camino Santiago is a 13,549-square-foot lot with a single-family residence designated as contributing to the Downtown and Eastside Historic District and the east (façade # 1) and south (façade # 4) designated as primary. The 1,485-square-foot single-family residence is the only structure on the lot and was constructed in 1966 in a mid-century modern design by Register. The structure is a good example of Mid-Century Modern Santa Fe Style, with its low, projecting roofline and south fin wall as character-defining elements. The primary façades include the south, east and north interior walls of the carport in addition to the east facade of the residence and the portal that runs the full length of the east elevation. According to the window assessment, the windows throughout the house are fixed, wood windows and aluminum-sliding windows from 1964, and the doors were all replaced by 1996.

The Plaza del Monte landscape includes low retaining walls, built in several phases, with dates of construction between 1950 and 1973. Some of the lots do have above-ground property line walls, which are constructed of stucco-clad concrete masonry units. The retaining and property line walls appear to post-date the construction of their associated units. The retaining walls vary in height from 8" up to 38", though most are 20" in height.

The Applicant proposes the following exterior alterations:

1. Replace windows and doors, including historic windows on the primary façade. An exception is requested to SFCC Section 14-5.2(D)(5)(a)(i-iii) for replacing historic windows and infilling a door opening on primary east and south façades. According to

the window assessment, windows A, B, C, E, F are historic, however, the tracks and special locks are no longer manufactured. The units would need to be replaced to function. The windows will be replaced in-kind with single-lite windows.

a. East Elevation (primary façade)
    i. The two kitchen windows (A and B) are horizontal sliders, single lite, both are historic and will be replaced with thermal-glass, awning windows in a single lite; the size of the window is not changing.
    ii. The front entry door, 15-panel, non-historic, will be replaced with an 8-raised-panel wood door.
    iii. The sliding, glass patio door, non-historic, will be replaced with a 3-panel sliding door with single lites.
    iv. Infill the door (door # 2) under the carport that enters the kitchen.
    v. Remove the door, six-panel, non-historic, to the storage area under the portal as part of the new enclosure. The opening for this door will remain (but will be interior after an enclosure is added under the carport).

b. North Elevation
    i. Remove and infill the historic window (C) in the living room.
    ii. Replace the non-historic window (D) at the den, increasing the height but without changing the width of the window.

c. West Elevation
    i. Replace the historic window (E) in the bedroom, increasing the height but without changing the width of the window.
    ii. Remove the historic window (F) in the primary bedroom and replace it with two tall, narrow windows, which will meet egress requirements.
    iii. Install a window in the primary bathroom where there are none currently.

2. Construct a 64-square-foot enclosure under the carport. An exception is requested to SFCC Section 14-5.2(D)(2)(c-d) for placing an addition on a primary façade. The enclosure will have two pedestrian doors. This decreases the depth of the carport, but the carport will remain.
3. Construct a free-standing latilla-post fence with a pedestrian gate under the portal between the carport and the front of the residence to enclose the courtyard. An exception is requested to SFCC Section 14-5.2(D)(5)(b) for placing an architectural feature on a primary façade where no there is no evidence it was there previously.
4. Demolish the existing cantilever overhang on the west façade.
5. Construct a Pueblo Revival Style portal to replace the cantilever on the west façade. The portal will include vigas, beams and corbels and will be constructed to a height of 9’8”.
6. Demolish the low yard wall to the east of the building to remove the small courtyard area. The taller section of the wall that connects to the north wall of the residence will be retained.
7. Replace the existing low yard wall with a 4’6”-high yard wall with pedestrian gate to close in the front yard. This wall will connect directly to the taller wall that connects to the north wall of the residence.
8. Construct a rear and side 6-foot-high coyote fence with a pedestrian gate.
9. Roof the residence using TPO in tan.
10. Stucco in cementitious “Buckskin” with “White” under the portal, retaining the historic texture.

FINDINGS OF FACT

After conducting a public hearing and having heard from the Applicant and all interested persons, the Board hereby FINDS, as follows:

1. Land Use Department Staff conducted a preliminary zoning review ("PZR") and determined that the application appears to meet the underlying zoning standards set forth in the Santa Fe City Code ("SFCC").
2. Historic Preservation Division Staff reviewed the application and related materials and information submitted by the Applicant for conformity with applicable SFCC requirements and provided the Board with a written report of its findings ("Staff Report"), which evaluates the factors relevant to the application.
3. Historic Preservation Division Staff Recommendation: Staff recommended findings that the exception criteria:
   - to SFCC Section 14-5.2(D)(5)(a)(i) for replacing historic windows and infilling a door on the primary east and south façades have been met, and recommended **approval** of this exception;
   - to SFCC Section 14-5.2(D)(2)(c-d) for adding a storage enclosure under the carport on the east, primary façade have been met, and recommended **approval** of this exception; and
   - to SFCC Section 14-5.2(D)(5)(b) for placing an architectural element on the east, primary façade where there was no evidence it previously existed have not been met, and recommended **denial** of this exception.

   Otherwise, staff recommended approval of the other elements of the application that did not require exceptions, as they comply with SFCC Sections 14-5.2(D), General Design Standards for all Historic Districts, and 14-5.2(E), Downtown and Eastside Historic District Design Standards.
4. The project is subject to SFCC Section 14-5.2(C), Regulation of Significant and Contributing Structures.
5. The project is subject to the requirements and general design standards set forth in SFCC Section 14-5.2(D), General Design Standards.
6. The property is located in the Downtown and Eastside Historic District and is subject to the district design standards set forth in SFCC Section 14-5.2(E).
7. Under SFCC Sections 14-2.6(B-C), 14-5.2(A)(1), 14-5.2(C)(2)(a-d & f), 14-5.2(C)(3)(a-b), 14-5.2(C)(4), and 14-5.2(D), the Board has authority to review, approve, with or without conditions, or deny, all or some of the Applicant's proposed design to assure overall compliance with applicable design standards.

Replacement of Historic Windows and Infill of Door:

8. Under SFCC Section 14-5.2(D)(5)(a), subsection (i) requires historic windows to be repaired or restored wherever possible, and subsection (iii) prohibits the infill of any existing opening.
9. The Applicant proposes to replace historic windows (A and B) on the east primary façade and to infill a door (door # 2) on the south primary façade. Staff determined that an exception to SFCC Section 14-5.2(D)(5)(a)(i-iii) would be required for approval of the application, and the Applicant requested an exception.

10. To obtain an exception, the Applicant was required to conclusively demonstrate that the three exception criteria set forth in SFCC Section 14-5.2(C)(5)(b) have been met.
11. Based on the information set forth in the Staff Report and exhibits, and the evidence and testimony presented at the hearing, the Board finds that the Applicant has conclusively demonstrated that all exception criteria have been met.
    a. Pursuant to SFCC Section 14-5.2(C)(5)(b)(i), the Board finds that granting the exception would not damage the character of the district because the replacement windows will be in-kind, and the door to be infilled is under the carport and has minimal public visibility;
    b. Pursuant to SFCC Section 14-5.2(C)(5)(b)(ii), the Board finds that the exception is required to prevent a hardship to the Applicant or an injury to the public welfare, because the windows no longer work and parts needed to repair them are no longer made; the door, which opens from the carport into the small, galley kitchen, encumbers space needed for a more functional kitchen; and
    c. Pursuant to SFCC Section 14-5.2(C)(5)(b)(iii), the Board finds that granting the exception would strengthen the unique heterogeneous character of the City by providing a full range of design options to ensure that residents can continue to reside within the Historic Districts because the new windows will function properly and allow for better ventilation, and removal of the door will allow more counter space or room for a small table.
12. The Board finds that the Applicant has conclusively demonstrated that all of the exception criteria have been met for replacement of historic windows A and B and infill of a door # 2 on the primary façades.

Addition of Enclosed Storage Area on Primary Façade:

13. Under SFCC Section 14-5.2(D)(2)(c-d) additions are not permitted to primary façades, and additions are not permitted to the side of the existing footprint unless the addition is set back a minimum of 10 feet from the primary façade.
14. The Applicant proposes to construct enclosed storage space attached to the east, primary façade, under the carport. Staff determined that an exception to SFCC Section 14-5.2(D)(2)(c-d) would be required for approval of the application, and the Applicant requested an exception.
15. To obtain an exception, the Applicant was required to conclusively demonstrate that the three exception criteria set forth in SFCC Section 14-5.2(C)(5)(b) have been met.
16. Based on the information set forth in the Staff Report and exhibits, and the evidence and testimony presented at the hearing, the Board finds that the Applicant has conclusively demonstrated that all exception criteria have been met:
    a. Pursuant to SFCC Section 14-5.2(C)(5)(b)(i), the Board finds that granting the exception would not damage the character of the district because the addition will be small (64 square feet), it will be set back from the street inside a carport, it will be minimally visible from the street, and it does not affect the overall appearance of the residence;
    b. Pursuant to SFCC Section 14-5.2(C)(5)(b)(ii), the Board finds that the exception is required to prevent a hardship to the Applicant or an injury to the public welfare, because it will allow the property owner to store tools out of sight which are presently stored under the open carport, are visible to the public and create a

cluttered appearance; and

c. Pursuant to SFCC Section 14-5.2(C)(5)(b)(iii), the Board finds that granting the exception would strengthen the unique heterogeneous character of the City by providing a full range of design options to ensure that residents can continue to reside within the Historic Districts, because there is little storage space in this house and this allows the family to secure tools which otherwise are stored outside, subject to theft, and impair the aesthetics of the primary façade.

17. The Board finds that the Applicant has conclusively demonstrated that all of the exception criteria have been met with respect to the addition of enclosed storage space on the east façade under the carport.

Latilla Fence and Gate Under Front Portal:

18. Under SFCC Section 14-5.2(D)(5)(b), no new material or feature for which there is no evidence of its prior existence may be placed on any façade of a contributing, significant or landmark structure.
19. The Applicant proposes to construct a latilla fence with pedestrian gate from the carport to the front entrance under the portal of the primary, east facade. Staff determined that an exception to SFCC Section 14-5.2(D)(5)(b), would be required for approval of the application, and the Applicant requested an exception.
20. To obtain an exception, the Applicant was required to conclusively demonstrate that the three exception criteria set forth in SFCC Section 14-5.2(C)(5)(b) have been met.
21. Based on the information set forth in the Staff Report and exhibits, and the evidence and testimony presented at the hearing, the Board agrees with Staff's finding that the Applicant has conclusively demonstrated that all exception criteria have been met.
    a. Pursuant to SFCC Section 14-5.2(C)(5)(b)(i), the Board finds that granting the exception would not damage the character of the district, because the fence and gate will be small (42" high x about 4' wide), it will not attach to the residence and will be partly concealed behind a structural column of the portal;
    b. Pursuant to SFCC Section 14-5.2(C)(5)(b)(ii), the Board finds that the exception is required to prevent a hardship to the Applicant or an injury to the public welfare, because it prevents small children and pets from having access to the street; and
    c. Pursuant to SFCC Section 14-5.2(C)(5)(b)(iii), the Board finds that granting the exception would strengthen the unique heterogeneous character of the City by providing a full range of design options to ensure residents can continue to reside in the Historic Districts, because it creates additional safety for children and pets so that a growing family can better utilize the outdoor space at this residence.
22. The Board finds that the Applicant has conclusively demonstrated that all of the exception criteria have been met for addition of a latilla fence with pedestrian gate under the east portal.

23. The information contained in the Staff Report and exhibits, and the testimony and evidence submitted at the hearing, establishes that all applicable requirements for Board review as herein described have been met.
24. The information contained in the Staff Report, and the exhibits, testimony and evidence submitted at the hearing, establishes that all applicable design criteria have been met.

CONCLUSIONS OF LAW

Under the circumstances and given the evidence and testimony submitted during the hearing, the Board acted upon the application as follows:

1. The Board has the authority to review and approve the application.
2. The Board approves Items # 1-10 as set forth in the application, as recommended by Staff.
3. With respect to Items # 1(a)(i) and (iv), the Board grants the exception to Section 14-5.2(D)(5)(a)(i-iii) requested in the application.
4. With respect to Item # 2, the Board grants the exception to Section 14-5.2(D)(5)(b) requested in the application.
5. With respect to Item # 3, the Board grants the exception to Section 14-5.2(D)(2)(c-d) requested in the application.

IT IS SO ORDERED ON THIS 8th DAY of SEPTEMBER, 2026, BY THE HISTORIC DISTRICTS REVIEW BOARD OF THE CITY OF SANTA FE.

_____ _____
Cecilia Rios, Chair Date

FILED:

_____ _____
Geralyn Cardenas Date
City Clerk

APPROVED AS TO FORM:

_____ _____
Frank Ruybalid Date
Assistant City Attorney

City of Santa Fe
Historic Districts Review Board
Findings of Fact and Conclusions of Law

Case # 2025-11549-HDRB
Address – 527 Agua Fria St.
Agent's Name – Richard Woodbury, Osage Design Studio
Owner/Applicant's Name – Neirika, LLC

THIS MATTER came before the Historic Districts Review Board ("Board") for hearing on December 9, 2025.

BACKGROUND

The 3,017-square-foot multi-family residence at 527 Agua Fria St. has been described as a conglomeration of styles representing different periods in New Mexico history. The core structure was built on this 0.418-acre lot sometime before 1908, with a small rear addition added before 1913, and a much larger addition added on its western elevation by 1921, according to Sanborn Fire Insurance Maps. On the 1930 Sanborn Map, the footprint of the building was changed from three simple rectangles to a blocky, almost square, footprint with the addition of a garage, and the outhouse was removed. Since 1930, relatively insignificant changes have taken place – primarily a restroom addition to the northeast corner and an added connector from the main house to the garage – both after 1985 but before 1998. The residential building is currently a three-unit structure that is being converted to a main residence with a guest house. It has an interior-only construction permit for the conversion work in progress.

Mrs. C.W. Dudrow is listed as the owner of the property on the 1912 Kings Map. Charles W. Dudrow came to Santa Fe between 1869 and 1872 and was involved in the lumber, coal and transport business. He was part owner with his wife's father of the Dudrow and Bear Ice, Transfer and Livery in 1881. The business was located near the train depot and Our Lady of Guadalupe Church and was a catalyst in the development of the area. The 1985 HCPI shows the residence was purchased by A.C. Koch in 1912 from the Dudrow Estate. A.C. Koch or a Koch family member is listed as the owner of the property from 1928 through 1964. Staff found that Adolphe Christian Koch, who died in 1939, lived in Santa Fe with his wife, Alice Broche Koch, who died in 1982 at 106 years old. Their son Ferdinand Adolph Koch was a prominent figure in Santa Fe's history, active in the dry cleaning business, land sales, including the Santa Fe Ski Basin, and various civic associations. Mrs. Dorothea K. Dunakin, a nurse, was associated with the property from 1944 through 1951.

The residence is built in a Mediterranean style with thick, stucco-plastered walls, red-tiled roofs, and ornate archways, with large, symmetrical facades designed for warmth and indoor-outdoor living. The roof is a red, metal tile roof with gables of various heights, gable horns and exposed rafters. According to the 1997 Historic Building Inventory, the roof was changed to the existing tile roof in 1920-1925. The 2025 Historic Cultural Properties Inventory reads that the original roof was a flat with drainage to the north. At some point, a gabled roof was added, raising the elevations of the residence. It is not evident if that was a clay tile roof,

but the present metal roof simulates a tile roof.

The historic status of this house is not clear, therefore, a designer representing the owner has requested the Board clarify its status. The GIS map shows the residence as significant to the Westside-Guadalupe Historic District, and the 1997 HBI reads that this structure is significant, and that it is listed on the National Register of Historic Places. However, a 1985 HBI reads that it is contributing, not significant. The 2025 HCPI clarifies that while the residence is listed in the State Register from September 29, 1972 (State Register # 260) and to the National Register from July 23, 1973 (National Register # 73001150), it is listed as a part of the Santa Fe Historic District, not individually. Tina Reames, the author of the 2025 HCPI who characterized the structure as a conglomeration of styles, recommended a contributing status for the structure.

The Applicant requests a status review with primary façade designations, if applicable for the residence.

FINDINGS OF FACT

After conducting a public hearing and having heard from the Applicant and all interested persons, the Board hereby FINDS, as follows:

1. Historic Preservation Division City staff reviewed the application and related materials and information submitted by the Applicant for conformity with applicable Santa Fe City Code ("SFCC") requirements and provided the Board with a written report of its findings ("Staff Report"), which evaluates the factors relevant to the application.
2. Historic Preservation Division Staff Recommendation: Staff recommended the historic status of the structure be maintained as significant for its association with events or persons that are important on a local level and the historic integrity of the building, with all façades as primary, per SFCC Sections 14-5.2(C), Designation of Significant, Contributing or Non-Contributing Status Within Historic Districts.
3. The project is subject to SFCC Section 14-5.2(C), Regulation of Significant and Contributing Structures.
4. The project is subject to the requirements and general design standards set forth in SFCC Section 14-5.2(D), General Design Standards.
5. The property is located in the Westside-Guadalupe Historic District and is subject to the district design standards set forth in SFCC Section 14-5.2(I).
6. SFCC Section 14-5.2(C)(2)(a-c) gives the Board authority to review and approve "significant," "contributing," or "non-contributing" status designations and to designate primary façades of contributing structures.
7. Under SFCC Section 14-12.1, the definition of a "significant structure" is a "structure located in a Historic District that is approximately 50 years old or older, and that embodies distinctive characteristics of a type, period or method of construction. For a structure to be designated as significant, it must retain a high level of historic integrity. A structure may be designated as significant: (A) for its association with events or persons that are important on a local, regional, national, or global level; or (B) if it is listed on or is eligible to be listed on the State Register of Cultural Properties or the National

Register of Historic Places."

8. Under SFCC Section 14-12.1, the definition of a "contributing structure" is "a structure, located in a Historic District, approximately 50 years old or older that helps to establish and maintain the character of that Historic District. Although a contributing structure is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The contributing structure may have had minor alterations, but its integrity remains."
9. Under SFCC Section 14-12.1, the definition of a "primary façade" is one or more principal faces or elevations of a building with features that define the character of the building's architecture.
10. Under SFCC Section 14-12.1, the definition of a "non-contributing structure" is a "structure, located in a Historic District, that is less than 50 years old or that does not exhibit sufficient historic integrity to establish and maintain the character of the Historic District."
11. Based on the information set forth in the Staff Report and exhibits and the testimony and evidence presented at the hearing, the Board finds that the structure meets the definition of a "contributing structure," contrary to the recommendation by the Staff. The Board finds that most of house has gone unchanged since the 1930s, and it adds to the historic associations of the Westside-Guadalupe Historic District, but it does not have the high level of historic integrity required for a significant designation.
12. The Board finds that the primary facades of the structure, with the features that define the character of the structure's architecture, are the south façades, R1 and R3, and the east façades, R2, R4, R5 and R6, including the portal in the southeast corner and the alcove over the front south-facing exterior door, including all windows and doors, but excluding any non-historic materials.



13. The information contained in the application and provided in testimony and evidence establishes that all applicable requirements for Board review have been met.

CONCLUSIONS OF LAW

Under the circumstances and given the evidence and testimony submitted during the hearing, the Board acted upon the application as follows:

1. The Board has the authority to review and approve the application.
2. The Board grants the Applicant's request to review historic status.
3. The Board designates the residence as a contributing structure.
4. The Board designates the following elevations of the residence as the primary

façades: south façades, R1 and R3, and the east façades, R2, R4, R5 and R6, including the portal in the southeast corner and the alcove over the front south-facing exterior door, including all windows and doors, but excluding any non-historic materials.

IT IS SO ORDERED ON THIS 8th DAY of SEPTEMBER, 2026, BY THE HISTORIC DISTRICTS REVIEW BOARD OF THE CITY OF SANTA FE.

_____ _____
Cecilia Rios Date
Chair

FILED:

_____ _____
Geralyn Cardenas Date
City Clerk

APPROVED AS TO FORM:

_____ _____
Frank Ruybalid Date
Assistant City Attorney

City of Santa Fe
Historic Districts Review Board
Findings of Fact and Conclusions of Law

Case # 2025-11700-HDRB
Address – 123 Camino Santiago
Agent's Name – John A. Padilla, AIA
Owner/Applicant's Name – Plaza del Monte, LLC

THIS MATTER came before the Historic Districts Review Board ("Board") for hearing on January 13, 2026.

BACKGROUND

Plaza del Monte, formerly the Plaza del Monte Retirement Compound, is an approximately six-acre, L-shaped subdivision bounded by Bishops Lodge Road on the east and Old Taos Highway on the west. The earliest plans by architects Kenneth Clark and Phillippe Register in the late 1950s were for the buildings on the eastern part of the development, and were Spanish-Pueblo Revival in style. However, when Register solely took over the project in the 1960s, his designs evolved into contemporary flat-roof structures with the use of canales, viga-roof portales and carport elements. In the mid-1960s, Camino Santiago was extended, and development at the western end of the development began. This is when Register chose to eliminate several free-standing houses on the plans and replace them with quad apartments. Once fully developed, the compound consisted of 25 single-family residences and three quad apartment structures. The apartments include 105, 123, 125 and 126 Camino Santiago.

The quad apartments at 123 and 125 Camino Santiago, built circa 1970, are listed as non-contributing to the Downtown and Eastside Historic District. The structure is rectangular with bilateral symmetry, having block massing at the north and south, which bookend a portal along the length of the east elevation. A block mass in the center has a large, square opening, and is open on the sides to allow the portal to extend underneath. The doors and windows on the east street-facing elevation are in a uniform pattern. The entry doors are wood with lite panels. The windows are standard multi-lite steel casements. The north and south elevations contain three aluminum-casement windows. The west elevation holds four patios sheltered by shallow overhangs and sliding-door entries. The structure is 3,563 square feet and is divided into four apartments; there is a Unit A and a Unit B at each address. A concrete and stone retaining wall separates the structure from the northern neighboring property.

All structures in Plaza del Monte were assigned statuses under Case #s H-17-098A in 2018 and H-19-019 in 2019. Under Case # H-17-098A, the property at 123 and 125 Camino Santiago was designated non-contributing, as they were not 50 years old at that time and deemed non-historic. No yard walls were considered for status except for those located at 126 Camino Santiago, which were designated contributing.

The Applicant requests a status review with primary façade designation, if applicable, for the quadplex located at 123 and 125 Camino Santiago. The Staff finds the structure to be a

contributing structure due to its association with Clark and Register's master-planned community and historic compound, Plaza del Monte, and the association with the Presbyterian Church. The structure is a good example of mid-century modern Santa Fe Style. Character-defining features include the massing blocks at either end and the blocking mass in the center of the structure, and the full-length portal on the east elevation.

FINDINGS OF FACT

After conducting a public hearing and having heard from the Applicant and all interested persons, the Board hereby FINDS, as follows:

1. Historic Preservation Division City staff reviewed the application and related materials and information submitted by the Applicant for conformity with applicable Santa Fe City Code ("SFCC") requirements and provided the Board with a written report of its findings (Staff Report), which evaluates the factors relevant to the application.
2. Historic Preservation Division Staff Recommendation: Staff recommended the historic status of the residential structure be upgraded to contributing with the entire east elevation (R1, R2, R3, R4 and R5) designated as the primary façade, including the portal but excluding the non-historic materials; and that the north property line retaining wall be designated as non-contributing, per SFCC Section 14-5.2(C), Designation of Significant, Contributing or Non-Contributing Status Within Historic Districts.
3. The project is subject to SFCC Section 14-5.2(C), Regulation of Significant and Contributing Structures.
4. The project is subject to the requirements and general design standards set forth in SFCC Section 14-5.2(D), General Design Standards.
5. The property is located in the Downtown and Eastside Historic District and is subject to the district design standards set forth in SFCC Section 14-5.2(E).
6. SFCC Section 14-5.2(C)(2)(a-c) gives the Board authority to review and approve "significant," "contributing," or "non-contributing" status designations and to designate primary façades of contributing structures.
7. Under SFCC Section 14-12.1, the definition of a "contributing structure" is "a structure, located in a Historic District, approximately 50 years old or older that helps to establish and maintain the character of that Historic District. Although a contributing structure is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The contributing structure may have had minor alterations, but its integrity remains."
8. Under SFCC Section 14-12.1, the definition of a "primary façade" is one or more principal faces or elevations of a building with features that define the character of the building's architecture.
9. Under SFCC Section 14-12.1, the definition of a "non-contributing structure" is a "structure, located in a Historic District, that is less than 50 years old or that does not exhibit sufficient historic integrity to establish and maintain the character of the Historic District."
10. Based on the information set forth in the Staff Report and exhibits and the testimony and evidence presented at the hearing, the Board finds that the structure meets the definition

of a "contributing structure," as recommended by staff. The structure is a good example of mid-century modern Santa Fe Style. Character-defining features include the massing blocks at both ends and the blocking mass in the center of the structure, and the portal that extends the full length of the east elevation.

11. The Board finds that all façades on the east elevation (R1, R2, R3, R4 and R5) are the primary façades of the structure, with the features that define the character of the structure's architecture. (These include the façades on the attached apartments at 125 Camino Santiago (R1, R2 and R3); see Case # 2025-11701-HDRB.)
12. The information contained in the application and provided in testimony and evidence establishes that all applicable requirements for Board review have been met.

CONCLUSIONS OF LAW

Under the circumstances and given the evidence and testimony submitted during the hearing, the Board acted upon the application as follows:

1. The Board has the authority to review and approve the application.
2. The Board grants the Applicant's request to review historic status.
3. The Board upgrades the status of the structure to contributing.
4. The Board designates the following as the primary façades: east (R3, R4 and R5).

IT IS SO ORDERED ON THIS 8th DAY of SEPTEMBER, 2026, BY THE HISTORIC DISTRICTS REVIEW BOARD OF THE CITY OF SANTA FE.

_____ _____
Cecilia Rios Date
Chair

FILED:

_____ _____
Geralyn Cardenas Date
City Clerk

APPROVED AS TO FORM:

_____ _____
Frank Ruybalid Date
Assistant City Attorney

City of Santa Fe
Historic Districts Review Board
Findings of Fact and Conclusions of Law

Case # 2025-11701-HDRB
Address – 125 Camino Santiago
Agent's Name – John A. Padilla, AIA
Owner/Applicant's Name – Plaza del Monte, LLC

THIS MATTER came before the Historic Districts Review Board ("Board") for hearing on January 13, 2026.

BACKGROUND

Plaza del Monte, formerly the Plaza del Monte Retirement Compound, is an approximately six-acre, L-shaped subdivision bounded by Bishops Lodge Road on the east and Old Taos Highway on the west. The earliest plans by architects Kenneth Clark and Phillippe Register in the late 1950s were for the buildings on the eastern part of the development, and were Spanish-Pueblo Revival in style. However, when Register solely took over the project in the 1960s, his designs evolved into contemporary flat-roof structures with the use of canales, viga-roof portales and carport elements. In the mid-1960s, Camino Santiago was extended, and development at the western end of the development began. This is when Register chose to eliminate several free-standing houses on the plans and replace them with quad apartments. Once fully developed, the compound consisted of 25 single-family residences and three quad apartment structures. The apartments include 105, 123, 125 and 126 Camino Santiago.

The quad apartments at 123 and 125 Camino Santiago, built circa 1970, are listed as non-contributing to the Downtown and Eastside Historic District. The structure is rectangular with bilateral symmetry, having block massing at the north and south, which bookend a portal along the length of the east elevation. A block mass in the center has a large, square opening, and is open on the sides to allow the portal to extend underneath. The doors and windows on the east street-facing elevation are in a uniform pattern. The entry doors are wood with lite panels. The windows are standard multi-lite steel casements. The north and south elevations contain three aluminum-casement windows. The west elevation holds four patios sheltered by shallow overhangs and sliding-door entries. The structure is 3,563 square feet and is divided into four apartments; there is a Unit A and a Unit B at each address. A concrete and stone retaining wall separates the structure from the northern neighboring property.

All structures in Plaza del Monte were assigned statuses under Case #s H-17-098A in 2018 and H-19-019 in 2019. Under Case # H-17-098A, the property at 123 and 125 Camino Santiago was designated non-contributing, as they were not 50 years old at that time and deemed non-historic. No yard walls were considered for status except for those located at 126 Camino Santiago, which were designated contributing.

The Applicant requests a status review with primary façade designation, if applicable, for the quadplex located at 123 and 125 Camino Santiago. The Staff finds the structure to be a

contributing structure due to its association with Clark and Register's master-planned community and historic compound, Plaza del Monte, and the association with the Presbyterian Church. The structure is a good example of mid-century modern Santa Fe Style. Character-defining features include the massing blocks at either end and the blocking mass in the center of the structure, and the full-length portal on the east elevation.

FINDINGS OF FACT

After conducting a public hearing and having heard from the Applicant and all interested persons, the Board hereby FINDS, as follows:

1. Historic Preservation Division City staff reviewed the application and related materials and information submitted by the Applicant for conformity with applicable Santa Fe City Code ("SFCC") requirements and provided the Board with a written report of its findings (Staff Report), which evaluates the factors relevant to the application.
2. Historic Preservation Division Staff Recommendation: Staff recommended the historic status of the residential structure be upgraded to contributing with the entire east elevation (R1, R2, R3, R4 and R5) designated as the primary façade, including the portal but excluding the non-historic materials; and that the north property line retaining wall be designated as non-contributing, per SFCC Section 14-5.2(C), Designation of Significant, Contributing or Non-Contributing Status Within Historic Districts.
3. The project is subject to SFCC Section 14-5.2(C), Regulation of Significant and Contributing Structures.
4. The project is subject to the requirements and general design standards set forth in SFCC Section 14-5.2(D), General Design Standards.
5. The property is located in the Downtown and Eastside Historic District and is subject to the district design standards set forth in SFCC Section 14-5.2(E).
6. SFCC Section 14-5.2(C)(2)(a-c) gives the Board authority to review and approve "significant," "contributing," or "non-contributing" status designations and to designate primary façades of contributing structures.
7. Under SFCC Section 14-12.1, the definition of a "contributing structure" is "a structure, located in a Historic District, approximately 50 years old or older that helps to establish and maintain the character of that Historic District. Although a contributing structure is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The contributing structure may have had minor alterations, but its integrity remains."
8. Under SFCC Section 14-12.1, the definition of a "primary façade" is one or more principal faces or elevations of a building with features that define the character of the building's architecture.
9. Under SFCC Section 14-12.1, the definition of a "non-contributing structure" is a "structure, located in a Historic District, that is less than 50 years old or that does not exhibit sufficient historic integrity to establish and maintain the character of the Historic District."
10. Based on the information set forth in the Staff Report and exhibits and the testimony and evidence presented at the hearing, the Board finds that the structure meets the definition

of a "contributing structure," as recommended by staff. The structure is a good example of mid-century modern Santa Fe Style. Character-defining features include the massing blocks at both ends and the blocking mass in the center of the structure, and the portal that extends the full length of the east elevation.

11. The Board finds that all façades on the east elevation (R1, R2, R3, R4 and R5) are the primary façades of the structure, with the features that define the character of the structure's architecture. (These include the façades on the attached apartments at 123 Camino Santiago (R3, R4 and R5); see Case # 2025-11700-HDRB.)
12. The information contained in the application and provided in testimony and evidence establishes that all applicable requirements for Board review have been met.

CONCLUSIONS OF LAW

Under the circumstances and given the evidence and testimony submitted during the hearing, the Board acted upon the application as follows:

1. The Board has the authority to review and approve the application.
2. The Board grants the Applicant's request to review historic status.
3. The Board upgrades the status of the structure to contributing.
4. The Board designates the following as the primary façades: east (R1, R2 and R3).

IT IS SO ORDERED ON THIS 8th DAY of SEPTEMBER, 2026, BY THE HISTORIC DISTRICTS REVIEW BOARD OF THE CITY OF SANTA FE.

_____ _____
Cecilia Rios Date
Chair

FILED:

_____ _____
Geralyn Cardenas Date
City Clerk

APPROVED AS TO FORM:

_____ _____
Frank Ruybalid Date
Assistant City Attorney

City of Santa Fe, New Mexico

memo

DATE: September 8, 2026

TO: Historic Districts Review Board Members

VIA: Heather Lamboy, AICP, Planning & Land Use Department Director
Maggie Moore, Assistant Land Use Director, MM

FROM: Lani McCulley, Senior Planner, Historic Preservation Division, LGM

2026-012916-HDRB. 104 Camino Matías, Downtown & Eastside Historic District, contributing, Bernie Romero, agent for Vicki Montano-Torres, owner, proposes to construct a 438 sq. ft. portal to a height of 9'-10" and a 35 sq. ft. addition, replace windows and doors, construct a 5'-0" high yard wall, and install HVAC. Exceptions are requested to 14-4.6(E)(4)(I)(a) to replace windows and doors on a primary façade, and 14-4.6(E)(2)(II)(b) to construct an addition within 10' of a primary façade.

REFERENCE ATTACHMENTS (Sequentially):

CITY SUBMITTALS

____ **District Standards & yard wall & fence standards.**

__x__ **Historic Inventory Form**

__x__ **Zoning Review Sheet**

__x__ **Other**: [Plaza del Monte documents]

APPLICANT SUBMITTALS

__x__ **Proposal Letter**

__x__ **Site Plan/Floor Plan**

__x__ **Elevations**

__x__ **Photographs**

__x__ **Other:** [exception criteria]

STAFF RECOMMENDATION:

Staff finds that the exception criteria to 14-4.6(E)(4)(I)(a) have been met and recommends approval for replacing the windows and doors on a primary façade. Staff finds that the exception criteria to 14-4.6(E)(2)(II)(a) have not been met and recommends denial for constructing an addition on a primary façade. Otherwise, staff recommends approval of the other elements of the application as they comply with 14-5.2(D) General Design Standards for all Historic Districts, and 14-4.6(G)(2) Downtown and Eastside Historic District Design Standards.

Sample motions:

a. In case 2026-012916-HDRB, for 104 Camino Matias, approve/deny the exception to 14-4.6(E)(4)(I)(a) to replace windows and doors on a primary façade, finding that the exception criteria have/have not been met.
b. In case 2026-012916-HDRB, for 104 Camino Matias, approve/deny the exception to 14-4.6(E)(2)(II)(a) to construct an addition on a primary façade, finding that the exception criteria have/have not been met.
c. In case 2026-012916-HDRB, for 104 Camino Matias, approve/deny the elements of the project that do not require an exception.

Should the Board deny the exception request(s), the applicant shall return with an alternative proposal for review and approval before proceeding to a building permit.

The property lies within the Historic Downtown Archaeological Review District. See Chapter 14, SFCC, Article 14-14-4.2(D). There may be archaeological concerns associated with this project, and archaeological clearance may be required.

BACKGROUND & SUMMARY:

Streetscape:

Plaza del Monte, formerly the Plaza del Monte Retirement Center, is an approximately six-acre subdivision that is "L" shaped and is bounded by Bishops Lodge Road on the east and Old Taos Highway on the west. The development has two roads, Camino Santiago and Camino Matias. While several structures predate the center, the communal living center was originally developed for retired members of the Presbyterian Church, starting in the late 1950s and continuing until 1977. The earliest plans by Clark and Register are for the buildings on the eastern portion of the development and were Spanish-Pueblo Revival in style. However, when Philippe Register took over the project in the 1960s, his designs evolved into a contemporary flat-roof structure with the use of canales, viga-roof portales, and carport elements. In the mid-1960s, Camino Santiago was extended, and development of the western end of the development began. This is when Register chose to eliminate several freestanding houses on the plans and replace them with quad apartments. Once fully developed, the compound consisted of 25 single-family residences and 3 quad apartment structures. The apartments include the structures at 105, 125, and 126 Camino Santiago.

The Plaza del Monte landscape includes retaining walls, constructed of formed concrete or concrete and stone, built over several phases, dating generally between 1950 and 1973. The walls were constructed to retain earth or to separate building pads. Very few of them rise above grade. A few lots have above-ground property line walls. These are made of stucco-clad concrete masonry units. The retaining and property line walls appear to post-date the construction of their associated units.

Site Description:

The single-family residence at 104 Camino Matias was one of the first units to be constructed in the Plaza del Monte compound in 1965. The residence is listed as contributing to the Downtown and Eastside Historic District. The northwest and northeast elevations are designated as primary.

The L-shaped residence is approximately 1,143 sq. ft. and presents a Spanish-Pueblo Revival plan. There is a carport located on the north and a carport on the west. The portal is supported by simple round columns, is ornamented by corbels, and houses a viga roof. The carport is a single bay behind the portal and has a subdued presence unlike most in the compound. The windows are aluminum casement units. According to the 2018 HCPI, *"It represents the closest interpretation of the original 1960 Kenneth S. Clark and Philippe Register template design for the development."*

PREVIOUS CASE SUMMARIES:

ARC:
The property has received Archaeological clearance under case 2023-007030-ARC.

HDRB:
All structures in Plaza del Monte were assigned statuses under cases H-17-098A and H-19-019 in 2018 and 2019. Under case H-19-019, the property at 104 Camino Santiago was designated as contributing, with the north and west facades as primary. No yard walls were considered for status except for those located at 126 Camino Santiago, which were designated as contributing.

ADMINISTRATIVE:
No administrative approval is on file for this property.

APPLICANT'S REQUEST:
The applicant proposes the following exterior alterations:

1) An addition on the west elevation beneath the existing portal. This will result in the relocation of the primary entrance to the residence from facing west to facing south. An exception is requested to 14-4.6(E)(2)(II)(a) for placing an addition on a primary façade.
2) Replace all windows in the residence with wood clad in bronze with single-lite windows to match the existing in the same-size openings. An exception is requested to 14-4.6(E)(4)(I)(a) to replace historic windows.
    a. Windows A, B, C, D, F, G, H, I, and J are historic windows. According to the window assessment, these windows are not repairable.
    b. Window E is not historic.
    c. Doors 1, 2, 3, 4, and 5 are not historic.
3) Replace all doors in the residence, infill the south entry, and create a door from a window on the east elevation.
4) Construct a portal on the east elevation to match the existing west portal with a medium walnut stain.
5) Construct two 5'0" high stuccoed yard walls on the east side of the residence that run east from the residence to the existing yard wall at the east property line. There will be no gates in these yard walls.

6) Stucco the residence in cementitious "Adobe" with cementitious "Colonial White" under the portal to retain the existing appearance of the residence. The structure has a historic brocade texture, and the texture shall be retained.
7) Install condensers in the rear (east) yard. The screen to prevent public visibility will be the 5'-0" high yard walls.

EXCEPTION CRITERIA AND RESPONSES:

Exception to 14-4.6(E)(4)(I)(a): The applicant requests an exception to replace historic windows on a primary façade.

(i) *Do not damage the character of the district*

Applicant Response: The existing windows are old-style sliding windows and are very difficult to open. The tracks for the sliding window units are damaged and, even with a little muscle, will not open. The windows will be replaced with new clad bronze windows in-kind and will not damage or change the character of the district.

Staff Response: Staff finds that this criterion is met. According to the window assessment, windows A, B, C, D, F, G, H, I, and J are non-repairable historic windows. The replacement windows are wood-clad in bronze with single-lite windows, which will appear the same as the historic windows and therefore will not damage the character of the district.

(ii) *Are required to prevent a hardship to the applicant or an injury to the public welfare*

Applicant Response: The existing sliding mechanisms are damaged beyond repair, and the owner requests replacing them due to the difficulty of operating them.

Staff Response: Staff finds that this criterion is met. According to the window assessment, windows A, B, C, D, F, G, H, I, and J are non-repairable historic windows, as the parts needed to repair the windows are no longer manufactured. If the windows cannot be repaired, then requiring the preservation of inoperable windows would constitute a hardship to the applicant.

(iii*) Strengthen the unique heterogeneous character of the City by providing a full range of design options to ensure that residents can continue to reside within the historic districts*

Applicant Response: Replacing the existing windows with in-kind windows does not damage the unique heterogeneous character of the City, and the elevations and openings will not be changed.

Staff Response: Staff finds that this criterion is met. There is no plan to change the openings of the windows, which are part of the defining characteristics of the building. The new windows will appear the same in those openings. Replacing the existing inoperable windows with functioning windows will ensure the structure can continue to be used for residential purposes.

Exception to 14-4.6(E)(2)(II)(a): The applicant requests an exception to construct an addition on a primary façade.

(i) *Do not damage the character of the district*

Applicant Response: The new entry addition will be constructed under the existing portal. The entire portal will remain, surrounding the proposed entry area, which will remain similar to the existing, and the change to the existing character will be minimal.

Staff Response: Staff finds that this criterion is not met. There are no structures in this historic compound with this type of entry. It is contrary to the original design of the buildings. Therefore, the alteration will change the character of the structure, compound, and ultimately, the district.

(ii) *Are required to prevent a hardship to the applicant or an injury to the public welfare*
Applicant Response: There is no hardship for the new entry installation. My client would like to make this change to enhance the entry and make it more accessible.

Staff Response: Staff finds that this criterion is not met. This residence has stood since the early 1960s with this west-facing door and no entry foyer to the residence. There is no hardship in entering the residence directly into the living space, especially since there is a large portal for protection from the weather and as a transition to residence entry.

(iii*) Strengthen the unique heterogeneous character of the City by providing a full range of design options to ensure that residents can continue to reside within the historic districts*
Applicant Response: Installing a new entry under the existing portal will not damage the unique heterogeneous character of the City, and the west elevation with the new entry will enhance the residence.

Staff Response: Staff finds that this criterion is not met. The residence was purchased with this entry; the entry matches those of other structures in the compound and of the district. No other design options have been considered. This entry addition is not required to ensure the continued use of the structure as a residence.

RELEVANT CODE CITATIONS:

14-4.6 HISTORIC DISTRICTS

A. General Provisions

1. Purpose

In order to promote the economic, cultural, and general welfare of the people of Santa Fe and to ensure the harmonious, orderly, and efficient growth and development of the City, the Governing Body deems it essential to preserve the qualities relating to the history and culture of Santa Fe, maintain a harmonious outward appearance to preserve property values, and attract residents and tourists alike. The specific purposes of this section are to preserve qualities relating to the history of Santa Fe, such as the following:

I. Continue the existence and preservation of historic areas and buildings;

II. Continued construction of buildings in Santa Fe's historic styles; and

III. General harmony as to architectural style, form, color, height, proportion, texture, and material between buildings of historic design and those of more modern design.

C. Buildings with Significant or Contributing Historic Status

I. Purpose

Historic designation is intended to address the following:

I. Recognizing each structure as a physical record of its time, place, and use.

II. Preventing changes that create a false sense of historical development, such as the addition of conjectural features or architectural elements from other buildings;

III. Preserving and retaining changes to structures that have acquired historic importance in their own right, recognizing that most structures change over time;

IV. Preserving distinctive features, finishes, and construction techniques or examples of craftsmanship that characterize a structure; and

V. Avoiding making new additions and related or adjacent new construction in such a manner that, if removed in the future, the original form and integrity of the historic property and its environment would be unimpaired.

2. Designation of Significant, Contributing, or Noncontributing Status

I. Status Designation

Structures within historic districts may be designated a status of "significant," "contributing," or "noncontributing," as defined in Section 14-9.3, *General Definitions.* Staff shall maintain a record of the current status of structures located in the historic districts.

II. HDRB Authority to Review Status Designation

a. The HDRB may change the status of a structure or designate a status for a structure that has no status designated.

b. A change in status or the designation of a status shall be based upon an evaluation of data provided through survey or other relevant sources of information and the definitions of "significant," "contributing," or "noncontributing."

c. When the HDRB designates a structure as contributing, it shall also specify which facades of the structure are primary.

V. Restoration of Status

If a property owner makes changes to a structure without the proper City approvals, which result in the lowering of the structure's status, staff or the Board may require the property owner to restore the structure such that its former status is restored.

3. Review by Historic Districts Review Board Required

I. Except where this chapter provides for review by staff, the HDRB shall review all applications for new construction, alteration, or demolition in the historic districts and of landmark structures throughout the city, based on the standards set forth in this section.

II. The historic board shall judge any proposed alteration or new structure for harmony with adjacent buildings, preservation of historical and characteristic qualities, and conformity to the standards for architectural style set forth in this section.

III. The HDRB may approve, deny, approve with conditions, or, with the consent of the applicant, postpone an application.
   a. For applications approved with conditions, no permit shall be issued until the HDRB conditions have been met.
   b. An application that is postponed shall be heard at a date agreed upon by the HDRB and the applicant.

IV. No permit shall be issued until the time for appeal to the Governing Body has expired.

4. Compliance with General and Specific Design Standards Required

All development located within the historic districts and subject to this section shall comply with all applicable general development standards set forth in Section 14-4.6E), *General Design Standards for All Historic Districts,* as well as any applicable specific development standards set forth in Section 14-4.6G), *Additional District-Specific Design Standards.*

E. General Design Standards for All Historic Districts

These standards shall apply to all additions or alterations to existing structures in the Historic Districts. Contributing, significant, and landmark structures may be subject to specific additional restrictions and district-specific standards in Section 14-4.6(G).

I. General

I. The historic status of a property with a historic status designation of significant, contributing, or landmark structure shall be retained and preserved. If a proposed alteration will cause a property to lose its significant, contributing, or landmark status, the application shall be denied. The removal of historic materials or alteration of architectural features and spaces that embody the status is prohibited.

II. If a proposed alteration or new construction will cause an adjacent property to lose its significant, contributing, or landmark status, the application may be denied.

III. For the regulations of this subsection, all facades of a significant structure are primary facades.

2. Building Additions

I. Design
   a. Building additions that meet the standards of Section 14-4.6G2, *Downtown and Eastside Historic District,* shall continue to meet those standards, in addition to the standards set forth in this section.
   b. Building additions shall have similar materials, architectural treatments and styles, features, and details as the existing structure, but shall be distinguishable from and not attempt to duplicate the existing structure.

II. Size and Location
   a. Building additions are not permitted on primary facades.

b. All building additions shall be set back a minimum of ten feet from the primary facade.
c. Building additions shall not exceed 50 percent of the square footage of the building's historic footprint and shall not exceed 50 percent of the historic length in linear feet of the primary facade.
d. To the extent architecturally practicable, new building additions shall be attached to any existing non-primary facade of a structure rather than attaching them to the primary facade of a structure.

III. Height
a. The maximum height of building additions to significant and landmark structures shall be at least six inches lower than the parapet or equivalent roof feature of the existing adjacent connecting facade.
b. Building additions to contributing structures shall be no more than one additional story higher than the existing structure. To the extent architecturally practicable, two-story additions shall be set to the rear or the side rear of the structure. When an additional story is to be placed upon an existing contributing structure, that footprint may be no greater than fifty percent of the footprint of the existing structure, subject to the provisions of Subsection A(1) above. For the purposes of this paragraph, an additional story shall not exceed twelve (12) feet from the existing rooftop to the highest point of that story.

IV. Remodeling to Increase Height
a. For remodeling of an existing significant or landmark structure, no increase in height of the structure is permitted.
b. For remodeling an existing contributing structure, a height increase may be permitted through approval of an exception, as described in Section 14-4.6D.

V. Rooftop Equipment

Rooftop equipment, including but not limited to solar collectors, clerestories, decks, or mechanical equipment, may only be installed on contributing and noncontributing structures and shall not be publicly visible, nor shall a parapet be raised to conceal such equipment.

3. Porches and Portals

Existing porches or portals on significant and landmark structures, and on primary facades of contributing structures, shall not be permanently enclosed.

4. Windows, Doors, and Other Architectural Features

I. For all facades of significant and landmark structures and for the primary facades of contributing structures:
a. Historic windows shall be repaired or restored wherever possible. Historic windows that cannot be repaired or restored shall be duplicated in the size, style, and material of the original. Thermal double-pane glass may be used. No window opening shall be widened or narrowed.
b. Window depth and other characteristics of window and door fenestration shall

be preserved.

c. No new opening shall be made where one presently does not exist unless historic documentation supports its prior existence.

d. No historic opening shall be closed.

II. For all facades of contributing, significant, and landmark structures:

a. Architectural features, finishes, and details other than doors and windows shall be repaired rather than replaced.

b. In the event replacement is necessary, the use of new material may be approved. The new material shall match the material being replaced in composition, design, color, texture, and other visual qualities.

c. Replacement or duplication of missing features shall be substantiated by documentation, physical, or pictorial evidence.

5. Roofs

The existing historic roof styles and materials shall be maintained or replaced in kind if necessary. The addition of dormers or other roof features should only be considered when they are an existing historic feature of the structure.

6. Surface Cleaning

The surface cleaning of structures shall employ the gentlest means possible. Chemical or physical treatments, such as sandblasting, that cause damage to historic materials are not permitted.

7. Archaeological Resources

Discovery of archaeological resources made during the development of a historic property shall be referred to the Archaeological Review Committee. See Section 14-2.1G.1.V.c, *Unexpected Discoveries.*

8. Signs

9. Murals

10. Pedestrian-Oriented Areas

F. Height, Pitch, Scale, Massing, and Floor Stepbacks.

The height, pitch, scale, and massing of any structure in a historic district, as defined in this section, shall be limited as provided for in this section, unless further restricted elsewhere within this chapter.

I. Applicability

The following sections identify specific areas and specific projects subject to this section. The Planning and Land Use Director shall determine whether or not properties are included within this section.

I. Specific Areas

The height limitations in this subsection F apply:

a. Within the following historic districts:

1. Downtown and Eastside;
2. Don Gaspar Area;
3. Historic Transition; and
4. Westside-Guadalupe.

b. In the Historic Review district, as specified herein.

II. Streetscape Standards

III. Project Location

Planning and Land Use Department staff shall determine the applicability of this section to individual projects and the applicable streetscape

2. Height

I. Official Map of Building Heights in the Historic Districts - Procedures

II. Height Limitations

The HDRB shall limit the height of structures as set forth in this section. Heights of existing structures shall be as set forth on the official map of building heights in the historic districts.

a. If a proposed building has a parapet, the façade shall not exceed two feet above the average of the height of the façades in the streetscape.
b. If the proposed building has a pitched roof, the ridge height of the proposed building shall not exceed two feet above the average of the ridge height of the pitched roofs in the streetscape.
c. Yard walls and fences shall be limited to a height that does not exceed the average of the height of other yard walls and fences in the streetscape.
d. The height of any other structure shall be limited to the allowable building height within the applicable streetscape, as defined in this section.
e. The height and dimensions of signage are as set forth in Section 14-7.61, *Sign Regulations in the Historic Districts.*
f. The HDRB may increase the allowable height for proposed buildings and additions located on a sloping site where the difference in the natural grade along the structure's foundation exceeds two feet. In no case shall the height of a façade exceed four feet above the allowable height of the applicable streetscape measured from natural or finished grade, whichever is more restrictive. This increase in height shall be constructed only in the form of building setbacks from the street.

III. Height Measurement

a. In historic districts, height shall be the vertical distance measured between the highest part of a structure and the existing grade or finished grade, whichever is more restrictive, at the midpoint of the street-facing facade, excluding rooftop appurtenances, the increased height of walls or fences over pedestrian and vehicular openings, and gates (either in open or closed position).
b. For structures that do not have street frontage, height shall be determined by the facade that contains the tallest vertical distance measured between the highest part of a structure and the existing grade or finished grade, whichever is more

restrictive. The height of walls and fences is measured from the street-facing side of the wall or fence.

IV. Pitch

If the determined streetscape includes over 50 percent buildings with pitched roofs, the proposed building may have a pitched roof. A pitched roof is defined as a gable, shed, or hipped roof. The pitch of the roof shall match the predominant pitch extant in the streetscape.

V. Scale

The height of a proposed building or addition, its façade length, and its roof form and pitch shall appear to be in proportion to the height, façade length, and roof form and pitch of buildings in the applicable streetscape, or the building on which the addition is proposed.

VI. Massing and Floor Stepbacks

The HDRB may require that upper floor levels be stepped back, to carry out the intent of this section; provided that the HDRB in making such determinations shall take into account whether the height of the proposed building, yard wall, fence, or proposed step back of upper floor levels is in harmony with the massing of the applicable streetscape and preservation of the historic and characteristic visual qualities of the streetscape. The HDRB shall also require that the publicly visible facades of the structure be in conformance with Section 14-4.6G), *Additional District-Specific Design Standards,* and, in meeting those requirements, may require that different floor levels be stepped back.

G. Additional District-Specific Design Standards

2. Downtown and Eastside Historic District

The governing body recognizes that a style of architecture has evolved within the city from the year 1600 to the present characterized by construction with adobe, hereafter called "old Santa Fe style", and that another style has evolved, hereafter called "recent Santa Fe style", which is a development from, and an elaboration of the old Santa Fe style, with different materials and frequently with added decorations.

I. Old Santa Fe Style

Old Santa Fe style, characterized by construction with adobe, is defined as including the so-called "pueblo" or "pueblo-Spanish" or "Spanish-Indian" and "territorial" styles and is more specifically described as follows:

a. With rare exception, buildings are of one story; a few have three stories, and the characteristic effect is that the buildings are long and low. Roofs are flat with a slight slope and surrounded on at least three sides by a firewall of the same color and material as the walls or of brick. Roofs are never carried out beyond the line of the walls except to cover an enclosed portal or porch formed by setting back a portion of the wall or to form an exterior portal, the outer edge of the roof being

supported by wooden columns.

Two-story construction is more common in the territorial than in other sub-styles, and is preferably accompanied by a balcony at the level of the floor of the second story. Facades are flat, varied by inset portales, exterior portales, projecting vigas or roof beams, canales or water-spouts, flanking buttresses and wooden lintels, architraves and cornices, which, as well as doors, are frequently carved, and the carving may be picked out with bright colors. Arches are almost never used except for nonfunctional arches, slightly ogival, over gateways in freestanding walls.

b. All exterior walls of a building are painted alike. The colors range from a light earth color to a dark earth color. The exception to this rule is the protected space under portales, or in church-derived designs, inset panels in a wall under the roof, in which case the roof overhangs the panel. These spaces may be painted white or a contrasting color or have mural decorations.
c. Solid wall space is always greater in any façade than window and door space combined. Single panes of glass larger than thirty (30) inches in any dimension are not permissible except as otherwise provided in this section;
d. The rules as to flat roofs shall not be constructed to prevent the construction of skylights or installation of air conditioning devices, or any other necessary roof structures, but such structures other than chimneys, flues, vents and aerials, shall be so placed as to be concealed by the firewall from the view of anyone standing in the street on which the building fronts;
e. True old Santa Fe style buildings are made of adobe with mud plaster finish. Construction with masonry blocks, bricks, or other materials with which the adobe effect can be simulated is permissible, provided that the exterior walls are not less than eight (8) inches thick and that geometrically straight façade lines are avoided. Mud plaster or hard plaster simulating adobe, laid on smoothly, is required; and
f. It is characteristic of Old Santa Fe style commercial buildings to place a portal so that it covers the entire sidewalk, the columns being set at the curb line.

II. Recent Santa Fe Style

Recent Santa Fe style intends to achieve harmony with historic buildings by retention of a similarity of materials, color, proportion, and general detail. The dominating effect is to be that of adobe construction, prescribed as follows:

a. No building shall be over two stories in height in any façade unless the façade shall include projecting or recessed portales, setbacks, or other design elements;
b. The combined door and window area in any publicly visible façade shall not exceed forty percent of the total area of the façade except for doors or windows located under a portal. No door or window in a publicly visible façade shall be located nearer than three (3) feet from the corner of the façade;
c. No cantilevers shall be permitted except over projecting vigas, beams, or wood corbels, or as part of the roof treatment described below;

d. No less than eighty percent of the surface area of any publicly visible façade shall be adobe finish, or stucco simulating adobe finish. The balance of the publicly visible façade, except as above, may be of natural stone, wood, brick, tile, terra cotta, or other material, subject to approval as hereinafter provided for building permits;
e. The publicly visible façade of any building and of any adjoining walls shall, except as otherwise provided, be of one color, which color shall simulate a light earth or dark earth color, matte or dull finish, and of relatively smooth texture. Facade surfaces under portales may be of contrasting or complementary colors. Windows, doors, and portals on publicly visible portions of the building and walls shall be of one of the old Santa Fe styles, except that buildings with portals may have larger plate glass areas for windows under portals only. Deep window recesses are characteristic
f. Flat roofs shall have not more than thirty (30) inches overhang.

City of Santa Fe, New Mexico

200 Lincoln Avenue, P.O. Box 909, Santa Fe, NM 87504-0909
www.santafenm.gov

Alan Webber, Mayor

Councilors:
Signe I. Lindell, Mayor Pro Tem, District 1
Renee Villarreal, District 1
Peter N. Ives, District 2
Carol Romero-Wirth, District 2
Roman "Tiger" Abeyta, District 3
Chris Rivera, District 3
Mike Harris, District 4
JoAnne Vigil Coppler, District 4

PROJECT DESCRIPTION: Historic status review and designation of primary façades, if applicable, for all residential structures in the Plaza del Monte Subdivision, except those reviewed for historic status in Case #H-17-098A (122, 124, 125, 126, and garages south of 126 Camino Santiago).

Case number: **H-19-019**
Project Type: HDRB

PROJECT LOCATION (S): 101, 102, 103, 105, 106, 109, 110, 111, 113, 114, 115, 117, 118, 119, 120, 121 Camino Santiago and 104, 105, 107, 109, 111, 116/120 Camino Matias

PROJECT NAMES:

OW – Plaza del Monte LLC	8814 Horizon Blvd. Suite 400	Albuquerque, NM 87113
AG – Lloyd and Associates	321 West San Francisco Street Suit A	Santa Fe, NM 87501

BOARD ACTION

This is to certify that the Historic Districts Review Board (HDRB) acted on the HDRB-initiated status review for Plaza del Monte at their hearing on June 25, 2019. The decision of the Board was to assign "Contributing" historic status to all structures except 118 Camino Santiago and 116/120 Camino Matias, to which they assigned "Non-contributing" historic status. Please see the attached table for detailed actions and primary façade designations. The Board further acted to direct staff to bring forward an evaluation of Plaza del Monte for possible designation as a historic compound. For further information please call 955-6605.

Sincerely,

Lisa Roach
Planner Manager, Historic Preservation Division

NOTE: Applicant can use this action letter to apply for construction permit, but the permit shall not be released until the end of the appeal period which starts on the date of filing of the Findings and Conclusions in the City Clerk's office (SFCC 14-3.17(D)). Your permit will be denied if any changes on plans that were not approved by the HDRB or if conditions of approval are not met. **Please attach copies of this letter to all sets when submitting for construction permits.**

Attachment: Table of Historic Status and Primary Façade Designations for Plaza del Monte

Designations of Historic Status and Primary Façades at Plaza del Monte (Case H-19-019)

Address	Historic Status	Primary Façade(s)	Basis for Status
101 Camino Santiago	Contributing	South (1)	Because the structure is a good example of Mid-Century Modern Santa Fe Style (portal extension and timber posts as character defining features) and because of its association with Plaza del Monte, a master planned community by architects Clark and Register
102 Camino Santiago	Contributing	West (1) & South (2)	Because the structure is a good example of Mid-Century Modern Santa Fe Style (combined portal and carport as character defining feature) and because of its association with Plaza del Monte, a master planned community by architects Clark and Register
103 Camino Santiago	Contributing	South (1)	Because the structure is a good example of Mid-Century Modern Santa Fe Style (L-plan, portal, carport, and front door side lights as character defining features) and because of its association with Plaza del Monte, a master planned community by architects Clark and Register
105 Camino Santiago	Contributing	South (1)	Because the structure is a good example of Mid-Century Modern Santa Fe Style (massing blocks at either end and overall quality of the architecture as character defining) and because of its association with Plaza del Monte, a master planned community by architects Clark and Register
106 Camino Santiago	Contributing	North (2) & East (1)	Because the structure is a good example of Mid-Century Modern Santa Fe Style and because of its association with Plaza del Monte, a master planned community by architects Clark and Register
109 Camino Santiago	Contributing	South (1-5)	Because the structure is a good example of Mid-Century Modern Santa Fe Style, because of its association with Plaza del Monte, a master planned community, and because it is a good example of Phillipe Register's work
110/112 Camino Santiago	Contributing	South (5) & West (2, 3, 4)	Because the structure is a good example of Mid-Century Modern Santa Fe Style and because of its association with Plaza del Monte, a master planned community by architects Clark and Register

Address	Historic Status	Primary Façade(s)	Basis for Status
111 Camino Santiago	Contributing	South (1)	Because the structure is a good example of Mid-Century Modern Santa Fe Style and because of its association with Plaza del Monte, a master planned community by architects Clark and Register
113/115 Camino Santiago	Contributing	South (1, 2, 3)	Because the structure is approximately 50 years old, because it is a good example of Mid-Century Modern Santa Fe Style (flagstone paving, vertical window pattern, and blocked massing on ends as character defining) and because of its association with Plaza del Monte, a master planned community by architects Clark and Register
114 Camino Santiago	Contributing	North (1) & East (2)	Because the structure is approximately 50 years old, because it is a good example of Mid-Century Modern Santa Fe Style (carport and double posts as character defining) and because of its association with Plaza del Monte, a master planned community by architects Clark and Register
117 Camino Santiago	Contributing	East (1 & 2) and South (7)	Because the structure is exemplary in the evolution of design in Plaza del Monte and of Philippe Register's efforts to comply with the historic district design standards in a modernist expression, and because of its associations with Plaza del Monte and with Mid-Century Santa Fe Style
118 Camino Santiago	Non-contributing	N/A	Due to age and lack of character-defining features
119 Camino Santiago	Contributing	East (1) & South (4)	Because the structure is a good example of Mid-Century Modern Santa Fe Style (low projecting roofline and south fin wall as character defining) and because of its association with Plaza del Monte, a master planned community by architects Clark and Register
120 Camino Santiago	Contributing	West (1 & 2)	Because the structure is a good example of Mid-Century Modern Santa Fe Style (carport, storage rooms, and massing as character defining) and because of its association with Plaza del Monte, a master planned community by architects Clark and Register

Address	Historic Status	Primary Façade(s)	Basis for Status
121 Camino Santiago	Contributing	East (1) & South (4)	Because the structure is a good example of Mid-Century Modern Santa Fe Style and because of its association with Plaza del Monte, a master planned community by architects Clark and Register
104 Camino Matias	Contributing	North (1 & 4)	Because the structure is a good example of Mid-Century Modern Santa Fe Style and because of its association with Plaza del Monte, a master planned community by architects Clark and Register
105 Camino Matias	Contributing	North (3)	Because of its age, because of its association with the Alison James School, because it is a typical example of post-WWII construction, and because it along with 107, 109 and 111 Camino Matias anchor the orientation of Plaza del Monte around a common space.
107 Camino Matias	Contributing	North (3)	Because of its age, because of its association with the Alison James School, because it is a typical example of post-WWII construction, and because it along with 105, 109 and 111 Camino Matias anchor the orientation of Plaza del Monte around a common space.
109 Camino Matias	Contributing	North (3)	Because of its age, because of its association with the Alison James School, because it is a typical example of post-WWII construction, and because it along with 105, 107 and 111 Camino Matias anchor the orientation of Plaza del Monte around a common space.
111 Camino Matias	Contributing	West (1) & South (2)	Because of its age, because of its association with the Alison James School and because of Plaza del Monte-era additions that provide visual association with the planned development.
116/120 Camino Matias	Non-contributing	N/A	Because of extensive disharmonious additions.

Santa Fe
Mapping the City Different

104 Camino Matias





Legend

- City Limits
- Address Points
- Building Footprint
- Roads
- Major Roads
- Santa Fe County Parcels
- Santa Fe River
- Rail Road

Notes

© Latitude Geographics Group Ltd.

47.0 0 23.51 47.0 Feet

WGS_1984_Web_Mercator_Auxiliary_Sphere

This map is a user generated static output from an Internet mapping site and is for reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable.
THIS MAP IS NOT TO BE USED FOR NAVIGATION

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 1	104 Camino Matias *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693073, -105.935289

10. Photo Information Negative: John Murphey View of: Front, north elevation, facing northeast.

11. Brief Description of the Property:

One of the first units to be constructed at Plaza del Monte, 104 Camino Matias is an L-shaped dwelling with a combined carport and portal. The approximately 1,143-square-foot, flat-roof structure holds two bedrooms. The bedrooms are placed in a wing forming the north end of the residence. Its front (west) façade presents a Spanish-Pueblo Revival plan with its cubic, battered mass and viga-roofed portal. Unlike many houses in the development, the carport plays a secondary role on the façade. The single-bay structure, arranged behind the portal, is less exuberant in its display of wood elements. The bedroom mass is fenestrated with small, rectangular windows; the remaining elevations have windows arranged in a more traditional pattern. The windows are mostly aluminum casement units. The portal elevation is painted white. A line of vigas runs along the top of the wall. It is supported by shiplap wood girders resting on round posts with zappos-type corbels. The house was constructed in c.1965. It represents the closest interpretation of the original 1960 Kenneth S. Clark and Philippe Register template design for the development.

12. Who uses the property? Residence

13. Construction Date: c.1965
_x_Known _x_ Source: aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1)

(Continued from other side)

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

20. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Frederick H. Dawson, who is listed as a tenant in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing _x_ Non-contributing __ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Contributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte Residence 1	104 Camino Matias *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Casement	Aluminum	1-1	6
Casement	Aluminum	1-1F-1F-1	1
[?]	[?]	[?]	1

*Because of storm covers, the operation and material is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ View Light	Wood	2
Single-Leaf	Flush	Wood	2
Sliding	Patio	Aluminum	1

12. Chimneys
One, stucco-clad, south exposure

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: __ _x_ No known modifications

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other:

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 1	2. Location: 104 Camino Matias *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Constructed before 1968, and representing the original Clark and Register design template for the Plaza del Monte retirement homes, the house is a good example of the "Santa Fe style." For this reason, the recommendation is to designate 104 Camino Matias a Contributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* __NRHP __SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 1	2. Location: 104 Camino Matias *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 1	2. Location: 104 Camino Matias *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street and south elevations, facing southeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 1	2. Location: 104 Camino Matias *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Photo 2: Street and north elevations, facing southeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2*		
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 1	2. Location: 104 Camino Matias *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Photo 3: East elevation, facing northwest.

CITY OF SANTA FE

HISTORIC PRELIMINARY ZONING REVIEW
PLUD-20

PURPOSE AND INSTRUCTIONS

Prior to a public hearing in front of the Historic District Review Board (HDRB) all applicants must obtain Historic Districts Preliminary Zoning Review (HPZR) from the Current Planning Division. The HPZR does not grant zoning approval. Following design approval from the HDRB, final zoning review will be performed at the time of building permit.

Applicants must submit complete and accurate information for review. Incomplete submittals will not be processed. All HPZR requests must be submitted to Current Planning via zoningcounter@santafenm.gov

PROJECT INFORMATION

Date 6/30/2026	Property Owner of Record VICKI MONTANO-TORRES		
Applicant/Agent Contact	BERNIE ROMERO		
Site Address	104 CAMINO MATIAS		
Suite or Space #	Subdivision Name PLAZA DEL MONTE		
Lot # 29	Block #	Total Roof Area (square feet) 2244 SQ FT	
Lot Coverage % 23.2	Lot Size (square feet) 9661 SQ. FT		
Proposed Construction Description	REPLACE EXIST'G EXTERIOR DOORS & WINDOWS. INSTALL NEW PORTAL AT REAR OF RESIDENCE & INTERIOR REMODEL.		
The following documents are required for review as applicable:	☒ Legal Lot of Record ☑ Building Plans ☑ Existing site plan w/ setbacks ☒ Proposed site plan w/ setbacks ☒ Existing & Proposed Elevations ☒ Development Plan		
Zoning District	Overlay Districts ☐ Escarpment ☐ Flood Plain ☐ Other		
Proposed Setbacks	Front 25'	Rear 15'	Left Side 5' / Right Side 5'
Required Setbacks	Front 25'	Rear 15'	Left Side 5' / Right Side 5'
Proposed Height 11'-4"	Max Height	Parking Required 2 / Provided 2	Bike Parking / Provided

Historic Planning Case Manager LANI McCAULLEY

If you selected "other," please write in the name of your case manager.

ADDITIONAL SUBMITALS (IF APPLICABLE)

☐ Y ☒ N Affidavit Restricting Use of an Accessory Structure Containing a Bathroom or Kitchen		
☐ Y ☒ N Setback Affidavit and Agreement		
☐ Y ☒ N Site Visibility Triangle	☐ Y ☒ N Escarpment Slope Analysis	☐ Y ☒ N Flood Plain Grading Plan

This hereby certifies that the information provided for preliminary zoning review is accurate and will not be modified without consulting the Land Use Department staff prior to HDRB hearing.

☐ Owner ☒ Applicant ☒ Agent

To Be Completed by Land Use Department Staff

PRELIMINARY REVIEW STATUS

☒ Preliminarily Reviewed	☐ Reviewed w/ conditions	☐ Denied
Comments/Conditions		
Preliminary Zoning Review completed by Benjamin Pfeifer	Date 07/09/2026	
Preliminary Zoning Review # 2026-012777		

Bernie Romero

11 Caminito Santera

Santa Fe, New Mexico 87505

August 7, 2026

Historic Preservation Division

Santa Fe, New Mexico 87504

RE: Additions and renovations

104 Camino Matias

Santa Fe, New Mexico 87501

On behalf of Vicki Montano-Torres,

I request approval for modifications and renovations of her residence.

The residence was built in approximately 1967 and there are no records of any renovations or modifications of the existing residence.

The existing residence heated area is 1170 sq. ft. with an attached carport/storage of 636 sq. ft. The total roofed area is 1806 sq. ft. and is situated on a lot of 9661 sq. ft. The existing lot coverage is 18.7%.

Propose a new portal addition of 438 sq. ft on the east side of the residence and a new 35 sq. ft. entry under the existing west portal. The proposed portal will not increase the height of the existing residence.

Propose to repair base of rotted wood portal columns.

The existing west facing entry door will be moved to south wall of the new entry area. All construction for the new entry will be under the existing portal and will have minimal impact on the west elevation.

Propose removing all existing exterior windows and doors and replacing them with same size clad/wood units in bronze color cladding. The existing door on the south wall of dining area will be removed and

infilled with framing and stucco. The east wall of the residence will have two doors to the portal and the existing windows will be replaced with same size units bronze clad.

The proposed east portal will match the existing west portal/carport in-kind. The stain finish will be medium walnut to match with new corbels to match existing.

Propose a new stuccoed c.m.u. yardwall on the east side of the residence to run from the residence to the existing yardwall at the rear property line of the residence. There will be no gate on the yardwall.

Propose to install new LAHABRA “Adobe” cementitious color coat on the entire residence. Portal colorcoat to be LAHABRA “Colonial white.

Propose to install new heating/cooling condensers at rear yard area, screened from neighbors by the new yardwall.

Respectfully submitted,

Bernie Romero

Bernie Romero

11 Caminito Santera

Santa Fe, New Mexico 87505

July 13, 2026

Historic Preservation Division

Santa Fe, New Mexico 87504

RE: Additions and renovations

104 Camino Matias

Santa Fe, New Mexico 87501

On behalf of Vicki Montano-Torres,

I request approval of two exceptions for the renovation of her residence.

Exception 1:

Propose to replace existing exterior wood sliding windows and existing doors.

Do not damage the character of the district:

The existing windows are old style sliding windows and are very difficult to open. The tracks for the sliding window units are damaged and even with a little muscle will not open. The windows will be replaced with new clad bronze windows in-kind and will not damage or change the character of the district.

Are required to prevent hardship to the applicant or an injury to the public welfare:

The existing sliding mechanisms are damaged beyond repair and the owner requests replacing them due to the difficulty of operating them.

Strengthen the unique heterogeneous character of the City by providing a full range of design options to ensure that residents can continue to reside within the historic districts:

Replacing the existing windows with in-kind windows does not damage the unique heterogeneous character of the City and the elevations and openings will not be changed.

Exception 2:

Propose to install new entry area under the existing portal.

Do not damage the character of the district:

The new entry addition will be constructed under the existing portal. The entire portal will remain, surrounding the proposed entry area which will remain similar to existing and the change to the existing character will be minimal.

Are required to prevent hardship to the applicant or an injury to the public welfare:

There is no hardship for the new entry installation. Mt client would like to make this change to enhance the entry and make it more handicap accessible.

Strengthen the unique heterogeneous character of the City by providing a full range of design options to ensure that residents can continue to reside within the historic districts:

Installing a new entry under the existing portal will not damage the unique heterogeneous character of the City and the west elevation with the new entry will enhance the residence.

Respectfully submitted,

Bernie Romero

104 CAMINO MATIAS- WEST ELEVATION

104 CAMINO MATIAS- WEST ELEVATION- CARPORT

104 CAMINO MATIAS- WEST ELEVATION

104 CAMINO MATIAS-
WEST ELEVATION

104 CAMINO MATIAS-
WEST ELEVATION

104 CAMINO MATIAS-SOUTH ELEVATION

104 CAMINO MATIAS-EAST ELEVATION

104 CAMINO MATIAS- EAST ELEVATION

104 CAMINO MATIAS- NORTH ELEVATION

104 CAMINO MATIAS- NORTH ELEVATION

Pepperidge SW 3017

Spicewood SW 3021

Shagbark SW 3001

Rock Rose SW 3016

Buckthorn SW 3003

Caribou SW 3025

Body: Belvedere Tan SW 3002 (Solid Rain Refresh™)

Smoke Tree SW 3019

Belvedere Tan SW 3002

Sand Castle SW 3006

Semi-Transparent STAIN COLOR

The WoodScapes® Polyurethane Semi-Transparent Stain is available in a wide variety of colors including 24 stains*.

White Birch SW 3503

Baja Beige SW 3509

Crossroads SW 35

Spice Chest

LAHABRA

SOUTHWEST STUCCO COLOR COLLECTION

116-ADOBE

106-BUCKSKIN

115-COTTONWOOD

125-LA LUZ


100-COLONIAL WHITE


113-DOVE GRAY

114-DESERT ROSE

212-MADERA

135-SAHARA

197-LA MORENA

101-NAVAJO WHITE

117-FAWN

COLORS ARE EXCLUSIVE FOR APPROVED SOUTHWEST CUSTOMERS.

Color plays a vitally important role in the world in which we live. When we look at art, fashion, food, and interior décor we immediately experience an emotion from the colors projected. The color that is used on the exteriors of homes and buildings has this same effect – selecting the right stucco color accentuates building design and complements the other elements such as brick, stone veneers, siding, and trim.

NOTE: Due to variations in finishes and textures, it is strongly recommended that a physical sample be obtained in the color and texture desired for appraisal prior to ordering material. Apply a sample of the finish to the substrate being used before proceeding with the application and wet cure per application instructions. LaHabra is not responsible for color correctness of applied finish. Color must be verified and approved by owner prior to application.

Our most current General Sales Conditions shall apply.
Please consult the Data Sheet prior to any use and processing
© 2024 Sika Corporation, 14000997 rev 06/2024

Sika Corporation
201 Polito Avenue
Lyndhurst, NJ 07071 USA
Customer Service (800) 433-9517
Technical Service (800) 243-6739
usa.sika.com/lahabra

STUCCO COLOR

BUILDING TRUST



SITE DATA:

LOT SIZE= 9661 SQ. FT.
EXISTING TOTAL ROOFED AREA= 1806 SQ. FT.
EXISTING HEATED AREA= 1170 SQ. FT.
CARPORT/STORAGE= 636 SQ. FT.
TOTAL EXISTING LOT COVERAGE= 18.7%

EXISTING SITE PLAN

1"=10'-0"

N

5' 10' 20'

7/13/2026

ROMERO DESIGN & DRAFTING
BERNIE ROMERO (505)-670-9936 CELL (505)-988-2431 HOME
11 CAMINITO SANTERRA SANTA FE, NEW MEXICO 87505

EXISTING SITE PLAN

REVISED	DATE:	BY:	DRAWN BY:	DATE:	JOB NAME:	JOB #
			BR	P.Z.R. SUBMITTAL 6/30/2025	MONTANO-TORRES ADDITION AND RENOVATIONS 104 CAMINO MATIAS SANTA FE, NEW MEXICO	

A1



SITE DATA:

LOT SIZE= 9661 SQ. FT.
TOTAL EXISTING HEATED AREA= 1170 SQ. FT.
TOTAL EXISTING CARPORT/STORAGE/PORTAL= 636 SQ. FT.
EXISTING TOTAL ROOFED AREA= 1806 SQ. FT.
PROPOSED NEW PORTAL= 370 SQ.FT.
TOTAL NEW AND EXISTING ROOFED AREA= 2176 SQ. FT.
PROPOSED LOT COVERAGE= 22.5%

PROPOSED SITE PLAN

1"=10'-0"

N

5' 10' 20'

ROMERO DESIGN & DRAFTING
BERNIE ROMERO (505)-670-9936 CELL (505)-988-2431 HOME
11 CAMINITO SANTERRA SANTA FE, NEW MEXICO 87505

PROPOSED SITE PLAN

REVISED:	DATE:	BY:	DRAWN BY:	DATE:	JOB NAME:	JOB #
			BR	P.Z.R. SUBMITTAL 6/30/2025	MONTANO-TORRES ADDITION AND RENOVATIONS 104 CAMINO MATIAS SANTA FE, NEW MEXICO	

A2

7/13/2026



EXISTING FLOOR PLAN

1/4"= 1'-0"

0 2 5 10

7/13/2026

ROMERO DESIGN & DRAFTING
BERNIE ROMERO (505)-670-9936 CELL (505)-988-2431 HOME
11 CAMINITO SANTERRA SANTA FE, NEW MEXICO 87505

EXISTING FLOOR PLAN

REVISED:	DATE:	BY:	DRAWN BY:	DATE:	JOB NAME:	JOB #
			BR	P.Z.R. SUBMITTAL 6/30/2026	MONTANO-TORRES ADDITION AND RENOVATIONS 104 CAMINO MATIAS SANTA FE, NEW MEXICO	

A3

DOOR SCHEDULE					
NO.	DESCRIPTION	W.	H.	T.	REMARKS
1	ANDERSEN FRENCH DOOR	3'-0"	6'-8"	1-3/4"	
2	ANDERSEN FRENCH SLIDER	5'-0"	6'-8"	1-3/4"	
3	ANDERSEN FRENCH SLIDER	5'-0"	6'-8"	1-3/4"	
4	OWNER SELECT	2'-0"	6'-8"	1-3/4"	

WINDOW SCHEDULE				
NO.	MANUFACTURER & CATALOG NUMBER	ROUGH OPENING (W x H)	HD. HGT.	QTY.
A	ANDERSEN BRONZE CLAD SLIDER	4'-8 3/4" x 2'-2 3/4"-VERIFY	EXIST'G	2
B	ANDERSEN BRONZE CLAD SLIDER	3'-6 3/4" x 4'-2 3/4"-VERIFY	EXIST'G	2
C	ANDERSEN BRONZE CLAD SLIDER	3'-8 3/4" x 4'-2 3/4"-VERIFY	EXIST'G	1
D	ANDERSEN BRONZE CLAD SLIDER	5'-8 3/4" x 2'-10 3/4"-VERIFY	EXIST'G	1
E	ANDERSEN BRONZE CLAD SLIDER	1'-10 3/4" x 5'-2 3/4"-VERIFY	EXIST'G	1
F	ANDERSEN BRONZE CLAD SLIDER	4'-8 3/4" x 3'-8 3/4"-VERIFY	EXIST'G	1
G	ANDERSEN BRONZE CLAD SLIDER	3'-8 3/4" x 2'-2 3/4"-VERIFY	EXIST'G	1
H	ANDERSEN BRONZE CLAD SLIDER	4'-6 3/4" x 2'-2 3/4"-VERIFY	EXIST'G	2

NOTE:
ALL EXTERIOR DOORS AND WINDOWS TO BE BRONZE.



PROPOSED FLOOR PLAN

1/4"= 1'-0"

0 2 5 10

7/13/2026

ROMERO DESIGN & DRAFTING
BERNIE ROMERO (505)-670-9936 CELL (505)-988-2431 HOME
11 CAMINITO SANTERRA SANTA FE, NEW MEXICO 87505

PROPOSED FLOOR PLAN

REVISED:	DATE:	BY:	DRAWN BY:	DATE:	JOB NAME:	JOB #
			BR	P.Z.R. SUBMITTAL 6/30/2025	MONTANO-TORRES ADDITION AND RENOVATIONS 104 CAMINO MATIAS SANTA FE, NEW MEXICO	

A4



EXISTING WEST ELEVATION

1/4"= 1'-0"

0 2 5 10



PROPOSED WEST ELEVATION

1/4"= 1'-0"

0 2 5 10

7/13/2026

ROMERO DESIGN & DRAFTING

BERNIE ROMERO (505)-670-9936 CELL (505)-988-2431 HOME
11 CAMINITO SANTERRA SANTA FE, NEW MEXICO 87505

SITE PLAN

REVISED:	DATE:	BY:	DRAWN BY:	DATE:	JOB NAME:	JOB #
			BR	P_Z_R. SUBMITTAL 6/30/2025	MONTANO-TORRES ADDITION AND RENOVATIONS 104 CAMINO MATIAS SANTA FE, NEW MEXICO	

A5



EXISTING EAST ELEVATION

1/4"= 1'-0"

0 2 5 10



PROPOSED EAST ELEVATION

1/4"= 1'-0"

0 2 5 10

7/13/2026

ROMERO
DESIGN &
DRAFTING
BERNIE ROMERO (505)-670-9936 CELL (505)-988-2431 HOME
11 CAMINITO SANTERRA SANTA FE, NEW MEXICO 87505

EXISTING & PROPOSED EAST ELEVATIONS

REVISED	DATE	BY:	DRAWN BY:	DATE:	JOB NAME:	JOB #
			BR	P.Z.R. SUBMITTAL 6/30/2026	MONTANO-TORRES ADDITION AND RENOVATIONS 104 CAMINO MATIAS SANTA FE, NEW MEXICO	

A6



EXISTING SOUTH ELEVATION

1/4"= 1'-0"

0 2 5 10



PROPOSED SOUTH ELEVATION

1/4"= 1'-0"

0 2 5 10

7/13/2026

ROMERO
DESIGN &
DRAFTING

BERNIE ROMERO (505)-670-9936 CELL (505)-988-2431 HOME
11 CAMINITO SANTERRA SANTA FE, NEW MEXICO 87505

EXISTING & PROPOSED SOUTH ELEVATIONS

REVISES	DATE:	BY:	DRAWN BY:	DATE:	JOB NAME	JOB #
			BR	P.Z.R. SUBMITTAL 6/30/2026	MONTANO-TORRES ADDITION AND RENOVATIONS 104 CAMINO MATIAS SANTA FE, NEW MEXICO	

A7



EXISTING NORTH ELEVATION

1/4"= 1'-0"

0 2 5 10



PROPOSED NORTH ELEVATION

1/4"= 1'-0"

0 2 5 10

7/13/2026

ROMERO
DESIGN &
DRAFTING
BERNIE ROMERO (505)-670-9936 CELL (505)-988-2431 HOME
11 CAMINITO SANTERRA SANTA FE, NEW MEXICO 87505

EXISTING & PROPOSED NORTH ELEVATIONS

REVISED:	DATE:	BY:	DRAWN BY:	DATE:	JOB NAME:	JOB #
			BR	P.Z.R. SUBMITTAL 6/30/2026	MONTANO-TORRES ADDITION AND RENOVATIONS 104 CAMINO MATIAS SANTA FE, NEW MEXICO	

A8

Subdivision Survey prepared for
Plaza Del Monte, LLC of
Tract B on Camino Santiago and Camino Matias, City of Santa Fe, NM

SUBDIVISION SURVEY ON TRACT B LAST DESCRIBED ON SURVEY FILED
IN SANTA FE COUNTY CLERK PLAT BOOK 785, PAGES 023-024, INSTRUMENT NO. 1759,727
SAID TRACT B LYING AND BEING WITHIN THE SANTA FE GRANT
PROJECTED SECTION 24, T17N, R9E, NMPM
TRACT B IS LOCATED ON CAMINO SANTIAGO AND CAMINO MATIAS IN THE CITY OF SANTA FE
COUNTY OF SANTA FE, STATE OF NEW MEXICO

THE PURPOSE OF THE IS PLAT IS TO SUBDIVIDE
TRACT B INTO 30 INDIVIDUAL LOTS



ARMIJO SURVEYS LLC
PAUL A. ARMIJO NMPLS, NO. 15604
P. O. BOX 24436, SANTA FE, NM 87502-4436
PH: (505) 471-1553 FAX: (505) 471-1625

SUBDIVISION SURVEY PREPARED FOR
PLAZA DEL MONTE, LLC
TRACT B, CAMINO SANTIAGO/CAMINO MATIAS, SANTA FE, NM

DRAWN BY: P.A.A. DATE: JULY 2021
SURVEY NO.: 2021158 SHEET NO. 1 OF 3

SHEET 1 OF 3

OWNERS CONSENT

THE UNDERSIGNED OWNER(S) DOES HEREBY CONSENT TO THE SUBDIVISION OF LANDS AS SHOWN HEREON. THIS SURVEY AND SUBDIVISION IS BEING MADE WITH MY/OUR FREE CONSENT AND IS IN ACCORDANCE WITH MY/OUR DESIRES AND WISHES. ALL EASEMENTS ARE HEREBY GRANTED AS SHOWN. THESE LANDS LIE WITHIN THE PLANNING AND PLATTING JURISDICTION THE CITY OF SANTA FE, STATE OF NEW MEXICO.

PLAZA DEL MONTE, LLC — DATE 10/4/22

STATE OF NEW MEXICO } SS
COUNTY OF SANTA FE }

THIS INSTRUMENT WAS ACKNOWLEDGED BEFORE ME ON [illegible] E. LUCEY COOK

NOTARY PUBLIC [illegible] MY COMMISSION EXPIRES [illegible]

COLLEEN COOK
Notary Public - State of New Mexico
Commission # 1117268
My Comm. Expires October 3, 2025

SURVEYS NOTES

1. RECORD LOT DATA SHOWN HEREON TAKEN FROM THE RECORD SURVEY ENTITLED "LOT PLAT OF SUBDIVISION OF THE LANDS OF THE UNITED PRESBYTERIAN CHURCH U.S.A. CITY OF SANTA FE, NEW MEXICO", BY RUE, SMITH PAPPE NO. 0850 AND SMITH, WILLIAMSON & ASSOC., FILED ON MARCH 16, 1990, IN SANTA FE COUNTY CLERK PLAT BOOK 297, PAGE 013, AS INSTRUMENT NO. 701,830.

2. ADDITIONAL DATA TAKEN FROM THE RECORD SURVEY ENTITLED "ALTA/ACSM LAND TITLE SURVEY FOR CAMINO A STATE REALTY & DEVELOPMENT ADVISORS, LLC", BY PAUL A. ARMIJO NMPLS NO. 15604 AND ARMIJO SURVEYS, INC. FILED IN THE RECORDS OF THE SANTA FE COUNTY CLERK, ON MARCH 17, 2015, AS PLAT BOOK 769, PAGES 023 & 024 AS INSTRUMENT NO. 1736,781.

3. THE HORIZONTAL BASIS OF BEARING FOR THIS 2021 SURVEY IS THE PHOENIX BETWEEN THE SET CORNER MONUMENTS FOUND AT THE NORTHWEST AND SOUTHEAST CORNERS OF TRACT B AND REFERENCED TO THE RECORD BEARING S76°30'26"E 656.34', MEASURED BY THIS 2021 SURVEY: S76°30'26"E 654.39', SEE MAP FOR DETAILS.

4. DATES OF FIELD SURVEY: JUNE 16-18, 2021 AND JULY 8-9, 2021.

5. SPECIAL WARRANTY DEED AMERITITLEMAN MEDICAL SERVICES TO PLAZA DEL MONTE LLC FILED ON MARCH 30, 2015, AS INSTRUMENT NO. 1759,960.

6. SEE SHEET NO. 2 FOR SUBDIVISION SURVEY MAP.

UTILITY LOCATE DATA

1. UTILITY LOCATES: NMAN LOCATE REQUEST TICKET CONFIRMATION NO. 31123261B.
ORDER DATE: 06/23/2021.

SURVEYORS CERTIFICATE

I, PAUL A. ARMIJO, CERTIFY THAT I AM NEW MEXICO REGISTERED PROFESSIONAL SURVEYOR NO. 15604, AND THAT THIS PLAT WAS PREPARED BY ME OR UNDER MY DIRECTION AND IS BASED ON AN ACTUAL FIELD SURVEY PERFORMED UNDER MY DIRECTION BY ARMIJO SURVEYS, LLC, AND IS, TO THE BEST OF MY KNOWLEDGE AND BELIEF, CORRECT AND CONFORMS TO THE MINIMUM STANDARDS OF THE STANDARDS FOR LAND SURVEYS IN NEW MEXICO AS ADOPTED BY THE NEW MEXICO STATE BOARD OF REGISTRATION FOR PROFESSIONAL ENGINEERS AND PROFESSIONAL SURVEYORS.

Paul A. Armijo OCT. 4, 2022
PAUL A. ARMIJO, NMPLS NO. 15604

PAUL A. ARMIJO
NEW MEXICO
15604
PROFESSIONAL SURVEYOR

UTILITY COMPANY SIGNOFF

CITY OF SANTA FE WASTEWATER DEPARTMENT — DATE 9-22-23

QWEST CORP. d/b/a CENTURYLINK QC — DATE 10-19-2022

PUBLIC SERVICE COMPANY OF NEW MEXICO — DATE 09/19/2022

Frank St Aram — QUESTAR GAS COMPANY — DATE 9/19/2022

Doug Dale — DIRECT CABLE TV — DATE 9/19/2022

PUBLIC UTILITY EASEMENTS

Public utility easements shown on this plat are granted for the common and joint use of:

A. Public Service Company of New Mexico corporation, (PNM Electric) for installation, maintenance, and service of overhead and underground electrical lines, transformers, and other equipment, and related facilities reasonably necessary to provide electrical services.

B. New Mexico Gas Company (NMGCo) for installation, maintenance, and service of natural gas lines, valves and other equipment and facilities reasonably necessary to provide natural gas services.

C. Lumen Technologies for the installation, maintenance, and service of such lines, cables, and other related equipment and facilities reasonably necessary to provide Cable services.

D. Xfinity Video Services, LLC for the installation, maintenance, and service of such lines, cables, and other related equipment and facilities reasonably necessary to provide Cable services.

E. City of Santa Fe (public water and private sewer) for the installation, maintenance, and service of lines and other equipment and facilities reasonably necessary to provide services for Public Utility Easements. Granted is the right to build, rebuild, construct, reconstruct, locate, relocate, place the easement, change, remove, replace, modify, renew, operate and maintain facilities for purposes described above, together with free access in, over, and over said easements, with the right and privilege of going upon, over and across adjoining lands of Grantor for the purposes set forth herein and with the right to utilize the right of way and easement for ingress and egress of Grantee, including without restricting the generality thereof, for vehicle transportation, with the right and privilege to trim and remove trees, shrubs, or bushes which interfere with the purposes set forth herein. No building, sign, pool (aboveground or underground), hot tub, carports or wood pool decking, or other structure shall be erected or constructed on said easements, nor shall any soil be added or deposited thereon.

Easements for electric, transformers/switchgears, as installed, shall extend ten (10) feet in front of transformer/switchgear doors and five (5) feet on each side.

F. QWEST CORP. d/b/a CENTURYLINK QC for installation, maintenance and service of all buried and aerial communication lines and other related equipment and facilities reasonably necessary to provide communication services, including but not limited to stone grouted pedestals and closures. Plat does not grant approval for easement purposes only, the display of a plat does not in any way guarantee telephone service to the subdivision.

UTILITY DISCLAIMER

In approving this plat, Public Service Company of New Mexico (PNM) and New Mexico Gas Company(NMGCo) did not conduct a title search of the properties shown hereon. Consequently, PNM and NMGCo do not waive or release any easement or easement right which may have been granted by prior plat, replat, or other document and which are not shown on this plat.

RECORDING INFORMATION FOR COUNTY CLERK
SFC ASSESSOR DOC NO. FOR TRACT B 1-251-008-209-121
OWNER PLAZA DEL MONTE LLC
SPECIAL WARRANTY DEED, INSTRUMENT NO. 1759,960
LOCATION: TRACT B, PLAT BOOK 785, PAGES 023-024 LYING AND BEING SITUATE WITHIN THE SANTA FE GRANT PROJECTED SECTION 24, T17N, R9E, NMPM ADDRESS: CAMINO SANTIAGO AND CAMINO MATIAS CITY OF SANTA FE, COUNTY OF SANTA FE STATE OF NEW MEXICO

CITY OF SANTA FE REVIEW

CITY PLANNER — DATE 11/3/22

CITY ENGINEER FOR LAND USE — DATE 11/3/22

PUBLIC WORKS DEPT. — DATE 11/3/2022

COUNTY TREASURER — DATE 11/4/2022

CITY OF SANTA FE PLANNING COMMISSION APPROVAL

CASE NO. 2021-4545

CASE NO. 2021-4543

APPROVED AT THEIR MEETING OF

[illegible] — DATE 11/3/2022
PLANNING COMMISSION CHAIR

[illegible] — DATE 11/9/22
PLANNING COMMISSION SECRETARY

DEVELOPMENT NOTES:

1. PROPERTY DEVELOPMENT IS SUBJECT TO COMPLY WITH APPLICABLE PROVISIONS OF CHAPTER 14, LAND DEVELOPMENT CODE, SFCC 2001 AND SUBSEQUENT AMENDMENTS.

2. PROPERTY DEVELOPMENT IS REQUIRED TO COMPLY WITH THE PROVISIONS OF EACH CITY OF SANTA FE ORDINANCE ADOPTED PRIOR TO PLAT AND/OR DEVELOPMENT PLAN RECORDED WITH THE COUNTY CLERK OR SUBMITTAL FOR A BUILDING PERMIT APPLICATION THAT MODIFIES AND PREEMPTS OF CHAPTER 14, LAND DEVELOPMENT CODE, SFCC 2001 AND SUBSEQUENT AMENDMENTS.

3. BUILDABLE AREA FOR VACANT PARCELS WILL BE DETERMINED AT THE TIME OF BUILDING PERMIT APPLICATION AS DETAILED IN THE LAND DEVELOPMENT CODE. ANY BUILDABLE AREAS SHOWN HEREON ARE SUBJECT TO REVISIONS FOR CODE REQUIREMENTS.

4. THE DEVELOPMENT SHALL COMPLY WITH THE MOST CURRENT REQUIREMENTS OF THE AMERICANS WITH DISABILITIES ACT (ADA) FOR ALL INFRASTRUCTURE IMPROVEMENTS.

5. THESE LOTS ARE SERVED BY A PRIVATE ON-SITE SEWER SYSTEM AND ARE SUBJECT TO THE AGREEMENT FOR MAINTENANCE OF SHARED AMENITIES, ACCESS EASEMENTS AND DRAINAGE FACILITIES RECORDED IN THE RECORDS OF SANTA FE COUNTY ON [illegible], 2021, AS INSTRUMENT NO. 2021[illegible].

Document No. 2003738

STATE OF NEW MEXICO
COUNTY OF SANTA FE
I hereby certify that this instrument was filed
for record on the 23 day of DEC A.D. 2022
at 8:30 o'clock A.M. and was duly recorded in
Book 895 Page 20-24 of the Records of
Santa Fe County
Witness my hand and Seal of Office
KATHERINE CLARK
County Clerk, Santa Fe County, New Mexico
By: [illegible] Deputy


SUBDIVISION PLAT
08/03/2022
ARNOLD SURVEYS, INC.
SHEET 2 OF 3
PARK TRACT A
3,442 SF.
CAMINO SANTIAGO
S70°50'28"E 854.34'
N20°09'17"E 385.39'
N69°23'00"E 113.47'
S83°47'06"E 73.64'
S17°22'04"E 465.81'
S70°50'28"E 854.34'
LINE DATA
L1=S40°05'42"E 24.80'
HORIZONTAL SCALE: 1"=30'


DESCRIPTION OVERLAY
08/03/2022
ARNICO SURVEYS INC.
PAUL A. ARNICO, N.M.P.S. NO. 13634
P. O. BOX 24435, SANTA FE, NM 87502-9435
PH. (505) 471-1555 FAX. (505) 471-1825
DRAWN BY: _____ EXISTING DATA DATE: MAR. 2015
JOB NO.: N/A SHEET NO.: N/A
SHEET 3 OF 3
HORIZONTAL SCALE: 1"=30'
NOTES:
1. DATA IN PARENTHESIS (R) OR (M) IS RECORD DATA TAKEN FROM REFERENCE DOCUMENT NO. 1 LISTED ON SHEET 1 OF THIS NEW SURVEY.
2. DATA SHOWN ON ADJOINING PROPERTIES IS BACKGROUND OR INFORMATIONAL IN NATURE AND IS NOT A SURVEY OF ADJOINING PROPERTIES.
PARK TRACT A
CAMINO SANTIAGO
ACCESS, UTILITY & DRAINAGE EASEMENT, WIDTH VARIES
10' WIDE PRIVATE SEWER EASEMENT
10' WIDE WATER LINE EASEMENT
UTILITY EASEMENT
15' WIDE H2 BUILD ZONE
LEGEND
SURVEY MONUMENT FOUND
SURVEY MONUMENT SET 1/2" REBAR W/CAP STAMPED ARNICO 13634
CALCULATED POINT NOT SET
SANITARY SEWER MANHOLE COVER
STREET LAMP POLE
UTILITY POLE
UTILITY POLE WITH GUY WIRE ANCHOR
UTILITY POLE WITH GUY WIRE ANCHOR
ELECTRIC METER
GAS METER
WATER METER
ELECTRIC UTILITY MARKER
TELEPHONE UTILITY MARKER
TELEPHONE UTILITY PEDESTAL
ELECTRIC JUNCTION BOX
CROSS DRAIN DROP INLET GRATE
STUCCO WALL
DRIVEWAY ACCESS AS
TREE TRUNK(S) DENOTED
CURRENT ROOF CHARGE OR PORTAL ROOF CHARGE
NEW MEASURED DATA IN THIS NEW SURVEY
RECORD DATA BY OTHER
NEW TO TITLE BOUNDARY EXCEPTION NUMBER
LINE DATA
L1 - S40°05'52.5"E 24.80'
SURVEY TIE LINE DATA
T31 - S36°38'32"E 8.59'
SEE SHEET 1
Page 97 of 1444

PLAZA DEL MONTE DEVELOPMENT PLAN TRACT B ON CAMINO SANTIAGO AND CAMINO MATIAS

VICINITY MAP



GENERAL NOTES

1. METES AND BOUNDS DESCRIPTIONS OF LOTS, ROADWAYS, DRAINAGE, UTILITY, AND ACCESS RIGHTS-OF-WAYS AND/OR EASEMENTS ARE DESCRIBED ON THE SUBDIVISION PLAT.
2. PROPERTY DEVELOPMENT IS REQUIRED TO COMPLY WITH APPLICABLE PROVISIONS OF CHAPTER 14, LAND DEVELOPMENT CODE, SFCC 1987 AND SUBSEQUENT AMENDMENTS.
3. PER SFCC § 14-7.2, TABLE 14-7.2-1, BUILDING SETBACKS ARE ESTABLISHED BY THIS DEVELOPMENT PLAN AND SHALL APPLY TO ALL PERMANENT STRUCTURES, INCLUDING ACCESSORY STRUCTURES.
4. NEW STRUCTURES AND/OR ADDITIONS ARE NOT LIMITED TO STRUCTURES SHOWN HEREON, AND FUTURE DEVELOPMENT IS SUBJECT TO ESTABLISHED BUILDING SETBACKS, APPLICABLE PROVISIONS OF SFCC CHAPTER 14, AND BUILDING PERMIT REQUIREMENTS.
5. SITE AND INDIVIDUAL LOT FENCING LOCATIONS TO BE DETERMINED AT TIME OF BUILDING PERMIT.
6. DEVELOPMENT OF LOT 23 IS SUBJECT TO THE WATER ALLOCATION AND/OR WATER OFFSET RETROFIT PROVISIONS OF ORDINANCE NO. 2002-29 AND RESOLUTION 2003-56 AT THE TIME OF PERMIT APPLICATION OR WATER HOOKUP REQUEST.
7. ACCESSIBILITY FEATURE DESIGN WITHIN THE SITE SHALL COMPLY WITH NEW MEXICO DEPARTMENT OF TRANSPORTATION (NMDOT) PEDESTRIAN ACCESS ROUTE DETAILS (SERIAL 608) OR MUST DEMONSTRATE COMPLIANCE WITH APPLICABLE AMERICANS WITH DISABILITIES ACT (ADA) REGULATIONS BY OTHER MEANS AS PROVIDED IN THE PERMITTED CONSTRUCTION DOCUMENTS.
8. FENCES, WALLS OR OTHER OBSTRUCTIONS SHALL NOT BE PLACED OR CONSTRUCTED ACROSS PUBLIC SANITARY SEWER EASEMENTS.
9. ALL PROPOSED CHANGES TO THE APPROVED IMPROVEMENT PLANS SHALL RECEIVE PRIOR APPROVAL BY THE CITY OF SANTA FE PLANNING AND LAND USE DEPARTMENT BEFORE CONSTRUCTION.
10. PROPERTY DEVELOPMENT IS REQUIRED TO COMPLY WITH THE PROVISIONS OF THE COSF ORDINANCE NO. 2008-02 (IMPACT FEES).
11. PROPERTY DEVELOPMENT, BOTH PUBLIC AND PRIVATE OWNERSHIP, SHALL COMPLY WITH THE COSF ORDINANCE NO. 2002-20 (TERRAIN AND STORMWATER MANAGEMENT) AT THE TIME OF BUILDING PERMIT APPLICATION.
12. PROPERTY DEVELOPMENT IS SUBJECT TO THE PROVISIONS OF SECTION 14-8.4(F)(5), "PLANT MATERIAL STANDARDS," WHEREIN PRESERVATION OF SIGNIFICANT TREES IS REQUIRED.
13. FIRE DEPARTMENT ACCESS SHALL BE MAINTAINED THROUGHOUT ALL DEVELOPMENT CONSTRUCTION PHASES AS PER IFC 1410.1.
14. PERMANENT TRAFFIC CONTROL DEVICES SHALL BE INSTALLED PER APPROVED PLAN BY THE DEVELOPER.
15. PRIVATE ROADS AND ASSOCIATED PARKING WITHIN THE SUBDIVISION SHALL BE MAINTAINED BY THE PLAZA DEL MONTE HOMEOWNER'S ASSOCIATION.
16. THIS DEVELOPMENT LIES WITHIN THE DOWNTOWN AND EASTSIDE HISTORIC DISTRICT.
17. THIS DEVELOPMENT LIES WITHIN THE SUBURBAN ARCHAEOLOGICAL REVIEW DISTRICT.
18. THE PROPOSED SANITARY SEWER SYSTEM SERVING THIS DEVELOPMENT IS PRIVATE AND WILL NOT BE MAINTAINED OR OWNED BY THE CITY OF SANTA FE.

DUST CONTROL NOTES

ALL ON-SITE SOIL DISTURBING CONSTRUCTION ACTIVITIES SHALL BE ADDRESSED AND PROVIDE MEASURES TO MITIGATE OR CONTROL DUST FROM BEING TRANSPORTED OFFSITE AND POLLUTING NEIGHBORING PROPERTIES.

ANY PERSON, OWNER, CONTRACTOR OR OPERATOR WHO CONDUCTS EARTHMOVING AND/OR DUST GENERATING ACTIVITIES IS RESPONSIBLE FOR IMPLEMENTING BEST MANAGEMENT PRACTICES (BMPs) IN ORDER TO MITIGATE OFF-PROPERTY TRANSPORT OF FUGITIVE DUST EMISSIONS.

A PLAN, OR STORMWATER POLLUTION PREVENTION PLAN (SWPPP) WHEN APPLICABLE, LISTING THE BEST MANAGEMENT PRACTICES SHALL BE PROVIDED TO THE CITY ENGINEER, OR HIS/HER DESIGNEE, FOR REVIEW AND APPROVAL. THE APPROVED BMPs SHALL BE APPLIED TO THE GRADED AND/OR DISTURBED SOIL IN ORDER TO STABILIZE THE SITE.

THE INITIAL BMP SHALL ADDRESS HOW THE CONTRACTOR WILL MINIMIZE THE AMOUNT OF DISTURBED SOIL AND HOW THE CONTRACTOR WILL STABILIZE THE DISTURBED SURFACE AREA EXPOSED TO WIND OR VEHICLE TRAFFIC DURING CONSTRUCTION.

SOME BMPs SHALL INCLUDE:

- THE REDUCTION OF VEHICLE SPEEDS: ESTABLISH A MAXIMUM SPEED LIMIT OR INSTALL TRAFFIC CALMING DEVICES TO REDUCE SPEEDS TO A RATE TO MITIGATE OFF-PROPERTY TRANSPORT OF DUST ENTRAINED BY VEHICLES.
- THE MINIMIZATION OF DROP HEIGHT: DRIVERS AND OPERATORS SHALL UNLOAD TRUCK BEDS AND LOADER OR EXCAVATOR BUCKETS SLOWLY AND MINIMIZE DROP HEIGHT OF MATERIALS TO THE LOWEST HEIGHT POSSIBLE, INCLUDING SCREENING OPERATIONS.
- HIGH WINDS RESTRICTION: TEMPORARILY HALT WORK ACTIVITIES DURING HIGH WIND EVENTS GREATER THAN 30 MPH IF OPERATIONS WOULD RESULT IN OFF-PROPERTY TRANSPORT.
- RESTRICT ACCESS: RESTRICT ACCESS TO THE WORK AREA TO ONLY AUTHORIZED VEHICLES AND PERSONNEL.

IN THE EVENT THE ABOVE PRACTICES ARE INEFFECTIVE TO PREVENT OFF PROPERTY TRANSPORT, THE PERSON, OWNER OR OPERATOR SHALL USE ONE OR MORE OF THE FOLLOWING BMPs:

- WET SUPPRESSION: APPLY WATER TO DISTURBED SOIL SURFACES, BACKFILL MATERIALS, SCREENINGS AND OTHER DUST GENERATING OPERATIONS AS NECESSARY AND APPROPRIATE CONSIDERING CURRENT WEATHER CONDITIONS, AND PREVENT WATER USED FOR DUST CONTROL FROM ENTERING ANY PUBLIC RIGHT-OF-WAY, STORM WATER DRAINAGE FACILITY, OR WATERCOURSE.
- WIND BARRIER: CONSTRUCT A FENCE OR OTHER TYPE OF WIND BARRIER TO PREVENT WIND EROSION OF THE GRADED OR DISTURBED SURFACE.
- VEGETATION: PLANT VEGETATION APPROPRIATE FOR RETAINING SOILS OR CREATING A WIND BREAK.
- SURFACE ROUGHENING: STABILIZE AN ACTIVE CONSTRUCTION AREA DURING PERIODS OF INACTIVITY WHEN VEGETATION CANNOT BE IMMEDIATELY ESTABLISHED.
- COVER: INSTALL COVER MATERIALS SUCH AS TACKIFIERS, EROSION CONTROL BLANKETS, GRAVEL, VEGETATION (WHEN APPROPRIATE), COLD-MILLINGS, ETC. DURING PERIODS OF INACTIVITY AND PROPERLY ANCHOR THE COVER.
- SOIL RETENTION: STABILIZE DISTURBED OR EXPOSED SOIL SURFACE AREAS THAT WILL BE INACTIVE FOR MORE THAN 30 DAYS OR WHILE VEGETATION IS BEING ESTABLISHED.

AFFIDAVIT

KNOW ALL PERSONS BY THESE PRESENTS THAT THE UNDERSIGNED OWNERS HAVE CAUSED THIS FINAL DEVELOPMENT PLAN TO BE PREPARED, ALL THAT APPEARS ON THIS PLAN IS MADE WITH THE FREE CONSENT AND IN ACCORDANCE WITH THE DESIRES OF THE OWNER.

8/8/23

PLAZA DEL MONTE, LLC

THE FOREGOING WAS SWORN, ACKNOWLEDGED AND SUBSCRIBED BEFORE ME BY E. Larry Lujan
THIS 25th DAY OF October, 2022.

NOTARY PUBLIC

October 6, 2023
MY COMMISSION EXPIRES

STORMWATER AGREEMENT

PROPERTY OWNER(S) HEREBY AGREE THAT ALL STORMWATER EASEMENTS AND ANY OTHER DRAINAGE IMPROVEMENTS ON PRIVATE PROPERTY WILL BE MAINTAINED AND KEPT FULLY FUNCTIONAL AS ORIGINALLY DESIGNED AND CONSTRUCTED WITHIN PRIVATE PROPERTY BOUNDARIES; THE CITY HAS THE RIGHT OF ACCESS FOR INSPECTION OF SAID IMPROVEMENTS; THE CITY HAS THE RIGHT, IN THE EVENT OF DRAINAGE FACILITY MAINTENANCE DEFICIENCY AND AFTER TEN (10) DAYS WRITTEN NOTICE TO THE RESPECTIVE PROPERTY OWNER, TO ENTER AND RESTORE FULL FUNCTIONAL CAPACITY OF THE DRAINAGE IMPROVEMENTS AND TO LIEN THE PROPERTY FOR BOTH DIRECT AND INDIRECT COSTS ASSOCIATED WITH SUCH WORK. BY SIGNATURE AFFIXED TO THIS INSTRUMENT, THE PROPERTY OWNER(S) APPROVE AND AGREE THAT THIS AGREEMENT IS BINDING PERPETUALLY, RUNNING WITH THE LAND, ON PRESENT AND FUTURE OWNERS, HEIRS, AND ASSIGNS.

PLAZA DEL MONTE, LLC

THE FOREGOING WAS SWORN, ACKNOWLEDGED AND SUBSCRIBED BEFORE ME BY E. Larry Lujan
THIS 21st DAY OF November, 2022.

NOTARY PUBLIC

10.5.2023
MY COMMISSION EXPIRES

DRAINAGE FACILITY MAINTENANCE SCHEDULE SHALL BE AS FOLLOWS:

1. ALL DRAINAGE FACILITIES SHALL BE MAINTAINED BY THE HOME OWNERS ASSOCIATION.
2. THE DRAINAGE FACILITIES MAINTENANCE SCHEDULE SHALL BE AS FOLLOWS: MARCH 15TH, SEPTEMBER 15TH AND AFTER STORMS OF ONE INCH OR GREATER.
   a. FLUSH ALL CULVERTS AND DRAIN PIPES TO REMOVE SEDIMENT AND VEGETATION.
   b. FLUSH STORM DRAIN MANHOLES AND DROP INLETS.
   c. IF SEDIMENT IN PONDS IS DEEPER THAN 6 INCHES, REMOVE AND RESEED WITH NATIVE GRASSES.
   d. CHECK POND DRAINS AND RIP-RAP INTEGRITY. REPAIR AS NECESSARY.
   e. CHECK FOR SOIL EROSION WITHIN AND AROUND ALL SWALES, FILL SLOPES, CUT SLOPES AND RETAINING WALLS. UNSTABILIZED SOILS SHALL BE STABILIZED WITH VEGETATION, ROCK PLATING OR EROSION MATS.

DEVELOPMENT PLAN SIGNATURES

APPROVED BY THE SANTA FE PLANNING COMMISSION AT THEIR MEETING ON JANUARY 6, 2022
AS PLANNED DEVELOPMENT PRELIM CASE # 2021-4546 & 2021-4548

PLANNING & LAND USE DIRECTOR — DATE 11/4/2022

PLANNING COMMISSION SECRETARY — DATE 12/9/22

REVIEWED BY THE CITY OF SANTA FE

CITY ATTORNEY — DATE 11/7/22

CITY MANAGER FOR CLERK'S USE — DATE 11/14/22

COUNTY OF SANTA FE } ss
STATE OF NEW MEXICO }

I HEREBY CERTIFY THAT THIS INSTRUMENT WAS FILED FOR RECORD ON THIS ____ DAY OF _____ A.D. 20__ AT _____ O'CLOCK ___ M. AND WAS DULY RECORDED IN BOOK ____ PAGE ____ OF THE RECORDS OF SANTA FE COUNTY.

WITNESS MY HAND AND SEAL OF OFFICE
KATHARINE CLARK
COUNTY CLERK, SANTA FE COUNTY, NM

DEPUTY

CITY REVIEW

DEPARTMENT	SIGNOFF	DATE
WASTEWATER MANAGEMENT DIV.	SIGNATURE ON FILE	
WATER RESOURCES		
STREETS DIV.		
TRAFFIC DIV.		
FIRE		
LANDSCAPE		
SUBDIVISION ENGINEER		

2021-4546
CASE # 2021-4548

CITY USE ONLY

JENKINSGAVIN
LAND DEVELOPMENT PROJECT MANAGEMENT
130 Grant Avenue, Suite 101
Santa Fe, NM 87501
505 820-7444

FINAL DEVELOPMENT PLAN AND FINAL SUBDIVISION PLAT SUBMITTAL FOR PLAZA DEL MONTE

DEVELOPMENT PLAN
SHEET 1 OF 2

DATE:	SCALE:	SHEET:
NOVEMBER 2021	N.T.S.	1-1

PLAZA DEL MONTE DEVELOPMENT PLAN
TRACT B ON CAMINO SANTIAGO AND CAMINO MATIAS

NOTE:
THE PROPOSED SANITARY SEWER SYSTEM SERVING THIS DEVELOPMENT IS PRIVATE AND WILL NOT BE MAINTAINED OR OWNED BY THE CITY OF SANTA FE.



PROJECT DATA

SITE AREA: 6.625 ACRES
ZONING: R-29 (RESIDENTIAL)
OVERLAY: DOWNTOWN AND EASTSIDE HISTORIC DISTRICT

DENSITY:
Gross Lot Area = 6.625 acres
100-yr Floodplain = 0.452 acres (19,671 sq ft)
Net Lot Area = 6.173 acres
Maximum Allowable Density = 6.173 acres x 10 DU/Acre = 61 DU
Proposed Density = 30 DU/6.625 acres = 4.5 DU/Acre

LOT COVERAGE:
Maximum Allowable Lot Coverage = 40%, per SFCC Table 14-7.2-1
Proposed Lot Coverage = Not to exceed 40% per lot

BUILDING SETBACKS: (As established by this Development Plan, per SFCC Table 14-7.2-1)
Front Yard Setback: 7 feet from edge of Access & Utility Easement.
Side Yard Setback: 5 feet from property line for Detached Homes OR
0 feet from property line if adjacent setback is increased to 10 feet.
0 feet from property line for Attached Homes if fire-rated wall is provided.
Garage Setback: 10 feet from edge of Access & Utility Easement, for all lots, except Lot 28, where the setback shall be 3 feet from edge of Access & Utility Easement to accommodate an existing carport. If this carport is demolished, any new garage or carport shall conform to the 10-foot garage setback that applies to the Subdivision.
Rear Setback: 10 feet from property line.

PARKING:
Total Required Parking = 2 off-street spaces per residence
Total Provided Parking = 3 off-street spaces per residence (90 spaces)
Total Required Guest Parking = 0.5 guest spaces per DU x 30 DU = 14 guest spaces
Total Provided Guest Parking = 15 guest spaces

COMMON OPEN SPACE:
Required = None required
Provided = 9,412 sq ft (Pocket Park – Tract A)

LEGEND
- PROPOSED SIDEWALK
- EXISTING SIDEWALK
- PROPOSED DRIVEWAY
- PROPOSED LOT LINE

DEVELOPMENT PLAN
SCALE: 1" = 40'

0 20 40 80
SCALE: 1" = 40'

CITY REVIEW			
DEPARTMENT	SIGNATURE	SIGN OFF	DATE
WASTEWATER MANAGEMENT DIV.			
WATER SERVICES			
STREETS DIV.			
TRAFFIC ENG.			
FIRE			
LANDSCAPE			
SUBDIVISION ENGINEER			

2021-4548
CASE # 2021-4548
CITY USE ONLY

JENKINSGAVIN
LAND DEVELOPMENT MANAGEMENT
130 Grant Avenue, Suite 101
Santa Fe, NM 87501
505.820.7444

FINAL DEVELOPMENT PLAN AND FINAL SUBDIVISION PLAT SUBMITTAL FOR PLAZA DEL MONTE

DEVELOPMENT PLAN
SHEET 2 OF 2

DATE:	SCALE:	SHEET:
NOVEMBER 2021	1" = 40'	2-2

RPA & Associates, LLC.

PRESERVING OUR HISTORY

508 Ortega Rd NW Los Ranchos de Albuquerque, NM 87114
P.O. Box 10328 Albuquerque, NM 87184
505-379-7900
rpahistoric@gmail.com

TO Bernie Romero Design & Drafting
11 Caminito Santera
Santa Fe, NM 87505
bpromero07@gmail.com

JOB	DATE
104 Camino Mathias	07/28/2026

LOCATION	DESCRIPTION
WEST	
A	54” x 25” HORIZONTAL SLIDER 1-LT ALL WOOD WITH ALUMINUM STORM
DR #1	36” x 80” LH INSWING 10-PANEL ALL WOOD DOOR
B	88” x 50” TWIN HORIZONTAL SLIDERS 1-LT ALL WOOD WITH ALUMINUM STORM
C	42” x 50” HORIZONTAL SLIDER 1-LT ALL WOOD WITH ALUMINUM STORM
SOUTH	
D	66” x 33” HORIZONTAL SLIDER 1-LT ALL WOOD WITH ALUMINUM STORM
DR #2	32” x 80” LH INSWING DOOR BIRCH WITH HALF LITE, 3-LITE KIT ALL WOOD
NORTH	
DR #3	48” x 82” TWIN LH OUTSWING T&G ALL WOOD DOOR (2-24”)
DR #4	48” x 82” TWIN RH OUTSWING T&G ALL WOOD DOOR (2-24”)
EAST	
DR #5	72” x 82” SLIDING GLASS DOOR 1-LT MILL FINISH ALL ALUMINUM
NORTH	
E	20” x 60” FIXED WINDOW 1-LT ALL WOOD STOPPED IN GLASS
EAST	
F	53” x 42” HORIZONTAL SLIDER 1-LT ALL WOOD WITH ALUMINUM STORM
G	42” x 24” HORIZONTAL SLIDER 1-LT ALL WOOD WITH ALUMINUM STORM
H	54” x 25” HORIZONTAL SLIDER 1-LT ALL WOOD WITH ALUMINUM STORM
NORTH	
I	108” x 25” TWIN HORIZONTAL SLIDER 1-LT ALL WOOD WITH ALUMINUM
J	54” x 25” HORIZONTAL SLIDER 1-LT ALL WOOD WITH ALUMINUM

In closing, my professional opinion is as follows:

Windows A, B, C, D, F, G, H, I, and J are historic windows however the units are unrestorable. The window units are 1950 +/- Andersen horizontal gliding windows. The tracks, pins, sash rods, and locks are not available anymore therefore the windows cannot be made to operate correctly or seal.

Window E is non-historic.

Doors 1, 2, 3, 4, and 5 are non-historic.

My recommendation is to replace the windows with casement units with horizontal lites to replicate the steel casements of that era. The doors should be a wood paneled look of that 1950 era.

If you have any questions, please contact me at 505-379-7900.

Assessment prepared by: Ra N. Patterson

RPA & ASSOCIATES, LLC| WINDOW & DOOR CONDITION AND INTEGRITY CODES

CODE	CONDITION AND INTEGRITY CODES
P = PREMIUM	EXTERIOR FINISHES AND SASH, FRAME, AND CASING MEMBER IN PREMIUM OR VERY GOOD CONDITION
	PUTTY GLAZE INTACT
	ONLY COSMECTIC TOUCH-UP, IF NEEDED
S = SATISFACTORY	EXTERIOR FINISHES FADING AND WORN IN PLACES BUT STILL ADHERED TO THE WINDOW MEMBERS.
	PUTTY GLAZING CRACKING BUT INTACT AND ALL SASHES, FRAMES, AND CASING MEMBER WITH LESS THAN 30% – 40% DETERIORATION
F = FAIR	EXTERIOR FINISHES HAVE CRACKED & PEELED, MISSING TO BARE SURFACE
	PUTTY GLAZING CRACKING AND MISSING IN 30% – 40% OF THE SASHES. ALL SASHES, FRAMES, AND CASINGS HAVE SOME MEMBERS 30% – 40% COMPLETELY DETERIORATED
U = UNSATISFACTORY	EXTERIOR FINISHES HAVE COMPLETELY DETERIORATED
	PUTTY GLAZING MOSTLY MISSING – ALL SASHES, FRAMES, AND CASING MEMBERS HAVE MORE THAN 30% - 40% DETERIORATION, BEYOND REPAIR

NOTES:

LABEL	WINDOW & DOOR DESCRIPTION	CONDITION & INTEGRITY CODE	HISTORIC/NON-HISTORIC - AGE
WEST			
A	54" x 25" HORIZONTAL SLIDER 1-LT ALL WOOD WITH ALUMINUM STORM	U	**HISTORIC** – THE TRACKS, PIVOT PINS & HANDLES ARE NOT AVAILABLE TO REPLACE 1950 +/- (ANDERSEN)
DR #1	36" x 80" LH INSWING 10-PANEL ALL WOOD DOOR	S	**NON-HISTORIC** – SIMPSON (1996)
B	88" x 50" TWIN HORIZONTAL SLIDERS ALL WOOD WITH ALUMINUM STORM	U	**HISTORIC** – THE TRACKS, PIVOT PINS & HANDLES ARE NOT AVAILABLE TO REPLACE 1950 +/- (ANDERSEN)
C	42" x 50" HORIZONTAL SLIDER 1-LT ALL WOOD WITH ALUMINUM STORM	U	**HISTORIC** – THE TRACKS, PIVOT PINS & HANDLES ARE NOT AVAILABLE TO REPLACE 1950 +/- (ANDERSEN)
SOUTH			
D	66" x 33" HORIZONTAL ALL WOOD WITH ALUMINUM STORM	U	**HISTORIC** – THE TRACKS, PIVOT PINS & HANDLES ARE NOT AVAILABLE TO REPLACE 1950 +/- (ANDERSEN)
DR #2	32" x 80" LH INSWING DOOR BIRCH WITH HALF LITE 3 LITE KIT ALL WOOD	S	**NON-HISTORIC** – BIRCH DOOR WITH LITE KITE VENEERED (1996)
NORTH			
DR #3	48" x 82" TWIN LH OUTSWING T&G ALL WOOD DOOR	F	**NON-HISTORIC** – SHOP MADE DOORS, MECHANICAL AIR NAILS (1996)
DR #4	48" x 82" TWIN RH OUTSWING T&G ALL WOOD DOOR	F	**NON-HISTORIC** – SHOP MADE DOORS, MECHANICAL AIR NAILS (1996)

NOTES:

LABEL	WINDOW & DOOR DESCRIPTION	CONDITION & INTEGRITY CODE	HISTORIC/NON-HISTORIC – AGE
EAST			
DR #5	72" x 82" SLIDING GLASS DOORS, MILL FINISH, 1-LT ALL ALUMINUM	S	**NON-HISTORIC** – ALENCO MANUFACTURED GLASS DATE 1987
NORTH			
E	20" x 60" FIXED 1-LT ALL WOOD WINDOW STOPPED IN GLASS	F	**NON-HISTORIC** – GLASS DATE 1987, GLAZED
EAST			
F	53" x 42" HORIZONTAL SLIDER 1-LT ALL WOOD WITH ALUMINUM	U	**HISTORIC** – THE TRACKS, PIVOT PINS & HANDLES ARE NOT AVAILABLE TO REPLACE 1950 +/- (ANDERSEN)
G	42" x 24" HORIZONTAL SLIDER 1-LT ALL WOOD WITH ALUMINUM	U	**HISTORIC** – THE TRACKS, PIVOT PINS & HANDLES ARE NOT AVAILABLE TO REPLACE 1950 +/- (ANDERSEN)
H	54" x 25" HORIZONTAL SLIDER 1-LT ALL WOOD WITH ALUMINUM	U	**HISTORIC** – THE TRACKS, PIVOT PINS & HANDLES ARE NOT AVAILABLE TO REPLACE 1950 +/- (ANDERSEN)
NORTH			
I	108" x 25" TWIN HORIZONTAL SLIDER 1-LT ALL WOOD WITH ALUMINUM	U	**HISTORIC** – THE TRACKS, PIVOT PINS & HANDLES ARE NOT AVAILABLE TO REPLACE 1950 +/- (ANDERSEN)
J	54" x 25" HORIZONTAL SLIDER 1-LT ALL WOOD WITH ALUMINUM	U	**HISTORIC** – THE TRACKS, PIVOT PINS & HANDLES ARE NOT AVAILABLE TO REPLACE 1950 +/- (ANDERSEN)

NOTES:

EXISTING FLOOR PLAN



7/15/2026

A3

EXISTING FLOOR PLAN

MONTANO-TORRES ADDITION AND RENOVATIONS

ROMERO DESIGN & DRAFTING

104
Camino
Matias
West
Elevation

West Elevation
Window A.

West Elevation
Door #1.

West Elevation
Window B.

West
Elevation
Window C.

South Elevation
Window
D.

South Elevation
Door #2.

North Elevatiion
Door #3.

North
Elevation
Door #4.

104 Camino Matias
South Carport
Elevation.

East Elevation
Door #5

North Elevation
Window E.

East Elevation
Window F.

East
Elevation
Window G.

East Elevation
Window H.

North Elevation
Window I.

North Elevation
Window J.

104 Camino Matias North Elevation.

104 Camino Matias
Southeast Elevation.

104 Camino
Matias
Northeast
Elevation.

Typical
discontinued
window tracks
and pivots

Typical
discontinued
window
hardware.

104 Camino
Matias
North Carport

City of Santa Fe
Historic Districts Review Board
Findings of Fact and Conclusions of Law

Case #H-19-019
Address – 101, 103, 105, 106, 109, 110, 111, 113, 114, 115, 117, 118, 119, 120, 121 Camino Santiago and 104, 105, 107, 109, 111, 116/120 Camino Matias
Agent's Name – Lloyd and Associates
Owner/Applicant's Name – Plaza del Monte

THIS MATTER came before the Historic Districts Review Board ("Board") for hearing on June 25, 2019.

BACKGROUND

101-121 Camino Santiago and 104-120 Camino Matias are 22 residential structures (hereafter the "Relevant Properties"), which along with 122, 124, 125, 126 and the garages at 126 Camino Santiago, comprise the Plaza del Monte subdivision, located in the Downtown and Eastside Historic District. The historic status for all 27 structures in Plaza del Monte as of the date of this hearing is summarized in the table below:

Address	**Construction Date(s)**	**Current Historic Status**	**Recommended Historic Status In HRE Report**	**HDRB Status Review Case**
101 Camino Santiago	c.1967-68	NC	NC	H-19-019
102 Camino Santiago	c.1965	NC	C	H-19-019
103 Camino Santiago	c.1965	NC	C	H-19-019
105 Camino Santiago (Units 1-4)	1971	NS	NC	H-19-019
106 Camino Santiago	c.1965	NS	C	H-19-019
109 Camino Santiago	c.1965	NS	NC	H-19-019
110 Cam. Santiago / 112 Cam. Matias	c.1962/c.1968	NS	NC	H-19-019
111 Camino Santiago	c.1965	NS	C	H-19-019
113 Camino Santiago	c.1970	NS	NC	H-19-019
114 Camino Santiago	c.1972	NS	NC	H-19-019

115 Camino Santiago	c.1970	NS	NC	H-19-019
117 Camino Santiago	1966-67	NS	NC	H-19-019
118 Camino Santiago	c.1973	NS	NC	H-19-019
119 Camino Santiago	c.1965	NS	NC	H-19-019
120 Camino Santiago	c.1971	NS	NC	H-19-019
121 Camino Santiago	c.1971	NS	NC	H-19-019
122 Camino Santiago	c.1971	NC	-	H-17-098A
124 Camino Santiago	c.1968	C	-	H-17-098A
125 Camino Santiago (Units 1-4)	c.1970	NC	-	H-17-098A
126 Camino Santiago	c.1968	C	-	H-17-098A
Garages south of 126 Cam. Santiago	c.1968/1977	NC	-	H-17-098A
104 Camino Matias	c.1965	NC	C	H-19-019
105 Camino Matias	1950	C	NC	H-19-019
107 Camino Matias	1950	NC	NC	H-19-019
109 Camino Matias	1950	NC	NC	H-19-019
111 Camino Matias	pre-1960 (moved to site)	NC	NC	H-19-019
116/120 Camino Matias	pre-1957 w/c.1984 addition	NC	NC	H-19-019

NS = Non-statused NC = Non-contributing C = Contributing

Historic status for 122, 124, 125, 126 and the garages at 126 Camino Santiago were assigned in Case H-17-098A. An extensive case history was provided as an attachment to the March 28, 2018 Plaza Del Monte Historic Resources Evaluation Report, prepared by John W. Murphey, architectural historian (hereafter, "HRE Report"). On March 26, 2019, the HDRB reviewed the status of seven non-statused structures in Plaza del Monte (105, 113, 114, 115, 118, 120, and 121 Camino Santiago) and voted to assign Contributing status to all seven structures because of their association to the Plaza del Monte, an historic planned subdivision, and because they are representative examples of Mid-century Modern influenced expressions of Santa Fe Style. On April 23, 2019, the HDRB rescinded its motion from the March 26, 2019, hearing regarding

the assignment of contributing historic status for the seven structures, citing insufficient discussion of each individual structure to justify the assignment of contributing status, including failure to designate primary façades. The conditions of this action were in the form of the following directives: 1) that the Land Use Director provide interpretation of the "50-year rule"; 2) that staff provide information regarding applicability of the provisions in the code for "Historic Compound" designation; and 3) that staff bring all remaining structures in Plaza del Monte back to the HDRB for review under a single status review case.

The HRE report was included as an attachment to the staff report for this hearing. At this hearing, Staff presented all structures in Plaza del Monte for which status is not currently assigned for status review, including designation of primary façades as needed for those structures that receive contributing status.

HISTORICAL SUMMARY OF PLAZA DEL MONTE

The Plaza del Monte subdivision, or Plaza del Monte Retirement Center as it was formerly known, was originally conceived in the late 1950s as a communal living center for retired Presbyterian pastors, missionaries, and other church officials. After the Allison-James School closed in 1958, the United Presbyterian Church decided to plan for re-development of the site, and they selected the architectural firm of Kenneth S. Clark and Phillippe Register to design it as a large retirement community. The architects divided the former campus into two parts – the site of the older buildings termed the "South Area" would be developed first with a congregate building, and the "North Area" would be developed in a second phase with individual residences. A preliminary layout of the development in 1960 showed a cul-de-sac arrangement of the homes built around two new streets. Camino Santiago would run along the northern portion of the property, turning south and terminating in a cul-de-sac, and Camino Matias would be a loop off of Camino Santiago running through the older residences at the southern portion of the property.

As is described in the Plaza del Monte Historic Resources Evaluation, Clark and Register conceived the design of the residences as a modified L-plan to which a carport and portal were attached. Architectural details are sympathetic to the Spanish-Pueblo Revival tradition – with room-block stuccoed massing, rounded corners, and vigas, posts and corbels on the portals and carports – but re-framed in mid-century styling. This contemporary influence became more pronounced on the exteriors of the later homes in the development, when the low, horizontal lines of the residences were further accentuated with flat overhanging roofs at times intersected with vertical planes. The latest homes constructed in Plaza del Monte in the early 1970s experimented with angular walls and a more compact massing with carport-dominant façades.

SUMMARIES OF INDIVIDUAL PROPERTIES

101 Camino Santiago: Situated near the east entrance to Plaza del Monte, the house is a roughly 1,332 square foot contemporary residence constructed in 1967-68. In plan, the three-bedroom dwelling has a square form with an attached L-shaped portal and garage, giving it a combined square footprint. It presents to the street a long portal with the roof carrying over the garage. It is fenestrated with aluminum windows, primarily of a sliding operation. A paneled wood door gives entry to the residence at the east end of the portal. The garage entry is fitted with a

recent vinyl overhead door. Cementitious brocade stucco in a peach tone covers the frame building. The roof consists of a mixture of gravel and asphalt material. An interior parapet outlines the dwelling portion of the mass. While contemporary in form, the vigas across the portal give the residence a regional feel.

102 Camino Santiago: One of the earliest units to be constructed at Plaza del Monte, 102 Camino Santiago is a 2,064 square foot dwelling with one addition. The two bedroom, flat-roof house faces Camino Matias. It shows to the street (west) a façade-long portal, continuing at the south end as a single-space carport. The portal is supported by shiplap wood girders resting on round posts with double-ended corbels. Most of the portal façade is painted white. A line of vigas runs along the top of the wall. The elevation is penetrated by two doors and large windows, with the southernmost window not meeting the ordinance in regard to its distance from the corner. The north elevation facing Camino Santiago displays a variety of window openings holding tall metal casements. A shallow overhang supported by short vigas carries over most of the elevation. At the northeast corner is a roomblock-like projection holding the bedroom wing. The rear (east) elevation presents a number of alterations. The largest is a post-1969 addition, over what was a patio. The 380-square-foot addition is fenestrated with modern windows and is sheltered by a parapet-type portal. The house was constructed in c. 1965, and its designer/architect is unverified but assumed to be Kenneth S. Clark and Phillippe Register.

103 Camino Santiago: Roughly 1,533 square feet, the one-story residence is designed as an L-plan form. The plan puts the bedrooms in a cube-like mass, with the remainder of the functions of the house strung along a linear spine. Its façade is defined by a long portal sheltering its entry and patio doors. The east end of the composition terminates as a one-bay carport. A line of vigas runs along the back (north) elevation supporting a short overhang. An exterior chimney breaks through the overhang, rising several feet above the roof. The house is fenestrated with an array of original and replacement aluminum windows. It is entered under the portal through a stylized wood panel door flanked by one set of sidelights. The dwelling's flat roof is outlined by a short parapet; the roof is covered with gravel. The frame structure is finished with cementitious brocade stucco in the buckskin tone. While contemporary in form, vigas used across the portal and the roomblock bedroom wing give the residence a Spanish-Pueblo Revival feel. The house was constructed in c. 1965; its architect/designer is unverified but assumed to be architect Phillippe Register.

105 Camino Santiago (Units 1-4): Forming a long, linear composition, 105 Camino Santiago is one of three apartment buildings erected at Plaza del Monte. The carport-dominated structure works its way down the slope as two L-plan units joined together at the center by a laundry room. The structure is bookended by masses holding the apartments. The larger apartments containing two bedrooms are situated in the projecting roomblocks. The apartments share a party wall at the living room. Spanning between the apartments are the carports and the laundry room. The carports are detailed with a viga-roof structure which continues as a portal along the inner apartments. The rear (north) elevation is divided into small patios. The apartments are entered through wood panel doors; solid wood doors give access to the storage units and the laundry. The original multi-light steel casement windows have been replaced with aluminum units. A short parapet follows the outline of the apartments, and is penetrated on the south, east and west elevations with cut-through metal canals. The frame structure is finished with cementitious

brocade stucco in a peach tone. While contemporary in form, the vigas used across the portales and carports and the cubed apartment masses give the residence a regional feel. The roughly 4,198 square foot apartment building was constructed in 1971, after a design by architect Phillipe Register.

106 Camino Santiago: Likely the third unit to be constructed at Plaza del Monte, 106 Camino Santiago is a 2,031 square foot dwelling with a portal across two elevations (north and east). In plan, it has an L-shaped foundation with an attached carport. The flat-roof dwelling holds three bedrooms confined to a wing at the west end. The rear (south) elevation is focused on a small patio cut into the southwest corner of the home. The southeast corner is terminated by a one-space carport. The two-sided portal runs along the north and east elevations. The structure is made of vigas which sit on square girders held up by round posts with corbels. The portal elevations are painted white and fenestrated with doors on each exposure. Small rectangular windows penetrate the bedroom wing. The remaining windows vary, including large picture and grouped casements and sliding units. The roof is finished with rolled asphalt which carries over the inner parapets. A squat stucco-faced chimney rises at the northeast corner. The house is finished with textured cementitious stucco in a light buckskin tone. The residence was constructed in c.1965. Its designer is unverified but is suspected to be an early Clark and Register design.

109 Camino Santiago: Composed of a series of angled walls, the carport dominated residence was constructed in 1966, after a design by architect Phillipe Register. The house presents to the street a tall and wide carport framed with a viga roof. The west end of the carport is sheltered by a double splayed wall. The angled wall composition is echoed across the east elevation. In plan, the residence is roughly an L with its form obscured by the carport. The approximately 1,220 square foot dwelling holds two bedrooms in a cube-like mass anchoring the east end. Between the bedroom mass and carport is a small enclosed patio and portal sheltering the main entry and a pair of oversized wood windows. The rear (north) elevation has a small viga canopy protecting a patio door. A tapered chimney breaks the wall plane on this elevation. Fenestration consists of mainly aluminum windows. The frame structure is finished with cementitious brocade stucco in the buckskin tone. The contemporary style home was constructed in 1965 and is one of the earliest residences to be constructed in Plaza del Monte.

110 Camino Santiago: Located at the west end of the common area are two residential units which were joined together at some point after 1970. The older unit, addressed as 110 Camino Santiago, takes up the east end of the footprint. Constructed in c.1962, after a design by architect Kenneth S. Clark, it is roughly an L-shaped box with a rear portal and connected carport. The street facing façade (north) is defined by a small recessed entry. The remainder of the façade is divided into rectangular window openings holding sliding units. Smaller, rectangular sliding windows are applied across the east bedroom wing. A shallow portal runs across the rear (south) elevation historically leading to a single-space carport. The portal elevation is fenestrated with a patio door, sliding windows, and a louvered door leading to a utility room. The house is outlined by parapets and finished in buckskin cementitious stucco. It holds three bedrooms. Attached to the west end of the original Clark design is a post-1966 addition. Arranged at a lower height, the approximately 864 square foot appendage is a rectangular box with overhanging eaves and a porch. The addition, most likely designed by architect Phillipe Register, introduces a contemporary vocabulary. A shallow overhang supported by squared rafters carries across the north and south elevations.

Similar beams extend out from the west elevation to create the porch. A tall angular wall rising above the roofline defines its south edge. The addition is fenestrated with a few doors and square window openings, holding single-light metal casements. Most likely occurring with the addition, the carport was widened (or constructed anew) to hold two vehicles. Set back from the addition, the roughly 1,054 square foot structure is supported by a viga and post system.

111 Camino Santiago: Arranged at an east-west orientation, the house is a one-story, approximately 1,616 square foot, flat-roof dwelling erected in c.1965. The dwelling has an L-shaped plan with its two bedrooms confined to a rectangular wing at the west end. The remaining house holds the living room, kitchen and dining area. The front (south) façade is market y along portal which continues across to an attached one-bay carport. The portal shelters the front entry and a sliding patio door. The structure is supported by round poles holding a viga roof. The house is fenestrated with common windows, most of them appearing to be replacement units. It is entered through a raised wood panel door flanked on one side by a sidelight. The rear (north) elevation contains a few windows and a door sheltered by a shallow viga-supported visor. A tapered chimney breaks through the visor, terminating with a terra cotta cap. The frame building is finished in a smooth cementitious stucco in a buckskin tone. The flat roof is covered with asphalt, which carries over the east exposure to the bedroom wing. While contemporary in form, the vigas used across the portal give the residence a Spanish-Pueblo Revival feel. The placement and restrained size of the carport helps maintain the regional tradition. The building was constructed after a design by architect Phillipe Register.

113 Camino Santiago: Sitting on a slight rise, the house shares a party wall at the carport with its neighbor at 115 Camino Santiago. The roughly 1,281 square foot dwelling contains two bedrooms arranged at the front of the structure in a small L-shaped volume. The remainder of the footprint holds the living functions of the house. It presents to the street two roomblock-like volumes penetrated by horizontally oriented aluminum casement windows. A viga-framed carport and short portal terminate the west end of the footprint. The house is entered through a raised wood panel door with a center view light. The rear (north) elevation has a few windows and a sliding glass door. A shallow overhang supported by square wood beams carries across the elevation. The frame dwelling is finished in cementitious peach color stucco worked into a brocade pattern. Tall parapets outline the perimeter of the bedroom wing. The roof is covered in asphalt which carries over the west exposure of the bedroom mass. It was erected in c.1970, and its designer/architect is unknown.

114 Camino Santiago: The house presents to Camino Santiago a traditional design of a cube-like mass projecting from a linear arm. In plan, it is roughly L-shaped with a large connecting carport attached to its southeast corner. The west end holds two bedrooms; the remainder of the footprint contains a large living room, kitchen and utility closet. The south exposure of the bedroom wing is penetrated by sliding glass doors. East of the bedroom wing, the front façade (north) is divided into a recessed entry and a large casement-framed picture window. The entry holds a raised square panel wood door with center view light. It is sheltered by a short overhang resting on vigas. A similar combined picture and casement window is found on the east elevation of the living room. The carport makes up most of the secondary street elevation (north, set back). It is supported by a wood viga-and-post system. The structure shelters a patio door and single raised panel wood door leading to the utility room and storage area. Wood, trough-like canales

penetrate the parapets on the east and west elevations. The roof is covered in rolled asphalt, which carries over the bedroom wing's east exposure. A short stucco-clad chimney topped with a terra cotta cap rises from the center of the roof. Erected in c.1972, the residence was designed by Register, Ross & Burnett Architects.

115 Camino Santiago: Sharing a wall with the dwelling to the east (113 Camino Santiago), the small house contains two bedrooms. The dwelling portion of the building is composed of a rectangular bedroom wing. Attached to this are the living room, kitchen, and a one-space carport. Connecting these elements is a beam portal. Together, both areas hold about 1,290 square feet. The front (south) façade presents a simple canvas of a projecting mass balanced on one end with the void of the carport at the other. In between is the portal with its few window and door openings. The portal is supported by double round posts toped with corbels. The rear (north) elevation contains a few windows and a sliding glass door sheltered by a shallow viga-supported overhang. The windows in the residence are tall, single-light aluminum casements. A raised panel-and-view-light door gives entry to the dwelling under the portal. Short parapets outline the perimeter of the bedroom wing. The roof's asphalt material carries over the east exposure of the parapet. The house was erected in c.1970, and the designer/architect is unknown.

117 Camino Santiago: Tucked into the northwest corner of the development, the house is a single-story, flat-roof dwelling characterized by its viga carport and continuous overhang. In form, its two box-like volumes are arranged in a modified L-plan. The house holds two bedrooms slung along the west wall. A large living room occupies the foot of the L. With its carport included, the house contains 1,422 square feet. The unarticulated flat front façade is penetrated by non-historic casement windows. A wood panel and view light door gives entry to the dwelling under the front portal. The rear (west) elevation is fenestrated with an asymmetrical pattern of tall aluminum casement windows. The frame building is finished with brocade-type stucco rendered in the buckskin color. It was constructed in 1966-67, after a design by architect Phillipe Register. Window replacements appear to have removed the pedimented heads shown on Register's drawings.

118 Camino Santiago: Erected in c.1973, the stucco-over-frame, two bedroom house sits on a rise a the southeast corner of Camino Santiago and Camino Matias. In plan, it is a modified L shaped structure with a carport attached to its front (north) façade. The roughly 1,245 square foot dwelling has its bedrooms segregated to a wing across the west elevation. This volume is taller than the rest of the house and is outline with parapets. The lower volume contains a living room, kitchen and dining area. The north (front) façade is divided between the carport and the north face of the bedroom wing. The single carport is erected over a wood structure supported by round posts. The outside beam continues across the façade, sheltering the front entry. As with the door under the carport, the entry holds a raised square panel unit. The secondary elevations are fenestrated with single-light metal casement windows. The south (rear) elevation has an array of casement windows and an enclosure giving access to the carport. A shallow overhang resting on vigas outlines the elevation. The house is finished with cementitious brocade stucco in a peach pigment. The roof is covered with rolled asphalt, which carries over a portion of the bedroom wing's east exposure. Large, trough-like wood canales pierce the west parapet. It was designed by Register, Ross & Burnet Architects, and is one of the last houses to be completed in Plaza del Monte.

119 Camino Santiago: Arranged slightly above grade, the box-like house is characterized by its continuous portal and horizontal emphasis. In plan it is a compact rectangle framed by angled walls on its north and south exposures. Large windows, a wood panel door and a three-panel sliding glass door appear on the front (east) façade. The rear (west) elevation has double sets of sliding windows and a patio door arranged under an overhang. The house's windows appear to be mostly replacement units. The south end of the dwelling is weighted with a large carport. A tall double splayed wall creates the south exposure. The portal is supported by vigas resting on a square beam. Round posts topped with double ended corbels carry the weight to the floor. The roughly 1,485 square foot structure contains two bedrooms placed along the west wall. The building was constructed in c.1965, after a design by architect Phillipe Register. The main alteration is the removal of most of the angled wall along the northeast corner. Originally, this feature enclosed a small patio.

120 Camino Santiago: The small two bedroom house presents a contemporary carport-dominant design. Located along the east side of Camino Santiago, it sits back from the street. In plan, it is a modified T form with an attached carport projecting from the front (west) façade. Its two bedrooms are confined to a wing making up the north elevation. Higher than the rest of the house, it is outlined with shaped parapets. The parapets are pierced with canales across the north and south exposures. The lower volume, historically containing a living room, kitchen and music room, is faced with a shallow overhang resting on vigas. The overhang shelters sliding glass doors, a window and a pedestrian entry. The secondary elevations are fenestrated with aluminum casement windows. The front (west) elevation is dominated by the carport. The structure is erected over a viga-and-post support system. The portal's outside beam continues across the façade, sheltering the front (west) entry. A wood raised square panel door with a center view light gives entry to the residence. Including its carport and utility room, the building contains 1,804 square feet. The house was built in c.1971 after a design by Register, Ross & Burnet Architects.

121 Camino Santiago: Reflecting a carport-dominant design, the small vernacular dwelling sits at grade on the west side of Camino Santiago. The roughly 1,309 square foot structure holds one bedroom. In plan, it is a compact square enclosed by an angled wall across its south exposure. Unlike most units in Plaza del Monte, it has a low pitched roof. The front (east) façade is dominated by the one-vehicle carport. The remainder of the façade is divided into windows and doors. The windows are uniformly multi-light steel casements in various standard sizes. The gabled north elevation has three identical windows. The rear (west) side of the house has more articulation, expressed through its beamed canopy over a pair of sliding doors. The frame house is finished with heavy brocade cementitious stucco in a peach like color. A shallow square-beam supported overhang runs along the east and west elevations. It was constructed in c.1971, after a design by Register, Ross & Brunet Architects.

104 Camino Matias: One of the first units to be constructed at Plaza del Monte, 104 Camino Matias is an L shaped dwelling with a combined carport and portal. The approximately 1,143 square foot, flat roof structures holds two bedrooms. The bedrooms are placed in a wing forming the north end of the residence. Its front (west) façade presents a Spanish-Pueblo Revival plan, with its cubic, battered mass and viga roofed portal. Unlike many houses in the development, the carport plays a secondary role on the façade. The single-bay structure, arranged behind the portal, is less exuberant in its display of wood elements. The bedroom mass is fenestrated with

small, rectangular windows; the remaining elevations have windows arranged in a more traditional pattern. The windows are mostly aluminum casement units. The portal elevation is painted white. A line of vigas runs along the top of the wall. It is supported by shiplap wood girders resting on round posts with corbels. The house was constructed in c.1965. It represents the closest interpretation of the original 1960 Kenneth S. Clark and Phillipe Register template design for the development.

105 Camino Matias: This small house is one of three units constructed in 1950 for married staff employed by the Allison James School. Arranged in a terrace-like fashion, each unit is a rectangular plan, side-gabled dwelling with an attached garage. The house has a telescoping roof form evident in its north exposure. The roof extends over the walls on the north and south elevations to form small porches. The house is fenestrated with a mix of original and non-historic windows and doors. The windows are terminated with stuccoed concrete sills. Views from the house are oriented north toward the commons area. The north elevation contains a large picture window flanked by casements. Public entry is through an original ½-glass wood door on the south elevation. The garage door is a recent vinyl paneled unit. The roof is covered with three-tab asphalt shingles. Wood fascia has been applied to the north and south roof ends, obscuring (or removing) the original exposed rafters. A short stuccoed chimney rises from the north roof slope. The approximately 1,102 square foot house holds three bedrooms. A non-historic, 220-square foot carport has been erected over the driveway.

107 Camino Matias: This small house is one of three units constructed in 1950 for married staff employed by the Allison James School. Arranged in a terrace-like fashion, each unit is a rectangular plan, side-gabled dwelling with an attached garage. The gabled roof extends over the walls on the north and south elevations to form small porches. The dwelling is fenestrated with a mix of original and non-historic windows, terminated with stuccoed concrete sills. Views from the house are oriented north towards the commons area of Plaza del Monte. The north elevation contains a large picture window flanked by casements. Public entry is through an original ½-glass wood door on the south elevation. Two vertical [solar?] panels have been applied to the south façade. The garage door is recent vinyl paneled unit. The roof is covered with three-tab asphalt shingles. Wood fascia has been applied to the north and south roof ends, obscuring (or removing) the original exposed rafters. A short stuccoed chimney rises from the north roof slope. The house originally had an exposed pedimented entry on the north elevation, which was reduced at some point in depth after 1969. The approximately 1,145 square foot house holds two bedrooms. Its association is with the Allison James School (demolished in 1960) rather than with Plaza del Monte.

109 Camino Matias: This small house is one of three units constructed in 1950 for married staff employed by the Allison James School. Arranged in a terrace-like fashion, each unit is a rectangular plan, side-gabled dwelling with an attached garage. The house has a telescoping roof form evident in its north exposure. The roof extends over the walls on the north and south elevations to form small porches. The front (south) façade reveals an altered composition. At some point after 1960, a 131 square foot addition was appended to the southwest corner creating a sunroom. The dwelling is fenestrated with a mix of original and non-historic windows, which are mostly double hung sash and are terminated with stuccoed concrete sills. Views from the house are oriented north toward the Plaza del Monte commons area. The north elevation contains a large

picture window flanked by casements. Public entry is through an original ½-glass wood door on the south elevation. The garage door is a recent vinyl paneled unit. The roof is covered with three-tab asphalt shingles. Wood fascia has been applied to the north and south roof ends, obscuring (or removing) the original exposed rafters. A short stuccoed chimney rises from the north roof slope. The approximately 1,141 square foot house contains two bedrooms. Its association is with the Allison James School (demolished in 1960) rather than with Plaza del Monte.

111 Camino Matias: Moved to the site prior to 1960, 111 Camino Matias is an altered three bedroom house. The house is arranged on a north-south axis, facing west, and in plan consists of two telescoping gabled sections. To this basic form was added an L-shaped porch and connected carport in c.1966. The medium pitch roofs are covered with asphalt shingles and extended with overhangs. A short stuccoed chimney rises from the ridgeline. Small wood louvers are attached to the gabled ends. The house is fenestrated with an array of original and non-historic windows, recessed from the walls and terminated with concrete sills. The combined porch and carport are supported by a framework of wood girders resting on grouped square posts. The single carport includes double storage units. A short breezeway leads from the carport to a back door. The 1,712 square foot house is finished with textured cementitious stucco in a light buckskin color.

116/120 Camino Matias: The vernacular, two unit residence was erected before 1957 and modified nearly 30 years later with the addition of a cross-gabled entry. The combined residence is aligned along a north-south axis on the west side of Camino Matias. In plan, it is a side-gabled rectangle with a cross-gable appended to its northeast corner. The north unit (120) holds about 1,256 square feet with three bedrooms. A window wall spanning the northeast corner signals its contemporary design. The north elevation under the gable is marred by a c.1984 shed-roof structure enclosing the furnace and water heater. The front façade faces east and is dominated by the non-historic cross gable entry. A recessed entry at the south end leads to 116. The interior, encompassing approximately 939 square feet, is arranged like an apartment. A similar non-historic stuccoed enclosure around the furnace and water heater is attached to the south elevation. The rear (west) elevation of the combined units faces onto a common area. A continuous overhang characterizes this façade. It is penetrated with three sliding glass doors and a mixture of fixed and sliding windows of different sizes. The roof is sheathed with rib metal panels. It is unclear who designed the original house. The c.1984 addition of the cross gable and furnace and water heater enclosures was drawn in Phillipe Register's shop. Built prior to 1958 and substantially modified in the mid-1980s, the historic integrity of the house has been compromised, and the style of the home neither harmonizes with the district nor with Plaza del Monte. As with the other Allison James School-era residences on Camino Matias, the house neither harmonizes with the district nor with Plaza del Monte, and its association is with the Allison James School rather than Plaza del Monte.

FINDINGS OF FACT

1. After conducting a public hearing and having heard from the Applicant and all interested persons, the Board hereby FINDS, as follows:
2. Staff Recommendation: Staff generally agreed with the status recommendations provided in the "Plaza del Monte Historic Resources Evaluation" but deferred to the Board for individual status assignments, per Section 14-5.2(C) Designation of Significant and Contributing Structures.

3. Under Section 14-5.2(A)(1)(a), the general purpose of City's historic preservation ordinance is to preserve the qualities relating to the history of Santa Fe, and a harmonious outward appearance, s in order to preserve property values and attract tourist and residents alike. These purposes are effectuated through the continued existence and preservation of historical areas and buildings.
4. The project is subject to requirements of the following sections of the Santa Fe Land Development Code:
   - Section 14-5.2(D)(9), General Design Standards, Height Pitch Scale and Massing (of any structure);
   - Section 14-5.2(D), General Design Standards; and
   - Section 14-5.2(C), Regulation of Significant and Contributing Structures.
5. The property is located in the following district and subject to the related sections of the Santa Fe Land Development Code:
   - Downtown and Eastside Historic District (Section 14-5.2(E)).
6. Under Section 14-5.2(C)(2)(a), the Board has the authority to designate status as "significant," "contributing," or "noncontributing" based upon the definitions of these terms in Section 14-12.
7. Under Section 14-12.1, a "contributing" structure is defined as "a structure, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a contributing structure is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The contributing structure may have had minor alterations, but its integrity remains."
8. Under Section 14-12.1, a "noncontributing" structure is defined as "a structure, located in an H district, that is less than fifty years old or that does not exhibit sufficient historic integrity to establish and maintain the character of the H District."
9. Under Section 14-12.1, "significant" structure is defined as "a structure located in a historic district that is approximately fifty years old or older, and that embodies distinctive characteristics of a type, period or method of construction. For a structure to be designated as significant, it must retain a high level of historic integrity. A structure may be designated as significant:

   (A) for its association with events or persons that are important on a local, regional, national or global level; or

   (B) if it is listed on or is eligible to be listed on the State Register of Cultural Properties or the National Register of Historic Places.
10. Under Section 14-12.1, a "primary façade" is defined as "[o]ne or more principal faces or elevations of a building with features that define the character of the building's architecture."
11. Under Section 14-5.2(C)(2)(b)(i), the Board is authorized to change the status of a structure or to designate a status for a structure with no status designated.
12. Under Section 14-5.2(C)(2)(b)(ii), a "change in status or the designation of a status shall be based upon an evaluation of data provided through survey or other relevant sources of information and the definitions of 'significant,' 'contributing,' or 'noncontributing.'"
13. On Tuesday June 25, 2019, the Property Owner through their representative, Karl Sommer, provided the City with a letter contesting the Board's proposed adjudication of status of the properties under this case number scheduled for that same day.

14. Under Section 14-5.2(C)(2)(c), the Board may review status designations upon the City's request, provided that Staff must notify the property owner.
15. Pursuant to Section 14-5.2(C)(2)(d), Staff provided notice by mailing a letter dated June 7, 2019, by certified mail return receipt requested, to the property owner and by securely and prominently posting notice posters on June 10, 2019 at the Bishops Lodge entrance and Old Taos Highway entrance, which are visible from a public street.
16. The information contained in the Application and provided in testimony and evidence establishes that all applicable requirements for Board review as herein described have been met.
17. The Board discussed the fact that the HRE report applied the 50-year-rule as a bright-line rule.
18. In the Staff report, Staff provided guidance about how the "50-year Rule" set forth in the National Historic Preservation Act of 1966 has been interpreted and explained that exceptions to this standard have been applied to sites, structures, and places that are less than fifty years old but which have demonstrated "exceptional importance," independent of age.
19. At the hearing, the Board considered Section 14-1.9(G), which provides that "[w]ords and phrases shall be construed according to the common and approved usage of the language, but technical words and phrases that may have acquired a peculiar and appropriate meaning in law shall be construed and understood according to that meaning."
20. The "Summaries of Individual Properties" and the "Historical Summary of Plaza Del Monte" above were originally included in the hearing packet and are incorporated into the findings of fact by reference.
21. Section 14-5.2(K) requires the preservation of a historic compound listed on the City's historic compound register. "Historic compounds shall be comprised of a group of at least three buildings that are historically, physically, and/or spatially related. In order for a compound to be considered historic, at least fifty percent of the buildings in the compound shall be designated contributing, significant or landmark." Section 14-5.2(K)(2)(a).

FINDINGS AS TO SPECIFIC PROPERTIES

101Camino Santiago:

1. This structure was built over 50 years ago between 1967-68. The footprint has not changed since original build, and the windows appear to have their original opening dimensions. This property is an adaptation of mid-century modern, incorporating Santa Fe style into a more contemporary motion and as such, the property is very unique to Santa Fe. The heavy traditional posts and extension of the portal over the garage set this property as a good example of Santa Fe Style. Additionally, this property is associated with Plaza del Monte, a master planned community by significant architects Clark and Register. This structure meets the definition of "contributing" set forth in Section 14-12.1.

102 Camino Santiago:

1. This structure, built over 50 years ago in 1965, is representative of the original be Kenneth S. Clark and Phillippe Register design template for Plaza del Monte residences and is a good example of Mid-Century Santa Fe Style, with the combined portal and carport as a

character defining feature of that style. The Board adopts the recommendation of the HRE that this structure should be designated as contributing.

103 Camino Santiago:

1. This structure, built over 50 years ago in 1965, is representative of Mid-century Santa Fe Style due to its L-plan, portal, carport, and front door side lights, which are character defining features of that style. Additionally, this property is associated with Plaza del Monte, a master planned community by significant architects Clark and Register. The Board adopts the recommendation of the HRE that this structure should be designated as contributing.

105 Camino Santiago (Units 1-4):

1. This structure, constructed approximately 50 years ago in 1971, has large lot masses on the sides with the portal in the middle, which is representative of Mid-Century Modern Santa Fe style. Additionally, this property is associated with Plaza del Monte, a master planned community by significant architects Clark and Register. Further, this property was constructed after a design by significant architect Phillipe Register. This structure meets the definition of "contributing" set forth in Section 14-12.1.

106 Camino Santiago

1. This structure, built over 50 years ago in 1965, is characterized in the HRE Report as a great use of Mid-Century Modern Santa Fe style. Additionally, this property is associated with Plaza del Monte, a master planned community by architects significant Clark and Register. The Board adopts the recommendation of the HRE that this structure should be designated as contributing.

109 Camino Santiago:

1. This structure, built over 50 years ago in 1965, is a good example of Mid-Century Modern Santa Fe Style. Additionally, this property is associated with Plaza del Monte, a master planned community by significant architects Clark and Register. This property is a good example of significant architect Phillipe Register's work. This structure meets the definition of "contributing" set forth in Section 14-12.1.

110/112 Camino Santiago:

1. These structures are greater than 50-years-old: 110 Camino Santiago was constructed circa 1962, and 112 Camino Santiago constructed circa 1966. Additionally, the structures are a good example of Mid-Century Modern Santa Fe Style, having each been designed by significant architects Clark and Register: 110 Camino Santiago having been designed by Kenneth S. Clark and 112 Camino Santiago having been designed by Phillipe Register. Additionally, this property is associated with Plaza del Monte, a master planned community by significant architects Clark and Register. This structure meets the definition of "contributing" set forth in Section 14-12.1.

111 Camino Santiago:

1. The HRE Report recommended designating this structure, constructed over 50 years ago in1965, with contributing status. Additionally, the structure is a good example of Mid-

Century Modern Santa Fe Style and is associated with Plaza del Monte, a master planned community by significant architects Clark and Register. The Board adopts the recommendation of the HRE that this structure should be designated as contributing.

113/115 Camino Santiago:

1. These properties were constructed very close in time, approximately 50 years ago, and were constructed circa 1970. In all likelihood, these properties were planned in early 1969 and construction begun in 1969. These structures are a good example of Mid-Century Modern Santa Fe Style due to the incorporation of defining characteristics of that style into the architecture, including the flagstone paving leading to the carport, vertical window pattern, and blocked massing on the ends. Additionally, the property is associated with Plaza del Monte, a master planned community by significant architects Clark and Register. This structure meets the definition of "contributing" set forth in Section 14-12.1.

114 Camino Santiago:

1. This structure, constructed circa 1972, is approximately 50 years old. This structure is a good example of Mid-Century Modern Santa Fe Style due to its character-defining characteristics, which include a carport and double posts and flagstone leading to the carport. Additionally, the property is associated with Plaza del Monte, a master planned community by significant architects Clark and Register. This structure meets the definition of "contributing" set forth in Section 14-12.1.

117 Camino Santiago:

1. This structure, constructed between 1966-67, is over 50 years old and has a distinct "modified L" or "boomerang" shape. As such, the structure is exemplary in the evolution of design in Plaza del Monte and of Philippe Register's efforts to comply with the historic district design standards while exercising a modernist expression. Further, it is associated with Plaza del Monte and is a compelling example of Mid-Century Santa Fe Style due to how the structure conforms to the site and balances with the landscape, as noted above. This structure meets the definition of "contributing" set forth in Section 14-12.1.

118 Camino Santiago:

1. This structure was the most recently built of the Plaza Del Monte properties reviewed in the HRE report, having been built in 1973. While this property is associated with Plaza del Monte, a master planned community by significant architects Clark and Register, the structure lacks character-defining features. This structure does not meet the definition of "contributing" set forth in Section 14-12.1.

119 Camino Santiago:

1. This structure, constructed in 1965, is over 50 years old and is a clear expression of Mid-Century Modern Santa Fe Style due to the long, low projecting roofline and south fin wall, which are character defining of that style. Further, this structure is associated with Plaza del Monte, a master planned community by significant architects Clark and Register. This structure meets the definition of "contributing" set forth in Section 14-12.1.

120 Camino Santiago:

1. This structure, constructed in 1971, is approximately 50 years old, and is a clear expression of Mid-Century Modern Santa Fe Style due to its character-defining elements, which include the carport, outdoor storage rooms, and overall massing. Further, this structure is associated with Plaza del Monte, a master planned community by significant architects Clark and Register. This structure meets the definition of "contributing" set forth in Section 14-12.1.

121 Camino Santiago:

1. This structure is approximately 50 years old, having been constructed circa 1971. This structure is a good example of Mid-Century Modern Santa Fe Style, utilizing steel casement windows with three divisions, storage cabinets in the carport. Additionally, the property is associated with Plaza del Monte, a master planned community by significant architects Clark and Register. This structure meets the definition of "contributing" set forth in Section 14-12.1.

104 Camino Matias:

1. This structure is over 50 years old, having been constructed in 1965, and is one of the first constructed Plaza Del Monte structures reviewed in the HRE Report. The structure is a good example of Mid-Century Modern Santa Fe Style and is associated with Plaza del Monte, a master planned community by significant architects Clark and Register. The Board adopts the recommendation of the HRE that this structure should be designated as contributing.

105 Camino Matias:

1. This structure is greater than 50 years old and is associated with the Alison James School. The structure's defining characteristics include concrete seals, pitched roof, and the presence of some original doors and windows. The structure exemplifies post-WWII construction. This structure, along with 107, 109 and 111 Camino Matias, anchor the orientation of Plaza del Monte around a common space. This structure meets the definition of "contributing" set forth in Section 14-12.1.

107 Camino Matias:

1. This structure is over 50 years old, having been constructed in 1950. This structure is associated with the Alison James School. The structure's defining characteristics include concrete seals, pitched roof, large picture windows, and other elements that are also reflected in the neighboring properties at 105 and 109 Camino Matias. These structures exemplify post-WWII construction. This structure, along with 105, 109 and 111 Camino Matias, anchor the orientation of Plaza del Monte around a common space. This structure meets the definition of "contributing" set forth in Section 14-12.1.

109 Camino Matias:

1. This structure is over 50 years old, having been constructed in 1950. This structure is associated with the Alison James School. The structure's defining characteristics include concrete seals, pitched roof, and casement windows, and the structure exemplifies post-WWII construction. This structure, along with 105, 107 and 111 Camino Matias, anchor

the orientation of Plaza del Monte around a common space. This structure meets the definition of "contributing" set forth in Section 14-12.1.

111 Camino Matias:

1. This structure was moved to its current property location in 1966, and as such, was constructed over 50 years ago. This structure is associated with the Alison James School and includes Plaza del Monte-era additions that provide visual association with the planned development. This structure meets the definition of "contributing" set forth in Section 14-12.1.

116/120 Camino Matias:

1. This structure is over 50 years old, having been constructed in 1957. However, this structure has been extensively modified from its original construction, and those disharmonious additions result in a lack of defining characteristics. These structures do not meet the definition of "contributing" set forth in Section 14-12.1.

CONCLUSIONS OF LAW

Under the circumstances and given the evidence and testimony submitted during the hearing, the Board acted upon the Application as follows:

1. The Board directs Historic Preservation Division Staff to prepare and present an evaluation of Plaza del Monte for possible designation as a historic compound under Code Section 14-5.2(K).
2. The Board has the authority to initiate, review, and approve the status designation of the Relevant Properties.
3. The Board designates the following statuses and primary façades for the Relevant Properties:

Address	Historic Status	Primary Façade(s)
101 Camino Santiago	Contributing	South (1)
102 Camino Santiago	Contributing	West (1) & South (2)
103 Camino Santiago	Contributing	South (1)
105 Camino Santiago	Contributing	South (1)
106 Camino Santiago	Contributing	North (2) & East (1)
109 Camino Santiago	Contributing	South (1-5)
110/112 Camino Santiago	Contributing	South (5) & West (2, 3, 4)
111 Camino Santiago	Contributing	South (1)
113/115 Camino Santiago	Contributing	South (1, 2, 3)
114 Camino Santiago	Contributing	North (1) & East (2)
117 Camino Santiago	Contributing	East (1 & 2) and South (7)
118 Camino Santiago	Non-contributing	N/A
119 Camino Santiago	Contributing	East (1) & South (4)
120 Camino Santiago	Contributing	West (1 & 2)
121 Camino Santiago	Contributing	East (1) & South (4)
104 Camino Matias	Contributing	North (1 & 4)
105 Camino Matias	Contributing	North (3)
107 Camino Matias	Contributing	North (3)
109 Camino Matias	Contributing	North (3)
111 Camino Matias	Contributing	West (1) & South (2)
116/120 Camino Matias	Non-contributing	N/A

IT IS SO ORDERED ON THIS 13th DAY OF AUGUST 2019, THE HISTORIC DISTRICTS REVIEW BOARD OF THE CITY OF SANTA FE.

_____ _____
Chairperson Date:

FILED:

_____ _____
Yolanda Y. Vigil Date:
City Clerk

APPROVED AS TO FORM:

_____ _____
Gabriel A. Smith Date:
Assistant City Attorney

City of Santa Fe

Agenda

HISTORIC DISTRICTS REVIEW BOARD FIELD TRIP

TUESDAY, June 25, 2019 at 12:00 NOON

HISTORIC PRESERVATION DIVISION, 1st FLOOR CITY HALL

HISTORIC DISTRICTS REVIEW BOARD HEARING

TUESDAY, June 25, 2019 at 5:30 P.M.

CITY COUNCIL CHAMBERS

*****AMENDED*****

CALL TO ORDER

A. ROLL CALL

B. APPROVAL OF AGENDA

C. APPROVAL OF MINUTES: June 11, 2019

D. FINDINGS OF FACT & CONCLUSIONS OF LAW

Case #H-19-041. 202 Gonzales Road
Case #H-19-0047. 133 Romero Street.
Case #H-19-045A. 917 Acequia Madre.
Case #H-19-046. 1658 Cerro Gordo Road.
Case #H-19-044. 1011 Camino Santander.
Case #H-19-045B. 917 Acequia Madre.

E. BUSINESS FROM THE FLOOR

F. COMMUNICATIONS

G. ACTION ITEMS

1. **Case #H-19-040. 336 Don Cubero Place. Don Gaspar Area Historic District. Doug Webb, agent for Rob Hagey, owner, proposes to replace eyebrow overhangs with a 290 sq. ft. 9'4" high portal, replace a pedestrian gate, install exterior lighting, and restucco a yardwall and a non-contributing residential building. (Carlos Gemora, cegemora@santafenm.gov, 955-6670)**

2. **Case #H-16-012B. 314 N. Guadalupe Street. Westside-Guadalupe Historic District. Paul Duran, agent for John and Melinda Balling, owners, propose to demolish a non-contributing accessory structure. (Lisa Roach, lxroach@santafenm.gov, 955-6657)**

3. **Case #H-19-019. 101, 102, 103, 105, 106, 109, 110, 111, 113, 114, 115, 117, 118, 119, 120, 121 Camino Santiago and 104, 105, 107, 109, 111, 116/120 Camino Matias. Downtown & Eastside Historic District. Lloyd and Associates, agent for Plaza del Monte LLC, owners. The Historic Districts Review Board requests historic status review and designation of primary façades, if applicable, for all residential structures in the Plaza del Monte Subdivision, except those reviewed for historic status in Case #H-17-098A (122, 124, 125, 126, and garages south of 126 Camino Santiago). (Lisa Roach)**

H. MATTERS FROM THE BOARD

I. ADJOURNMENT

Cases on this agenda may be postponed to a later date by the Historic Districts Review Board at the noticed meeting. Please contact the Historic Preservation Division at 955-6605 or check https://www.santafenm.gov/historic_districts_review_board for more information regarding cases on this agenda. Persons with disabilities in need of accommodations, contact the Historic Preservation Division office at (505) 955-6605 five (5) working days prior to the meeting date.

RECEIVED AT THE CITY CLERK'S OFFICE
DATE: June 19, 2019
TIME: 2:22 PM

City of Santa Fe

Agenda

HISTORIC DISTRICTS REVIEW BOARD FIELD TRIP

TUESDAY, June 25, 2019 at 12:00 NOON

HISTORIC PRESERVATION DIVISION, 1st FLOOR CITY HALL

HISTORIC DISTRICTS REVIEW BOARD HEARING

TUESDAY, June 25, 2019 at 5:30 P.M.

CITY COUNCIL CHAMBERS

CALL TO ORDER

A. ROLL CALL

B. APPROVAL OF AGENDA

C. APPROVAL OF MINUTES: June 11, 2019

D. FINDINGS OF FACT & CONCLUSIONS OF LAW

Case #H-19-041. 202 Gonzales Road
Case #H-19-0047. 133 Romero Street.
Case #H-19-045A. 917 Acequia Madre.
Case #H-19-046. 1658 Cerro Gordo Road.
Case #H-19-044. 1011 Camino Santander.
Case #H-19-045B. 917 Acequia Madre.

E. BUSINESS FROM THE FLOOR

F. COMMUNICATIONS

G. ACTION ITEMS

1. **Case #H-19-040. 336 Don Cubero Place. Don Gaspar Area Historic District. Doug Webb, agent for Rob Hagey, owner, proposes to replace eyebrow overhangs with a 290 sq. ft. 9'4" high portal, replace a pedestrian gate, install exterior lighting, and restucco a yardwall and a non-contributing residential building. (Carlos Gemora, cegemora@santafenm.gov, 955-6670)**

2. **Case #H-16-012B. 314 N. Guadalupe Street. Westside-Guadalupe Historic District. Liaison Planning, agent for John and Melinda Balling, owners, propose to demolish a non-contributing accessory structure. (Lisa Roach, lxroach@santafenm.gov, 955-6657)**

3. **Case #H-19-019. 101, 102, 103, 105, 106, 109, 110, 111, 113, 114, 115, 117, 118, 119, 120, 121 Camino Santiago and 104, 105, 107, 109, 111, 116/120 Camino Matias. Downtown & Eastside Historic District. Lloyd and Associates, agent for Plaza del Monte LLC, owners, historic status review and designation of primary façades, if applicable, for all residential structures in the Plaza del Monte Subdivision, except those reviewed for historic status in Case #H-17-098A (122, 124, 125, 126, and garages south of 126 Camino Santiago). (Lisa Roach)**

H. MATTERS FROM THE BOARD

I. ADJOURNMENT

Cases on this agenda may be postponed to a later date by the Historic Districts Review Board at the noticed meeting. Please contact the Historic Preservation Division at 955-6605 or check https://www.santafenm.gov/historic_districts_review_board for more information regarding cases on this agenda. Persons with disabilities in need of accommodations, contact the Historic Preservation Division office at (505) 955-6605 five (5) working days prior to the meeting date.

RECEIVED AT THE CITY CLERK'S OFFICE	
DATE:	June 7, 2019
TIME:	9:01 AM

SUMMARY INDEX
HISTORIC DISTRICTS REVIEW BOARD
June 25, 2019

ITEM	ACTION TAKEN	PAGE(S)
B. Roll Call	Quorum Present	1
C. Approval of Agenda	Approved as amended	1-2
D. Approval of Minutes - June 11, 2019	Approved as presented	2
E. Findings of Fact & Conclusions of Law	Approved as presented	2-3
F. Business from the Floor	Comments	3
G. Communications	Announcement	3
H. Action Items		
1. **Case #H-19-040.**	Approved with conditions 336 Don Cubero Place	3-10
2. **Case #H-16-012B.**	Approved demotion 314 N. Guadalupe Street	10-14
3. **Case #H-19-019.** 101, 102, 103, 105, 106, 109, 110, 111, 113, 114, 115, 117, 118, 119, 120, 121 Camino Santiago and 104, 105, 107, 109, 111, 116/120 Camino Matias.	Approved some Contributing	14-57
I. Matters from the Board	Comment	57
J. Adjournment	Adjourned at 10:16 p.m.	57

MINUTES OF THE

CITY OF SANTA FE

HISTORIC DISTRICTS REVIEW BOARD

June 25, 2019

CALL TO ORDER

A regular meeting of the City of Santa Fe Historic Districts Review Board was called to order by Ms. Cecilia Rios, Chair, on the above date at approximately 5:30 p.m. in the Council Chambers at City Hall, 200 Lincoln Avenue, Santa Fe, New Mexico.

A. ROLL CALL

Roll Call indicated the presence of a quorum as follows:

MEMBERS PRESENT:
Ms. Cecilia Rios, Chair
Mr. Frank Katz, Vice Chair
Ms. Jennifer Biedscheid
Mr. Anthony Guida
Ms. Flynn G. Larson
Mr. Herbert Lotz
Mr. Buddy Roybal

MEMBERS EXCUSED:

OTHERS PRESENT:
Mr. Carlos Gemora, Senior Planner
Ms. Lisa Roach, Planner Manager
Mr. Gabe Smith, City Attorney's Office
Mr. Carl Boaz, Stenographer

NOTE: All items in the Committee packet for all agenda items are incorporated herewith by reference. The original Committee packet is on file in the Historic Planning Department and available on the City of Santa Fe web site.

Chair Rios asked Mr. Boaz if this was his last meeting with the HDRB.

Mr. Boaz said it was.

Chair Rios thanked him for his service to the H Board.

B. APPROVAL OF AGENDA

MOTION: Member Roybal moved, seconded by Member Guida, to approve the agenda as presented.

VOTE: The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.

C. APPROVAL OF MINUTES: June 11, 2019

Chair Rios requested the following changes to the minutes:

On page 17, 4th paragraph it should say that Chair Rios asked if there were gabions demolished.

MOTION: Member Katz moved, seconded by Member Guida, to approve the minutes of June 11, 2019 as amended.

VOTE: The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.

D. FINDINGS OF FACT AND CONCLUSIONS OF LAW

Case #H-19-041. 202 Gonzales Road Case #H-19-046. 1658 Cerro Gordo Road. Case #H-19-0047. 133 Romero Street. Case #H-19-044. 1011 Camino Santander. Case #H-19-045A. 917 Acequia Madre. Case #H-19-045B. 917 Acequia Madre.

MOTION: Member Biedscheid moved, seconded by Member Larson, to approve the Findings of Fact and Conclusions of Law as presented.

VOTE: The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.

E. BUSINESS FROM THE FLOOR

Ms. Stefanie Beninato, PO Box 1601, said, "I too, thank Carl for staffing this Board and others, and for being patient with boards and the public."

Regarding separation of powers and what was supposedly an interpretation of the law by the Land Use Director, she had concern for the H Board. She pointed out an ordinance that says the LUD can interpret the Code. But in the State Legislature, the Executive cannot make the law nor remake law as they want it. There is no wording about "ambiguous." As an attorney, that is probably unconstitutional and not legal.

In my neighborhood, we were told that the City was going to use a less rigorous process in approving variances to setbacks for an administrative process instead of a public process. But when there is a conflict, a more rigorous interpretation must be used. So the underlying zoning says the Board should do it because it is the more restrictive process. "I hope you strongly hold on to that provision."

Regarding administrative approvals, Ms. Beninato said when she learned that a significant structure got administrative approval for a four-foot fence on the street, she was greatly concerned. That should come to the Board before it is finally approved. It could be done like a consent calendar. All administrative approvals should be on the consent agenda so the Board and public would know what was approved out there and that the Board could pull something off the calendar like a significant building for discussion by the Board.

There was no other business from the floor.

F. COMMUNICATIONS

There were no communications.

G. ACTION ITEMS

Chair Rios announced to the public that decisions of the Board could be appealed to the Governing Body within fifteen days after the Findings of Fact and Conclusions of Law have been approved.

1. **Case #H-19-040. 336 Don Cubero Place.** Don Gaspar Area Historic District. Doug Webb, agent for Rob Hagey, owner, proposes to replace eyebrow overhangs with a 290 sq. ft. 9'4" high portal, replace a pedestrian gate, install exterior lighting, and restucco a yardwall and a non-contributing residential building. (Carlos Gemora, cegemora@santafenm.gov, 955-6670)

Mr. Gemora presented the Staff Report as follows:

BACKGROUND & SUMMARY:

336 Don Cubero Place is a non-contributing multi-unit residential property located in the Don Gaspar Historic District. In 2005, the Board approved changes, which included replacing windows, doors, changing fenestrations, removing a south-facing portal, and restuccoing yard walls. On May 28, 2019, the applicant presented a proposal to construct a portal, replace the entry gate, stucco the yard wall and house, and install exterior address lighting. The board postponed the case, asking for changes to the gate design, the portal design, and alternative stucco colors.

Front Yard Wall Gate: The applicant originally proposed replacing the front, entry, antiqued wood gate with a solid steel gate but the board requested more wood, less steel, and more of a "friendly" design.

1. The applicant proposes a gate with a weathered wood finish and a rusted steel frame. Two additional gate designs are provided (Page 3B) with blue-painted wood gates but are not the applicant's preferred proposal.

Front Portal: The applicant originally proposed a 13' deep portal modeled after the existing carport on the property. The Board requested that the applicant redesign the proposed portal as a harmonious complement to the existing house and neighborhood. The Board suggested the applicant consider adding parapets, a smaller size, features to match the gate, more height, and changing the roof design.

2. Preferred Option A: The applicant proposes a corrugated metal, low-pitch shed roof portal at 10' deep instead of 13' with enlarged posts and beams and the addition of corbels.

   Option B: The applicant provides alternative designs for a portal with parapet. The applicant also asks for flexibility regarding canales.

Stucco Color: The applicant originally proposed a "sage green" color of stucco on the yard wall and house but the Board requested color alternatives and that the applicant consider the color of the rest of the two-unit structure.

3. The applicant now proposes a color similar to El Rey "La Luz" (earthtone).

Exterior Light:

4. The applicant proposes a metal, downward-facing light fixture to illuminate the street address and which will approximately match the existing light fixtures.

STAFF RECOMMENDATION:

Staff recommends approval of the proposed project and finds that the application complies with Section 14-5.2(D)(9) General Design Standards for all Historic Districts – Height, Pitch, Scale, and Massing, and 14-5.2(H) Don Gaspar Area Historic District.

Questions to Staff

Member Roybal saw there are two portal options and asked which option Staff approved.

Mr. Gemora said either one could be approved.

Chair Rios asked, in both A and B, what the depth, height and width would be.

Mr. Gemora said it would be 10' plus the overhang and 8' 6" in height. Option B would be 13' deep, and both are the same width (23') and height. The height would probably be about 10' to top of parapet.

Applicant's Presentation

Mr. Rob Hagey, 336 Don Cubero, was sworn. He said, "I like the color. My preference is a metal roof. Corten is used as a substantial roof compound. The depth of the portal is ten feet with the preferred drawing and I'm flexible. It could even be 8 feet deep. The main goal is to enjoy my yard outside with coffee in the morning and wine in the evening. And I will get bids for the cost."

Questions to the Applicant

Chair Rios asked in Option A if the canales go under the roof.

Mr. Hagey agreed. He indicated he spoke with someone at the City who thought both were okay. For drainage, he thought about a French drain. He also thought he could add another inch by lowering it directly at the foundation.

Member Guida asked him to explain the gate design that has three options.

Mr. Hagey asked the Board to pick one. He said, "I wanted a rusted metal gate and a man at the last hearing suggested adding wood to it. I went to Hansen Wood and found some great wood for a wood fence. We can do metal swaling and if it doesn't work, I can paint it blue."

Member Guida saw that as the third option - a metal frame with weathered wood. The first option has a lintel on it.

Mr. Hagey said with the lintel on top, he would move the gate a little back from the wall. "It is possible, and I see about half of the homes have that in the district. I was not trying to do anything unusual."

Member Guida asked for a sample of the stucco color.

Mr. Hagey said, "El Rey is one of leading compounds in New Mexico. The color I chose is El Rey."

Member Guida asked what the stucco color is now.

Mr. Hagey called it Rose. He said he planned to use the same color on all of the house, including the patio.

Member Guida noted there are two colors on the house now.

Mr. Hagey said no. There is a subtle difference. This is about me wanting to change the color. I have not seen a Rose color at all. But it is now a rose color and I don't know the exact name, but I am not interested in that color.

Member Guida asked, "Which surfaces to you want to paint?"

Mr. Hagey said "paint" is interesting. I did not know paint was an option. I don't know the criteria. My stucco has no cracks and there is no issue with leakage. I thought I could paint it, but I was told I could not; that I had to do stucco. I would like some clarification.

Chair Rios asked Staff to clarify.

Ms. Roach clarified that, in the past, the Division Staff's practice was that paint was only allowed on stucco if paint was already on the stucco and if not, stucco is only allowed and cannot be painted.

Mr. Hagey had no problem with that.

Chair Rios said if the gate options, option 1 was the nicest looking for her.

Member Biedscheid asked if he intended to stucco both wall and house.

Mr. Hagey said he did, and he has permission to do that.

Member Lotz liked gate option 3 very much.

Member Larson was concerned with the drainage issue if the roof has pitch. She would prefer the first gate option.

Member Biedscheid asked if he said option one for the gate would require it to be moved.

Mr. Hagey thought moving it would be best, but it would cost more. Right now, he can make it work with the beam on top.

Member Biedscheid did not see a drawing of the lintel.

Mr. Hagey said, "Right now, I just want to focus on this."

Member Biedscheid felt the 10-foot depth would be very deep and overwhelm the house. The HCPI shows a portal on the south that is more in scale and Mr. Hagey said he would consider a shorter depth. The south one was probably 5-6'.

Mr. Hagey was willing to compromise at 8'. To compare it with the carport that is already there and not used often, was not fair. This will be an attractive addition to the home.

Member Katz thought 8 feet would work very well. It is the width of our portal.

Chair Rios said she was having an 8-foot portal being built now.

Public Comment

Ms. Heidi Britt was sworn. She said, "I'm here to represent myself and some neighbors. After leaving the hearing last time, we came to realize something very important to us will be removed - a 60 foot ash tree that we have enjoyed for many years. We (she and her neighbors) have lived there 20-49 years. The tree is a focal point of our landscape and Mr. Hagey moved here less than a year ago. I'm not sure he appreciates that tree the way we do. It was also recommended that he reach out to his neighbors to include them in what he was doing and that has not happened.

"We composed a letter and asked him to include the tree in his design. We think it is a magnificent opportunity to do something creative. I have photos of the tree from each of the properties."

Chair Rios explained that the Board doesn't have purview over a tree.

Mr. Gemora said it sounds like some neighbors talked with LUD about removing the tree. It sounds like there is no barrier to that. But I could be wrong.

Ms. Britt said the tree was originally cited as a Siberian Elm and that is incorrect. The burden of maintenance is a very small excuse.

She added, "I don't see much improvement on the design. One drawing shows a carving but another shows none. One shows thicker than the other. In the design shown, Mr. Hagey wants to create an outdoor living space and only half would be useful for that. Because it is on the north side, it will cut off light. I'm suggesting maybe a beautiful gazebo for outdoor living and using the cost from cutting down the tree to have a center yard gazebo. I think it would be really attractive and add to the value of the neighborhood.

Ms. Britt said she would give him 15 hours of design time free. If the Board would consider some other solutions. I'm not sure many have been thought about. I don't feel he has researched it much. The tree cutting would cost about a thousand dollars.

Chair Rios asked Mr. Gemora about the elevation.

Mr. Gemora said one could see a bit of the portal above the wall. It is not overwhelming to the structure - a small to medium addition and it depends on the angle of the pitch if it a shed roof and not a parapet. There are different ways to think about it.

Mr. Stefanie Beninato, P. O. Box 1601, was sworn. She said, "I am happy the applicant made the portal smaller. I really agree it should be six feet wide but understand his desire. Eight feet is the widest it should be. I'm also concerned about the columns and the detailing at the top. It would look like a carport. It would make it darker there. The minimum slope should be 1.5 inch drop for six feet width. So it needs a different slope.

Regarding the tree, I understand the City has jurisdiction over native species of over 12-inch diameter. So I'm not sure why the City does not have jurisdiction over that."

Mr. John Eddy, 227 East Palace, Suite D, was sworn. He said, "This is very interesting case. Coming back after listening to you and the artistic work he has brought really helps us understand it. As for the gate, Option A was identified by two Board members as their favorite. I installed one just like it on Agua Fria. It is wonderful to bring such good drawings. Thank you.

As for the tree, there may be a solution. The City might have purview because it is probably 12 inches in diameter. Perhaps a ramada with open beams to provide shade and allow some sunlight into the windows would be better. In the summer, it would have breezy shade and air passage. Taking that depth of the shed back to 8 feet is a good solution and allow more light into that area. Bringing down to a steeper pitch is probably good but a ramada would potentially allow the tree to stay there with a ramada through the tree. And that would allow the water to come down to the roots of the tree."

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Mr. Hagey said one thing not considered is that the tree is 28" from the house and while putting new flooring in, he saw there is already some damage to the hallway near where the tree is. I have pictures that show it. He passed around the pictures.

Mr. Hagey shared his experience in living in a house on the coast with a palm tree in the bathroom. They encased it in sheet metal and the tree would move the sheet metal. With the tree being so close to the property, he thought perhaps he could plant a new tree and spend some time with the neighborhood. A more mature tree planted might be a nice compromise.

Board Discussion

Mr. Gemora commented on detailing on the drawing. He explained it is not a carving. It is dashed lines and not details. There is also no carving in option A.

When talking about the gate, he hoped the Board recognized that metal with wood was the preferred option in the packet.

Member Guida thought Staff mentioned an option on the canales.

Mr. Gemora agreed. The two canales existing are proposed above the pitched metal roof. It might block off one and it could be moved to the right side. It doesn't sound like both would be moved but one would be moved to the right.

Member Guida concluded there would be no change to the design.

Mr. Gemora agreed.

Member Larson saw in the existing drawing on page 2 that the existing corbels are a little more traditional and it might be well to incorporate that same design.

Member Guida said it was important to him in the submissions to get clarity in the work. The owner brought this portal design and the full scope is expressed. The gate is either in the same place or it is not. That scope needs to be clear to the Board. It is necessary to get accurate quality drawings to eliminate ambiguity.

The quality of the drawings is to allow the Board to understand that what is built will line up with those drawings. That is a big deal for him. He did not see a tremendous improvement, but it would be nice to have more detail.

Action of the Board

MOTION: Member Guida moved, seconded by Member Katz, in Case #H-19-040 at 336 Don Cubero Place, to approve the front portal, option A at 8' deep with wood columns equally spaced and revised updated design drawings submitted to Staff, and stucco color be approved with the understanding the stucco will be on both wall and house; approve the exterior light and for front gate the Board approve either option 2 or 3 because there was no clarity on #1.

Chair Rios asked for a friendly amendment that the stucco color is La Luz.

Member Larson asked for more clarity on the corbels that they be like the original corbels.

Member Guida accepted both amendments as friendly.

VOTE: The motion passed by majority 5-1 voice vote with Member Biedscheid voting against.

2. **Case #H-16-012B. 314 N. Guadalupe Street.** Westside-Guadalupe Historic District. Paul Duran, agent for John and Melinda Balling, owners, propose to demolish a non-contributing accessory structure. (Lisa Roach, lxroach@santafenm.gov, 955-6657)

Ms. Roach presented the Staff Report as follows:

BACKGROUND & SUMMARY:

314 North Guadalupe Street is a large lot with a single family residence and a free-standing garage. The residence was constructed before 1930 in the California Bungalow style and is listed as Contributing to the Westside-Guadalupe Historic District. The north and west façades of the main residence were designated as primary at the March 8, 2016, hearing of the HDRB, and the garage structure was assigned non-contributing historic status at the same hearing, due to extensive non-historic modifications and insufficient historic integrity.

As is described in the attached HCPI form, the garage was originally constructed before 1930 as a rectangular structure with a shed roof sloping to the west, a vehicular door on the east elevation, and white painted historic 6-lite hopper window on each of the north and south elevations. After 1966, an addition was constructed off-center on the east elevation, where the vehicular door is now located.

Now, the applicant proposes to demolish the non-contributing garage structure, as its

location interferes with a proposed lot-split, which will facilitate the proposal of infill housing units on the proposed rear lot.

RELEVANT CODE CITATIONS:

14-3.14 Demolition of Historic or Landmark Structure

(A) Summary of Procedure

(1) Upon receiving an application for demolition of a structure within the historic districts the HDRB shall, within sixty-five calendar days from the date of application, either grant or deny the application. Ordinarily, the HDRB will act on an application for demolition at its next regular meeting, if the application is submitted in proper form at least seven days before its next regular meeting; however, the HDRB may use the entire sixty-five day time period if the HDRB, on motion duly passed, determines such delay is necessary.

(2) Upon receiving an application for demolition of a landmark structure the HDRB shall, within sixty-five calendar days from the date of application, make a recommendation to the governing body to either grant or deny the application.

(B) Hearing Required

(1) In all applications involving the demolition of a structure, provision shall be made for a hearing, as set forth in the preceding section.

(2) The HDRB or governing body, as applicable, shall restrict its review to a consideration of whether the application will be in conformity with the standards established by this section.

(3) Notice of the time and place for each hearing shall be sent in writing to each applicant.

(4) An agenda of the HDRB shall be sent to all groups requesting notification and copies of meeting agendas, as set forth in the officially adopted neighborhood planning policies.

(5) On-site notice, by a sign of proposed demolition and of the time, date and place of the HDRB or governing body review shall be posted by the city on the affected property fourteen days prior to HDRB or governing body review of application for demolition. Such notice shall be prominently displayed, visible from a public street and securely placed on the property.

(C) Staff Review and Report

Before granting approval or denial to a demolition request, the land use director shall provide the following information on the structure under consideration.

(1) A report on the historic or architectural significance of the structure;

(2) A report from the city building inspector on the state of repair and structural stability of the structure;

(3) If the structure is more than seventy-five years old, and the entire project of which demolition is a part requires an archaeological clearance permit, a report from the land use director on whether the demolition would damage possible archaeological artifacts; and

(4) Other information as requested by the HDRB or governing body.

(F) Denial of Demolition Request

A determination that the structure should not be demolished shall impose a duty on the owner or other persons having legal custody and control to immediately take the action required under Section 14-5.2(B) (Minimum Maintenance Requirements).

(G) Standards

(1) In determining whether a request for demolition in a historic district should be approved or denied, the HDRB shall consider the following:
(a) Whether the structure is of historical importance;
(b) Whether the structure for which demolition is requested is an essential part of a unique street section or block front and whether this street section or block front will be reestablished by a proposed structure; and
(c) The state of repair and structural stability of the structure under consideration.

(2) In determining whether a request for demolition of a landmark structure should be approved or denied, the HDRB and governing body shall consider the following:
(a) The historical importance of the structure; and
(b) The state of repair and structural stability of the structure.

STAFF RECOMMENDATION:

Staff recommends approval of the proposed demolition and finds that the application complies with Section 14-3.14 Demolition of Historic or Landmark Structure.

Questions to Staff

There were no questions to Staff.

Applicant's Presentation

Mr. Paul Duran was sworn. He thought Staff explained the proposal very well and he would answer questions.

Questions to the Applicant

There were no questions to the Applicant.

Public Comment

Ms. Beninato (previously sworn), said, "I know it is noncontributing. But since there is no degradation of the building, what are the criteria for demolition? If Staff could explain that, it would help."

Chair Rios said they did see degradation of the building on the site visit.

Ms. Roach said section G outlines the standards. She read them aloud.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Board Discussion

Ms. Roach explained that there is no stipulation that the application has to meet all three criteria for demolition.

Action of the Board

MOTION: Member Katz moved, seconded by Member Roybal, in Case #H-16-012B at 314 N. Guadalupe Street, to grant the demolition application.

VOTE: The motion passed by unanimous 6-0 voice vote.

3. **Case #H-19-019. 101, 102, 103, 105, 106, 109, 110, 111, 113, 114, 115, 117, 118, 119, 120, 121 Camino Santiago and 104, 105, 107, 109, 111, 116/120 Camino Matias.** Downtown & Eastside Historic District. Lloyd and Associates, agent for Plaza del Monte LLC, owners. The Historic Districts Review Board requests historic status review and designation of primary façades, if applicable, for all residential structures in the Plaza del Monte Subdivision, except those reviewed for historic status in Case #H-17-098A (122, 124, 125, 126, and garages south of 126 Camino Santiago). (Lisa Roach)

Ms. Roach presented the Staff Report. She explained that there is no applicant. It was initiated at the request of the Board for these properties. We did get a letter at 5:00 indicating concerns that the City has denied due process and requesting to withdraw the application and stating the applicant has been preparing an application for development. There was no application for status review so there is no application to withdraw. It is the position of the City to proceed.

Chair Rios asked if the owner has to give consent.

Ms. Roach said no. The Board can initiate a status review and the only requirement is that the proper notification be made to the owner and that was done properly. Staff did follow all proper procedures and felt this was important.

Member Katz said it was ingenuous of owners to not have status of buildings before the plan.

Ms. Roach said she would not give the entire report but background and comments on the 50-year rule. And then as the Board considers status, suggested we go property-by-property and discuss and make a motion on each. She wondered about moving public comment earlier- perhaps after she reads the staff report.

Chair Rios suggested that also. Maybe the public will have general comments but could single out specific addresses.

Member Roybal asked where the status recommendations were taken.

Ms. Roach explained how Staff considered each individual property.

Member Roybal pointed out that eight months have passed since their first review.

Ms. Roach said the original application was submitted two years ago and we opened a new case in February.

Member Roybal asked if those recommendations were different.

Ms. Roach said they are.

BACKGROUND:

101-121 Camino Santiago and 104-120 Camino Matias are 22 residential structures, which along with 122, 124, 125, 126 and the garages at 126 Camino Santiago, comprise the Plaza del Monte subdivision, located in the Downtown and Eastside Historic District. Historic status for all 27 structures in Plaza del Monte is summarized in the table below:

	Construction Date(s)	Current Historic Status	Recommended Historic Status	HDRB Status Review Case
101 Camino Santiago	c.1967-68	NC	NC	H-19-019
102 Camino Santiago	c.1965	NC	C	H-19-019
103 Camino Santiago	c.1965	NC	C	H-19-019
105 Camino Santiago (Units 1-4)	1971	NS	NC	H-19-019
106 Camino Santiago	c.1965	NS	C	H-19-019
109 Camino Santiago	c.1965	NS	NC	H-19-019
110 Cam. Santiago / 112 Cam.	c.1962/c.1968	NS	NC	H-19-019
111 Camino Santiago	c.1965	NS	C	H-19-019
113 Camino Santiago	c.1970	NS	NC	H-19-019
114 Camino Santiago	c.1972	NS	NC	H-19-019
115 Camino Santiago	c.1970	NS	NC	H-19-019
117 Camino Santiago	1966-67	NS	NC	H-19-019
118 Camino Santiago	c.1973	NS	NC	H-19-019
119 Camino Santiago	c.1965	NS	NC	H-19-019
120 Camino Santiago	c.1971	NS	NC	H-19-019
121 Camino Santiago	c.1971	NS	NC	H-19-019
122 Camino Santiago	c.1971	NC	-	H-17-098A
124 Camino Santiago	c.1968	C	-	H-17-098A
125 Camino Santiago (Units 1-4)	c.1970	NC	-	H-17-098A
126 Camino Santiago	c.1968	C	-	H-17-098A
Garages south of 126 Cam.	c.1968/1977	NC	-	H-17-098A
104 Camino Matias	c.1965	NC	C	H-19-019
105 Camino Matias	1950	C	NC	H-19-019
107 Camino Matias	1950	NC	NC	H-19-019
109 Camino Matias	1950	NC	NC	H-19-019
111 Camino Matias	pre-1960 (moved to site)	NC	NC	H-19-019
116/120 Camino Matias	pre-1957 w/c.1984 addition	NC	NC	H-19-019

NS = Non-statused NC = Non-contributing C = Contributing

[1]historic status for 122, 124, 125, 126 and the garages at 126 Camino Santiago were assigned in Case H-17-098A. Recent HDRB actions on the status of Plaza del Monte are provided here, and a more extensive case history is provided as an attachment to

[1] Historic Status Recommendations are taken from the "Plaza del Monte Historic Resources Evaluation," by John Murphey (2018).

this report. On March 26, 2019, the HDRB reviewed the status of the seven non-statused structures in Plaza del Monte (105, 113, 114, 115, 118, 120, and 121 Camino Santiago), and their decision was to assign Contributing status to all seven structures because of their association to the Plaza del Monte, an historic planned subdivision, and because they are representative examples of Mid-century Modern influenced expressions of Santa Fe Style. On April 23, 2019, the HDRB rescinded their motion from the March 26, 2019, hearing regarding the assignment of contributing historic status for the seven non-statused structures at Plaza del Monte, citing insufficient discussion of each individual structure to justify the assignment of contributing status, including failure to designate primary façades. The conditions of this action were in the form of the following directives: 1) that the Land Use Director provide interpretation of the "50-year rule"; 2) that staff provide information regarding applicability of the provisions in the code for "Historic Compound" designation; and 3) that staff bring all remaining structures in Plaza del Monte back to the HDRB for review under a single status review case.

This report represents staff's response to directives included in the April 23rd rescission of status designation for seven non-statused structures in Plaza del Monte. All structures in Plaza del Monte for which status has not previously been reviewed by the HDRB are herein presented to the HDRB for status review, including designation of primary façades as needed for those structures that receive contributing status.

HISTORICAL SUMMARY OF PLAZA DEL MONTE[2]

The Plaza del Monte subdivision, or Plaza del Monte Retirement Center as it was formerly known, was originally conceived in the late 1950s as a communal living center for retired Presbyterian pastors, missionaries, and other church officials. After the Allison-James School closed in 1958, the United Presbyterian Church decided to plan for re-development of the site, and they selected the architectural firm of Kenneth S. Clark and Phillippe Register to design it as a large retirement community. The architects divided the former campus into two parts – the site of the older buildings termed the "South Area" would be developed first with a congregate building, and the "North Area" would be developed in a second phase with individual residences. A preliminary layout of the development in 1960 showed a cul-de-sac arrangement of the homes built around two new streets. Camino Santiago would run along the northern portion of the property, turning south and terminating in a cul-de-sac, and Camino Matias would be a loop off of Camino Santiago running through the older residences at the southern portion of the property.

As is described in the Plaza del Monte Historic Resources Evaluation, Clark and Register conceived the design of the residences as a modified L-plan to which a carport and portal were attached. Architectural details are sympathetic to the Spanish-Pueblo Revival tradition – with room-block stuccoed massing, rounded corners, and vigas,

[2] Historical Summary paraphrases research presented in the "Plaza del Monte Historic Resources Evaluation," by John Murphey (2018).

posts and corbels on the portals and carports – but re-framed in mid-century styling. This contemporary influence became more pronounced on the exteriors of the later homes in the development, when the low, horizontal lines of the residences were further accentuated with flat overhanging roofs at times intersected with vertical planes. The latest homes constructed in Plaza del Monte in the early 1970s experimented with angular walls and a more compact massing with carport-dominant façades.

RELEVANT CODE CITATIONS:

14-5.2(C) Regulation of Significant and Contributing Structures in the Historic Districts

(1) Purpose and Intent

It is intended that:

(a) Each structure to be recognized as a physical record of its time, place, and use. Changes that create a false sense of historical development, such as the addition of conjectural features or architectural elements from other buildings, shall not be undertaken;

(b) Changes to structures that have acquired historic significance in their own right shall be retained and preserved, recognizing that most structures change over time;

(c) Distinctive features, finishes, and construction techniques or examples of craftsmanship that characterize a structure be preserved; and

(d) New additions and related or adjacent new construction be undertaken in such a manner that if removed in the future, the original form and integrity of the historic property and its environment would be unimpaired.

14-12 Significant Structure:

A structure located in a historic district that is approximately fifty years old or older, and that embodies distinctive characteristics of a type, period or method of construction. For a structure to be designated as significant, it must retain a high level of historic integrity. A structure may be designated as significant:

(A) for its association with events or persons that are important on a local, regional, national or global level; or

(B) if it is listed on or is eligible to be listed on the State Register of Cultural Properties or the National Register of Historic Places.

14-12 Contributing Structure:

A structure, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a contributing structure is not unique in itself, it adds to the historic associations or historic architectural

design qualities that are significant for a district. The contributing structure may have had minor alterations, but its integrity remains.

14-12 Primary Façade:
One or more principal faces or elevations of a building with features that define the character of the building's architecture.

14-12 Noncontributing Structure:
A structure, located in an H district, that is less than fifty years old or that does not exhibit sufficient historic integrity to establish and maintain the character of the H district.

"50-YEAR RULE" GUIDANCE:

The "50-year rule" is one of the most widely accepted principles within the historic preservation movement in the U.S., establishing the standard that properties approximately fifty years old or older are of sufficient age to have established historic significance as a threshold for triggering preservation. The rule was established by the National Park Service in 1948 and codified at the federal level in the National Historic Preservation Act of 1966. Exceptions to this standard have been applied to sites, structures and places that are less than fifty years old, but which have demonstrated "exceptional importance" independent of age. This chronological filter has been applied to properties nominated to the National Register of Historic Places, and it has been widely utilized in local historic preservation ordinances across the country as a means to settle potential controversies over the nature of historic significance. 3

The "50-year rule" was included in Santa Fe's historic preservation ordinance in 1957 – one of the earliest uses of the standard at the local level. Because it has its origins in federal historic preservation policy, it stands to reason that its administration at the local level should follow federal guidance. In doing so, the HDRB is encouraged to apply the "50-year rule" as a guideline when evaluating historic status of properties. Accordingly, properties less than fifty years old may be deemed to be contributing or significant if the Board determines that they are of "exceptional importance" (association with or representative of events, people or trends of historical or architectural significance).

That said, there has been much recent discussion of the "50-year rule," including calls to reconsider its utility and application.

STAFF RECOMMENDATION:

Staff generally agrees with the status recommendations provided in the "Plaza del Monte Historic Resources Evaluation" but defers to the Board for individual status assignments, per 14-5.2(C) Designation of Significant and Contributing Structures.

---

[3] "'Of Exceptional Importance': The Origins of the 'Fifty-Year Rule' in Historic Preservation," by John H. Sprinkle Jr. (2007) *The Public Historian: A Journal of Public History.*

Ms. Roach read the definitions of contributing and significant structures from the Code before reviewing each address. She consulted with City Attorney, LUD and State Historic Planner. She read from the 50 year rule.

She explained it was an approximate guideline and up to the Board to determine if they were significant enough to be designated Contributing and some are less than 50 years old but there is not a rule that the Board could not designate a 47 year old as Contributing.

Chair Rios said the homes are 47 to 69 years old. What is important in the review is the contribution the Presbyterian Church made to this community and those occupations of retired church individuals were an important group. So it was not only representative of time and place but also its association to the City.

Ms. Roach agreed and noted it was not an important theme by John Murphy.

Member Roybal said his concern was with the rule but also that they do not meet Santa Fe Style criteria.

Ms. Roach replied that we have many examples of buildings that don't meet Santa Fe Style like the Cathedral and Scottish Rite Temple. And whether the Board feels mid-century does fall into that category. It is also on impulse of the ordinance in 1957 to counter the introduction of mid-century and is why we don't have a lot of examples of that style. When Plaza del Monte was approved, the HDRB felt it did comply sufficiently with Santa Fe Style to allow its construction.

Member Roybal said he was just concerned in applying the 50 year rule without consideration of design.

Member Biedscheid wanted to consider them as a compound. The value is that they are part of a conceived compound and wondered what criteria they might use for that.

Ms. Roach referred to Section K of the Code. It has not been utilized frequently. There was an effort in 2005 and 2006 to follow through and a survey took place at that time, but we are having trouble finding if the register of compounds was ever created. She would talk in general terms about the criteria and the innovations of the property for any potential designation. She read that section of the code to identify compounds.

Ms. Roach said this compound would not have been considered at that time since it was not near old enough and the criteria said half of the buildings must be designated as contributing.

Member Biedscheid asked, if the Board designates 50% or more as contributing, whether a separate motion should be made to consider historic compound status.

Member Roybal asked, since we don't have an applicant here, if they have a right to appeal.

Ms. Roach said the owner does have that right.

Member Guida asked if there is anything about what we might call a compound that would exclude it from consideration.

Ms. Roach believed this development would qualify in its plan for development and location of the buildings and they are historically related. A compound is more about spatial relationship and intent. There are four different types mentioned in the code.

Member Katz pointed out that it is all owned by the same person and always has been and the people rent their units. He asked if the lots are separate lots of record.

Ms. Roach said there are separate lots of record, but all are owned by the same individual.

Mr. Gemora said regarding the 50-year mark, that the contributing definition says "is approximately fifty years old and has the design features..." So it doesn't have to be of the style but add to the qualities of that district so other different styles could be added.

Ms. Roach said she actually didn't know for sure that they were separate lots of record and would have to research that.

Member Larson said in moving forward, this has a very important part in the context of our City and environment.

Mr. Smith pointed out in Chapter 14-1.9, under construction, that all expressions shall be considered in the context. Approximately is not defined. In accordance with the General Plan, "approximate" would not have a definite number.

Member Katz looked at "approximate" to cover when you did not know when something was created. There are aerial photos that are dated. He thought it needs to be 50 years, but when you don't know it, is where approximately comes in... except if it has great importance.

Public Hearing

Chair Rios asked for general comments at this point and would later ask for public comment at each one.

Ms. Nancy Armbruster, 111 Camino Santiago, was sworn. She read her testimony statement. She is 85 years old and has lived joyfully in Plaza del Monte for 20 years and in Santa Fe for 50 years. "I've spoken to you many times about the beauty and camaraderie of our Plaza del Monte community, so close to the center of our City. I understand the developers have the financial resources to destroy all of our community completely, probably to put up condos and you have the power to tell them to go away and develop some other town. What do you want in downtown Santa Fe? A cluttered city just like any other old city center. Or a beautiful special area with tall trees and old houses cherished in value by many who long for living in a town like ours? You know what is right and do it and do it as soon as possible. Thanks for listening to us."

Ms. Ellen Armbruster, 1 Ladera Place, was sworn. She said, "I've spoken here on numerous times and tonight, I ask you to find all of these to be of contributing status and halt the ongoing assault by the developer on this beloved community, by recognizing the historical value of the houses which belongs together as an integrated and unified whole. Please, remember also that this community has for many years provided affordable housing for the people of Santa Fe recently for senior living and now including young families. I ask you to save all of it in its entirety by designating all buildings to have contributing status."

Ms. Madeline Pryor, 3362 La Avenida de San Marcos, was sworn. She welcomed the new Board members who were appointed after her last testimony. She said, "I'm very interested because I lived there at Plaza del Monte for 11 years until required by the present owners to leave. The apartment I lived in was declared noncontributing because it was only 49 years old. I'm going to ask that you consider adding all the structures recommended as non-contributing due to age as contributing. They are all almost 50 years old. Philippe Register designed them and the seven on the list Mr. Murphy recommended noncontributing were all because of age - not quite 50 years of age and four as of contemporary design and no reason for 101 Camino Santiago. But Register designed all of them.

"On the five homes that were recommended as part of the Allison James School for teachers and not designed by Register, when it was transitioned from Allison James to Presbyterian retirement - they have features that are quite charming. They are on Camino Matias.

"I was surprised when reading the second amendment to the March 24, 2018 report, on page 4, that because of timing issues he (Murphy) did not have a chance to review the First Presbyterian Church Historic Library or the Menaul School Historic Library.

I don't know if that was important or not or whether he since reviewed it or not.

My basic request is that you accepted those who were recommended noncontributing just because of age because they are approximately fifty years old. And look at what he considered contemporary design because of the significance of this

community and of the architect Register, who did it.

"There is one inaccuracy in the review on the home at 121 Camino Santiago, because he got the bedrooms wrong. Thank you."

Ms. Natasha Torres, Creston Colorado, was sworn. She said, "I lived at 116 Camino Santiago for 6 years. I loved that community and I loved all the architectural and history of the district. I loved the teachers' homes by the same architect. It is not good to break up the whole area."

Mr. John Eddy (previously sworn) was grateful that a decision was made to rescind a previous decision on this property because the due diligence undertaken is now very important. When it first came two years ago, I suggested at the first hearing that it needed to be considered as a whole - of a piece, because this neighborhood was a single concept by Clark and Register. They were very respected architects in Santa Fe. And it was on the wishes of the Presbyterian organization and most unique in Santa Fe. The most salient feature - many other developments came about through a vernacular approach with individuals designing their own home. This was conceived for a specific use for giving people a place to live that was affordable. It has gone through different changes - when mid-Century came along - influences coming in and will become a very accepted part of our conversation. A beautiful example for mid-century is the building across from old St. Vincent hospital. Modest homes that do not shout out we are experts of mid-century modern so the architectural historian might have called out they are not classic mid-century but in the direction Santa Fe was going. You had one up on Camino Santander. This property was built with a big concept in mind and that is most salient to take away in the process.

I think the idea of time and approximately close to 50 years, means you do have wiggle room here. I also think because they developed over time, that continuum has to be recognized as a whole not just houses plopped down. They were placed very deliberately.

The idea of classification as a historic compound is very important and I hope you find that is a classification that can be applied on this property and it will belie the fact that you understand that."

Ms. Linda Payne, 414 Bishops Lodge Road, was sworn. She said, "I look down on Plaza del Monte and, for the last 48 years, have been a neighbor. I remember it in its heyday and hope as you go house-by-house that you will consider it historic. It is a cohesive neighborhood and ties in what Mr. Eddy just said. It is a peaceful community and we are losing a lot of neighborhoods with condos and Air BnB's. New people are coming in and renting and older families leaving. And I hope you consider it a historic property."

Ms. Stefanie Beninato (previously sworn) agreed with much of what has been said and everyone who speaks, talks about it as a community and a unified holistic design to be considered as a whole. I am happy that Member Biedscheid suggested considering it as a whole. And acknowledging the integrated design. I think you could consider it together. And the Presbyterian Church had no intent to divide it up to sell.

It is too bad several were already designated as noncontributing and sad you could not reconsider that. The ones to the north are more modern but this was approved when HDRB was in existence and thought it was an appropriate design to embody the traditional and contemporary and we need to acknowledge it. The approximately 50 year rule is helpful and when part of a whole, we need to preserve the whole and a 47 year old structure would contribute to that whole.

It is also important because it has a strong historic association with the Presbyterian Church, which, in New Mexico, has done a lot of positive things in the community to create a compound where ministers and missionaries could have a place to retire for people who contributed greatly. It is so beautiful on some level.

There were no other speakers from the public regarding this part of the case and the public hearing portion was closed.

Board Discussion

Member Guida asked if the Board could make general comments before going to each unit.

Chair Rios agreed.

Member Guida said Staff made recommendations in two broad categories on those for contributing and a distinction with those on Camino Santiago on the 50 year rule. It is a problematic distinction that classifies later Register designs as contemporary. That doesn't work for me and the later ones are a better interpretation of mid-century style. I'd like to know where the Board members are as an overall opinion. Should Significant be on the table for these, although they are humble structures?

Member Larson thought the beauty of the National Register is that it is up to the experts and we are looking at a master-planned community. We see a lot of highlights and the fact that it is master-planned. I would have to agree that it is the big picture we are looking at. I'm not sure I agree with the recommendations of the historic surveyor.

Member Katz looked at the GIS and it is a single lot that emphasizes that it is of a piece.

Member Biedscheid said her intent was to see this as a historic compound and she thought it was eligible and does contribute to the historic district. The streets were

conceived in the current situation and locations were all planned and still are intact today.

For consistency in making a decision, of the five already applied, should hold to the 50-year rule. We've already gone down that road. And she also disagreed with many of the results of the historic evaluation.

She pointed out that the Code does not address contemporary design and the influence on architects at that time does not affect historic status."

Member Roybal said his concern was with the evaluation of John Murphy. And he did not think the Board should go down each individual structure if it is considered as a compound. He thought the Board should designate it as a full compound.

Ms. Roach explained that the Board is required to designate each status before considering it as a compound. She added that the association with Presbyterians and Register are relevant.

Member Roybal asked if those built in 1973 or 1972 would not qualify.

Ms. Roach said they could, however the Board interprets the 50-year rule. And as Member Biedscheid mentioned, five already have had their status designated. Her intent was to stick with that designation.

Chair Rios asked how many members felt they must stick with the exact 50 years.

Three members raised their hands and three did not. Member Katz, Member Roybal and Member Biedscheid wanted to stick with exactly 50 years.

Member Katz thought all the Board accepted it as a planned community - all of a piece. And as a compound, it protects all structures through the compound designation. And several of them are 2-3 years away from the 50 year mark and we don't have to stretch to make those historic if 50% of them are historic. That would then allow us to proceed with the compound process.

Ms. Roach said regarding compound protections, that there are things to assist. If the compound continued to be owned by a single owner, that the owner would come forward with what the compound plan is for any proposed changes and if divided with multiple owners, the new owners would still have to comply with limits on height, total additions added, similar materials and style of the compound and any blockage of the spatial nature of the compound. So with the protections of the compound status, the Board would not be compelled to make every structure have a contributing status.

Chair Rios noted that if the whole was determined to be a compound, at least 13 would need to be contributing.

Ms. Roach said they would need 14 to be a majority.

Chair Rios observed that obviously harmony would play a huge role but not as strictly for noncontributing.

Ms. Roach, in interpreting Section K, said that there would be similar restrictions as with contributing buildings and limitations on new construction. Spatial relationships and form are considered part of the compound (harmony). So there are standards that would apply to modifications and a little more strict - height regulations, etc.

Member Lotz felt it was a complex issue for him and he might have to abstain.

Member Guida did not want to beat on the 50-year rule but he did not understand why the Board should be so strict about it. We are making an argument about the compound being of a piece - and of design integrity and consistency and challenged by the limitations of contributing. We could go about it with a focus on view. We are also designating façades as primary. Some of them are visible from different angles.

He said the piecemealing at a macro level concerned him. But all are individual structures, to be consistent with the ordinance. They are bringing it philosophically.

Chair Rios agreed on that interpretation because each building relates to one another to create the compound.

Chair Rios thanked those who came out for this case.

Member Larson said- the 50-year rule is so important. At the National Park Service, we are handling it as a specific movement, not restricted to the 50 year rule. Like Member Guida said, we are looking at a master plan very common in that area. With the National Register, there is flexibility in making evaluations and is why it is there. The 50-year rule was created to manage nominations for the National Register when it was coming of age.

Ms. Roach said as she looked at the evaluations and at the time, tended to agree with recommendations. But now, she has shifted. She would present John Murphy's recommendations, but the Board should have the privilege to decide. She said she would participate in the discussion but refrain from a specific recommendation. She also explained that the packet has two façades photographed for each individual property.

SUMMARIES OF INDIVIDUAL PROPERTIES

101 Camino Santiago: Situated near the east entrance to Plaza del Monte, the house is a roughly 1,332 square foot contemporary residence constructed in 1967-68. In plan, the three-bedroom dwelling has a square form with an attached L-shaped portal and

garage, giving it a combined square footprint. It presents to the street a long portal with the roof carrying over the garage. It is fenestrated with aluminum windows, primarily of a sliding operation. A paneled wood door gives entry to the residence at the east end of the portal. The garage entry is fitted with a recent vinyl overhead door. Cementitious brocade stucco in a peach tone covers the frame building. The roof consists of a mixture of gravel and asphalt material. An interior parapet outlines the dwelling portion of the mass. While contemporary in form, the vigas across the portal give the residence a regional feel.

The recommendation of John Murphy was Noncontributing because of contemporary design. If it is considered to be Contributing, the south façade is recommended as primary.

Board Discussion

Member Guida asked which façade is also shown.

Ms. Roach said it was the north elevation (rear).

Chair Rios asked Ms. Roach is she would agree all of them have had no footprint changes, but some window openings have changed.

Ms. Roach said this is the original footprint. The garage door is recent. She was unclear if windows were original, but it appears they are the original openings.

Public Comment

Ms. Beninato (previously sworn) asked for its age.

Ms. Roach said it was constructed in1968.

Ms. Beninato felt this property is Contributing. The footprint is original. The Board should accept the garage door and should find it Contributing with the south façade as primary. That one is probably typical.

Ms. Roach, commenting on that issue, said if the intent is to consider this as a compound, there are sufficient protections relating to building form and stylistic elements that the Board could deny an application that would substantially change it.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: **Member Katz moved, seconded by Member Biedscheid, in Case #H-19-019 at 101 Camino Santiago, that it be Contributing with the south façade as primary and in that photo you would not find a mid-century house like it anywhere else but in Santa Fe. It is a wonderful adaptation the way they incorporated it into this home.**

Member Biedscheid added that the portal over the garage is a novel approach and use of timber posts. Member Katz agreed.

VOTE: **The motion passed by majority (5-1) voice vote with Members Biedscheid, Katz, Guida, Larson, and Lotz voting in favor, and Member Roybal voting against.**

102 Camino Santiago: One of the earliest units to be constructed at Plaza del Monte, 102 Camino Santiago is a 2,064 square foot dwelling with one addition. The two bedroom, flat-roof house faces Camino Matias. It shows to the street (west) a façade-long portal, continuing at the south end as a single-space carport. The portal is supported by shiplap wood girders resting on round posts with double-ended corbels. Most of the portal façade is painted white. A line of vigas runs along the top of the wall. The elevation is penetrated by two doors and large windows, with the southernmost window not meeting the ordinance in regard to its distance from the corner. The north elevation facing Camino Santiago displays a variety of window openings holding tall metal casements. A shallow overhang supported by short vigas carries over most of the elevation. At the northeast corner is a room block-like projection holding the bedroom wing. The rear (east) elevation presents a number of alterations. The largest is a post-1969 addition, over what was a patio. The 380-square-foot addition is fenestrated with modern windows and is sheltered by a parapet-type portal. The house was constructed in c. 1965, and its designer/architect is unverified but assumed to be Kenneth S. Clark and Phillippe Register. Contributing status is recommended for this structure, as it is representative of the original Clark and Register design template for Plaza del Monte residences and is a good example of Mid-century Santa Fe Style. If the Board assigns contributing status to the residence, the west façade is recommended as primary.

Board Discussion

Member Guida said the carport seems very significant. His concern would be on the significant changes to that façade.

Ms. Roach commented on the rule that new construction shall not block. There is sufficient justification to deny contributing with that factor.

Public Comment

Ms. Beninato (previously sworn) said she would like to see it designated Contributing but would want more than one façade designated primary. Garage doors are significant, and the design has setback. All three should be primary. Even though we have the rules about setbacks from primary façades, people come in and cry about getting an exception and get to crowd up on the primary façade.

Mr. John Eddy (previously sworn) asked if in the photo outlined in yellow, it is in a plane with the vigas and lintel above it - there appears to be no setback in that façade.

Ms. Roach thought that was correct.

Mr. Eddy thought that was infill of a substantial portal.

Chair Rios asked Ms. Roach to identify the elevations.

Ms. Roach said the front façade is facing northeast. The building faces Camino Matias and the rear faces east.

Chair Rios wanted to make sure.

Ms. Natasha Torres (previously sworn) said the layout shows it clearly.

Action of the Board

MOTION: Member Biedscheid moved, seconded by Member Guida, in Case #H-19-019 at 102 Camino Santiago, to designate the structure as Contributing with west and south façades as primary.

VOTE: The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.

103 Camino Santiago: Roughly 1,533 square feet, the one-story residence is designed as an L-plan form. The plan puts the bedrooms in a cube-like mass, with the remainder of the functions of the house strung along a linear spine. Its façade is defined by a long portal sheltering its entry and patio doors. The east end of the composition terminates as a one-bay carport. A line of vigas runs along the back (north) elevation supporting a short overhang. An exterior chimney breaks through the overhang, rising several feet above the roof. The house is fenestrated with an array of original and replacement aluminum windows. It is entered under the portal through a stylized wood panel door flanked by one set of sidelights. The dwelling's flat roof is outlined by a short parapet;

the roof is covered with gravel. The frame structure is finished with cementitious brocade stucco in the buckskin tone. While contemporary in form, vigas used across the portal and the room block bedroom wing give the residence a Spanish-Pueblo Revival feel. The house was constructed in c. 1965; its architect/designer is unverified but assumed to be architect Phillippe Register. Contributing status is recommended for this structure, as it is representative of the original Clark and Register design template for Plaza del Monte residences and is a good example of Mid-century Santa Fe Style. If the Board assigns contributing status to the residence, the south façade is recommended as primary.

Public Comment

Ms. Beninato (previously sworn) said she was happy this is recommended as Contributing with the south façade as primary. She suggested the Board might consider the vigas side also. It does contribute to that house and has more Santa Fe character and the beginning prototype.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: Member Katz moved, seconded by Member Lotz, in Case #H-19-019, at 103 Camino Santiago, to designate the structure Contributing with the south elevation as primary.

Chair Rios asked mover to be specific why it should be Contributing.

Member Katz said it follows the Staff recommendation and follows the L-shaped form that is characteristic.

Member Larson asked for a friendly amendment to add that side elevation as primary.

Member Katz declined.

VOTE: The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.

105 Camino Santiago (Units 1-4): Forming a long, linear composition, 105 Camino Santiago is one of three apartment buildings erected at Plaza del Monte. The carport-

dominated structure works its way down the slope as two L-plan units joined together at the center by a laundry room. The structure is bookended by masses holding the apartments. The larger apartments containing two bedrooms are situated in the projecting room blocks. The apartments share a party wall at the living room. Spanning between the apartments are the carports and the laundry room. The carports are detailed with a viga-roof structure which continues as a portal along the inner apartments. The rear (north) elevation is divided into small patios. The apartments are entered through wood panel doors; solid wood doors give access to the storage units and the laundry. The original multi-light steel casement windows have been replaced with aluminum units. A short parapet follows the outline of the apartments, and is penetrated on the south, east and west elevations with cut-through metal canales. The frame structure is finished with cementitious brocade stucco in a peach tone. While contemporary in form, the vigas used across the portales and carports and the cubed apartment masses give the residence a regional feel. The roughly 4,198 square foot apartment building was constructed in 1971, after a design by architect Phillipe Register. Non-contributing status is recommended for this presently non-statused multi-unit residential structure due to age and contemporary design features. However, the Board may consider that its association with architect Phillipe Register and with the Plaza del Monte planned development could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the south façade is recommended as primary.

Board Discussion

Member Guida pointed out that both photos are of the south façade.

Ms. Roach agreed. She said page 143 shows the HCPI photos. Photo 2 shows south and east. And also the north in Photo #1.

Member Katz noted it is a very interesting Santa Fe style with large block masses. It is classic Santa Fe style. He thought it was sufficiently Santa Fe style that he would want to make it Contributing, but it is not an exceptional building that we could make 47 years be 50 years. He recommended noncontributing due to its age.

Member Roybal agreed with Member Katz.

Member Guida countered that the Board is also making the point about the association with the architect. And it is the work of a significant architect. He recommended Contributing by association.

Member Flynn agreed with Member Guida that it is the work of a significant architect for an exception.

Public Comment

Mr. Eddy (previously sworn) asked if we could see the picture of the other façade.

He respectfully disagreed with Member Katz. This building makes a very strong impact on the streetscape. It really does exemplify what the architect is doing here with his design.

Ms. Roach showed the other façades.

Ms. Beninato (previously sworn) thanked the Staff for correcting that it is 48 years old. She understood the consistency with 50 years actual because the owner is likely to appeal.

This clearly embodies the Santa Fe style in vernacular design. It mimics one that was done by John Gaw Meem and she felt it was appropriate for it to be Contributing.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: **Member Guida moved, seconded by Member Flynn in Case #H-19-019 at 105 Camino Santiago, to designate the structure as Contributing with south façade primary because of association with Register and the quality of expression here that is clearly of Santa Fe Style.**

VOTE: **The motion resulted in a tie vote with Member Guida, Member Lotz and Member Flynn voting in favor and Member Katz, Member Biedscheid and Member Roybal voting against. Chair Rios voted in favor, breaking the tie. The motion passed by 4-3 voice vote.**

106 Camino Santiago: Likely the third unit to be constructed at Plaza del Monte, 106 Camino Santiago is a 2,031 square foot dwelling with a portal across two elevations (north and east). In plan, it has an L-shaped foundation with an attached carport. The flat-roof dwelling holds three bedrooms confined to a wing at the west end. The rear (south) elevation is focused on a small patio cut into the southwest corner of the home. The southeast corner is terminated by a one-space carport. The two-sided portal runs along the north and east elevations. The structure is made of vigas which sit on square girders held up by round posts with corbels. The portal elevations are painted white and fenestrated with doors on each exposure. Small rectangular windows penetrate the bedroom wing. The remaining windows vary, including large picture and grouped

casements and sliding units. The roof is finished with rolled asphalt which carries over the inner parapets. A squat stucco-faced chimney rises at the northeast corner. The house is finished with textured cementitious stucco in a light buckskin tone. The residence was constructed in c.1965. Its designer is unverified but is suspected to be an early Clark and Register design. Contributing status is recommended for this presently non-statused residence, as it may represent an original Clark and Register design template for Plaza del Monte, and the house is a good example of a mid-century expression of Santa Fe Style. If contributing status is assigned to the residence, the north and east facades are recommended as primary.

Ms. Roach added that the reasons for Contributing are in the report and the Board can just refer to those, if desired.

Board Discussion

Member Katz agreed with the Staff recommendation, "but looking at the photos, to have the historian say some are contemporary style and then say this is real Santa Fe style makes my head spin."

Member Larson described this as a modernist building and not contemporary. Contemporary is not even a relevant term.

Public Comment

There were no speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: **Member Biedscheid moved, seconded by Member Larson, in Case #H-19-019 at 106 Camino Santiago, to designate the property as Contributing with north and east façades as primary for reasons stated in the Staff report.**

VOTE: **The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.**

109 Camino Santiago: Composed of a series of angled walls, the carport dominated residence was constructed in 1966, after a design by architect Phillipe Register. The

house presents to the street a tall and wide carport framed with a viga roof. The west end of the carport is sheltered by a double splayed wall. The angled wall composition is echoed across the east elevation. In plan, the residence is roughly an L with its form obscured by the carport. The approximately 1,220 square foot dwelling holds two bedrooms in a cube-like mass anchoring the east end. Between the bedroom mass and carport is a small enclosed patio and portal sheltering the main entry and a pair of oversized wood windows. The rear (north) elevation has a small viga canopy protecting a patio door. A tapered chimney breaks the wall plane on this elevation. Fenestration consists of mainly aluminum windows. The frame structure is finished with cementitious brocade stucco in the buckskin tone. The contemporary style home was constructed in 1965 and is one of the earliest residences to be constructed in Plaza del Monte. The architectural historian recommends non-contributing status for this residence, due to its contemporary design which does not harmonize with the district. However, the Board may consider that its association with architect Phillipe Register and with the Plaza del Monte planned development could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the south façades are recommended as primary.

Public Comment

Mr. Eddy (previously sworn) thought the south façades should be primary. In the bottom photo, Staff referred to it as a viga roof.

Ms. Roach said it is a viga canopy.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Ms. Roach said there are multiple façades on the south and wanted to verify.

Action of the Board

MOTION: Member Guida moved, seconded by Member Katz, in Case #H-19-019 at 109 Camino Santiago, to give the structure a Contributing status with south facing façades 1, 2, 3, 4, and 5 as primary.

He did not agree with John Murphy recommendations and saw this as one of the best examples of his work.

Member Larson added that the original features are still featured such as carport and that adds to the reasons why it is contributing.

VOTE: The motion passed by majority (5-1) voice vote with Members Biedscheid, Katz, Guida, Larson, and Lotz voting in favor, and Member Roybal voting against.

110/112 Camino Santiago: Located at the west end of the common area are two residential units which were joined together at some point after 1970. The older unit, addressed as 110 Camino Santiago, takes up the east end of the footprint. Constructed in c.1962, after a design by architect Kenneth S. Clark, it is roughly an L-shaped box with a rear portal and connected carport. The street facing façade (north) is defined by a small recessed entry. The remainder of the façade is divided into rectangular window openings holding sliding units. Smaller, rectangular sliding windows are applied across the east bedroom wing. A shallow portal runs across the rear (south) elevation historically leading to a single-space carport. The portal elevation is fenestrated with a patio door, sliding windows, and a louvered door leading to a utility room. The house is outlined by parapets and finished in buckskin cementitious stucco. It holds three bedrooms. Attached to the west end of the original Clark design is a post-1966 addition. Arranged at a lower height, the approximately 864 square foot appendage is a rectangular box with overhanging eaves and a porch. The addition, most likely designed by architect Philippe Register, introduces a contemporary vocabulary. A shallow overhang supported by squared rafters carries across the north and south elevations. Similar beams extend out from the west elevation to create the porch. A tall angular wall rising above the roofline defines its south edge. The addition is fenestrated with a few doors and square window openings, holding single-light metal casements. Most likely occurring with the addition, the carport was widened (or constructed anew) to hold two vehicles. Set back from the addition, the roughly 1,054 square foot structure is supported by a viga and post system. Due to substantial changes to the massing and appearance of the structure when two residences were combined and carport added and subsequently widened, noncontributing status is recommended for this residence.

Ms. Roach showed additional photos.

Board Discussion

Member Katz said, in looking at the two façades, the top was classic standard, but the bottom seems totally Santa Fe style.

Member Larson didn't see integrity but contemporary on the north façade, so she agreed with Mr. Murphy.

Public Comment

Mr. Eddy (previously sworn) thanked staff for the other photos. He agreed with

Member Larson that the north façade degrades the house. But all the others show interesting character strengthening a Contributing status. And the portal work is important. He would consider that Contributing, excluding the north elevation.

Mr. Ken Rawie, 112 Camino Matias, was sworn. He pointed out that most of the pictures are of 110 and not 112. There was no picture of 112 Camino Santiago - north and south. The bottom photo shows the background of the carport. The resident there moved out just recently.

Ms. Roach said 110 and 112 are joined physically, so there is only one status for both.

Chair Rios understood, but as Mr. Eddy pointed out, if it is made Contributing, The Board could identify non-historic façades.

Ms. Roach agreed - or designate primary excluding nonhistoric portions.

Member Biedscheid did not believe there were any nonhistoric portions.

Ms. Roach agreed but asked the Board to consider 110 and 112 as one structure though from two different architects and thinking about harmony that they would work.

Action of the Board

MOTION: **Member Biedscheid moved, seconded by Member Guida, in Case #H-19-019 at 110/112 Camino Santiago, to designate 110/112 as Contributing because it has the original footprint and the alterations are historic, because it is associated with Register and recommended that the south and west façades be designated as primary.**

VOTE: **The motion passed by majority (5-1) voice vote with Members Biedscheid, Katz, Guida, Larson, and Lotz voting in favor, and Member Roybal voting against.**

111 Camino Santiago: Arranged at an east-west orientation, the house is a one-story, approximately 1,616 square foot, flat-roof dwelling erected in c.1965. The dwelling has an L-shaped plan with its two bedrooms confined to a rectangular wing at the west end. The remaining house holds the living room, kitchen and dining area. The front (south) façade is marked by a long portal which continues across to an attached one-bay carport. The portal shelters the front entry and a sliding patio door. The structure is supported by round poles holding a viga roof. The house is fenestrated with common windows, most of them appearing to be replacement units. It is entered through a raised

wood panel door flanked on one side by a sidelight. The rear (north) elevation contains a few windows and a door sheltered by a shallow viga-supported visor. A tapered chimney breaks through the visor, terminating with a terra cotta cap. The frame building is finished in a smooth cementitious stucco in a buckskin tone. The flat roof is covered with asphalt, which carries over the east exposure to the bedroom wing. While contemporary in form, the vigas used across the portal give the residence a Spanish-Pueblo Revival feel. The placement and restrained size of the carport helps maintain the regional tradition. The building was constructed after a design by architect Phillipe Register. Contributing status is recommended for this structure, as it represents an original design template by Clark and Register for Plaza del Monte and because it is an example of mid-century expressions of Santa Fe Style. If the Board finds this structure to be contributing, the south façade is recommended to be primary.

Member Guida saw that this is virtually the same as 103.

Ms. Roach agreed.

Public Comment

Mr. Eddy (previously sworn) pointed out the sidelights on the entry door. He would like to see it contributing because that angled element contributes greatly to the whole development.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: **Member Katz moved, seconded by Member Larson, in Case #H-19-019 at 111 Camino Santiago, to assign Contributing status for reasons in the Staff report and designating the south façade as primary.**

VOTE: **The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.**

113 Camino Santiago: Sitting on a slight rise, the house shares a party wall at the carport with its neighbor at 115 Camino Santiago. The roughly 1,281 square foot dwelling contains two bedrooms arranged at the front of the structure in a small L-shaped volume. The remainder of the footprint holds the living functions of the house. It presents to the street two room block-like volumes penetrated by horizontally oriented

aluminum casement windows. A viga-framed carport and short portal terminate the west end of the footprint. The house is entered through a raised wood panel door with a center view light. The rear (north) elevation has a few windows and a sliding glass door. A shallow overhang supported by square wood beams carries across the elevation. The frame dwelling is finished in cementitious peach color stucco worked into a brocade pattern. Tall parapets outline the perimeter of the bedroom wing. The roof is covered in asphalt which carries over the west exposure of the bedroom mass. It was erected in c.1970, and its designer/architect is unknown. Noncontributing status is recommended for this structure due to its age slightly under 50 years. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the south façades are recommended as primary.

Board Discussion

Member Larson disagreed with historian evaluation. She believed it is contributing for mid-century modern and, in comments, the flagstone is very characteristic.

Ms. Roach noted in looking at it and previous action on 110/112 - that 113 and 115 are actually joined, as well. Each footprint is quite distinct. Jointed by a party wall. So you might assign status to the structure as a whole.

Member Guida said, at 115, he would argue in favor of considering duplexes as one.

Ms. Roach said the description of 115 is almost identical and the rec was the same - slightly under 50 years as the primary reason for noncontributing status. Otherwise is almost identical.

115 Camino Santiago: Sharing a wall with the dwelling to the east (113 Camino Santiago), the small house contains two bedrooms. The dwelling portion of the building is composed of a rectangular bedroom wing. Attached to this are the living room, kitchen, and a one-space carport. Connecting these elements is a beam portal. Together, both areas hold about 1,290 square feet. The front (south) façade presents a simple canvas of a projecting mass balanced on one end with the void of the carport at the other. In between is the portal with its few window and door openings. The portal is supported by double round posts topped with corbels. The rear (north) elevation contains a few windows and a sliding glass door sheltered by a shallow viga-supported overhang. The windows in the residence are tall, single-light aluminum casements. A raised panel-and-view-light door gives entry to the dwelling under the portal. Short parapets outline the perimeter of the bedroom wing. The roof's asphalt material carries over the east exposure of the parapet. The house was erected in c.1970, and the designer/architect is unknown. Noncontributing status is recommended for this structure

due to its age slightly under 50 years. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the south façades are recommended as primary.

Member Biedscheid asked if they were constructed together.

Ms. Roach thought so.

Public Comment (on 115)

Mr. Eddy (previously sworn) considered 113 and 115 as one structure. He was pleased with term "party wall" which is really applicable here and he would like to see them considered as one.

Ms. Pryor (previously sworn) said, in looking at the construction date on the report, that "c" means around or circa. On the second amendment by Murphy, it looks like, and he states there that 113 is c 1970 and doesn't appear on the 1969 aerial. So he thought it was built in 1970 because it did not show up on the aerial, but it is pretty close.

Ms. Roach showed added photos - first of 113.

Mr. Eddy pointed out on the east elevation, that it showed a vertical fenestration on the windows which was a prominent element in the big Casa Grande that was demolished. That was a classic element in that building and replicated here.

Member Guida commented this as very interesting, with buildings very close and massing for four units with a slight variation.

Member Katz thought this was approximately 50 years old.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: Member Guida moved, seconded by Member Larson, in Case #H-19-019 at 113/115 Camino Santiago, to designate them Contributing with south facing façades as primary.

VOTE: The motion passed by majority (4-2) voice vote with Members Katz, Guida, Larson, and Lotz voting in favor, and Members Biedscheid

and Roybal voting against.

Ms. Roach asked for reasons to be included.

Member Guida said it is approximately 50 years old and represents mid-century Santa Fe style and is the work of Clark and Register.

Member Larson added that it exhibits character-defining features of the flagstone paving to the carport and the vertical divided windows.

Ms. Roach added that it has block massing on both sides.

Member Katz added that the aerial photograph was from February 1969, so it was probably being built in 1969.

114 Camino Santiago: The house presents to Camino Santiago a traditional design of a cube-like mass projecting from a linear arm. In plan, it is roughly L-shaped with a large connecting carport attached to its southeast corner. The west end holds two bedrooms; the remainder of the footprint contains a large living room, kitchen and utility closet. The south exposure of the bedroom wing is penetrated by sliding glass doors. East of the bedroom wing, the front façade (north) is divided into a recessed entry and a large casement-framed picture window. The entry holds a raised square panel wood door with center view light. It is sheltered by a short overhang resting on vigas. A similar combined picture and casement window is found on the east elevation of the living room. The carport makes up most of the secondary street elevation (north, set back). It is supported by a wood viga-and-post system. The structure shelters a patio door and single raised panel wood door leading to the utility room and storage area. Wood, trough-like canales penetrate the parapets on the east and west elevations. The roof is covered in rolled asphalt, which carries over the bedroom wing's east exposure. A short stucco-clad chimney topped with a terra cotta cap rises from the center of the roof. Erected in c.1972, the residence was designed by Register, Ross & Burnett Architects. Noncontributing status is recommended for this structure due to age. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the north façades are recommended as primary.

Member Larson said, although under the 50-year rule, we see the same elements repeated and the picture window, which is one example of mid-century modern and she would recommend contributing.

Public Comment

Mr. Eddy (previously sworn) pointed out an element that recurs in these buildings and Register's work. It is the use of double and triple posts under corbels and he assumed it was Mr. Register's innovation that probably was controversial.

He added, "When my father did a remodel of our house on Camino del Monte Sol, he did that too. So it really stuck as an innovation and adds to our vernacular style over time."

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Ms. Roach showed photos of the north, street-facing and east side containing the portal feature.

Member Larson appreciated Mr. Eddy pointing that out.

Action of the Board

MOTION: Member Larson moved, seconded by Member Guida, in Case #H-19-019 at 114 Camino Santiago, to designate the structure as Contributing because of mid-century modern exhibited through picture window and carport and designate north and east as primary.

Discussion on the Motion

Ms. Roach said the south elevation contains the picture window and the east.

Mr. Rawie clarified, as the next-door neighbor, that the north façade is on Camino Santiago and the east façade is facing Camino Matias. So the bottom photo with picture window is on the east side and the top picture is the north side.

Member Roybal commented that we are really pushing the 50-year rule on this house.

Member Biedscheid thought the Board should have justification for the age.

Member Larson argued that this exception is in character-defining features such as picture window, car port and double posts.

VOTE: The motion resulted in a tie vote with Member Larson, Member Guida, and Member Lotz voting in favor and with Member Roybal,

Member Katz and Member Biedscheid voting against. Chair Rios voted in favor, breaking the tie. The motion passed by 4-3 voice vote.

117 Camino Santiago: Tucked into the northwest corner of the development, the house is a single-story, flat-roof dwelling characterized by its viga carport and continuous overhang. In form, its two box-like volumes are arranged in a modified L-plan. The house holds two bedrooms slung along the west wall. A large living room occupies the foot of the L. With its carport included, the house contains 1,422 square feet. The unarticulated flat front façade is penetrated by non-historic casement windows. A wood panel and view light door gives entry to the dwelling under the front portal. The rear (west) elevation is fenestrated with an asymmetrical pattern of tall aluminum casement windows. The frame building is finished with brocade-type stucco rendered in the buckskin color. It was constructed in 1966-67, after a design by architect Philippe Register. Window replacements appear to have removed the pedimented heads shown on Register's drawings. Noncontributing status is recommended due to contemporary design that the architectural historian did not feel harmonized with the district. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the east (street-facing) façades are recommended as primary.

Ms. Roach said this building has an interesting modified L plan on an angle, not 90 degrees.

Public Comment

Mr. Eddy (previously sworn) said it is not truly an L-shape but a deliberate statement of the architect whether to the landscape or the way it fits but makes for an interesting house. The viga canopy in the lower photo contributes to the neighborhood architecturally.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Board Discussion

Ms. Roach believed the lower photo was the rear elevation and the upper was of the east façades #1 and #2. The recommendation for primary is 1 and 2 on the east. The south is 7, if the Board wants more carport.

Member Guida thanked Mr. Eddy for pointing out the modified L. While it is not the most beautiful or compelling design, it is interesting to look at the development as kind of laboratory. As a consequence, we have a span of how the architect figured it out and particularly one who is exploring what is possible with the limitations in Santa Fe. So a really compelling example of Santa Fe style. Not the prettiest but important.

Member Larson said the new windows diminish the character. But thanks to Mr. Eddy for pointing out the boomerang shape. In the aerial view you can see it is quite specific and balancing with the landscape. That would necessitate Contributing status.

Action of the Board

MOTION: **Member Guida moved, seconded by Member Biedscheid, in Case #H-19-019 at 117 Camino Santiago, to designate the structure as Contributing with the east façade as primary for the reasons in the Staff Report, that it is a significant expression of mid-century design and that it contributes to the plaza complex.**

Member Biedscheid requested the south façade to be primary to capture the carport (#7). Member Guida accepted the amendment as friendly.

VOTE: **The motion passed by majority (5-1) voice vote with Members Biedscheid, Katz, Guida, Larson, and Lotz voting in favor, and Member Roybal voting against.**

118 Camino Santiago: Erected in c.1973, the stucco-over-frame, two bedroom house sits on a rise at the southeast corner of Camino Santiago and Camino Matias. In plan, it is a modified L shaped structure with a carport attached to its front (north) façade. The roughly 1,245 square foot dwelling has its bedrooms segregated to a wing across the west elevation. This volume is taller than the rest of the house and is outline with parapets. The lower volume contains a living room, kitchen and dining area. The north (front) façade is divided between the carport and the north face of the bedroom wing. The single carport is erected over a wood structure supported by round posts. The outside beam continues across the façade, sheltering the front entry. As with the door under the carport, the entry holds a raised square panel unit. The secondary elevations are fenestrated with single-light metal casement windows. The south (rear) elevation has an array of casement windows and an enclosure giving access to the carport. A shallow overhang resting on vigas outlines the elevation. The house is finished with cementitious brocade stucco in a peach pigment. The roof is covered with rolled asphalt, which carries over a portion of the bedroom wing's east exposure. Large, trough-like wood canales pierce the west parapet. It was designed by Register, Ross & Burnet Architects, and is one of the last houses to be completed in Plaza del Monte. Noncontributing status is recommended for this residence by the architectural historian,

due to age. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the north façades are recommended as primary.

Member Larson asked if it is a planter in the bottom photo.

Ms. Roach believed so.

Member Larson thought since it is a last completion, it is an evolution and she had not seen a planter. That planter does harmonize with the landscape.

Member Katz did not think it is of exceptional importance. It should be part of the compound, but he did not see it as very special. It fits in but is not the Guggenheim Museum.

Mr. Gemora believed they had planters on Camino Matias.

Public Comments

There were no speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: **Member Katz moved, seconded by Member Roybal, in Case #H-19-019 at 118 Camino Santiago, to designate the structure Non-Contributing.**

VOTE: **The motion resulted in a tie vote with Member Roybal, Member Katz and Member Biedscheid voting in favor and Member Lotz, Member Larson and Member Guida voting against. Chair Rios voted in favor, breaking the tie. The motion passed by 4-3 voice vote to designate 118 Camino Santiago as Non-contributing.**

119 Camino Santiago: Arranged slightly above grade, the box-like house is characterized by its continuous portal and horizontal emphasis. In plan it is a compact rectangle framed by angled walls on its north and south exposures. Large windows, a wood panel door and a three-panel sliding glass door appear on the front (east) façade. The rear (west) elevation has double sets of sliding windows and a patio door arranged under an overhang. The house's windows appear to be mostly replacement units. The

south end of the dwelling is weighted with a large carport. A tall double splayed wall creates the south exposure. The portal is supported by vigas resting on a square beam. Round posts topped with double ended corbels carry the weight to the floor. The roughly 1,485 square foot structure contains two bedrooms placed along the west wall. The building was constructed in c.1965, after a design by architect Phillipe Register. The main alteration is the removal of most of the angled wall along the northeast corner. Originally, this feature enclosed a small patio. Noncontributing status is recommended for this structure due to contemporary design that the architectural historian did not feel harmonized with the district. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the east (street-facing) façade is recommended as primary.

Chair Rios noted this one is 54 years old.

Member Guida said this is an exceptional one in the community and echoed what we say with 109 in plan. And in particular, it is an expression of long and low with carport and it projects across the front of the house.

Member Larson pointed out that they used a lower wall along the front to shelter the entryway and that is characteristic of mid-century and also a shelter. So it is part of Santa Fe style and mid-century modern.

Public Comment

Mr. Eddy (previously sworn) mentioned for the record in previous testimony that the Presbyterian organization, in planning these structures for residents, gave input on what they wanted to see in the house. So it was a contributing element at the patio wall and might have been the case here.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: **Member Guida moved, seconded by Member Biedscheid, in Case #H-19-019 at 119 Camino Santiago, to designate it Contributing with east (#1) and south (#4) as primary elevations. It is more than 50 years old and represents a clear expression of mid-century modern architecture.**

Member Biedscheid added that the east façade has a low projecting viga element.

Member Larson said the wall in front of the entry is part of the façade and significant in design.

Member Guida accepted both statements as friendly.

VOTE: **The motion passed by majority (5-1) voice vote with Members Biedscheid, Katz, Guida, Larson, and Lotz voting in favor, and Member Roybal voting against.**

120 Camino Santiago: The small two bedroom house presents a contemporary carport-dominant design. Located along the east side of Camino Santiago, it sits back from the street. In plan, it is a modified T form with an attached carport projecting from the front (west) façade. Its two bedrooms are confined to a wing making up the north elevation. Higher than the rest of the house, it is outlined with shaped parapets. The parapets are pierced with canales across the north and south exposures. The lower volume, historically containing a living room, kitchen and music room, is faced with a shallow overhang resting on vigas. The overhang shelters sliding glass doors, a window and a pedestrian entry. The secondary elevations are fenestrated with aluminum casement windows. The front (west) elevation is dominated by the carport. The structure is erected over a viga-and-post support system. The portal's outside beam continues across the façade, sheltering the front (west) entry. A wood raised square panel door with a center view light gives entry to the residence. Including its carport and utility room, the building contains 1,804 square feet. The house was built in c.1971 after a design by Register, Ross & Burnet Architects. Noncontributing status is recommended for this structure due to age. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the west (street-facing) façade is recommended as primary.

Chair Rios considered it nonconforming and noncontributing.

Member Guida highlighted the carport and outdoor storage rooms as period-defining elements.

Public Comment

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: **Member Biedscheid moved, seconded by Member Roybal, in Case #H-19-019 at 120 Camino Santiago, to designate the property Non-contributing, based on its age.**

VOTE: **The motion failed (3-4) with Members Larson, Guida, Biedscheid and Chair Rios voting no.**

MOTION: **Member Guida moved, seconded by Member Larson, in Case #H-19-019 at 120 Camno Santiago, to designate the property as Contributing because it presents a clear expression of mid-century modern style with carport, storage rooms and overall massing and is approximately 50 years of age, and designating the west facing façades #1 and #2 as primary.**

VOTE: **The motion resulted in a tie vote with Member Guida, Member Larson and Member Lotz voting in favor and Member Roybal, Member Katz and Member Biedscheid voting against. Chair Rios voted in favor, breaking the tie. The motion passed by 4-3 voice vote.**

121 Camino Santiago: Reflecting a carport-dominant design, the small vernacular dwelling sits at grade on the west side of Camino Santiago. The roughly 1,309 square foot structure holds one bedroom. In plan, it is a compact square enclosed by an angled wall across its south exposure. Unlike most units in Plaza del Monte, it has a low pitched roof. The front (east) façade is dominated by the one-vehicle carport. The remainder of the façade is divided into windows and doors. The windows are uniformly multi-light steel casements in various standard sizes. The gabled north elevation has three identical windows. The rear (west) side of the house has more articulation, expressed through its beamed canopy over a pair of sliding doors. The frame house is finished with heavy brocade cementitious stucco in a peach like color. A shallow square-beam supported overhang runs along the east and west elevations. It was constructed in c.1971, after a design by Register, Ross & Brunet Architects. Noncontributing status is recommended for this structure due to age and contemporary design that the architectural historian did not feel harmonized with the district. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the east (street-facing) façade is recommended as primary.

Member Roybal was concerned with this recommendation. We are really pushing the 50-year rule.

Member Larson noted the casement windows with three divisions are really unique and she has only seen them twice - just to take note of that.

Public Comment

Ms. Pryor (previously sworn) said this house is not one big room. It has an extra room that might be a library, a den or a music room.

Ms. Roach showed the south elevation and the low angled pitched roof, and the west elevation.

Mr. Eddy (previously sworn) pointed out the storage cabinets within the car port we've seen before.

Member Larson noted the south elevation with the portal is a theme repeated throughout town and is an interesting feature to take into account.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: Member Katz moved, seconded by Member Biedscheid, in Case #H-19-019 at 121 Camino Santiago, to designate the property Non-contributing because of its age.

VOTE: The motion failed (3-4) with Members Larson, Guida, Lotz and Chair Rios voting no.

Chair Rios asked for another motion.

MOTION: Member Larson moved, seconded by Member Guida, in Case #H-19-019 at 121 Camino Santiago, for Contributing status with east (#1) and south (#4) façades as primary. This is an exception to the 50 - year rule because of exceptional design as mid-century, use of casement windows, and storage features reflecting the era and its association Register.

VOTE: The motion resulted in a tie vote with Member Guida, Member Larson and Member Lotz voting in favor and Member Roybal, Member Katz and Member Biedscheid voting against. Chair Rios voted in favor, breaking the tie. The motion passed by 4-3 voice vote.

104 Camino Matias: One of the first units to be constructed at Plaza del Monte, 104 Camino Matias is an L shaped dwelling with a combined carport and portal. The approximately 1,143 square foot, flat roof structures holds two bedrooms. The bedrooms are placed in a wing forming the north end of the residence. Its front (west) façade presents a Spanish-Pueblo Revival plan, with its cubic, battered mass and viga roofed portal. Unlike many houses in the development, the carport plays a secondary role on the façade. The single-bay structure, arranged behind the portal, is less exuberant in its display of wood elements. The bedroom mass is fenestrated with small, rectangular windows; the remaining elevations have windows arranged in a more traditional pattern. The windows are mostly aluminum casement units. The portal elevation is painted white. A line of vigas runs along the top of the wall. It is supported by shiplap wood girders resting on round posts with corbels. The house was constructed in c.1965. It represents the closest interpretation of the original 1960 Kenneth S. Clark and Phillipe Register template design for the development. Contributing status is recommended for this residence, due to its early date of construction and representation of the original Clark and Register design template for Plaza del Monte retirement homes and due to its exemplary expression of mid-century Santa Fe Style. The west façades are recommended as primary.

Public Comment

Mr. Eddy (previously sworn) said, although it appears unremarkable, it is very important that it represents the original template from which the others grew.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Ms. Roach corrected that the front façade may be misrepresented. It is #1, for the front and façades on Camino Matias (Northwest). It is shown correctly on page 32 of the packet.

Action of the Board

MOTION: **Member Katz moved, seconded by Member Roybal, in Case #H-19-019 at 104 Camino Matias, to designate the property Contributing for reasons stated in the report and with façade #1 as primary.**

Member Biedscheid asked for #4 to also be primary as unique to the property. Member Katz accepted #4 as primary.

VOTE: The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.

105 Camino Matias: This small house is one of three units constructed in 1950 for married staff employed by the Allison James School. Arranged in a terrace-like fashion, each unit is a rectangular plan, side-gabled dwelling with an attached garage. The house has a telescoping roof form evident in its north exposure. The roof extends over the walls on the north and south elevations to form small porches. The house is fenestrated with a mix of original and non-historic windows and doors. The windows are terminated with stuccoed concrete sills. Views from the house are oriented north toward the commons area. The north elevation contains a large picture window flanked by casements. Public entry is through an original ½-glass wood door on the south elevation. The garage door is a recent vinyl paneled unit. The roof is covered with three-tab asphalt shingles. Wood fascia has been applied to the north and south roof ends, obscuring (or removing) the original exposed rafters. A short stuccoed chimney rises from the north roof slope. The approximately 1,102 square foot house holds three bedrooms. A non-historic, 220-square foot carport has been erected over the driveway. Non-contributing status is recommended for this structure. As the architectural historian states, the house neither harmonizes with the district nor with Plaza del Monte and includes non-conforming elements such as corner windows and cantilevered canopies over entries. Its association is with the Allison James School (demolished in 1960) rather than with Plaza del Monte. Staff agrees with this assessment.

Member Guida said this one and the next few properties are all associated with the school. He asked if that was correct.

Ms. Roach explained that 105, 107 and 109 Camino Matias are associated with the Allison James School, but 111 was moved to this site prior to 1960 and is not part of the same construction episode.

116 and 120 Camino Santiago were also associate with the school but later in 1957.

Member Katz considered this property a tough one. They have a similar history with the Presbyterian school and were incorporated. It maybe is not the same style but shows the history.

Member Larson appreciated seeing this in the neighborhood that showed the immediate style - much simpler and vernacular from the others. But she was not seeing character-defining elements here. So she recommended Non-contributing status.

Member Biedscheid observed there is a mix of original windows. It is an anchor for the compound around green space. And associated with the Presbyterian Church to provide living facilities and she thought it should be Contributing.

Member Guida said one strong argument is the stature of the architect and quality of design on Camino Santiago. On declining blocks and post war architecture. Its connection with Santa Fe Style is pretty weak and they don't read as connected with the rest of the development. It doesn't have all the points to make.

Public Comment

Ms. Pryor (previously sworn) said, according to her notes, they were all associated with Allison James teachers. She asked that the Board consider that association. It is what these houses represent. When they were here, those other houses were not built and their front porch was on the north-facing side, not the street-facing side.

Mr. Eddy (previously sworn) had to agree with all that has been said. They are conflicting but the points of view are valid, and the historicity is what is important. They are associated with Allison James School and what detracts are the alterations. The footprint and pitched roofs are important. It is the pitched roofs here that are important and derivative of the pitched roof of the Allison James School. So he recommended Contributing with their historicity and association with the school and he stated for the record that these other photos show a lot more character to be explored.

The Presbyterian organization was important for Santa Fe and throughout northern New Mexico which has a very detailed history in Chimayo.

Ms. Carol Rawie was sworn and mentioned "As you can see from the map. the façades on the green area is what you see when you walk around from Bishop's Lodge Road and what most people see, which is different than along the alley in the back."

Chair Rios did not think those were meant to have Santa Fe style.

Member Larson agreed. "After seeing more images, I agree that this style - they were just trying to do it as part of the school."

Action of the Board

MOTION: **Member Biedscheid moved, seconded by Member Katz, in Case #H-19-019 at 105 Camino Matias, to designate it as Contributing, based on age of the structure and the defining character of concrete sills, pitched roofs, windows and orientation as reference points to streets and spaces and with the north façade as primary.**

Member Katz added that it clearly is not Santa Fe style but an important historic style for this area and the history of it.

Member Biedscheid mentioned association with Allison James School.

VOTE: **The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.**

107 Camino Matias: This small house is one of three units constructed in 1950 for married staff employed by the Allison James School. Arranged in a terrace-like fashion, each unit is a rectangular plan, side-gabled dwelling with an attached garage. The gabled roof extends over the walls on the north and south elevations to form small porches. The dwelling is fenestrated with a mix of original and non-historic windows, terminated with stuccoed concrete sills. Views from the house are oriented north towards the commons area of Plaza del Monte. The north elevation contains a large picture window flanked by casements. Public entry is through an original ½-glass wood door on the south elevation. Two vertical [solar?] panels have been applied to the south façade. The garage door is recent vinyl paneled unit. The roof is covered with three-tab asphalt shingles. Wood fascia has been applied to the north and south roof ends, obscuring (or removing) the original exposed rafters. A short stuccoed chimney rises from the north roof slope. The house originally had an exposed pedimented entry on the north elevation, which was reduced at some point in depth after 1969. The approximately 1,145 square foot house holds two bedrooms. As the architectural historian states, the house neither harmonizes with the district nor with Plaza del Monte and includes non-conforming elements such as corner windows and cantilevered canopies over entries. Its association is with the Allison James School (demolished in 1960) rather than with Plaza del Monte. Non-contributing status is recommended for this structure, and staff agrees with this assessment.

Public Comment

There were no speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: **Member Biedscheid moved, seconded by Member Guida, in Case #H-19-019 at 107 Camino Matias, to designate it Contributing. based on its association with Allison James School, pitched roof, concrete sills and large picture window similar to 105 and 109 Camino Matias, with the north façade as primary.**

VOTE: **The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.**

109 Camino Matias: This small house is one of three units constructed in 1950 for married staff employed by the Allison James School. Arranged in a terrace-like fashion, each unit is a rectangular plan, side-gabled dwelling with an attached garage. The house has a telescoping roof form evident in its north exposure. The roof extends over the walls on the north and south elevations to form small porches. The front (south) façade reveals an altered composition. At some point after 1960, a 131 square foot addition was appended to the southwest corner creating a sunroom. The dwelling is fenestrated with a mix of original and non-historic windows, which are mostly double hung sash and are terminated with stuccoed concrete sills. Views from the house are oriented north toward the Plaza del Monte commons area. The north elevation contains a large picture window flanked by casements. Public entry is through an original ½-glass wood door on the south elevation. The garage door is a recent vinyl paneled unit. The roof is covered with three-tab asphalt shingles. Wood fascia has been applied to the north and south roof ends, obscuring (or removing) the original exposed rafters. A short stuccoed chimney rises from the north roof slope. The approximately 1,141 square foot house contains two bedrooms. As the architectural historian states, the house neither harmonizes with the district nor with Plaza del Monte and includes non-conforming elements such as corner windows and cantilevered canopies over entries. Its association is with the Allison James School (demolished in 1960) rather than with Plaza del Monte. Non-contributing status is recommended for this structure, and staff agrees with this assessment.

Public Comment

Mr. Eddy (previously sworn) suggested Contributing except for the addition on the south elevation.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: **Member Larson moved to designate the property as Contributing due to age of building, association with Allison James School and primary be the #4 - north front of the building, and on the south - 1 and 2.**

The motion died for lack of a second.

MOTION: **Member Biedscheid moved, seconded by Member Larson, in Case #H-19-019 at 109 Camino Matias, to designate the structure as Contributing, based on age, character of pitched roof, sills, association with Allison James and with the north façade as primary.**

Member Larson added the casement windows as character-defining.

VOTE: **The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.**

111 Camino Matias: Moved to the site prior to 1960, 111 Camino Matias is an altered three bedroom house. The house is arranged on a north-south axis, facing west, and in plan consists of two telescoping gabled sections. To this basic form was added an L-shaped porch and connected carport in c.1966. The medium pitch roofs are covered with asphalt shingles and extended with overhangs. A short stuccoed chimney rises from the ridgeline. Small wood louvers are attached to the gabled ends. The house is fenestrated with an array of original and non-historic windows, recessed from the walls and terminated with concrete sills. The combined porch and carport are supported by a framework of wood girders resting on grouped square posts. The single carport includes double storage units. A short breezeway leads from the carport to a back door. The 1,712 square foot house is finished with textured cementitious stucco in a light buckskin color. Non-contributing status is recommended for this residence. It was moved to the site before 1960 and extensively modified in 1966 with the addition of the carport and portal. As with the other Allison James School-era residences on Camino Matias, the house neither harmonizes with the district nor with Plaza del Monte, and its association is with the Allison James School rather than Plaza del Monte.

Member Larson commented that moved structures are always tricky with many different angles. I am not sure where I stand. It exhibits characteristics that are interesting but not sure it needs to be contributing. I'd like to hear from others on it.

Public Comment

Mr. Eddy (previously sworn) said what is interesting is that the portals were added after it was moved here. He asked if this was the first iteration of double posts. He wondered if it was before Register got his license.

He pointed out that the roof line is classic northern New Mexico style. The other thing is the little storage cabinets under the portal. Could it be Philippe Register before he got his license.

Ms. Roach said they are post-1966 so he had his license then.

Mr. Eddy (previously sworn) felt they were interesting details there.

Ms. Pryor (previously sworn) stated that this was the Principal's house.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: **Member Biedscheid moved, seconded by Member Katz, in Case #H-19-019 at 111 Camino Matias, to make it Contributing with the west elevation and south as primary (front entire portal).**

VOTE: **The motion passed by majority (5-1) voice vote with Members Biedscheid, Katz, Guida, Larson, and Lotz voting in favor, and Member Roybal voting against.**

116/120 Camino Matias: The vernacular, two unit residence was erected before 1957 and modified nearly 30 years later with the addition of a cross-gabled entry. The combined residence is aligned along a north-south axis on the west side of Camino Matias. In plan, it is a side-gabled rectangle with a cross-gable appended to its northeast corner. The north unit (120) holds about 1,256 square feet with three bedrooms. A window wall spanning the northeast corner signals its contemporary design. The north elevation under the gable is marred by a c.1984 shed-roof structure enclosing the furnace and water heater. The front façade faces east and is dominated by the non-historic cross gable entry. A recessed entry at the south end leads to 116. The interior, encompassing approximately 939 square feet, is arranged like an apartment. A similar non-historic stuccoed enclosure around the furnace and water heater is attached to the south elevation. The rear (west) elevation of the combined units faces onto a common area. A continuous overhang characterizes this façade. It is penetrated with three sliding glass doors and a mixture of fixed and sliding windows of different sizes. The roof is sheathed with rib metal panels. It is unclear who designed the original house. The c.1984 addition of the cross gable and furnace and water heater enclosures was drawn in Phillipe Register's shop. Built prior to 1958 and substantially modified in the mid-1980s, the historic integrity of the house has been compromised, and the style of the home neither harmonizes with the district nor with Plaza del Monte. As with the other Allison James School-era residences on Camino Matias, the house neither harmonizes with the district nor with Plaza del Monte, and its association is with the Allison James School rather than Plaza del Monte.

Board Discussion

Member Larson would be interested in knowing the further association with the school. It is in harmony with 1950s.

Member Katz felt it was modified too much in 1980's to qualify for contributing.

Member Roybal agreed with Member Katz. The whole house seems out of character.

Public Comment

Ms. Pryor (previously sworn) said this was teacher housing and on the east side, there is a notice above the door that it was Auburn Cottage even though divided into two apartments.

Mr. Rawie clarified that it is two bedrooms, not three.

Mr. Eddy (previously sworn) was sorry we are at the end of this because it has been very enjoyable. He would encourage nonconforming or noncontributing because it does not have double posts.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: **Member Katz moved, seconded by Member Larson, in Case #H-2019-19 at 116/120 Camino Matias to designate the property as Noncontributing due to 1980's modifications.**

VOTE: **The motion passed by majority (5-1) voice vote with Members Biedscheid, Katz, Guida, Lotz and Roybal voting in favor, and Member Larson voting against.**

Consideration of Compound Status:

MOTION: **Member Katz moved, seconded by Member Larson, in Case #H-19-019 at 101, 102, 103, 105, 106, 109, 110, 111, 113, 114, 115, 117, 118, 119, 120, 121 Camino Santiago and 104, 105, 107, 109, 111, 116/120 Camino Matias, to direct Staff to prepare an evaluation concerning compound status.**

Ms. Roach proposed a subcommittee of the Board should create the recommendation.

Chair Rios said no to a subcommittee.

Member Guida asked if it would come back as a case.

Ms. Roach believed it could.

Member Katz asked if it would be a recommendation to the Governing Body.

Ms. Roach said Staff could bring back an evaluation as Case #H-2019-19B.

VOTE: The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.

H. MATTERS FROM THE BOARD

Chair Rios thanked everyone for staying through this long meeting.

I. ADJOURNMENT

Having completed the agenda and with no further business to come before the Board, the meeting was adjourned at 10:16 p.m.

Approved by:

Cecilia Rios

Cecilia Rios, Chair

Submitted by:

Carl G. Boaz

Carl Boaz for Carl G. Boaz, Inc.

CITY OF SANTA FE, NEW MEXICO

PROJECT DESCRIPTION: Lloyd and Associates, agent for Plaza del Monte LLC, owners, historic status review and designation of primary façades, if applicable, for all residential structures in the Plaza del Monte Subdivision, except those reviewed for historic status in Case #H-17-098A (122, 124, 125, 126, and garages south of 126 Camino Santiago).

Case number: **H-19-019**
Project Type: HDRB

PROJECT LOCATION (S): 101, 102, 103, 105, 106, 109, 110, 111, 113, 114, 115, 117, 118, 119, 120, 121 Camino Santiago and 104, 105, 107, 109, 111, 116/120 Camino Matias

PROJECT NAMES:

OW –	Plaza del Monte LLC	8814 Horizon Blvd. Suite 400	Albuquerque, NM 87113
AP –	Lloyd and Associates	321 West San Francisco Street Suit A	Santa Fe, NM 87501

PROJECT DATA:

HISTORIC DISTRICT

Don Gaspar Area ☐ Downtown and Eastside ☑ Historic Review ☐ Transition ☐ Westside-Guadalupe ☐

HISTORIC BUILDING STATUS

Non-Statused ☑ Non-Contributing ☑ Contributing ☐ Significant ☐ Landmark ☐ N/A ☐

PRIMARY ELEVATIONS: North ☐ South ☐ West ☐ East ☐ N/A ☑

PUBLICLY VISIBLE FACADE-EAST Yes ☑ No ☐

PUBLICLY VISIBLE FACADE-NORTH Yes ☐ No ☐

PUBLICLY VISIBLE FACADE-SOUTH Yes ☑ No ☐

PUBLICLY VISIBLE FACADE-WEST Yes ☑ No ☐

HISTORIC DISTRICT INVENTORY NUMBER _____

YEAR OF CONSTRUCTION 1950 - 1972

PROJECT TYPE

Status ☑ Primary Elevations ☑ Remodel ☐ Demolition ☐ New ☐ Other _____

USE, EXISTING Residential ☑ Non-Residential ☐ Vacant ☐

USE, PROPOSED Residential ☑ Non-Residential ☐

HISTORIC BUILDING NAME Plaza del Monte

City of Santa Fe, New Mexico

memo

DATE: June 25, 2019

TO: Historic Districts Review Board Members

FROM: Lisa Roach, Historic Preservation Division Manager LR

Case # H-19-019

Address: 101, 102, 103, 105, 106, 109, 110, 111, 113, 114, 115, 117, 118, 119, 120, 121 Camino Santiago and 104, 105, 107, 109, 111, 116/120 Camino Matias
Historic Status: Contributing, Non-Contributing, Non-statused
Historic District: Downtown and Eastside

REFERENCE ATTACHMENTS (Sequentially):

CITY SUBMITTALS

__x__ **Historic Inventory Form**

____ **Zoning Review Sheet**

__x__ **Other:**
1) Summary of Case History
2) Property Map
3) Certified letter from City staff notifying property owner of HDRB status review
4) "50-year rule" Guidance

APPLICANT SUBMITTALS

__x__ **Proposal Letter**

____ **Site Plan/Floor Plan**

____ **Elevations**

____ **Photographs**

____ **Other:**
"Plaza del Monte Historic Resources Evaluation," by John Murphey

STAFF RECOMMENDATION:

Staff generally agrees with the status recommendations provided in the "Plaza del Monte Historic Resources Evaluation" but defers to the Board for individual status assignments, per 14-5.2(C) Designation of Significant and Contributing Structures.

BACKGROUND:

101-121 Camino Santiago and 104-120 Camino Matias are 22 residential structures, which along with 122, 124, 125, 126 and the garages at 126 Camino Santiago, comprise the Plaza del Monte subdivision, located in the Downtown and Eastside Historic District. Historic status for all 27 structures in Plaza del Monte is summarized in the table below:

Address	Construction Date(s)	Current Historic Status	Recommended[1] Historic Status	HDRB Status Review Case
101 Camino Santiago	c.1967-68	NC	NC	H-19-019
102 Camino Santiago	c.1965	NC	C	H-19-019
103 Camino Santiago	c.1965	NC	C	H-19-019
105 Camino Santiago (Units 1-4)	1971	NS	NC	H-19-019
106 Camino Santiago	c.1965	NS	C	H-19-019
109 Camino Santiago	c.1965	NS	NC	H-19-019
110 Cam. Santiago / 112 Cam. Matias	c.1962/c.1968	NS	NC	H-19-019
111 Camino Santiago	c.1965	NS	C	H-19-019
113 Camino Santiago	c.1970	NS	NC	H-19-019
114 Camino Santiago	c.1972	NS	NC	H-19-019
115 Camino Santiago	c.1970	NS	NC	H-19-019
117 Camino Santiago	1966-67	NS	NC	H-19-019
118 Camino Santiago	c.1973	NS	NC	H-19-019
119 Camino Santiago	c.1965	NS	NC	H-19-019
120 Camino Santiago	c.1971	NS	NC	H-19-019
121 Camino Santiago	c.1971	NS	NC	H-19-019
122 Camino Santiago	c.1971	NC	-	H-17-098A
124 Camino Santiago	c.1968	C	-	H-17-098A
125 Camino Santiago (Units 1-4)	c.1970	NC	-	H-17-098A
126 Camino Santiago	c.1968	C	-	H-17-098A
Garages south of 126 Cam. Santiago	c.1968/1977	NC	-	H-17-098A
104 Camino Matias	c.1965	NC	C	H-19-019
105 Camino Matias	1950	C	NC	H-19-019
107 Camino Matias	1950	NC	NC	H-19-019
109 Camino Matias	1950	NC	NC	H-19-019
111 Camino Matias	pre-1960 (moved to site)	NC	NC	H-19-019
116/120 Camino Matias	pre-1957 w/c.1984 addition	NC	NC	H-19-019

NS = Non-statused *NC = Non-contributing* *C = Contributing*

[1] Historic Status Recommendations are taken from the "Plaza del Monte Historic Resources Evaluation," by John Murphey (2018).

Historic status for 122, 124, 125, 126 and the garages at 126 Camino Santiago were assigned in Case H-17-098A. Recent HDRB actions on the status of Plaza del Monte are provided here, and a more extensive case history is provided as an attachment to this report. On March 26, 2019, the HDRB reviewed the status of the seven non-statused structures in Plaza del Monte (105, 113, 114, 115, 118, 120, and 121 Camino Santiago), and their decision was to assign Contributing status to all seven structures because of their association to the Plaza del Monte, an historic planned subdivision, and because they are representative examples of Mid-century Modern influenced expressions of Santa Fe Style. On April 23, 2019, the HDRB rescinded their motion from the March 26, 2019, hearing regarding the assignment of contributing historic status for the seven non-statused structures at Plaza del Monte, citing insufficient discussion of each individual structure to justify the assignment of contributing status, including failure to designate primary façades. The conditions of this action were in the form of the following directives: 1) that the Land Use Director provide interpretation of the "50-year rule"; 2) that staff provide information regarding applicability of the provisions in the code for "Historic Compound" designation; and 3) that staff bring all remaining stuctures in Plaza del Monte back to the HDRB for review under a single status review case.

This report represents staff's response to directives included in the April 23rd recission of status designation for seven non-statused structures in Plaza del Monte. All structures in Plaza del Monte for which status has not previously been reviewed by the HDRB are herein presented to the HDRB for status review, including designation of primary façades as needed for those structures that receive contributing status.

HISTORICAL SUMMARY OF PLAZA DEL MONTE[2]

The Plaza del Monte subdivision, or Plaza del Monte Retirement Center as it was formerly known, was originally conceived in the late 1950s as a communal living center for retired Presbyterian pastors, missionaries, and other church officials. After the Allison-James School closed in 1958, the United Presbyterian Church decided to plan for re-development of the site, and they selected the architectural firm of Kenneth S. Clark and Phillippe Register to design it as a large retirement community. The architects divided the former campus into two parts – the site of the older buildings termed the "South Area" would be developed first with a congregate building, and the "North Area" would be developed in a second phase with individual residences. A preliminary layout of the development in 1960 showed a cul-de-sac arrangement of the homes built around two new streets. Camino Santiago would run along the northern portion of the property, turning south and terminating in a cul-de-sac, and Camino Matias would be a loop off of Camino Santiago running through the older residences at the southern portion of the property.

As is described in the Plaza del Monte Historic Resources Evaluation, Clark and Register conceived the design of the residences as a modified L-plan to which a carport and portal were attached. Architectural details are sympathetic to the Spanish-Pueblo Revival tradition – with room-block stuccoed massing, rounded corners, and vigas, posts and corbels on the portals and carports – but re-framed in mid-century styling. This contemporary influence became more

[2] Historical Summary paraphrases research presented in the "Plaza del Monte Historic Resources Evaluation," by John Murphey (2018).

pronounced on the exteriors of the later homes in the development, when the low, horizontal lines of the residences were further accentuated with flat overhanging roofs at times intersected with vertical planes. The latest homes constructed in Plaza del Monte in the early 1970s experimented with angular walls and a more compact massing with carport-dominant façades.

SUMMARIES OF INDIVIDUAL PROPERTIES[3]

101 Camino Santiago: Situated near the east entrance to Plaza del Monte, the house is a roughly 1,332 square foot contemporary residence constructed in 1967-68. In plan, the three-bedroom dwelling has a square form with an attached L-shaped portal and garage, giving it a combined square footprint. It presents to the street a long portal with the roof carrying over the garage. It is fenestrated with aluminum windows, primarily of a sliding operation. A paneled wood door gives entry to the residence at the east end of the portal. The garage entry is fitted with a recent vinyl overhead door. Cementitious brocade stucco in a peach tone covers the frame building. The roof consists of a mixture of gravel and asphalt material. An interior parapet outlines the dwelling portion of the mass. While contemporary in form, the vigas across the portal give the residence a regional feel.

102 Camino Santiago: One of the earliest units to be constructed at Plaza del Monte, 102 Camino Santiago is a 2,064 square foot dwelling with one addition. The two bedroom, flat-roof house faces Camino Matias. It shows to the street (west) a façade-long portal, continuing at the south end as a single-space carport. The portal is supported by shiplap wood girders resting on round posts with double-ended corbels. Most of the portal façade is painted white. A line of vigas runs along the top of the wall. The elevation is penetrated by two doors and large windows, with the southernmost window not meeting the ordinance in regard to its distance from the corner. The north elevation facing Camino Santiago displays a variety of window openings holding tall metal casements. A shallow overhang supported by short vigas carries over most of the elevation. At the northeast corner is a roomblock-like projection holding the bedroom wing. The rear (east) elevation presents a number of alterations. The largest is a post-1969 addition, over what was a patio. The 380-square-foot addition is fenestrated with modern windows and is sheltered by a parapet-type portal. The house was constructed in c. 1965, and its designer/architect is unverified but assumed to be Kenneth S. Clark and Phillippe Register. Contributing status is recommended for this structure, as it is representative of the original Clark and Register design template for Plaza del Monte residences and is a good example of Mid-century Santa Fe Style. If the Board assigns contributing status to the residence, the west façade is recommended as primary.

103 Camino Santiago: Roughly 1,533 square feet, the one-story residence is designed as an L-plan form. The plan puts the bedrooms in a cube-like mass, with the remainder of the functions of the house strung along a linear spine. Its façade is defined by a long portal sheltering its entry and patio doors. The east end of the composition terminates as a one-bay carport. A line of vigas runs along the back (north) elevation supporting a short overhang. An exterior chimney breaks through the overhang, rising several feet above the roof. The house is fenestrated with

[3] Property summaries are presented as excerpts from the "Plaza del Monte Historic Resources Evaluation," by John Murphey (2018).

an array of original and replacement aluminum windows. It is entered under the portal through a stylized wood panel door flanked by one set of sidelights. The dwelling's flat roof is outlined by a short parapet; the roof is covered with gravel. The frame structure is finished with cementitious brocade stucco in the buckskin tone. While contemporary in form, vigas used across the portal and the roomblock bedroom wing give the residence a Spanish-Pueblo Revival feel. The house was constructed in c. 1965; its architect/designer is unverified but assumed to be architect Phillippe Register. Contributing status is recommended for this structure, as it is representative of the original Clark and Register design template for Plaza del Monte residences and is a good example of Mid-century Santa Fe Style. If the Board assigns contributing status to the residence, the south façade is recommended as primary.

105 Camino Santiago (Units 1-4): Forming a long, linear composition, 105 Camino Santiago is one of three apartment buildings erected at Plaza del Monte. The carport-dominated structure works its way down the slope as two L-plan units joined together at the center by a laundry room. The structure is bookended by masses holding the apartments. The larger apartments containing two bedrooms are situated in the projecting roomblocks. The apartments share a party wall at the living room. Spanning between the apartments are the carports and the laundry room. The carports are detailed with a viga-roof structure which continues as a portal along the inner apartments. The rear (north) elevation is divided into small patios. The apartments are entered through wood panel doors; solid wood doors give access to the storage units and the laundry. The original multi-light steel casement windows have been replaced with aluminum units. A short parapet follows the outline of the apartments, and is penetrated on the south, east and west elevations with cut-through metal canals. The frame structure is finished with cementitious brocade stucco in a peach tone. While contemporary in form, the vigas used across the portales and carports and the cubed apartment masses give the residence a regional feel. The roughly 4,198 square foot apartment building was constructed in 1971, after a design by architect Phillipe Register. Non-contributing status is recommended for this presently non-statused multi-unit residential structure due to age and contemporary design features. However, the Board may consider that its association with architect Phillipe Register and with the Plaza del Monte planned development could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the south façade is recommended as primary.

106 Camino Santiago: Likely the third unit to be constructed at Plaza del Monte, 106 Camino Santiago is a 2,031 square foot dwelling with a portal across two elevations (north and east). In plan, it has an L-shaped foundation with an attached carport. The flat-roof dwelling holds three bedrooms confined to a wing at the west end. The rear (south) elevation is focused on a small patio cut into the southwest corner of the home. The southeast corner is terminated by a one-space carport. The two-sided portal runs along the north and east elevations. The structure is made of vigas which sit on square girders held up by round posts with corbels. The portal elevations are painted white and fenestrated with doors on each exposure. Small rectangular windows penetrate the bedroom wing. The remaining windows vary, including large picture and grouped casements and sliding units. The roof is finished with rolled asphalt which carries over the inner parapets. A squat stucco-faced chimney rises at the northeast corner. The house is finished with textured cementitious stucco in a light buckskin tone. The residence was constructed in c.1965. Its designer is unverified but is suspected to be an early Clark and

Register design. Contributing status is recommended for this presently non-statused residence, as it may represent an original Clark and Register design template for Plaza del Monte, and the house is a good example of a mid-century expression of Santa Fe Style. If contributing status is assigned to the residence, the north and east facades are recommended as primary.

109 Camino Santiago: Composed of a series of angled walls, the carport dominated residence was constructed in 1966, after a design by architect Phillipe Register. The house presents to the street a tall and wide carport framed with a viga roof. The west end of the carport is sheltered by a double splayed wall. The angled wall composition is echoed across the east elevation. In plan, the residence is roughly an L with its form obscured by the carport. The approximately 1,220 square foot dwelling holds two bedrooms in a cube-like mass anchoring the east end. Between the bedroom mass and carport is a small enclosed patio and portal sheltering the main entry and a pair of oversized wood windows. The rear (north) elevation has a small viga canopy protecting a patio door. A tapered chimney breaks the wall plane on this elevation. Fenestration consists of mainly aluminum windows. The frame structure is finished with cementitious brocade stucco in the buckskin tone. The contemporary style home was constructed in 1965 and is one of the earliest residences to be constructed in Plaza del Monte. The architectural historian recommends non-contributing status for this residence, due to its contemporary design which does not harmonize with the district. However, the Board may consider that its association with architect Phillipe Register and with the Plaza del Monte planned development could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the south façades are recommended as primary.

110 Camino Santiago: Located at the west end of the common area are two residential units which were joined together at some point after 1970. The older unit, addressed as 110 Camino Santiago, takes up the east end of the footprint. Constructed in c.1962, after a design by architect Kenneth S. Clark, it is roughly an L-shaped box with a rear portal and connected carport. The street facing façade (north) is defined by a small recessed entry. The remainder of the façade is divided into rectangular window openings holding sliding units. Smaller, rectangular sliding windows are applied across the east bedroom wing. A shallow portal runs across the rear (south) elevation historically leading to a single-space carport. The portal elevation is fenestrated with a patio door, sliding windows, and a louvered door leading to a utility room. The house is outlined by parapets and finished in buckskin cementitious stucco. It holds three bedrooms. Attached to the west end of the original Clark design is a post-1966 addition. Arranged at a lower height, the approximately 864 square foot appendage is a rectangular box with overhanging eaves and a porch. The addition, most likely designed by architect Phillipe Register, introduces a contemporary vocabulary. A shallow overhang supported by squared rafters carries across the north and south elevations. Similar beams extend out from the west elevation to create the porch. A tall angular wall rising above the roofline defines its south edge. The addition is fenestrated with a few doors and square window openings, holding single-light metal casements. Most likely occurring with the addition, the carport was widened (or constructed anew) to hold two vehicles. Set back from the addition, the roughly 1,054 square foot structure is supported by a viga and post system. Due to substantial changes to the massing and appearance of the structure when two residences were

combined and carport added and subsequently widened, noncontributing status is recommended for this residence.

111 Camino Santiago: Arranged at an east-west orientation, the house is a one-story, approximately 1,616 square foot, flat-roof dwelling erected in c.1965. The dwelling has an L-shaped plan with its two bedrooms confined to a rectangular wing at the west end. The remaining house holds the living room, kitchen and dining area. The front (south) façade is market y along portal which continues across to an attached one-bay carport. The portal shelters the front entry and a sliding patio door. The structure is supported by round poles holding a viga roof. The house is fenestrated with common windows, most of them appearing to be replacement units. It is entered through a raised wood panel door flanked on one side by a sidelight. The rear (north) elevation contains a few windows and a door sheltered by a shallow viga-supported visor. A tapered chimney breaks through the visor, terminating with a terra cotta cap. The frame building is finished in a smooth cementitious stucco in a buckskin tone. The flat roof is covered with asphalt, which carries over the east exposure to the bedroom wing. While contemporary in form, the vigas used across the portal give the residence a Spanish-Pueblo Revival feel. The placement and restrained size of the carport helps maintain the regional tradition. The building was constructed after a design by architect Phillipe Register. Contributing status is recommended for this structure, as it represents an original design template by Clark and Register for Plaza del Monte and because it is an example of mid-century expressions of Santa Fe Style. If the Board finds this structure to be contributing, the south façade is recommended to be primary.

113 Camino Santiago: Sitting on a slight rise, the house shares a party wall at the carport with its neighbor at 115 Camino Santiago. The roughly 1,281 square foot dwelling contains two bedrooms arranged at the front of the structure in a small L-shaped volume. The remainder of the footprint holds the living functions of the house. It presents to the street two roomblock-like volumes penetrated by horizontally oriented aluminum casement windows. A viga-framed carport and short portal terminate the west end of the footprint. The house is entered through a raised wood panel door with a center view light. The rear (north) elevation has a few windows and a sliding glass door. A shallow overhang supported by square wood beams carries across the elevation. The frame dwelling is finished in cementitious peach color stucco worked into a brocade pattern. Tall parapets outline the perimeter of the bedroom wing. The roof is covered in asphalt which carries over the west exposure of the bedroom mass. It was erected in c.1970, and its designer/architect is unknown. Noncontributing status is recommended for this structure due to its age slightly under 50 years. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the south façades are recommended as primary.

114 Camino Santiago: The house presents to Camino Santiago a traditional design of a cube-like mass projecting from a linear arm. In plan, it is roughly L-shaped with a large connecting carport attached to its southeast corner. The west end holds two bedrooms; the remainder of the footprint contains a large living room, kitchen and utility closet. The south exposure of the bedroom wing is penetrated by sliding glass doors. East of the bedroom wing, the front façade

(north) is divided into a recessed entry and a large casement-framed picture window. The entry holds a raised square panel wood door with center view light. It is sheltered by a short overhang resting on vigas. A similar combined picture and casement window is found on the east elevation of the living room. The carport makes up most of the secondary street elevation (north, set back). It is supported by a wood viga-and-post system. The structure shelters a patio door and single raised panel wood door leading to the utility room and storage area. Wood, trough-like canales penetrate the parapets on the east and west elevations. The roof is covered in rolled asphalt, which carries over the bedroom wing's east exposure. A short stucco-clad chimney topped with a terra cotta cap rises from the center of the roof. Erected in c.1972, the residence was designed by Register, Ross & Burnett Architects. Noncontributing status is recommended for this structure due to age. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the north façades are recommended as primary.

115 Camino Santiago: Sharing a wall with the dwelling to the east (113 Camino Santiago), the small house contains two bedrooms. The dwelling portion of the building is composed of a rectangular bedroom wing. Attached to this are the living room, kitchen, and a one-space carport. Connecting these elements is a beam portal. Together, both areas hold about 1,290 square feet. The front (south) façade presents a simple canvas of a projecting mass balanced on one end with the void of the carport at the other. In between is the portal with its few window and door openings. The portal is supported by double round posts toped with corbels. The rear (north) elevation contains a few windows and a sliding glass door sheltered by a shallow viga-supported overhang. The windows in the residence are tall, single-light aluminum casements. A raised panel-and-view-light door gives entry to the dwelling under the portal. Short parapets outline the perimeter of the bedroom wing. The roof's asphalt material carries over the east exposure of the parapet. The house was erected in c.1970, and the designer/architect is unknown. Noncontributing status is recommended for this structure due to its age slightly under 50 years. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the south façades are recommended as primary.

117 Camino Santiago: Tucked into the northwest corner of the development, the house is a single-story, flat-roof dwelling characterized by its viga carport and continuous overhang. In form, its two box-like volumes are arranged in a modified L-plan. The house holds two bedrooms slung along the west wall. A large living room occupies the foot of the L. With its carport included, the house contains 1,422 square feet. The unarticulated flat front façade is penetrated by non-historic casement windows. A wood panel and view light door gives entry to the dwelling under the front portal. The rear (west) elevation is fenestrated with an asymmetrical pattern of tall aluminum casement windows. The frame building is finished with brocade-type stucco rendered in the buckskin color. It was constructed in 1966-67, after a design by architect Phillipe Register. Window replacements appear to have removed the pedimented heads shown on Register's drawings. Noncontributing status is recommended due to contemporary design that the architectural historian did not feel harmonized with the

district. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the east (street-facing) façades are recommended as primary.

118 Camino Santiago: Erected in c.1973, the stucco-over-frame, two bedroom house sits on a rise a the southeast corner of Camino Santiago and Camino Matias. In plan, it is a modified L shaped structure with a carport attached to its front (north) façade. The roughly 1,245 square foot dwelling has its bedrooms segregated to a wing across the west elevation. This volume is taller than the rest of the house and is outline with parapets. The lower volume contains a living room, kitchen and dining area. The north (front) façade is divided between the carport and the north face of the bedroom wing. The single carport is erected over a wood structure supported by round posts. The outside beam continues across the façade, sheltering the front entry. As with the door under the carport, the entry holds a raised square panel unit. The secondary elevations are fenestrated with single-light metal casement windows. The south (rear) elevation has an array of casement windows and an enclosure giving access to the carport. A shallow overhang resting on vigas outlines the elevation. The house is finished with cementitious brocade stucco in a peach pigment. The roof is covered with rolled asphalt, which carries over a portion of the bedroom wing's east exposure. Large, trough-like wood canales pierce the west parapet. It was designed by Register, Ross & Burnet Architects, and is one of the last houses to be completed in Plaza del Monte. Noncontributing status is recommended for this residence by the architectural historian, due to age. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the north façades are recommended as primary.

119 Camino Santiago: Arranged slightly above grade, the box-like house is characterized by its continuous portal and horizontal emphasis. In plan it is a compact rectangle framed by angled walls on its north and south exposures. Large windows, a wood panel door and a three-panel sliding glass door appear on the front (east) façade. The rear (west) elevation has double sets of sliding windows and a patio door arranged under an overhang. The house's windows appear to be mostly replacement units. The south end of the dwelling is weighted with a large carport. A tall double splayed wall creates the south exposure. The portal is supported by vigas resting on a square beam. Round posts topped with double ended corbels carry the weight to the floor. The roughly 1,485 square foot structure contains two bedrooms placed along the west wall. The building was constructed in c.1965, after a design by architect Phillipe Register. The main alteration is the removal of most of the angled wall along the northeast corner. Originally, this feature enclosed a small patio. Noncontributing status is recommended for this structure due to contemporary design that the architectural historian did not feel harmonized with the district. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the east (street-facing) façade is recommended as primary.

120 Camino Santiago: The small two bedroom house presents a contemporary carport-dominant design. Located along the east side of Camino Santiago, it sits back from the street. In

plan, it is a modified T form with an attached carport projecting from the front (west) façade. Its two bedrooms are confined to a wing making up the north elevation. Higher than the rest of the house, it is outlined with shaped parapets. The parapets are pierced with canales across the north and south exposures. The lower volume, historically containing a living room, kitchen and music room, is faced with a shallow overhang resting on vigas. The overhang shelters sliding glass doors, a window and a pedestrian entry. The secondary elevations are fenestrated with aluminum casement windows. The front (west) elevation is dominated by the carport. The structure is erected over a viga-and-post support system. The portal's outside beam continues across the façade, sheltering the front (west) entry. A wood raised square panel door with a center view light gives entry to the residence. Including its carport and utility room, the building contains 1,804 square feet. The house was built in c.1971 after a design by Register, Ross & Burnet Architects. Noncontributing status is recommended for this structure due to age. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the west (street-facing) façade is recommended as primary.

121 Camino Santiago: Reflecting a carport-dominant design, the small vernacular dwelling sits at grade on the west side of Camino Santiago. The roughly 1,309 square foot structure holds one bedroom. In plan, it is a compact square enclosed by an angled wall across its south exposure. Unlike most units in Plaza del Monte, it has a low pitched roof. The front (east) façade is dominated by the one-vehicle carport. The remainder of the façade is divided into windows and doors. The windows are uniformly multi-light steel casements in various standard sizes. The gabled north elevation has three identical windows. The rear (west) side of the house has more articulation, expressed through its beamed canopy over a pair of sliding doors. The frame house is finished with heavy brocade cementitious stucco in a peach like color. A shallow square-beam supported overhang runs along the east and west elevations. It was constructed in c.1971, after a design by Register, Ross & Brunet Architects. Noncontributing status is recommended for this structure due to age and contemporary design that the architectural historian did not feel harmonized with the district. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the east (street-facing) façade is recommended as primary.

104 Camino Matias: One of the first units to be constructed at Plaza del Monte, 104 Camino Matias is an L shaped dwelling with a combined carport and portal. The approximately 1,143 square foot, flat roof structures holds two bedrooms. The bedrooms are placed in a wing forming the north end of the residence. Its front (west) façade presents a Spanish-Pueblo Revival plan, with its cubic, battered mass and viga roofed portal. Unlike many houses in the development, the carport plays a secondary role on the façade. The single-bay structure, arranged behind the portal, is less exuberant in its display of wood elements. The bedroom mass is fenestrated with small, rectangular windows; the remaining elevations have windows arranged in a more traditional pattern. The windows are mostly aluminum casement units. The portal elevation is painted white. A line of vigas runs along the top of the wall. It is supported by shiplap wood girders resting on round posts with corbels. The house was constructed in c.1965.

It represents the closest interpretation of the original 1960 Kenneth S. Clark and Phillipe Register template design for the development. Contributing status is recommended for this residence, due to its early date of construction and representation of the original Clark and Register design template for Plaza del Monte retirement homes and due to its exemplary expression of mid-century Santa Fe Style. The west façades are recommended as primary.

105 Camino Matias: This small house is one of three units constructed in 1950 for married staff employed by the Allison James School. Arranged in a terrace-like fashion, each unit is a rectangular plan, side-gabled dwelling with an attached garage. The house has a telescoping roof form evident in its north exposure. The roof extends over the walls on the north and south elevations to form small porches. The house is fenestrated with a mix of original and non-historic windows and doors. The windows are terminated with stuccoed concrete sills. Views from the house are oriented north toward the commons area. The north elevation contains a large picture window flanked by casements. Public entry is through an original ½-glass wood door on the south elevation. The garage door is a recent vinyl paneled unit. The roof is covered with three-tab asphalt shingles. Wood fascia has been applied to the north and south roof ends, obscuring (or removing) the original exposed rafters. A short stuccoed chimney rises from the north roof slope. The approximately 1,102 square foot house holds three bedrooms. A non-historic, 220-square foot carport has been erected over the driveway. Non-contributing status is recommended for this structure. As the architectural historian states, the house neither harmonizes with the district nor with Plaza del Monte and includes non-conforming elements such as corner windows and cantilevered canopies over entries. Its association is with the Allison James School (demolished in 1960) rather than with Plaza del Monte. Staff agrees with this assessment.

107 Camino Matias: This small house is one of three units constructed in 1950 for married staff employed by the Allison James School. Arranged in a terrace-like fashion, each unit is a rectangular plan, side-gabled dwelling with an attached garage. The gabled roof extends over the walls on the north and south elevations to form small porches. The dwelling is fenestrated with a mix of original and non-historic windows, terminated with stuccoed concrete sills. Views from the house are oriented north towards the commons area of Plaza del Monte. The north elevation contains a large picture window flanked by casements. Public entry is through an original ½-glass wood door on the south elevation. Two vertical [solar?] panels have been applied to the south façade. The garage door is recent vinyl paneled unit. The roof is covered with three-tab asphalt shingles. Wood fascia has been applied to the north and south roof ends, obscuring (or removing) the original exposed rafters. A short stuccoed chimney rises from the north roof slope. The house originally had an exposed pedimented entry on the north elevation, which was reduced at some point in depth after 1969. The approximately 1,145 square foot house holds two bedrooms. As the architectural historian states, the house neither harmonizes with the district nor with Plaza del Monte and includes non-conforming elements such as corner windows and cantilevered canopies over entries. Its association is with the Allison James School (demolished in 1960) rather than with Plaza del Monte. Non-contributing status is recommended for this structure, and staff agrees with this assessment.

109 Camino Matias: This small house is one of three units constructed in 1950 for married staff employed by the Allison James School. Arranged in a terrace-like fashion, each unit is a

rectangular plan, side-gabled dwelling with an attached garage. The house has a telescoping roof form evident in its north exposure. The roof extends over the walls on the north and south elevations to form small porches. The front (south) façade reveals an altered composition. At some point after 1960, a 131 square foot addition was appended to the southwest corner creating a sunroom. The dwelling is fenestrated with a mix of original and non-historic windows, which are mostly double hung sash and are terminated with stuccoed concrete sills. Views from the house are oriented north toward the Plaza del Monte commons area. The north elevation contains a large picture window flanked by casements. Public entry is through an original ½-glass wood door on the south elevation. The garage door is a recent vinyl paneled unit. The roof is covered with three-tab asphalt shingles. Wood fascia has been applied to the north and south roof ends, obscuring (or removing) the original exposed rafters. A short stuccoed chimney rises from the north roof slope. The approximately 1,141 square foot house contains two bedrooms. As the architectural historian states, the house neither harmonizes with the district nor with Plaza del Monte and includes non-conforming elements such as corner windows and cantilevered canopies over entries. Its association is with the Allison James School (demolished in 1960) rather than with Plaza del Monte. Non-contributing status is recommended for this structure, and staff agrees with this assessment.

111 Camino Matias: Moved to the site prior to 1960, 111 Camino Matias is an altered three bedroom house. The house is arranged on a north-south axis, facing west, and in plan consists of two telescoping gabled sections. To this basic form was added an L-shaped porch and connected carport in c.1966. The medium pitch roofs are covered with asphalt shingles and extended with overhangs. A short stuccoed chimney rises from the ridgeline. Small wood louvers are attached to the gabled ends. The house is fenestrated with an array of original and non-historic windows, recessed from the walls and terminated with concrete sills. The combined porch and carport are supported by a framework of wood girders resting on grouped square posts. The single carport includes double storage units. A short breezeway leads from the carport to a back door. The 1,712 square foot house is finished with textured cementitious stucco in a light buckskin color. Non-contributing status is recommended for this residence. It was moved to the site before 1960 and extensively modified in 1966 with the addition of the carport and portal. As with the other Allison James School-era residences on Camino Matias, the house neither harmonizes with the district nor with Plaza del Monte, and its association is with the Allison James School rather than Plaza del Monte.

116/120 Camino Matias: The vernacular, two unit residence was erected before 1957 and modified nearly 30 years later with the addition of a cross-gabled entry. The combined residence is aligned along a north-south axis on the west side of Camino Matias. In plan, it is a side-gabled rectangle with a cross-gable appended to its northeast corner. The north unit (120) holds about 1,256 square feet with three bedrooms. A window wall spanning the northeast corner signals its contemporary design. The north elevation under the gable is marred by a c.1984 shed-roof structure enclosing the furnace and water heater. The front façade faces east and is dominated by the non-historic cross gable entry. A recessed entry at the south end leads to 116. The interior, encompassing approximately 939 square feet, is arranged like an apartment. A similar non-historic stuccoed enclosure around the furnace and water heater is attached to the south elevation. The rear (west) elevation of the combined units faces onto a common area. A continuous overhang characterizes this façade. It is penetrated with three

sliding glass doors and a mixture of fixed and sliding windows of different sizes. The roof is sheathed with rib metal panels. It is unclear who designed the original house. The c.1984 addition of the cross gable and furnace and water heater enclosures was drawn in Phillipe Register's shop. Built prior to 1958 and substantially modified in the mid-1980s, the historic integrity of the house has been compromised, and the style of the home neither harmonizes with the district nor with Plaza del Monte. As with the other Allison James School-era residences on Camino Matias, the house neither harmonizes with the district nor with Plaza del Monte, and its association is with the Allison James School rather than Plaza del Monte.

RELEVANT CODE CITATIONS:

14-5.2(C) Regulation of Significant and Contributing Structures in the Historic Districts

(1) Purpose and Intent

It is intended that:

(a) Each structure to be recognized as a physical record of its time, place, and use. Changes that create a false sense of historical development, such as the addition of conjectural features or architectural elements from other buildings, shall not be undertaken;

(b) Changes to structures that have acquired historic significance in their own right shall be retained and preserved, recognizing that most structures change over time;

(c) Distinctive features, finishes, and construction techniques or examples of craftsmanship that characterize a structure be preserved; and

(d) New additions and related or adjacent new construction be undertaken in such a manner that if removed in the future, the original form and integrity of the historic property and its environment would be unimpaired.

14-12 Significant Structure:

A structure located in a historic district that is approximately fifty years old or older, and that embodies distinctive characteristics of a type, period or method of construction. For a structure to be designated as significant, it must retain a high level of historic integrity. A structure may be designated as significant:

(A) for its association with events or persons that are important on a local, regional, national or global level; or

(B) if it is listed on or is eligible to be listed on the State Register of Cultural Properties or the National Register of Historic Places.

14-12 Contributing Structure:

A structure, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a contributing structure is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The contributing structure may have had minor alterations, but its integrity remains.

14-12 Primary Façade:

One or more principal faces or elevations of a building with features that define the character of the building's architecture.

14-12 Noncontributing Structure:

A structure, located in an H district, that is less than fifty years ld or that does not exhibit sufficient historic integrity to establish and maintain the character of the H district.

"50-YEAR RULE" GUIDANCE:

The "50-year rule" is one of the most widely accepted principles within the historic preservation movement in the U.S., establishing the standard that properties approximately fifty years old or older are of sufficient age to have established historic significance as a threshold for triggering preservation. The rule was established by the National Park Service in 1948 and codified at the federal level in the National Historic Preservation Act of 1966. Exceptions to this standard have been applied to sites, structures and places that are less than fifty years old but which have demonstrated "exceptional importance" independent of age. This chronological filter has been applied to properties nominated to the National Register of Historic Places, and it has been widely utilized in local historic preservation ordinances across the country as a means to settle potential controversies over the nature of historic significance. [4]

The "50-year rule" was included in Santa Fe's historic preservation ordinance in 1957 – one of the earliest uses of the standard at the local level. Because it has its origins in federal historic preservation policy, it stands to reason that its administration at the local level should follow federal guidance. In doing so, the HDRB is encouraged to apply the "50-year rule" as a guideline when evaluating historic status of properties. Accordingly, properties less than fifty years old may be deemed to be contributing or significant if the Board determines that they are of "exceptional importance" (association with or representative of events, people or trends of historical or architectural significance). That said, there has been much recent discussion of the "50-year rule," including calls to reconsider its utility and application.

[4] "'Of Exceptional Importance': The Origins of the 'Fifty-Year Rule' in Historic Preservation," by John H. Sprinkle Jr. (2007) *The Public Historian: A Journal of Public History*.

Plaza del Monte: Previous HDRB Case History
(101-126 Camino Santiago and 104-120 Camino Matias)

On **November 28, 2017**, the applicant requested status review of four non-statused structures (122, 124, 125, and 126 Camino Santiago) and proposed demolition of these structures. Both cases (H-17-098A and H-17-098B) were postponed at the request of the Board for a full HCPI report for all of the Plaza del Monte subdivision.

On **April 24, 2018**, the applicant presented a full HCPI for Plaza del Monte and requested status reviews for the structures at 122, 124, 125, 126 Camino Santiago and again requested demolition of these structures. The HDRB designated 122, 125, and 126 Camino Santiago as Contributing and to designate 124 Camino Santiago and the garages at 126 Camino Santiago as Non-contributing. The requests to demolish 124 Camino Santiago and the garages at 126 Camino Santiago were granted.

On **May 15, 2018**, the HDRB reconsidered their previous actions on Cases H-17-098A and B out of concerns over age of the structures, over the historical value of mid-century architecture, and over due process as status review was requested by the Board for all structures in Plaza del Monte. The Board decided at that time to rescind their previous actions on status and demolition from the April 24, 2018 hearing. After some public discussion and a closed deliberation on the matter, both cases were postponed for additional information regarding dates of construction.

On **June 26, 2018**, the HDRB reviewed the status of and demolition request for five structures as requested by the applicant, including residences at 122, 124, 125 and 126 Camino Santiago and the garages south of 126 Camino Santiago. The applicant provided updated information regarding dates of construction in two amendments to the original HCPI for Plaza del Monte. In case H-17-098A, the Board assigned Contributing status to the residences at 124 and 126 Camino Santiago and their associated rock walls, and assigned Non-contributing status to 122 and 125 Camino Santiago and to the garages south of 126 Camino Santiago. In case H-17-098B, the Board postponed hearing the demolition request for the Contributing structures at 124 and 126 Camino Santiago and denied the demolition request for 122 and 125 Camino Santiago and the garages south of 126 Camino Santiago.

On **January 9, 2019**, the Governing Body heard an appeal of Cases H-17-098A and B, filed by the applicant. The Governing Body upheld the Board's determination of historic status in case H-17-098A. Regarding demolition, the Governing Body determined to allow demolition of the garage structures south of 126 Camino Santiago but to uphold the denial of demolition for 122 and 125 Camino Santiago.

On **March 26, 2019**, the HDRB reviewed the status of the seven non-statused structures in Plaza del Monte (105, 113, 114, 115, 118, 120, and 121 Camino Santiago), and their decision was to assign Contributing status to all seven structures because of their association to the Plaza del Monte, an historic planned subdivision, and as they are representative examples of Mid-century Modern influenced expressions of Santa Fe Style.

On **April 23, 2019**, the HDRB rescinded their motion from the March 26, 2019, hearing regarding the assignment of contributing historic status for the seven non-statused structures at Plaza del Monte, citing insufficient discussion of each individual structure to justify the assignment of contributing status, including failure to designate primary façades. The conditions of this action were in the form of the following directives: 1) that the Land Use Director provide interpretation of the "50-year rule"; 2) that staff provide information regarding applicability of the provisions in the code for "Historic Compound" designation; and 3) that staff bring all remaining stuctures in Plaza del Monte back to the HDRB for review under a single status review case.

Santa Fe
Mapping the City Different





Legend

- City Limits
- Address Points
- Roads
- Major Roads
- Santa Fe County Parcels
- Santa Fe River
- Rail Road

Historic Buildings Status

- Landmark
- Significant
- Contributing
- Non-Contributing
- Not Resurveyed

Historic Districts

- Don Gaspar Area HD
- Downtown And Eastside HD
- Historic Review HD
- Historic Transition HD
- Westside-Guadalupe HD

1: 2,257

376.2 0 188.08 376.2 Feet

WGS_1984_Web_Mercator_Auxiliary_Sphere

This map is a user generated static output from an Internet mapping site and is for reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable.
THIS MAP IS NOT TO BE USED FOR NAVIGATION

Notes

Note that 124 and 126 Camino Santiago have been designated as Contributing, and 122, 125 and the garages south of 126 Camino Santiago have been designated as Non-contributing.

Santa Fe
Mapping the City Different

101 Camino Santiago



Legend

- City Limits
- Address Points
- Building Footprint
- Roads
- Major Roads
- Santa Fe County Parcels
- Santa Fe River
- Rail Road

Notes

© Latitude Geographics Group Ltd.

47.0 0 23.51 47.0 Feet

WGS_1984_Web_Mercator_Auxiliary_Sphere

This map is a user generated static output from an Internet mapping site and is for reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable.
THIS MAP IS NOT TO BE USED FOR NAVIGATION

Santa Fe
Mapping the City Different

102 Camino Santiago



Legend

- City Limits
- Address Points
- Building Footprint
- Roads
- Major Roads
- Santa Fe County Parcels
- Santa Fe River
- Rail Road

Notes

© Latitude Geographics Group Ltd.

47.0 0 23.51 47.0 Feet

WGS_1984_Web_Mercator_Auxiliary_Sphere

This map is a user generated static output from an Internet mapping site and is for reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable.
THIS MAP IS NOT TO BE USED FOR NAVIGATION

Santa Fe
Mapping the City Different

103 Camino Santiago





Legend

- City Limits
- Address Points
- Building Footprint
- Roads
- Major Roads
- Santa Fe County Parcels
- Santa Fe River
- Rail Road

Notes

© Latitude Geographics Group Ltd.

47.0 0 23.51 47.0 Feet

WGS_1984_Web_Mercator_Auxiliary_Sphere

This map is a user generated static output from an Internet mapping site and is for reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable.
THIS MAP IS NOT TO BE USED FOR NAVIGATION

Santa Fe
Mapping the City Different

105 Camino Santiago





Legend

- City Limits
- Address Points
- Building Footprint
- Roads
- Major Roads
- Santa Fe County Parcels
- Santa Fe River
- Rail Road

Notes

© Latitude Geographics Group Ltd.

47.0 0 23.51 47.0 Feet

WGS_1984_Web_Mercator_Auxiliary_Sphere

This map is a user generated static output from an Internet mapping site and is for reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable.
THIS MAP IS NOT TO BE USED FOR NAVIGATION

Santa Fe
Mapping the City Different

106 Camino Santiago



Legend

- City Limits
- Address Points
- Building Footprint
- Roads
- Major Roads
- Santa Fe County Parcels
- Santa Fe River
- Rail Road

1: 282

47.0 0 23.51 47.0 Feet

WGS_1984_Web_Mercator_Auxiliary_Sphere

This map is a user generated static output from an Internet mapping site and is for reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable.
THIS MAP IS NOT TO BE USED FOR NAVIGATION

Notes

© Latitude Geographics Group Ltd.

Santa Fe
Mapping the City Different

109 Camino Santiago





Legend

- City Limits
- Address Points
- Building Footprint
- Roads
- Major Roads
- Santa Fe County Parcels
- Santa Fe River
- Rail Road

1: 282

47.0 0 23.51 47.0 Feet

WGS_1984_Web_Mercator_Auxiliary_Sphere

This map is a user generated static output from an Internet mapping site and is for reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable.
THIS MAP IS NOT TO BE USED FOR NAVIGATION

Notes

© Latitude Geographics Group Ltd.

Santa Fe
Mapping the City Different

110 Camino Santiago



Legend

- City Limits
- Address Points
- Building Footprint
- Roads
- Major Roads
- Santa Fe County Parcels
- Santa Fe River
- Rail Road

Notes

© Latitude Geographics Group Ltd.

47.0 0 23.51 47.0 Feet

WGS_1984_Web_Mercator_Auxiliary_Sphere

This map is a user generated static output from an Internet mapping site and is for reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable.
THIS MAP IS NOT TO BE USED FOR NAVIGATION

Santa Fe
Mapping the City Different

114 Camino Santiago





Legend

- City Limits
- Address Points
- Building Footprint
- Roads
- Major Roads
- Santa Fe County Parcels
- Santa Fe River
- Rail Road

Notes

© Latitude Geographics Group Ltd.

47.0 0 23.51 47.0 Feet

WGS_1984_Web_Mercator_Auxiliary_Sphere

This map is a user generated static output from an Internet mapping site and is for reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable.
THIS MAP IS NOT TO BE USED FOR NAVIGATION

25

Santa Fe
Mapping the City Different

113/115 Camino Santiago



Legend

- City Limits
- Address Points
- Building Footprint
- Roads
- Major Roads
- Santa Fe County Parcels
- Santa Fe River
- Rail Road

Notes

© Latitude Geographics Group Ltd.

47.0 0 23.51 47.0 Feet

WGS_1984_Web_Mercator_Auxiliary_Sphere

This map is a user generated static output from an Internet mapping site and is for reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable.

THIS MAP IS NOT TO BE USED FOR NAVIGATION

Santa Fe
Mapping the City Different

17 Camino Santiago





Legend

- City Limits
- Address Points
- Building Footprint
- Roads
- Major Roads
- Santa Fe County Parcels
- Santa Fe River
- Rail Road

Notes

© Latitude Geographics Group Ltd.

47.0 0 23.51 47.0 Feet

WGS_1984_Web_Mercator_Auxiliary_Sphere

This map is a user generated static output from an Internet mapping site and is for reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable.

THIS MAP IS NOT TO BE USED FOR NAVIGATION

City of Santa Fe
Mapping the City Different

118 Camino Santiago



1: 282

47.0 0 23.51 47.0 Feet

WGS_1984_Web_Mercator_Auxiliary_Sphere

This map is a user generated static output from an Internet mapping site and is for reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable.
THIS MAP IS NOT TO BE USED FOR NAVIGATION

Legend

- City Limits
- Address Points
- Building Footprint
- Roads
- Major Roads
- Santa Fe County Parcels
- Santa Fe River
- Rail Road

Notes

© Latitude Geographics Group Ltd.

Santa Fe
Mapping the City Different

19 Camino Santiago



Legend

- City Limits
- Address Points
- Building Footprint
- Roads
- Major Roads
- Santa Fe County Parcels
- Santa Fe River
- Rail Road

Notes

© Latitude Geographics Group Ltd.

47.0 0 23.51 47.0 Feet

WGS_1984_Web_Mercator_Auxiliary_Sphere

This map is a user generated static output from an Internet mapping site and is for reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable.

THIS MAP IS NOT TO BE USED FOR NAVIGATION

29


Santa Fe
Mapping the City Different
120 Camino Santiago
CAMINO SANTIAGO
120
116
1
2
3
4
5
1: 282
47.0
0
23.51
47.0 Feet
WGS_1984_Web_Mercator_Auxiliary_Sphere
Santa Fe
Legend
City Limits
Address Points
Building Footprint
Roads
Major Roads
Santa Fe County Parcels
Santa Fe River
Rail Road
Notes
© Latitude Geographics Group Ltd.
This map is a user generated static output from an Internet mapping site and is for reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable.
THIS MAP IS NOT TO BE USED FOR NAVIGATION

Santa Fe
Mapping the City Different

121 Camino Santiago





Legend

- City Limits
- Address Points
- Building Footprint
- Roads
- Major Roads
- Santa Fe County Parcels
- Santa Fe River
- Rail Road

Notes

© Latitude Geographics Group Ltd.

47.0 0 23.51 47.0 Feet

WGS_1984_Web_Mercator_Auxiliary_Sphere

This map is a user generated static output from an Internet mapping site and is for reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable.
THIS MAP IS NOT TO BE USED FOR NAVIGATION

Santa Fe
Mapping the City Different

104 Camino Matias



Legend

- City Limits
- Address Points
- Building Footprint
- Roads
- Major Roads
- Santa Fe County Parcels
- Santa Fe River
- Rail Road

Notes

© Latitude Geographics Group Ltd.

47.0 0 23.51 47.0 Feet

WGS_1984_Web_Mercator_Auxiliary_Sphere

This map is a user generated static output from an Internet mapping site and is for reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable.
THIS MAP IS NOT TO BE USED FOR NAVIGATION

Santa Fe
Mapping the City Different

105 Camino Matias



Legend

- City Limits
- Address Points
- Building Footprint
- Roads
- Major Roads
- Santa Fe County Parcels
- Santa Fe River
- Rail Road

Notes

© Latitude Geographics Group Ltd.

47.0 0 23.51 47.0 Feet

WGS_1984_Web_Mercator_Auxiliary_Sphere

This map is a user generated static output from an Internet mapping site and is for reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable.
THIS MAP IS NOT TO BE USED FOR NAVIGATION

Santa Fe
Mapping the City Different

107 Camino Matias





Legend

- City Limits
- Address Points
- Building Footprint
- Roads
- Major Roads
- Santa Fe County Parcels
- Santa Fe River
- Rail Road

Notes

© Latitude Geographics Group Ltd.

47.0 0 23.51 47.0 Feet

WGS_1984_Web_Mercator_Auxiliary_Sphere

This map is a user generated static output from an Internet mapping site and is for reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable.

THIS MAP IS NOT TO BE USED FOR NAVIGATION

Santa Fe
Mapping the City Different

109 Camino Matias



Legend

- City Limits
- Address Points
- Building Footprint
- Roads
- Major Roads
- Santa Fe County Parcels
- Santa Fe River
- Rail Road

Notes

© Latitude Geographics Group Ltd.

47.0 0 23.51 47.0 Feet

WGS_1984_Web_Mercator_Auxiliary_Sphere

This map is a user generated static output from an Internet mapping site and is for reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable.

THIS MAP IS NOT TO BE USED FOR NAVIGATION

Santa Fe
Mapping the City Different

111 Camino Matias



Legend

- City Limits
- Address Points
- Building Footprint
- Roads
- Major Roads
- Santa Fe County Parcels
- Santa Fe River
- Rail Road

Notes

© Latitude Geographics Group Ltd.

47.0 0 23.51 47.0 Feet

WGS_1984_Web_Mercator_Auxiliary_Sphere

This map is a user generated static output from an Internet mapping site and is for reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable.

THIS MAP IS NOT TO BE USED FOR NAVIGATION

Santa Fe
Mapping the City Different

116/120 Camino Matias





Legend

- City Limits
- Address Points
- Building Footprint
- Roads
- Major Roads
- Santa Fe County Parcels
- Santa Fe River
- Rail Road

Notes

© Latitude Geographics Group Ltd.

47.0 0 23.51 47.0 Feet

WGS_1984_Web_Mercator_Auxiliary_Sphere

This map is a user generated static output from an Internet mapping site and is for reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable.
THIS MAP IS NOT TO BE USED FOR NAVIGATION

City of Santa Fe, New Mexico

200 Lincoln Avenue, P.O. Box 909, Santa Fe, NM 87504-0909
www.santafenm.gov

Alan Webber, Mayor

Councilors:
Signe I. Lindell, Mayor Pro Tem, District 1
Renee Villarreal, District 1
Peter N. Ives, District 2
Carol Romero-Wirth, District 2
Roman "Tiger" Abeyta, District 3
Chris Rivera, District 3
Mike Harris, District 4
JoAnne Vigil Coppler, District 4

June 7, 2019

Plaza del Monte LLC
8814 Horizon Blvd, Suite 400
Albuquerque, NM 87113

RE: Review of Historic Status for Plaza del Monte

Dear Property Owner,

This letter is written notice that the City of Santa Fe Historic Districts Review Board will be reviewing the historic status designations of structures at 101, 102, 103, 105, 106, 109, 110, 111, 113, 114, 115, 117, 118, 119, 120, 121 Camino Santiago and 104, 105, 107, 109, 111, 116/120 Camino Matias in the Plaza del Monte Subdivision. The designation of a historic status category, including "significant", "contributing", and "non-contributing," is the most important determining factor in how properties within the City of Santa Fe's historic districts may be physically altered. The Official Historic Status Map for all structures that are located within the City of Santa Fe's historic districts may be found in the Historic Preservation Division at the first floor Land Use Department of City Hall at 200 Lincoln Avenue or through the City of Santa Fe website.

Please be advised that the Historic Districts Review Board will review historic status for these structures at their request and that the status review will take place at a public hearing on June 25, 2019, starting at 5:30pm in the City Council Chambers at City Hall. Decisions made by the Historic Districts Review Board regarding a change in historic status designation may be appealed to the Governing Body.

Any questions regarding this issue should be directed to the Historic Preservation Division at (505) 955-6605 or (505) 955-6577 between 8:00am and noon or between 1:00pm and 5:00pm, Monday through Friday.

Sincerely,

Lisa Roach

Lisa Gavioli Roach
Historic Preservation Division Manager

14-5.2(C)(2)(d) Notice of Board's Review of Status
(i) Staff shall mail notice, certified main return receipt requested, to the property owner of the subject property no less than fifteen days prior to the board's review of a change in or designation of status.

PLAZA DEL MONTE

Santa Fe, New Mexico

Historic Resources Evaluation

March 28, 2018

Client: Wayne S. Lloyd, A.I.A.
Lloyd & Associates, Architects
321 W. San Francisco St., Suite A
Santa Fe, NM 87501

Consultant: John W. Murphey
Architectural Historian
2833 Plaza Verde
Santa Fe, NM 87507


125

Summary

This Historic Resources Evaluation was prepared at the request of Wayne Lloyd, Lloyd and Associates, Architects. It responds to a motion the Santa Fe Historic Districts Review Board made at its November 28, 2017 hearing, requiring the applicant to provide a complete study of the buildings comprising Plaza del Monte, a former Presbyterian retirement center (Case #H-17-098A, minutes). The original application called for the demolition of five structures, addressed as 122, 124, 125, and 126 Camino Santiago, and a standalone garage/carport structure behind 126.

The present report was prepared to satisfy the Board's requirement regarding the evaluation of cultural resources set forth in the Historic Districts Ordinance (14-5.2) and the policies and guidelines developed by the City of Santa Fe Historic Preservation Division.

The Historic Districts Ordinance created a system of classifications in which cultural resources are evaluated and designated as to whether they contribute to the Historic District (14-5.2(C)(2)(a)). The Board is given the authority to designate and/or change a status of a cultural property (14-5.2(C)(2)(a)(1)). This action commonly occurs when an applicant submits a project that may affect an assigned or "un-statused" property within the Historic District. Identification of historical significance is typically accomplished through a survey and evaluation of identified resources using the New Mexico Historic Cultural Properties Inventory (HCPI) form.

Findings

After an intensive-level survey, archival investigations, and an evaluation of historical significance, the conclusion is that five buildings (102, 103, 106, 111 Camino Santiago and 104 Camino Matias) are eligible for Contributing Structure status to the Downtown and Eastside Historic District. Due to either 1) a lack of age-eligibility, or 2) non-compatible architectural elements, the remaining buildings were determined to be Noncontributing to the district.

Table of Contents

I. PROJECT DESCRIPTION 1

II. PROJECT AREA 2

III. RESEARCH METHODS 4

IV. FIELD METHODS 4

V. HISTORICAL OVERVIEW 5

VI. DESCRIPTION OF RESOURCES 16

VII. RESOURCE EVALUATION 17

VIII. TABLE OF SURVEYED RESOURCES 19

IX. BIBLIOGRAPHY 22

X. MAPS AND AERIAL PHOTOGRAPHS 23

XI. HISTORIC CULTURAL PROPERTIES INVENTORY FORMS 30

I. Project Description

The applicant, Wayne, Lloyd, Lloyd and Associates, Architects, representing the owner, Plaza del Monte, LLC, approached the Historic Districts Review Board on November 28, 2017, with a request to demolish five units of the Plaza del Monte retirement center (Case #H-17-098A).

The case planner, David Rasch, stated in his report that the five structures (122, 124, 125, and 126, and a separate garage/carport), should be determined Noncontributing, "due to marginal historic date of construction, lack of Santa Fe style, and non-historic alterations."

After discussion, the Board postponed the case, requesting the applicant provide a full historic evaluation report on the 27 units making up the former retirement community. Further discussion with David Rasch indicated that this would consist of complete HCPI forms 1 & 2 for each standing structure on the property, and an evaluation of their potential historic status for the Downtown and Eastside Historic District.

This report attempts to fulfill that request by providing HCPI forms for each residential unit, a brief historical context, associated aerial photographs and maps, and an evaluation of individual and district eligibility. The project attempted, using various sources, to determine the actual date of construction of each residential unit of Plaza del Monte.

II. Project Area

The property, generally known as Plaza del Monte, or Plaza del Monte Retirement Center, spreads across a roughly six-acre parcel located north of the Santa Fe Plaza. The pistol-shaped tract is bounded on the east by Bishop's Lodge Road; on the north by the grounds of Fort Marcy Recreation Complex and Magers Field; on the west by the alignment of Arroyo Mascaras; and on the south by a combination of land formerly associated with Plaza del Monte and tracts and residential lots under private ownership (Figure 1).

The surveyed area includes two private streets (Camino Santiago and Camino Matias) that were constructed in the 1960s as part of the retirement facility. The roads are arranged in a typical suburban pattern of a cul-de-sac and a loop. The land descends east-to-west toward the arroyo. During development, it was shaped as terraced pads along the north side of Camino Santiago. Separate terracing is found on the north side of Camino Matias, dating to an earlier construction period.

Near the center of the development is an informal grassy area that once served as a social area. Mature native trees, likely planted during the 1960s, are found throughout. The house landscapes, however, have evolved, changing from lawns to areas filled with boulders and xeric plantings. Concrete pedestrian paths loop through a few sections of the development.

Houses are typically placed in the center or close to the back of the lot. They are arranged with their long elevations facing the street. Carports are approached by wide concrete driveways. Most likely due to the limitation of the lot size or community guidelines, there are no notable ancillary structures. Grounds are kept minimal, free of tenant clutter.



Figure 1: Portion of "Santa Fe, N. Mex." USGS quadrangle map, 1961, photo-revised 1977. Scale- 1:24,000.

III. Research Methods

Prior to starting fieldwork, the project historian reviewed the City of Santa Fe's and the New Mexico Historic Preservation Division's records for properties listed and/or evaluated within the project area. This included a review of listings on the National Register of Historic Places, State Register of Cultural Properties, as well as resources documented with New Mexico Historic Building Inventory or Historic Cultural Properties Inventory forms. The research found no previous surveyed or registered properties within the project area.

A separate archival phase encompassed a review of primary and secondary sources held at various repositories, including the Fray Angélico Chávez Library, Palace of Governors Photo Library, State Library-Southwest Room and the State Archives and Records Center, all located in Santa Fe. In addition, archived newspaper and online sources were searched. The historian was also given access to an incomplete set of drawings covering most of the surveyed buildings.

IV. Field Methods

John W. Murphey, Architectural Historian, conducted a site survey on January 18, 2018. This consisted of a preliminary inventory of all standing structures on the parcel. A follow-up recordation was conducted by Sharon Joyce on February 23, 2018.

As per Santa Fe Historic Preservation Division policy, each resource was recorded with photographs documenting the principal elevations. The surveyors identified character-defining details and noted any perceived exterior alterations. The survey recorded 27 buildings on 26 Historic Cultural Properties Inventory forms. The forms are attached to this report.

V. Historical Overview

Plaza Del Monte was conceived in the late 1950s as a communal living center for retired Presbyterian pastors, missionaries, and other church officials. The Board of Pensions of the United Presbyterian Church considered this use for their Santa Fe property north of the Plaza, after the Allison-James School closed in 1958.

Established in 1880 by the Board of Domestic Missions, the school taught Spanish-American children at the junior and senior levels of high school.[1] The campus originally spread over 18 acres and included six major buildings, many designed in the Mission Revival style.

Figure 2: The Margaret Olivia Sage Hall, demolished in 1960 to construct Plaza del Monte. Source: Atkins, 1983.

With the closure of the school, the Board of Pensions began to plan for a large retirement community to join similar centers in Cooperstown, New York, Philadelphia and Kansas City. New Mexico's climate, the church's history in the state, and the fact they already owned the land motivated the Board to build the next community in Santa Fe.

In 1959, the Board selected the Santa Fe architectural firm of Kenneth S. Clark and Philippe Register Architects to create a plan for the as-of-yet-unnamed community.

[1] The school's history dates back to 1866, to the first Presbyterian Mission in Santa Fe. The school originally instructed Native American, Anglo and African American girls at the primary through high school levels. In 1934, it became a co-educational junior high school. (Work Progress Administration, "History of the Allison-James School.")

Kenneth Clark (1909-1990), an Oklahoma-born architect and Philippe de Montauzan Register (1921-2006), a younger, Yale-trained architect of French lineage, formed a partnership in 1956. Prior to the retirement center, the pair had worked on large military projects at Sandia Base and White Sands Missile Range, and locally designed the Santa Fe County Health Building (1958) and a gymnasium for the New Mexico School for the Deaf (1960), among other commissions.

The architects divided the former Allison-James School campus into two parts. The site of the older buildings, termed the "South Area" would be developed first with a congregate building. The lesser built area above the old campus ("North Area"), would be developed later with individual retirement residences.

Casa Grande

Clark and Register initially put their focus on designing the Congregate Home on a parcel fronting then Federal Way and Taos Highway. The building, later dubbed "Casa Grande" was a sprawling combined administrative and community living complex. Church staff and the architects reportedly studied congregate communities in the Netherlands to develop the design.[2] Congregate centers, an arrangement where elderly residents lived communally and were encouraged to participate in shared activities, emerged as a planning trend for retirement facilities in the United States in the 1950s.[3]

Work began on the communal center on August 1960, after the City of Santa Fe issued a $99,000 permit for the larger project.[4] In preparation, four earlier school buildings were demolished. These encompassed a hall, dormitories and a gymnasium.

Constructed in 1960-61, the Congregate Home had a layout similar to the "finger plan" used for elementary schools of the period. The plan included a long north-south oriented mass, to which were attached at right angles separate wings or "fingers" connected to each other by short corridors. The plan allowed for additional wings to be added, and a fourth was constructed in the 1970s.

The combined building included separate areas for administrative offices, a reception room, a large commercial kitchen and dining room, a lounge, a beauty parlor, and a dormitory that could house up to 40 residents.[5]

---

[2] *Santa Fe New Mexican*, August 31, 1961, 27.
[3] Geneva Mathiasen and Edward H. Noakes, editors, *Planning Homes for the Aged*, (New York: F.W. Dodge Corporation, 1959).
[4] *Santa Fe New Mexican*, September 4, 1960, 12.
[5] Ibid., October 22, 1968, 3; August 31, 1971, 15.

Facing two public streets, the southwest corner of the Congregant Home received the most architectural treatment of the development. This area became the public face of the retirement community. Here the architects placed a long entrance portal leading to the front (public) doors. A Pueblo style mass anchored the southwest corner, its broad walls cut with narrow, vertical church-like windows (Figure 3).

The Congregant Home opened on November 16, 1961. Nearly 300 people attended the ceremony for the $750,000 development.[6]



Figure 3: Casa Grande under construction, showing original south façade, May 1961. Courtesy *San Fe New Mexican*.

The parcel north of Casa Grande would be developed over the years with 20 free-standing retirement residences, colloquially called cottages.[7] This section had been lightly worked during the school's use of the property, and contained three houses constructed in 1950 for married faculty and a few ancillary structures (Figure 4 and Aerial 1). The faculty units and a moved building (111 Camino Matias) were converted into retirement homes, and were in use by the fall of 1961.

[6] Ibid., September 28, 1961, 51.
[7] Ibid., August 31, 1961, 27.

Figure 4: Rear (north) elevation of married faculty cottages, c. 1950s. Source: Atkins, 1983.

Retirement Cottages

A June 1960 preliminary layout developed by Clark and Register depicted a typical suburban cul-de-sac arrangement of free-standing homes built around two new streets (Figure 5). Camino Santiago, running along the north side of the property, terminated as a tight cul-de-sac. A second street, Camino Matias, worked as a circulating loop between Camino Santiago and the existing teacher residences to the south.



Figure 5: Portion of layout and grading plan showing cottages to be constructed, June 1960.

The architects initially proposed five new houses (R1-R5), completing the loop between the streets. Of these, four were constructed before 1966. Another 14 units, principally sited along Camino Santiago, were identified for future development on the plan.

The houses depicted on the plan reveal a uniform design. Each consisted of a modified L-plan to which was attached a carport and connecting portal. The earliest elevations prepared by Clark and Register show a design sympathetic to the Spanish-Pueblo Revival tradition (Figure 6). The front elevation included a projecting roomblock-like mass with rounded corners and a portal at a slight offset, a design trope introduced by architect John Gaw Meem nearly four decades earlier. Anchoring the end of the structure was a carport pushed back from the façade. Following the idiom, vigas were used for the actual roofing structure, window openings were small, and in most cases, arranged on the horizontal. The Spanish-Pueblo Revival theme continued along the portal and carport with a viga structure supported by rustic round posts topped with zappos-type corbels (Figure 6).



Figure 6: June 1960 Clark and Register drawing showing typical retirement residence. The drawing corresponds with 104 Camino Matias.

The floor plan, however, was mostly modern. It segregated bedrooms to a wing placed in the ell, which from the exterior looked like a rounded roomblock. The remaining functions of the house were clustered in a tight square (Figure 6).

Resident Number 1, at 104 Camino Matias, is representative of this early composition.

Evolution of Design

The design of the retirement units began to evolve as the project progressed. After the first construction phase, Philippe Register left the firm, opening his own practice in late 1960. It appears that Register and his evolving firm were contracted at least twice (1963 and 1967) by the Board of Retirement to further expand the retirement center, including a job to build an additional wing on Casa Grande. (Several houses constructed in the late 1960s and early '70s are not associated with Register's firm; their designers, at this point, are unknown).

Surviving drawings show Register pushing beyond the traditional plan of the earlier Clark and Register designs. While previous elevation and floor plans were recycled for subsequent houses, Register opted to add large areas of glass across the front façade, primarily by inserting sliding doors under the portal (103 and 111 Camino Santiago) (Figure 7). While retaining the basic roomblock bedroom wing, Register often attenuated the stem of the "L" with a more contemporary, one-room-wide Ranch house plan.

Figure 7: 111 Camino Santiago, an example of Philippe Register's transitional work.

The contemporary influence later moved to the exterior, as elevations became longer and leaner. Many reveal a then-poplar horizontal emphasis. This emphasis was furthered with overhangs arranged across front, back, and sometimes side elevations (117, 119, 121 Camino Santiago) (Figure 8). In this way, many of the units constructed in the mid-to-late 1960s are examples of the Contemporary flat-roof house form.

Figure 8: 119 Camino Santiago, an example of a Contemporary flat-roof form.

Soon the architect began to insert more radical elements to the retirement units. Register experimented with angular composition, in which side walls were divided into several splayed planes (109, 117, 119, 124 Camino Santiago) (Figure 9). This may have been influenced by his work at the College of Santa Fe, and fit within the experiments of younger architects such as Ted Luna.



Figure 9: Roof plan for 109 Camino Santiago, 1963.

The design of each unit, however, was totally driven by economy. While not particularly well-suited for the climate, carports were employed as an economical method to shelter automobiles. Prominent carports emerged as almost a design motif in the drawings produced in Register's shop. Framed by either vigas or square beams, the structures were often placed in front of the dwelling, sometimes marring the balance of composition (109, 120, 121, 122 Camino Santiago and 111 Camino Matias) (Figure 10). The use of carports further ushered the houses into the contemporary context.

Figure 10: Example of carport dominated front façade, 109 Camino Santiago.

Cost-savings also informed the selection of construction materials and finishes. All houses were erected with standard 2x4 framing, clad with stucco. The stucco was worked, most likely with rubber gloves, into a heavily textured brocade finish, a treatment used frequently in tract developments of the period. The later units were fenestrated with pre-fitted windows (steel casement or aluminum sliding) and manufactured doors. Finished floors were carpet or vinyl over concrete; walls and ceiling were faced with sand or smooth plaster.

In contrast to the factory-built materials, the carports and portales were — somewhat ironically — built with heavy, traditional timber and viga framing. The woodwork included in many instances end-lapped girders and zappos-type corbels. Even though these elements were most likely pre-cut, they added a romanticized, regional touch to the otherwise Contemporary designs.

Further Development

From aerial photographs, it appears the first phase of the retirement cottages was completed by 1966, with eight new units constructed (Aerial 3). Similar to the projected layout, the houses were grouped along Camino Matias and the east end of Camino Santiago. Two residences placed north of the earlier faculty houses framed an open grassy area, which informally became a communal area.

Subsequent work focused on developing the remaining lots. By the mid-1960s, Register had reworked the earlier layout, extending Camino Santiago several hundred feet south. He eliminated a few freestanding houses and replaced with them quad apartments.

Construction of the apartments met delays, as a variance was required to build multi-unit buildings on the residential (R2) zoned property. Further delay arrived when the Board of Adjustment voted down the apartments in 1964.[8] Eventually approved, the buildings erected between 1969 and 1971 (105, 125 and 126 Camino Santiago) contained a line of apartments flanking a central laundry room. Each apartment had a small concrete patio at the rear.

The development's later phases were prepared by a partnership Register formed in 1967 with architects James Abelardo Brunet and Terrance Ross, going by the name RSB Architects. For the apartments, the firm used novel triangular-shaped walls as dividers and end pieces. They introduced one of these walls cut with a passage to the addition given to the original Kenneth S. Clark design at 110 Camino Santiago.

Figure 11: 126 Camino Santiago.

The quad apartment block terminating Camino Santiago (126) represents the most radical plan of the development. For its design, the architects removed the roomblock massing from the ends, moving it to the center to act as hood over the laundry. Raised triangular party walls divide the sections and bookend the building (Figure 11). Despite its avant-garde appearance, a viga portal was tacked on to the front façade.

Some of the last residential units to be built in the early 1970s (120 and 122 Camino Santiago) returned to a more traditional compact, room-block massing, yet with a carport-dominant façade (Figure 12). Construction of the originally planned 20 units was finished by 1977 with the expansion of the garage/carport structure behind 126 Camino Santiago.

[8] Ibid., June 23, 1964, 36; December 29, 1964, 20; December 31, 1964, 20.

Figure 12: 120 Camino Santiago, constructed in c. 1971.

A Tightknit Community

In its nearly two decades of existence, Plaza del Monte developed into a community of retired, service-oriented professionals. Between Casa Grande and the cottages, at its height the community supported around 100 residents. Residents ranged from pastors, to clergy, to nurses and doctors who had once worked for the church. Many had been missionaries, serving across the world. A few were noteworthy. Reverend Ovid R. Sellers, who arrived in 1972 to live in the recently finished house at 120 Camino Santiago, was known in his day as a Biblical scholar with expertise on the Dead Sea Scrolls.[9]

The retirees bonded together, forming a gardening club and reading circles. Those with musical talent gave performances in their homes; another group of less talented formed the tongue-in-cheek Geriatric Glee Club.[10] Plaza del Monte, along with El Castillo and other smaller developments, set the opening chapter of a trend to accommodate retirees in the city of Santa Fe.

[9] Ibid., October 29, 1972, C-3.
[10] Ibid., December 31, 1971, 17.

Decline of Center

In the late 1980s, after experiencing heavy losses, the Presbyterian Board of Pensions began shedding retirement centers across the United States. The Board placed the entire Santa Fe property for sale in December 1987, listing it at $1.5 million. Fear of its sale led residents to leave.[11] Nearly two years later, the Presbyterian Medical Services and the Ghost Ranch Foundation signed an agreement to purchase the land. Under the terms of the agreement, Ghost Ranch would manage Casa Grande, while Presbyterian Medical Services would take over the retirement cottages.[12]

The joint use of the property lasted over 20 years before economic conditions forced both entities to sell their holdings. In 2015, a group of Albuquerque and Santa Fe investors acquired Plaza del Monte. The earlier sale of the land containing Casa Grande resulted in its demolition, which was completed in the fall of 2017.

[11] Ibid., January 3, 1988, 9; March 23, 1988, 3.
[12] Ibid., July 10, 1989, A-8.

VI. Description of Resources

Plaza del Monte holds 27 separate buildings, erected between approximately 1950 and 1977. Five of these buildings pre-date the retirement community, and are associated with the Allison-James School, a nearly 100-year-old Presbyterian mission school that was demolished in 1960 for the development of Plaza del Monte.

Of the buildings directly associated with retirement center, 12 are (or will be) 50 years of age in 2018. The remaining ten buildings were constructed after the 50-year mark, with the last completed in 1977.

The majority of units are small, single-family residences, containing 1,000 to 1,500 square-feet. These have compact and economical floor plans holding two or three bedrooms. Plaza del Monte additionally includes three apartment buildings. They are laid out as single-story, linear forms, with one to two bedroom apartments stacked in a line.

Constructed over several phases, the retirement cottages reveal a variety of architectural forms and styles. The earliest residences, designed by Kenneth S. Clark and Philippe Register, show a sympathy for the Spanish-Revival Revival tradition — employing a modified L-plan form with bedrooms placed in a wing emulating an adobe mass. Set back from the wing is a viga-roof portal, and further back, a one-bay carport.

After Register started his own firm in 1960, the designs became more contemporary, typically with a horizontal emphasis and a stronger placement of the carport. Later work became more abstracted from regional traditions, as Register and fellow architects introduced angled and splayed wall enclosures. Equally during this time, the use of glazing across the front and back elevations increased, with insertion of glass doors. While the forms and elevations were contemporary, Register continued to include regional revival elements, mostly confined to the use of canales and viga-roof portales and carports.

VII. Resource Evaluation

Existing Status

Currently, nine of the 27 freestanding structures have been assigned an historical status. Of these, eight were determined at the time to be Noncontributing (101, 102, 103 Camino Santiago and 104, 107, 109, 111, 116/120 Camino Matias) to the Downtown and Eastside Historic District (Map 1). The one Contributing structure is a 1950 teacher's cottage, located at 105 Camino Matias.

Integrity

Based on the survey, the majority of buildings were found to retain their integrity of location, design and setting. Many, if not most, have experienced a change in materials, principally through replacement of doors and windows. Only three buildings (102 and 110 (112) Camino Santiago and 116/120 Camino Matias) have received a major addition.

Evaluation

The north half of the former Plaza del Monte Presbyterian retirement center holds an array of buildings constructed in different phases between roughly 1950 and 1977. The earliest buildings are associated with the Allison-James School, which was demolished in 1960. The remaining 22 units were built as part of Plaza del Monte.

The inventory determined that of the Plaza del Monte ear buildings, 12 met (or will meet) the 50-year age mark in 2018 (Table of Surveyed Resources and Map 2). Five of these were deemed to be good examples of the development's original design template, developed by Kenneth S. Clark and Philippe Register and later, Phillipe Register. These are mostly compatible with the Old and Recent Santa Fe styles, because of their Spanish-Pueblo Revival façade treatment. The recommended Contributing houses, show a balanced composition, where the carport is set back from the portal.

The remaining seven age-eligible structures were determined Noncontributing, due to their more contemporary forms and façade treatments. In many cases, they are Contemporary-style designs dressed with regional elements, and do not represent the Recent Santa Fe Style. While novel, the use of angled and canted walls and other treatments does not contribute to the historic district or reflect the intent of the ordinance. In addition, the strong placement of

carports was found to be incompatible with the Spanish-Pueblo Revival idiom or the intent of the district ordinance.

The ten buildings constructed after 1968 were deemed Noncontributing, as they did not meet the 50-year age requirement.

Historic District

The surveyed area comprises only half of what was once a larger campus. The earliest and most architecturally significant part of the campus lay south of the retirement residences, as the Congregate Home. This building and several ancillary structures were demolished in 2017. This land is now under different ownership.

The section comprising the retirement houses reveals a mixed lineage. It encompasses buildings that predate Plaza del Monte, as well as disparate retirement units constructed during multiple phases of work, starting in 1960 and ending in 1977.

The original design for the retirement campus is represented in only a few buildings. The remaining units move away from that template and reflect more evolving architectural trends. In this way, the development does not communicate a unified history, pattern of development, or unified architectural vocabulary, as found with other multi-phased communities in Santa Fe.

Given its disparate origins and lack of cohesive architectural style, it was determined that the collection of retirement residences is not eligible for separate Historic District designation.

VIII. Table of Surveyed Resources

Address	Year Built*	Architect Date of Drawings	Existing Status	Recommended Status	First City Directory Entry
CAMINO SANTIAGO					
101	c.1967-68	Unknown	Non Contributing	Non Contributing	1967 "Under Construction"
102 R-2	c.1965	Kenneth S. Clark & Philippe Register, assumed	Non Contributing	Contributing	1966 Gaylord Knox
103 R-12	c.1965	Philippe Register 1962	Non Contributing	Contributing	1966 Joseph M. McNeill
105 R-14	1971	Register, Ross & Burnet 1970	No Status	Non Contributing	1972 Ruth Erwin and Ellen Foster
106 R-3	c.1965	Kenneth S. Clark & Philippe Register, assumed	No Status	Contributing	1966 Deforest N. Shotwell
R-15	c.1965	Philippe Register 1963	No Status	Non Contributing	1966 Jane Barber
110 (112) R-5	c.1962/ c.1968	Kenneth S. Clark 1962, original house; Register, Ross & Burnet, addition	No Status	Non Contributing	1966 Dorothy B. Fritz (110) 1970 Theo R. Finley (112)
111	c.1965	Philippe Register 1963	No Status	Contributing	1966 Neva B. Palameter
113	c.1970	Unknown	No Status	Non Contributing	1971 Harry B. Wood
114 R-26	c.1972	Register, Ross & Burnet 1971	No Status	Non Contributing	1972 "Under Construction"
115	c.1970	Unknown	No Status	Non Contributing	1971 Westley L. Almy

Address	Year Built*	Architect Date of Drawings	Existing Status	Recommended Status	First City Directory Entry
117	1966-67	Philippe Register 1965; 1966	No Status	Non Contributing	1967 Reverend David H. Thomas
118	c.1973	Register, Ross & Burnet 1971 Register & Burnet 1972	No Status	Non Contributing	1974 Duncan R. Spinning
119	c.1965	Philippe Register 1965/1968	No Status	Non Contributing	1966 Muriel M. Boone
120 R-25	c. 1971	Register, Ross & Burnet 1970	No Status	Non Contributing	1972 Ovid Sellers
121 R-20	c.1971	Register, Ross & Burnet 1970	No Status	Non Contributing	1972 Boyd L. Gilbert
122	c.1971	Register, Ross & Burnet 1967	No Status	Non Contributing	1972 Dewitt Safford
1 3	c.1968	Philippe Register 1967	No Status	Non Contributing	1968 "Under Construction"
125 R-21	c.1970	Register, Ross & Burnet 1969	No Status	Non Contributing	1971 John M. Currie, Violet Sherratt, Merrrill Henry, Warren Blodgett
126 R-24	c.1968	Philippe Register 1967	No Status	Non Contributing	1968 "Under Construction"
126 Garage	c.1968/ 1977	Unknown		Non Contributing	N/A
CAMINO MATIAS					
104	c.1965	Kenneth S. Clark & Philippe Register, assumed; Philippe Register 1963, alteration	Non Contributing	Contributing	1966 Frederick Dawson
105 R-10	1950	Unknown	Contributing	Non Contributing	N/A Pre-existing Building

Address	Year Built*	Architect Date of Drawings	Existing Status	Recommended Status	First City Directory Entry
107 R-9	1950	Unknown	Non Contributing	Non Contributing	N/A Pre-existing Building
109 R-8	1950	Unknown	Non Contributing	Non Contributing	N/A Pre-existing Building
111 R-6	Pre-1960, moved to site	Unknown	Non Contributing	Non Contributing	N/A Pre-existing Building
116/120 R-7	Pre-1957, with c.1984 additions	Unknown; Philippe Register and Associates 1984	Non Contributing	Non Contributing	N/A Pre-existing Building

** The date of construction is derived from a number of sources, including original drawings, aerial photographs, USGS quadrangle maps, city directory entries and newspaper accounts. The identified construction date is considered for more accurate than dates provided by the Santa Fe County Assessor records, which are often inaccurate.*

IX. Bibliography

Atkins, Carolyn. *The Allison-James Picture Book, 1866-1959*. Albuquerque: Menaul Historical Library of the Southwest, 1983.

Bunting, Bainbridge. *Architecture in New Mexico*. Albuquerque: University of New Mexico Press, 1976.

Bunting, Bainbridge and John P. Conron. "The Architecture of Northern New Mexico." New Mexico Architecture. Vol. 8 Nos. 9 and 10, September-October 1966: 14-50.

Mathiasen, Geneva and Edward H. Noakes, editors. *Planning Homes for the Aged*. New York: F.W. Dodge Corporation, 1959.

Santa Fe New Mexican (newspaper). Various issues: 1958-2016.

Sze, Corrine P. and Beverly Spears. *Santa Fe Historic Neighborhood Study*. Report prepared for the City of Santa Fe, 1988.

Works Progress Administration. "History of the Allison-James School." No date. Typed manuscript. "Presbyterian Church" vertical file, Fray Angélico Chávez Library, Santa Fe.

X. Maps and Aerial Photographs



Map 1: Currrent Historic Status Designations.
Source: City of Santa Fe GIS, Historic Districts Overlay.

Map 2: Recommended Status made by consultant.
Source: City of Santa Fe GIS, Historic Districts Overlay.



Map 3: 1948 map showing extent of Allison-James School campus.
All buildings except for structure in dashed box were demolished in 1960 to create Plaza del Monte.
Source: 1930/1948 Sanborn Fire Insurance Map.



Aerial 1: 1951 Aerial Photograph.
Dashed box indicates presence of three married residences.
Courtesy NMDOT.



Aerial 2: November 10, 1958 Aerial Photograph. Dashed box indicates presence of combined unit, currently addressed as 116/120 Camino Matias. Courtesy NMDOT.

Aerial 3: May 2, 1966 Aerial Photograph.
Images indicates eight residences had been completed at this time.
Courtesy NMDOT.

Aerial 4: February 27, 1969 Aerial Photograph. Image shows residences constructed to date. Courtesy NMDOT.

XI. Historic Cultural Properties Inventory Forms

See attached forms

PLAZA DEL MONTE

Santa Fe, New Mexico
Historic Resources Evaluation

Amendment to March 28, 2018 Report

May 7, 2018

Client: Wayne S. Lloyd, A.I.A.
Lloyd and Associates, Architects
100 N Guadalupe Street, # 201
Santa Fe, NM 87501

Consultant: John W. Murphey
Architectural Historian
2833 Plaza Verde
Santa Fe, NM 87507

RECEIVED
MAY 08 2018
BY:_____

Introduction

This brief amendment addresses issues the Historic Districts Review Board brought up at the April 24, 2018 hearing, as well as information requested by the City of Santa Fe Historic Preservation Division after the hearing.

Retaining Walls: 124 and 126 A Camino Santiago

David Rasch, the case manager for the project, communicated to the applicant after the hearing that the retaining walls of the two units granted demolition by the Board required documentation.

On May 3, 2018, the consultant recorded the retaining walls at 124 and 126 A Camino Santiago (the combined garage/carport structure), associated with the two units granted demolition at the April 24, 2018 hearing.

Both units include low concrete-and-stone walls which work as retaining walls and/or transitions between building pads.

The wall for 126 A retains the dirt between the apartment building (126) and the parking stalls. It is constructed of non-reinforced concrete, mixed with heavy stones most likely taken from the adjacent arroyo (Figure 1).

The wall is erected over a concrete walkway and stands approximately 32" above the sidewalk and 14" above the contained earth. The 10"-thick structure presents an angled face similar to a dam. It is topped with rounded concrete coping. The wall runs the length of the parking structure before tapering to the ground on the west and rising above grade to the east as a pathway entry.

A wall of similar composition edges the south and east exposures of the back yard of 124 Camino Santiago (Figure 2). It begins at 9½" above grade at the patio, and continues in a northerly direction, ranging between 18" to 26" above inside grade. Near the northeast tangent, it connects with another wall erected with the construction of 122 Camino Santiago.

Based on aerial photographs, neither the 124 nor 126 A retaining walls predate the construction of their associated units. And while this fact is inconclusive, neither wall is visible on the February 28, 1968 aerial photograph (Aerial 1). The retaining walls are apparent on a February 27, 1969 photograph, indicating the completion of the units and their landscaping (Aerial 2).

Given their low architectural value, and assumed c.1968+ construction date, neither is recommended for Contributing Structure status to the Downtown and Eastside Historic District.

Additional Walls

As stated in the Historic Resources Evaluation, the Plaza del Monte landscape includes a number of retaining walls. The retaining walls, constructed of formed concrete or concrete and stone, were built over several phases, dating generally between 1950 and 1973. The walls were constructed to retain earth or to separate building pads (Figure 3). Very few of them rise above grade. A few lots have above-ground property line walls. These are made of stucco-clad concrete masonry units (Figure 4). From aerial photographs, both retaining and property line walls appear to post-date the construction of their associated units.

Given their recent date of construction and utilitarian quality, the retaining and property walls are not recommended for individual or collective Contributing Structure status to the Downtown and Eastside Historic District.

Aerial Imagery

To address the Board's concern over the lack of c.1968-69 aerial imagery for the west side of Plaza del Monte, the consultant approached the NMDOT seeking additional photographs.

The head of aerial photography, Alane Wainwright, confirmed in an April 30 email to the consultant that the February 27, 1969 aerial (1969_02_27_4072) presented in the Historic Resources Evaluation represented the end of the flight line. The email supported her January 17, 2018 communication, which asserted that the image was all that the NMDOT could offer. Wainwright explained in that email that the image didn't "get the entire area."[1]

However, given the importance of the case, on April 30 Wainwright performed an additional due-diligence search and found three 1968-69 era photographs that are not available to the public.[2] These include two secondary images from the February 27, 1969 flight and one from February 28, 1968. Wainwright additionally provided several images from May 1973.

Both the 1968 and 1969 aerials show the southwest quadrant of Plaza del Monte to be populated with only two structures: 124 and 126 Camino Santiago (Aerials 1 & 2).

---

[1] Alane Wainwright, email communication to John Murphey, January 17, 2018.
[2] Ibid., April 30, 2018.

The newly revealed aerial photographs present a strong case that only a handful of units were fully completed by February 28, 1968. The 1973 image shows most of the units finished, and 118 Camino Santiago still in the framing stage (Aerial 3).

Construction Dates

At the April 24, 2018 hearing, the Board expressed apprehension about the report's assigned construction dates. The dates were premised on the consultant's methodology which used various sources (primarily aerial photographs, city directory entries, and architectural drawings), to arrive at a relative — though most often accurate — "circa" date of construction.

Sowing confusion was mention of a 1988 appraiser's estimate of dates introduced during sworn testimony. This information was neither viewed by the Board nor officially introduced into the record.

Given the Board's questioning, the consultant reviewed the sources again, examined the 1988 appraiser's estimates, and evaluated the additional aerial photographs recently made available. This analysis is presented in the table below.

After this exercise, the consultant believes that the Historic Resources Evaluation's assigned dates of construction are mainly accurate.

Table 1: Year of Construction

Address	Year Built*	Date of Drawings	1988 Appraiser's Estimate**	Consultant's Original and/or Revised Estimate ***	Source and Justification
CAMINO SANTIAGO					
101	c.1967-68	Unknown	1968	c.1967-68	Aerial photographs and first city directory
102 R-2	c.1965	Kenneth S. Clark & Philippe Register, assumed	1962 *Appraiser assigns address to Camino Matias*	Before 1966	May 2, 1966 aerial photograph and first city directory entry
103 R-12	c.1965	Philippe Register 1962	1968	Before 1966	May 2, 1966 aerial photograph and first city directory entry
105 R-14	1971	Register, Ross & Burnet 1970	1962	1971	Does not appear on either May 2, 1966 or February 27, 1969 aerial photographs Drawing, aerial photographs and first city directory entry
106 R-3	c.1965	Kenneth S. Clark & Philippe Register, assumed	1962 *Appraiser assigns address to Camino Matias*	Before 1966	May 2, 1966 aerial photograph and first city directory entry
109 R-15	c.1965	Philippe Register 1963	1963	Before 1966	May 2, 1966 aerial photograph and first city directory entry
110 (112) R-5	c.1962/ c.1968	Kenneth S. Clark 1962, original house; Register, Ross & Burnet, addition	110: 1962 112: 1968	110: c.1962 112: c.1968	Drawings, aerial photographs and first city directory entries
111	c.1965	Philippe Register 1963	Unknown; remodeled, 1962	Before 1966	Drawings, aerial photographs and first city directory entry
113	c.1970	Unknown	1970 *Appraiser assigns address as 115 a*	c.1970	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry
114 R-26	c.1972	Register, Ross & Burnet 1971	1971	c.1972	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry
115	c.1970	Unknown	1970	c.1970	Does not appear on February 27, 1969 aerial photograph First city directory entry
117	1966-67	Philippe Register 1965; 1966	Unknown; estimated 1963-1968	1966-67	May 2, 1966 aerial photograph and first city directory entry

Address	Year Built*	Date of Drawings	1988 Appraiser's Estimate**	Consultant's Original and/or Revised Estimate ***	Source and Justification
118	c.1973	Register, Ross & Burnet 1971 Register & Burnet 1972	1972	**1973**	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry
119	c.1965	Philippe Register 1965/1968	1963	**Before 1966**	May 2, 1966 aerial photograph and first city directory entry
120 R-25	c. 1971	Register, Ross & Burnet 1970	1970	c. 1971	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry
121 R-20	c.1971	Register, Ross & Burnet 1970	1970	**c.1971**	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry
122	c.1971	Register, Ross & Burnet 1967	Unknown; estimated 1963-1968	**c.1971**	Does not appear on February 27, 1969 aerial photograph First city directory entry
124 R-23	c.1968	Philippe Register 1967	1964	**c.1968**	Does not appear on May 2, 1966 aerial photograph.
125 R-21	c.1970	Register, Ross & Burnet 1969	1969	**c.1970**	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry
126 R-24	c.1968	Philippe Register 1967	1967	**c.1968**	Drawings, aerial photographs and first city directory entry
126 Garage	c.1968/ 1977	Unknown	No covered	**c.1968/ 1977**	Drawings and April 9, 1975 aerial photograph
CAMINO MATIAS					
104	c.1965	Kenneth S. Clark & Philippe Register, assumed; Philippe Register 1963, alteration	1962	**Before 1966**	May 2, 1966 aerial photograph
105 R-10	1950	Unknown	Unknown; remodeled 1962	**1950**	Carolyn Atkins, *The Allison-Jomes Picture Book, 1866-1959*, (Albuquerque: Menaul Historical Library of the Southwest, 1983), 25; aerial photographs
107 R-9	1950	Unknown	Unknown; remodeled 1962	**1950**	Carolyn Atkins, *The Allison-James Picture Book, 1866-1959*, (Albuquerque: Menaul Historical Library of the Southwest, 1983), 25; aerial photographs
109 R-8	1950	Unknown	Unknown; remodeled 1962	**1950**	Carolyn Atkins, *The Allison-James Picture Book, 1866-1959*, (Albuquerque: Menaul Historical Library of the

Address	Year Built*	Date of Drawings	1988 Appraiser's Estimate**	Consultant's Original and/or Revised Estimate ***	Source and Justification
					Southwest, 1983), 25; aerial photographs
111 R-6	Pre-1960, moved to site	Unknown	Unknown; remodeled 1962	Pre-1960, moved to site	Aerial photographs
116/120 R-7	Pre-1957, with c.1984 additions	Unknown; Philippe Register and Associates 1984	110: Unknown; renovated 1967; remodeled 1986 120: remodeled/ Renovated 1962	Pre-1957, with c.1984 additions	Drawings and aerial photographs

Key:

**The year the consultant originally estimated, as presented in March 28, 2018,* Plaza del Monte, Santa Fe, Historic Resources Evaluation *report.*

*** Taken from "As of 1988" table of appraiser's estimate of construction dates. The table was referenced in sworn testimony during the April 24, 2018, Historic Districts Review Board hearing. The Board did not see the table nor was it introduced in the record. The consultant took an iPhone image of the table at the hearing (Figure 3).*

**** The consultant's original and/or revised estimate based on best sources available, including dated aerial photographs, dated architectural drawings and dated city directory entries, and previously publicly unavailable February 28, 1968 and February 27, 1969 aerial photographs, NMDOT provided to consultant on April 30, 2018.*

Figures and Aerial Photographs

Figure 1: 126 A Camino Santiago, Garage/Carport Structure, retaining wall, May 3, 2018.

Figure 2: 124 Camino Santiago, rear retaining wall, May 3, 2018.

Figure 3: c.1950 concrete retaining in front of 107 Camino Matias. January 18, 2018.



Figure 4: Stucco-on-block property wall between 114 and 118 Camino Santiago, January 18, 2018.



IMPROVEMENT SUMMARY CHART
LAS PLACITAS RESIDENTIAL COMPOUND
PLAZA DEL MONTE

I.D.	Street Address	Type of Dwelling	Area (Sq.Ft.)	Room Count (Total-Bedrooms-Baths)	Age (Yrs.)	Comments
R-1	104 Camino Matias	Single-Family	944	4-2-1.5	26	
R-2	102 Camino Matias	Single-Family	944	4-2-1.5	26	
R-3	106 Camino Matias	Single-Family	944	4-2-1.5	26	
R-4	118 Camino Santiago	Single-Family	1,141	5-2-2	16	
R-5a	110 Camino Matias	Duplex	897	5-2-1	26	
R-5b	112 Camino Matias	Duplex	839	4-1-1	26	Addition 1968
R-6	111 Camino Matias	Single-Family	1,433	6-3-2	Unknown	Remodeled/Renovated 1962
R-7a	116 Camino Matias	Duplex	1,072	4-2-2	Unknown	Renovated 1967, Remodeled 1986
R-7b	120 Camino Matias	Duplex	1,099	4-2-2	Unknown	Renovated 1962, Remodeled 1986
R-8	109 Camino Matias	Single-Family	1,095	5-2-1	Unknown	Remodeled/Renovated 1962
R-9	107 Camino Matias	Single-Family	932	4-2-1	Unknown	Remodeled/Renovated 1962
R-10	105 Camino Matias	Single-Family	932	5-2-1	Unknown	Remodeled/Renovated 1962
R-11	101 Camino Santiago	Single-Family	1,163	4-2-1	20	
R-12	103 Camino Santiago	Single-Family	1,064	5-2-2	20	
R-14a	105a Camino Santiago	Fourplex	926	4-2-1	26	
R-14b	105b Camino Santiago	Fourplex	699	3-2-1	26	
R-14c	105c Camino Santiago	Fourplex	699	3-2-1	26	
R-14d	105d Camino Santiago	Fourplex	926	4-2-1	26	
R-15	109 Camino Santiago	Single-Family	1,029	4-2-2	25	
R-16	111 Camino Santiago	Single-Family	1,082	4-2-2	25	
R-17a	115a Camino Santiago	Duplex	1,052	4-2-2	18	
R-17b	115b Camino Santiago	Duplex	1,179	4-2-2	18	
R-18	117 Camino Santiago	Single-Family	1,356	6-2-2	Unknown	Estimated effective age 20-25 yrs.
R-19	119 Camino Santiago	Single-Family	1,105	5-2-1	25	
R-20	121 Camino Santiago	Single-Family	1,152	5-2-2	18	
R-21a	125a Camino Santiago	Fourplex	944	4-2-1	19	
R-21b	125b Camino Santiago	Fourplex	676	3-2-1	19	
R-21c	125c Camino Santiago	Fourplex	676	3-2-1	19	
R-21d	125d Camino Santiago	Fourplex	944	4-2-1	19	
R-22	122 Camino Santiago	Single-Family	1,218	5-2-2	Unknown	Estimated effective age 20-25 yrs.
R-23	124 Camino Santiago	Single-Family	1,153	4-2-2	21	
R-24a	126a Camino Santiago	Fourplex	690	3-1-1	21	
R-24b	126b Camino Santiago	Fourplex	690	3-1-1	21	
R-24c	126c Camino Santiago	Fourplex	690	3-1-1	21	
R-24d	126d Camino Santiago	Fourplex	690	3-1-1	21	
R-25	120 Camino Santiago	Single-Family	1,259	5-2-2	18	
R-26	114 Camino Santiago	Single-Family	1,318	4-2-2	17	

Figure 5: iPhone image of c.1988 Plaza del Monte appraiser report referenced at April 24, 2018 hearing.

Aerial 1: Portion of February 28, 1968 aerial photograph. Source: NMDOT – 02_28_68_0021.

Aerial 2: Portion of February 27, 1969 aerial photograph. Source: NMDOT – 1969_2_27_4071.



Aerial 3: Portion of May 11, 1973 aerial photograph showing 118 Camino Santiago under construction. Source: NMDOT- 05-11-73_0053.

PLAZA DEL MONTE

Santa Fe, New Mexico
Historic Resources Evaluation

Second Amendment to March 28, 2018 Report

May 17, 2018

Client: Wayne S. Lloyd, A.I.A.
Lloyd and Associates, Architects
100 N Guadalupe Street, # 201
Santa Fe, NM 87501

Consultant: John W. Murphey
Architectural Historian
2833 Plaza Verde
Santa Fe, NM 87507

Introduction

This second amendment addresses issues the Historic Districts Review Board brought up at the April 24, 2018 hearing, information requested by the City of Santa Fe Historic Preservation Division after that hearing, and additional comments made by the Board at the follow-up May 17, 2018 hearing.

Retaining Walls: 124 and 126 A Camino Santiago

David Rasch, the case manager for the project, communicated to the applicant after the April 24 hearing that the retaining walls of the two units granted demolition by the Board required documentation.

On May 3, 2018, the consultant recorded the retaining walls at 124 and 126 A Camino Santiago (the combined garage/carport structure), associated with the two units granted demolition.

Both units include low concrete-and-stone walls which work as retaining walls and/or transitions between building pads.

The wall for 126 A retains the dirt between the apartment building (126) and the parking stalls. It is constructed of non-reinforced concrete, mixed with heavy stones most likely taken from the adjacent arroyo (Figure 1).

The wall is erected over a concrete walkway and stands approximately 32" above the sidewalk and 14" above the contained earth. The 10"-thick structure presents an angled face similar to a dam. It is topped with rounded concrete coping. The wall runs the length of the parking structure before tapering to the ground on the west and rising above grade to the east as a pathway entry.

A wall of similar composition but of lesser height edges the south and east exposures of the back yard of 124 Camino Santiago (Figure 2). It begins at 9½" above grade at the patio, and continues in a northerly direction, ranging between 18" to 26" above inside grade. Near the northeast tangent, it connects with another wall erected with the construction of 122 Camino Santiago.

Based on aerial photographs, neither the 124 nor 126 A retaining walls predate the construction of their associated units. And while this fact is inconclusive, neither wall is visible on the February 28, 1968 aerial photograph (Aerial 2). The retaining walls are apparent on a

February 27, 1969 photograph, indicating the completion of the units and their landscaping (Aerial 3).

Given their low architectural value, and assumed c.1968+ construction date, neither is recommended for Contributing Structure status to the Downtown and Eastside Historic District.

Additional Walls

As stated in the Historic Resources Evaluation, the Plaza del Monte landscape includes a number of retaining walls. The retaining walls, constructed of formed concrete or concrete and stone, were built over several phases, dating generally between 1950 and 1973. The walls were constructed to retain earth or to separate building pads (Figure 3). Very few of them rise above grade. A few lots have above-ground property line walls. These are made of stucco-clad concrete masonry units (Figure 4). From aerial photographs, both retaining and property line walls appear to post-date the construction of their associated units.

Given their recent date of construction and utilitarian quality, the retaining and property walls are not recommended for individual or collective Contributing Structure status to the Downtown and Eastside Historic District.

Aerial Imagery

To address the Board's concern over the lack of c.1968-69 aerial imagery for the west side of Plaza del Monte, the consultant approached the NMDOT seeking additional photographs after the April 24 hearing.

The head of aerial photography, Alane Wainwright, confirmed in an April 30 email to the consultant that the February 27, 1969 aerial (1969_02_27_4072) presented in the Historic Resources Evaluation represented the end of the flight line. The email supported her January 17, 2018 communication, which asserted that the image was all that the NMDOT could offer. Wainwright explained in that email that the image didn't "get the entire area."[1]

However, given the importance of the case, Wainwright performed an additional due-diligence search and found three 1968-69 era photographs that are not available to the public.[2] These

[1] Alane Wainwright, email communication to John Murphey, January 17, 2018. See chain of communication in Appendix A.
[2] Ibid., April 30, 2018.

include two secondary images from the February 27, 1969 flight and one from February 28, 1968. Wainwright additionally provided several photographs from May 1973.

Both the 1968 and 1969 aerials show the southwest quadrant of Plaza del Monte to be populated with only two structures: 124 and 126 Camino Santiago (Aerials 2 & 3).

The newly revealed aerial photographs present a strong case that only a handful of units were fully completed by February 28, 1968. The 1973 image shows most of the units finished, and 118 Camino Santiago still in the framing stage (Aerial 4).

At the follow-up May 15, 2018 hearing, member Powell expressed suspicion over the fact that additional aerial photographs had surfaced after the initial hearing. The consultant includes with this amendment the entire email communication with NMDOT's Alane Wainwright. The communications on January 16, January 17, April 26, April 30 and May 1 are specific to this subject (Appendix A).

Construction Dates

At the April 24, 2018 hearing, a few members of the Board expressed apprehension about the report's assigned construction dates. The dates were premised on the consultant's methodology which used various sources (primarily aerial photographs, city directory entries, and architectural drawings), to arrive at a relative — though most often accurate — "circa" date of construction.

Sowing confusion was mention of a 1988 appraiser's estimate of dates introduced during sworn testimony. This information was neither viewed by the Board nor officially introduced into the record.

Given the Board's questioning, the consultant reviewed the sources again, examined the 1988 appraiser's estimates, and evaluated the additional aerial photographs recently made available. This analysis is presented in Table 1.

At the follow-up hearing, member Powell continued to question the dates of construction provided by the consultant, pointing to differing years he found on the Santa Fe County Assessor's parcel map website, from his cellphone during the hearing. The consultant had already discarded the county's dates as being mostly inaccurate, as noted in the Table of Surveyed Resources in the March 28 report. But given Powell's insistence, the consultant reviewed the assessor's dates again on May 17, and identifies the errors in the county's

estimates in Table 2. In general, the county's dates do not comport with evidence found on aerial photographs.

At conclusion of both exercises, the consultant believes that the Historic Resources Evaluation's assigned dates of construction are mainly accurate. The consultant, however, because of timing issues, did not get to review additional material that may have surfaced at the Santa Fe Presbyterian church library or the Menaul facility.

Table 1: Year of Construction

Address	Year Built*	Date of Drawings	1988 Appraiser's Estimate**	Consultant's Original and/or Revised Estimate ***	Source and Justification
CAMINO SANTIAGO					
101	c.1967-68	Unknown	1968	**c.1967-68**	Aerial photographs and first city directory
102 R-2	c.1965	Kenneth S. Clark & Philippe Register, assumed	1962 *Appraiser assigns address to Camino Matias*	**Before 1966**	May 2, 1966 aerial photograph and first city directory entry
103 (-12	c.1965	Philippe Register 1962	1968	**Before 1966**	May 2, 1966 aerial photograph and first city directory entry
105 R-14	1971	Register, Ross & Burnet 1970	1962	**1971**	Does not appear on either May 2, 1966 or February 27, 1969 aerial photographs Drawing, aerial photographs and first city directory entry
106 R-3	c.1965	Kenneth S. Clark & Philippe Register, assumed	1962 *Appraiser assigns address to Camino Matias*	**Before 1966**	May 2, 1966 aerial photograph and first city directory entry
109 R-15	c.1965	Philippe Register 1963	1963	**Before 1966**	May 2, 1966 aerial photograph and first city directory entry
110 (112) R-5	c.1962/ c.1968	Kenneth S. Clark 1962, original house; Register, Ross & Burnet, addition	110: 1962 112: 1968	110: c.**1962** 112: **c.1968**	Drawings, aerial photographs and first city directory entries
111	c.1965	Philippe Register 1963	Unknown; remodeled, 1962	**Before 1966**	Drawings, aerial photographs and first city directory entry
113	c.1970	Unknown	1970 *Appraiser assigns address as 115 a*	**c.1970**	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry

ddress	Year Built*	Date of Drawings	1988 Appraiser's Estimate**	Consultant's Original and/or Revised Estimate ***	Source and Justification
114 R-26	c.1972	Register, Ross & Burnet 1971	1971	**c.1972**	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry
115	c.1970	Unknown	1970	**c.1970**	Does not appear on February 27, 1969 aerial photograph First city directory entry
117	1966-67	Philippe Register 1965; 1966	Unknown; estimated 1963-1968	**1966-67**	May 2, 1966 aerial photograph and first city directory entry
118	c.1973	Register, Ross & Burnet 1971 Register & Burnet 1972	1972	**1973**	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry
119	c.1965	Philippe Register 1965/1968	1963	**Before 1966**	May 2, 1966 aerial photograph and first city directory entry
120 R-25	c. 1971	Register, Ross & Burnet 1970	1970	**c. 1971**	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry
121 R-20	c.1971	Register, Ross & Burnet 1970	1970	**c.1971**	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry
122	c.1971	Register, Ross & Burnet 1967	Unknown; estimated 1963-1968	**c.1971**	Does not appear on February 27, 1969 aerial photograph First city directory entry
124 R-23	c.1968	Philippe Register 1967	1964	**c.1967**	Does not appear on May 2, 1966 aerial photograph.
125 R-21	c.1970	Register, Ross & Burnet 1969	1969	**c.1970**	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry
126 R-24	c.1968	Philippe Register 1967	1967	**c.1967**	Drawings, aerial photographs and first city directory entry
126 Garage	c.1968/ 1977	Unknown	No covered	**c.1968/ 1977**	Drawings and April 9, 1975 aerial photograph
CAMINO MATIAS					
104	c.1965	Kenneth S. Clark & Philippe Register, assumed; Philippe Register 1963, alteration	1962	**Before 1966**	May 2, 1966 aerial photograph

ddress	Year Built*	Date of Drawings	1988 Appraiser's Estimate**	Consultant's Original and/or Revised Estimate ***	Source and Justification
105 R-10	1950	Unknown	Unknown; remodeled 1962	**1950**	Carolyn Atkins, *The Allison-James Picture Book, 1866-1959*, (Albuquerque: Menaul Historical Library of the Southwest, 1983), 25; aerial photographs
107 R-9	1950	Unknown	Unknown; remodeled 1962	**1950**	Carolyn Atkins, *The Allison-James Picture Book, 1866-1959*, (Albuquerque: Menaul Historical Library of the Southwest, 1983), 25; aerial photographs
109 R-8	1950	Unknown	Unknown; remodeled 1962	**1950**	Carolyn Atkins, *The Allison-James Picture Book, 1866-1959*, (Albuquerque: Menaul Historical Library of the Southwest, 1983), 25; aerial photographs
111 R-6	Pre-1960, moved to site	Unknown	Unknown; remodeled 1962	**Pre-1960, moved to site**	Aerial photographs
116/120 R-7	Pre-1957, with c.1984 additions	Unknown; Philippe Register and Associates 1984	110: Unknown; renovated 1967; remodeled 1986 120: remodeled/ Renovated 1962	**Pre-1957, with c.1984 additions**	Drawings and aerial photographs

Key:

**The year the consultant originally estimated, as presented in March 28, 2018,* Plaza del Monte, Santa Fe, Historic Resources Evaluation *report.*

*** Taken from "As of 1988" table of appraiser's estimate of construction dates. The table was referenced in sworn testimony during the April 24, 2018, Historic Districts Review Board hearing. The Board did not see the table nor was it introduced in the record. The consultant took an iPhone image of the table at the hearing (Figure 5).*

**** The consultant's original and/or revised estimate based on best sources available, including dated aerial photographs, dated architectural drawings and dated city directory entries, and previously unavailable February 28, 1968 and February 27, 1969 aerial photographs, NMDOT provided to consultant on April 30, 2018.*

Table 2: Santa Fe County Assessor Dates

Address	Consultant's Original and/or Revised Estimate *	Santa Fe County Assessor Estimate**	Errors with County Estimated Dates
CAMINO SANTIAGO			
101	c.1967-68	1964	Does not appear on May 2, 1966 aerial photograph
102 R-2	Before 1966	1964	Only May 2, 1966 aerial photograph available for the period
103 R-12	Before 1966	1964	Does not appear on May 2, 1966 aerial photograph
105 R-14	1971	1964	Does not appear on either May 2, 1966 or February 27, 1969 aerial photographs
106 R-3	Before 1966	1964	Only May 2, 1966 aerial photograph available for the period
109 R-15	Before 1966	1964	Only May 2, 1966 aerial photograph available for the period
110 112) R-5	110: c.1962 112: c.1968	1969	Appears on May 2, 1966 aerial photograph
111	Before 1966	No Date Provided	
113	c.1970	1964	Does not appear on either May 2, 1966 or February 27, 1969 aerial photographs
114 R-26	c.1972	No Date Provided	
115	c.1970	1964	Does not appear on either May 2, 1966 or February 27, 1969 aerial photographs
117	1966-67	1964	Only May 2, 1966 aerial photograph available for the period
118	1973		Does not appear on February 27, 1969 aerial photograph; still under construction on May 3, 1973 aerial photograph
119	Before 1966	1969	Appears on May 2, 1966 aerial photograph
120 R-25	c. 1971	1968	Does not appear on February 27, 1969 aerial photograph

ddress	Consultant's Original and/or Revised Estimate *	Santa Fe County Assessor Estimate**	Errors with County Estimated Dates
121 R-20	c.1971	1969	Does not appear on February 27, 1969 aerial photograph
122	c.1971	1968	Does not appear on February 27, 1969 aerial photograph
124 R-23	c.1967	1968	
125 R-21	c.1970	No Date Provided	
126 R-24	c.1967	No Date Provided	
126 Garage	c.1968/ 1977	No Date Provided	
CAMINO MATIAS			
104	Before 1966	1968	Appears on May 2, 1966 aerial photograph
05 R-10	1950	1964	Documented as constructed in 1950 in Carolyn Atkins, *The Allison-James Picture Book, 1866-1959*, (Albuquerque: Menaul Historical Library of the Southwest, 1983), 25, and appears on 1951 aerial photograph
107 R-9	1950	1964	Documented as constructed in 1950 in Carolyn Atkins, *The Allison-James Picture Book, 1866-1959*, (Albuquerque: Menaul Historical Library of the Southwest, 1983), 25, and appears on 1951 aerial photograph
109 R-8	1950	1964	Documented as constructed in 1950 in Carolyn Atkins, *The Allison-James Picture Book, 1866-1959*, (Albuquerque: Menaul Historical Library of the Southwest, 1983), 25, and appears on 1951 aerial photograph
111 R-6	Pre-1960, moved to site	1969	Appears on May 2, 1966 aerial photograph
116/120 R-7	Pre-1957, with c.1984 additions	No Date Provided	

Key:

**The consultant's original and/or revised estimate based on best sources available, including dated aerial photographs, dated architectural drawings and dated city directory entries, and previously unavailable February 28, 1968 and February 27, 1969 aerial photographs, NMDOT provided to consultant on April 30, 2018, and additional review of images after May 15 hearing.*

*** Dates as taken from Santa Fe County Assessor parcel map (http://assessor.santafecountynm.gov/map.php) on May 17, 2018. Webpage states the information was accurate as of April 3, 2018.*

Figures and Aerial Photographs

Figure 1: 126 A Camino Santiago, Garage/Carport Structure, retaining wall, May 3, 2018.

Figure 2: 124 Camino Santiago, rear retaining wall, May 3, 2018.

Figure 3: c.1950 concrete retaining in front of 107 Camino Matias. January 18, 2018.

Figure 4: Stucco-on-block property wall between 114 and 118 Camino Santiago, January 18, 2018.

IMPROVEMENT SUMMARY CHART
LAS PLACITAS RESIDENTIAL COMPOUND
PLAZA DEL MONTE

I.D.	Street Address	Type of Dwelling	Area (Sq.Ft.)	Room Count (Total-Bedrooms-Baths)	Age (Yrs.)	Comments
R-1	104 Camino Matias	Single-Family	944	4-2-1.5	26	
R-2	102 Camino Matias	Single-Family	944	4-2-1.5	26	
R-3	106 Camino Matias	Single-Family	944	4-2-1.5	26	
R-4	118 Camino Santiago	Single-Family	1,141	5-2-2	16	
R-5a	110 Camino Matias	Duplex	897	5-2-1	26	
R-5b	112 Camino Matias	Duplex	839	4-1-1	26	Addition 1968
R-6	111 Camino Matias	Single-Family	1,433	6-3-2	Unknown	Remodeled/Renovated 1962
R-7a	116 Camino Matias	Duplex	1,072	4-2-2	Unknown	Renovated 1967, Remodeled 1986
R-7b	120 Camino Matias	Duplex	1,099	4-2-2	Unknown	Renovated 1962, Remodeled 1986
R-8	109 Camino Matias	Single-Family	1,095	5-2-1	Unknown	Remodeled/Renovated 1962
R-9	107 Camino Matias	Single-Family	932	4-2-1	Unknown	Remodeled/Renovated 1962
R-10	105 Camino Matias	Single-Family	932	5-2-1	Unknown	Remodeled/Renovated 1962
R-11	101 Camino Santiago	Single-Family	1,163	4-2-1	20	
R-12	103 Camino Santiago	Single-Family	1,064	5-2-2	20	
R-14a	105a Camino Santiago	Fourplex	926	4-2-1	26	
R-14b	105b Camino Santiago	Fourplex	699	3-2-1	26	
R-14c	105c Camino Santiago	Fourplex	699	3-2-1	26	
R-14d	105d Camino Santiago	Fourplex	926	4-2-1	26	
R-15	109 Camino Santiago	Single-Family	1,029	4-2-2	25	
R-16	111 Camino Santiago	Single-Family	1,082	4-2-2	25	
R-17a	115a Camino Santiago	Duplex	1,052	4-2-2	18	
R-17b	115b Camino Santiago	Duplex	1,179	4-2-2	18	
R-18	117 Camino Santiago	Single-Family	1,356	6-2-2	Unknown	Estimated effective age 20-25 yrs.
R-19	119 Camino Santiago	Single-Family	1,105	5-2-1	25	
R-20	121 Camino Santiago	Single-Family	1,152	5-2-2	18	
R-21a	125a Camino Santiago	Fourplex	944	4-2-1	19	
R-21b	125b Camino Santiago	Fourplex	676	3-2-1	19	
R-21c	125c Camino Santiago	Fourplex	676	3-2-1	19	
R-21d	125d Camino Santiago	Fourplex	944	4-2-1	19	
R-22	122 Camino Santiago	Single-Family	1,218	5-2-2	Unknown	Estimated effective age 20-25 yrs.
R-23	124 Camino Santiago	Single-Family	1,153	4-2-2	21	
R-24a	126a Camino Santiago	Fourplex	690	3-1-1	21	
R-24b	126b Camino Santiago	Fourplex	690	3-1-1	21	
R-24c	126c Camino Santiago	Fourplex	690	3-1-1	21	
R-24d	126d Camino Santiago	Fourplex	690	3-1-1	21	
R-25	120 Camino Santiago	Single-Family	1,259	5-2-2	18	
R-26	114 Camino Santiago	Single-Family	1,318	4-2-2	17	

Figure 5: iPhone image of c.1988 Plaza del Monte appraiser report referenced at April 24, 2018 hearing.



Aerial 1: Portion of May 2, 1966 aerial photograph. Source: NMDOT – 05-02-66_0015.

Aerial 2: Portion of February 28, 1968 aerial photograph. Source: NMDOT – 02_28_68_0021.

Aerial 3: Portion of February 27, 1969 aerial photograph. Source: NMDOT – 1969_2_27_4071.

Aerial 4: Portion of May 11, 1973 aerial photograph showing 118 Camino Santiago under construction. Source: NMDOT- 05-11-73_0053.

Appendix A: Complete Email Communications between John Murphey and Alane Wainwright, January 16 to May 4, 2018.

(see attached)

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte	101 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory
		4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693490, -105.934887

10. Photo Information Negative: John Murphey View of: Front, south elevation, facing north.

11. Brief Description of the Property:

Situated near the east entrance to Plaza del Monte, the house is a roughly 1,332-square-foot contemporary residence constructed in 1967-68. In plan, the three-bedroom dwelling has a square form with an attached L-shaped portal and garage, giving it a combined square footprint. It presents to the street a long portal with the roof carrying over the garage. It is fenestrated with aluminum windows, primarily of a sliding operation. A paneled wood door gives entry to the residence at the east end of portal. The garage entry is fitted with a recent vinyl overhead door. Cementitious brocade stucco in a peach tone covers the frame building. The roof consists of a mixture of gravel and asphalt material. An interior parapet outlines the dwelling portion of the mass. While contemporary in form, the vigas across the portal give the residence a regional feel.

12. Who uses the property? Residence

13. Construction Date: c.1968
_x_Known _x_ Source: aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

J. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Sam M. Dean, who is listed as a tenant in the 1970 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing _x_ Non-contributing __ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte	101 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Casement	Aluminum	Single	11
Sliding	Aluminum	1-1	2

*Because of storm covers, the operation and material information is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel	Wood	1
Single-Leaf	½-Light	Wood	1
Garage	Sectional	Vinyl	1

12. Chimneys
N/A

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: Unknown; replaced garage door; and material and visual evidence.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	__ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other: Contemporary with Spanish-Pueblo Revival ornamentation

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:	***Please complete HCPI FORM 1 before completing FORM 2***	
HCPI No._____ District No._____	___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **101 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Representing a Contemporary design, the house does not harmonize or contribute to the historical character of the district. For this reason, the recommendation is to maintain 101 Camino Santiago a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **101 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building not present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte	2. Location: 101 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018



Figure 2: February 27, 1969 aerial photograph
Building present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **101 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street elevation and north elevations, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte**	**2. Location:** **101 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Photo 2: Street and west elevations, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte	2. Location: 101 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Photo 3: North elevation, facing south and southwest
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 2	102 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693288, -105.935161

10. Photo Information Negative: John Murphey View of: Front, west elevation, facing northeast.

11. Brief Description of the Property:

One of the earliest units to be constructed at Plaza del Monte, 102 Camino Santiago is a 2,064-square-foot dwelling with one addition. The two-bedroom, flat-roof house faces Camino Matias. It shows to the street a façade-long portal, continuing at the south end as a single-space carport. The portal is supported by shiplap wood girders resting on round posts with double-ended corbels. Most of the portal façade is painted white. A line of vigas runs along the top of the wall. The elevation is penetrated by two doors and large windows, with the southernmost window not meeting the ordinance in regard to its distance from the corner. The north elevation facing Camino Santiago displays a variety of window openings holding tall metal casements. A shallow overhang supported by short vigas carries over most of the elevation. At the northeast corner is a roomblock-like projection holding the bedroom wing. The rear (east) elevation presents a number of alterations. The largest is a post-1969 addition, over what was a patio. The 380-square-foot addition is fenestrated with modern windows and is sheltered by a parapet-type portal. The house was constructed in c.1965; its designer/architect is unknown but assumed to be Kenneth S. Clark and Philippe Register.

12. Who uses the property? Residence

13. Construction Date: c.1965
_x_Known _x_ Source: aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North Box Indicates Post-1968 Addition

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

J. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Gaylord Knox, who is listed as a tenant in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing _x_ Non-contributing __ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Contributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte Residence 2	102 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Casement	Aluminum	Single	9
Fixed	Aluminum	Single	3
Fixed	Aluminum	Single, flanked by Casement	1
Fixed	Aluminum	12	4

*Because of storm covers, the operation and material information is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel	Wood	2
Single-Leaf	Full-Light	Aluminum	1
Double	Carport Storage Doors	Wood	2

12. Chimneys
One, stucco-clad inside parapet

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: Post-1969; addition to rear, northeast corner; aerial photographs and material and visual evidence.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes: Other:

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** NRHP SRCP Criteria A B C D	
1. Name of property: **Plaza del Monte Residence 2**	**2. Location:** **102 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Constructed before 1968, and representing the original Clark and Register design template for the Plaza del Monte retirement homes, the house is a good example of the "Santa Fe style." For this reason, the recommendation is to designate 102 Camino Santiago a Contributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 2	2. Location: 102 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building present; pre-addition.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 2	2. Location: 102 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018



Figure 2: February 27, 1969 aerial photograph
Building present, pre-addition.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte Residence 2**	**2. Location:** **102 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street elevation and south elevations, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte Residence 2**	**2. Location:** **102 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: North and street elevations, facing southeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 2	**2. Location:** 102 Camino Santiago *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: East elevation, facing northwest.
Non-historic addition on left.

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 6	103 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693597, -105.935145

10. Photo Information Negative: John Murphey View of: Front, south elevation, facing northwest.

11. Brief Description of the Property:

Roughly 1,533 square-feet, the one-story residence is designed as an L-plan form. The plan puts the bedrooms in a cube-like mass, with the remainder of the functions of the house strung along a linear spine. Its façade is defined by a long portal sheltering its entry and patio doors. The east end of the composition terminates as a one-bay carport. A line of vigas runs along the back (north) elevation supporting a short overhang. An exterior chimney breaks through the overhang, rising several feet above the roof. The house is fenestrated with an array of original and replacement aluminum windows. It is entered under the portal through a stylized wood panel door flanked by one set of sidelights. The dwelling's flat roof is outlined by a short parapet; the roof is covered with gravel. The frame structure is finished with cementitious brocade stucco in the buckskin tone. While contemporary in form, vigas used across the portal and the roomblock bedroom wing give the residence a Spanish-Pueblo Revival feel. The house was constructed in c.1965; its architect/designer is unknown but assumed to be architect Philippe Register.

12. Who uses the property? Residence

13. Construction Date: c.1965
_x_Known _x_ Source: aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

). Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Joseph McNeill, who is listed as a tenant in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing _x_ Non-contributing __ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Contributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte Residence 6	103 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Sliding	Aluminum	1-1	9
Fixed	Aluminum	Single	2

*Because of storm covers, the operation and material information is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel	Wood	1
Single-Leaf	Raised Square Panel, w/single sidelight	Wood	1

12. Chimneys
One, stucco-clad, exposed on north elevation

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: Unknown; replaced windows; visual and material evidence

HCPI Detail Form (FORM 2) *(Continued from other side)*

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes: Other:

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:	***Please complete HCPI FORM 1 before completing FORM 2***	
HCPI No._____ District No._____	___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 6**	**2. Location:** **103 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Constructed before 1968, and representing the original Clark and Register design template for the Plaza del Monte retirement homes, the house is a good example of the "Santa Fe style." For this reason, the recommendation is to designate 103 Camino Santiago a Contributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 6	2. Location: 103 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 6**	**2. Location:** **103 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street and east elevations, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte** **Residence 6**	**2. Location:** **103 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: Street and west elevations (top), facing northeast; west elevation, facing south (Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 6	**2. Location:** 103 Camino Santiago *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: North elevation, facing southwest
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 14	105 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693730, -105.935558

10. Photo Information Negative: John Murphey View of: Front, south elevation, facing northeast.

11. Brief Description of the Property:

Forming a long, linear composition, 105 Camino Santiago is one of three apartment buildings erected at Plaza del Monte. The carport-dominated structure works its way down the slope as two L-plan units joined together at the center by a laundry room. The structure is bookended by masses holding the apartments. The larger apartments containing two bedrooms are situated in the projecting roomblocks. The apartments share a party wall at the living room. Spanning between the apartments are the carports and the laundry room. The carports are detailed with a viga-roof structure which continues as a portal along the inner apartments. The rear (north) elevation is divided into small patios. The apartments are entered through wood panel doors; solid wood doors give access to the storage units and the laundry. The original multi-light steel casement windows have been replaced with aluminum units. A short parapet follows the outline of the apartments, and is penetrated on the south, east and west elevations with cut-through metal canales. The frame structure is finished with cementitious brocade stucco in a peach tone. While contemporary in form, the vigas used across the portales and carports and the cubed apartment masses give the residence a regional feel. The roughly 4,198-square-foot apartment building was constructed in 1971, after a design by architect Philippe Register.

12. Who uses the property? Residence

13. Construction Date: 1971
_x_Known _x_ Source: aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

20. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The apartments were constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first residents identified are Ruth Erwin and Ellen Foster. They are listed as tenants in the 1972 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 14	105 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _x_ Asphalt
__ Earth __ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Sliding	Aluminum	1-1	10
Sliding	Aluminum	1-1F-1	4

*Because of storm covers, the operation and material information is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ View Light	Wood	4
Single-Leaf	Flush [?]	Wood	12
Sliding	Patio	Aluminum	8

12. Chimneys
4, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: __ _x_ No known modifications

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	__ Spanish-Pueblo Revival
Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other: Contemporary with Spanish-Pueblo Revival ornamentation

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 14**	**2. Location:** **105 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Evaluation of Historical Status

Representing a Contemporary design, the building does not harmonize or contribute to the historical character of the district. In addition, constructed in 1971, it does not meet the minimum age threshold for consideration. For this reason, the recommendation is to designate 105 Camino Santiago a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2*		
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 14	**2. Location:** 105 Camino Santiago *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building not present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2*		
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 14	2. Location: 105 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Figure 2: February 27, 1969 aerial photograph
Building not present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 14	**2. Location:** 105 Camino Santiago *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street elevation and east elevations, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 14	**2. Location:** 105 Camino Santiago *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: Street and west elevations, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 14	2. Location: 105 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Photo 3: East Unit (top), facing northeast;
West Unit (bottom), facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 14	2. Location: 105 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Photo 4: North elevation, facing west (top) and east (bottom)
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 3	106 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693427, -105.935448

10. Photo Information Negative: John Murphey View of: Front, north elevation, facing south.

11. Brief Description of the Property:

Likely the third unit to be constructed at Plaza del Monte, 106 Camino Santiago is a 2,301-square-foot dwelling with a portal across two elevations. In plan, it has an L-shaped foundation with an attached carport. The flat-roof dwelling holds three bedrooms confined to a wing at the west end. The rear (south) elevation is focused on a small patio cut into the southwest corner of the house. The southeast corner is terminated by a one-space carport. The two-sided portal runs along the north and east elevations. The structure is made of vigas which sit on square girders held up by round posts with zappos-type corbels. The portal elevations are painted white and fenestrated with doors on each exposure. Small rectangular windows penetrate the bedroom wing. The remaining windows vary, including large picture and grouped casements and sliding units. The roof is finished with rolled asphalt which carries over the inner parapets. A squat stucco-faced chimney rises at the northeast corner. The house is finished with textured cementitious stucco in a light buckskin tone. It was erected in c.1965. Its designer is unknown but is suspected to be an early Clark and Register design.

12. Who uses the property? Residence

13. Construction Date: c.1965
_x_Known _x_ Source: aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

). Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is De Forest N. Shotwell, who is listed as a tenant in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Contributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria _A _B _C _D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte Residence 3	106 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _x_ Asphalt
__ Earth __ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Sliding	Aluminum	1-1	6
Fixed	Wood [?]	Single	1

*Because of storm covers, the operation and material is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ View Light	Wood	4
Sliding	Patio	Aluminum	1

12. Chimneys
One, stucco-clad, west exposure

13. Porches __ N/A
Type: _x_ Entry- portal- 2 __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: __ _x_ No known modifications

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes: Other:

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No.	*Please complete HCPI FORM 1 before completing FORM 2* District No.	NRHP SRCP Criteria A B C D
1. Name of property: Plaza del Monte Residence 3	2. Location: 106 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Constructed before 1968, and representing the original Clark and Register design template for the Plaza del Monte retirement homes, the house is a good example of the "Santa Fe style." For this reason, the recommendation is to designate 106 Camino Santiago a Contributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 3	2. Location: 106 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 3	2. Location: 106 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: South and east elevations, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 3	**2. Location:** 106 Camino Santiago *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: South and east elevations, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 3	2. Location: 106 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Photo 3: Street and west elevations, facing southeast.

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 15	109 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
_ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693826, -105.935966

10. Photo Information Negative: John Murphey View of: Front, south elevation, facing north.

11. Brief Description of the Property:

Composed of a series of angled walls, the carport dominated residence was constructed in 1966, after a design by architect Philippe Register. The house presents to the street a tall and wide carport framed with a viga roof. The west end of the carport is sheltered by double splayed wall. The angled wall composition is echoed across the east elevation. In plan, the residence is roughly an "L" with its form obscured by the carport. The approximately 1,220-square-foot dwelling holds two bedrooms in a cube-like mass anchoring the east end. Between the bedroom mass and carport is a small enclosed patio and portal sheltering the main entry and a pair of oversized wood windows. The rear (north) elevation has a small viga canopy protecting a patio door. A tapered chimney breaks the wall plane on this elevation. Fenestration consists of mainly aluminum windows. The frame structure is finished with cementitious brocade stucco in the buckskin tone. The Contemporary-style house was constructed in c.1965.

12. Who uses the property? Residence

13. Construction Date: c.1965
_x_Known _x_ Source: aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

omments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

J. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Jane Barber, who is listed as a tenant in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte Residence 15	109 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Sliding	Aluminum	1-1	6
Fixed	Wood	2	1

*Because of storm covers, the operation and material information is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel	Wood	4
Single-Leaf	Flush	Wood	1
Sliding	Patio	Aluminum	1

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: __ _x_ No known modifications

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	__ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other: Contemporary with Spanish-Pueblo Revival ornamentation

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 15**	**2. Location:** **109 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Evaluation of Historical Status

Representing a Contemporary design, the house does not harmonize or contribute to the historical character of the district. For this reason, the recommendation is to designate 109 Camino Santiago a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 15	2. Location: 109 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 15	2. Location: 109 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street and east elevations, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 15	2. Location: 109 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Photo 2: Street and west elevations (top), facing northeast. West elevation (bottom), facing southeast
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2*		
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte** **Residence 15**	**2. Location:** **109 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Photo 3: North elevation, facing southeast (top), west (bottom)
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 5	110 (112) Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693575, -105.936130

10. Photo Information Negative: John Murphey View of: Front, north elevation, facing south.

11. Brief Description of the Property:

Located at the west end of the common area are two residential units which were joined together at some point after 1970. The older unit, addressed 110 Camino Santiago, takes up the east end of the footprint. Constructed in c.1962, after a design by architect Kenneth S. Clark, it is roughly an L-shaped box with a rear portal and connected carport. The street-facing façade is defined by a small recessed entry. The entry holds a single door placed across the west wall. The remainder of the façade is divided into rectangular window openings holding sliding units. Smaller, rectangular sliding windows are applied across the east bedroom wing. A shallow portal runs across the rear (south) elevation historically leading to a single-space carport. The portal elevation is fenestrated with a patio door, sliding windows, and a louvered door leading to a utility room. The house is outlined with parapets and finished in buckskin cementitious stucco. It holds three bedrooms. ***Continued on Page 5***

12. Who uses the property? Residence

13. Construction Date: c.1962, with c.1968 addition and carport expansion
_x_Known _x_ Source: aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

20. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the original house (110) is Dorothy B. Fritz, who is listed as a tenant in the 1966 Santa Fe city directory. The first resident identified with the addition (112) is Theo R. Finley, listed in the 1970 Santa Fe city directory as a tenant. Currently the Santa Fe County Assessor treats the combined buildings as one residence addressed as 110 Camino Santiago.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa: Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte Residence 5	110 (112) Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Sliding	Aluminum	1-1	11
Sliding	Aluminum	Single	1
Casement	Aluminum	1-1F-1	2

*Because of storm covers, the operation and material information is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ View Light	Wood	2
Single-Leaf	Flush	Wood	1
Double	Panel	Wood	1
Double	Louver	Wood	1
Sliding	Patio	Aluminum	2

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry- portal- 2 __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: c.1968; addition across west elevation and widening of carport; aerial photographs, drawings, material and visual evidence.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other:

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 5	2. Location: 110 (112) Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Continuation of Architectural Description:

Attached to the west end of the original Clark design is a post-1966 addition. Arranged at a lower height, the approximately 864-square-foot appendage is a rectangular box with overhanging eaves and a porch. The addition, mostly likely designed by architect Philippe Register, introduces a contemporary vocabulary. A shallow overhang supported by squared rafters carries across the north and south elevations. Similar beams extend out from the west elevation to create the porch. A tall angular wall rising above the roofline defines its south edge. The addition is fenestrated with a few doors and square window openings holding single-light metal casements. The frame structure is finished with cementitious brocade stucco in the buckskin pigment. Most likely occurring with the addition, the carport was widened (or constructed anew) to hold two vehicles. Set back from the addition, the roughly 1,054-square-foot structure is supported by a viga-and-post system.

Evaluation of Historical Status

The original house received a contemporary addition across its secondary street façade and a demolition and widening of its carport in c. 1968. The combined alterations changed the overall massing and the appearance of the west elevation of the original structure. For this reason, the recommendation is to designate 110 (112) Camino Santiago a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* NRHP SRCP Criteria A B C D	
1. Name of property: Plaza del Monte Residence 5	2. Location: 110 (112) Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph. Only east portion of building present. Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 5**	**2. Location:** **110 (112) Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**



Figure 2: February 27, 1969 aerial photograph
West addition and portal expansion present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte** **Residence 5**	**2. Location:** **110 (112) Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street and north elevations, facing southeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 5**	**2. Location:** **110 (112) Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: Street and west elevations of addition, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte** **Residence 5**	**2. Location:** **110 (112) Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: South and west elevations of addition and expanded carport, facing east.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte** **Residence 5**	**2. Location:** **110 (112) Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 4: South elevation, facing north.

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte	111 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory
		4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693910, -105.936232

10. Photo Information Negative: John Murphey View of: Front, south elevation, facing north.

11. Brief Description of the Property:

Arranged at an east-west orientation, the house is a one-story, approximately 1,616-square-foot, flat-roof dwelling erected in c.1965. The dwelling has an L-shaped plan with its two bedrooms confined to a rectangular wing at the west end. The remaining house holds the living room, kitchen and dining area. The front (south) façade is marked by a long portal which continues across to an attached one-bay carport. The portal shelters the front entry and a sliding patio door. The structure is supported round poles holding a viga roof. The house is fenestrated with common windows, most of them appearing to be replacement units. It is entered through a raised wood panel door flanked on one side by a sidelight. The rear (north) elevation contains a few windows and a door sheltered by a shallow viga-supported visor. A tapered chimney breaks through the visor, terminating with a terra cotta cap. The frame building is finished in smooth cementitious stucco in the buckskin tone. The flat roof is covered with asphalt, which carries over the east exposure of the bedroom wing. While contemporary in form, the vigas used across the portal give the residence a Spanish-Pueblo Revival feel. The placement and restrained size of the carport helps maintain the regional tradition. The building was constructed after a design by architect Philippe Register.

12. Who uses the property? Residence

13. Construction Date: c.1965
_x_Known _x_ **Source:** aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

20. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Neva B. Palameter, who is listed as a tenant in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa: Downtown and Eastside Historic District

Recommended Contributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte	111 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe	__ Brick	__ Composition	__ Concrete: Block
__ Concrete: Cast Stone	__ Concrete: Poured	__ Earth Plaster	__ Masonry: Simulated
__ Metal: Corrugated	__ Metal: Structural Siding	__ Metal: V-Crimp	__ Stone: Random Ashlar
Stone: __ Random Coursed	__ Stone: River Rock	__Stone: Rusticated	__ Stone: Tabular
_x_Stucco:	__ Tile: Clay	__ Vinyl Siding	__ Wood: Board and Batten
Wood: __ Horizontal Siding	__ Wood: Jacal	__ Wood: Log	__ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Sliding	Aluminum	1-1	3
Double-Hung	Wood	3	2
Double-Hung	Wood	1/1	1

*Because of storm covers, the operation and material is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ single sidelight	Wood	1
Single-Leaf	Raised Square Panel	Wood	1
Single-Leaf	½-Light	Wood	1
Sliding	Patio	Aluminum	2

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry- portal- __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: Date unknown; replaced windows; drawings and visual and material evidence.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other:

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:	***Please complete HCPI FORM 1 before completing FORM 2***	
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte**	**2. Location:** **111 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Constructed before 1968, and representing the original Clark and Register design template for the Plaza del Monte retirement homes, the house is a good example of the "Santa Fe style." For this reason, the recommendation is to designate 111 Camino Santiago a Contributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2*		
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte**	**2. Location:** **111 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte**	**2. Location:** **111 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street and east elevations, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **111 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: Street and west elevations, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **111 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: North elevation, facing southwest
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte	113 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory
		4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693980, -105.936500

10. Photo Information Negative: John Murphey View of: Front, south elevation, facing north.

11. Brief Description of the Property:

Sitting on a slight rise, the house shares a party wall at the carport with its neighbor at 115 Camino Santiago. The roughly 1,281-square-foot dwelling contains two bedrooms. These are arranged at the front of the structure in a small L-shaped volume. The remainder of the footprint holds the living functions of the house. It presents to the street two roomblock-like volumes penetrated by horizontally oriented aluminum casement windows. A viga-framed carport and short portal terminate the west end of the footprint. The house is entered through a raised wood panel door with a center view light. The rear (north) elevation has a few windows and sliding glass door. A shallow overhang supported by square wood beams carries across the elevation. The frame dwelling is finished cementitious peach color stucco worked into a brocade pattern. Tall parapets outline the perimeter of the bedroom wing. The roof is covered with asphalt which carries over the west exposure of the bedroom mass. It was erected in c.1970; its designer/architect is unknown.

12. Who uses the property? Residence

13. Construction Date: c.1970
_x_Known _x_ Source: aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

20. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Harry Wood, who is listed as a tenant in the 1971 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa: Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte	113 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Casement	Aluminum	1-1F-1	7
Casement	Aluminum	Single	1

*Because of storm covers, the operation and material information is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ View Light	Wood	4
Sliding	Patio	Aluminum	1

12. Chimneys
One, stucco-clad, east exposure

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other:

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** NRHP SRCP Criteria A B C D	
1. Name of property: **Plaza del Monte**	**2. Location:** **113 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Evaluation of Historical Status

Constructed in c.1970, it does not meet the minimum age threshold for consideration. For this reason, the recommendation is to designate 113 Camino Santiago a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **113 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building not present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte	2. Location: 113 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street and east elevations, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **113 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: North elevation, facing southeast and southwest
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 26	114 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
5.693668, -105.936489

10. Photo Information Negative: John Murphey View of: Front, north elevation, facing southeast.

11. Brief Description of the Property:

The house presents to Camino Santiago a traditional design of a cube-like mass projecting from a linear arm. In plan, it is roughly L-shaped with a large connecting carport attached to its southeast corner. The west end holds two bedrooms; the remainder of the footprint contains a large living room, kitchen and utility closet. The south exposure of the bedroom wing is penetrated by sliding glass doors. East of the bedroom wing, the front façade is divided into a recessed entry and a large casement-framed picture window. The entry holds a raised square panel wood door with a center view light. It is sheltered by a short overhang resting on vigas. A similar combined picture and casement window is found on the east elevation of the living room. The carport makes up most of the secondary street elevation. It is supported by a wood viga-and-post system. The structure shelters a patio door and single raised panel wood doors leading to the utility room and storage area. Wood, trough-like canales penetrate the parapets on the east and west elevations. The roof is covered with rolled asphalt, which carries over the bedroom wing's east exposure. A short stucco-clad chimney topped with a terra cotta cap rises from the center of the roof. Erected in c.1972, the residence was designed by Register, Ross & Burnet Architects.

12. Who uses the property? Residence

13. Construction Date: c.1972
_x_Known _x_ Source: drawings, aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

). Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The 1972 Santa Fe directory indicates the house was under construction at that time.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte Residence 26	114 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe	__ Brick	__ Composition	__ Concrete: Block
__ Concrete: Cast Stone	__ Concrete: Poured	__ Earth Plaster	__ Masonry: Simulated
__ Metal: Corrugated	__ Metal: Structural Siding	__ Metal: V-Crimp	__ Stone: Random Ashlar
Stone: __ Random Coursed	__ Stone: River Rock	__Stone: Rusticated	__ Stone: Tabular
_x_Stucco:	__ Tile: Clay	__ Vinyl Siding	__ Wood: Board and Batten
Wood: __ Horizontal Siding	__ Wood: Jacal	__ Wood: Log	__ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Casement	Aluminum	1-1	3
Casement	Aluminum	1-1F-1	4

*Because of storm covers, the operation and material information is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ View Light	Wood	2
Single-Leaf	Raised Square Panel	Wood	2
Sliding	Patio	Aluminum	2

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: Unknown; replaced windows and doors; drawings and material and visual evidence.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other:

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 26	2. Location: 114 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Constructed in c.1972, it does not meet the minimum age threshold for consideration. For this reason, the recommendation is to designate 114 Camino Santiago a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 26	2. Location: 114 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building not present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 26**	**2. Location:** **114 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: East and south elevations, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte** **Residence 26**	**2. Location:** **114 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: West elevation, facing southeast.

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte	115 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.694030, -105.936677

10. Photo Information Negative: John Murphey View of: Front, south elevation, facing northwest.

11. Brief Description of the Property:

Sharing a wall with the dwelling to the east (113 Camino Santiago), the small house contains two bedrooms. The dwelling portion of the building is composed of a rectangular bedroom wing. Attached to this are the living room, kitchen and a one-space carport. Connecting these elements is a beam portal. Together, both areas hold about 1,290 square feet. The front façade presents a simple canvas of a projecting mass balanced on one end with the void of the carport at the other. In between is the portal with its few window and door openings. The portal is supported by double round posts topped with zappos-type corbels. The rear (north) elevation contains a few windows and a sliding glass door sheltered by a shallow viga-supported overhang. The house is fenestrated with common doors and windows. The windows are tall, single-light aluminum casements. A raised-panel-and-view-light door gives entry to the dwelling under the portal. Short parapets outline the perimeter of the bedroom wing. The roof's asphalt material carries over the east exposure of the parapet. The house was erected in c.1970; its designer/architect is unknown.

12. Who uses the property? Residence

13. Construction Date: c.1970
_x_Known _x_ Source: aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

). Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Westley L. Almy, who is listed as a tenant in the 1971 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
CPI No._____ District No._____ __NRHP __SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte	115 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Casement	Aluminum	1	1
Casement	Aluminum	1-1	1
Casement	Aluminum	1-1F-1	2
]Casement	Aluminum	1-2F-1	1

*Because of storm covers, the operation and material information is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ View Light	Wood	2
Sliding	Patio	Aluminum	2
Double	Carport	Wood	1

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: __ _x_ No known modifications

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other:

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte	2. Location: 115 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Constructed in c.1970, it does not meet the minimum age threshold for consideration. For this reason, the recommendation is to designate 115 Camino Santiago a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte	**2. Location:** 115 Camino Santiago *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building not present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte**	**2. Location:** **115 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street and east elevations, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **115 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: Street and west elevations, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **115 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: North elevation, facing southwest
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte	117 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory
		4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.694087, -105.936953

10. Photo Information Negative: John Murphey View of: Front, east elevation, facing northwest.

11. Brief Description of the Property:

Tucked into the northwest corner of the development, the house is a single-story, flat-roof dwelling characterized by its viga carport and continuous overhang. In form, its two box-like volumes are arranged in a modified L-plan. The house holds two bedrooms slung along the west wall. A large living room occupies the foot of the "L." With its carport included, the house contains approximately 1,422 square feet. The unarticulated flat front façade is penetrated by non-historic casement windows. A wood panel and view light door gives entry to the dwelling under the front portal. The rear (west) elevation is fenestrated with an asymmetrical pattern of tall aluminum casement windows. The frame building is finished with brocade-type stucco rendered in the buckskin color. It was constructed in 1966-67, after a design by architect Philippe Register. Window replacements appear to have removed the pedimented heads shown on Register's drawings.

12. Who uses the property? Residence

13. Construction Date: 1966-67
_x_Known _x_ Source: drawings, aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

). Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Reverend H. Thomas, who is listed as a tenant in the 1967 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte	117 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Casement	Aluminum	1	2
Casement	Aluminum	1-1	3
Casement	Aluminum	1-1F-1	1
]Casement	Aluminum	1-2F-1	3

*Because of storm covers, the operation and material information is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ View Light	Wood	2
Single-Leaf	Raised Panel	Metal	1
Sliding	Patio	Aluminum	2
Double	Carport	Wood	1

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ **Entry- portal** __**Partial-Width** __ **Full-Width** __ **Wrap**

14. Other Significant Features N/A

15. Modifications: x __ **No known modifications**

#1 Date: Unknown; replaced windows and doors; drawings and material and visual evidence.

HCPI Detail Form (FORM 2) *(Continued from other side)*

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	__ Spanish-Pueblo Revival
Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other: Contemporary with Spanish-Pueblo Revival ornamentation

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:	***Please complete HCPI FORM 1 before completing FORM 2***	
CPI No. _____ District No. _____	___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **117 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Representing a Contemporary design, the house does not harmonize or contribute to the historical character of the district. For this reason, the recommendation is to maintain 117 Camino Santiago as a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte**	**2. Location:** **117 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building not present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte	2. Location: 117 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street, west and south elevations, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte**	**2. Location:** **117 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: West elevation, facing southwest
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **117 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: North elevation, facing south
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte	118 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693715, -105.936696

10. Photo Information Negative: John Murphey View of: Front, north elevation, facing southwest.

11. Brief Description of the Property:

Erected in c.1973, the stucco-over-frame, two-bedroom house sits on a rise at the southwest corner of Camino Santiago and Camino Matias. In plan, it is a modified L-shaped structure with a carport attached to its front façade. The roughly 1,245-square-foot dwelling has its bedrooms segregated to a wing across the west elevation. This volume is taller than the rest of the house and is outlined with parapets. The lower volume contains a living room, kitchen and dining area. The north (front) façade is divided between the carport and the north face of the bedroom wing. The single space carport is erected over a wood structure supported by round posts. The outside beam continues across the façade, sheltering the front entry. As with the door under the carport, the entry holds a raised square panel unit. The secondary elevations are fenestrated with single-light metal casement windows. The south (rear) elevation has an array of casement windows and an enclosure giving access to the carport. A shallow overhang resting on vigas outlines the elevation. The house is finished with cementitious brocade stucco in a peach pigment. The roof is covered with rolled asphalt, which carries over a portion of the bedroom wing's east exposure. Large, trough-like wood canales pierce the west parapet. It was designed by Register, Ross & Burnet Architects, and is one of the last houses to be completed in the development.

12. Who uses the property? Residence

13. Construction Date: c.1973
_x_Known _x_ Source: drawings, aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

). Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Duncan Spinning, who is listed as a tenant in the 1974 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa: Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
CPI No._____ District No._____ __NRHP __SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte	118 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__21/2 Other:

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Casement	Steel	2-2F-2	1
Casement	Steel	3-3	2
Casement	Steel	3-3F-3	2
Casement	Steel	3-3F-3F-3	2

*Because of storm covers, the operation and material is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ View Light	Wood	1
Single-Leaf	Raised Square Panel	Wood	1
Double	Carport	Wood	1

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: __ _x_ No known modifications

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other:

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **118 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Evaluation of Historical Status

Constructed in c.1973, it does not meet the minimum age threshold for consideration. For this reason, the recommendation is to designate 118 Camino Santiago a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2*		
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte**	**2. Location:** **118 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building not present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte**	**2. Location:** **118 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street and east elevations, facing southwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte**	**2. Location:** **118 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: West elevation, facing east.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **118 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: West and south elevations, facing northeast.

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte	119 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693915, -105.937077

10. Photo Information Negative: John Murphey View of: Front, east elevation, facing west.

11. Brief Description of the Property:

Arranged slightly above grade, the box-like house is characterized by its continuous portal and horizontal emphasis. In plan it is a compact rectangle framed by angled walls on its north and south exposures. Large windows, a wood panel door and a three-panel sliding glass door appear on the front façade. The rear (west) elevation has double sets of sliding windows and a patio door arranged under an overhang. The house's windows appear to be mostly replacement units. The south end of the dwelling is weighted with a large carport. A tall double splayed wall creates the south exposure. The portal is supported by vigas resting on a square beam. Round posts topped with double-ended corbels carry the weight to the floor. The roughly 1,485-square-foot structure contains two bedrooms placed along the west wall. The building was constructed in c.1965, after a design by architect Philippe Register. The main alteration is the removal of most of the angled wall along the northeast corner. Originally this feature enclosed a small patio.

12. Who uses the property? Residence

13. Construction Date: c.1965
_x_Known _x_ Source: drawings, aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

). Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Muriel M. Boone, who is listed as a tenant in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte	119 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Sliding	Aluminum	1-1	6
Fixed	Wood	Single	2

*Because of storm covers, the operation and material information is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel	Wood	4
Sliding	Patio	Aluminum	2

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry- portal- __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: Unknown; partial removal and alteration of northeast angled patio enclosure; drawings and material and visual evidence.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	__ Spanish-Pueblo Revival
Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other: Contemporary with Spanish-Pueblo Revival ornamentation

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:	***Please complete HCPI FORM 1 before completing FORM 2***	
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte**	**2. Location:** **119 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Representing a Contemporary design, the house does not harmonize or contribute to the historical character of the district. For this reason, the recommendation is to maintain 119 Camino Santiago as a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte	2. Location: 119 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte	2. Location: 119 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street and south elevations, facing northwest.
Box indicates removed portion of angled patio wall.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **119 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: West elevation, facing south
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **119 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: North elevation, facing southwest
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 25	120 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory
		4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693597, -105.936785

10. Photo Information Negative: John Murphey View of: Front, west elevation, facing southeast.

11. Brief Description of the Property:

The small two bedroom house presents a contemporary carport-dominant design. Located along the south side of Camino Santiago, it sits back from the street. In plan, it is a modified "T" form with an attached carport projecting from the front façade. Its two bedrooms are confined to a wing making up the north elevation. Higher than the rest of the house, it is outlined with shaped parapets. The parapets are pierced with canales across the north and south exposures. The lower volume, historically containing a living room, kitchen and music room, is faced with a shallow overhang resting on vigas. The overhang shelters sliding glass doors, a window and a pedestrian entry. The secondary elevations are fenestrated with aluminum casement windows. ***Continued on Page 5***

12. Who uses the property? Residence

13. Construction Date: c.1971
_x_Known _x_ Source: drawings, aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

J. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Ovid Sellers, who is listed as a tenant in the 1972 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte Residence 25	120 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Casement	Aluminum	2-2F-2	1
Casement	Aluminum	3-3F-3	4
Fixed	Aluminum	21	1

*Because of storm covers, the operation and material is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ View Light	Wood	1
Single-Leaf	Raised Panel	Metal	1
Double	French	Aluminum	1
Double	Carport	Wood	3

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: Unknown; replaced windows and doors; drawings and material and visual evidence.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes: Other:

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:	***Please complete HCPI FORM 1 before completing FORM 2***	
HCPI No. _____ District No. _____	___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 25**	**2. Location:** **120 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Continuation of Architectural Description:

The front (west) elevation is dominated by the carport. The structure is erected over a viga-and-post support system. The portal's outside beam continues across the façade, sheltering the front entry. A wood raised square panel door with a center view light gives entry to the residence. The frame building is faced with cementitious stucco with brocade finish in a peach-like pigment. Including its carport and utility room, the building contains 1,804 square-feet. The house was erected in c.1971, after a design by Register, Ross & Burnet Architects.

Evaluation of Historical Status

Constructed in c.1971, it does not meet the minimum age threshold for consideration. For this reason, the recommendation is to designate 120 Camino Santiago a Noncontributing Structure to the Downtown and Eastside Historic District.

Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2*		
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 25	**2. Location:** 120 Camino Santiago *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building not present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 25**	**2. Location:** **120 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: East elevation, facing north.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 25**	**2. Location:** **Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: South elevation, facing northeast
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 25**	**2. Location:** **120 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: North elevation, facing southwest
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 20	121 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693719, -105.937155

10. Photo Information Negative: John Murphey View of: Front, east elevation, facing northwest.

11. Brief Description of the Property:

Reflecting a carport-dominant design, the small, vernacular dwelling sits at grade on the west side of Camino Santiago. The roughly 1,309-square-foot structure holds one bedroom. In plan, it is a compact square enclosed by an angled wall across its south exposure. Unlike most units at Plaza del Monte, it has a low pitch roof. The front (east) façade is dominated by the one-vehicle carport. The remainder of the façade is divided into windows and doors. The windows are uniformly multi-light steel casements in various standard sizes. The gabled north elevation has three identical windows. The rear (west) side of the house has more articulation, expressed through its beamed canopy over a pair of sliding doors. The frame house is finished with heavy brocade cementitious stucco in a peach-like color. A shallow square-beam supported overhang runs along the east and west elevations. It was constructed in c. 1971, after a design by Register, Ross and Brunet Architects.

12. Who uses the property? Residence

13. Construction Date: c.1971
_x_Known _x_ Source: drawings, aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

). Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Gilbert L. Boyd, who is listed as a tenant in the 1972 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 20	121 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Casement	Steel	2-2	3
Casement	Steel	3 [?]	1
Casement	Steel	3-3	5
Casement	Steel	3-3F-3F-3	1

*Because of storm covers, the operation and material is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ View Light	Wood	1
Single-Leaf	Raised Square Panel	Wood	1
Sliding	Patio	Aluminum	2
Double	Carport	Wood	3

12. Chimneys
One, stucco-clad, west exposure

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: __ _x_ No known modifications

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	__ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other: Contemporary with Spanish-Pueblo Revival ornamentation

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte** **Residence 20**	**2. Location:** **121 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Evaluation of Historical Status

Representing a Contemporary design, the house does not harmonize or contribute to the historical character of the district. Constructed in c.1971, it does not meet the minimum age threshold for consideration. For this reason, the recommendation is to designate 121 Camino Santiago a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 20**	**2. Location:** **121 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building not present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* __NRHP __SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 20**	**2. Location:** **121 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: South elevation, facing northeast and northwest
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 20**	**2. Location:** **121 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: West elevation, southeast
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 1	104 Camino Matias *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693073, -105.935289

10. Photo Information Negative: John Murphey View of: Front, north elevation, facing northeast.

11. Brief Description of the Property:

One of the first units to be constructed at Plaza del Monte, 104 Camino Matias is an L-shaped dwelling with a combined carport and portal. The approximately 1,143-square-foot, flat-roof structure holds two bedrooms. The bedrooms are placed in a wing forming the north end of the residence. Its front (west) façade presents a Spanish-Pueblo Revival plan with its cubic, battered mass and viga-roofed portal. Unlike many houses in the development, the carport plays a secondary role on the façade. The single-bay structure, arranged behind the portal, is less exuberant in its display of wood elements. The bedroom mass is fenestrated with small, rectangular windows; the remaining elevations have windows arranged in a more traditional pattern. The windows are mostly aluminum casement units. The portal elevation is painted white. A line of vigas runs along the top of the wall. It is supported by shiplap wood girders resting on round posts with zappos-type corbels. The house was constructed in c.1965. It represents the closest interpretation of the original 1960 Kenneth S. Clark and Philippe Register template design for the development.

12. Who uses the property? Residence

13. Construction Date: c.1965
_x_Known _x_ Source: aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

). Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Frederick H. Dawson, who is listed as a tenant in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing _x_ Non-contributing __ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Contributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 1	104 Camino Matias *Downtown and Eastside Historic District*	Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Casement	Aluminum	1-1	6
Casement	Aluminum	1-1F-1F-1	1
[?]	[?]	[?]	1

*Because of storm covers, the operation and material is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ View Light	Wood	2
Single-Leaf	Flush	Wood	2
Sliding	Patio	Aluminum	1

12. Chimneys
One, stucco-clad, south exposure

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: __ _x_ No known modifications

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes: Other:

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No. _____ District No. _____	***Please complete HCPI FORM 1 before completing FORM 2*** NRHP SRCP Criteria A B C D	
1. Name of property: **Plaza del Monte** **Residence 1**	**2. Location:** **104 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Evaluation of Historical Status

Constructed before 1968, and representing the original Clark and Register design template for the Plaza del Monte retirement homes, the house is a good example of the "Santa Fe style." For this reason, the recommendation is to designate 104 Camino Matias a Contributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2*		
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 1	**2. Location:** 104 Camino Matias *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 1**	**2. Location:** **104 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street and south elevations, facing southeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2*		
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte** **Residence 1**	**2. Location:** **104 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Photo 2: Street and north elevations, facing southeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte** **Residence 1**	**2. Location:** **104 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: East elevation, facing northwest.

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 10	105 Camino Matias *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693249, -105.935608

10. Photo Information Negative: John Murphey View of: Front, south elevation, facing north.

11. Brief Description of the Property:

This small house is one of three units constructed in 1950 for married staff employed by the Allison-James School. Arranged in a terrace-like fashion, each unit is a rectangular plan, side-gabled dwelling with an attached garage. The house has a telescoping roof form, evident along its north exposure. The roof extends over the walls on the north and south elevations to form small porches. The house is fenestrated with a mix of original and non-historic windows and doors. The windows are terminated with stuccoed concrete sills. Views from the house are oriented north toward the commons area. The north elevation contains a large picture window flanked by casements. Public entry is through an original ½-glass wood door on the south elevation. The garage door is a recent vinyl paneled unit. The roof is covered with three-tab asphalt shingles. Wood fascia has been applied to the north and south roof ends, obscuring (or removing) the original exposed rafters. A short stuccoed chimney rises from the north roof slope. The approximately 1,102-square-foot house holds three bedrooms. A non-historic, 220-square-foot carport has been erected over the driveway.

12. Who uses the property? Residence

13. Construction Date: 1950
_x_Known _x_ Source: Allison-James School publication and aerial photographs

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: __ Similar _x_ Dissimilar

Comments: Vernacular, gabled building, dissimilar to the Contemporary and Spanish-Pueblo Revival housing of Plaza del Monte

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

J. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The first resident identified with the house during the Plaza del Monte period is Sidney S. Brown, who is listed as a tenant in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: _x_ Contributing __ Non-contributing __ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa: Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 10	105 Camino Matias *Downtown and Eastside Historic District*	Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Double-Hung	Wood	1/1	4
Double-Hung	Metal	2/2	3
Fixed	Wood	Single	1
Fixed	Metal/Wood	Singled flanked by 2/2 DH	1
Sliding	Wood	1-1	1

*Because of storm covers, the operation and material is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel	Wood	2
Single-Leaf	½ -Glass	Wood	1
Overhead	Sectional	Vinyl	1

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: Unknown; replaced garage door; material and visual evidence.
#2 Date: 1960s; assumed replacement of original windows in majority of openings.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	__ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other: No style – side-gable vernacular form

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte** **Residence 10**	**2. Location:** **105 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Evaluation of Historical Status

Erected as a teacherage residence, the house does not harmonize or contribute to the aesthetic of Plaza del Monte or the historical character of the district. This includes non-conforming elements, such corner windows and cantilevered canopies over entries, which do not meet the ordinance standards. Additionally, its historical association lies with the Allison-James School, which was demolished in 1960. For these reasons, the recommendation is to designate 105 Camino Matias a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 10	2. Location: 105 Camino Matias *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte** **Residence 10**	**2. Location:** **105 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Figure 2: Rear (north) elevation of teacherage; Allison-James School in background. Source: Atkins, 1983.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2*		
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte** **Residence 10**	**2. Location:** **105 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: west elevation, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 10	**2. Location:** 105 Camino Matias *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: East elevation, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 10**	**2. Location:** **105 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: North elevation, facing southeast.

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 9	107 Camino Matias *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693289, -105.935797

10. Photo Information Negative: John Murphey View of: Front, south elevation, facing north.

11. Brief Description of the Property:

This small house is one of three units constructed in 1950 for married staff employed by the Allison-James School. Arranged in a terrace-like fashion, each unit is a rectangular plan, side-gabled dwelling with an attached garage. The house has a simple side-gable form terminating at the east end with a hipped roof over the garage. The gabled roof extends over the walls on the north and south elevations to form small porches. The dwelling is fenestrated with a mix of original and non-historic windows and doors. They are terminated with stuccoed concrete sills. Views from the house are oriented north toward the commons area. The north elevation contains a large picture window flanked by casements. Public entry is through an original ½-glass wood door on the south elevation. Two vertical [solar?] panels have been applied to the façade. The garage door is a recent vinyl paneled unit. The roof is covered with three-tab asphalt shingles. Wood fascia has been applied to the north and south roof ends, obscuring (or removing) the original exposed rafters. A short stuccoed chimney rises from the north roof slope. The house originally had an enclosed pedimented entry on the north elevation, which was reduced at some point in depth after 1969. The approximately 1,145-square-foot house holds two bedrooms.

12. Who uses the property? Residence

13. Construction Date: 1950
_x_Known _x_ Source: Allison-James School publication and aerial photographs

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: __ Similar _x_ Dissimilar

Comments: Vernacular, gabled building, dissimilar to the Contemporary and Spanish-Pueblo Revival housing of Plaza del Monte

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

). Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The first resident identified with the house during the Plaza del Monte period is Adin B. Brooks, who is listed as a tenant in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing _x_ Non-contributing __ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte Residence 9	107 Camino Matias *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe	__ Brick	__ Composition	__ Concrete: Block
__ Concrete: Cast Stone	__ Concrete: Poured	__ Earth Plaster	__ Masonry: Simulated
__ Metal: Corrugated	__ Metal: Structural Siding	__ Metal: V-Crimp	__ Stone: Random Ashlar
Stone: __ Random Coursed	__ Stone: River Rock	__Stone: Rusticated	__ Stone: Tabular
_x_Stucco:	__ Tile: Clay	__ Vinyl Siding	__ Wood: Board and Batten
Wood: __ Horizontal Siding	__ Wood: Jacal	__ Wood: Log	__ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Double-Hung	Metal	2/2	6
Fixed	Metal/Wood	Singled flanked by 2/2 DH	1
Sliding	Metal	1-1	1

*Because of storm covers, the operation and material is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	½ -Glass	Wood	2
Overhead	Sectional	Vinyl	1

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

1 Date: Post-1969; change of back door opening and enclosure; photograph, aerial imagery and material and visual evidence.
2 Date: Unknown; replaced garage door; material and visual evidence.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	__ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other: No style – side-gable vernacular form

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 9	2. Location: 107 Camino Matias *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Erected as a teacherage residence, the house does not harmonize or contribute to the aesthetic of Plaza del Monte or the historical character of the district. It includes non-conforming elements, such corner windows and cantilevered canopies over entries, which do not meet the ordinance standards. Additionally, its historical association lies with the Allison-James School, which was demolished in 1960. For these reasons, the recommendation is to maintain the status of 107 Camino Matias as a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 9	**2. Location:** 107 Camino Matias *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 9	2. Location: 107 Camino Matias *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018



Figure 2: Rear (north) elevation of teacherage; Allison-James School in background. Source: Atkins, 1983.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte Residence 9**	**2. Location:** **107 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 2: Street and east elevations, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 9**	**2. Location:** **107 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: Street west elevations, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 9	**2. Location:** 107 Camino Matias *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: North elevation, facing south.

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 8	109 Camino Matias *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693343, -105.936001

10. Photo Information Negative: John Murphey View of: Front, south elevation, facing northwest.

11. Brief Description of the Property:

This small house is one of three units constructed in 1950 for married staff employed by the Allison-James School. Arranged in a terrace-like fashion, each unit is a rectangular plan, side-gabled dwelling with an attached garage. The house has a telescoping roof form. The roof extends over the walls on the north and south elevations to form small porches. The front (south) façade reveals an altered composition. At some point after 1960, a 131-square-foot addition was appended to the southwest corner creating a sunroom. The dwelling is fenestrated with a mix of original and non-historic windows and doors. The windows are mostly double-hung sash. They are terminated with stuccoed concrete sills. Views from the house are oriented north toward the commons area. The north elevation contains a large picture window flanked by casements. Public entry is through an original ½-glass wood door on the south elevation. The garage door is a recent vinyl paneled unit. The roof is covered with three-tab asphalt shingles. Wood fascia has been applied to the north and south roof ends, obscuring (or removing) the original exposed rafters. A short stuccoed chimney rises from the north roof slope. The approximately 1,141-square-foot house contains two bedrooms.

12. Who uses the property? Residence

13. Construction Date: 1950
_x_Known _x_ Source: Allison-James School publication and aerial photographs

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: __ Similar _x_ Dissimilar

Comments: Vernacular, gabled building, dissimilar to the Contemporary and Spanish-Pueblo Revival housing of Plaza del Monte

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

20. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The first resident identified with the house during the Plaza del Monte period is Chester E. Wittier, who is listed as a tenant in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing _x_ Non-contributing __ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa: Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ __NRHP __SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte Residence 8	109 Camino Matias *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe	__ Brick	__ Composition	__ Concrete: Block
__ Concrete: Cast Stone	__ Concrete: Poured	__ Earth Plaster	__ Masonry: Simulated
__ Metal: Corrugated	__ Metal: Structural Siding	__ Metal: V-Crimp	__ Stone: Random Ashlar
Stone:			
__ Random Coursed	__ Stone: River Rock	__Stone: Rusticated	__ Stone: Tabular
_x_Stucco:	__ Tile: Clay	__ Vinyl Siding	__ Wood: Board and Batten
Wood:			
__ Horizontal Siding	__ Wood: Jacal	__ Wood: Log	__ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Double-Hung	Metal	2/2	8
Fixed	Metal/Wood	Singled flanked by 2/2 DH	1
Sliding	Metal	1-1	1

*Because of storm covers, the operation and material is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	½ -Glass	Wood	2
Overhead	Sectional	Vinyl	1

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: Pre-1966; introduction of projection across front, south, façade; aerial photographs.
#3 Date: Unknown; replaced garage door; and material and visual evidence.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	__ Spanish-Pueblo Revival
Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other: No style – side-gable vernacular form

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:	*Please complete HCPI FORM 1 before completing FORM 2*	
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 8	2. Location: 109 Camino Matias *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Erected as a teacherage residence, the house does not harmonize or contribute to the aesthetic of Plaza del Monte or the historical character of the district. This includes non-conforming elements, such corner windows and cantilevered canopies over entries, which do not meet the ordinance standards. Additionally, its historical association lies with the Allison-James School, which was demolished in 1960. For these reasons, the recommendation is to maintain the status of 109 Camino Matias as a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 8	2. Location: 109 Camino Matias *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 8	2. Location: 109 Camino Matias *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Figure 2: Rear (north) elevation of teacherage; Allison-James School in background. Source: Atkins, 1983.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 8	**2. Location:** 109 Camino Matias *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street and east elevations, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 8	**2. Location:** 109 Camino Matias *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: Street and west elevations, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **109 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: North elevation, facing southwest.

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 6	111 Camino Matias *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693391, -105.936212

10. Photo Information Negative: John Murphey View of: Front, west elevation, facing northeast

11. Brief Description of the Property:

Moved to the site prior to 1960, 111 Camino Matias is an altered three-bedroom house. The house is arranged on a north-south axis, and in plan consists of two telescoping gabled sections. To this basic form was added an L-shaped porch and connected carport in c.1966. The medium pitch roofs are covered with asphalt shingles and extend with overhangs. A short stuccoed chimney rises from the ridgeline. Small wood louvers are attached to the gable ends. The house is fenestrated with an array of original and non-historic windows. The windows — mostly double-hung sash — are arranged for interior functions. Windows are recessed from the wall and terminated with concrete sills. The combined porch and carport are supported by a framework of wood girders resting on grouped square posts. The single carport includes double storage units. A short breezeway leads from the carport to a back door. The 1,712-square-foot frame house is finished with textured cementitious stucco in a light buckskin color.

12. Who uses the property? Residence

13. Construction Date: Pre-1960; moved to site c.1960; portal and carport added c.1966
_x_Known _x_ Source: aerial photographs

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: __ Similar _x_ Dissimilar

Comments: Vernacular, gabled buildings, dissimilar to the Contemporary and Spanish-Pueblo Revival housing of Plaza del Monte

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

). Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The first resident identified with the house during the Plaza del Monte period is Daniel O. Shoop, who is listed as a tenant in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing _x_ Non-contributing __ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte Residence 6	111 Camino Matias *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Double-Hung	Metal	2/2	11
Fixed	Metal/Wood	Singled flanked by 2/2 DH	1

*Because of storm covers, the operation and material is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Panel	Wood	1
Single-Leaf	Flush	Wood	1
Double	Carport Storage	Wood	2

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry-portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: Pre-1960; house moved to site; primary source material and aerial photograph.
#2 Date: Pre-1966; introduction of portal and carport; layout plan and aerial photograph.
#3 Date: Pre-1966 (assumed); introduction of metal windows; visual and material evidence.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	__ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other: No style – side-gable vernacular form

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 6	2. Location: 111 Camino Matias *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Moved to this location before 1960, and modified in the mid-1960s with the addition of the portal and carport, the house does not harmonize or contribute to the aesthetic of Plaza del Monte or the historical character of the district. Additionally, its historical association lies with the Allison-James School, which was demolished in 1960. For these reasons, the recommendation is to maintain the status of 111 Camino Matias as a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte Residence 6**	**2. Location:** **111 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte Residence 6**	**2. Location:** **111 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: East elevation, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* __NRHP __SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 6**	**2. Location:** **111 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: North and west elevations, facing southeast.

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 7	116/120 Camino Matias *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693448, -105.936542

10. Photo Information Negative: John Murphey View of: Front, east elevation, facing northwest

11. Brief Description of the Property:

The vernacular, two-unit residence was erected before 1957, and modified nearly 30 years later with the addition of a cross gable entry. The combined residence is aligned along a north-south axis on the west side of Camino Matias. In plan, it is a side-gabled rectangle with a cross gable appended to its northeast corner. The north unit (120) holds about 1,256 square-feet, with three bedrooms. A window wall spanning the northeast corner signals its contemporary design. The north elevation under the gable is marred by a c.1984 shed-roof structure enclosing the furnace and water heater. The front façade faces east and is dominated by the non-historic cross gable entry. A recessed entry at the south end leads to 116. The interior, encompassing approximately 939 square feet, is arranged like an apartment. A similar non-historic stuccoed enclosure around the furnace and water heater is attached to the south elevation. The rear (west) elevation of the combined units faces onto a common area. A continuous overhang characterizes this façade. It is penetrated with three sliding glass doors and a mixture of fixed and sliding windows of different sizes. The roof is sheathed with rib metal panels. It unclear who designed the original house. The c.1984 addition of the cross gable and furnace and water heater enclosures was drawn in Philippe Register's shop.

12. Who uses the property? Residence

13. Construction Date: pre-1958, with alterations and cross-gable entry added on front façade in c.1984
_x_Known _x_ Source: aerial photograph

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: __ Similar _x_ Dissimilar

Comments: Vernacular, gabled buildings, dissimilar to the Contemporary and Spanish-Pueblo Revival housing of Plaza del Monte

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North ⬆ **Box Indicates Post-1968 Addition**

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

20. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The first residents identified with the house during the Plaza del Monte period are Margaret D. Becker (116) and Minnie C. Wither (120). Both are identified as tenants in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing _x_ Non-contributing __ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte Residence 7	116/120 Camino Matias *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Casement	Aluminum	8-8	2
Sliding	Aluminum	1-1	8
Fixed	Wood	Single	1

*Because of storm covers, the operation and material is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Flush	Wood	4
Single	Full-Glass	Wood	1
Sliding	Patio	Aluminum	3

12. Chimneys
N/A

13. Porches _x_ N/A
Type: __ Entry-portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: Pre-1966; introduction of modern fenestration; material and visual evidence.
#2 Date: c.1984; introduction of cross-gable entry across front, east, façade; drawings, aerial photographs and material and visual evidence.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	__ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other: No style – side-gable vernacular form with Ranch style elements

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 7**	**2. Location:** **116/120 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Evaluation of Historical Status

Erected before 1958, and modified in the mid-1980s with a cross-gable entry and small additions, the house does not harmonize or contribute to the aesthetic of Plaza del Monte or the historic character of the district. Additionally, its historical association lies with the Allison-James School, which was demolished in 1960. For these reasons, the recommendation is to maintain the status of 116/120 Camino Matias as a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 7**	**2. Location:** **116/120 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building present; pre-alteration.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 7	2. Location: 116/120 Camino Matias *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018



Figure 2: February 27, 1969 aerial photograph.
Building present; pre-alteration.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 7	**2. Location:** 116/120 Camino Matias *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street and north elevations, facing southwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 7**	**2. Location:** **116/120 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: South elevation, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte Residence 7**	**2. Location:** **116/120 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: West elevation, facing northeast.

City of Santa Fe

Agenda

HISTORIC DISTRICTS REVIEW BOARD FIELD TRIP

TUESDAY, June 25, 2019 at 12:00 NOON

HISTORIC PRESERVATION DIVISION, 1st FLOOR CITY HALL

HISTORIC DISTRICTS REVIEW BOARD HEARING

TUESDAY, June 25, 2019 at 5:30 P.M.

CITY COUNCIL CHAMBERS

*****AMENDED*****

CALL TO ORDER

A. ROLL CALL

B. APPROVAL OF AGENDA

C. APPROVAL OF MINUTES: June 11, 2019

D. FINDINGS OF FACT & CONCLUSIONS OF LAW

Case #H-19-041. 202 Gonzales Road
Case #H-19-0047. 133 Romero Street.
Case #H-19-045A. 917 Acequia Madre.
Case #H-19-046. 1658 Cerro Gordo Road.
Case #H-19-044. 1011 Camino Santander.
Case #H-19-045B. 917 Acequia Madre.

E. BUSINESS FROM THE FLOOR

F. COMMUNICATIONS

G. ACTION ITEMS

1. **Case #H-19-040. 336 Don Cubero Place. Don Gaspar Area Historic District. Doug Webb, agent for Rob Hagey, owner, proposes to replace eyebrow overhangs with a 290 sq. ft. 9'4" high portal, replace a pedestrian gate, install exterior lighting, and restucco a yardwall and a non-contributing residential building. (Carlos Gemora, cegemora@santafenm.gov, 955-6670)**

2. **Case #H-16-012B. 314 N. Guadalupe Street. Westside-Guadalupe Historic District. Paul Duran, agent for John and Melinda Balling, owners, propose to demolish a non-contributing accessory structure. (Lisa Roach, lxroach@santafenm.gov, 955-6657)**

3. **Case #H-19-019. 101, 102, 103, 105, 106, 109, 110, 111, 113, 114, 115, 117, 118, 119, 120, 121 Camino Santiago and 104, 105, 107, 109, 111, 116/120 Camino Matias. Downtown & Eastside Historic District. Lloyd and Associates, agent for Plaza del Monte LLC, owners. The Historic Districts Review Board requests historic status review and designation of primary façades, if applicable, for all residential structures in the Plaza del Monte Subdivision, except those reviewed for historic status in Case #H-17-098A (122, 124, 125, 126, and garages south of 126 Camino Santiago). (Lisa Roach)**

H. MATTERS FROM THE BOARD

I. ADJOURNMENT

Cases on this agenda may be postponed to a later date by the Historic Districts Review Board at the noticed meeting. Please contact the Historic Preservation Division at 955-6605 or check https://www.santafenm.gov/historic_districts_review_board for more information regarding cases on this agenda. Persons with disabilities in need of accommodations, contact the Historic Preservation Division office at (505) 955-6605 five (5) working days prior to the meeting date.

RECEIVED AT THE CITY CLERK'S OFFICE
DATE: June 19, 2019
TIME: 2:22 PM

City of Santa Fe

Agenda

HISTORIC DISTRICTS REVIEW BOARD FIELD TRIP

TUESDAY, June 25, 2019 at 12:00 NOON

HISTORIC PRESERVATION DIVISION, 1st FLOOR CITY HALL

HISTORIC DISTRICTS REVIEW BOARD HEARING

TUESDAY, June 25, 2019 at 5:30 P.M.

CITY COUNCIL CHAMBERS

CALL TO ORDER

A. ROLL CALL

B. APPROVAL OF AGENDA

C. APPROVAL OF MINUTES: June 11, 2019

D. FINDINGS OF FACT & CONCLUSIONS OF LAW

Case #H-19-041. 202 Gonzales Road
Case #H-19-0047. 133 Romero Street.
Case #H-19-045A. 917 Acequia Madre.
Case #H-19-046. 1658 Cerro Gordo Road.
Case #H-19-044. 1011 Camino Santander.
Case #H-19-045B. 917 Acequia Madre.

E. BUSINESS FROM THE FLOOR

F. COMMUNICATIONS

G. ACTION ITEMS

1. Case #H-19-040. 336 Don Cubero Place. Don Gaspar Area Historic District. Doug Webb, agent for Rob Hagey, owner, proposes to replace eyebrow overhangs with a 290 sq. ft. 9'4" high portal, replace a pedestrian gate, install exterior lighting, and restucco a yardwall and a non-contributing residential building. (Carlos Gemora, cegemora@santafenm.gov, 955-6670)

2. Case #H-16-012B. 314 N. Guadalupe Street. Westside-Guadalupe Historic District. Liaison Planning, agent for John and Melinda Balling, owners, propose to demolish a non-contributing accessory structure. (Lisa Roach, lxroach@santafenm.gov, 955-6657)

3. Case #H-19-019. 101, 102, 103, 105, 106, 109, 110, 111, 113, 114, 115, 117, 118, 119, 120, 121 Camino Santiago and 104, 105, 107, 109, 111, 116/120 Camino Matias. Downtown & Eastside Historic District. Lloyd and Associates, agent for Plaza del Monte LLC, owners, historic status review and designation of primary façades, if applicable, for all residential structures in the Plaza del Monte Subdivision, except those reviewed for historic status in Case #H-17-098A (122, 124, 125, 126, and garages south of 126 Camino Santiago). (Lisa Roach)

H. MATTERS FROM THE BOARD

I. ADJOURNMENT

Cases on this agenda may be postponed to a later date by the Historic Districts Review Board at the noticed meeting. Please contact the Historic Preservation Division at 955-6605 or check https://www.santafenm.gov/historic_districts_review_board for more information regarding cases on this agenda. Persons with disabilities in need of accommodations, contact the Historic Preservation Division office at (505) 955-6605 five (5) working days prior to the meeting date.

RECEIVED AT THE CITY CLERK'S OFFICE
DATE: June 7, 2019
TIME: 9:01 AM

SUMMARY INDEX
HISTORIC DISTRICTS REVIEW BOARD
June 25, 2019

ITEM	ACTION TAKEN	PAGE(S)
B. Roll Call	Quorum Present	1
C. Approval of Agenda	Approved as amended	1-2
D. Approval of Minutes - June 11, 2019	Approved as presented	2
E. Findings of Fact & Conclusions of Law	Approved as presented	2-3
F. Business from the Floor	Comments	3
G. Communications	Announcement	3
H. Action Items		
1. **Case #H-19-040.**	Approved with conditions 336 Don Cubero Place	3-10
2. **Case #H-16-012B.**	Approved demotion 314 N. Guadalupe Street	10-14
3. **Case #H-19-019.** 101, 102, 103, 105, 106, 109, 110, 111, 113, 114, 115, 117, 118, 119, 120, 121 Camino Santiago and 104, 105, 107, 109, 111, 116/120 Camino Matias.	Approved some Contributing	14-57
I. Matters from the Board	Comment	57
J. Adjournment	Adjourned at 10:16 p.m.	57

MINUTES OF THE

CITY OF SANTA FE

HISTORIC DISTRICTS REVIEW BOARD

June 25, 2019

CALL TO ORDER

A regular meeting of the City of Santa Fe Historic Districts Review Board was called to order by Ms. Cecilia Rios, Chair, on the above date at approximately 5:30 p.m. in the Council Chambers at City Hall, 200 Lincoln Avenue, Santa Fe, New Mexico.

A. ROLL CALL

Roll Call indicated the presence of a quorum as follows:

MEMBERS PRESENT:
Ms. Cecilia Rios, Chair
Mr. Frank Katz, Vice Chair
Ms. Jennifer Biedscheid
Mr. Anthony Guida
Ms. Flynn G. Larson
Mr. Herbert Lotz
Mr. Buddy Roybal

MEMBERS EXCUSED:

OTHERS PRESENT:
Mr. Carlos Gemora, Senior Planner
Ms. Lisa Roach, Planner Manager
Mr. Gabe Smith, City Attorney's Office
Mr. Carl Boaz, Stenographer

NOTE: All items in the Committee packet for all agenda items are incorporated herewith by reference. The original Committee packet is on file in the Historic Planning Department and available on the City of Santa Fe web site.

Chair Rios asked Mr. Boaz if this was his last meeting with the HDRB.

Mr. Boaz said it was.

Chair Rios thanked him for his service to the H Board.

B. APPROVAL OF AGENDA

MOTION: Member Roybal moved, seconded by Member Guida, to approve the agenda as presented.

VOTE: The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.

C. APPROVAL OF MINUTES: June 11, 2019

Chair Rios requested the following changes to the minutes:

On page 17, 4th paragraph it should say that Chair Rios asked if there were gabions demolished.

MOTION: Member Katz moved, seconded by Member Guida, to approve the minutes of June 11, 2019 as amended.

VOTE: The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.

D. FINDINGS OF FACT AND CONCLUSIONS OF LAW

Case #H-19-041. 202 Gonzales Road Case #H-19-046. 1658 Cerro Gordo Road. Case #H-19-0047. 133 Romero Street. Case #H-19-044. 1011 Camino Santander. Case #H-19-045A. 917 Acequia Madre. Case #H-19-045B. 917 Acequia Madre.

MOTION: Member Biedscheid moved, seconded by Member Larson, to approve the Findings of Fact and Conclusions of Law as presented.

VOTE: The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.

E. BUSINESS FROM THE FLOOR

Ms. Stefanie Beninato, PO Box 1601, said, "I too, thank Carl for staffing this Board and others, and for being patient with boards and the public."

Regarding separation of powers and what was supposedly an interpretation of the law by the Land Use Director, she had concern for the H Board. She pointed out an ordinance that says the LUD can interpret the Code. But in the State Legislature, the Executive cannot make the law nor remake law as they want it. There is no wording about "ambiguous." As an attorney, that is probably unconstitutional and not legal.

In my neighborhood, we were told that the City was going to use a less rigorous process in approving variances to setbacks for an administrative process instead of a public process. But when there is a conflict, a more rigorous interpretation must be used. So the underlying zoning says the Board should do it because it is the more restrictive process. "I hope you strongly hold on to that provision."

Regarding administrative approvals, Ms. Beninato said when she learned that a significant structure got administrative approval for a four-foot fence on the street, she was greatly concerned. That should come to the Board before it is finally approved. It could be done like a consent calendar. All administrative approvals should be on the consent agenda so the Board and public would know what was approved out there and that the Board could pull something off the calendar like a significant building for discussion by the Board.

There was no other business from the floor.

F. COMMUNICATIONS

There were no communications.

G. ACTION ITEMS

Chair Rios announced to the public that decisions of the Board could be appealed to the Governing Body within fifteen days after the Findings of Fact and Conclusions of Law have been approved.

1. **Case #H-19-040. 336 Don Cubero Place.** Don Gaspar Area Historic District. Doug Webb, agent for Rob Hagey, owner, proposes to replace eyebrow overhangs with a 290 sq. ft. 9'4" high portal, replace a pedestrian gate, install exterior lighting, and restucco a yardwall and a non-contributing residential building. (Carlos Gemora, cegemora@santafenm.gov, 955-6670)

Mr. Gemora presented the Staff Report as follows:

BACKGROUND & SUMMARY:

336 Don Cubero Place is a non-contributing multi-unit residential property located in the Don Gaspar Historic District. In 2005, the Board approved changes, which included replacing windows, doors, changing fenestrations, removing a south-facing portal, and restuccoing yard walls. On May 28, 2019, the applicant presented a proposal to construct a portal, replace the entry gate, stucco the yard wall and house, and install exterior address lighting. The board postponed the case, asking for changes to the gate design, the portal design, and alternative stucco colors.

Front Yard Wall Gate: The applicant originally proposed replacing the front, entry, antiqued wood gate with a solid steel gate but the board requested more wood, less steel, and more of a "friendly" design.

1. The applicant proposes a gate with a weathered wood finish and a rusted steel frame. Two additional gate designs are provided (Page 3B) with blue-painted wood gates but are not the applicant's preferred proposal.

Front Portal: The applicant originally proposed a 13' deep portal modeled after the existing carport on the property. The Board requested that the applicant redesign the proposed portal as a harmonious complement to the existing house and neighborhood. The Board suggested the applicant consider adding parapets, a smaller size, features to match the gate, more height, and changing the roof design.

2. Preferred Option A: The applicant proposes a corrugated metal, low-pitch shed roof portal at 10' deep instead of 13' with enlarged posts and beams and the addition of corbels.

   Option B: The applicant provides alternative designs for a portal with parapet. The applicant also asks for flexibility regarding canales.

Stucco Color: The applicant originally proposed a "sage green" color of stucco on the yard wall and house but the Board requested color alternatives and that the applicant consider the color of the rest of the two-unit structure.

3. The applicant now proposes a color similar to El Rey "La Luz" (earthtone).

Exterior Light:

4. The applicant proposes a metal, downward-facing light fixture to illuminate the street address and which will approximately match the existing light fixtures.

STAFF RECOMMENDATION:

Staff recommends approval of the proposed project and finds that the application complies with Section 14-5.2(D)(9) General Design Standards for all Historic Districts – Height, Pitch, Scale, and Massing, and 14-5.2(H) Don Gaspar Area Historic District.

Questions to Staff

Member Roybal saw there are two portal options and asked which option Staff approved.

Mr. Gemora said either one could be approved.

Chair Rios asked, in both A and B, what the depth, height and width would be.

Mr. Gemora said it would be 10' plus the overhang and 8' 6" in height. Option B would be 13' deep, and both are the same width (23') and height. The height would probably be about 10' to top of parapet.

Applicant's Presentation

Mr. Rob Hagey, 336 Don Cubero, was sworn. He said, "I like the color. My preference is a metal roof. Corten is used as a substantial roof compound. The depth of the portal is ten feet with the preferred drawing and I'm flexible. It could even be 8 feet deep. The main goal is to enjoy my yard outside with coffee in the morning and wine in the evening. And I will get bids for the cost."

Questions to the Applicant

Chair Rios asked in Option A if the canales go under the roof.

Mr. Hagey agreed. He indicated he spoke with someone at the City who thought both were okay. For drainage, he thought about a French drain. He also thought he could add another inch by lowering it directly at the foundation.

Member Guida asked him to explain the gate design that has three options.

Mr. Hagey asked the Board to pick one. He said, "I wanted a rusted metal gate and a man at the last hearing suggested adding wood to it. I went to Hansen Wood and found some great wood for a wood fence. We can do metal swaling and if it doesn't work, I can paint it blue."

Member Guida saw that as the third option - a metal frame with weathered wood. The first option has a lintel on it.

Mr. Hagey said with the lintel on top, he would move the gate a little back from the wall. "It is possible, and I see about half of the homes have that in the district. I was not trying to do anything unusual."

Member Guida asked for a sample of the stucco color.

Mr. Hagey said, "El Rey is one of leading compounds in New Mexico. The color I chose is El Rey."

Member Guida asked what the stucco color is now.

Mr. Hagey called it Rose. He said he planned to use the same color on all of the house, including the patio.

Member Guida noted there are two colors on the house now.

Mr. Hagey said no. There is a subtle difference. This is about me wanting to change the color. I have not seen a Rose color at all. But it is now a rose color and I don't know the exact name, but I am not interested in that color.

Member Guida asked, "Which surfaces to you want to paint?"

Mr. Hagey said "paint" is interesting. I did not know paint was an option. I don't know the criteria. My stucco has no cracks and there is no issue with leakage. I thought I could paint it, but I was told I could not; that I had to do stucco. I would like some clarification.

Chair Rios asked Staff to clarify.

Ms. Roach clarified that, in the past, the Division Staff's practice was that paint was only allowed on stucco if paint was already on the stucco and if not, stucco is only allowed and cannot be painted.

Mr. Hagey had no problem with that.

Chair Rios said if the gate options, option 1 was the nicest looking for her.

Member Biedscheid asked if he intended to stucco both wall and house.

Mr. Hagey said he did, and he has permission to do that.

Member Lotz liked gate option 3 very much.

Member Larson was concerned with the drainage issue if the roof has pitch. She would prefer the first gate option.

Member Biedscheid asked if he said option one for the gate would require it to be moved.

Mr. Hagey thought moving it would be best, but it would cost more. Right now, he can make it work with the beam on top.

Member Biedscheid did not see a drawing of the lintel.

Mr. Hagey said, "Right now, I just want to focus on this."

Member Biedscheid felt the 10-foot depth would be very deep and overwhelm the house. The HCPI shows a portal on the south that is more in scale and Mr. Hagey said he would consider a shorter depth. The south one was probably 5-6'.

Mr. Hagey was willing to compromise at 8'. To compare it with the carport that is already there and not used often, was not fair. This will be an attractive addition to the home.

Member Katz thought 8 feet would work very well. It is the width of our portal.

Chair Rios said she was having an 8-foot portal being built now.

Public Comment

Ms. Heidi Britt was sworn. She said, "I'm here to represent myself and some neighbors. After leaving the hearing last time, we came to realize something very important to us will be removed - a 60 foot ash tree that we have enjoyed for many years. We (she and her neighbors) have lived there 20-49 years. The tree is a focal point of our landscape and Mr. Hagey moved here less than a year ago. I'm not sure he appreciates that tree the way we do. It was also recommended that he reach out to his neighbors to include them in what he was doing and that has not happened.

"We composed a letter and asked him to include the tree in his design. We think it is a magnificent opportunity to do something creative. I have photos of the tree from each of the properties."

Chair Rios explained that the Board doesn't have purview over a tree.

Mr. Gemora said it sounds like some neighbors talked with LUD about removing the tree. It sounds like there is no barrier to that. But I could be wrong.

Ms. Britt said the tree was originally cited as a Siberian Elm and that is incorrect. The burden of maintenance is a very small excuse.

She added, "I don't see much improvement on the design. One drawing shows a carving but another shows none. One shows thicker than the other. In the design shown, Mr. Hagey wants to create an outdoor living space and only half would be useful for that. Because it is on the north side, it will cut off light. I'm suggesting maybe a beautiful gazebo for outdoor living and using the cost from cutting down the tree to have a center yard gazebo. I think it would be really attractive and add to the value of the neighborhood.

Ms. Britt said she would give him 15 hours of design time free. If the Board would consider some other solutions. I'm not sure many have been thought about. I don't feel he has researched it much. The tree cutting would cost about a thousand dollars.

Chair Rios asked Mr. Gemora about the elevation.

Mr. Gemora said one could see a bit of the portal above the wall. It is not overwhelming to the structure - a small to medium addition and it depends on the angle of the pitch if it a shed roof and not a parapet. There are different ways to think about it.

Mr. Stefanie Beninato, P. O. Box 1601, was sworn. She said, "I am happy the applicant made the portal smaller. I really agree it should be six feet wide but understand his desire. Eight feet is the widest it should be. I'm also concerned about the columns and the detailing at the top. It would look like a carport. It would make it darker there. The minimum slope should be 1.5 inch drop for six feet width. So it needs a different slope.

Regarding the tree, I understand the City has jurisdiction over native species of over 12-inch diameter. So I'm not sure why the City does not have jurisdiction over that."

Mr. John Eddy, 227 East Palace, Suite D, was sworn. He said, "This is very interesting case. Coming back after listening to you and the artistic work he has brought really helps us understand it. As for the gate, Option A was identified by two Board members as their favorite. I installed one just like it on Agua Fria. It is wonderful to bring such good drawings. Thank you.

As for the tree, there may be a solution. The City might have purview because it is probably 12 inches in diameter. Perhaps a ramada with open beams to provide shade and allow some sunlight into the windows would be better. In the summer, it would have breezy shade and air passage. Taking that depth of the shed back to 8 feet is a good solution and allow more light into that area. Bringing down to a steeper pitch is probably good but a ramada would potentially allow the tree to stay there with a ramada through the tree. And that would allow the water to come down to the roots of the tree."

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Mr. Hagey said one thing not considered is that the tree is 28" from the house and while putting new flooring in, he saw there is already some damage to the hallway near where the tree is. I have pictures that show it. He passed around the pictures.

Mr. Hagey shared his experience in living in a house on the coast with a palm tree in the bathroom. They encased it in sheet metal and the tree would move the sheet metal. With the tree being so close to the property, he thought perhaps he could plant a new tree and spend some time with the neighborhood. A more mature tree planted might be a nice compromise.

Board Discussion

Mr. Gemora commented on detailing on the drawing. He explained it is not a carving. It is dashed lines and not details. There is also no carving in option A.

When talking about the gate, he hoped the Board recognized that metal with wood was the preferred option in the packet.

Member Guida thought Staff mentioned an option on the canales.

Mr. Gemora agreed. The two canales existing are proposed above the pitched metal roof. It might block off one and it could be moved to the right side. It doesn't sound like both would be moved but one would be moved to the right.

Member Guida concluded there would be no change to the design.

Mr. Gemora agreed.

Member Larson saw in the existing drawing on page 2 that the existing corbels are a little more traditional and it might be well to incorporate that same design.

Member Guida said it was important to him in the submissions to get clarity in the work. The owner brought this portal design and the full scope is expressed. The gate is either in the same place or it is not. That scope needs to be clear to the Board. It is necessary to get accurate quality drawings to eliminate ambiguity.

The quality of the drawings is to allow the Board to understand that what is built will line up with those drawings. That is a big deal for him. He did not see a tremendous improvement, but it would be nice to have more detail.

Action of the Board

MOTION: Member Guida moved, seconded by Member Katz, in Case #H-19-040 at 336 Don Cubero Place, to approve the front portal, option A at 8' deep with wood columns equally spaced and revised updated design drawings submitted to Staff, and stucco color be approved with the understanding the stucco will be on both wall and house; approve the exterior light and for front gate the Board approve either option 2 or 3 because there was no clarity on #1.

Chair Rios asked for a friendly amendment that the stucco color is La Luz.

Member Larson asked for more clarity on the corbels that they be like the original corbels.

Member Guida accepted both amendments as friendly.

VOTE: The motion passed by majority 5-1 voice vote with Member Biedscheid voting against.

2. **Case #H-16-012B. 314 N. Guadalupe Street.** Westside-Guadalupe Historic District. Paul Duran, agent for John and Melinda Balling, owners, propose to demolish a non-contributing accessory structure. (Lisa Roach, lxroach@santafenm.gov, 955-6657)

Ms. Roach presented the Staff Report as follows:

BACKGROUND & SUMMARY:

314 North Guadalupe Street is a large lot with a single family residence and a free-standing garage. The residence was constructed before 1930 in the California Bungalow style and is listed as Contributing to the Westside-Guadalupe Historic District. The north and west façades of the main residence were designated as primary at the March 8, 2016, hearing of the HDRB, and the garage structure was assigned non-contributing historic status at the same hearing, due to extensive non-historic modifications and insufficient historic integrity.

As is described in the attached HCPI form, the garage was originally constructed before 1930 as a rectangular structure with a shed roof sloping to the west, a vehicular door on the east elevation, and white painted historic 6-lite hopper window on each of the north and south elevations. After 1966, an addition was constructed off-center on the east elevation, where the vehicular door is now located.

Now, the applicant proposes to demolish the non-contributing garage structure, as its

location interferes with a proposed lot-split, which will facilitate the proposal of infill housing units on the proposed rear lot.

RELEVANT CODE CITATIONS:

14-3.14 Demolition of Historic or Landmark Structure

(A) Summary of Procedure

(1) Upon receiving an application for demolition of a structure within the historic districts the HDRB shall, within sixty-five calendar days from the date of application, either grant or deny the application. Ordinarily, the HDRB will act on an application for demolition at its next regular meeting, if the application is submitted in proper form at least seven days before its next regular meeting; however, the HDRB may use the entire sixty-five day time period if the HDRB, on motion duly passed, determines such delay is necessary.

(2) Upon receiving an application for demolition of a landmark structure the HDRB shall, within sixty-five calendar days from the date of application, make a recommendation to the governing body to either grant or deny the application.

(B) Hearing Required

(1) In all applications involving the demolition of a structure, provision shall be made for a hearing, as set forth in the preceding section.

(2) The HDRB or governing body, as applicable, shall restrict its review to a consideration of whether the application will be in conformity with the standards established by this section.

(3) Notice of the time and place for each hearing shall be sent in writing to each applicant.

(4) An agenda of the HDRB shall be sent to all groups requesting notification and copies of meeting agendas, as set forth in the officially adopted neighborhood planning policies.

(5) On-site notice, by a sign of proposed demolition and of the time, date and place of the HDRB or governing body review shall be posted by the city on the affected property fourteen days prior to HDRB or governing body review of application for demolition. Such notice shall be prominently displayed, visible from a public street and securely placed on the property.

(C) Staff Review and Report

Before granting approval or denial to a demolition request, the land use director shall provide the following information on the structure under consideration.

(1) A report on the historic or architectural significance of the structure;

(2) A report from the city building inspector on the state of repair and structural stability of the structure;

(3) If the structure is more than seventy-five years old, and the entire project of which demolition is a part requires an archaeological clearance permit, a report from the land use director on whether the demolition would damage possible archaeological artifacts; and

(4) Other information as requested by the HDRB or governing body.

(F) Denial of Demolition Request

A determination that the structure should not be demolished shall impose a duty on the owner or other persons having legal custody and control to immediately take the action required under Section 14-5.2(B) (Minimum Maintenance Requirements).

(G) Standards

(1) In determining whether a request for demolition in a historic district should be approved or denied, the HDRB shall consider the following:
(a) Whether the structure is of historical importance;
(b) Whether the structure for which demolition is requested is an essential part of a unique street section or block front and whether this street section or block front will be reestablished by a proposed structure; and
(c) The state of repair and structural stability of the structure under consideration.

(2) In determining whether a request for demolition of a landmark structure should be approved or denied, the HDRB and governing body shall consider the following:
(a) The historical importance of the structure; and
(b) The state of repair and structural stability of the structure.

STAFF RECOMMENDATION:

Staff recommends approval of the proposed demolition and finds that the application complies with Section 14-3.14 Demolition of Historic or Landmark Structure.

Questions to Staff

There were no questions to Staff.

Applicant's Presentation

Mr. Paul Duran was sworn. He thought Staff explained the proposal very well and he would answer questions.

Questions to the Applicant

There were no questions to the Applicant.

Public Comment

Ms. Beninato (previously sworn), said, "I know it is noncontributing. But since there is no degradation of the building, what are the criteria for demolition? If Staff could explain that, it would help."

Chair Rios said they did see degradation of the building on the site visit.

Ms. Roach said section G outlines the standards. She read them aloud.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Board Discussion

Ms. Roach explained that there is no stipulation that the application has to meet all three criteria for demolition.

Action of the Board

MOTION: Member Katz moved, seconded by Member Roybal, in Case #H-16-012B at 314 N. Guadalupe Street, to grant the demolition application.

VOTE: The motion passed by unanimous 6-0 voice vote.

3. **Case #H-19-019. 101, 102, 103, 105, 106, 109, 110, 111, 113, 114, 115, 117, 118, 119, 120, 121 Camino Santiago and 104, 105, 107, 109, 111, 116/120 Camino Matias.** Downtown & Eastside Historic District. Lloyd and Associates, agent for Plaza del Monte LLC, owners. The Historic Districts Review Board requests historic status review and designation of primary façades, if applicable, for all residential structures in the Plaza del Monte Subdivision, except those reviewed for historic status in Case #H-17-098A (122, 124, 125, 126, and garages south of 126 Camino Santiago). (Lisa Roach)

Ms. Roach presented the Staff Report. She explained that there is no applicant. It was initiated at the request of the Board for these properties. We did get a letter at 5:00 indicating concerns that the City has denied due process and requesting to withdraw the application and stating the applicant has been preparing an application for development. There was no application for status review so there is no application to withdraw. It is the position of the City to proceed.

Chair Rios asked if the owner has to give consent.

Ms. Roach said no. The Board can initiate a status review and the only requirement is that the proper notification be made to the owner and that was done properly. Staff did follow all proper procedures and felt this was important.

Member Katz said it was ingenuous of owners to not have status of buildings before the plan.

Ms. Roach said she would not give the entire report but background and comments on the 50-year rule. And then as the Board considers status, suggested we go property-by-property and discuss and make a motion on each. She wondered about moving public comment earlier- perhaps after she reads the staff report.

Chair Rios suggested that also. Maybe the public will have general comments but could single out specific addresses.

Member Roybal asked where the status recommendations were taken.

Ms. Roach explained how Staff considered each individual property.

Member Roybal pointed out that eight months have passed since their first review.

Ms. Roach said the original application was submitted two years ago and we opened a new case in February.

Member Roybal asked if those recommendations were different.

Ms. Roach said they are.

BACKGROUND:

101-121 Camino Santiago and 104-120 Camino Matias are 22 residential structures, which along with 122, 124, 125, 126 and the garages at 126 Camino Santiago, comprise the Plaza del Monte subdivision, located in the Downtown and Eastside Historic District. Historic status for all 27 structures in Plaza del Monte is summarized in the table below:

	Construction Date(s)	Current Historic Status	Recommended Historic Status	HDRB Status Review Case
101 Camino Santiago	c.1967-68	NC	NC	H-19-019
102 Camino Santiago	c.1965	NC	C	H-19-019
103 Camino Santiago	c.1965	NC	C	H-19-019
105 Camino Santiago (Units 1-4)	1971	NS	NC	H-19-019
106 Camino Santiago	c.1965	NS	C	H-19-019
109 Camino Santiago	c.1965	NS	NC	H-19-019
110 Cam. Santiago / 112 Cam.	c.1962/c.1968	NS	NC	H-19-019
111 Camino Santiago	c.1965	NS	C	H-19-019
113 Camino Santiago	c.1970	NS	NC	H-19-019
114 Camino Santiago	c.1972	NS	NC	H-19-019
115 Camino Santiago	c.1970	NS	NC	H-19-019
117 Camino Santiago	1966-67	NS	NC	H-19-019
118 Camino Santiago	c.1973	NS	NC	H-19-019
119 Camino Santiago	c.1965	NS	NC	H-19-019
120 Camino Santiago	c.1971	NS	NC	H-19-019
121 Camino Santiago	c.1971	NS	NC	H-19-019
122 Camino Santiago	c.1971	NC	-	H-17-098A
124 Camino Santiago	c.1968	C	-	H-17-098A
125 Camino Santiago (Units 1-4)	c.1970	NC	-	H-17-098A
126 Camino Santiago	c.1968	C	-	H-17-098A
Garages south of 126 Cam.	c.1968/1977	NC	-	H-17-098A
104 Camino Matias	c.1965	NC	C	H-19-019
105 Camino Matias	1950	C	NC	H-19-019
107 Camino Matias	1950	NC	NC	H-19-019
109 Camino Matias	1950	NC	NC	H-19-019
111 Camino Matias	pre-1960 (moved to site)	NC	NC	H-19-019
116/120 Camino Matias	pre-1957 w/c.1984 addition	NC	NC	H-19-019

NS = Non-statused NC = Non-contributing C = Contributing

[1]historic status for 122, 124, 125, 126 and the garages at 126 Camino Santiago were assigned in Case H-17-098A. Recent HDRB actions on the status of Plaza del Monte are provided here, and a more extensive case history is provided as an attachment to

[1] Historic Status Recommendations are taken from the "Plaza del Monte Historic Resources Evaluation," by John Murphey (2018).

this report. On March 26, 2019, the HDRB reviewed the status of the seven non-statused structures in Plaza del Monte (105, 113, 114, 115, 118, 120, and 121 Camino Santiago), and their decision was to assign Contributing status to all seven structures because of their association to the Plaza del Monte, an historic planned subdivision, and because they are representative examples of Mid-century Modern influenced expressions of Santa Fe Style. On April 23, 2019, the HDRB rescinded their motion from the March 26, 2019, hearing regarding the assignment of contributing historic status for the seven non-statused structures at Plaza del Monte, citing insufficient discussion of each individual structure to justify the assignment of contributing status, including failure to designate primary façades. The conditions of this action were in the form of the following directives: 1) that the Land Use Director provide interpretation of the "50-year rule"; 2) that staff provide information regarding applicability of the provisions in the code for "Historic Compound" designation; and 3) that staff bring all remaining structures in Plaza del Monte back to the HDRB for review under a single status review case.

This report represents staff's response to directives included in the April 23rd rescission of status designation for seven non-statused structures in Plaza del Monte. All structures in Plaza del Monte for which status has not previously been reviewed by the HDRB are herein presented to the HDRB for status review, including designation of primary façades as needed for those structures that receive contributing status.

HISTORICAL SUMMARY OF PLAZA DEL MONTE[2]

The Plaza del Monte subdivision, or Plaza del Monte Retirement Center as it was formerly known, was originally conceived in the late 1950s as a communal living center for retired Presbyterian pastors, missionaries, and other church officials. After the Allison-James School closed in 1958, the United Presbyterian Church decided to plan for re-development of the site, and they selected the architectural firm of Kenneth S. Clark and Phillippe Register to design it as a large retirement community. The architects divided the former campus into two parts – the site of the older buildings termed the "South Area" would be developed first with a congregate building, and the "North Area" would be developed in a second phase with individual residences. A preliminary layout of the development in 1960 showed a cul-de-sac arrangement of the homes built around two new streets. Camino Santiago would run along the northern portion of the property, turning south and terminating in a cul-de-sac, and Camino Matias would be a loop off of Camino Santiago running through the older residences at the southern portion of the property.

As is described in the Plaza del Monte Historic Resources Evaluation, Clark and Register conceived the design of the residences as a modified L-plan to which a carport and portal were attached. Architectural details are sympathetic to the Spanish-Pueblo Revival tradition – with room-block stuccoed massing, rounded corners, and vigas,

[2] Historical Summary paraphrases research presented in the "Plaza del Monte Historic Resources Evaluation," by John Murphey (2018).

posts and corbels on the portals and carports – but re-framed in mid-century styling. This contemporary influence became more pronounced on the exteriors of the later homes in the development, when the low, horizontal lines of the residences were further accentuated with flat overhanging roofs at times intersected with vertical planes. The latest homes constructed in Plaza del Monte in the early 1970s experimented with angular walls and a more compact massing with carport-dominant façades.

RELEVANT CODE CITATIONS:

14-5.2(C) Regulation of Significant and Contributing Structures in the Historic Districts

(1) Purpose and Intent

It is intended that:

(a) Each structure to be recognized as a physical record of its time, place, and use. Changes that create a false sense of historical development, such as the addition of conjectural features or architectural elements from other buildings, shall not be undertaken;

(b) Changes to structures that have acquired historic significance in their own right shall be retained and preserved, recognizing that most structures change over time;

(c) Distinctive features, finishes, and construction techniques or examples of craftsmanship that characterize a structure be preserved; and

(d) New additions and related or adjacent new construction be undertaken in such a manner that if removed in the future, the original form and integrity of the historic property and its environment would be unimpaired.

14-12 Significant Structure:

A structure located in a historic district that is approximately fifty years old or older, and that embodies distinctive characteristics of a type, period or method of construction. For a structure to be designated as significant, it must retain a high level of historic integrity. A structure may be designated as significant:

(A) for its association with events or persons that are important on a local, regional, national or global level; or

(B) if it is listed on or is eligible to be listed on the State Register of Cultural Properties or the National Register of Historic Places.

14-12 Contributing Structure:

A structure, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a contributing structure is not unique in itself, it adds to the historic associations or historic architectural

design qualities that are significant for a district. The contributing structure may have had minor alterations, but its integrity remains.

14-12 Primary Façade:
One or more principal faces or elevations of a building with features that define the character of the building's architecture.

14-12 Noncontributing Structure:
A structure, located in an H district, that is less than fifty years old or that does not exhibit sufficient historic integrity to establish and maintain the character of the H district.

"50-YEAR RULE" GUIDANCE:

The "50-year rule" is one of the most widely accepted principles within the historic preservation movement in the U.S., establishing the standard that properties approximately fifty years old or older are of sufficient age to have established historic significance as a threshold for triggering preservation. The rule was established by the National Park Service in 1948 and codified at the federal level in the National Historic Preservation Act of 1966. Exceptions to this standard have been applied to sites, structures and places that are less than fifty years old, but which have demonstrated "exceptional importance" independent of age. This chronological filter has been applied to properties nominated to the National Register of Historic Places, and it has been widely utilized in local historic preservation ordinances across the country as a means to settle potential controversies over the nature of historic significance. 3

The "50-year rule" was included in Santa Fe's historic preservation ordinance in 1957 – one of the earliest uses of the standard at the local level. Because it has its origins in federal historic preservation policy, it stands to reason that its administration at the local level should follow federal guidance. In doing so, the HDRB is encouraged to apply the "50-year rule" as a guideline when evaluating historic status of properties. Accordingly, properties less than fifty years old may be deemed to be contributing or significant if the Board determines that they are of "exceptional importance" (association with or representative of events, people or trends of historical or architectural significance).

That said, there has been much recent discussion of the "50-year rule," including calls to reconsider its utility and application.

STAFF RECOMMENDATION:

Staff generally agrees with the status recommendations provided in the "Plaza del Monte Historic Resources Evaluation" but defers to the Board for individual status assignments, per 14-5.2(C) Designation of Significant and Contributing Structures.

---

[3] "'Of Exceptional Importance': The Origins of the 'Fifty-Year Rule' in Historic Preservation," by John H. Sprinkle Jr. (2007) *The Public Historian: A Journal of Public History.*

Ms. Roach read the definitions of contributing and significant structures from the Code before reviewing each address. She consulted with City Attorney, LUD and State Historic Planner. She read from the 50 year rule.

She explained it was an approximate guideline and up to the Board to determine if they were significant enough to be designated Contributing and some are less than 50 years old but there is not a rule that the Board could not designate a 47 year old as Contributing.

Chair Rios said the homes are 47 to 69 years old. What is important in the review is the contribution the Presbyterian Church made to this community and those occupations of retired church individuals were an important group. So it was not only representative of time and place but also its association to the City.

Ms. Roach agreed and noted it was not an important theme by John Murphy.

Member Roybal said his concern was with the rule but also that they do not meet Santa Fe Style criteria.

Ms. Roach replied that we have many examples of buildings that don't meet Santa Fe Style like the Cathedral and Scottish Rite Temple. And whether the Board feels mid-century does fall into that category. It is also on impulse of the ordinance in 1957 to counter the introduction of mid-century and is why we don't have a lot of examples of that style. When Plaza del Monte was approved, the HDRB felt it did comply sufficiently with Santa Fe Style to allow its construction.

Member Roybal said he was just concerned in applying the 50 year rule without consideration of design.

Member Biedscheid wanted to consider them as a compound. The value is that they are part of a conceived compound and wondered what criteria they might use for that.

Ms. Roach referred to Section K of the Code. It has not been utilized frequently. There was an effort in 2005 and 2006 to follow through and a survey took place at that time, but we are having trouble finding if the register of compounds was ever created. She would talk in general terms about the criteria and the innovations of the property for any potential designation. She read that section of the code to identify compounds.

Ms. Roach said this compound would not have been considered at that time since it was not near old enough and the criteria said half of the buildings must be designated as contributing.

Member Biedscheid asked, if the Board designates 50% or more as contributing, whether a separate motion should be made to consider historic compound status.

Member Roybal asked, since we don't have an applicant here, if they have a right to appeal.

Ms. Roach said the owner does have that right.

Member Guida asked if there is anything about what we might call a compound that would exclude it from consideration.

Ms. Roach believed this development would qualify in its plan for development and location of the buildings and they are historically related. A compound is more about spatial relationship and intent. There are four different types mentioned in the code.

Member Katz pointed out that it is all owned by the same person and always has been and the people rent their units. He asked if the lots are separate lots of record.

Ms. Roach said there are separate lots of record, but all are owned by the same individual.

Mr. Gemora said regarding the 50-year mark, that the contributing definition says "is approximately fifty years old and has the design features..." So it doesn't have to be of the style but add to the qualities of that district so other different styles could be added.

Ms. Roach said she actually didn't know for sure that they were separate lots of record and would have to research that.

Member Larson said in moving forward, this has a very important part in the context of our City and environment.

Mr. Smith pointed out in Chapter 14-1.9, under construction, that all expressions shall be considered in the context. Approximately is not defined. In accordance with the General Plan, "approximate" would not have a definite number.

Member Katz looked at "approximate" to cover when you did not know when something was created. There are aerial photos that are dated. He thought it needs to be 50 years, but when you don't know it, is where approximately comes in... except if it has great importance.

Public Hearing

Chair Rios asked for general comments at this point and would later ask for public comment at each one.

Ms. Nancy Armbruster, 111 Camino Santiago, was sworn. She read her testimony statement. She is 85 years old and has lived joyfully in Plaza del Monte for 20 years and in Santa Fe for 50 years. "I've spoken to you many times about the beauty and camaraderie of our Plaza del Monte community, so close to the center of our City. I understand the developers have the financial resources to destroy all of our community completely, probably to put up condos and you have the power to tell them to go away and develop some other town. What do you want in downtown Santa Fe? A cluttered city just like any other old city center. Or a beautiful special area with tall trees and old houses cherished in value by many who long for living in a town like ours? You know what is right and do it and do it as soon as possible. Thanks for listening to us."

Ms. Ellen Armbruster, 1 Ladera Place, was sworn. She said, "I've spoken here on numerous times and tonight, I ask you to find all of these to be of contributing status and halt the ongoing assault by the developer on this beloved community, by recognizing the historical value of the houses which belongs together as an integrated and unified whole. Please, remember also that this community has for many years provided affordable housing for the people of Santa Fe recently for senior living and now including young families. I ask you to save all of it in its entirety by designating all buildings to have contributing status."

Ms. Madeline Pryor, 3362 La Avenida de San Marcos, was sworn. She welcomed the new Board members who were appointed after her last testimony. She said, "I'm very interested because I lived there at Plaza del Monte for 11 years until required by the present owners to leave. The apartment I lived in was declared noncontributing because it was only 49 years old. I'm going to ask that you consider adding all the structures recommended as non-contributing due to age as contributing. They are all almost 50 years old. Philippe Register designed them and the seven on the list Mr. Murphy recommended noncontributing were all because of age - not quite 50 years of age and four as of contemporary design and no reason for 101 Camino Santiago. But Register designed all of them.

"On the five homes that were recommended as part of the Allison James School for teachers and not designed by Register, when it was transitioned from Allison James to Presbyterian retirement - they have features that are quite charming. They are on Camino Matias.

"I was surprised when reading the second amendment to the March 24, 2018 report, on page 4, that because of timing issues he (Murphy) did not have a chance to review the First Presbyterian Church Historic Library or the Menaul School Historic Library.

I don't know if that was important or not or whether he since reviewed it or not.

My basic request is that you accepted those who were recommended noncontributing just because of age because they are approximately fifty years old. And look at what he considered contemporary design because of the significance of this

community and of the architect Register, who did it.

"There is one inaccuracy in the review on the home at 121 Camino Santiago, because he got the bedrooms wrong. Thank you."

Ms. Natasha Torres, Creston Colorado, was sworn. She said, "I lived at 116 Camino Santiago for 6 years. I loved that community and I loved all the architectural and history of the district. I loved the teachers' homes by the same architect. It is not good to break up the whole area."

Mr. John Eddy (previously sworn) was grateful that a decision was made to rescind a previous decision on this property because the due diligence undertaken is now very important. When it first came two years ago, I suggested at the first hearing that it needed to be considered as a whole - of a piece, because this neighborhood was a single concept by Clark and Register. They were very respected architects in Santa Fe. And it was on the wishes of the Presbyterian organization and most unique in Santa Fe. The most salient feature - many other developments came about through a vernacular approach with individuals designing their own home. This was conceived for a specific use for giving people a place to live that was affordable. It has gone through different changes - when mid-Century came along - influences coming in and will become a very accepted part of our conversation. A beautiful example for mid-century is the building across from old St. Vincent hospital. Modest homes that do not shout out we are experts of mid-century modern so the architectural historian might have called out they are not classic mid-century but in the direction Santa Fe was going. You had one up on Camino Santander. This property was built with a big concept in mind and that is most salient to take away in the process.

I think the idea of time and approximately close to 50 years, means you do have wiggle room here. I also think because they developed over time, that continuum has to be recognized as a whole not just houses plopped down. They were placed very deliberately.

The idea of classification as a historic compound is very important and I hope you find that is a classification that can be applied on this property and it will belie the fact that you understand that."

Ms. Linda Payne, 414 Bishops Lodge Road, was sworn. She said, "I look down on Plaza del Monte and, for the last 48 years, have been a neighbor. I remember it in its heyday and hope as you go house-by-house that you will consider it historic. It is a cohesive neighborhood and ties in what Mr. Eddy just said. It is a peaceful community and we are losing a lot of neighborhoods with condos and Air BnB's. New people are coming in and renting and older families leaving. And I hope you consider it a historic property."

Ms. Stefanie Beninato (previously sworn) agreed with much of what has been said and everyone who speaks, talks about it as a community and a unified holistic design to be considered as a whole. I am happy that Member Biedscheid suggested considering it as a whole. And acknowledging the integrated design. I think you could consider it together. And the Presbyterian Church had no intent to divide it up to sell.

It is too bad several were already designated as noncontributing and sad you could not reconsider that. The ones to the north are more modern but this was approved when HDRB was in existence and thought it was an appropriate design to embody the traditional and contemporary and we need to acknowledge it. The approximately 50 year rule is helpful and when part of a whole, we need to preserve the whole and a 47 year old structure would contribute to that whole.

It is also important because it has a strong historic association with the Presbyterian Church, which, in New Mexico, has done a lot of positive things in the community to create a compound where ministers and missionaries could have a place to retire for people who contributed greatly. It is so beautiful on some level.

There were no other speakers from the public regarding this part of the case and the public hearing portion was closed.

Board Discussion

Member Guida asked if the Board could make general comments before going to each unit.

Chair Rios agreed.

Member Guida said Staff made recommendations in two broad categories on those for contributing and a distinction with those on Camino Santiago on the 50 year rule. It is a problematic distinction that classifies later Register designs as contemporary. That doesn't work for me and the later ones are a better interpretation of mid-century style. I'd like to know where the Board members are as an overall opinion. Should Significant be on the table for these, although they are humble structures?

Member Larson thought the beauty of the National Register is that it is up to the experts and we are looking at a master-planned community. We see a lot of highlights and the fact that it is master-planned. I would have to agree that it is the big picture we are looking at. I'm not sure I agree with the recommendations of the historic surveyor.

Member Katz looked at the GIS and it is a single lot that emphasizes that it is of a piece.

Member Biedscheid said her intent was to see this as a historic compound and she thought it was eligible and does contribute to the historic district. The streets were

conceived in the current situation and locations were all planned and still are intact today.

For consistency in making a decision, of the five already applied, should hold to the 50-year rule. We've already gone down that road. And she also disagreed with many of the results of the historic evaluation.

She pointed out that the Code does not address contemporary design and the influence on architects at that time does not affect historic status."

Member Roybal said his concern was with the evaluation of John Murphy. And he did not think the Board should go down each individual structure if it is considered as a compound. He thought the Board should designate it as a full compound.

Ms. Roach explained that the Board is required to designate each status before considering it as a compound. She added that the association with Presbyterians and Register are relevant.

Member Roybal asked if those built in 1973 or 1972 would not qualify.

Ms. Roach said they could, however the Board interprets the 50-year rule. And as Member Biedscheid mentioned, five already have had their status designated. Her intent was to stick with that designation.

Chair Rios asked how many members felt they must stick with the exact 50 years.

Three members raised their hands and three did not. Member Katz, Member Roybal and Member Biedscheid wanted to stick with exactly 50 years.

Member Katz thought all the Board accepted it as a planned community - all of a piece. And as a compound, it protects all structures through the compound designation. And several of them are 2-3 years away from the 50 year mark and we don't have to stretch to make those historic if 50% of them are historic. That would then allow us to proceed with the compound process.

Ms. Roach said regarding compound protections, that there are things to assist. If the compound continued to be owned by a single owner, that the owner would come forward with what the compound plan is for any proposed changes and if divided with multiple owners, the new owners would still have to comply with limits on height, total additions added, similar materials and style of the compound and any blockage of the spatial nature of the compound. So with the protections of the compound status, the Board would not be compelled to make every structure have a contributing status.

Chair Rios noted that if the whole was determined to be a compound, at least 13 would need to be contributing.

Ms. Roach said they would need 14 to be a majority.

Chair Rios observed that obviously harmony would play a huge role but not as strictly for noncontributing.

Ms. Roach, in interpreting Section K, said that there would be similar restrictions as with contributing buildings and limitations on new construction. Spatial relationships and form are considered part of the compound (harmony). So there are standards that would apply to modifications and a little more strict - height regulations, etc.

Member Lotz felt it was a complex issue for him and he might have to abstain.

Member Guida did not want to beat on the 50-year rule but he did not understand why the Board should be so strict about it. We are making an argument about the compound being of a piece - and of design integrity and consistency and challenged by the limitations of contributing. We could go about it with a focus on view. We are also designating façades as primary. Some of them are visible from different angles.

He said the piecemealing at a macro level concerned him. But all are individual structures, to be consistent with the ordinance. They are bringing it philosophically.

Chair Rios agreed on that interpretation because each building relates to one another to create the compound.

Chair Rios thanked those who came out for this case.

Member Larson said- the 50-year rule is so important. At the National Park Service, we are handling it as a specific movement, not restricted to the 50 year rule. Like Member Guida said, we are looking at a master plan very common in that area. With the National Register, there is flexibility in making evaluations and is why it is there. The 50-year rule was created to manage nominations for the National Register when it was coming of age.

Ms. Roach said as she looked at the evaluations and at the time, tended to agree with recommendations. But now, she has shifted. She would present John Murphy's recommendations, but the Board should have the privilege to decide. She said she would participate in the discussion but refrain from a specific recommendation. She also explained that the packet has two façades photographed for each individual property.

SUMMARIES OF INDIVIDUAL PROPERTIES

101 Camino Santiago: Situated near the east entrance to Plaza del Monte, the house is a roughly 1,332 square foot contemporary residence constructed in 1967-68. In plan, the three-bedroom dwelling has a square form with an attached L-shaped portal and

garage, giving it a combined square footprint. It presents to the street a long portal with the roof carrying over the garage. It is fenestrated with aluminum windows, primarily of a sliding operation. A paneled wood door gives entry to the residence at the east end of the portal. The garage entry is fitted with a recent vinyl overhead door. Cementitious brocade stucco in a peach tone covers the frame building. The roof consists of a mixture of gravel and asphalt material. An interior parapet outlines the dwelling portion of the mass. While contemporary in form, the vigas across the portal give the residence a regional feel.

The recommendation of John Murphy was Noncontributing because of contemporary design. If it is considered to be Contributing, the south façade is recommended as primary.

Board Discussion

Member Guida asked which façade is also shown.

Ms. Roach said it was the north elevation (rear).

Chair Rios asked Ms. Roach is she would agree all of them have had no footprint changes, but some window openings have changed.

Ms. Roach said this is the original footprint. The garage door is recent. She was unclear if windows were original, but it appears they are the original openings.

Public Comment

Ms. Beninato (previously sworn) asked for its age.

Ms. Roach said it was constructed in1968.

Ms. Beninato felt this property is Contributing. The footprint is original. The Board should accept the garage door and should find it Contributing with the south façade as primary. That one is probably typical.

Ms. Roach, commenting on that issue, said if the intent is to consider this as a compound, there are sufficient protections relating to building form and stylistic elements that the Board could deny an application that would substantially change it.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: **Member Katz moved, seconded by Member Biedscheid, in Case #H-19-019 at 101 Camino Santiago, that it be Contributing with the south façade as primary and in that photo you would not find a mid-century house like it anywhere else but in Santa Fe. It is a wonderful adaptation the way they incorporated it into this home.**

Member Biedscheid added that the portal over the garage is a novel approach and use of timber posts. Member Katz agreed.

VOTE: **The motion passed by majority (5-1) voice vote with Members Biedscheid, Katz, Guida, Larson, and Lotz voting in favor, and Member Roybal voting against.**

102 Camino Santiago: One of the earliest units to be constructed at Plaza del Monte, 102 Camino Santiago is a 2,064 square foot dwelling with one addition. The two bedroom, flat-roof house faces Camino Matias. It shows to the street (west) a façade-long portal, continuing at the south end as a single-space carport. The portal is supported by shiplap wood girders resting on round posts with double-ended corbels. Most of the portal façade is painted white. A line of vigas runs along the top of the wall. The elevation is penetrated by two doors and large windows, with the southernmost window not meeting the ordinance in regard to its distance from the corner. The north elevation facing Camino Santiago displays a variety of window openings holding tall metal casements. A shallow overhang supported by short vigas carries over most of the elevation. At the northeast corner is a room block-like projection holding the bedroom wing. The rear (east) elevation presents a number of alterations. The largest is a post-1969 addition, over what was a patio. The 380-square-foot addition is fenestrated with modern windows and is sheltered by a parapet-type portal. The house was constructed in c. 1965, and its designer/architect is unverified but assumed to be Kenneth S. Clark and Phillippe Register. Contributing status is recommended for this structure, as it is representative of the original Clark and Register design template for Plaza del Monte residences and is a good example of Mid-century Santa Fe Style. If the Board assigns contributing status to the residence, the west façade is recommended as primary.

Board Discussion

Member Guida said the carport seems very significant. His concern would be on the significant changes to that façade.

Ms. Roach commented on the rule that new construction shall not block. There is sufficient justification to deny contributing with that factor.

Public Comment

Ms. Beninato (previously sworn) said she would like to see it designated Contributing but would want more than one façade designated primary. Garage doors are significant, and the design has setback. All three should be primary. Even though we have the rules about setbacks from primary façades, people come in and cry about getting an exception and get to crowd up on the primary façade.

Mr. John Eddy (previously sworn) asked if in the photo outlined in yellow, it is in a plane with the vigas and lintel above it - there appears to be no setback in that façade.

Ms. Roach thought that was correct.

Mr. Eddy thought that was infill of a substantial portal.

Chair Rios asked Ms. Roach to identify the elevations.

Ms. Roach said the front façade is facing northeast. The building faces Camino Matias and the rear faces east.

Chair Rios wanted to make sure.

Ms. Natasha Torres (previously sworn) said the layout shows it clearly.

Action of the Board

MOTION: Member Biedscheid moved, seconded by Member Guida, in Case #H-19-019 at 102 Camino Santiago, to designate the structure as Contributing with west and south façades as primary.

VOTE: The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.

103 Camino Santiago: Roughly 1,533 square feet, the one-story residence is designed as an L-plan form. The plan puts the bedrooms in a cube-like mass, with the remainder of the functions of the house strung along a linear spine. Its façade is defined by a long portal sheltering its entry and patio doors. The east end of the composition terminates as a one-bay carport. A line of vigas runs along the back (north) elevation supporting a short overhang. An exterior chimney breaks through the overhang, rising several feet above the roof. The house is fenestrated with an array of original and replacement aluminum windows. It is entered under the portal through a stylized wood panel door flanked by one set of sidelights. The dwelling's flat roof is outlined by a short parapet;

the roof is covered with gravel. The frame structure is finished with cementitious brocade stucco in the buckskin tone. While contemporary in form, vigas used across the portal and the room block bedroom wing give the residence a Spanish-Pueblo Revival feel. The house was constructed in c. 1965; its architect/designer is unverified but assumed to be architect Phillippe Register. Contributing status is recommended for this structure, as it is representative of the original Clark and Register design template for Plaza del Monte residences and is a good example of Mid-century Santa Fe Style. If the Board assigns contributing status to the residence, the south façade is recommended as primary.

Public Comment

Ms. Beninato (previously sworn) said she was happy this is recommended as Contributing with the south façade as primary. She suggested the Board might consider the vigas side also. It does contribute to that house and has more Santa Fe character and the beginning prototype.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: Member Katz moved, seconded by Member Lotz, in Case #H-19-019, at 103 Camino Santiago, to designate the structure Contributing with the south elevation as primary.

Chair Rios asked mover to be specific why it should be Contributing.

Member Katz said it follows the Staff recommendation and follows the L-shaped form that is characteristic.

Member Larson asked for a friendly amendment to add that side elevation as primary.

Member Katz declined.

VOTE: The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.

105 Camino Santiago (Units 1-4): Forming a long, linear composition, 105 Camino Santiago is one of three apartment buildings erected at Plaza del Monte. The carport-

dominated structure works its way down the slope as two L-plan units joined together at the center by a laundry room. The structure is bookended by masses holding the apartments. The larger apartments containing two bedrooms are situated in the projecting room blocks. The apartments share a party wall at the living room. Spanning between the apartments are the carports and the laundry room. The carports are detailed with a viga-roof structure which continues as a portal along the inner apartments. The rear (north) elevation is divided into small patios. The apartments are entered through wood panel doors; solid wood doors give access to the storage units and the laundry. The original multi-light steel casement windows have been replaced with aluminum units. A short parapet follows the outline of the apartments, and is penetrated on the south, east and west elevations with cut-through metal canales. The frame structure is finished with cementitious brocade stucco in a peach tone. While contemporary in form, the vigas used across the portales and carports and the cubed apartment masses give the residence a regional feel. The roughly 4,198 square foot apartment building was constructed in 1971, after a design by architect Phillipe Register. Non-contributing status is recommended for this presently non-statused multi-unit residential structure due to age and contemporary design features. However, the Board may consider that its association with architect Phillipe Register and with the Plaza del Monte planned development could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the south façade is recommended as primary.

Board Discussion

Member Guida pointed out that both photos are of the south façade.

Ms. Roach agreed. She said page 143 shows the HCPI photos. Photo 2 shows south and east. And also the north in Photo #1.

Member Katz noted it is a very interesting Santa Fe style with large block masses. It is classic Santa Fe style. He thought it was sufficiently Santa Fe style that he would want to make it Contributing, but it is not an exceptional building that we could make 47 years be 50 years. He recommended noncontributing due to its age.

Member Roybal agreed with Member Katz.

Member Guida countered that the Board is also making the point about the association with the architect. And it is the work of a significant architect. He recommended Contributing by association.

Member Flynn agreed with Member Guida that it is the work of a significant architect for an exception.

Public Comment

Mr. Eddy (previously sworn) asked if we could see the picture of the other façade.

He respectfully disagreed with Member Katz. This building makes a very strong impact on the streetscape. It really does exemplify what the architect is doing here with his design.

Ms. Roach showed the other façades.

Ms. Beninato (previously sworn) thanked the Staff for correcting that it is 48 years old. She understood the consistency with 50 years actual because the owner is likely to appeal.

This clearly embodies the Santa Fe style in vernacular design. It mimics one that was done by John Gaw Meem and she felt it was appropriate for it to be Contributing.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: **Member Guida moved, seconded by Member Flynn in Case #H-19-019 at 105 Camino Santiago, to designate the structure as Contributing with south façade primary because of association with Register and the quality of expression here that is clearly of Santa Fe Style.**

VOTE: **The motion resulted in a tie vote with Member Guida, Member Lotz and Member Flynn voting in favor and Member Katz, Member Biedscheid and Member Roybal voting against. Chair Rios voted in favor, breaking the tie. The motion passed by 4-3 voice vote.**

106 Camino Santiago: Likely the third unit to be constructed at Plaza del Monte, 106 Camino Santiago is a 2,031 square foot dwelling with a portal across two elevations (north and east). In plan, it has an L-shaped foundation with an attached carport. The flat-roof dwelling holds three bedrooms confined to a wing at the west end. The rear (south) elevation is focused on a small patio cut into the southwest corner of the home. The southeast corner is terminated by a one-space carport. The two-sided portal runs along the north and east elevations. The structure is made of vigas which sit on square girders held up by round posts with corbels. The portal elevations are painted white and fenestrated with doors on each exposure. Small rectangular windows penetrate the bedroom wing. The remaining windows vary, including large picture and grouped

casements and sliding units. The roof is finished with rolled asphalt which carries over the inner parapets. A squat stucco-faced chimney rises at the northeast corner. The house is finished with textured cementitious stucco in a light buckskin tone. The residence was constructed in c.1965. Its designer is unverified but is suspected to be an early Clark and Register design. Contributing status is recommended for this presently non-statused residence, as it may represent an original Clark and Register design template for Plaza del Monte, and the house is a good example of a mid-century expression of Santa Fe Style. If contributing status is assigned to the residence, the north and east facades are recommended as primary.

Ms. Roach added that the reasons for Contributing are in the report and the Board can just refer to those, if desired.

Board Discussion

Member Katz agreed with the Staff recommendation, "but looking at the photos, to have the historian say some are contemporary style and then say this is real Santa Fe style makes my head spin."

Member Larson described this as a modernist building and not contemporary. Contemporary is not even a relevant term.

Public Comment

There were no speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: **Member Biedscheid moved, seconded by Member Larson, in Case #H-19-019 at 106 Camino Santiago, to designate the property as Contributing with north and east façades as primary for reasons stated in the Staff report.**

VOTE: **The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.**

109 Camino Santiago: Composed of a series of angled walls, the carport dominated residence was constructed in 1966, after a design by architect Phillipe Register. The

house presents to the street a tall and wide carport framed with a viga roof. The west end of the carport is sheltered by a double splayed wall. The angled wall composition is echoed across the east elevation. In plan, the residence is roughly an L with its form obscured by the carport. The approximately 1,220 square foot dwelling holds two bedrooms in a cube-like mass anchoring the east end. Between the bedroom mass and carport is a small enclosed patio and portal sheltering the main entry and a pair of oversized wood windows. The rear (north) elevation has a small viga canopy protecting a patio door. A tapered chimney breaks the wall plane on this elevation. Fenestration consists of mainly aluminum windows. The frame structure is finished with cementitious brocade stucco in the buckskin tone. The contemporary style home was constructed in 1965 and is one of the earliest residences to be constructed in Plaza del Monte. The architectural historian recommends non-contributing status for this residence, due to its contemporary design which does not harmonize with the district. However, the Board may consider that its association with architect Phillipe Register and with the Plaza del Monte planned development could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the south façades are recommended as primary.

Public Comment

Mr. Eddy (previously sworn) thought the south façades should be primary. In the bottom photo, Staff referred to it as a viga roof.

Ms. Roach said it is a viga canopy.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Ms. Roach said there are multiple façades on the south and wanted to verify.

Action of the Board

MOTION: Member Guida moved, seconded by Member Katz, in Case #H-19-019 at 109 Camino Santiago, to give the structure a Contributing status with south facing façades 1, 2, 3, 4, and 5 as primary.

He did not agree with John Murphy recommendations and saw this as one of the best examples of his work.

Member Larson added that the original features are still featured such as carport and that adds to the reasons why it is contributing.

VOTE: The motion passed by majority (5-1) voice vote with Members Biedscheid, Katz, Guida, Larson, and Lotz voting in favor, and Member Roybal voting against.

110/112 Camino Santiago: Located at the west end of the common area are two residential units which were joined together at some point after 1970. The older unit, addressed as 110 Camino Santiago, takes up the east end of the footprint. Constructed in c.1962, after a design by architect Kenneth S. Clark, it is roughly an L-shaped box with a rear portal and connected carport. The street facing façade (north) is defined by a small recessed entry. The remainder of the façade is divided into rectangular window openings holding sliding units. Smaller, rectangular sliding windows are applied across the east bedroom wing. A shallow portal runs across the rear (south) elevation historically leading to a single-space carport. The portal elevation is fenestrated with a patio door, sliding windows, and a louvered door leading to a utility room. The house is outlined by parapets and finished in buckskin cementitious stucco. It holds three bedrooms. Attached to the west end of the original Clark design is a post-1966 addition. Arranged at a lower height, the approximately 864 square foot appendage is a rectangular box with overhanging eaves and a porch. The addition, most likely designed by architect Philippe Register, introduces a contemporary vocabulary. A shallow overhang supported by squared rafters carries across the north and south elevations. Similar beams extend out from the west elevation to create the porch. A tall angular wall rising above the roofline defines its south edge. The addition is fenestrated with a few doors and square window openings, holding single-light metal casements. Most likely occurring with the addition, the carport was widened (or constructed anew) to hold two vehicles. Set back from the addition, the roughly 1,054 square foot structure is supported by a viga and post system. Due to substantial changes to the massing and appearance of the structure when two residences were combined and carport added and subsequently widened, noncontributing status is recommended for this residence.

Ms. Roach showed additional photos.

Board Discussion

Member Katz said, in looking at the two façades, the top was classic standard, but the bottom seems totally Santa Fe style.

Member Larson didn't see integrity but contemporary on the north façade, so she agreed with Mr. Murphy.

Public Comment

Mr. Eddy (previously sworn) thanked staff for the other photos. He agreed with

Member Larson that the north façade degrades the house. But all the others show interesting character strengthening a Contributing status. And the portal work is important. He would consider that Contributing, excluding the north elevation.

Mr. Ken Rawie, 112 Camino Matias, was sworn. He pointed out that most of the pictures are of 110 and not 112. There was no picture of 112 Camino Santiago - north and south. The bottom photo shows the background of the carport. The resident there moved out just recently.

Ms. Roach said 110 and 112 are joined physically, so there is only one status for both.

Chair Rios understood, but as Mr. Eddy pointed out, if it is made Contributing, The Board could identify non-historic façades.

Ms. Roach agreed - or designate primary excluding nonhistoric portions.

Member Biedscheid did not believe there were any nonhistoric portions.

Ms. Roach agreed but asked the Board to consider 110 and 112 as one structure though from two different architects and thinking about harmony that they would work.

Action of the Board

MOTION: **Member Biedscheid moved, seconded by Member Guida, in Case #H-19-019 at 110/112 Camino Santiago, to designate 110/112 as Contributing because it has the original footprint and the alterations are historic, because it is associated with Register and recommended that the south and west façades be designated as primary.**

VOTE: **The motion passed by majority (5-1) voice vote with Members Biedscheid, Katz, Guida, Larson, and Lotz voting in favor, and Member Roybal voting against.**

111 Camino Santiago: Arranged at an east-west orientation, the house is a one-story, approximately 1,616 square foot, flat-roof dwelling erected in c.1965. The dwelling has an L-shaped plan with its two bedrooms confined to a rectangular wing at the west end. The remaining house holds the living room, kitchen and dining area. The front (south) façade is marked by a long portal which continues across to an attached one-bay carport. The portal shelters the front entry and a sliding patio door. The structure is supported by round poles holding a viga roof. The house is fenestrated with common windows, most of them appearing to be replacement units. It is entered through a raised

wood panel door flanked on one side by a sidelight. The rear (north) elevation contains a few windows and a door sheltered by a shallow viga-supported visor. A tapered chimney breaks through the visor, terminating with a terra cotta cap. The frame building is finished in a smooth cementitious stucco in a buckskin tone. The flat roof is covered with asphalt, which carries over the east exposure to the bedroom wing. While contemporary in form, the vigas used across the portal give the residence a Spanish-Pueblo Revival feel. The placement and restrained size of the carport helps maintain the regional tradition. The building was constructed after a design by architect Phillipe Register. Contributing status is recommended for this structure, as it represents an original design template by Clark and Register for Plaza del Monte and because it is an example of mid-century expressions of Santa Fe Style. If the Board finds this structure to be contributing, the south façade is recommended to be primary.

Member Guida saw that this is virtually the same as 103.

Ms. Roach agreed.

Public Comment

Mr. Eddy (previously sworn) pointed out the sidelights on the entry door. He would like to see it contributing because that angled element contributes greatly to the whole development.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: **Member Katz moved, seconded by Member Larson, in Case #H-19-019 at 111 Camino Santiago, to assign Contributing status for reasons in the Staff report and designating the south façade as primary.**

VOTE: **The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.**

113 Camino Santiago: Sitting on a slight rise, the house shares a party wall at the carport with its neighbor at 115 Camino Santiago. The roughly 1,281 square foot dwelling contains two bedrooms arranged at the front of the structure in a small L-shaped volume. The remainder of the footprint holds the living functions of the house. It presents to the street two room block-like volumes penetrated by horizontally oriented

aluminum casement windows. A viga-framed carport and short portal terminate the west end of the footprint. The house is entered through a raised wood panel door with a center view light. The rear (north) elevation has a few windows and a sliding glass door. A shallow overhang supported by square wood beams carries across the elevation. The frame dwelling is finished in cementitious peach color stucco worked into a brocade pattern. Tall parapets outline the perimeter of the bedroom wing. The roof is covered in asphalt which carries over the west exposure of the bedroom mass. It was erected in c.1970, and its designer/architect is unknown. Noncontributing status is recommended for this structure due to its age slightly under 50 years. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the south façades are recommended as primary.

Board Discussion

Member Larson disagreed with historian evaluation. She believed it is contributing for mid-century modern and, in comments, the flagstone is very characteristic.

Ms. Roach noted in looking at it and previous action on 110/112 - that 113 and 115 are actually joined, as well. Each footprint is quite distinct. Jointed by a party wall. So you might assign status to the structure as a whole.

Member Guida said, at 115, he would argue in favor of considering duplexes as one.

Ms. Roach said the description of 115 is almost identical and the rec was the same - slightly under 50 years as the primary reason for noncontributing status. Otherwise is almost identical.

115 Camino Santiago: Sharing a wall with the dwelling to the east (113 Camino Santiago), the small house contains two bedrooms. The dwelling portion of the building is composed of a rectangular bedroom wing. Attached to this are the living room, kitchen, and a one-space carport. Connecting these elements is a beam portal. Together, both areas hold about 1,290 square feet. The front (south) façade presents a simple canvas of a projecting mass balanced on one end with the void of the carport at the other. In between is the portal with its few window and door openings. The portal is supported by double round posts topped with corbels. The rear (north) elevation contains a few windows and a sliding glass door sheltered by a shallow viga-supported overhang. The windows in the residence are tall, single-light aluminum casements. A raised panel-and-view-light door gives entry to the dwelling under the portal. Short parapets outline the perimeter of the bedroom wing. The roof's asphalt material carries over the east exposure of the parapet. The house was erected in c.1970, and the designer/architect is unknown. Noncontributing status is recommended for this structure

due to its age slightly under 50 years. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the south façades are recommended as primary.

Member Biedscheid asked if they were constructed together.

Ms. Roach thought so.

Public Comment (on 115)

Mr. Eddy (previously sworn) considered 113 and 115 as one structure. He was pleased with term "party wall" which is really applicable here and he would like to see them considered as one.

Ms. Pryor (previously sworn) said, in looking at the construction date on the report, that "c" means around or circa. On the second amendment by Murphy, it looks like, and he states there that 113 is c 1970 and doesn't appear on the 1969 aerial. So he thought it was built in 1970 because it did not show up on the aerial, but it is pretty close.

Ms. Roach showed added photos - first of 113.

Mr. Eddy pointed out on the east elevation, that it showed a vertical fenestration on the windows which was a prominent element in the big Casa Grande that was demolished. That was a classic element in that building and replicated here.

Member Guida commented this as very interesting, with buildings very close and massing for four units with a slight variation.

Member Katz thought this was approximately 50 years old.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: Member Guida moved, seconded by Member Larson, in Case #H-19-019 at 113/115 Camino Santiago, to designate them Contributing with south facing façades as primary.

VOTE: The motion passed by majority (4-2) voice vote with Members Katz, Guida, Larson, and Lotz voting in favor, and Members Biedscheid

and Roybal voting against.

Ms. Roach asked for reasons to be included.

Member Guida said it is approximately 50 years old and represents mid-century Santa Fe style and is the work of Clark and Register.

Member Larson added that it exhibits character-defining features of the flagstone paving to the carport and the vertical divided windows.

Ms. Roach added that it has block massing on both sides.

Member Katz added that the aerial photograph was from February 1969, so it was probably being built in 1969.

114 Camino Santiago: The house presents to Camino Santiago a traditional design of a cube-like mass projecting from a linear arm. In plan, it is roughly L-shaped with a large connecting carport attached to its southeast corner. The west end holds two bedrooms; the remainder of the footprint contains a large living room, kitchen and utility closet. The south exposure of the bedroom wing is penetrated by sliding glass doors. East of the bedroom wing, the front façade (north) is divided into a recessed entry and a large casement-framed picture window. The entry holds a raised square panel wood door with center view light. It is sheltered by a short overhang resting on vigas. A similar combined picture and casement window is found on the east elevation of the living room. The carport makes up most of the secondary street elevation (north, set back). It is supported by a wood viga-and-post system. The structure shelters a patio door and single raised panel wood door leading to the utility room and storage area. Wood, trough-like canales penetrate the parapets on the east and west elevations. The roof is covered in rolled asphalt, which carries over the bedroom wing's east exposure. A short stucco-clad chimney topped with a terra cotta cap rises from the center of the roof. Erected in c.1972, the residence was designed by Register, Ross & Burnett Architects. Noncontributing status is recommended for this structure due to age. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the north façades are recommended as primary.

Member Larson said, although under the 50-year rule, we see the same elements repeated and the picture window, which is one example of mid-century modern and she would recommend contributing.

Public Comment

Mr. Eddy (previously sworn) pointed out an element that recurs in these buildings and Register's work. It is the use of double and triple posts under corbels and he assumed it was Mr. Register's innovation that probably was controversial.

He added, "When my father did a remodel of our house on Camino del Monte Sol, he did that too. So it really stuck as an innovation and adds to our vernacular style over time."

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Ms. Roach showed photos of the north, street-facing and east side containing the portal feature.

Member Larson appreciated Mr. Eddy pointing that out.

Action of the Board

MOTION: Member Larson moved, seconded by Member Guida, in Case #H-19-019 at 114 Camino Santiago, to designate the structure as Contributing because of mid-century modern exhibited through picture window and carport and designate north and east as primary.

Discussion on the Motion

Ms. Roach said the south elevation contains the picture window and the east.

Mr. Rawie clarified, as the next-door neighbor, that the north façade is on Camino Santiago and the east façade is facing Camino Matias. So the bottom photo with picture window is on the east side and the top picture is the north side.

Member Roybal commented that we are really pushing the 50-year rule on this house.

Member Biedscheid thought the Board should have justification for the age.

Member Larson argued that this exception is in character-defining features such as picture window, car port and double posts.

VOTE: The motion resulted in a tie vote with Member Larson, Member Guida, and Member Lotz voting in favor and with Member Roybal,

Member Katz and Member Biedscheid voting against. Chair Rios voted in favor, breaking the tie. The motion passed by 4-3 voice vote.

117 Camino Santiago: Tucked into the northwest corner of the development, the house is a single-story, flat-roof dwelling characterized by its viga carport and continuous overhang. In form, its two box-like volumes are arranged in a modified L-plan. The house holds two bedrooms slung along the west wall. A large living room occupies the foot of the L. With its carport included, the house contains 1,422 square feet. The unarticulated flat front façade is penetrated by non-historic casement windows. A wood panel and view light door gives entry to the dwelling under the front portal. The rear (west) elevation is fenestrated with an asymmetrical pattern of tall aluminum casement windows. The frame building is finished with brocade-type stucco rendered in the buckskin color. It was constructed in 1966-67, after a design by architect Philippe Register. Window replacements appear to have removed the pedimented heads shown on Register's drawings. Noncontributing status is recommended due to contemporary design that the architectural historian did not feel harmonized with the district. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the east (street-facing) façades are recommended as primary.

Ms. Roach said this building has an interesting modified L plan on an angle, not 90 degrees.

Public Comment

Mr. Eddy (previously sworn) said it is not truly an L-shape but a deliberate statement of the architect whether to the landscape or the way it fits but makes for an interesting house. The viga canopy in the lower photo contributes to the neighborhood architecturally.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Board Discussion

Ms. Roach believed the lower photo was the rear elevation and the upper was of the east façades #1 and #2. The recommendation for primary is 1 and 2 on the east. The south is 7, if the Board wants more carport.

Member Guida thanked Mr. Eddy for pointing out the modified L. While it is not the most beautiful or compelling design, it is interesting to look at the development as kind of laboratory. As a consequence, we have a span of how the architect figured it out and particularly one who is exploring what is possible with the limitations in Santa Fe. So a really compelling example of Santa Fe style. Not the prettiest but important.

Member Larson said the new windows diminish the character. But thanks to Mr. Eddy for pointing out the boomerang shape. In the aerial view you can see it is quite specific and balancing with the landscape. That would necessitate Contributing status.

Action of the Board

MOTION: **Member Guida moved, seconded by Member Biedscheid, in Case #H-19-019 at 117 Camino Santiago, to designate the structure as Contributing with the east façade as primary for the reasons in the Staff Report, that it is a significant expression of mid-century design and that it contributes to the plaza complex.**

Member Biedscheid requested the south façade to be primary to capture the carport (#7). Member Guida accepted the amendment as friendly.

VOTE: **The motion passed by majority (5-1) voice vote with Members Biedscheid, Katz, Guida, Larson, and Lotz voting in favor, and Member Roybal voting against.**

118 Camino Santiago: Erected in c.1973, the stucco-over-frame, two bedroom house sits on a rise at the southeast corner of Camino Santiago and Camino Matias. In plan, it is a modified L shaped structure with a carport attached to its front (north) façade. The roughly 1,245 square foot dwelling has its bedrooms segregated to a wing across the west elevation. This volume is taller than the rest of the house and is outline with parapets. The lower volume contains a living room, kitchen and dining area. The north (front) façade is divided between the carport and the north face of the bedroom wing. The single carport is erected over a wood structure supported by round posts. The outside beam continues across the façade, sheltering the front entry. As with the door under the carport, the entry holds a raised square panel unit. The secondary elevations are fenestrated with single-light metal casement windows. The south (rear) elevation has an array of casement windows and an enclosure giving access to the carport. A shallow overhang resting on vigas outlines the elevation. The house is finished with cementitious brocade stucco in a peach pigment. The roof is covered with rolled asphalt, which carries over a portion of the bedroom wing's east exposure. Large, trough-like wood canales pierce the west parapet. It was designed by Register, Ross & Burnet Architects, and is one of the last houses to be completed in Plaza del Monte. Noncontributing status is recommended for this residence by the architectural historian,

due to age. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the north façades are recommended as primary.

Member Larson asked if it is a planter in the bottom photo.

Ms. Roach believed so.

Member Larson thought since it is a last completion, it is an evolution and she had not seen a planter. That planter does harmonize with the landscape.

Member Katz did not think it is of exceptional importance. It should be part of the compound, but he did not see it as very special. It fits in but is not the Guggenheim Museum.

Mr. Gemora believed they had planters on Camino Matias.

Public Comments

There were no speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: **Member Katz moved, seconded by Member Roybal, in Case #H-19-019 at 118 Camino Santiago, to designate the structure Non-Contributing.**

VOTE: **The motion resulted in a tie vote with Member Roybal, Member Katz and Member Biedscheid voting in favor and Member Lotz, Member Larson and Member Guida voting against. Chair Rios voted in favor, breaking the tie. The motion passed by 4-3 voice vote to designate 118 Camino Santiago as Non-contributing.**

119 Camino Santiago: Arranged slightly above grade, the box-like house is characterized by its continuous portal and horizontal emphasis. In plan it is a compact rectangle framed by angled walls on its north and south exposures. Large windows, a wood panel door and a three-panel sliding glass door appear on the front (east) façade. The rear (west) elevation has double sets of sliding windows and a patio door arranged under an overhang. The house's windows appear to be mostly replacement units. The

south end of the dwelling is weighted with a large carport. A tall double splayed wall creates the south exposure. The portal is supported by vigas resting on a square beam. Round posts topped with double ended corbels carry the weight to the floor. The roughly 1,485 square foot structure contains two bedrooms placed along the west wall. The building was constructed in c.1965, after a design by architect Phillipe Register. The main alteration is the removal of most of the angled wall along the northeast corner. Originally, this feature enclosed a small patio. Noncontributing status is recommended for this structure due to contemporary design that the architectural historian did not feel harmonized with the district. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the east (street-facing) façade is recommended as primary.

Chair Rios noted this one is 54 years old.

Member Guida said this is an exceptional one in the community and echoed what we say with 109 in plan. And in particular, it is an expression of long and low with carport and it projects across the front of the house.

Member Larson pointed out that they used a lower wall along the front to shelter the entryway and that is characteristic of mid-century and also a shelter. So it is part of Santa Fe style and mid-century modern.

Public Comment

Mr. Eddy (previously sworn) mentioned for the record in previous testimony that the Presbyterian organization, in planning these structures for residents, gave input on what they wanted to see in the house. So it was a contributing element at the patio wall and might have been the case here.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: **Member Guida moved, seconded by Member Biedscheid, in Case #H-19-019 at 119 Camino Santiago, to designate it Contributing with east (#1) and south (#4) as primary elevations. It is more than 50 years old and represents a clear expression of mid-century modern architecture.**

Member Biedscheid added that the east façade has a low projecting viga element.

Member Larson said the wall in front of the entry is part of the façade and significant in design.

Member Guida accepted both statements as friendly.

VOTE: **The motion passed by majority (5-1) voice vote with Members Biedscheid, Katz, Guida, Larson, and Lotz voting in favor, and Member Roybal voting against.**

120 Camino Santiago: The small two bedroom house presents a contemporary carport-dominant design. Located along the east side of Camino Santiago, it sits back from the street. In plan, it is a modified T form with an attached carport projecting from the front (west) façade. Its two bedrooms are confined to a wing making up the north elevation. Higher than the rest of the house, it is outlined with shaped parapets. The parapets are pierced with canales across the north and south exposures. The lower volume, historically containing a living room, kitchen and music room, is faced with a shallow overhang resting on vigas. The overhang shelters sliding glass doors, a window and a pedestrian entry. The secondary elevations are fenestrated with aluminum casement windows. The front (west) elevation is dominated by the carport. The structure is erected over a viga-and-post support system. The portal's outside beam continues across the façade, sheltering the front (west) entry. A wood raised square panel door with a center view light gives entry to the residence. Including its carport and utility room, the building contains 1,804 square feet. The house was built in c.1971 after a design by Register, Ross & Burnet Architects. Noncontributing status is recommended for this structure due to age. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the west (street-facing) façade is recommended as primary.

Chair Rios considered it nonconforming and noncontributing.

Member Guida highlighted the carport and outdoor storage rooms as period-defining elements.

Public Comment

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: **Member Biedscheid moved, seconded by Member Roybal, in Case #H-19-019 at 120 Camino Santiago, to designate the property Non-contributing, based on its age.**

VOTE: **The motion failed (3-4) with Members Larson, Guida, Biedscheid and Chair Rios voting no.**

MOTION: **Member Guida moved, seconded by Member Larson, in Case #H-19-019 at 120 Camno Santiago, to designate the property as Contributing because it presents a clear expression of mid-century modern style with carport, storage rooms and overall massing and is approximately 50 years of age, and designating the west facing façades #1 and #2 as primary.**

VOTE: **The motion resulted in a tie vote with Member Guida, Member Larson and Member Lotz voting in favor and Member Roybal, Member Katz and Member Biedscheid voting against. Chair Rios voted in favor, breaking the tie. The motion passed by 4-3 voice vote.**

121 Camino Santiago: Reflecting a carport-dominant design, the small vernacular dwelling sits at grade on the west side of Camino Santiago. The roughly 1,309 square foot structure holds one bedroom. In plan, it is a compact square enclosed by an angled wall across its south exposure. Unlike most units in Plaza del Monte, it has a low pitched roof. The front (east) façade is dominated by the one-vehicle carport. The remainder of the façade is divided into windows and doors. The windows are uniformly multi-light steel casements in various standard sizes. The gabled north elevation has three identical windows. The rear (west) side of the house has more articulation, expressed through its beamed canopy over a pair of sliding doors. The frame house is finished with heavy brocade cementitious stucco in a peach like color. A shallow square-beam supported overhang runs along the east and west elevations. It was constructed in c.1971, after a design by Register, Ross & Brunet Architects. Noncontributing status is recommended for this structure due to age and contemporary design that the architectural historian did not feel harmonized with the district. However, the Board may consider that its association with the Plaza del Monte planned development and its design as a mid-century expression of Santa Fe Style could constitute "exceptional importance" such that contributing status may be warranted. If contributing status is assigned, the east (street-facing) façade is recommended as primary.

Member Roybal was concerned with this recommendation. We are really pushing the 50-year rule.

Member Larson noted the casement windows with three divisions are really unique and she has only seen them twice - just to take note of that.

Public Comment

Ms. Pryor (previously sworn) said this house is not one big room. It has an extra room that might be a library, a den or a music room.

Ms. Roach showed the south elevation and the low angled pitched roof, and the west elevation.

Mr. Eddy (previously sworn) pointed out the storage cabinets within the car port we've seen before.

Member Larson noted the south elevation with the portal is a theme repeated throughout town and is an interesting feature to take into account.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: Member Katz moved, seconded by Member Biedscheid, in Case #H-19-019 at 121 Camino Santiago, to designate the property Non-contributing because of its age.

VOTE: The motion failed (3-4) with Members Larson, Guida, Lotz and Chair Rios voting no.

Chair Rios asked for another motion.

MOTION: Member Larson moved, seconded by Member Guida, in Case #H-19-019 at 121 Camino Santiago, for Contributing status with east (#1) and south (#4) façades as primary. This is an exception to the 50 - year rule because of exceptional design as mid-century, use of casement windows, and storage features reflecting the era and its association Register.

VOTE: The motion resulted in a tie vote with Member Guida, Member Larson and Member Lotz voting in favor and Member Roybal, Member Katz and Member Biedscheid voting against. Chair Rios voted in favor, breaking the tie. The motion passed by 4-3 voice vote.

104 Camino Matias: One of the first units to be constructed at Plaza del Monte, 104 Camino Matias is an L shaped dwelling with a combined carport and portal. The approximately 1,143 square foot, flat roof structures holds two bedrooms. The bedrooms are placed in a wing forming the north end of the residence. Its front (west) façade presents a Spanish-Pueblo Revival plan, with its cubic, battered mass and viga roofed portal. Unlike many houses in the development, the carport plays a secondary role on the façade. The single-bay structure, arranged behind the portal, is less exuberant in its display of wood elements. The bedroom mass is fenestrated with small, rectangular windows; the remaining elevations have windows arranged in a more traditional pattern. The windows are mostly aluminum casement units. The portal elevation is painted white. A line of vigas runs along the top of the wall. It is supported by shiplap wood girders resting on round posts with corbels. The house was constructed in c.1965. It represents the closest interpretation of the original 1960 Kenneth S. Clark and Phillipe Register template design for the development. Contributing status is recommended for this residence, due to its early date of construction and representation of the original Clark and Register design template for Plaza del Monte retirement homes and due to its exemplary expression of mid-century Santa Fe Style. The west façades are recommended as primary.

Public Comment

Mr. Eddy (previously sworn) said, although it appears unremarkable, it is very important that it represents the original template from which the others grew.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Ms. Roach corrected that the front façade may be misrepresented. It is #1, for the front and façades on Camino Matias (Northwest). It is shown correctly on page 32 of the packet.

Action of the Board

MOTION: **Member Katz moved, seconded by Member Roybal, in Case #H-19-019 at 104 Camino Matias, to designate the property Contributing for reasons stated in the report and with façade #1 as primary.**

Member Biedscheid asked for #4 to also be primary as unique to the property. Member Katz accepted #4 as primary.

VOTE: The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.

105 Camino Matias: This small house is one of three units constructed in 1950 for married staff employed by the Allison James School. Arranged in a terrace-like fashion, each unit is a rectangular plan, side-gabled dwelling with an attached garage. The house has a telescoping roof form evident in its north exposure. The roof extends over the walls on the north and south elevations to form small porches. The house is fenestrated with a mix of original and non-historic windows and doors. The windows are terminated with stuccoed concrete sills. Views from the house are oriented north toward the commons area. The north elevation contains a large picture window flanked by casements. Public entry is through an original ½-glass wood door on the south elevation. The garage door is a recent vinyl paneled unit. The roof is covered with three-tab asphalt shingles. Wood fascia has been applied to the north and south roof ends, obscuring (or removing) the original exposed rafters. A short stuccoed chimney rises from the north roof slope. The approximately 1,102 square foot house holds three bedrooms. A non-historic, 220-square foot carport has been erected over the driveway. Non-contributing status is recommended for this structure. As the architectural historian states, the house neither harmonizes with the district nor with Plaza del Monte and includes non-conforming elements such as corner windows and cantilevered canopies over entries. Its association is with the Allison James School (demolished in 1960) rather than with Plaza del Monte. Staff agrees with this assessment.

Member Guida said this one and the next few properties are all associated with the school. He asked if that was correct.

Ms. Roach explained that 105, 107 and 109 Camino Matias are associated with the Allison James School, but 111 was moved to this site prior to 1960 and is not part of the same construction episode.

116 and 120 Camino Santiago were also associate with the school but later in 1957.

Member Katz considered this property a tough one. They have a similar history with the Presbyterian school and were incorporated. It maybe is not the same style but shows the history.

Member Larson appreciated seeing this in the neighborhood that showed the immediate style - much simpler and vernacular from the others. But she was not seeing character-defining elements here. So she recommended Non-contributing status.

Member Biedscheid observed there is a mix of original windows. It is an anchor for the compound around green space. And associated with the Presbyterian Church to provide living facilities and she thought it should be Contributing.

Member Guida said one strong argument is the stature of the architect and quality of design on Camino Santiago. On declining blocks and post war architecture. Its connection with Santa Fe Style is pretty weak and they don't read as connected with the rest of the development. It doesn't have all the points to make.

Public Comment

Ms. Pryor (previously sworn) said, according to her notes, they were all associated with Allison James teachers. She asked that the Board consider that association. It is what these houses represent. When they were here, those other houses were not built and their front porch was on the north-facing side, not the street-facing side.

Mr. Eddy (previously sworn) had to agree with all that has been said. They are conflicting but the points of view are valid, and the historicity is what is important. They are associated with Allison James School and what detracts are the alterations. The footprint and pitched roofs are important. It is the pitched roofs here that are important and derivative of the pitched roof of the Allison James School. So he recommended Contributing with their historicity and association with the school and he stated for the record that these other photos show a lot more character to be explored.

The Presbyterian organization was important for Santa Fe and throughout northern New Mexico which has a very detailed history in Chimayo.

Ms. Carol Rawie was sworn and mentioned "As you can see from the map. the façades on the green area is what you see when you walk around from Bishop's Lodge Road and what most people see, which is different than along the alley in the back."

Chair Rios did not think those were meant to have Santa Fe style.

Member Larson agreed. "After seeing more images, I agree that this style - they were just trying to do it as part of the school."

Action of the Board

MOTION: **Member Biedscheid moved, seconded by Member Katz, in Case #H-19-019 at 105 Camino Matias, to designate it as Contributing, based on age of the structure and the defining character of concrete sills, pitched roofs, windows and orientation as reference points to streets and spaces and with the north façade as primary.**

Member Katz added that it clearly is not Santa Fe style but an important historic style for this area and the history of it.

Member Biedscheid mentioned association with Allison James School.

VOTE: The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.

107 Camino Matias: This small house is one of three units constructed in 1950 for married staff employed by the Allison James School. Arranged in a terrace-like fashion, each unit is a rectangular plan, side-gabled dwelling with an attached garage. The gabled roof extends over the walls on the north and south elevations to form small porches. The dwelling is fenestrated with a mix of original and non-historic windows, terminated with stuccoed concrete sills. Views from the house are oriented north towards the commons area of Plaza del Monte. The north elevation contains a large picture window flanked by casements. Public entry is through an original ½-glass wood door on the south elevation. Two vertical [solar?] panels have been applied to the south façade. The garage door is recent vinyl paneled unit. The roof is covered with three-tab asphalt shingles. Wood fascia has been applied to the north and south roof ends, obscuring (or removing) the original exposed rafters. A short stuccoed chimney rises from the north roof slope. The house originally had an exposed pedimented entry on the north elevation, which was reduced at some point in depth after 1969. The approximately 1,145 square foot house holds two bedrooms. As the architectural historian states, the house neither harmonizes with the district nor with Plaza del Monte and includes non-conforming elements such as corner windows and cantilevered canopies over entries. Its association is with the Allison James School (demolished in 1960) rather than with Plaza del Monte. Non-contributing status is recommended for this structure, and staff agrees with this assessment.

Public Comment

There were no speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: Member Biedscheid moved, seconded by Member Guida, in Case #H-19-019 at 107 Camino Matias, to designate it Contributing. based on its association with Allison James School, pitched roof, concrete sills and large picture window similar to 105 and 109 Camino Matias, with the north façade as primary.

VOTE: **The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.**

109 Camino Matias: This small house is one of three units constructed in 1950 for married staff employed by the Allison James School. Arranged in a terrace-like fashion, each unit is a rectangular plan, side-gabled dwelling with an attached garage. The house has a telescoping roof form evident in its north exposure. The roof extends over the walls on the north and south elevations to form small porches. The front (south) façade reveals an altered composition. At some point after 1960, a 131 square foot addition was appended to the southwest corner creating a sunroom. The dwelling is fenestrated with a mix of original and non-historic windows, which are mostly double hung sash and are terminated with stuccoed concrete sills. Views from the house are oriented north toward the Plaza del Monte commons area. The north elevation contains a large picture window flanked by casements. Public entry is through an original ½-glass wood door on the south elevation. The garage door is a recent vinyl paneled unit. The roof is covered with three-tab asphalt shingles. Wood fascia has been applied to the north and south roof ends, obscuring (or removing) the original exposed rafters. A short stuccoed chimney rises from the north roof slope. The approximately 1,141 square foot house contains two bedrooms. As the architectural historian states, the house neither harmonizes with the district nor with Plaza del Monte and includes non-conforming elements such as corner windows and cantilevered canopies over entries. Its association is with the Allison James School (demolished in 1960) rather than with Plaza del Monte. Non-contributing status is recommended for this structure, and staff agrees with this assessment.

Public Comment

Mr. Eddy (previously sworn) suggested Contributing except for the addition on the south elevation.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: **Member Larson moved to designate the property as Contributing due to age of building, association with Allison James School and primary be the #4 - north front of the building, and on the south - 1 and 2.**

The motion died for lack of a second.

MOTION: **Member Biedscheid moved, seconded by Member Larson, in Case #H-19-019 at 109 Camino Matias, to designate the structure as Contributing, based on age, character of pitched roof, sills, association with Allison James and with the north façade as primary.**

Member Larson added the casement windows as character-defining.

VOTE: **The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.**

111 Camino Matias: Moved to the site prior to 1960, 111 Camino Matias is an altered three bedroom house. The house is arranged on a north-south axis, facing west, and in plan consists of two telescoping gabled sections. To this basic form was added an L-shaped porch and connected carport in c.1966. The medium pitch roofs are covered with asphalt shingles and extended with overhangs. A short stuccoed chimney rises from the ridgeline. Small wood louvers are attached to the gabled ends. The house is fenestrated with an array of original and non-historic windows, recessed from the walls and terminated with concrete sills. The combined porch and carport are supported by a framework of wood girders resting on grouped square posts. The single carport includes double storage units. A short breezeway leads from the carport to a back door. The 1,712 square foot house is finished with textured cementitious stucco in a light buckskin color. Non-contributing status is recommended for this residence. It was moved to the site before 1960 and extensively modified in 1966 with the addition of the carport and portal. As with the other Allison James School-era residences on Camino Matias, the house neither harmonizes with the district nor with Plaza del Monte, and its association is with the Allison James School rather than Plaza del Monte.

Member Larson commented that moved structures are always tricky with many different angles. I am not sure where I stand. It exhibits characteristics that are interesting but not sure it needs to be contributing. I'd like to hear from others on it.

Public Comment

Mr. Eddy (previously sworn) said what is interesting is that the portals were added after it was moved here. He asked if this was the first iteration of double posts. He wondered if it was before Register got his license.

He pointed out that the roof line is classic northern New Mexico style. The other thing is the little storage cabinets under the portal. Could it be Philippe Register before he got his license.

Ms. Roach said they are post-1966 so he had his license then.

Mr. Eddy (previously sworn) felt they were interesting details there.

Ms. Pryor (previously sworn) stated that this was the Principal's house.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: **Member Biedscheid moved, seconded by Member Katz, in Case #H-19-019 at 111 Camino Matias, to make it Contributing with the west elevation and south as primary (front entire portal).**

VOTE: **The motion passed by majority (5-1) voice vote with Members Biedscheid, Katz, Guida, Larson, and Lotz voting in favor, and Member Roybal voting against.**

116/120 Camino Matias: The vernacular, two unit residence was erected before 1957 and modified nearly 30 years later with the addition of a cross-gabled entry. The combined residence is aligned along a north-south axis on the west side of Camino Matias. In plan, it is a side-gabled rectangle with a cross-gable appended to its northeast corner. The north unit (120) holds about 1,256 square feet with three bedrooms. A window wall spanning the northeast corner signals its contemporary design. The north elevation under the gable is marred by a c.1984 shed-roof structure enclosing the furnace and water heater. The front façade faces east and is dominated by the non-historic cross gable entry. A recessed entry at the south end leads to 116. The interior, encompassing approximately 939 square feet, is arranged like an apartment. A similar non-historic stuccoed enclosure around the furnace and water heater is attached to the south elevation. The rear (west) elevation of the combined units faces onto a common area. A continuous overhang characterizes this façade. It is penetrated with three sliding glass doors and a mixture of fixed and sliding windows of different sizes. The roof is sheathed with rib metal panels. It is unclear who designed the original house. The c.1984 addition of the cross gable and furnace and water heater enclosures was drawn in Phillipe Register's shop. Built prior to 1958 and substantially modified in the mid-1980s, the historic integrity of the house has been compromised, and the style of the home neither harmonizes with the district nor with Plaza del Monte. As with the other Allison James School-era residences on Camino Matias, the house neither harmonizes with the district nor with Plaza del Monte, and its association is with the Allison James School rather than Plaza del Monte.

Board Discussion

Member Larson would be interested in knowing the further association with the school. It is in harmony with 1950s.

Member Katz felt it was modified too much in 1980's to qualify for contributing.

Member Roybal agreed with Member Katz. The whole house seems out of character.

Public Comment

Ms. Pryor (previously sworn) said this was teacher housing and on the east side, there is a notice above the door that it was Auburn Cottage even though divided into two apartments.

Mr. Rawie clarified that it is two bedrooms, not three.

Mr. Eddy (previously sworn) was sorry we are at the end of this because it has been very enjoyable. He would encourage nonconforming or noncontributing because it does not have double posts.

There were no other speakers from the public regarding this case and the public hearing portion was closed.

Action of the Board

MOTION: **Member Katz moved, seconded by Member Larson, in Case #H-2019-19 at 116/120 Camino Matias to designate the property as Noncontributing due to 1980's modifications.**

VOTE: **The motion passed by majority (5-1) voice vote with Members Biedscheid, Katz, Guida, Lotz and Roybal voting in favor, and Member Larson voting against.**

Consideration of Compound Status:

MOTION: **Member Katz moved, seconded by Member Larson, in Case #H-19-019 at 101, 102, 103, 105, 106, 109, 110, 111, 113, 114, 115, 117, 118, 119, 120, 121 Camino Santiago and 104, 105, 107, 109, 111, 116/120 Camino Matias, to direct Staff to prepare an evaluation concerning compound status.**

Ms. Roach proposed a subcommittee of the Board should create the recommendation.

Chair Rios said no to a subcommittee.

Member Guida asked if it would come back as a case.

Ms. Roach believed it could.

Member Katz asked if it would be a recommendation to the Governing Body.

Ms. Roach said Staff could bring back an evaluation as Case #H-2019-19B.

VOTE: The motion passed by unanimous (6-0) voice vote with Members Biedscheid, Katz, Guida, Larson, Lotz and Roybal voting in favor and none voting against.

H. MATTERS FROM THE BOARD

Chair Rios thanked everyone for staying through this long meeting.

I. ADJOURNMENT

Having completed the agenda and with no further business to come before the Board, the meeting was adjourned at 10:16 p.m.

Approved by:

Cecilia Rios

Cecilia Rios, Chair

Submitted by:

Carl G. Boaz

Carl Boaz for Carl G. Boaz, Inc.

Subdivision Survey prepared for
Plaza Del Monte, LLC of
Tract B on Camino Santiago and Camino Matias, City of Santa Fe, NM

SUBDIVISION SURVEY ON TRACT B LAST DESCRIBED ON SURVEY FILED
IN SANTA FE COUNTY CLERK PLAT BOOK 785, PAGES 023–024, INSTRUMENT NO. 1759,727
SAID TRACT B LYING AND BEING WITHIN THE SANTA FE GRANT
PROJECTED SECTION 24, T17N, R9E, NMPM
TRACT B IS LOCATED ON CAMINO SANTIAGO AND CAMINO MATIAS IN THE CITY OF SANTA FE
COUNTY OF SANTA FE, STATE OF NEW MEXICO

THE PURPOSE OF THE IS PLAT IS TO SUBDIVIDE
TRACT B INTO 30 INDIVIDUAL LOTS

OWNERS CONSENT

THE UNDERSIGNED OWNER(S) DOES HEREBY CONSENT TO THE SUBDIVISION OF LANDS AS SHOWN HEREON. THIS SURVEY AND SUBDIVISION IS BEING MADE WITH THEIR FREE CONSENT AND IS IN ACCORDANCE WITH THEIR DESIRES AND WISHES. ALL EASEMENTS ARE HEREBY GRANTED AS SHOWN. THESE LANDS LIE WITHIN THE PLANNING AND PLATTING JURISDICTION THE CITY OF SANTA FE, STATE OF NEW MEXICO.

PLAZA DEL MONTE, LLC — DATE 10/4/22

STATE OF NEW MEXICO)
COUNTY OF SANTA FE) SS

THIS INSTRUMENT WAS ACKNOWLEDGED BEFORE ME ON OCTOBER 4, 2022 BY E. LARRY LUJAN

NOTARY PUBLIC Colleen C. Gavin MY COMMISION EXPIRES: October 8, 2023

COLLEEN C. GAVIN
Notary Public - State of New Mexico
Commission # 1127282
My Comm. Expires October 8, 2023

SURVEYORS NOTES

1. RECORD LOT DATA SHOWN HEREON TAKEN FROM THE RECORD SURVEY ENTITLED "LOT SPLIT OF SURVEY OF THE BOARD OF PENSIONS OF THE UNITED PRESBYTERIAN CHURCH U.S.A. CITY OF SANTA FE, NEW MEXICO", BY R.E. SMITH NMPS NO. 5837 AND SMITH WILLIAMSON & ASSOC., FILED ON MARCH 16, 1990, IN SANTA FE COUNTY CLERK PLAT BOOK 207, PAGE 035, AS INSTRUMENT NO. 701,830.

1. ADDITIONAL DATA TAKEN FROM THE RECORD SURVEY ENTITLED "ALTA/ACSM LAND TITLE SURVEY FOR CAUWELS & STUVE REALTY & DEVELOPMENT ADVISORS, LLC", BY PAUL A. ARMIJO NMPS NO. 13604 AND ARMIJO SURVEYS, INC., FILED IN THE RECORDS OF THE SANTA FE COUNTY CLERK, ON MARCH 17, 2015, IN PLAT BOOK 785, PAGES 023 & 024 AS INSTRUMENT NO. 1759,727.

2. THE HORIZONTAL BASIS OF BEARING FOR THIS 2021 SURVEY IS THE INVERSE BETWEEN THE LOT CORNER MONUMENTS FOUND AT THE NORTHWEST AND NORTHEAST CORNERS OF TRACT B AND REFERENCED TO THE RECORD BEARING S70°50'26"E 654.34'. MEASURED BY THIS 2021 SURVEY: S70°50'26"E 654.34'. SEE MAP FOR DETAILS.

3. DATES OF FIELD SURVEY: JUNE 14–16, 2021 AND JULY 6–9, 2021.

4. SPECIAL WARRANTY DEED. PRESBYTERIAN MEDICAL SERVICES TO PLAZA DEL MONTE LLC FILED ON MARCH 20,2015, AS INSTRUMENT NO. 1759,998.

5. SEE SHEET NO. 2 FOR SUBDIVISION SURVEY MAP.

UTILITY LOCATE DATA

1. UTILITY LOCATE: NM811 LOCATE REQUEST TICKET CONFIRMATION NO. 21JN230465. ORDER DATE: 06/23/2021.

SURVEYORS CERTIFICATION

I, PAUL A. ARMIJO, CERTIFY THAT I AM NEW MEXICO REGISTERED PROFESSIONAL SURVEYOR NO. 13604, AND THAT THIS PLAT WAS PREPARED BY ME OR UNDER MY DIRECTION AND IS BASED ON AN ACTUAL FIELD SURVEY PERFORMED UNDER MY DIRECTION IN JUNE–JULY, 2021 AND IS, TO THE BEST OF MY KNOWLEDGE AND BELIEF, CORRECT AND CONFORMS TO THE MINIMUM REQUIREMENTS OF THE STANDARDS FOR LAND SURVEYS IN NEW MEXICO AS ADOPTED BY THE NEW MEXICO STATE BOARD OF REGISTRATION FOR PROFESSIONAL ENGINEERS AND PROFESSIONAL SURVEYORS.

Paul A. Armijo OCT. 4, 2022
PAUL A. ARMIJO, N.M.P.S. NO. 13604

PAUL A. ARMIJO NEW MEXICO 13604 REGISTERED PROFESSIONAL SURVEYOR

VICINITY MAP–NOT TO SCALE



UTILITY COMPANY REVIEW

CITY OF SANTA FE WASTEWATER DEPARTMENT — 9-22-23 DATE

~~SANGRE DE CRISTO WATER COMPANY~~ CITY OF SANTA FE WATER DIVISION — 10-13-2022 DATE

PUBLIC SERVICE COMPANY OF N.M.–ELECTRIC — 09/19/2022 DATE

NEW MEXICO GAS COMPANY — 9/19/2022 DATE

QWEST CORP. d/b/a/ CENTURYLINK QC — 9/19/2022 DATE

XFINITY CABLE TV — 9/19/2022 DATE

PUBLIC UTILITY EASEMENTS

Public Utility Easements shown on this plat are granted for the common and joint use of:

A. Public Service Company of New Mexico corporation, (PNM Electric) for installation, maintenance, and service of overhead and underground electrical lines, transformers, and other equipment and related facilities resonably necessary to provide electrical services.

B. New Mexico Gas Company (NMGCo.) for installation, maintenance, and service of natural gas lines, valves and other equipment and facilities resonably necessary to provide natural gas services.

C. Lumen Technologies for the installation, maintenance, and srevice of such lines, cable, and other related equipment and facilities resonably necessary to provide communication services.

D. Xfinity &/or Lumen Technologies for the installation, maintenance, and service of such lines, cable, and other related equipment and facilities resonably necessary to provide Cable services.

E. City of Santa Fe (public water and private sewer) for the installation, maintenance, and service of lines and other equipment and facilities resonably necessary to provide services to Public Utility Easements. Included is the right to build, rebuild , construct, reconstruct, locate, relocate, within the easement, change, remove, replace, modify, renew, operate and maintain facilities for purposes described above, together with free access to, from, and over said easements, with the right and privilege of going upon, over and across adjoining lands of Granter for the purpose set forth herein and with the right to utilize the right of way and easement to extend services to costumers of Grantee, including sufficent working area space for electric transformers, with the right and privilege to trim and remove trees, shrubs, or bushes which interfere with the purposes set forth herein. No building, sign, pool (aboveground or subsurface), hot tub, concrete or wood pool decking, or other structure shall be erected or constructed on said easements, nor shall any well be drilled or operated thereon.

Easements for electric, transformers/switchgears, as installed, shall extend ten (10) feet in front of transformer/switchgearer doors and five (5) feet on each side.

F. QWEST CORP. d/b/a CENTURYLINK QC for installation, maintenance and service of all buried and aerial communication lines and other related equipment and facilities reasonably necessary to provide communication services, including but not limited to above ground pedestals and closures. This plat has been approved for easement purposes only. The signing of this plat does not in any way guarantee telephone services to the subdivision.

UTILITY DISCLAIMER

In approving this plat, Public Service Company of New Mexico (PNM) and New Mexico Gas Company(NMGC) did not conduct a title search of the properties shown hereon. Consequently, PNM and NMGC DO NOT waive or release any easement or easement rights which may have been granted by prior plat, replat or other document and which are not shown on this plat.

INDEXING INFORMATION FOR COUNTY CLERK
SFC ASSESSOR UPC NO. FOR TRACT B: 1–054–099–309–421
OWNER: PLAZA DEL MONTE LLC SPECIAL WARRANTY DEED, INSTRUMENT NO. 1759,998
LOCATION: TRACT B, PLAT BOOK 785, PAGES 023–024 LYING AND BEING SITUATE WITHIN THE SANTA FE GRANT PROJECTED SECTION 24, T17N, R9E, NMPM ADDRESS: CAMINO SANTIAGO AND CAMINO MATIAS CITY OF SANTA FE, COUNTY OF SANTA FE STATE OF NEW MEXICO

89[illegible]

ARMIJO SURVEYS INC
PAUL A. ARMIJO N.M.P.S. NO. 13604
P. O. BOX 24438, SANTA FE, NM 87502–9438
PH. (505) 471–1955 FAX. (505) 471–1925

SUBDIVISION SURVEY PREPARED FOR
PLAZA DEL MONTE, LLC
TRACT B, CAMINO SANTIAGO/CAMINO MATIAS, SANTA FE, NM

DRAWN BY P.A.A. — DATE JULY 2021
SURVEY NO. 2021158 — SHEET NO. 1 OF 3

CITY OF SANTA FE REVIEW

CITY PLANNER — 11/3/22 DATE

CITY ENGINEER FOR LAND USE — 11/3/22 DATE

PUBLIC WORKS DEPT. — 11/30/2022 DATE

COUNTY TREASURER — Oct. 6, 2022 DATE

CITY OF SANTA FE PLANNING COMMISION APPROVAL

CASE NO. 2021–4548

CASE NO. 2021–4549

APPROVED AT THEIR MEETING OF

PLANNING DIVISION CHAIR — 11/3/2022 DATE

PLANNING COMMISSION SECRETARY — 11/7/22 DATE

DEVELOPMENT NOTES:

1. PROPERTY DEVELOPMENT IS REQUIRED TO COMPLY WITH APPLICABLE PROVISIONS OF CHAPTER 14, LAND DEVELOPMENT CODE, SFCC 2001 AND SUBSEQUENT AMENDMENTS.

2. PROPERTY DEVELOPMENT IS REQUIRED TO COMPLY WITH THE PROVISIONS OF EACH CITY OF SANTA FE ORDINANCE ADOPTED PRIOR TO PLAT AND/OR DEVELOPMENT PLAN RECORDING WITH THE COUNTY CLERK OR SUBMITTAL FOR A BUILDING PERMIT APPLICATION THAT MODIFIES ANY PROVISION OF CHAPTER 14, LAND DEVELOPMENT CODE, SFCC 2001 AND SUBSEQUENT AMENDMENTS.

3. BUILDABLE AREA FOR VACANT PARCEL(S) WILL BE DETERMINED AT THE TIME OF BUILDING PERMIT APPLICATION AS DETAILED IN THE LAND DEVELOPMENT CODE. ANY BUILDABLE AREAS SHOWN HEREON ARE SUBJECT TO RELOCATION PER CODE REQUIREMENTS.

4. THE DEVELOPMENT SHALL COMPLY WITH THE MOST CURRENT REQUIREMENTS OF THE AMERICANS WITH DISABILITIES ACT (ADA) FOR ALL INFRASTRUCTURE IMPROVEMENTS.

5. THESE LOTS ARE SERVED BY A PRIVATE ON–SITE SEWER SYSTEM AND ARE SUBJECT TO THE AGREEMENT FOR MAINTENANCE OF SHARED PARKING, ACCESS EASEMENTS AND DRAINAGE FACILITIES RECORDED IN THE RECORDS OF SANTA FE COUNTY ON December 23, 2022, AS INSTRUMENT NO. 2003739

Document No. 2003738

COUNTY CLERKS INSTRUMENT BLOCK
COUNTY OF SANTA FE, STATE OF NEW MEXICO

I hereby certify that this instrument was filed for record on the 23 day of Dec A.D. 2022 at 9:30 o'clock A m, and was duly recorded in Book 898 Page 20-24 of the Records of Santa Fe County
Witness my Hand and Seal of Office
KATHERINE CLARK
County Clerk, Santa Fe County, New Mexico

DEPUTY

COUNTY CLERK SEAL

LOT	LOT AREA	ROOF AREA	COVERAGE
1	8,449 SF.	1,881 SF.	22%
2	6,946 SF.	1,664 SF.	24%
3	7,127 SF.	2,646 SF.	37%
4	7,716 SF.	2,662 SF.	34%
5	7,314 SF.	1,664 SF.	23%
6	8,719 SF.	1,650 SF.	19%
7	6,756 SF.	1,597 SF.	24%
8	6,777 SF.	1,621 SF.	24%
9	8,978 SF.	1,918 SF.	21%
10	13,549 SF.	2,002 SF.	15%
11	10,997 SF.	1,747 SF.	16%
12	12,385 SF.	1,935 SF.	16%
13	25,474 SF.	2,175 SF.	9%
14	12,915 SF.	4,463 SF.	36%
15	15,102 SF.	3,672 SF.	24%
16	8,819 SF.	1,895 SF.	21%
17	6,988 SF.	1,740 SF.	25%
18	9,337 SF.	1,781 SF.	19%
19	6,340 SF.	1,625 SF.	26%
20	8,112 SF.	1,764 SF.	22%
21	9,102 SF.	2,232 SF.	23%
22	9,552 SF.	2,678 SF.	28%
23	6,031 SF.	0 SF.	N/A
24	8,098 SF.	1,964 SF.	24%
25	8,058 SF.	2,079 SF.	26%
26	7,352 SF.	1,451 SF.	20%
27	6,658 SF.	1,435 SF.	22%
28	8,617 SF.	1,529 SF.	18%
29	9,601 SF.	1,825 SF.	19%
30	13,305 SF.	2,306 SF.	17%

BUILDING SETBACKS:

Front Yard Setback: 7 feet from edge of Access & Utility Easement.
Side Yard Setback: 5 feet from property line for Detached Homes; OR
0 feet from property line if adjacent setback is increased to 10 feet.
0 feet from property line for Attached Homes if fire-rated wall is provided.

Garage Setback: 10 feet from edge of Access & Utility Easement, for all lots
except Lot 28, where the setback shall be 8 feet from edge of Access & Utility Easement to accommodate an existing carport. If this carport is demolished, any new garage or carport shall conform to the 10-foot garage setback that applies to the Subdivision.

Rear Setback: 10 feet from property line.

8630021

SUBDIVISION PLAT
08/03/2022

ARMIJO SURVEYS INC.
PAUL A. ARMIJO N.M.P.S. NO. 13604
P. O. BOX 24438, SANTA FE, NM 87502-9438
PH. (505) 471-1955 FAX. (505) 471-1925

DRAWN BY _____ EXISTING DATA DATE MAR. 2015
JOB NO. N/A SHEET NO. N/A

SHEET 2 OF 3

NOTES:

1. DATA IN PARENTHESIS (R1-DATA) IS RECORD DATA TAKEN FROM REFERENCE DOCUMENT NO. 1 LISTED ON SHEET 1 OF THIS NEW SURVEY.
2. DATA SHOWN ON ADJOINING PROPERTIES IS BACKGROUND OR INFORMATIONAL IN NATURE AND IS NOT A SURVEY OF ADJOINING PROPERTIES.

LINE TABLE		
LINE	LENGTH	BEARING
L5	105.11	N42°37'05"W
L6	15.13	N69°14'53"W
L7	13.44	N76°09'41"W
L8	23.70	N76°09'41"W
L9	7.51	N76°09'41"W
L10	54.70	N73°58'41"W
L11	21.84	N73°58'41"W
L12	88.83'	N73°58'41"W
L13	43.53'	N72°23'21"W
L14	76.94'	N73°58'41"W
L15	36.17'	N73°58'41"W
L16	52.58	N73°58'41"W
L17	25.03	N73°58'41"W
L18	27.68	N74°44'35"W
L19	11.19	N74°44'35"W
L20	19.71'	S28°51'50"W
L21	5.85'	S28°51'50"W
L22	0.45'	S28°51'50"W
L23	25.92'	S28°51'50"W
L24	27.24	S28°51'50"W
L25	3.52'	S61°12'57"E
L26	3.51'	S28°47'03"W
L27	2.93	S28°47'03"W
L28	5.44	S14°12'51"W
L29	14.22'	S19°09'34"W
L30	7.53'	S01°25'41"E
L31	37.26'	S17°10'08"W
L32	11.14'	S39°38'13"W
L33	22.51'	S12°06'44"W
L34	23.96	N17°37'56"E
L35	10.93	N45°03'46"E
L36	6.70	N25°16'31"E
L37	76.91	N16°01'19"E
L38	47.34	S66°00'14"E
L39	5.47	S39°52'26"E
L40	18.17	S17°28'11"W
L41	64.85	N20°31'51"E
L42	4.87'	N89°22'53"W

CURVE TABLE					
CURVE	DELTA	LENGTH	RADIUS	CH. BEARING	CHORD
C5	6°42'09"	5.91	50.50	N45°58'09"W	5.90
C6	19°55'39"	17.56	50.50	N59°17'03"W	17.48
C7	6°54'48"	10.92	90.50	N72°42'17"W	10.91
C8	0°35'44"	10.39	1000.00	N74°16'33"W	10.39
C9	0°10'10"	2.96	1000.00	N74°39'30"W	2.96
C10	27°17'00"	23.81	50.00	N88°23'05"W	23.58
C11	23°04'32"	20.14	50.00	S66°26'09"W	20.00
C12	26°02'03"	22.72	50.00	S41°52'51"W	22.52
C13	26°01'12"	36.33	80.00	N41°52'26"E	36.02
C14	11°30'26"	16.07	80.00	N60°38'15"E	16.04
C15	30°16'51"	35.30	66.79	N60°12'12"E	34.89
C16	19°47'15"	29.82	86.35	N35°10'09"E	29.67
C17	0°45'19"	2.43	184.50	N24°53'51"E	2.43
C18	8°29'53"	27.37	184.50	N20°16'15"E	27.34
C19	26°07'48"	57.82	126.78	N52°56'20"W	57.32
C20	73°00'28"	105.53	82.82	S54°06'53"W	98.54
C21	24°13'38"	33.83	80.00	N78°30'18"E	33.58

EASEMENT KEY

(A) 10' WIDE WATERLINE EASEMENT MISC. BK. 176, PG. 027. CENTERLINE CALLS FROM SAID EASEMENT. EXCEPTION NO. 14.
EX. NO. 14.

(B) 10' WIDE GAS PIPELINE RIGHT OF WAY AND EASEMENT, MISC. BK. 206, PG. 429 CALLS FROM SAID EASEMENT EX. NO. 15.
EX. NO. 15.

(C) 5' WIDE UTILITY LINE EASEMENT MISC. BK. 253, PG. 647 EX. NO. 17
EX. NO. 17.

(D) INGRESS-EGRESS ACCESS EASEMENT ACROSS TRACT A FOR TRACT B
EASEMENT FILED AS INSTRUMENT NO. 1753,281
EX. NO. 11.
EX. NO. 11.

LINE DATA
L1-S40°05'42"E 24.80'
(RECORD DATA R1-S40°07'49"E 24.80')

SURVEY TIE LINE DATA:
T1: TIE-S84°20'21"E 18.39'

LEGEND

- SURVEY MONUMENT FOUND
- SURVEY MONUMENT 1/2" REBAR STAKE W/CAP STAMPED ARMIJO-13604
- SURVEY MONUMENT SET 1/2" REBAR STAKE W/CAP STAMPED ARMIJO-13604
- CACULATED POINT NOT SET
- SSMH SANITARY SEWER MANHOLE COVER
- LP STREET LAMP POLE
- UP UTILITY POLE
- UTILITY POLE WITH GUY WIRE ANCHOR
- UTILITY POLE WITH GUY WIRE ANCHOR
- EM ELECTRIC METER
- GM GAS METER
- WM WATER METER
- E ELECTRIC UTILITY MANHOLE
- T TELEPHONE UTILITY MANHOLE
- TP TELEPHONE UTILITY PEDESTAL
- E ELECTRIC JUNCTION BOX
- DI STORM DRAIN DROP INLET GRATE
- SW STUCCO WALL
- CS CRAWLSPACE ACCESS HATCH
- STOR. FREE STANDING STUCCO STORAGE BUILDING
- CARPORT ROOF CANOPY OR PORTAL ROOF CANOPY
- S70°50'26"E 654.34' NEW MEASURED DATA BY THIS NEW SURVEY
- (R1-S70°50'26"E 654.35') RECORD DATA BY OTHERS
- EX. NO. 11. NOTE TO TITLE COMMITMENT EXCEPTION NUMBER

HORIZONTAL SCALE: 1"=30'
30 15 0 30 60

PAUL A. ARMIJO NEW MEXICO 13604 REGISTERED PROFESSIONAL SURVEYOR
10-4-22

F:\RICK\1-PROJECTS\ARMIJO\PLAZA DEL MONTE\dwg\2022-08-03 PDM PLAT.dwg, SUBDIVISION PLAT, 8/3/2022 10:17:53 PM

DESCRIPTION OVERLAY
08/03/2022

ARMIJO SURVEYS INC.
PAUL A. ARMIJO N.M.P.S. NO. 13604
P. O. BOX 24438, SANTA FE, NM 87502-9438
PH. (505) 471-1955 FAX. (505) 471-1925

DRAWN BY _____ EXISTING DATA DATE MAR. 2015
JOB NO. N/A SHEET NO. N/A

SHEET 3 OF 3

EASEMENT KEY

(A) 10' WIDE WATERLINE EASEMENT MISC. BK. 176, PG. 021. CENTERLINE CALLS FROM SAID EASEMENT. EXCEPTION NO. 14. EX. NO. 14.

(B) 10' WIDE GAS PIPELINE RIGHT OF WAY AND EASEMENT, MISC. BK. 205, PG. 429 CALLS FROM SAID EASEMENT EX. NO. 15. EX. NO. 15.

(C) 5' WIDE UTILITY LINE EASEMENT MISC. BK. 253, PG. 647 EX. NO. 17 EX. NO. 17.

(D) INGRESS-EGRESS ACCESS EASEMENT ACROSS TRACT A FOR TRACT B EASEMENT FILED AS INSTRUMENT NO. 175,281 EX. NO. 11 EX. NO. 11.

HORIZONTAL SCALE: 1"=30'
30 15 0 30 60

NOTES:

1. DATA IN PARENTHESIS (R1-DATA) IS RECORD DATA TAKEN FROM REFERENCE DOCUMENT NO. 1 LISTED ON SHEET 1 OF THIS NEW SURVEY.
2. DATA SHOWN ON ADJOINING PROPERTIES IS BACKGROUND OR INFORMATIONAL IN NATURE AND IS NOT A SURVEY OF ADJOINING PROPERTIES.

LINE TABLE		
LINE	LENGTH	BEARING
L204	52.79	N28°51'50"E
L205	9.28	N28°51'50"E
L206	3.96	N72°22'04"W
L207	8.38	N72°22'04"W
L208	2.08	N33°43'06"W
L209	5.9	N33°43'06"W
L210	61.31	N63°11'34"W
L211	25.02	N28°51'50"E
L212	39.71	S63°11'34"E
L213	37.37	S49°56'25"E
L214	18.17	S17°28'11"W
L215	27.37	S63°11'34"E
L216	5.08	S33°43'06"E
L217	34.47	S72°22'04"E
L218	5.00	S16°33'15"W
L219	10.00	S16°33'15"W
L220	10.00	S16°33'15"W
L221	31.37	N72°22'04"W
L222	56.10	S72°22'04"E
L223	10.00	S17°37'56"W
L224	55.91	N72°22'04"W
L225	10.00	S17°37'56"W
L226	55.72	N72°22'04"W
L227	11.72	S14°12'51"W
L228	37.95	N72°22'04"W
L229	25.00	N17°37'56"E
L230	16.28	S72°22'04"E
L231	1.18	S15°59'24"W
L232	43.37	S17°28'35"W
L233	3.77	N68°31'49"W
L234	10.03	N68°31'49"W
L235	43.75	N17°12'31"E
L236	43.12	N17°12'31"E
L237	79.61	S17°28'35"W
L238	3.38	N72°31'25"W
L239	10.00	N72°31'25"W
L240	80.57	N17°12'31"E
L241	79.37	N17°12'31"E
L245	127.89	S17°26'39"W
L246	2.86	N72°23'21"W
L247	10.00	N72°23'21"W
L248	129.38	N17°12'31"E
L249	127.86	N17°12'31"E

CURVE TABLE					
CURVE	DELTA	LENGTH	RADIUS	CH. BEARING	CHORD
C1	34°06'47"	11.91	20.00	N35°53'17"E	11.73
C2	26°59'48"	46.09	97.82	S43°43'36"W	45.67
C3	30°07'23"	55.90	106.32	S75°18'36"W	55.26
C4	61°45'17"	70.06	65.00	N59°44'28"E	66.72
C5	28°53'13"	32.77	65.00	S43°18'27"W	32.43
C6	17°42'02"	20.08	65.00	S66°36'04"W	20.00
C7	29°48'20"	33.81	65.00	N89°38'45"W	33.43
C8	0°45'53"	13.55	1015.00	N74°21'38"W	13.55
C9	6°54'48"	12.13	100.50	N72°42'17"W	12.12
C10	17°35'01"	18.57	60.50	N60°27'22"W	18.49
C11	9°02'47"	9.55	60.50	N47°08'28"W	9.54
C12	25°30'46"	13.59	30.52	N07°06'45"W	13.48
C13	12°06'10"	8.92	42.24	N35°49'29"W	8.91
C14	98°09'31"	40.98	23.92	S85°00'40"W	36.15
C15	8°27'31"	29.45	199.50	N20°15'04"E	29.43
C16	0°47'41"	2.77	199.50	N24°52'41"E	2.77
C17	19°47'15"	35.00	101.35	N35°10'09"E	34.83
C18	33°14'35"	47.45	81.79	N61°41'04"E	46.79
C19	1°38'27"	2.20	76.79	N79°07'35"E	2.20
C20	27°50'49"	37.32	76.79	S86°07'47"E	36.96
C21	25°33'49"	20.30	45.50	S59°25'29"E	20.13
C22	15°31'22"	13.68	50.50	S38°52'53"E	13.64
C23	17°55'34"	15.80	50.50	S22°09'25"E	15.74
C24	23°54'25"	18.99	45.50	S02°15'38"W	18.85
C25	60°05'13"	20.45	19.50	N15°49'45"W	19.53
C26	28°08'19"	12.02	24.50	N59°55'32"W	11.90
C27	0°36'23"	10.48	990.00	N74°16'53"W	10.48
C28	0°09'31"	2.74	990.00	N74°39'49"W	2.74
C29	76°23'35"	53.33	40.00	S67°03'38"W	49.47
C30	1°49'20"	2.87	90.17	N29°46'36"E	2.87
C31	24°24'39"	38.34	90.00	N42°53'42"E	38.06
C32	11°27'05"	17.99	90.00	N60°49'34"E	17.96
C33	24°04'00"	37.80	90.00	N78°35'07"E	37.53
C34	57°04'20"	72.54	72.82	S61°18'05"W	69.57
C35	27°42'39"	9.50	19.64	S07°49'03"W	9.41
C36	35°14'04"	11.99	19.50	S54°35'21"E	11.80
C37	51°11'10"	21.89	24.50	S11°22'44"E	21.17
C38	47°49'10"	20.45	24.50	S38°07'26"W	19.86
C39	34°59'11"	14.97	19.50	S84°01'40"W	14.61
C40	35°14'04"	11.99	19.50	N56°21'39"W	11.80
C41	54°45'56"	23.42	24.50	N11°21'39"W	22.54
C42	8°18'03"	25.28	174.50	N20°10'20"E	25.26
C43	0°57'09"	2.90	174.50	N24°47'56"E	2.90
C44	19°47'15"	26.37	76.35	N35°10'09"E	26.24
C45	28°47'51"	28.61	56.92	N59°29'45"E	28.31
C46	34°06'21"	30.83	51.79	S89°15'33"E	30.38

LINE TABLE		
LINE	LENGTH	BEARING
L1	14.16	S72°23'21"E
L2	12.24	N52°56'40"E
L3	24.76	N18°49'54"E
L4	6.38	N43°44'46"E
L5	11.00	N30°13'42"E
L6	10.06	N01°06'09"E
L7	9.93	S30°28'58"E
L8	0.21	S89°22'53"E
L9	52.98	N28°51'50"E
L10	17.20	N28°51'50"E
L11	9.81	N31°08'10"W
L12	44.98	N28°51'50"E
L13	7.94	N28°51'50"E
L14	9.81	N88°51'50"E
L15	60.19	N28°51'50"E
L16	15.40	N28°51'50"E
L17	5.52	N28°51'50"E
L18	11.48	S74°44'35"E
L19	27.39	S74°44'35"E
L20	25.01	S73°58'41"E
L21	88.89	S73°58'41"E
L22	5.00	S16°30'07"W
L23	76.18	S73°58'41"E
L24	89.43	S73°58'41"E
L25	76.43	S73°58'41"E
L26	7.75	S76°09'41"E
L27	36.71	S76°09'41"E
L28	15.13	S69°14'53"E
L29	28.51	S42°37'05"E
L30	23.60	S42°37'05"E
L31	23.82	S49°44'35"E
L32	1.91	N45°14'12"E
L33	5.18	S38°16'27"E
L34	4.71	N51°43'33"E
L35	24.80	S40°05'42"E
L36	18.10	S50°07'34"W
L37	27.46	S50°07'34"W
L38	2.19	N16°36'45"W
L39	0.31	N57°55'57"E
L40	87.22	N41°52'34"W

LINE TABLE		
LINE	LENGTH	BEARING
L41	2.93	S16°01'19"W
L42	34.70	S16°01'19"W
L43	7.02	S16°01'19"W
L44	6.70	S25°16'31"W
L45	10.93	S45°03'46"W
L46	5.00	N11°41'39"W
L47	25.09	N72°12'23"W
L48	59.53	N72°12'23"W
L49	67.41	N72°12'23"W
L50	39.83	N72°12'23"W
L51	5.00	S43°21'26"W
L52	10.87	N72°12'23"W
L53	3.82	N15°59'24"E
L54	13.95	S72°12'23"E
L55	53.13	N14°12'51"E
L56	13.24	N14°12'51"E
L57	5.00	N75°47'09"W
L58	43.90	N14°12'51"E
L59	5.00	N44°07'38"E
L60	44.18	N73°58'41"W
L61	38.87	N74°44'35"W
L62	25.55	S28°51'50"W
L63	72.85	S28°51'50"W
L64	87.09	S28°51'50"W
L65	28.54	S28°51'50"W
L66	5.87	N89°26'51"W
L67	10.33	S08°37'19"E
L68	46.47	S17°36'39"W
L69	18.70	N72°23'21"W
L70	43.53	N72°23'21"W
L171	5.01	N20°12'47"E
L172	9.21	N72°12'23"W
L173	9.81	S47°47'37"W
L174	26.56	N72°12'23"W
L175	5.00	S53°01'41"W
L176	4.86	N14°12'51"E
L177	9.81	N74°12'51"E

LINE TABLE		
LINE	LENGTH	BEARING
L178	47.15	N14°12'51"E
L179	3.41	N45°47'09"W
L180	6.41	N45°47'09"W
L181	47.20	N14°12'51"E
L182	5.00	S27°57'59"E
L183	77.52	S73°58'41"E
L187	55.39	S73°58'41"E
L188	9.81	S13°58'41"E
L189	10.38	S73°58'41"E
L190	40.00	S73°58'41"E
L191	25.55	S73°58'41"E
L192	9.81	N46°01'19"E
L193	20.90	S73°58'41"E
L194	5.00	N51°15'23"E
L195	41.22	S16°01'19"W
L196	6.70	S25°16'31"W
L197	10.93	S45°03'46"W
L198	5.01	N13°34'18"W
L199	25.10	N72°12'23"W
L200	60.09	N72°12'23"W
L201	18.30	N72°12'23"W
L202	9.81	N12°12'23"W
L203	43.72	N72°12'23"W

DRIVEWAY EASEMENT LINE DATA
L1=S72°23'21"E, 24.52' L5=N20°11'00"E, 30.00'
L2=S52°56'40"W 35.08' L6=S69°47'37"E, 6.31'
L3=S17°11'14"W 68.70' L7=N17°11'14"E, 38.79'
L4=N69°47'37"W 33.18' L8=N52°56'40"E 27.35'

DRIVEWAY EASEMENT CURVE DATA
C1: Δ=-35°45'26" R=20.00' L=12.48' CHL=12.28' CHB=S35°03'57"W
C2: Δ=93°01'09" R=5.00' L=8.12' CHL=7.25' CHB=S6°41'48"W
C3: Δ=93°01'09" R=10.00' L=16.23' CHL=14.51' CHB=N6°41'48"E
C4: Δ=-35°45'26" R=20.00' L=12.48' CHL=12.28' CHB=N35°03'57"E

LINE DATA
L1- S40°05'42"E 24.80'
(RECORD DATA R1-S40°07'49"E 24.80')
SURVEY TIE LINE DATA:
T1: TIE-S84°20'21"E 18.39'

LEGEND

- SURVEY MONUMENT FOUND
- SURVEY MONUMENT 1/2" REBAR STAKE W/CAP STAMPED ARMIJO-13604
- SURVEY MONUMENT SET 1/2" REBAR STAKE W/CAP STAMPED ARMIJO-13604
- CACULATED POINT NOT SET
- SANITARY SEWER MANHOLE COVER
- STREET LAMP POLE
- UTILITY POLE
- UTILITY POLE WITH GUY WIRE ANCHOR
- UTILITY POLE WITH GUY WIRE ANCHOR
- ELECTRIC METER
- GAS METER
- WATER METER
- ELECTRIC UTILITY MANHOLE
- TELEPHONE UTILITY MANHOLE
- TELEPHONE UTILITY PEDESTAL
- ELECTRIC JUNCTION BOX
- STORM DRAIN DROP INLET GRATE
- STUCCO WALL
- CRAWLSPACE ACCESS HATCH
- FREE STANDING STUCCO STORAGE BUILDING
- CARPORT ROOF CANOPY OR PORTAL ROOF CANOPY
- NEW MEASURED DATA BY THIS NEW SURVEY
- RECORD DATA BY OTHERS
- EX. NO. 11. NOTE TO TITLE COMMITMENT EXCEPTION NUMBER

PAUL A. ARMIJO NEW MEXICO 13604 REGISTERED PROFESSIONAL SURVEYOR
10-4-22

PLAZA DEL MONTE DEVELOPMENT PLAN TRACT B ON CAMINO SANTIAGO AND CAMINO MATIAS

VICINITY MAP



GENERAL NOTES

1. METES AND BOUNDS DESCRIPTIONS OF LOTS, ROADWAYS, DRAINAGE, UTILITY, AND ACCESS RIGHTS-OF-WAYS AND/OR EASEMENTS ARE DESCRIBED ON THE SUBDIVISION PLAT.
2. PROPERTY DEVELOPMENT IS REQUIRED TO COMPLY WITH APPLICABLE PROVISIONS OF CHAPTER 14, LAND DEVELOPMENT CODE, SFCC 1987 AND SUBSEQUENT AMENDMENTS.
3. PER SFCC § 14-7.2, TABLE 14-7.2-1, BUILDING SETBACKS ARE ESTABLISHED BY THIS DEVELOPMENT PLAN AND SHALL APPLY TO ALL PERMANENT STRUCTURES, INCLUDING ACCESSORY STRUCTURES.
4. NEW STRUCTURES AND/OR ADDITIONS ARE NOT LIMITED TO STRUCTURES SHOWN HEREON, AND FUTURE DEVELOPMENT IS SUBJECT TO ESTABLISHED BUILDING SETBACKS, APPLICABLE PROVISIONS OF SFCC CHAPTER 14, AND BUILDING PERMIT REQUIREMENTS.
5. SITE AND INDIVIDUAL LOT FENCING LOCATIONS TO BE DETERMINED AT TIME OF BUILDING PERMIT.
6. DEVELOPMENT OF LOT 23 IS SUBJECT TO THE WATER ALLOCATION AND/OR WATER OFFSET RETROFIT PROVISIONS OF ORDINANCE NO. 2002-29 AND RESOLUTION 2003-55 AT THE TIME OF PERMIT APPLICATION OR WATER HOOKUP REQUEST.
7. ACCESSIBILITY FEATURE DESIGN WITHIN THE SITE SHALL COMPLY WITH NEW MEXICO DEPARTMENT OF TRANSPORTATION (NMDOT) PEDESTRIAN ACCESS ROUTE DETAILS (SERIAL 608) OR MUST DEMONSTRATE COMPLIANCE WITH APPLICABLE AMERICANS WITH DISABILITIES ACT (ADA) REGULATIONS BY OTHER MEANS AS PROVIDED IN THE PERMITTED CONSTRUCTION DOCUMENTS.
8. FENCES, WALLS OR OTHER OBSTRUCTIONS SHALL NOT BE PLACED OR CONSTRUCTED ACROSS PUBLIC SANITARY SEWER EASEMENTS.
9. ALL PROPOSED CHANGES TO THE APPROVED IMPROVEMENT PLANS SHALL RECEIVE PRIOR APPROVAL BY THE CITY OF SANTA FE PLANNING AND LAND USE DEPARTMENT BEFORE CONSTRUCTION.
10. PROPERTY DEVELOPMENT IS REQUIRED TO COMPLY WITH THE PROVISIONS OF THE COSF ORDINANCE NO. 2008-02 (IMPACT FEES).
11. PROPERTY DEVELOPMENT, BOTH PUBLIC AND PRIVATE OWNERSHIP, SHALL COMPLY WITH THE COSF ORDINANCE NO. 2002-20 (TERRAIN AND STORMWATER MANAGEMENT) AT THE TIME OF BUILDING PERMIT APPLICATION.
12. PROPERTY DEVELOPMENT IS SUBJECT TO THE PROVISIONS OF SECTION 14-8.4(F)(5), "PLANT MATERIAL STANDARDS," WHEREIN PRESERVATION OF SIGNIFICANT TREES IS REQUIRED.
13. FIRE DEPARTMENT ACCESS SHALL BE MAINTAINED THROUGHOUT ALL DEVELOPMENT CONSTRUCTION PHASES AS PER IFC 1410.1.
14. PERMANENT TRAFFIC CONTROL DEVICES SHALL BE INSTALLED PER APPROVED PLAN BY THE DEVELOPER.
15. PRIVATE ROADS AND ASSOCIATED PARKING WITHIN THE SUBDIVISION SHALL BE MAINTAINED BY THE PLAZA DEL MONTE HOMEOWNER'S ASSOCIATION.
16. THIS DEVELOPMENT LIES WITHIN THE DOWNTOWN AND EASTSIDE HISTORIC DISTRICT.
17. THIS DEVELOPMENT LIES WITHIN THE SUBURBAN ARCHAEOLOGICAL REVIEW DISTRICT.
18. THE PROPOSED SANITARY SEWER SYSTEM SERVING THIS DEVELOPMENT IS PRIVATE AND WILL NOT BE MAINTAINED OR OWNED BY THE CITY OF SANTA FE.

DUST CONTROL NOTES

ALL ON-SITE SOIL DISTURBING CONSTRUCTION ACTIVITIES SHALL BE ADDRESSED AND PROVIDE MEASURES TO MITIGATE OR CONTROL DUST FROM BEING TRANSPORTED OFFSITE AND POLLUTING NEIGHBORING PROPERTIES.

ANY PERSON, OWNER, CONTRACTOR OR OPERATOR WHO CONDUCTS EARTHMOVING AND/OR DUST GENERATING ACTIVITIES IS RESPONSIBLE FOR IMPLEMENTING BEST MANAGEMENT PRACTICES (BMPs) IN ORDER TO MITIGATE OFF-PROPERTY TRANSPORT OF FUGITIVE DUST EMISSIONS.

A PLAN, OR STORMWATER POLLUTION PREVENTION PLAN (SWPPP) WHEN APPLICABLE, LISTING THE BEST MANAGEMENT PRACTICES SHALL BE PROVIDED TO THE CITY ENGINEER, OR HIS/HER DESIGNEE, FOR REVIEW AND APPROVAL. THE APPROVED BMPs SHALL BE APPLIED TO THE GRADED AND/OR DISTURBED SOIL IN ORDER TO STABILIZE THE SITE.

THE INITIAL BMP SHALL ADDRESS HOW THE CONTRACTOR WILL MINIMIZE THE AMOUNT OF DISTURBED SOIL AND HOW THE CONTRACTOR WILL STABILIZE THE DISTURBED SURFACE AREA EXPOSED TO WIND OR VEHICLE TRAFFIC DURING CONSTRUCTION.

SOME BMPs SHALL INCLUDE:

- THE REDUCTION OF VEHICLE SPEEDS: ESTABLISH A MAXIMUM SPEED LIMIT OR INSTALL TRAFFIC CALMING DEVICES TO REDUCE SPEEDS TO A RATE TO MITIGATE OFF-PROPERTY TRANSPORT OF DUST ENTRAINED BY VEHICLES.
- THE MINIMIZATION OF DROP HEIGHT: DRIVERS AND OPERATORS SHALL UNLOAD TRUCK BEDS AND LOADER OR EXCAVATOR BUCKETS SLOWLY AND MINIMIZE DROP HEIGHT OF MATERIALS TO THE LOWEST HEIGHT POSSIBLE, INCLUDING SCREENING OPERATIONS.
- HIGH WINDS RESTRICTION: TEMPORARILY HALT WORK ACTIVITIES DURING HIGH WIND EVENTS GREATER THAN 30 MPH IF OPERATIONS WOULD RESULT IN OFF-PROPERTY TRANSPORT.
- RESTRICT ACCESS: RESTRICT ACCESS TO THE WORK AREA TO ONLY AUTHORIZED VEHICLES AND PERSONNEL.

IN THE EVENT THE ABOVE PRACTICES ARE INEFFECTIVE TO PREVENT OFF PROPERTY TRANSPORT, THE PERSON, OWNER OR OPERATOR SHALL USE ONE OR MORE OF THE FOLLOWING BMPs:

- WET SUPPRESSION: APPLY WATER TO DISTURBED SOIL SURFACES, BACKFILL MATERIALS, SCREENINGS AND OTHER DUST GENERATING OPERATIONS AS NECESSARY AND APPROPRIATE CONSIDERING CURRENT WEATHER CONDITIONS, AND PREVENT WATER USED FOR DUST CONTROL FROM ENTERING ANY PUBLIC RIGHT-OF-WAY, STORM WATER DRAINAGE FACILITY, OR WATERCOURSE.
- WIND BARRIER: CONSTRUCT A FENCE OR OTHER TYPE OF WIND BARRIER TO PREVENT WIND EROSION OF THE GRADED OR DISTURBED SURFACE.
- VEGETATION: PLANT VEGETATION APPROPRIATE FOR RETAINING SOILS OR CREATING A WIND BREAK.
- SURFACE ROUGHENING: STABILIZE AN ACTIVE CONSTRUCTION AREA DURING PERIODS OF INACTIVITY WHEN VEGETATION CANNOT BE IMMEDIATELY ESTABLISHED.
- COVER: INSTALL COVER MATERIALS SUCH AS TACKIFIERS, EROSION CONTROL BLANKETS, GRAVEL, VEGETATION (WHEN APPROPRIATE), COLD-MILLINGS, ETC. DURING PERIODS OF INACTIVITY AND PROPERLY ANCHOR THE COVER.
- SOIL RETENTION: STABILIZE DISTURBED OR EXPOSED SOIL SURFACE AREAS THAT WILL BE INACTIVE FOR MORE THAN 30 DAYS OR WHILE VEGETATION IS BEING ESTABLISHED.

AFFIDAVIT

KNOW ALL PERSONS BY THESE PRESENTS THAT THE UNDERSIGNED OWNERS HAVE CAUSED THIS FINAL DEVELOPMENT PLAN TO BE PREPARED. ALL THAT APPEARS ON THIS PLAN IS MADE WITH THE FREE CONSENT AND IN ACCORDANCE WITH THE DESIRES OF THE OWNER.

PLAZA DEL MONTE, LLC

8C3023 83-0838

THE FOREGOING WAS SWORN, ACKNOWLEDGED AND SUBSCRIBED BEFORE ME BY E. LARRY LUJAN
THIS 25th DAY OF OCTOBER, 2022.

NOTARY PUBLIC

COLLEEN C. GAVIN
Notary Public - State of New Mexico
Commission # 1127282
My Comm. Expires October 8, 2023

OCTOBER 8, 2023
MY COMMISSION EXPIRES

STORMWATER AGREEMENT

PROPERTY OWNER(S) HEREBY AGREE THAT ALL STORMWATER EASEMENTS AND ANY OTHER DRAINAGE IMPROVEMENTS ON PRIVATE PROPERTY WILL BE MAINTAINED AND KEPT FULL Y FUNCTIONAL AS ORIGINALLY DESIGNED AND CONSTRUCTED WITHIN PRIVATE PROPERTY BOUNDARIES; THE CITY HAS THE RIGHT OF ACCESS FOR INSPECTION OF SAID IMPROVEMENTS; THE CITY HAS THE RIGHT, IN THE EVENT OF DRAINAGE FACILITY MAINTENANCE DEFICIENCY AND AFTER TEN (10) DAYS WRITTEN NOTICE TO THE RESPECTIVE PROPERTY OWNER, TO ENTER AND RESTORE FULL FUNCTIONAL CAPACITY OF THE DRAINAGE IMPROVEMENTS AND TO LIEN THE PROPERTY FOR BOTH DIRECT AND INDIRECT COSTS ASSOCIATED WITH SUCH WORK. BY SIGNATURE AFFIXED TO THIS INSTRUMENT, THE PROPERTY OWNER(S) APPROVE AND AGREE THAT THIS AGREEMENT IS BINDING PERPETUALLY, RUNNING WITH THE LAND, ON PRESENT AND FUTURE OWNERS, HEIRS, AND ASSIGNS.

PLAZA DEL MONTE, LLC

THE FOREGOING WAS SWORN, ACKNOWLEDGED AND SUBSCRIBED BEFORE ME BY E. Larry Lujan
THIS 21st DAY OF November, 2022.

NOTARY PUBLIC

JENNIFER JENKINS
Notary Public - State of New Mexico
Commission # 1127284
My Comm. Expires October 8, 2023

10.8.2023
MY COMMISSION EXPIRES

DRAINAGE FACILITY MAINTENANCE SCHEDULE SHALL BE AS FOLLOWS:

1. ALL DRAINAGE FACILITIES SHALL BE MAINTAINED BY THE HOME OWNERS ASSOCIATION.
2. THE DRAINAGE FACILITIES MAINTENANCE SCHEDULE SHALL BE AS FOLLOWS: MARCH 15TH, SEPTEMBER 15TH AND AFTER STORMS OF ONE INCH OR GREATER.

a. FLUSH ALL CULVERTS AND DRAIN PIPES TO REMOVE SEDIMENT AND VEGETATION.
b. FLUSH STORM DRAIN MANHOLES AND DROP INLETS.
c. IF SEDIMENT IN PONDS IS DEEPER THAN 6 INCHES, REMOVE AND RESEED WITH NATIVE GRASSES.
d. CHECK POND DRAINS AND RIP-RAP INTEGRITY. REPAIR AS NECESSARY.
e. CHECK FOR SOIL EROSION WITHIN AND AROUND ALL SWALES, FILL SLOPES, CUT SLOPES AND RETAINING WALLS. UNSTABILIZED SOILS SHALL BE STABILIZED WITH VEGETATION, ROCK PLATING OR EROSION MATS.

DEVELOPMENT PLAN SIGNATURES

APPROVED BY THE SANTA FE PLANNING COMMISSION AT THEIR MEETING ON JANUARY 6, 2022
AS PLANNING & DEVELOPMENT REVIEW CASE # 2021-4548 & 2021-4549

PLANNING COMMISSION CHAIR — DATE 11/16/2022

PLANNING COMMISSION SECRETARY — DATE 12/2/22

REVIEWED BY THE CITY OF SANTA FE:

CITY PLANNER — DATE 11.17.22

CITY ENGINEER FOR LAND USE — DATE 11/22/22

COUNTY OF SANTA FE } SS
STATE OF NEW MEXICO }

I HEREBY CERTIFY THAT THIS INSTRUMENT WAS FILED FOR RECORD ON THIS ___ DAY OF _____ A.D. 20___ AT _____ O'CLOCK___M. AND WAS DULY RECORDED IN BOOK____ PAGE_____ OF THE RECORDS OF SANTA FE COUNTY.

WITNESS MY HAND AND SEAL OF OFFICE
KATHARINE CLARK
COUNTY CLERK SANTA FE COUNTY NM

DEPUTY

CITY REVIEW

DEPARTMENT	SIGN-OFF	DATE
WASTEWATER MANAGEMENT DIV.	SIGNATURE ON FILE	
WATER SERVICES		
STREETS DIV.		
TRAFFIC DIV.		
FIRE		
LANDSCAPE		
SUBDIVISION ENGINEER		

CASE # 2021-4549 (2021-4548)
CITY USE ONLY

JENKINSGAVIN
LAND USE | PROJECT MANAGEMENT
130 Grant Avenue, Suite 101
Santa Fe, NM 87501
505.820.7444

FINAL DEVELOPMENT PLAN AND FINAL SUBDIVISION PLAT SUBMITTAL FOR PLAZA DEL MONTE

DEVELOPMENT PLAN
SHEET 1 OF 2

DATE:	SCALE:	SHEET:
NOVEMBER 2021	N.T.S.	3-1

PLAZA DEL MONTE DEVELOPMENT PLAN
TRACT B ON CAMINO SANTIAGO AND CAMINO MATIAS

NOTE:
THE PROPOSED SANITARY SEWER SYSTEM SERVING THIS DEVELOPMENT IS PRIVATE AND WILL NOT BE MAINTAINED OR OWNED BY THE CITY OF SANTA FE.



DEVELOPMENT PLAN
SCALE: 1" = 40'

0 20 40 80
SCALE: 1" = 40'

LEGEND

- PROPOSED SIDEWALK
- EXISTING SIDEWALK
- PROPOSED DRIVEWAY
- PROPOSED LOT LINE

PROJECT DATA

SITE AREA: 6.625 ACRES
ZONING: R-29 (RESIDENTIAL)
OVERLAY: DOWNTOWN AND EASTSIDE HISTORIC DISTRICT

DENSITY:
- Gross Lot Area = 6.625 acres
- 100-yr Floodplain = 0.452 acres (19,671 sq.ft.)
- Net Lot Area = 6.173 acres
- Maximum Allowable Density = 6.173 acres x 10 DU/acre = 61 DU
- Proposed Density = 30 DU/6.625 acres = 4.5 DU/acre

LOT COVERAGE:
- Maximum Allowable Lot Coverage = 40%, per SFCC Table 14-7.2-1
- Proposed Lot Coverage = Not to exceed 40% per lot

BUILDING SETBACKS: (As established by this Development Plan, per SFCC Table 14-7.2-1)
- Front Yard Setback: 7 feet from edge of Access & Utility Easement.
- Side Yard Setback: 5 feet from property line for Detached Homes OR 0 feet from property line if adjacent setback is increased to 10 feet. 0 feet from property line for Attached Homes if fire-rated wall is provided.
- Garage Setback: 10 feet from edge of Access & Utility Easement, for all lots except Lot 28, where the setback shall be 8 feet from edge of Access & Utility Easement to accommodate an existing carport. If this carport is demolished, any new garage or carport shall conform to the 10-foot garage setback that applies to the Subdivision.
- Rear Setback: 10 feet from property line.

PARKING:
- Total Required Parking = 2 off-street spaces per residence
- Total Provided Parking = 2 off-street spaces per residence (60 spaces)
- Total Required Guest Parking = 0.5 guest spaces per DU x 30 DU = 14 guest spaces
- Total Provided Guest Parking = 15 guest spaces

COMMON OPEN SPACE:
- Required = None required
- Provided = 3,412 sq.ft (Pocket Park – Tract A)

2021-4548
CASE # 2021-4549

CITY REVIEW		
DEPARTMENT	SIGN-OFF	DATE
WASTEWATER MANAGEMENT DIV.	SIGNATURE ON FILE	
WATER SERVICES		
STREETS DIV.		
TRAFFIC DIV.		
FIRE		
LANDSCAPE		
SUBDIVISION ENGINEER		

CITY USE ONLY

JENKINSGAVIN
LAND USE | PROJECT MANAGEMENT
130 Grant Avenue, Suite 101
Santa Fe, NM 87501
505.820.7444

FINAL DEVELOPMENT PLAN AND FINAL SUBDIVISION PLAT SUBMITTAL FOR PLAZA DEL MONTE

DEVELOPMENT PLAN
SHEET 2 OF 2

DATE:	SCALE:	SHEET:
NOVEMBER 2021	1" = 50'	3-2

PLAZA DEL MONTE

Santa Fe, New Mexico

Historic Resources Evaluation

March 28, 2018

Client: Wayne S. Lloyd, A.I.A.
Lloyd & Associates, Architects
321 W. San Francisco St., Suite A
Santa Fe, NM 87501

Consultant: John W. Murphey
Architectural Historian
2833 Plaza Verde
Santa Fe, NM 87507


125

Summary

This Historic Resources Evaluation was prepared at the request of Wayne Lloyd, Lloyd and Associates, Architects. It responds to a motion the Santa Fe Historic Districts Review Board made at its November 28, 2017 hearing, requiring the applicant to provide a complete study of the buildings comprising Plaza del Monte, a former Presbyterian retirement center (Case #H-17-098A, minutes). The original application called for the demolition of five structures, addressed as 122, 124, 125, and 126 Camino Santiago, and a standalone garage/carport structure behind 126.

The present report was prepared to satisfy the Board's requirement regarding the evaluation of cultural resources set forth in the Historic Districts Ordinance (14-5.2) and the policies and guidelines developed by the City of Santa Fe Historic Preservation Division.

The Historic Districts Ordinance created a system of classifications in which cultural resources are evaluated and designated as to whether they contribute to the Historic District (14-5.2(C)(2)(a)). The Board is given the authority to designate and/or change a status of a cultural property (14-5.2(C)(2)(a)(1)). This action commonly occurs when an applicant submits a project that may affect an assigned or "un-statused" property within the Historic District. Identification of historical significance is typically accomplished through a survey and evaluation of identified resources using the New Mexico Historic Cultural Properties Inventory (HCPI) form.

Findings

After an intensive-level survey, archival investigations, and an evaluation of historical significance, the conclusion is that five buildings (102, 103, 106, 111 Camino Santiago and 104 Camino Matias) are eligible for Contributing Structure status to the Downtown and Eastside Historic District. Due to either 1) a lack of age-eligibility, or 2) non-compatible architectural elements, the remaining buildings were determined to be Noncontributing to the district.

Table of Contents

I. PROJECT DESCRIPTION 1

II. PROJECT AREA 2

III. RESEARCH METHODS 4

IV. FIELD METHODS 4

V. HISTORICAL OVERVIEW 5

VI. DESCRIPTION OF RESOURCES 16

VII. RESOURCE EVALUATION 17

VIII. TABLE OF SURVEYED RESOURCES 19

IX. BIBLIOGRAPHY 22

X. MAPS AND AERIAL PHOTOGRAPHS 23

XI. HISTORIC CULTURAL PROPERTIES INVENTORY FORMS 30

I. Project Description

The applicant, Wayne, Lloyd, Lloyd and Associates, Architects, representing the owner, Plaza del Monte, LLC, approached the Historic Districts Review Board on November 28, 2017, with a request to demolish five units of the Plaza del Monte retirement center (Case #H-17-098A).

The case planner, David Rasch, stated in his report that the five structures (122, 124, 125, and 126, and a separate garage/carport), should be determined Noncontributing, "due to marginal historic date of construction, lack of Santa Fe style, and non-historic alterations."

After discussion, the Board postponed the case, requesting the applicant provide a full historic evaluation report on the 27 units making up the former retirement community. Further discussion with David Rasch indicated that this would consist of complete HCPI forms 1 & 2 for each standing structure on the property, and an evaluation of their potential historic status for the Downtown and Eastside Historic District.

This report attempts to fulfill that request by providing HCPI forms for each residential unit, a brief historical context, associated aerial photographs and maps, and an evaluation of individual and district eligibility. The project attempted, using various sources, to determine the actual date of construction of each residential unit of Plaza del Monte.

II. Project Area

The property, generally known as Plaza del Monte, or Plaza del Monte Retirement Center, spreads across a roughly six-acre parcel located north of the Santa Fe Plaza. The pistol-shaped tract is bounded on the east by Bishop's Lodge Road; on the north by the grounds of Fort Marcy Recreation Complex and Magers Field; on the west by the alignment of Arroyo Mascaras; and on the south by a combination of land formerly associated with Plaza del Monte and tracts and residential lots under private ownership (Figure 1).

The surveyed area includes two private streets (Camino Santiago and Camino Matias) that were constructed in the 1960s as part of the retirement facility. The roads are arranged in a typical suburban pattern of a cul-de-sac and a loop. The land descends east-to-west toward the arroyo. During development, it was shaped as terraced pads along the north side of Camino Santiago. Separate terracing is found on the north side of Camino Matias, dating to an earlier construction period.

Near the center of the development is an informal grassy area that once served as a social area. Mature native trees, likely planted during the 1960s, are found throughout. The house landscapes, however, have evolved, changing from lawns to areas filled with boulders and xeric plantings. Concrete pedestrian paths loop through a few sections of the development.

Houses are typically placed in the center or close to the back of the lot. They are arranged with their long elevations facing the street. Carports are approached by wide concrete driveways. Most likely due to the limitation of the lot size or community guidelines, there are no notable ancillary structures. Grounds are kept minimal, free of tenant clutter.



Figure 1: Portion of "Santa Fe, N. Mex." USGS quadrangle map, 1961, photo-revised 1977. Scale- 1:24,000.

III. Research Methods

Prior to starting fieldwork, the project historian reviewed the City of Santa Fe's and the New Mexico Historic Preservation Division's records for properties listed and/or evaluated within the project area. This included a review of listings on the National Register of Historic Places, State Register of Cultural Properties, as well as resources documented with New Mexico Historic Building Inventory or Historic Cultural Properties Inventory forms. The research found no previous surveyed or registered properties within the project area.

A separate archival phase encompassed a review of primary and secondary sources held at various repositories, including the Fray Angélico Chávez Library, Palace of Governors Photo Library, State Library-Southwest Room and the State Archives and Records Center, all located in Santa Fe. In addition, archived newspaper and online sources were searched. The historian was also given access to an incomplete set of drawings covering most of the surveyed buildings.

IV. Field Methods

John W. Murphey, Architectural Historian, conducted a site survey on January 18, 2018. This consisted of a preliminary inventory of all standing structures on the parcel. A follow-up recordation was conducted by Sharon Joyce on February 23, 2018.

As per Santa Fe Historic Preservation Division policy, each resource was recorded with photographs documenting the principal elevations. The surveyors identified character-defining details and noted any perceived exterior alterations. The survey recorded 27 buildings on 26 Historic Cultural Properties Inventory forms. The forms are attached to this report.

V. Historical Overview

Plaza Del Monte was conceived in the late 1950s as a communal living center for retired Presbyterian pastors, missionaries, and other church officials. The Board of Pensions of the United Presbyterian Church considered this use for their Santa Fe property north of the Plaza, after the Allison-James School closed in 1958.

Established in 1880 by the Board of Domestic Missions, the school taught Spanish-American children at the junior and senior levels of high school.[1] The campus originally spread over 18 acres and included six major buildings, many designed in the Mission Revival style.

Figure 2: The Margaret Olivia Sage Hall, demolished in 1960 to construct Plaza del Monte. Source: Atkins, 1983.

With the closure of the school, the Board of Pensions began to plan for a large retirement community to join similar centers in Cooperstown, New York, Philadelphia and Kansas City. New Mexico's climate, the church's history in the state, and the fact they already owned the land motivated the Board to build the next community in Santa Fe.

In 1959, the Board selected the Santa Fe architectural firm of Kenneth S. Clark and Philippe Register Architects to create a plan for the as-of-yet-unnamed community.

[1] The school's history dates back to 1866, to the first Presbyterian Mission in Santa Fe. The school originally instructed Native American, Anglo and African American girls at the primary through high school levels. In 1934, it became a co-educational junior high school. (Work Progress Administration, "History of the Allison-James School.")

Kenneth Clark (1909-1990), an Oklahoma-born architect and Philippe de Montauzan Register (1921-2006), a younger, Yale-trained architect of French lineage, formed a partnership in 1956. Prior to the retirement center, the pair had worked on large military projects at Sandia Base and White Sands Missile Range, and locally designed the Santa Fe County Health Building (1958) and a gymnasium for the New Mexico School for the Deaf (1960), among other commissions.

The architects divided the former Allison-James School campus into two parts. The site of the older buildings, termed the "South Area" would be developed first with a congregate building. The lesser built area above the old campus ("North Area"), would be developed later with individual retirement residences.

Casa Grande

Clark and Register initially put their focus on designing the Congregate Home on a parcel fronting then Federal Way and Taos Highway. The building, later dubbed "Casa Grande" was a sprawling combined administrative and community living complex. Church staff and the architects reportedly studied congregate communities in the Netherlands to develop the design.[2] Congregate centers, an arrangement where elderly residents lived communally and were encouraged to participate in shared activities, emerged as a planning trend for retirement facilities in the United States in the 1950s.[3]

Work began on the communal center on August 1960, after the City of Santa Fe issued a $99,000 permit for the larger project.[4] In preparation, four earlier school buildings were demolished. These encompassed a hall, dormitories and a gymnasium.

Constructed in 1960-61, the Congregate Home had a layout similar to the "finger plan" used for elementary schools of the period. The plan included a long north-south oriented mass, to which were attached at right angles separate wings or "fingers" connected to each other by short corridors. The plan allowed for additional wings to be added, and a fourth was constructed in the 1970s.

The combined building included separate areas for administrative offices, a reception room, a large commercial kitchen and dining room, a lounge, a beauty parlor, and a dormitory that could house up to 40 residents.[5]

---

[2] *Santa Fe New Mexican*, August 31, 1961, 27.
[3] Geneva Mathiasen and Edward H. Noakes, editors, *Planning Homes for the Aged*, (New York: F.W. Dodge Corporation, 1959).
[4] *Santa Fe New Mexican*, September 4, 1960, 12.
[5] Ibid., October 22, 1968, 3; August 31, 1971, 15.

Facing two public streets, the southwest corner of the Congregant Home received the most architectural treatment of the development. This area became the public face of the retirement community. Here the architects placed a long entrance portal leading to the front (public) doors. A Pueblo style mass anchored the southwest corner, its broad walls cut with narrow, vertical church-like windows (Figure 3).

The Congregant Home opened on November 16, 1961. Nearly 300 people attended the ceremony for the $750,000 development.[6]



Figure 3: Casa Grande under construction, showing original south façade, May 1961. Courtesy *San Fe New Mexican*.

The parcel north of Casa Grande would be developed over the years with 20 free-standing retirement residences, colloquially called cottages.[7] This section had been lightly worked during the school's use of the property, and contained three houses constructed in 1950 for married faculty and a few ancillary structures (Figure 4 and Aerial 1). The faculty units and a moved building (111 Camino Matias) were converted into retirement homes, and were in use by the fall of 1961.

[6] Ibid., September 28, 1961, 51.
[7] Ibid., August 31, 1961, 27.

Figure 4: Rear (north) elevation of married faculty cottages, c. 1950s. Source: Atkins, 1983.

Retirement Cottages

A June 1960 preliminary layout developed by Clark and Register depicted a typical suburban cul-de-sac arrangement of free-standing homes built around two new streets (Figure 5). Camino Santiago, running along the north side of the property, terminated as a tight cul-de-sac. A second street, Camino Matias, worked as a circulating loop between Camino Santiago and the existing teacher residences to the south.



Figure 5: Portion of layout and grading plan showing cottages to be constructed, June 1960.

The architects initially proposed five new houses (R1-R5), completing the loop between the streets. Of these, four were constructed before 1966. Another 14 units, principally sited along Camino Santiago, were identified for future development on the plan.

The houses depicted on the plan reveal a uniform design. Each consisted of a modified L-plan to which was attached a carport and connecting portal. The earliest elevations prepared by Clark and Register show a design sympathetic to the Spanish-Pueblo Revival tradition (Figure 6). The front elevation included a projecting roomblock-like mass with rounded corners and a portal at a slight offset, a design trope introduced by architect John Gaw Meem nearly four decades earlier. Anchoring the end of the structure was a carport pushed back from the façade. Following the idiom, vigas were used for the actual roofing structure, window openings were small, and in most cases, arranged on the horizontal. The Spanish-Pueblo Revival theme continued along the portal and carport with a viga structure supported by rustic round posts topped with zappos-type corbels (Figure 6).



Figure 6: June 1960 Clark and Register drawing showing typical retirement residence. The drawing corresponds with 104 Camino Matias.

The floor plan, however, was mostly modern. It segregated bedrooms to a wing placed in the ell, which from the exterior looked like a rounded roomblock. The remaining functions of the house were clustered in a tight square (Figure 6).

Resident Number 1, at 104 Camino Matias, is representative of this early composition.

Evolution of Design

The design of the retirement units began to evolve as the project progressed. After the first construction phase, Philippe Register left the firm, opening his own practice in late 1960. It appears that Register and his evolving firm were contracted at least twice (1963 and 1967) by the Board of Retirement to further expand the retirement center, including a job to build an additional wing on Casa Grande. (Several houses constructed in the late 1960s and early '70s are not associated with Register's firm; their designers, at this point, are unknown).

Surviving drawings show Register pushing beyond the traditional plan of the earlier Clark and Register designs. While previous elevation and floor plans were recycled for subsequent houses, Register opted to add large areas of glass across the front façade, primarily by inserting sliding doors under the portal (103 and 111 Camino Santiago) (Figure 7). While retaining the basic roomblock bedroom wing, Register often attenuated the stem of the "L" with a more contemporary, one-room-wide Ranch house plan.

Figure 7: 111 Camino Santiago, an example of Philippe Register's transitional work.

The contemporary influence later moved to the exterior, as elevations became longer and leaner. Many reveal a then-poplar horizontal emphasis. This emphasis was furthered with overhangs arranged across front, back, and sometimes side elevations (117, 119, 121 Camino Santiago) (Figure 8). In this way, many of the units constructed in the mid-to-late 1960s are examples of the Contemporary flat-roof house form.

Figure 8: 119 Camino Santiago, an example of a Contemporary flat-roof form.

Soon the architect began to insert more radical elements to the retirement units. Register experimented with angular composition, in which side walls were divided into several splayed planes (109, 117, 119, 124 Camino Santiago) (Figure 9). This may have been influenced by his work at the College of Santa Fe, and fit within the experiments of younger architects such as Ted Luna.



Figure 9: Roof plan for 109 Camino Santiago, 1963.

The design of each unit, however, was totally driven by economy. While not particularly well-suited for the climate, carports were employed as an economical method to shelter automobiles. Prominent carports emerged as almost a design motif in the drawings produced in Register's shop. Framed by either vigas or square beams, the structures were often placed in front of the dwelling, sometimes marring the balance of composition (109, 120, 121, 122 Camino Santiago and 111 Camino Matias) (Figure 10). The use of carports further ushered the houses into the contemporary context.

Figure 10: Example of carport dominated front façade, 109 Camino Santiago.

Cost-savings also informed the selection of construction materials and finishes. All houses were erected with standard 2x4 framing, clad with stucco. The stucco was worked, most likely with rubber gloves, into a heavily textured brocade finish, a treatment used frequently in tract developments of the period. The later units were fenestrated with pre-fitted windows (steel casement or aluminum sliding) and manufactured doors. Finished floors were carpet or vinyl over concrete; walls and ceiling were faced with sand or smooth plaster.

In contrast to the factory-built materials, the carports and portales were — somewhat ironically — built with heavy, traditional timber and viga framing. The woodwork included in many instances end-lapped girders and zappos-type corbels. Even though these elements were most likely pre-cut, they added a romanticized, regional touch to the otherwise Contemporary designs.

Further Development

From aerial photographs, it appears the first phase of the retirement cottages was completed by 1966, with eight new units constructed (Aerial 3). Similar to the projected layout, the houses were grouped along Camino Matias and the east end of Camino Santiago. Two residences placed north of the earlier faculty houses framed an open grassy area, which informally became a communal area.

Subsequent work focused on developing the remaining lots. By the mid-1960s, Register had reworked the earlier layout, extending Camino Santiago several hundred feet south. He eliminated a few freestanding houses and replaced with them quad apartments.

Construction of the apartments met delays, as a variance was required to build multi-unit buildings on the residential (R2) zoned property. Further delay arrived when the Board of Adjustment voted down the apartments in 1964.[8] Eventually approved, the buildings erected between 1969 and 1971 (105, 125 and 126 Camino Santiago) contained a line of apartments flanking a central laundry room. Each apartment had a small concrete patio at the rear.

The development's later phases were prepared by a partnership Register formed in 1967 with architects James Abelardo Brunet and Terrance Ross, going by the name RSB Architects. For the apartments, the firm used novel triangular-shaped walls as dividers and end pieces. They introduced one of these walls cut with a passage to the addition given to the original Kenneth S. Clark design at 110 Camino Santiago.

Figure 11: 126 Camino Santiago.

The quad apartment block terminating Camino Santiago (126) represents the most radical plan of the development. For its design, the architects removed the roomblock massing from the ends, moving it to the center to act as hood over the laundry. Raised triangular party walls divide the sections and bookend the building (Figure 11). Despite its avant-garde appearance, a viga portal was tacked on to the front façade.

Some of the last residential units to be built in the early 1970s (120 and 122 Camino Santiago) returned to a more traditional compact, room-block massing, yet with a carport-dominant façade (Figure 12). Construction of the originally planned 20 units was finished by 1977 with the expansion of the garage/carport structure behind 126 Camino Santiago.

[8] Ibid., June 23, 1964, 36; December 29, 1964, 20; December 31, 1964, 20.

Figure 12: 120 Camino Santiago, constructed in c. 1971.

A Tightknit Community

In its nearly two decades of existence, Plaza del Monte developed into a community of retired, service-oriented professionals. Between Casa Grande and the cottages, at its height the community supported around 100 residents. Residents ranged from pastors, to clergy, to nurses and doctors who had once worked for the church. Many had been missionaries, serving across the world. A few were noteworthy. Reverend Ovid R. Sellers, who arrived in 1972 to live in the recently finished house at 120 Camino Santiago, was known in his day as a Biblical scholar with expertise on the Dead Sea Scrolls.[9]

The retirees bonded together, forming a gardening club and reading circles. Those with musical talent gave performances in their homes; another group of less talented formed the tongue-in-cheek Geriatric Glee Club.[10] Plaza del Monte, along with El Castillo and other smaller developments, set the opening chapter of a trend to accommodate retirees in the city of Santa Fe.

[9] Ibid., October 29, 1972, C-3.
[10] Ibid., December 31, 1971, 17.

Decline of Center

In the late 1980s, after experiencing heavy losses, the Presbyterian Board of Pensions began shedding retirement centers across the United States. The Board placed the entire Santa Fe property for sale in December 1987, listing it at $1.5 million. Fear of its sale led residents to leave.[11] Nearly two years later, the Presbyterian Medical Services and the Ghost Ranch Foundation signed an agreement to purchase the land. Under the terms of the agreement, Ghost Ranch would manage Casa Grande, while Presbyterian Medical Services would take over the retirement cottages.[12]

The joint use of the property lasted over 20 years before economic conditions forced both entities to sell their holdings. In 2015, a group of Albuquerque and Santa Fe investors acquired Plaza del Monte. The earlier sale of the land containing Casa Grande resulted in its demolition, which was completed in the fall of 2017.

[11] Ibid., January 3, 1988, 9; March 23, 1988, 3.
[12] Ibid., July 10, 1989, A-8.

VI. Description of Resources

Plaza del Monte holds 27 separate buildings, erected between approximately 1950 and 1977. Five of these buildings pre-date the retirement community, and are associated with the Allison-James School, a nearly 100-year-old Presbyterian mission school that was demolished in 1960 for the development of Plaza del Monte.

Of the buildings directly associated with retirement center, 12 are (or will be) 50 years of age in 2018. The remaining ten buildings were constructed after the 50-year mark, with the last completed in 1977.

The majority of units are small, single-family residences, containing 1,000 to 1,500 square-feet. These have compact and economical floor plans holding two or three bedrooms. Plaza del Monte additionally includes three apartment buildings. They are laid out as single-story, linear forms, with one to two bedroom apartments stacked in a line.

Constructed over several phases, the retirement cottages reveal a variety of architectural forms and styles. The earliest residences, designed by Kenneth S. Clark and Philippe Register, show a sympathy for the Spanish-Revival Revival tradition — employing a modified L-plan form with bedrooms placed in a wing emulating an adobe mass. Set back from the wing is a viga-roof portal, and further back, a one-bay carport.

After Register started his own firm in 1960, the designs became more contemporary, typically with a horizontal emphasis and a stronger placement of the carport. Later work became more abstracted from regional traditions, as Register and fellow architects introduced angled and splayed wall enclosures. Equally during this time, the use of glazing across the front and back elevations increased, with insertion of glass doors. While the forms and elevations were contemporary, Register continued to include regional revival elements, mostly confined to the use of canales and viga-roof portales and carports.

VII. Resource Evaluation

Existing Status

Currently, nine of the 27 freestanding structures have been assigned an historical status. Of these, eight were determined at the time to be Noncontributing (101, 102, 103 Camino Santiago and 104, 107, 109, 111, 116/120 Camino Matias) to the Downtown and Eastside Historic District (Map 1). The one Contributing structure is a 1950 teacher's cottage, located at 105 Camino Matias.

Integrity

Based on the survey, the majority of buildings were found to retain their integrity of location, design and setting. Many, if not most, have experienced a change in materials, principally through replacement of doors and windows. Only three buildings (102 and 110 (112) Camino Santiago and 116/120 Camino Matias) have received a major addition.

Evaluation

The north half of the former Plaza del Monte Presbyterian retirement center holds an array of buildings constructed in different phases between roughly 1950 and 1977. The earliest buildings are associated with the Allison-James School, which was demolished in 1960. The remaining 22 units were built as part of Plaza del Monte.

The inventory determined that of the Plaza del Monte ear buildings, 12 met (or will meet) the 50-year age mark in 2018 (Table of Surveyed Resources and Map 2). Five of these were deemed to be good examples of the development's original design template, developed by Kenneth S. Clark and Philippe Register and later, Phillipe Register. These are mostly compatible with the Old and Recent Santa Fe styles, because of their Spanish-Pueblo Revival façade treatment. The recommended Contributing houses, show a balanced composition, where the carport is set back from the portal.

The remaining seven age-eligible structures were determined Noncontributing, due to their more contemporary forms and façade treatments. In many cases, they are Contemporary-style designs dressed with regional elements, and do not represent the Recent Santa Fe Style. While novel, the use of angled and canted walls and other treatments does not contribute to the historic district or reflect the intent of the ordinance. In addition, the strong placement of

carports was found to be incompatible with the Spanish-Pueblo Revival idiom or the intent of the district ordinance.

The ten buildings constructed after 1968 were deemed Noncontributing, as they did not meet the 50-year age requirement.

Historic District

The surveyed area comprises only half of what was once a larger campus. The earliest and most architecturally significant part of the campus lay south of the retirement residences, as the Congregate Home. This building and several ancillary structures were demolished in 2017. This land is now under different ownership.

The section comprising the retirement houses reveals a mixed lineage. It encompasses buildings that predate Plaza del Monte, as well as disparate retirement units constructed during multiple phases of work, starting in 1960 and ending in 1977.

The original design for the retirement campus is represented in only a few buildings. The remaining units move away from that template and reflect more evolving architectural trends. In this way, the development does not communicate a unified history, pattern of development, or unified architectural vocabulary, as found with other multi-phased communities in Santa Fe.

Given its disparate origins and lack of cohesive architectural style, it was determined that the collection of retirement residences is not eligible for separate Historic District designation.

VIII. Table of Surveyed Resources

Address	Year Built*	Architect Date of Drawings	Existing Status	Recommended Status	First City Directory Entry
CAMINO SANTIAGO					
101	c.1967-68	Unknown	Non Contributing	Non Contributing	1967 "Under Construction"
102 R-2	c.1965	Kenneth S. Clark & Philippe Register, assumed	Non Contributing	Contributing	1966 Gaylord Knox
103 R-12	c.1965	Philippe Register 1962	Non Contributing	Contributing	1966 Joseph M. McNeill
105 R-14	1971	Register, Ross & Burnet 1970	No Status	Non Contributing	1972 Ruth Erwin and Ellen Foster
106 R-3	c.1965	Kenneth S. Clark & Philippe Register, assumed	No Status	Contributing	1966 Deforest N. Shotwell
R-15	c.1965	Philippe Register 1963	No Status	Non Contributing	1966 Jane Barber
110 (112) R-5	c.1962/ c.1968	Kenneth S. Clark 1962, original house; Register, Ross & Burnet, addition	No Status	Non Contributing	1966 Dorothy B. Fritz (110) 1970 Theo R. Finley (112)
111	c.1965	Philippe Register 1963	No Status	Contributing	1966 Neva B. Palameter
113	c.1970	Unknown	No Status	Non Contributing	1971 Harry B. Wood
114 R-26	c.1972	Register, Ross & Burnet 1971	No Status	Non Contributing	1972 "Under Construction"
115	c.1970	Unknown	No Status	Non Contributing	1971 Westley L. Almy

Address	Year Built*	Architect Date of Drawings	Existing Status	Recommended Status	First City Directory Entry
117	1966-67	Philippe Register 1965; 1966	No Status	Non Contributing	1967 Reverend David H. Thomas
118	c.1973	Register, Ross & Burnet 1971 Register & Burnet 1972	No Status	Non Contributing	1974 Duncan R. Spinning
119	c.1965	Philippe Register 1965/1968	No Status	Non Contributing	1966 Muriel M. Boone
120 R-25	c. 1971	Register, Ross & Burnet 1970	No Status	Non Contributing	1972 Ovid Sellers
121 R-20	c.1971	Register, Ross & Burnet 1970	No Status	Non Contributing	1972 Boyd L. Gilbert
122	c.1971	Register, Ross & Burnet 1967	No Status	Non Contributing	1972 Dewitt Safford
1 3	c.1968	Philippe Register 1967	No Status	Non Contributing	1968 "Under Construction"
125 R-21	c.1970	Register, Ross & Burnet 1969	No Status	Non Contributing	1971 John M. Currie, Violet Sherratt, Merrrill Henry, Warren Blodgett
126 R-24	c.1968	Philippe Register 1967	No Status	Non Contributing	1968 "Under Construction"
126 Garage	c.1968/ 1977	Unknown		Non Contributing	N/A
CAMINO MATIAS					
104	c.1965	Kenneth S. Clark & Philippe Register, assumed; Philippe Register 1963, alteration	Non Contributing	Contributing	1966 Frederick Dawson
105 R-10	1950	Unknown	Contributing	Non Contributing	N/A Pre-existing Building

Address	Year Built*	Architect Date of Drawings	Existing Status	Recommended Status	First City Directory Entry
107 R-9	1950	Unknown	Non Contributing	Non Contributing	N/A Pre-existing Building
109 R-8	1950	Unknown	Non Contributing	Non Contributing	N/A Pre-existing Building
111 R-6	Pre-1960, moved to site	Unknown	Non Contributing	Non Contributing	N/A Pre-existing Building
116/120 R-7	Pre-1957, with c.1984 additions	Unknown; Philippe Register and Associates 1984	Non Contributing	Non Contributing	N/A Pre-existing Building

** The date of construction is derived from a number of sources, including original drawings, aerial photographs, USGS quadrangle maps, city directory entries and newspaper accounts. The identified construction date is considered for more accurate than dates provided by the Santa Fe County Assessor records, which are often inaccurate.*

IX. Bibliography

Atkins, Carolyn. *The Allison-James Picture Book, 1866-1959*. Albuquerque: Menaul Historical Library of the Southwest, 1983.

Bunting, Bainbridge. *Architecture in New Mexico*. Albuquerque: University of New Mexico Press, 1976.

Bunting, Bainbridge and John P. Conron. "The Architecture of Northern New Mexico." New Mexico Architecture. Vol. 8 Nos. 9 and 10, September-October 1966: 14-50.

Mathiasen, Geneva and Edward H. Noakes, editors. *Planning Homes for the Aged*. New York: F.W. Dodge Corporation, 1959.

Santa Fe New Mexican (newspaper). Various issues: 1958-2016.

Sze, Corrine P. and Beverly Spears. *Santa Fe Historic Neighborhood Study*. Report prepared for the City of Santa Fe, 1988.

Works Progress Administration. "History of the Allison-James School." No date. Typed manuscript. "Presbyterian Church" vertical file, Fray Angélico Chávez Library, Santa Fe.

X. Maps and Aerial Photographs



Map 1: Currrent Historic Status Designations.
Source: City of Santa Fe GIS, Historic Districts Overlay.

Map 2: Recommended Status made by consultant.
Source: City of Santa Fe GIS, Historic Districts Overlay.



Map 3: 1948 map showing extent of Allison-James School campus.
All buildings except for structure in dashed box were demolished in 1960 to create Plaza del Monte.
Source: 1930/1948 Sanborn Fire Insurance Map.



Aerial 1: 1951 Aerial Photograph.
Dashed box indicates presence of three married residences.
Courtesy NMDOT.



Aerial 2: November 10, 1958 Aerial Photograph. Dashed box indicates presence of combined unit, currently addressed as 116/120 Camino Matias. Courtesy NMDOT.

Aerial 3: May 2, 1966 Aerial Photograph.
Images indicates eight residences had been completed at this time.
Courtesy NMDOT.

Aerial 4: February 27, 1969 Aerial Photograph. Image shows residences constructed to date. Courtesy NMDOT.

XI. Historic Cultural Properties Inventory Forms

See attached forms

PLAZA DEL MONTE

Santa Fe, New Mexico
Historic Resources Evaluation

Amendment to March 28, 2018 Report

May 7, 2018

Client: Wayne S. Lloyd, A.I.A.
Lloyd and Associates, Architects
100 N Guadalupe Street, # 201
Santa Fe, NM 87501

Consultant: John W. Murphey
Architectural Historian
2833 Plaza Verde
Santa Fe, NM 87507

RECEIVED
MAY 08 2018
BY:_____

Introduction

This brief amendment addresses issues the Historic Districts Review Board brought up at the April 24, 2018 hearing, as well as information requested by the City of Santa Fe Historic Preservation Division after the hearing.

Retaining Walls: 124 and 126 A Camino Santiago

David Rasch, the case manager for the project, communicated to the applicant after the hearing that the retaining walls of the two units granted demolition by the Board required documentation.

On May 3, 2018, the consultant recorded the retaining walls at 124 and 126 A Camino Santiago (the combined garage/carport structure), associated with the two units granted demolition at the April 24, 2018 hearing.

Both units include low concrete-and-stone walls which work as retaining walls and/or transitions between building pads.

The wall for 126 A retains the dirt between the apartment building (126) and the parking stalls. It is constructed of non-reinforced concrete, mixed with heavy stones most likely taken from the adjacent arroyo (Figure 1).

The wall is erected over a concrete walkway and stands approximately 32" above the sidewalk and 14" above the contained earth. The 10"-thick structure presents an angled face similar to a dam. It is topped with rounded concrete coping. The wall runs the length of the parking structure before tapering to the ground on the west and rising above grade to the east as a pathway entry.

A wall of similar composition edges the south and east exposures of the back yard of 124 Camino Santiago (Figure 2). It begins at 9½" above grade at the patio, and continues in a northerly direction, ranging between 18" to 26" above inside grade. Near the northeast tangent, it connects with another wall erected with the construction of 122 Camino Santiago.

Based on aerial photographs, neither the 124 nor 126 A retaining walls predate the construction of their associated units. And while this fact is inconclusive, neither wall is visible on the February 28, 1968 aerial photograph (Aerial 1). The retaining walls are apparent on a February 27, 1969 photograph, indicating the completion of the units and their landscaping (Aerial 2).

Given their low architectural value, and assumed c.1968+ construction date, neither is recommended for Contributing Structure status to the Downtown and Eastside Historic District.

Additional Walls

As stated in the Historic Resources Evaluation, the Plaza del Monte landscape includes a number of retaining walls. The retaining walls, constructed of formed concrete or concrete and stone, were built over several phases, dating generally between 1950 and 1973. The walls were constructed to retain earth or to separate building pads (Figure 3). Very few of them rise above grade. A few lots have above-ground property line walls. These are made of stucco-clad concrete masonry units (Figure 4). From aerial photographs, both retaining and property line walls appear to post-date the construction of their associated units.

Given their recent date of construction and utilitarian quality, the retaining and property walls are not recommended for individual or collective Contributing Structure status to the Downtown and Eastside Historic District.

Aerial Imagery

To address the Board's concern over the lack of c.1968-69 aerial imagery for the west side of Plaza del Monte, the consultant approached the NMDOT seeking additional photographs.

The head of aerial photography, Alane Wainwright, confirmed in an April 30 email to the consultant that the February 27, 1969 aerial (1969_02_27_4072) presented in the Historic Resources Evaluation represented the end of the flight line. The email supported her January 17, 2018 communication, which asserted that the image was all that the NMDOT could offer. Wainwright explained in that email that the image didn't "get the entire area."[1]

However, given the importance of the case, on April 30 Wainwright performed an additional due-diligence search and found three 1968-69 era photographs that are not available to the public.[2] These include two secondary images from the February 27, 1969 flight and one from February 28, 1968. Wainwright additionally provided several images from May 1973.

Both the 1968 and 1969 aerials show the southwest quadrant of Plaza del Monte to be populated with only two structures: 124 and 126 Camino Santiago (Aerials 1 & 2).

---

[1] Alane Wainwright, email communication to John Murphey, January 17, 2018.
[2] Ibid., April 30, 2018.

The newly revealed aerial photographs present a strong case that only a handful of units were fully completed by February 28, 1968. The 1973 image shows most of the units finished, and 118 Camino Santiago still in the framing stage (Aerial 3).

Construction Dates

At the April 24, 2018 hearing, the Board expressed apprehension about the report's assigned construction dates. The dates were premised on the consultant's methodology which used various sources (primarily aerial photographs, city directory entries, and architectural drawings), to arrive at a relative — though most often accurate — "circa" date of construction.

Sowing confusion was mention of a 1988 appraiser's estimate of dates introduced during sworn testimony. This information was neither viewed by the Board nor officially introduced into the record.

Given the Board's questioning, the consultant reviewed the sources again, examined the 1988 appraiser's estimates, and evaluated the additional aerial photographs recently made available. This analysis is presented in the table below.

After this exercise, the consultant believes that the Historic Resources Evaluation's assigned dates of construction are mainly accurate.

Table 1: Year of Construction

Address	Year Built*	Date of Drawings	1988 Appraiser's Estimate**	Consultant's Original and/or Revised Estimate ***	Source and Justification
CAMINO SANTIAGO					
101	c.1967-68	Unknown	1968	c.1967-68	Aerial photographs and first city directory
102 R-2	c.1965	Kenneth S. Clark & Philippe Register, assumed	1962 *Appraiser assigns address to Camino Matias*	Before 1966	May 2, 1966 aerial photograph and first city directory entry
103 R-12	c.1965	Philippe Register 1962	1968	Before 1966	May 2, 1966 aerial photograph and first city directory entry
105 R-14	1971	Register, Ross & Burnet 1970	1962	1971	Does not appear on either May 2, 1966 or February 27, 1969 aerial photographs Drawing, aerial photographs and first city directory entry
106 R-3	c.1965	Kenneth S. Clark & Philippe Register, assumed	1962 *Appraiser assigns address to Camino Matias*	Before 1966	May 2, 1966 aerial photograph and first city directory entry
109 R-15	c.1965	Philippe Register 1963	1963	Before 1966	May 2, 1966 aerial photograph and first city directory entry
110 (112) R-5	c.1962/ c.1968	Kenneth S. Clark 1962, original house; Register, Ross & Burnet, addition	110: 1962 112: 1968	110: c.1962 112: c.1968	Drawings, aerial photographs and first city directory entries
111	c.1965	Philippe Register 1963	Unknown; remodeled, 1962	Before 1966	Drawings, aerial photographs and first city directory entry
113	c.1970	Unknown	1970 *Appraiser assigns address as 115 a*	c.1970	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry
114 R-26	c.1972	Register, Ross & Burnet 1971	1971	c.1972	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry
115	c.1970	Unknown	1970	c.1970	Does not appear on February 27, 1969 aerial photograph First city directory entry
117	1966-67	Philippe Register 1965; 1966	Unknown; estimated 1963-1968	1966-67	May 2, 1966 aerial photograph and first city directory entry

Address	Year Built*	Date of Drawings	1988 Appraiser's Estimate**	Consultant's Original and/or Revised Estimate ***	Source and Justification
118	c.1973	Register, Ross & Burnet 1971 Register & Burnet 1972	1972	**1973**	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry
119	c.1965	Philippe Register 1965/1968	1963	**Before 1966**	May 2, 1966 aerial photograph and first city directory entry
120 R-25	c. 1971	Register, Ross & Burnet 1970	1970	c. 1971	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry
121 R-20	c.1971	Register, Ross & Burnet 1970	1970	c.1971	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry
122	c.1971	Register, Ross & Burnet 1967	Unknown; estimated 1963-1968	c.1971	Does not appear on February 27, 1969 aerial photograph First city directory entry
124 R-23	c.1968	Philippe Register 1967	1964	c.1968	Does not appear on May 2, 1966 aerial photograph.
125 R-21	c.1970	Register, Ross & Burnet 1969	1969	c.1970	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry
126 R-24	c.1968	Philippe Register 1967	1967	c.1968	Drawings, aerial photographs and first city directory entry
126 Garage	c.1968/ 1977	Unknown	No covered	c.1968/ 1977	Drawings and April 9, 1975 aerial photograph
CAMINO MATIAS					
104	c.1965	Kenneth S. Clark & Philippe Register, assumed; Philippe Register 1963, alteration	1962	**Before 1966**	May 2, 1966 aerial photograph
105 R-10	1950	Unknown	Unknown; remodeled 1962	1950	Carolyn Atkins, *The Allison-Jomes Picture Book, 1866-1959*, (Albuquerque: Menaul Historical Library of the Southwest, 1983), 25; aerial photographs
107 R-9	1950	Unknown	Unknown; remodeled 1962	1950	Carolyn Atkins, *The Allison-James Picture Book, 1866-1959*, (Albuquerque: Menaul Historical Library of the Southwest, 1983), 25; aerial photographs
109 R-8	1950	Unknown	Unknown; remodeled 1962	1950	Carolyn Atkins, *The Allison-James Picture Book, 1866-1959*, (Albuquerque: Menaul Historical Library of the

Address	Year Built*	Date of Drawings	1988 Appraiser's Estimate**	Consultant's Original and/or Revised Estimate ***	Source and Justification
					Southwest, 1983), 25; aerial photographs
111 R-6	Pre-1960, moved to site	Unknown	Unknown; remodeled 1962	Pre-1960, moved to site	Aerial photographs
116/120 R-7	Pre-1957, with c.1984 additions	Unknown; Philippe Register and Associates 1984	110: Unknown; renovated 1967; remodeled 1986 120: remodeled/ Renovated 1962	Pre-1957, with c.1984 additions	Drawings and aerial photographs

Key:

**The year the consultant originally estimated, as presented in March 28, 2018,* Plaza del Monte, Santa Fe, Historic Resources Evaluation *report.*

*** Taken from "As of 1988" table of appraiser's estimate of construction dates. The table was referenced in sworn testimony during the April 24, 2018, Historic Districts Review Board hearing. The Board did not see the table nor was it introduced in the record. The consultant took an iPhone image of the table at the hearing (Figure 3).*

**** The consultant's original and/or revised estimate based on best sources available, including dated aerial photographs, dated architectural drawings and dated city directory entries, and previously publicly unavailable February 28, 1968 and February 27, 1969 aerial photographs, NMDOT provided to consultant on April 30, 2018.*

Figures and Aerial Photographs

Figure 1: 126 A Camino Santiago, Garage/Carport Structure, retaining wall, May 3, 2018.

Figure 2: 124 Camino Santiago, rear retaining wall, May 3, 2018.

Figure 3: c.1950 concrete retaining in front of 107 Camino Matias. January 18, 2018.



Figure 4: Stucco-on-block property wall between 114 and 118 Camino Santiago, January 18, 2018.



IMPROVEMENT SUMMARY CHART
LAS PLACITAS RESIDENTIAL COMPOUND
PLAZA DEL MONTE

I.D.	Street Address	Type of Dwelling	Area (Sq.Ft.)	Room Count (Total-Bedrooms-Baths)	Age (Yrs.)	Comments
R-1	104 Camino Matias	Single-Family	944	4-2-1.5	26	
R-2	102 Camino Matias	Single-Family	944	4-2-1.5	26	
R-3	106 Camino Matias	Single-Family	944	4-2-1.5	26	
R-4	118 Camino Santiago	Single-Family	1,141	5-2-2	16	
R-5a	110 Camino Matias	Duplex	897	5-2-1	26	
R-5b	112 Camino Matias	Duplex	839	4-1-1	26	Addition 1968
R-6	111 Camino Matias	Single-Family	1,433	6-3-2	Unknown	Remodeled/Renovated 1962
R-7a	116 Camino Matias	Duplex	1,072	4-2-2	Unknown	Renovated 1967, Remodeled 1986
R-7b	120 Camino Matias	Duplex	1,099	4-2-2	Unknown	Renovated 1962, Remodeled 1986
R-8	109 Camino Matias	Single-Family	1,095	5-2-1	Unknown	Remodeled/Renovated 1962
R-9	107 Camino Matias	Single-Family	932	4-2-1	Unknown	Remodeled/Renovated 1962
R-10	105 Camino Matias	Single-Family	932	5-2-1	Unknown	Remodeled/Renovated 1962
R-11	101 Camino Santiago	Single-Family	1,163	4-2-1	20	
R-12	103 Camino Santiago	Single-Family	1,064	5-2-2	20	
R-14a	105a Camino Santiago	Fourplex	926	4-2-1	26	
R-14b	105b Camino Santiago	Fourplex	699	3-2-1	26	
R-14c	105c Camino Santiago	Fourplex	699	3-2-1	26	
R-14d	105d Camino Santiago	Fourplex	926	4-2-1	26	
R-15	109 Camino Santiago	Single-Family	1,029	4-2-2	25	
R-16	111 Camino Santiago	Single-Family	1,082	4-2-2	25	
R-17a	115a Camino Santiago	Duplex	1,052	4-2-2	18	
R-17b	115b Camino Santiago	Duplex	1,179	4-2-2	18	
R-18	117 Camino Santiago	Single-Family	1,356	6-2-2	Unknown	Estimated effective age 20-25 yrs.
R-19	119 Camino Santiago	Single-Family	1,105	5-2-1	25	
R-20	121 Camino Santiago	Single-Family	1,152	5-2-2	18	
R-21a	125a Camino Santiago	Fourplex	944	4-2-1	19	
R-21b	125b Camino Santiago	Fourplex	676	3-2-1	19	
R-21c	125c Camino Santiago	Fourplex	676	3-2-1	19	
R-21d	125d Camino Santiago	Fourplex	944	4-2-1	19	
R-22	122 Camino Santiago	Single-Family	1,218	5-2-2	Unknown	Estimated effective age 20-25 yrs.
R-23	124 Camino Santiago	Single-Family	1,153	4-2-2	21	
R-24a	126a Camino Santiago	Fourplex	690	3-1-1	21	
R-24b	126b Camino Santiago	Fourplex	690	3-1-1	21	
R-24c	126c Camino Santiago	Fourplex	690	3-1-1	21	
R-24d	126d Camino Santiago	Fourplex	690	3-1-1	21	
R-25	120 Camino Santiago	Single-Family	1,259	5-2-2	18	
R-26	114 Camino Santiago	Single-Family	1,318	4-2-2	17	

Figure 5: iPhone image of c.1988 Plaza del Monte appraiser report referenced at April 24, 2018 hearing.

Aerial 1: Portion of February 28, 1968 aerial photograph. Source: NMDOT – 02_28_68_0021.

Aerial 2: Portion of February 27, 1969 aerial photograph. Source: NMDOT – 1969_2_27_4071.



Aerial 3: Portion of May 11, 1973 aerial photograph showing 118 Camino Santiago under construction. Source: NMDOT- 05-11-73_0053.

PLAZA DEL MONTE

Santa Fe, New Mexico
Historic Resources Evaluation

Second Amendment to March 28, 2018 Report

May 17, 2018

Client: Wayne S. Lloyd, A.I.A.
Lloyd and Associates, Architects
100 N Guadalupe Street, # 201
Santa Fe, NM 87501

Consultant: John W. Murphey
Architectural Historian
2833 Plaza Verde
Santa Fe, NM 87507

Introduction

This second amendment addresses issues the Historic Districts Review Board brought up at the April 24, 2018 hearing, information requested by the City of Santa Fe Historic Preservation Division after that hearing, and additional comments made by the Board at the follow-up May 17, 2018 hearing.

Retaining Walls: 124 and 126 A Camino Santiago

David Rasch, the case manager for the project, communicated to the applicant after the April 24 hearing that the retaining walls of the two units granted demolition by the Board required documentation.

On May 3, 2018, the consultant recorded the retaining walls at 124 and 126 A Camino Santiago (the combined garage/carport structure), associated with the two units granted demolition.

Both units include low concrete-and-stone walls which work as retaining walls and/or transitions between building pads.

The wall for 126 A retains the dirt between the apartment building (126) and the parking stalls. It is constructed of non-reinforced concrete, mixed with heavy stones most likely taken from the adjacent arroyo (Figure 1).

The wall is erected over a concrete walkway and stands approximately 32" above the sidewalk and 14" above the contained earth. The 10"-thick structure presents an angled face similar to a dam. It is topped with rounded concrete coping. The wall runs the length of the parking structure before tapering to the ground on the west and rising above grade to the east as a pathway entry.

A wall of similar composition but of lesser height edges the south and east exposures of the back yard of 124 Camino Santiago (Figure 2). It begins at 9½" above grade at the patio, and continues in a northerly direction, ranging between 18" to 26" above inside grade. Near the northeast tangent, it connects with another wall erected with the construction of 122 Camino Santiago.

Based on aerial photographs, neither the 124 nor 126 A retaining walls predate the construction of their associated units. And while this fact is inconclusive, neither wall is visible on the February 28, 1968 aerial photograph (Aerial 2). The retaining walls are apparent on a

February 27, 1969 photograph, indicating the completion of the units and their landscaping (Aerial 3).

Given their low architectural value, and assumed c.1968+ construction date, neither is recommended for Contributing Structure status to the Downtown and Eastside Historic District.

Additional Walls

As stated in the Historic Resources Evaluation, the Plaza del Monte landscape includes a number of retaining walls. The retaining walls, constructed of formed concrete or concrete and stone, were built over several phases, dating generally between 1950 and 1973. The walls were constructed to retain earth or to separate building pads (Figure 3). Very few of them rise above grade. A few lots have above-ground property line walls. These are made of stucco-clad concrete masonry units (Figure 4). From aerial photographs, both retaining and property line walls appear to post-date the construction of their associated units.

Given their recent date of construction and utilitarian quality, the retaining and property walls are not recommended for individual or collective Contributing Structure status to the Downtown and Eastside Historic District.

Aerial Imagery

To address the Board's concern over the lack of c.1968-69 aerial imagery for the west side of Plaza del Monte, the consultant approached the NMDOT seeking additional photographs after the April 24 hearing.

The head of aerial photography, Alane Wainwright, confirmed in an April 30 email to the consultant that the February 27, 1969 aerial (1969_02_27_4072) presented in the Historic Resources Evaluation represented the end of the flight line. The email supported her January 17, 2018 communication, which asserted that the image was all that the NMDOT could offer. Wainwright explained in that email that the image didn't "get the entire area."[1]

However, given the importance of the case, Wainwright performed an additional due-diligence search and found three 1968-69 era photographs that are not available to the public.[2] These

[1] Alane Wainwright, email communication to John Murphey, January 17, 2018. See chain of communication in Appendix A.
[2] Ibid., April 30, 2018.

include two secondary images from the February 27, 1969 flight and one from February 28, 1968. Wainwright additionally provided several photographs from May 1973.

Both the 1968 and 1969 aerials show the southwest quadrant of Plaza del Monte to be populated with only two structures: 124 and 126 Camino Santiago (Aerials 2 & 3).

The newly revealed aerial photographs present a strong case that only a handful of units were fully completed by February 28, 1968. The 1973 image shows most of the units finished, and 118 Camino Santiago still in the framing stage (Aerial 4).

At the follow-up May 15, 2018 hearing, member Powell expressed suspicion over the fact that additional aerial photographs had surfaced after the initial hearing. The consultant includes with this amendment the entire email communication with NMDOT's Alane Wainwright. The communications on January 16, January 17, April 26, April 30 and May 1 are specific to this subject (Appendix A).

Construction Dates

At the April 24, 2018 hearing, a few members of the Board expressed apprehension about the report's assigned construction dates. The dates were premised on the consultant's methodology which used various sources (primarily aerial photographs, city directory entries, and architectural drawings), to arrive at a relative — though most often accurate — "circa" date of construction.

Sowing confusion was mention of a 1988 appraiser's estimate of dates introduced during sworn testimony. This information was neither viewed by the Board nor officially introduced into the record.

Given the Board's questioning, the consultant reviewed the sources again, examined the 1988 appraiser's estimates, and evaluated the additional aerial photographs recently made available. This analysis is presented in Table 1.

At the follow-up hearing, member Powell continued to question the dates of construction provided by the consultant, pointing to differing years he found on the Santa Fe County Assessor's parcel map website, from his cellphone during the hearing. The consultant had already discarded the county's dates as being mostly inaccurate, as noted in the Table of Surveyed Resources in the March 28 report. But given Powell's insistence, the consultant reviewed the assessor's dates again on May 17, and identifies the errors in the county's

estimates in Table 2. In general, the county's dates do not comport with evidence found on aerial photographs.

At conclusion of both exercises, the consultant believes that the Historic Resources Evaluation's assigned dates of construction are mainly accurate. The consultant, however, because of timing issues, did not get to review additional material that may have surfaced at the Santa Fe Presbyterian church library or the Menaul facility.

Table 1: Year of Construction

Address	Year Built*	Date of Drawings	1988 Appraiser's Estimate**	Consultant's Original and/or Revised Estimate ***	Source and Justification
CAMINO SANTIAGO					
101	c.1967-68	Unknown	1968	**c.1967-68**	Aerial photographs and first city directory
102 R-2	c.1965	Kenneth S. Clark & Philippe Register, assumed	1962 *Appraiser assigns address to Camino Matias*	**Before 1966**	May 2, 1966 aerial photograph and first city directory entry
103 (-12	c.1965	Philippe Register 1962	1968	**Before 1966**	May 2, 1966 aerial photograph and first city directory entry
105 R-14	1971	Register, Ross & Burnet 1970	1962	**1971**	Does not appear on either May 2, 1966 or February 27, 1969 aerial photographs Drawing, aerial photographs and first city directory entry
106 R-3	c.1965	Kenneth S. Clark & Philippe Register, assumed	1962 *Appraiser assigns address to Camino Matias*	**Before 1966**	May 2, 1966 aerial photograph and first city directory entry
109 R-15	c.1965	Philippe Register 1963	1963	**Before 1966**	May 2, 1966 aerial photograph and first city directory entry
110 (112) R-5	c.1962/ c.1968	Kenneth S. Clark 1962, original house; Register, Ross & Burnet, addition	110: 1962 112: 1968	110: c.**1962** 112: **c.1968**	Drawings, aerial photographs and first city directory entries
111	c.1965	Philippe Register 1963	Unknown; remodeled, 1962	**Before 1966**	Drawings, aerial photographs and first city directory entry
113	c.1970	Unknown	1970 *Appraiser assigns address as 115 a*	**c.1970**	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry

ddress	Year Built*	Date of Drawings	1988 Appraiser's Estimate**	Consultant's Original and/or Revised Estimate ***	Source and Justification
114 R-26	c.1972	Register, Ross & Burnet 1971	1971	**c.1972**	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry
115	c.1970	Unknown	1970	**c.1970**	Does not appear on February 27, 1969 aerial photograph First city directory entry
117	1966-67	Philippe Register 1965; 1966	Unknown; estimated 1963-1968	**1966-67**	May 2, 1966 aerial photograph and first city directory entry
118	c.1973	Register, Ross & Burnet 1971 Register & Burnet 1972	1972	**1973**	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry
119	c.1965	Philippe Register 1965/1968	1963	**Before 1966**	May 2, 1966 aerial photograph and first city directory entry
120 R-25	c. 1971	Register, Ross & Burnet 1970	1970	**c. 1971**	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry
121 R-20	c.1971	Register, Ross & Burnet 1970	1970	**c.1971**	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry
122	c.1971	Register, Ross & Burnet 1967	Unknown; estimated 1963-1968	**c.1971**	Does not appear on February 27, 1969 aerial photograph First city directory entry
124 R-23	c.1968	Philippe Register 1967	1964	**c.1967**	Does not appear on May 2, 1966 aerial photograph.
125 R-21	c.1970	Register, Ross & Burnet 1969	1969	**c.1970**	Does not appear on February 27, 1969 aerial photograph Drawings and first city directory entry
126 R-24	c.1968	Philippe Register 1967	1967	**c.1967**	Drawings, aerial photographs and first city directory entry
126 Garage	c.1968/ 1977	Unknown	No covered	**c.1968/ 1977**	Drawings and April 9, 1975 aerial photograph
CAMINO MATIAS					
104	c.1965	Kenneth S. Clark & Philippe Register, assumed; Philippe Register 1963, alteration	1962	**Before 1966**	May 2, 1966 aerial photograph

ddress	Year Built*	Date of Drawings	1988 Appraiser's Estimate**	Consultant's Original and/or Revised Estimate ***	Source and Justification
105 R-10	1950	Unknown	Unknown; remodeled 1962	**1950**	Carolyn Atkins, *The Allison-James Picture Book, 1866-1959*, (Albuquerque: Menaul Historical Library of the Southwest, 1983), 25; aerial photographs
107 R-9	1950	Unknown	Unknown; remodeled 1962	**1950**	Carolyn Atkins, *The Allison-James Picture Book, 1866-1959*, (Albuquerque: Menaul Historical Library of the Southwest, 1983), 25; aerial photographs
109 R-8	1950	Unknown	Unknown; remodeled 1962	**1950**	Carolyn Atkins, *The Allison-James Picture Book, 1866-1959*, (Albuquerque: Menaul Historical Library of the Southwest, 1983), 25; aerial photographs
111 R-6	Pre-1960, moved to site	Unknown	Unknown; remodeled 1962	**Pre-1960, moved to site**	Aerial photographs
116/120 R-7	Pre-1957, with c.1984 additions	Unknown; Philippe Register and Associates 1984	110: Unknown; renovated 1967; remodeled 1986 120: remodeled/ Renovated 1962	**Pre-1957, with c.1984 additions**	Drawings and aerial photographs

Key:

**The year the consultant originally estimated, as presented in March 28, 2018,* Plaza del Monte, Santa Fe, Historic Resources Evaluation *report.*

*** Taken from "As of 1988" table of appraiser's estimate of construction dates. The table was referenced in sworn testimony during the April 24, 2018, Historic Districts Review Board hearing. The Board did not see the table nor was it introduced in the record. The consultant took an iPhone image of the table at the hearing (Figure 5).*

**** The consultant's original and/or revised estimate based on best sources available, including dated aerial photographs, dated architectural drawings and dated city directory entries, and previously unavailable February 28, 1968 and February 27, 1969 aerial photographs, NMDOT provided to consultant on April 30, 2018.*

Table 2: Santa Fe County Assessor Dates

Address	Consultant's Original and/or Revised Estimate *	Santa Fe County Assessor Estimate**	Errors with County Estimated Dates
CAMINO SANTIAGO			
101	c.1967-68	1964	Does not appear on May 2, 1966 aerial photograph
102 R-2	Before 1966	1964	Only May 2, 1966 aerial photograph available for the period
103 R-12	Before 1966	1964	Does not appear on May 2, 1966 aerial photograph
105 R-14	1971	1964	Does not appear on either May 2, 1966 or February 27, 1969 aerial photographs
106 R-3	Before 1966	1964	Only May 2, 1966 aerial photograph available for the period
109 R-15	Before 1966	1964	Only May 2, 1966 aerial photograph available for the period
110 112) R-5	110: c.1962 112: c.1968	1969	Appears on May 2, 1966 aerial photograph
111	Before 1966	No Date Provided	
113	c.1970	1964	Does not appear on either May 2, 1966 or February 27, 1969 aerial photographs
114 R-26	c.1972	No Date Provided	
115	c.1970	1964	Does not appear on either May 2, 1966 or February 27, 1969 aerial photographs
117	1966-67	1964	Only May 2, 1966 aerial photograph available for the period
118	1973		Does not appear on February 27, 1969 aerial photograph; still under construction on May 3, 1973 aerial photograph
119	Before 1966	1969	Appears on May 2, 1966 aerial photograph
120 R-25	c. 1971	1968	Does not appear on February 27, 1969 aerial photograph

ddress	Consultant's Original and/or Revised Estimate *	Santa Fe County Assessor Estimate**	Errors with County Estimated Dates
121 R-20	c.1971	1969	Does not appear on February 27, 1969 aerial photograph
122	c.1971	1968	Does not appear on February 27, 1969 aerial photograph
124 R-23	c.1967	1968	
125 R-21	c.1970	No Date Provided	
126 R-24	c.1967	No Date Provided	
126 Garage	c.1968/ 1977	No Date Provided	
CAMINO MATIAS			
104	Before 1966	1968	Appears on May 2, 1966 aerial photograph
05 R-10	1950	1964	Documented as constructed in 1950 in Carolyn Atkins, *The Allison-James Picture Book, 1866-1959*, (Albuquerque: Menaul Historical Library of the Southwest, 1983), 25, and appears on 1951 aerial photograph
107 R-9	1950	1964	Documented as constructed in 1950 in Carolyn Atkins, *The Allison-James Picture Book, 1866-1959*, (Albuquerque: Menaul Historical Library of the Southwest, 1983), 25, and appears on 1951 aerial photograph
109 R-8	1950	1964	Documented as constructed in 1950 in Carolyn Atkins, *The Allison-James Picture Book, 1866-1959*, (Albuquerque: Menaul Historical Library of the Southwest, 1983), 25, and appears on 1951 aerial photograph
111 R-6	Pre-1960, moved to site	1969	Appears on May 2, 1966 aerial photograph
116/120 R-7	Pre-1957, with c.1984 additions	No Date Provided	

Key:

**The consultant's original and/or revised estimate based on best sources available, including dated aerial photographs, dated architectural drawings and dated city directory entries, and previously unavailable February 28, 1968 and February 27, 1969 aerial photographs, NMDOT provided to consultant on April 30, 2018, and additional review of images after May 15 hearing.*

*** Dates as taken from Santa Fe County Assessor parcel map (http://assessor.santafecountynm.gov/map.php) on May 17, 2018. Webpage states the information was accurate as of April 3, 2018.*

Figures and Aerial Photographs

Figure 1: 126 A Camino Santiago, Garage/Carport Structure, retaining wall, May 3, 2018.

Figure 2: 124 Camino Santiago, rear retaining wall, May 3, 2018.

Figure 3: c.1950 concrete retaining in front of 107 Camino Matias. January 18, 2018.

Figure 4: Stucco-on-block property wall between 114 and 118 Camino Santiago, January 18, 2018.

IMPROVEMENT SUMMARY CHART
LAS PLACITAS RESIDENTIAL COMPOUND
PLAZA DEL MONTE

I.D.	Street Address	Type of Dwelling	Area (Sq.Ft.)	Room Count (Total-Bedrooms-Baths)	Age (Yrs.)	Comments
R-1	104 Camino Matias	Single-Family	944	4-2-1.5	26	
R-2	102 Camino Matias	Single-Family	944	4-2-1.5	26	
R-3	106 Camino Matias	Single-Family	944	4-2-1.5	26	
R-4	118 Camino Santiago	Single-Family	1,141	5-2-2	16	
R-5a	110 Camino Matias	Duplex	897	5-2-1	26	
R-5b	112 Camino Matias	Duplex	839	4-1-1	26	Addition 1968
R-6	111 Camino Matias	Single-Family	1,433	6-3-2	Unknown	Remodeled/Renovated 1962
R-7a	116 Camino Matias	Duplex	1,072	4-2-2	Unknown	Renovated 1967, Remodeled 1986
R-7b	120 Camino Matias	Duplex	1,099	4-2-2	Unknown	Renovated 1962, Remodeled 1986
R-8	109 Camino Matias	Single-Family	1,095	5-2-1	Unknown	Remodeled/Renovated 1962
R-9	107 Camino Matias	Single-Family	932	4-2-1	Unknown	Remodeled/Renovated 1962
R-10	105 Camino Matias	Single-Family	932	5-2-1	Unknown	Remodeled/Renovated 1962
R-11	101 Camino Santiago	Single-Family	1,163	4-2-1	20	
R-12	103 Camino Santiago	Single-Family	1,064	5-2-2	20	
R-14a	105a Camino Santiago	Fourplex	926	4-2-1	26	
R-14b	105b Camino Santiago	Fourplex	699	3-2-1	26	
R-14c	105c Camino Santiago	Fourplex	699	3-2-1	26	
R-14d	105d Camino Santiago	Fourplex	926	4-2-1	26	
R-15	109 Camino Santiago	Single-Family	1,029	4-2-2	25	
R-16	111 Camino Santiago	Single-Family	1,082	4-2-2	25	
R-17a	115a Camino Santiago	Duplex	1,052	4-2-2	18	
R-17b	115b Camino Santiago	Duplex	1,179	4-2-2	18	
R-18	117 Camino Santiago	Single-Family	1,356	6-2-2	Unknown	Estimated effective age 20-25 yrs.
R-19	119 Camino Santiago	Single-Family	1,105	5-2-1	25	
R-20	121 Camino Santiago	Single-Family	1,152	5-2-2	18	
R-21a	125a Camino Santiago	Fourplex	944	4-2-1	19	
R-21b	125b Camino Santiago	Fourplex	676	3-2-1	19	
R-21c	125c Camino Santiago	Fourplex	676	3-2-1	19	
R-21d	125d Camino Santiago	Fourplex	944	4-2-1	19	
R-22	122 Camino Santiago	Single-Family	1,218	5-2-2	Unknown	Estimated effective age 20-25 yrs.
R-23	124 Camino Santiago	Single-Family	1,153	4-2-2	21	
R-24a	126a Camino Santiago	Fourplex	690	3-1-1	21	
R-24b	126b Camino Santiago	Fourplex	690	3-1-1	21	
R-24c	126c Camino Santiago	Fourplex	690	3-1-1	21	
R-24d	126d Camino Santiago	Fourplex	690	3-1-1	21	
R-25	120 Camino Santiago	Single-Family	1,259	5-2-2	18	
R-26	114 Camino Santiago	Single-Family	1,318	4-2-2	17	

Figure 5: iPhone image of c.1988 Plaza del Monte appraiser report referenced at April 24, 2018 hearing.



Aerial 1: Portion of May 2, 1966 aerial photograph. Source: NMDOT – 05-02-66_0015.

Aerial 2: Portion of February 28, 1968 aerial photograph. Source: NMDOT – 02_28_68_0021.

Aerial 3: Portion of February 27, 1969 aerial photograph. Source: NMDOT – 1969_2_27_4071.

Aerial 4: Portion of May 11, 1973 aerial photograph showing 118 Camino Santiago under construction. Source: NMDOT- 05-11-73_0053.

Appendix A: Complete Email Communications between John Murphey and Alane Wainwright, January 16 to May 4, 2018.

(see attached)

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte	101 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory
		4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693490, -105.934887

10. Photo Information Negative: John Murphey View of: Front, south elevation, facing north.

11. Brief Description of the Property:

Situated near the east entrance to Plaza del Monte, the house is a roughly 1,332-square-foot contemporary residence constructed in 1967-68. In plan, the three-bedroom dwelling has a square form with an attached L-shaped portal and garage, giving it a combined square footprint. It presents to the street a long portal with the roof carrying over the garage. It is fenestrated with aluminum windows, primarily of a sliding operation. A paneled wood door gives entry to the residence at the east end of portal. The garage entry is fitted with a recent vinyl overhead door. Cementitious brocade stucco in a peach tone covers the frame building. The roof consists of a mixture of gravel and asphalt material. An interior parapet outlines the dwelling portion of the mass. While contemporary in form, the vigas across the portal give the residence a regional feel.

12. Who uses the property? Residence

13. Construction Date: c.1968
_x_Known _x_ Source: aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

J. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Sam M. Dean, who is listed as a tenant in the 1970 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing _x_ Non-contributing __ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte	101 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe	__ Brick	__ Composition	__ Concrete: Block
__ Concrete: Cast Stone	__ Concrete: Poured	__ Earth Plaster	__ Masonry: Simulated
__ Metal: Corrugated	__ Metal: Structural Siding	__ Metal: V-Crimp	__ Stone: Random Ashlar
Stone: __ Random Coursed	__ Stone: River Rock	__Stone: Rusticated	__ Stone: Tabular
_x_Stucco:	__ Tile: Clay	__ Vinyl Siding	__ Wood: Board and Batten
Wood: __ Horizontal Siding	__ Wood: Jacal	__ Wood: Log	__ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Casement	Aluminum	Single	11
Sliding	Aluminum	1-1	2

*Because of storm covers, the operation and material information is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel	Wood	1
Single-Leaf	½-Light	Wood	1
Garage	Sectional	Vinyl	1

12. Chimneys
N/A

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: Unknown; replaced garage door; and material and visual evidence.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	__ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other: Contemporary with Spanish-Pueblo Revival ornamentation

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2*** HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte**	**2. Location:** **101 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Representing a Contemporary design, the house does not harmonize or contribute to the historical character of the district. For this reason, the recommendation is to maintain 101 Camino Santiago a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **101 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building not present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte	2. Location: 101 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018



Figure 2: February 27, 1969 aerial photograph
Building present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **101 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street elevation and north elevations, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **101 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: Street and west elevations, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte	2. Location: 101 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Photo 3: North elevation, facing south and southwest
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 2	102 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693288, -105.935161

10. Photo Information Negative: John Murphey View of: Front, west elevation, facing northeast.

11. Brief Description of the Property:

One of the earliest units to be constructed at Plaza del Monte, 102 Camino Santiago is a 2,064-square-foot dwelling with one addition. The two-bedroom, flat-roof house faces Camino Matias. It shows to the street a façade-long portal, continuing at the south end as a single-space carport. The portal is supported by shiplap wood girders resting on round posts with double-ended corbels. Most of the portal façade is painted white. A line of vigas runs along the top of the wall. The elevation is penetrated by two doors and large windows, with the southernmost window not meeting the ordinance in regard to its distance from the corner. The north elevation facing Camino Santiago displays a variety of window openings holding tall metal casements. A shallow overhang supported by short vigas carries over most of the elevation. At the northeast corner is a roomblock-like projection holding the bedroom wing. The rear (east) elevation presents a number of alterations. The largest is a post-1969 addition, over what was a patio. The 380-square-foot addition is fenestrated with modern windows and is sheltered by a parapet-type portal. The house was constructed in c.1965; its designer/architect is unknown but assumed to be Kenneth S. Clark and Philippe Register.

12. Who uses the property? Residence

13. Construction Date: c.1965
_x_Known _x_ Source: aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North ⬆ **Box Indicates Post-1968 Addition**

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

J. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Gaylord Knox, who is listed as a tenant in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing _x_ Non-contributing __ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Contributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte Residence 2	102 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Casement	Aluminum	Single	9
Fixed	Aluminum	Single	3
Fixed	Aluminum	Single, flanked by Casement	1
Fixed	Aluminum	12	4

*Because of storm covers, the operation and material information is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel	Wood	2
Single-Leaf	Full-Light	Aluminum	1
Double	Carport Storage Doors	Wood	2

12. Chimneys
One, stucco-clad inside parapet

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: Post-1969; addition to rear, northeast corner; aerial photographs and material and visual evidence.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes: Other:

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** NRHP SRCP Criteria A B C D	
1. Name of property: **Plaza del Monte Residence 2**	**2. Location:** **102 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Constructed before 1968, and representing the original Clark and Register design template for the Plaza del Monte retirement homes, the house is a good example of the "Santa Fe style." For this reason, the recommendation is to designate 102 Camino Santiago a Contributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* NRHP SRCP Criteria A B C D	
1. Name of property: Plaza del Monte Residence 2	2. Location: 102 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building present; pre-addition.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 2	2. Location: 102 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018



Figure 2: February 27, 1969 aerial photograph
Building present, pre-addition.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte Residence 2**	**2. Location:** **102 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street elevation and south elevations, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte Residence 2**	**2. Location:** **102 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: North and street elevations, facing southeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 2	**2. Location:** 102 Camino Santiago *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: East elevation, facing northwest.
Non-historic addition on left.

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 6	103 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693597, -105.935145

10. Photo Information Negative: John Murphey View of: Front, south elevation, facing northwest.

11. Brief Description of the Property:

Roughly 1,533 square-feet, the one-story residence is designed as an L-plan form. The plan puts the bedrooms in a cube-like mass, with the remainder of the functions of the house strung along a linear spine. Its façade is defined by a long portal sheltering its entry and patio doors. The east end of the composition terminates as a one-bay carport. A line of vigas runs along the back (north) elevation supporting a short overhang. An exterior chimney breaks through the overhang, rising several feet above the roof. The house is fenestrated with an array of original and replacement aluminum windows. It is entered under the portal through a stylized wood panel door flanked by one set of sidelights. The dwelling's flat roof is outlined by a short parapet; the roof is covered with gravel. The frame structure is finished with cementitious brocade stucco in the buckskin tone. While contemporary in form, vigas used across the portal and the roomblock bedroom wing give the residence a Spanish-Pueblo Revival feel. The house was constructed in c.1965; its architect/designer is unknown but assumed to be architect Philippe Register.

12. Who uses the property? Residence

13. Construction Date: c.1965
_x_Known _x_ Source: aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

). Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Joseph McNeill, who is listed as a tenant in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing _x_ Non-contributing __ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Contributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte Residence 6	103 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Sliding	Aluminum	1-1	9
Fixed	Aluminum	Single	2

*Because of storm covers, the operation and material information is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel	Wood	1
Single-Leaf	Raised Square Panel, w/single sidelight	Wood	1

12. Chimneys
One, stucco-clad, exposed on north elevation

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: Unknown; replaced windows; visual and material evidence

HCPI Detail Form (FORM 2) *(Continued from other side)*

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes: Other:

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:	***Please complete HCPI FORM 1 before completing FORM 2***	
HCPI No._____ District No._____	___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 6**	**2. Location:** **103 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Constructed before 1968, and representing the original Clark and Register design template for the Plaza del Monte retirement homes, the house is a good example of the "Santa Fe style." For this reason, the recommendation is to designate 103 Camino Santiago a Contributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte** **Residence 6**	**2. Location:** **103 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 6**	**2. Location:** **103 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street and east elevations, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2*		
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte Residence 6**	**2. Location:** **103 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Photo 2: Street and west elevations (top), facing northeast; west elevation, facing south (Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 6	**2. Location:** 103 Camino Santiago *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: North elevation, facing southwest
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 14	105 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693730, -105.935558

10. Photo Information Negative: John Murphey View of: Front, south elevation, facing northeast.

11. Brief Description of the Property:

Forming a long, linear composition, 105 Camino Santiago is one of three apartment buildings erected at Plaza del Monte. The carport-dominated structure works its way down the slope as two L-plan units joined together at the center by a laundry room. The structure is bookended by masses holding the apartments. The larger apartments containing two bedrooms are situated in the projecting roomblocks. The apartments share a party wall at the living room. Spanning between the apartments are the carports and the laundry room. The carports are detailed with a viga-roof structure which continues as a portal along the inner apartments. The rear (north) elevation is divided into small patios. The apartments are entered through wood panel doors; solid wood doors give access to the storage units and the laundry. The original multi-light steel casement windows have been replaced with aluminum units. A short parapet follows the outline of the apartments, and is penetrated on the south, east and west elevations with cut-through metal canales. The frame structure is finished with cementitious brocade stucco in a peach tone. While contemporary in form, the vigas used across the portales and carports and the cubed apartment masses give the residence a regional feel. The roughly 4,198-square-foot apartment building was constructed in 1971, after a design by architect Philippe Register.

12. Who uses the property? Residence

13. Construction Date: 1971
_x_Known _x_ Source: aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

20. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The apartments were constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first residents identified are Ruth Erwin and Ellen Foster. They are listed as tenants in the 1972 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 14	105 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _x_ Asphalt
__ Earth __ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Sliding	Aluminum	1-1	10
Sliding	Aluminum	1-1F-1	4

*Because of storm covers, the operation and material information is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ View Light	Wood	4
Single-Leaf	Flush [?]	Wood	12
Sliding	Patio	Aluminum	8

12. Chimneys
4, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: __ _x_ No known modifications

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	__ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other: Contemporary with Spanish-Pueblo Revival ornamentation

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** NRHP SRCP Criteria A B C D	
1. Name of property: **Plaza del Monte** **Residence 14**	**2. Location:** **105 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Evaluation of Historical Status

Representing a Contemporary design, the building does not harmonize or contribute to the historical character of the district. In addition, constructed in 1971, it does not meet the minimum age threshold for consideration. For this reason, the recommendation is to designate 105 Camino Santiago a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2*		
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 14	**2. Location:** 105 Camino Santiago *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building not present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 14	2. Location: 105 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Figure 2: February 27, 1969 aerial photograph
Building not present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 14	**2. Location:** 105 Camino Santiago *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street elevation and east elevations, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 14**	**2. Location:** **105 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: Street and west elevations, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 14	2. Location: 105 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Photo 3: East Unit (top), facing northeast; West Unit (bottom), facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 14	2. Location: 105 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Photo 4: North elevation, facing west (top) and east (bottom)
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 3	106 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693427, -105.935448

10. Photo Information Negative: John Murphey View of: Front, north elevation, facing south.

11. Brief Description of the Property:

Likely the third unit to be constructed at Plaza del Monte, 106 Camino Santiago is a 2,301-square-foot dwelling with a portal across two elevations. In plan, it has an L-shaped foundation with an attached carport. The flat-roof dwelling holds three bedrooms confined to a wing at the west end. The rear (south) elevation is focused on a small patio cut into the southwest corner of the house. The southeast corner is terminated by a one-space carport. The two-sided portal runs along the north and east elevations. The structure is made of vigas which sit on square girders held up by round posts with zappos-type corbels. The portal elevations are painted white and fenestrated with doors on each exposure. Small rectangular windows penetrate the bedroom wing. The remaining windows vary, including large picture and grouped casements and sliding units. The roof is finished with rolled asphalt which carries over the inner parapets. A squat stucco-faced chimney rises at the northeast corner. The house is finished with textured cementitious stucco in a light buckskin tone. It was erected in c.1965. Its designer is unknown but is suspected to be an early Clark and Register design.

12. Who uses the property? Residence

13. Construction Date: c.1965
_x_Known _x_ Source: aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

). Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is De Forest N. Shotwell, who is listed as a tenant in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Contributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria _A _B _C _D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte Residence 3	106 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _x_ Asphalt
__ Earth __ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Sliding	Aluminum	1-1	6
Fixed	Wood [?]	Single	1

*Because of storm covers, the operation and material is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ View Light	Wood	4
Sliding	Patio	Aluminum	1

12. Chimneys
One, stucco-clad, west exposure

13. Porches __ N/A
Type: _x_ Entry- portal- 2 __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: __ _x_ No known modifications

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes: Other:

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No.	*Please complete HCPI FORM 1 before completing FORM 2* District No.	NRHP SRCP Criteria A B C D
1. Name of property: Plaza del Monte Residence 3	2. Location: 106 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Constructed before 1968, and representing the original Clark and Register design template for the Plaza del Monte retirement homes, the house is a good example of the "Santa Fe style." For this reason, the recommendation is to designate 106 Camino Santiago a Contributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 3	2. Location: 106 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 3	2. Location: 106 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: South and east elevations, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 3	**2. Location:** 106 Camino Santiago *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: South and east elevations, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 3	2. Location: 106 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Photo 3: Street and west elevations, facing southeast.

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 15	109 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
_ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693826, -105.935966

10. Photo Information Negative: John Murphey View of: Front, south elevation, facing north.

11. Brief Description of the Property:

Composed of a series of angled walls, the carport dominated residence was constructed in 1966, after a design by architect Philippe Register. The house presents to the street a tall and wide carport framed with a viga roof. The west end of the carport is sheltered by double splayed wall. The angled wall composition is echoed across the east elevation. In plan, the residence is roughly an "L" with its form obscured by the carport. The approximately 1,220-square-foot dwelling holds two bedrooms in a cube-like mass anchoring the east end. Between the bedroom mass and carport is a small enclosed patio and portal sheltering the main entry and a pair of oversized wood windows. The rear (north) elevation has a small viga canopy protecting a patio door. A tapered chimney breaks the wall plane on this elevation. Fenestration consists of mainly aluminum windows. The frame structure is finished with cementitious brocade stucco in the buckskin tone. The Contemporary-style house was constructed in c.1965.

12. Who uses the property? Residence

13. Construction Date: c.1965
_x_Known _x_ Source: aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

omments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

J. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Jane Barber, who is listed as a tenant in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte Residence 15	109 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Sliding	Aluminum	1-1	6
Fixed	Wood	2	1

*Because of storm covers, the operation and material information is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel	Wood	4
Single-Leaf	Flush	Wood	1
Sliding	Patio	Aluminum	1

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: __ _x_ No known modifications

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	__ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other: Contemporary with Spanish-Pueblo Revival ornamentation

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 15**	**2. Location:** **109 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Evaluation of Historical Status

Representing a Contemporary design, the house does not harmonize or contribute to the historical character of the district. For this reason, the recommendation is to designate 109 Camino Santiago a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 15	2. Location: 109 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 15**	**2. Location:** **109 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street and east elevations, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:	*Please complete HCPI FORM 1 before completing FORM 2*	
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte** **Residence 15**	**2. Location:** **109 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: Street and west elevations (top), facing northeast. West elevation (bottom), facing southeast
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 15	2. Location: 109 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Photo 3: North elevation, facing southeast (top), west (bottom)
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 5	110 (112) Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693575, -105.936130

10. Photo Information Negative: John Murphey View of: Front, north elevation, facing south.

11. Brief Description of the Property:

Located at the west end of the common area are two residential units which were joined together at some point after 1970. The older unit, addressed 110 Camino Santiago, takes up the east end of the footprint. Constructed in c.1962, after a design by architect Kenneth S. Clark, it is roughly an L-shaped box with a rear portal and connected carport. The street-facing façade is defined by a small recessed entry. The entry holds a single door placed across the west wall. The remainder of the façade is divided into rectangular window openings holding sliding units. Smaller, rectangular sliding windows are applied across the east bedroom wing. A shallow portal runs across the rear (south) elevation historically leading to a single-space carport. The portal elevation is fenestrated with a patio door, sliding windows, and a louvered door leading to a utility room. The house is outlined with parapets and finished in buckskin cementitious stucco. It holds three bedrooms. ***Continued on Page 5***

12. Who uses the property? Residence

13. Construction Date: c.1962, with c.1968 addition and carport expansion
_x_Known _x_ Source: aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

20. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the original house (110) is Dorothy B. Fritz, who is listed as a tenant in the 1966 Santa Fe city directory. The first resident identified with the addition (112) is Theo R. Finley, listed in the 1970 Santa Fe city directory as a tenant. Currently the Santa Fe County Assessor treats the combined buildings as one residence addressed as 110 Camino Santiago.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa: Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte Residence 5	110 (112) Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Sliding	Aluminum	1-1	11
Sliding	Aluminum	Single	1
Casement	Aluminum	1-1F-1	2

*Because of storm covers, the operation and material information is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ View Light	Wood	2
Single-Leaf	Flush	Wood	1
Double	Panel	Wood	1
Double	Louver	Wood	1
Sliding	Patio	Aluminum	2

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry- portal- 2 __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: c.1968; addition across west elevation and widening of carport; aerial photographs, drawings, material and visual evidence.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other:

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 5	2. Location: 110 (112) Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Continuation of Architectural Description:

Attached to the west end of the original Clark design is a post-1966 addition. Arranged at a lower height, the approximately 864-square-foot appendage is a rectangular box with overhanging eaves and a porch. The addition, mostly likely designed by architect Philippe Register, introduces a contemporary vocabulary. A shallow overhang supported by squared rafters carries across the north and south elevations. Similar beams extend out from the west elevation to create the porch. A tall angular wall rising above the roofline defines its south edge. The addition is fenestrated with a few doors and square window openings holding single-light metal casements. The frame structure is finished with cementitious brocade stucco in the buckskin pigment. Most likely occurring with the addition, the carport was widened (or constructed anew) to hold two vehicles. Set back from the addition, the roughly 1,054-square-foot structure is supported by a viga-and-post system.

Evaluation of Historical Status

The original house received a contemporary addition across its secondary street façade and a demolition and widening of its carport in c. 1968. The combined alterations changed the overall massing and the appearance of the west elevation of the original structure. For this reason, the recommendation is to designate 110 (112) Camino Santiago a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* NRHP SRCP Criteria A B C D	
1. Name of property: Plaza del Monte Residence 5	2. Location: 110 (112) Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph. Only east portion of building present. Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 5**	**2. Location:** **110 (112) Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**



Figure 2: February 27, 1969 aerial photograph
West addition and portal expansion present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 5**	**2. Location:** **110 (112) Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street and north elevations, facing southeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte** **Residence 5**	**2. Location:** **110 (112) Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: Street and west elevations of addition, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte** **Residence 5**	**2. Location:** **110 (112) Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: South and west elevations of addition and expanded carport, facing east.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte** **Residence 5**	**2. Location:** **110 (112) Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 4: South elevation, facing north.

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte	111 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory
		4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693910, -105.936232

10. Photo Information Negative: John Murphey View of: Front, south elevation, facing north.

11. Brief Description of the Property:

Arranged at an east-west orientation, the house is a one-story, approximately 1,616-square-foot, flat-roof dwelling erected in c.1965. The dwelling has an L-shaped plan with its two bedrooms confined to a rectangular wing at the west end. The remaining house holds the living room, kitchen and dining area. The front (south) façade is marked by a long portal which continues across to an attached one-bay carport. The portal shelters the front entry and a sliding patio door. The structure is supported round poles holding a viga roof. The house is fenestrated with common windows, most of them appearing to be replacement units. It is entered through a raised wood panel door flanked on one side by a sidelight. The rear (north) elevation contains a few windows and a door sheltered by a shallow viga-supported visor. A tapered chimney breaks through the visor, terminating with a terra cotta cap. The frame building is finished in smooth cementitious stucco in the buckskin tone. The flat roof is covered with asphalt, which carries over the east exposure of the bedroom wing. While contemporary in form, the vigas used across the portal give the residence a Spanish-Pueblo Revival feel. The placement and restrained size of the carport helps maintain the regional tradition. The building was constructed after a design by architect Philippe Register.

12. Who uses the property? Residence

13. Construction Date: c.1965
_x_Known _x_ Source: aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

20. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Neva B. Palameter, who is listed as a tenant in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa: Downtown and Eastside Historic District

Recommended Contributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte	111 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe	__ Brick	__ Composition	__ Concrete: Block
__ Concrete: Cast Stone	__ Concrete: Poured	__ Earth Plaster	__ Masonry: Simulated
__ Metal: Corrugated	__ Metal: Structural Siding	__ Metal: V-Crimp	__ Stone: Random Ashlar
Stone: __ Random Coursed	__ Stone: River Rock	__Stone: Rusticated	__ Stone: Tabular
_x_Stucco:	__ Tile: Clay	__ Vinyl Siding	__ Wood: Board and Batten
Wood: __ Horizontal Siding	__ Wood: Jacal	__ Wood: Log	__ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Sliding	Aluminum	1-1	3
Double-Hung	Wood	3	2
Double-Hung	Wood	1/1	1

*Because of storm covers, the operation and material is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ single sidelight	Wood	1
Single-Leaf	Raised Square Panel	Wood	1
Single-Leaf	½-Light	Wood	1
Sliding	Patio	Aluminum	2

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry- portal- __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: Date unknown; replaced windows; drawings and visual and material evidence.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other:

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** NRHP SRCP Criteria A B C D	
1. Name of property: **Plaza del Monte**	**2. Location:** **111 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Evaluation of Historical Status

Constructed before 1968, and representing the original Clark and Register design template for the Plaza del Monte retirement homes, the house is a good example of the "Santa Fe style." For this reason, the recommendation is to designate 111 Camino Santiago a Contributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte	2. Location: 111 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte**	**2. Location:** **111 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street and east elevations, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **111 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: Street and west elevations, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **111 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: North elevation, facing southwest
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte	113 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory
		4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693980, -105.936500

10. Photo Information Negative: John Murphey View of: Front, south elevation, facing north.

11. Brief Description of the Property:

Sitting on a slight rise, the house shares a party wall at the carport with its neighbor at 115 Camino Santiago. The roughly 1,281-square-foot dwelling contains two bedrooms. These are arranged at the front of the structure in a small L-shaped volume. The remainder of the footprint holds the living functions of the house. It presents to the street two roomblock-like volumes penetrated by horizontally oriented aluminum casement windows. A viga-framed carport and short portal terminate the west end of the footprint. The house is entered through a raised wood panel door with a center view light. The rear (north) elevation has a few windows and sliding glass door. A shallow overhang supported by square wood beams carries across the elevation. The frame dwelling is finished cementitious peach color stucco worked into a brocade pattern. Tall parapets outline the perimeter of the bedroom wing. The roof is covered with asphalt which carries over the west exposure of the bedroom mass. It was erected in c.1970; its designer/architect is unknown.

12. Who uses the property? Residence

13. Construction Date: c.1970
_x_Known _x_ Source: aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

20. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Harry Wood, who is listed as a tenant in the 1971 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa: Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte	113 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Casement	Aluminum	1-1F-1	7
Casement	Aluminum	Single	1

*Because of storm covers, the operation and material information is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ View Light	Wood	4
Sliding	Patio	Aluminum	1

12. Chimneys
One, stucco-clad, east exposure

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other:

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **113 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Evaluation of Historical Status

Constructed in c.1970, it does not meet the minimum age threshold for consideration. For this reason, the recommendation is to designate 113 Camino Santiago a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **113 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building not present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte	2. Location: 113 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street and east elevations, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **113 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: North elevation, facing southeast and southwest
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 26	114 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
5.693668, -105.936489

10. Photo Information Negative: John Murphey View of: Front, north elevation, facing southeast.

11. Brief Description of the Property:

The house presents to Camino Santiago a traditional design of a cube-like mass projecting from a linear arm. In plan, it is roughly L-shaped with a large connecting carport attached to its southeast corner. The west end holds two bedrooms; the remainder of the footprint contains a large living room, kitchen and utility closet. The south exposure of the bedroom wing is penetrated by sliding glass doors. East of the bedroom wing, the front façade is divided into a recessed entry and a large casement-framed picture window. The entry holds a raised square panel wood door with a center view light. It is sheltered by a short overhang resting on vigas. A similar combined picture and casement window is found on the east elevation of the living room. The carport makes up most of the secondary street elevation. It is supported by a wood viga-and-post system. The structure shelters a patio door and single raised panel wood doors leading to the utility room and storage area. Wood, trough-like canales penetrate the parapets on the east and west elevations. The roof is covered with rolled asphalt, which carries over the bedroom wing's east exposure. A short stucco-clad chimney topped with a terra cotta cap rises from the center of the roof. Erected in c.1972, the residence was designed by Register, Ross & Burnet Architects.

12. Who uses the property? Residence

13. Construction Date: c.1972
_x_Known _x_ Source: drawings, aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

). Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The 1972 Santa Fe directory indicates the house was under construction at that time.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte Residence 26	114 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Casement	Aluminum	1-1	3
Casement	Aluminum	1-1F-1	4

*Because of storm covers, the operation and material information is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ View Light	Wood	2
Single-Leaf	Raised Square Panel	Wood	2
Sliding	Patio	Aluminum	2

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: Unknown; replaced windows and doors; drawings and material and visual evidence.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_ Spanish-Pueblo Revival
Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes: Other:

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 26	2. Location: 114 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Constructed in c.1972, it does not meet the minimum age threshold for consideration. For this reason, the recommendation is to designate 114 Camino Santiago a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 26	2. Location: 114 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building not present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 26**	**2. Location:** **114 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: East and south elevations, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 26**	**2. Location:** **114 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: West elevation, facing southeast.

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte	115 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.694030, -105.936677

10. Photo Information Negative: John Murphey View of: Front, south elevation, facing northwest.

11. Brief Description of the Property:

Sharing a wall with the dwelling to the east (113 Camino Santiago), the small house contains two bedrooms. The dwelling portion of the building is composed of a rectangular bedroom wing. Attached to this are the living room, kitchen and a one-space carport. Connecting these elements is a beam portal. Together, both areas hold about 1,290 square feet. The front façade presents a simple canvas of a projecting mass balanced on one end with the void of the carport at the other. In between is the portal with its few window and door openings. The portal is supported by double round posts topped with zappos-type corbels. The rear (north) elevation contains a few windows and a sliding glass door sheltered by a shallow viga-supported overhang. The house is fenestrated with common doors and windows. The windows are tall, single-light aluminum casements. A raised-panel-and-view-light door gives entry to the dwelling under the portal. Short parapets outline the perimeter of the bedroom wing. The roof's asphalt material carries over the east exposure of the parapet. The house was erected in c.1970; its designer/architect is unknown.

12. Who uses the property? Residence

13. Construction Date: c.1970
_x_Known _x_ Source: aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

). Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Westley L. Almy, who is listed as a tenant in the 1971 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ __NRHP __SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte	115 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Casement	Aluminum	1	1
Casement	Aluminum	1-1	1
Casement	Aluminum	1-1F-1	2
]Casement	Aluminum	1-2F-1	1

*Because of storm covers, the operation and material information is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ View Light	Wood	2
Sliding	Patio	Aluminum	2
Double	Carport	Wood	1

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: __ _x_ No known modifications

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other:

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** NRHP __ SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **115 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Evaluation of Historical Status

Constructed in c.1970, it does not meet the minimum age threshold for consideration. For this reason, the recommendation is to designate 115 Camino Santiago a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte	**2. Location:** 115 Camino Santiago *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building not present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **115 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street and east elevations, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **115 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: Street and west elevations, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **115 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: North elevation, facing southwest
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte	117 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory
		4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.694087, -105.936953

10. Photo Information Negative: John Murphey View of: Front, east elevation, facing northwest.

11. Brief Description of the Property:

Tucked into the northwest corner of the development, the house is a single-story, flat-roof dwelling characterized by its viga carport and continuous overhang. In form, its two box-like volumes are arranged in a modified L-plan. The house holds two bedrooms slung along the west wall. A large living room occupies the foot of the "L." With its carport included, the house contains approximately 1,422 square feet. The unarticulated flat front façade is penetrated by non-historic casement windows. A wood panel and view light door gives entry to the dwelling under the front portal. The rear (west) elevation is fenestrated with an asymmetrical pattern of tall aluminum casement windows. The frame building is finished with brocade-type stucco rendered in the buckskin color. It was constructed in 1966-67, after a design by architect Philippe Register. Window replacements appear to have removed the pedimented heads shown on Register's drawings.

12. Who uses the property? Residence

13. Construction Date: 1966-67
_x_Known _x_ Source: drawings, aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

). Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Reverend H. Thomas, who is listed as a tenant in the 1967 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte	117 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Casement	Aluminum	1	2
Casement	Aluminum	1-1	3
Casement	Aluminum	1-1F-1	1
]Casement	Aluminum	1-2F-1	3

*Because of storm covers, the operation and material information is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ View Light	Wood	2
Single-Leaf	Raised Panel	Metal	1
Sliding	Patio	Aluminum	2
Double	Carport	Wood	1

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ **Entry- portal** __**Partial-Width** __ **Full-Width** __ **Wrap**

14. Other Significant Features N/A

15. Modifications: x __ **No known modifications**

#1 Date: Unknown; replaced windows and doors; drawings and material and visual evidence.

HCPI Detail Form (FORM 2) *(Continued from other side)*

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	__ Spanish-Pueblo Revival
Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other: Contemporary with Spanish-Pueblo Revival ornamentation

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:	***Please complete HCPI FORM 1 before completing FORM 2***	
CPI No. _____ District No. _____	___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **117 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Representing a Contemporary design, the house does not harmonize or contribute to the historical character of the district. For this reason, the recommendation is to maintain 117 Camino Santiago as a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte**	**2. Location:** **117 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building not present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte**	**2. Location:** **117 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street, west and south elevations, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte**	**2. Location:** **117 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: West elevation, facing southwest
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **117 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: North elevation, facing south
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte	118 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693715, -105.936696

10. Photo Information Negative: John Murphey View of: Front, north elevation, facing southwest.

11. Brief Description of the Property:

Erected in c.1973, the stucco-over-frame, two-bedroom house sits on a rise at the southwest corner of Camino Santiago and Camino Matias. In plan, it is a modified L-shaped structure with a carport attached to its front façade. The roughly 1,245-square-foot dwelling has its bedrooms segregated to a wing across the west elevation. This volume is taller than the rest of the house and is outlined with parapets. The lower volume contains a living room, kitchen and dining area. The north (front) façade is divided between the carport and the north face of the bedroom wing. The single space carport is erected over a wood structure supported by round posts. The outside beam continues across the façade, sheltering the front entry. As with the door under the carport, the entry holds a raised square panel unit. The secondary elevations are fenestrated with single-light metal casement windows. The south (rear) elevation has an array of casement windows and an enclosure giving access to the carport. A shallow overhang resting on vigas outlines the elevation. The house is finished with cementitious brocade stucco in a peach pigment. The roof is covered with rolled asphalt, which carries over a portion of the bedroom wing's east exposure. Large, trough-like wood canales pierce the west parapet. It was designed by Register, Ross & Burnet Architects, and is one of the last houses to be completed in the development.

12. Who uses the property? Residence

13. Construction Date: c.1973
_x_Known _x_ Source: drawings, aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

). Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Duncan Spinning, who is listed as a tenant in the 1974 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa: Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
CPI No._____ District No._____ __NRHP __SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte	118 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe	__ Brick	__ Composition	__ Concrete: Block
__ Concrete: Cast Stone	__ Concrete: Poured	__ Earth Plaster	__ Masonry: Simulated
__ Metal: Corrugated	__ Metal: Structural Siding	__ Metal: V-Crimp	__ Stone: Random Ashlar
Stone: __ Random Coursed	__ Stone: River Rock	__Stone: Rusticated	__ Stone: Tabular
_x_Stucco:	__ Tile: Clay	__ Vinyl Siding	__ Wood: Board and Batten
Wood: __ Horizontal Siding	__ Wood: Jacal	__ Wood: Log	__ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Casement	Steel	2-2F-2	1
Casement	Steel	3-3	2
Casement	Steel	3-3F-3	2
Casement	Steel	3-3F-3F-3	2

*Because of storm covers, the operation and material is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ View Light	Wood	1
Single-Leaf	Raised Square Panel	Wood	1
Double	Carport	Wood	1

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: __ _x_ No known modifications

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other:

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **118 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Constructed in c.1973, it does not meet the minimum age threshold for consideration. For this reason, the recommendation is to designate 118 Camino Santiago a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2*		
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte**	**2. Location:** **118 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building not present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2*		
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte**	**2. Location:** **118 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street and east elevations, facing southwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte**	**2. Location:** **118 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: West elevation, facing east.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2*		
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte**	**2. Location:** **118 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Photo 3: West and south elevations, facing northeast.

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte	119 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693915, -105.937077

10. Photo Information Negative: John Murphey View of: Front, east elevation, facing west.

11. Brief Description of the Property:

Arranged slightly above grade, the box-like house is characterized by its continuous portal and horizontal emphasis. In plan it is a compact rectangle framed by angled walls on its north and south exposures. Large windows, a wood panel door and a three-panel sliding glass door appear on the front façade. The rear (west) elevation has double sets of sliding windows and a patio door arranged under an overhang. The house's windows appear to be mostly replacement units. The south end of the dwelling is weighted with a large carport. A tall double splayed wall creates the south exposure. The portal is supported by vigas resting on a square beam. Round posts topped with double-ended corbels carry the weight to the floor. The roughly 1,485-square-foot structure contains two bedrooms placed along the west wall. The building was constructed in c.1965, after a design by architect Philippe Register. The main alteration is the removal of most of the angled wall along the northeast corner. Originally this feature enclosed a small patio.

12. Who uses the property? Residence

13. Construction Date: c.1965
_x_Known _x_ Source: drawings, aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

). Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Muriel M. Boone, who is listed as a tenant in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte	119 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Sliding	Aluminum	1-1	6
Fixed	Wood	Single	2

*Because of storm covers, the operation and material information is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel	Wood	4
Sliding	Patio	Aluminum	2

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry- portal- __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: Unknown; partial removal and alteration of northeast angled patio enclosure; drawings and material and visual evidence.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	__ Spanish-Pueblo Revival
Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other: Contemporary with Spanish-Pueblo Revival ornamentation

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:	***Please complete HCPI FORM 1 before completing FORM 2***	
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte**	**2. Location:** **119 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Representing a Contemporary design, the house does not harmonize or contribute to the historical character of the district. For this reason, the recommendation is to maintain 119 Camino Santiago as a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte	2. Location: 119 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte	2. Location: 119 Camino Santiago *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street and south elevations, facing northwest.
Box indicates removed portion of angled patio wall.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **119 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: West elevation, facing south
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **119 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: North elevation, facing southwest
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 25	120 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory
		4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693597, -105.936785

10. Photo Information Negative: John Murphey View of: Front, west elevation, facing southeast.

11. Brief Description of the Property:

The small two bedroom house presents a contemporary carport-dominant design. Located along the south side of Camino Santiago, it sits back from the street. In plan, it is a modified "T" form with an attached carport projecting from the front façade. Its two bedrooms are confined to a wing making up the north elevation. Higher than the rest of the house, it is outlined with shaped parapets. The parapets are pierced with canales across the north and south exposures. The lower volume, historically containing a living room, kitchen and music room, is faced with a shallow overhang resting on vigas. The overhang shelters sliding glass doors, a window and a pedestrian entry. The secondary elevations are fenestrated with aluminum casement windows. ***Continued on Page 5***

12. Who uses the property? Residence

13. Construction Date: c.1971
_x_Known _x_ Source: drawings, aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

J. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Ovid Sellers, who is listed as a tenant in the 1972 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte Residence 25	120 Camino Santiago *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Casement	Aluminum	2-2F-2	1
Casement	Aluminum	3-3F-3	4
Fixed	Aluminum	21	1

*Because of storm covers, the operation and material is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ View Light	Wood	1
Single-Leaf	Raised Panel	Metal	1
Double	French	Aluminum	1
Double	Carport	Wood	3

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: Unknown; replaced windows and doors; drawings and material and visual evidence.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes: Other:

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:	***Please complete HCPI FORM 1 before completing FORM 2***	
HCPI No. _____ District No. _____	___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 25**	**2. Location:** **120 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Continuation of Architectural Description:

The front (west) elevation is dominated by the carport. The structure is erected over a viga-and-post support system. The portal's outside beam continues across the façade, sheltering the front entry. A wood raised square panel door with a center view light gives entry to the residence. The frame building is faced with cementitious stucco with brocade finish in a peach-like pigment. Including its carport and utility room, the building contains 1,804 square-feet. The house was erected in c.1971, after a design by Register, Ross & Burnet Architects.

Evaluation of Historical Status

Constructed in c.1971, it does not meet the minimum age threshold for consideration. For this reason, the recommendation is to designate 120 Camino Santiago a Noncontributing Structure to the Downtown and Eastside Historic District.

Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 25	**2. Location:** 120 Camino Santiago *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building not present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2*		
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte** **Residence 25**	**2. Location:** **120 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: East elevation, facing north.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 25**	**2. Location:** **Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: South elevation, facing northeast
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 25**	**2. Location:** **120 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: North elevation, facing southwest
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 20	121 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693719, -105.937155

10. Photo Information Negative: John Murphey View of: Front, east elevation, facing northwest.

11. Brief Description of the Property:

Reflecting a carport-dominant design, the small, vernacular dwelling sits at grade on the west side of Camino Santiago. The roughly 1,309-square-foot structure holds one bedroom. In plan, it is a compact square enclosed by an angled wall across its south exposure. Unlike most units at Plaza del Monte, it has a low pitch roof. The front (east) façade is dominated by the one-vehicle carport. The remainder of the façade is divided into windows and doors. The windows are uniformly multi-light steel casements in various standard sizes. The gabled north elevation has three identical windows. The rear (west) side of the house has more articulation, expressed through its beamed canopy over a pair of sliding doors. The frame house is finished with heavy brocade cementitious stucco in a peach-like color. A shallow square-beam supported overhang runs along the east and west elevations. It was constructed in c. 1971, after a design by Register, Ross and Brunet Architects.

12. Who uses the property? Residence

13. Construction Date: c.1971
_x_Known _x_ Source: drawings, aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

). Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Gilbert L. Boyd, who is listed as a tenant in the 1972 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing __ Non-contributing _x_ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 20	121 Camino Santiago *Downtown and Eastside Historic District*	Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Casement	Steel	2-2	3
Casement	Steel	3 [?]	1
Casement	Steel	3-3	5
Casement	Steel	3-3F-3F-3	1

*Because of storm covers, the operation and material is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ View Light	Wood	1
Single-Leaf	Raised Square Panel	Wood	1
Sliding	Patio	Aluminum	2
Double	Carport	Wood	3

12. Chimneys
One, stucco-clad, west exposure

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: __ _x_ No known modifications

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	__ Spanish-Pueblo Revival
Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other: Contemporary with Spanish-Pueblo Revival ornamentation

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 20**	**2. Location:** **121 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Evaluation of Historical Status

Representing a Contemporary design, the house does not harmonize or contribute to the historical character of the district. Constructed in c.1971, it does not meet the minimum age threshold for consideration. For this reason, the recommendation is to designate 121 Camino Santiago a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 20**	**2. Location:** **121 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building not present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 20**	**2. Location:** **121 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: South elevation, facing northeast and northwest
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 20**	**2. Location:** **121 Camino Santiago** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: West elevation, southeast
(Sharon Joyce, February 23, 2018).

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 1	104 Camino Matias *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693073, -105.935289

10. Photo Information Negative: John Murphey View of: Front, north elevation, facing northeast.

11. Brief Description of the Property:

One of the first units to be constructed at Plaza del Monte, 104 Camino Matias is an L-shaped dwelling with a combined carport and portal. The approximately 1,143-square-foot, flat-roof structure holds two bedrooms. The bedrooms are placed in a wing forming the north end of the residence. Its front (west) façade presents a Spanish-Pueblo Revival plan with its cubic, battered mass and viga-roofed portal. Unlike many houses in the development, the carport plays a secondary role on the façade. The single-bay structure, arranged behind the portal, is less exuberant in its display of wood elements. The bedroom mass is fenestrated with small, rectangular windows; the remaining elevations have windows arranged in a more traditional pattern. The windows are mostly aluminum casement units. The portal elevation is painted white. A line of vigas runs along the top of the wall. It is supported by shiplap wood girders resting on round posts with zappos-type corbels. The house was constructed in c.1965. It represents the closest interpretation of the original 1960 Kenneth S. Clark and Philippe Register template design for the development.

12. Who uses the property? Residence

13. Construction Date: c.1965
_x_Known _x_ Source: aerial photographs, city directory entries

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar

Comments: N/A

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

). Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The house was constructed as part of the independent living section of Plaza del Monte, a Presbyterian residential community for retired clergy, missionaries and other professional staff. Developed between 1960 and 1977, Plaza del Monte operated as a retirement center until 1988. The first resident identified with the house is Frederick H. Dawson, who is listed as a tenant in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing _x_ Non-contributing __ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Contributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte Residence 1	104 Camino Matias *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Casement	Aluminum	1-1	6
Casement	Aluminum	1-1F-1F-1	1
[?]	[?]	[?]	1

*Because of storm covers, the operation and material is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel w/ View Light	Wood	2
Single-Leaf	Flush	Wood	2
Sliding	Patio	Aluminum	1

12. Chimneys
One, stucco-clad, south exposure

13. Porches __ N/A
Type: _x_ Entry- portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: __ _x_ No known modifications

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	_x_ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes: Other:

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No. _____ District No. _____	***Please complete HCPI FORM 1 before completing FORM 2*** NRHP SRCP Criteria A B C D	
1. Name of property: **Plaza del Monte** **Residence 1**	**2. Location:** **104 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Evaluation of Historical Status

Constructed before 1968, and representing the original Clark and Register design template for the Plaza del Monte retirement homes, the house is a good example of the "Santa Fe style." For this reason, the recommendation is to designate 104 Camino Matias a Contributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2*		
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 1	**2. Location:** 104 Camino Matias *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 1**	**2. Location:** **104 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street and south elevations, facing southeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte** **Residence 1**	**2. Location:** **104 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: Street and north elevations, facing southeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 1**	**2. Location:** **104 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: East elevation, facing northwest.

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 10	105 Camino Matias *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693249, -105.935608

10. Photo Information Negative: John Murphey View of: Front, south elevation, facing north.

11. Brief Description of the Property:

This small house is one of three units constructed in 1950 for married staff employed by the Allison-James School. Arranged in a terrace-like fashion, each unit is a rectangular plan, side-gabled dwelling with an attached garage. The house has a telescoping roof form, evident along its north exposure. The roof extends over the walls on the north and south elevations to form small porches. The house is fenestrated with a mix of original and non-historic windows and doors. The windows are terminated with stuccoed concrete sills. Views from the house are oriented north toward the commons area. The north elevation contains a large picture window flanked by casements. Public entry is through an original ½-glass wood door on the south elevation. The garage door is a recent vinyl paneled unit. The roof is covered with three-tab asphalt shingles. Wood fascia has been applied to the north and south roof ends, obscuring (or removing) the original exposed rafters. A short stuccoed chimney rises from the north roof slope. The approximately 1,102-square-foot house holds three bedrooms. A non-historic, 220-square-foot carport has been erected over the driveway.

12. Who uses the property? Residence

13. Construction Date: 1950
_x_Known _x_ Source: Allison-James School publication and aerial photographs

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: __ Similar _x_ Dissimilar

Comments: Vernacular, gabled building, dissimilar to the Contemporary and Spanish-Pueblo Revival housing of Plaza del Monte

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

J. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The first resident identified with the house during the Plaza del Monte period is Sidney S. Brown, who is listed as a tenant in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: _x_ Contributing __ Non-contributing __ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa: Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 10	105 Camino Matias *Downtown and Eastside Historic District*	Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Double-Hung	Wood	1/1	4
Double-Hung	Metal	2/2	3
Fixed	Wood	Single	1
Fixed	Metal/Wood	Singled flanked by 2/2 DH	1
Sliding	Wood	1-1	1

*Because of storm covers, the operation and material is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Square Panel	Wood	2
Single-Leaf	½ -Glass	Wood	1
Overhead	Sectional	Vinyl	1

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: Unknown; replaced garage door; material and visual evidence.
#2 Date: 1960s; assumed replacement of original windows in majority of openings.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	__ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other: No style – side-gable vernacular form

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2*		
CPI No. District No. NRHP SRCP Criteria A B C D		
1. Name of property: **Plaza del Monte** **Residence 10**	**2. Location:** **105 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Erected as a teacherage residence, the house does not harmonize or contribute to the aesthetic of Plaza del Monte or the historical character of the district. This includes non-conforming elements, such corner windows and cantilevered canopies over entries, which do not meet the ordinance standards. Additionally, its historical association lies with the Allison-James School, which was demolished in 1960. For these reasons, the recommendation is to designate 105 Camino Matias a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 10	2. Location: 105 Camino Matias *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 10**	**2. Location:** **105 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Figure 2: Rear (north) elevation of teacherage; Allison-James School in background. Source: Atkins, 1983.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2*		
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte** **Residence 10**	**2. Location:** **105 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: west elevation, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte** **Residence 10**	**2. Location:** **105 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: East elevation, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 10**	**2. Location:** **105 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: North elevation, facing southeast.

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 9	107 Camino Matias *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693289, -105.935797

10. Photo Information Negative: John Murphey View of: Front, south elevation, facing north.

11. Brief Description of the Property:

This small house is one of three units constructed in 1950 for married staff employed by the Allison-James School. Arranged in a terrace-like fashion, each unit is a rectangular plan, side-gabled dwelling with an attached garage. The house has a simple side-gable form terminating at the east end with a hipped roof over the garage. The gabled roof extends over the walls on the north and south elevations to form small porches. The dwelling is fenestrated with a mix of original and non-historic windows and doors. They are terminated with stuccoed concrete sills. Views from the house are oriented north toward the commons area. The north elevation contains a large picture window flanked by casements. Public entry is through an original ½-glass wood door on the south elevation. Two vertical [solar?] panels have been applied to the façade. The garage door is a recent vinyl paneled unit. The roof is covered with three-tab asphalt shingles. Wood fascia has been applied to the north and south roof ends, obscuring (or removing) the original exposed rafters. A short stuccoed chimney rises from the north roof slope. The house originally had an enclosed pedimented entry on the north elevation, which was reduced at some point in depth after 1969. The approximately 1,145-square-foot house holds two bedrooms.

12. Who uses the property? Residence

13. Construction Date: 1950
_x_Known _x_ Source: Allison-James School publication and aerial photographs

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: __ Similar _x_ Dissimilar

Comments: Vernacular, gabled building, dissimilar to the Contemporary and Spanish-Pueblo Revival housing of Plaza del Monte

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

). Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The first resident identified with the house during the Plaza del Monte period is Adin B. Brooks, who is listed as a tenant in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing _x_ Non-contributing __ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte Residence 9	107 Camino Matias *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe	__ Brick	__ Composition	__ Concrete: Block
__ Concrete: Cast Stone	__ Concrete: Poured	__ Earth Plaster	__ Masonry: Simulated
__ Metal: Corrugated	__ Metal: Structural Siding	__ Metal: V-Crimp	__ Stone: Random Ashlar
Stone: __ Random Coursed	__ Stone: River Rock	__Stone: Rusticated	__ Stone: Tabular
_x_Stucco:	__ Tile: Clay	__ Vinyl Siding	__ Wood: Board and Batten
Wood: __ Horizontal Siding	__ Wood: Jacal	__ Wood: Log	__ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Double-Hung	Metal	2/2	6
Fixed	Metal/Wood	Singled flanked by 2/2 DH	1
Sliding	Metal	1-1	1

*Because of storm covers, the operation and material is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	½ -Glass	Wood	2
Overhead	Sectional	Vinyl	1

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

1 Date: Post-1969; change of back door opening and enclosure; photograph, aerial imagery and material and visual evidence.
2 Date: Unknown; replaced garage door; material and visual evidence.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	__ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other: No style – side-gable vernacular form

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 9	2. Location: 107 Camino Matias *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Erected as a teacherage residence, the house does not harmonize or contribute to the aesthetic of Plaza del Monte or the historical character of the district. It includes non-conforming elements, such corner windows and cantilevered canopies over entries, which do not meet the ordinance standards. Additionally, its historical association lies with the Allison-James School, which was demolished in 1960. For these reasons, the recommendation is to maintain the status of 107 Camino Matias as a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 9	**2. Location:** 107 Camino Matias *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 9	2. Location: 107 Camino Matias *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018



Figure 2: Rear (north) elevation of teacherage; Allison-James School in background. Source: Atkins, 1983.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte Residence 9**	**2. Location:** **107 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 2: Street and east elevations, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 9**	**2. Location:** **107 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: Street west elevations, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 9	**2. Location:** 107 Camino Matias *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: North elevation, facing south.

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 8	109 Camino Matias *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693343, -105.936001

10. Photo Information Negative: John Murphey View of: Front, south elevation, facing northwest.

11. Brief Description of the Property:

This small house is one of three units constructed in 1950 for married staff employed by the Allison-James School. Arranged in a terrace-like fashion, each unit is a rectangular plan, side-gabled dwelling with an attached garage. The house has a telescoping roof form. The roof extends over the walls on the north and south elevations to form small porches. The front (south) façade reveals an altered composition. At some point after 1960, a 131-square-foot addition was appended to the southwest corner creating a sunroom. The dwelling is fenestrated with a mix of original and non-historic windows and doors. The windows are mostly double-hung sash. They are terminated with stuccoed concrete sills. Views from the house are oriented north toward the commons area. The north elevation contains a large picture window flanked by casements. Public entry is through an original ½-glass wood door on the south elevation. The garage door is a recent vinyl paneled unit. The roof is covered with three-tab asphalt shingles. Wood fascia has been applied to the north and south roof ends, obscuring (or removing) the original exposed rafters. A short stuccoed chimney rises from the north roof slope. The approximately 1,141-square-foot house contains two bedrooms.

12. Who uses the property? Residence

13. Construction Date: 1950
_x_Known _x_ Source: Allison-James School publication and aerial photographs

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: __ Similar _x_ Dissimilar

Comments: Vernacular, gabled building, dissimilar to the Contemporary and Spanish-Pueblo Revival housing of Plaza del Monte

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

20. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The first resident identified with the house during the Plaza del Monte period is Chester E. Wittier, who is listed as a tenant in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing _x_ Non-contributing __ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa: Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ __NRHP __SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 8	109 Camino Matias *Downtown and Eastside Historic District*	Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Double-Hung	Metal	2/2	8
Fixed	Metal/Wood	Singled flanked by 2/2 DH	1
Sliding	Metal	1-1	1

*Because of storm covers, the operation and material is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	½ -Glass	Wood	2
Overhead	Sectional	Vinyl	1

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: Pre-1966; introduction of projection across front, south, façade; aerial photographs.
#3 Date: Unknown; replaced garage door; and material and visual evidence.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	__ Spanish-Pueblo Revival
Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other: No style – side-gable vernacular form

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:	***Please complete HCPI FORM 1 before completing FORM 2***	
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: **Plaza del Monte Residence 8**	**2. Location:** **109 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory**
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Erected as a teacherage residence, the house does not harmonize or contribute to the aesthetic of Plaza del Monte or the historical character of the district. This includes non-conforming elements, such corner windows and cantilevered canopies over entries, which do not meet the ordinance standards. Additionally, its historical association lies with the Allison-James School, which was demolished in 1960. For these reasons, the recommendation is to maintain the status of 109 Camino Matias as a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:	*Please complete HCPI FORM 1 before completing FORM 2*	
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 8	**2. Location:** 109 Camino Matias *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2*		
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 8	2. Location: 109 Camino Matias *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Figure 2: Rear (north) elevation of teacherage; Allison-James School in background. Source: Atkins, 1983.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 8	**2. Location:** 109 Camino Matias *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street and east elevations, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte Residence 8**	**2. Location:** **109 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: Street and west elevations, facing northeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte**	**2. Location:** **109 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: North elevation, facing southwest.

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 6	111 Camino Matias *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693391, -105.936212

10. Photo Information Negative: John Murphey View of: Front, west elevation, facing northeast

11. Brief Description of the Property:

Moved to the site prior to 1960, 111 Camino Matias is an altered three-bedroom house. The house is arranged on a north-south axis, and in plan consists of two telescoping gabled sections. To this basic form was added an L-shaped porch and connected carport in c.1966. The medium pitch roofs are covered with asphalt shingles and extend with overhangs. A short stuccoed chimney rises from the ridgeline. Small wood louvers are attached to the gable ends. The house is fenestrated with an array of original and non-historic windows. The windows — mostly double-hung sash — are arranged for interior functions. Windows are recessed from the wall and terminated with concrete sills. The combined porch and carport are supported by a framework of wood girders resting on grouped square posts. The single carport includes double storage units. A short breezeway leads from the carport to a back door. The 1,712-square-foot frame house is finished with textured cementitious stucco in a light buckskin color.

12. Who uses the property? Residence

13. Construction Date: Pre-1960; moved to site c.1960; portal and carport added c.1966
_x_Known _x_ Source: aerial photographs

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: __ Similar _x_ Dissimilar

Comments: Vernacular, gabled buildings, dissimilar to the Contemporary and Spanish-Pueblo Revival housing of Plaza del Monte

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

). Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The first resident identified with the house during the Plaza del Monte period is Daniel O. Shoop, who is listed as a tenant in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing _x_ Non-contributing __ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte Residence 6	111 Camino Matias *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Double-Hung	Metal	2/2	11
Fixed	Metal/Wood	Singled flanked by 2/2 DH	1

*Because of storm covers, the operation and material is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Raised Panel	Wood	1
Single-Leaf	Flush	Wood	1
Double	Carport Storage	Wood	2

12. Chimneys
One, stucco-clad, north exposure

13. Porches __ N/A
Type: _x_ Entry-portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: Pre-1960; house moved to site; primary source material and aerial photograph.
#2 Date: Pre-1966; introduction of portal and carport; layout plan and aerial photograph.
#3 Date: Pre-1966 (assumed); introduction of metal windows; visual and material evidence.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	__ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other: No style – side-gable vernacular form

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 6	2. Location: 111 Camino Matias *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
		4. County: Santa Fe
		5. Date of Survey: January 18, 2018

Evaluation of Historical Status

Moved to this location before 1960, and modified in the mid-1960s with the addition of the portal and carport, the house does not harmonize or contribute to the aesthetic of Plaza del Monte or the historical character of the district. Additionally, its historical association lies with the Allison-James School, which was demolished in 1960. For these reasons, the recommendation is to maintain the status of 111 Camino Matias as a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte Residence 6**	**2. Location:** **111 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building present.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 6**	**2. Location:** **111 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: East elevation, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 6**	**2. Location:** **111 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: North and west elevations, facing southeast.

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only:
CPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number:
Plaza del Monte Residence 7	116/120 Camino Matias *Downtown and Eastside Historic District*	Santa Fe ID #: N/A Plaza del Monte Inventory 4. County: Santa Fe

5. Property Type:
_1_ Buildings:
__ Structures:
__ Site __ Object

6. Date of Survey:
January 18, 2018

7. Previous Survey Date(s):
__ Yes:
_x_ No:

8. Name of Project:
HDRB status review
Plaza del Monte

9. Lat/Long:
35.693448, -105.936542

10. Photo Information Negative: John Murphey View of: Front, east elevation, facing northwest

11. Brief Description of the Property:

The vernacular, two-unit residence was erected before 1957, and modified nearly 30 years later with the addition of a cross gable entry. The combined residence is aligned along a north-south axis on the west side of Camino Matias. In plan, it is a side-gabled rectangle with a cross gable appended to its northeast corner. The north unit (120) holds about 1,256 square-feet, with three bedrooms. A window wall spanning the northeast corner signals its contemporary design. The north elevation under the gable is marred by a c.1984 shed-roof structure enclosing the furnace and water heater. The front façade faces east and is dominated by the non-historic cross gable entry. A recessed entry at the south end leads to 116. The interior, encompassing approximately 939 square feet, is arranged like an apartment. A similar non-historic stuccoed enclosure around the furnace and water heater is attached to the south elevation. The rear (west) elevation of the combined units faces onto a common area. A continuous overhang characterizes this façade. It is penetrated with three sliding glass doors and a mixture of fixed and sliding windows of different sizes. The roof is sheathed with rib metal panels. It unclear who designed the original house. The c.1984 addition of the cross gable and furnace and water heater enclosures was drawn in Philippe Register's shop.

12. Who uses the property? Residence

13. Construction Date: pre-1958, with alterations and cross-gable entry added on front façade in c.1984
_x_Known _x_ Source: aerial photograph

14. Setting:
_x_ Suburban __ Rural __ Village __ Urban If Urban: __ Commercial __ Industrial _x_ Residential __Public

15. Relationship to Surroundings: __ Similar _x_ Dissimilar

Comments: Vernacular, gabled buildings, dissimilar to the Contemporary and Spanish-Pueblo Revival housing of Plaza del Monte

HCPI Base Form (FORM 1) *(Continued from other side)*

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

North ⬆ **Box Indicates Post-1968 Addition**

Source:
Google Imagery, 2018

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
FirstLight Consulting
505-577-7593
John@archhistoryservices.com

For: Wayne S. Lloyd, A.I.A., Lloyd and Associates, Architects

18. Owner (if known) and other knowledgeable people:

Plaza del Monte, LLC

19. Is Property Endangered? __ Unknown _x_ No __ Yes How?

20. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
The first residents identified with the house during the Plaza del Monte period are Margaret D. Becker (116) and Minnie C. Wither (120). Both are identified as tenants in the 1966 Santa Fe city directory.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? __ No _x_Yes
Why? See Analysis of Historical Status.

23. National or State Historic District:

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Contributing _x_ Non-contributing __ No Status

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa:
Downtown and Eastside Historic District

Recommended Noncontributing Structure to the Downtown and Eastside Historic District, March 28, 2018

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: ***Please complete HCPI FORM 1 before completing FORM 2***
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory
Plaza del Monte Residence 7	116/120 Camino Matias *Downtown and Eastside Historic District*	4. County: Santa Fe
		5. Date of Survey: January 18, 2018

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

__ Adobe __ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __ Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __ Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove ___ Other: Frame

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other:_____

8. Foundation: __ N/A
__ Not visible __ None
_x_ At Grade __ Raised
Materials: _x_ Concrete __ Stone
Other: _____
Notes:

9. Roof: __ N/A

Shape: _x_Flat
__ Hipped __ Pyramidal
__ Shed Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _ Asphalt
__ Earth _x_ Gravel
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam __ Metal: V- Crimp
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Windows* __ N/A

Operation	Material	Glazing	Number**
Casement	Aluminum	8-8	2
Sliding	Aluminum	1-1	8
Fixed	Wood	Single	1

*Because of storm covers, the operation and material is not definite.
**Includes single and grouped units

11. Doors __ N/A

Type	Style	Material	Number
Single-Leaf	Flush	Wood	4
Single	Full-Glass	Wood	1
Sliding	Patio	Aluminum	3

12. Chimneys
N/A

13. Porches _x_ N/A
Type: __ Entry-portal __Partial-Width __ Full-Width __ Wrap

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: Pre-1966; introduction of modern fenestration; material and visual evidence.
#2 Date: c.1984; introduction of cross-gable entry across front, east, façade; drawings, aerial photographs and material and visual evidence.

HCPI Detail Form (FORM 2)

(Continued from other side)

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	__ Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	__ Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes:

Other: No style – side-gable vernacular form with Ranch style elements

17. Documents Available and Their Locations

New Mexico Historic Preservation Division
407 Galisteo Street, Suite 236
Santa Fe, NM 87501
(505) 827-6320

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing? No

19. Site Plan: Current plan is not available.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 7**	**2. Location:** **116/120 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Evaluation of Historical Status

Erected before 1958, and modified in the mid-1980s with a cross-gable entry and small additions, the house does not harmonize or contribute to the aesthetic of Plaza del Monte or the historic character of the district. Additionally, its historical association lies with the Allison-James School, which was demolished in 1960. For these reasons, the recommendation is to maintain the status of 116/120 Camino Matias as a Noncontributing Structure to the Downtown and Eastside Historic District.

Ordinance Definition – "Contributing Structure"

A *structure*, located in a historic district, approximately fifty years old or older that helps to establish and maintain the character of that historic district. Although a *contributing structure* is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The *contributing structure* may have had minor *alterations*, but its integrity remains.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte** **Residence 7**	**2. Location:** **116/120 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Illustrations

Figure 1: May 2, 1966 aerial photograph.
Building present; pre-alteration.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 7	2. Location: 116/120 Camino Matias *Downtown and Eastside Historic District*	3. Local Reference Number: Santa Fe ID #: Plaza del Monte Inventory 4. County: Santa Fe 5. Date of Survey: January 18, 2018



Figure 2: February 27, 1969 aerial photograph.
Building present; pre-alteration.
Courtesy NMDOT.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Plaza del Monte Residence 7	**2. Location:** 116/120 Camino Matias *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Survey Photographs

(All images taken by John Murphey on January 18, 2018, except where indicated)

Photo 1: Street and north elevations, facing southwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____	*Please complete HCPI FORM 1 before completing FORM 2* ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: Plaza del Monte Residence 7	**2. Location:** 116/120 Camino Matias *Downtown and Eastside Historic District*	**3. Local Reference Number:** Santa Fe ID #: Plaza del Monte Inventory **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 2: South elevation, facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: CPI No._____ District No._____	***Please complete HCPI FORM 1 before completing FORM 2*** ___NRHP ___SRCP Criteria __A __B __C __D	
1. Name of property: **Plaza del Monte Residence 7**	**2. Location:** **116/120 Camino Matias** ***Downtown and Eastside Historic District***	**3. Local Reference Number:** **Santa Fe ID #:** **Plaza del Monte Inventory** **4. County: Santa Fe** **5. Date of Survey: January 18, 2018**

Photo 3: West elevation, facing northeast.

DONNELL
DONNELL
AND ASSOCIATES

April 29, 1988

Board of Pensions
Presbyterian Church (USA)
c/o Gaylan and Leona Friesenborg
417 Paseo de Peralta
P.O. Box 1888
Santa Fe, New Mexico 87504

REFERENCE: Appraisal Report
Plaza del Monte Retirement Community
417 Paseo de Peralta
Santa Fe, New Mexico

Dear Mr. and Mrs. Friesenborg:

Attached is our report containing our conclusions of market value from the inspection of the above referenced property. Our analysis indicated the values of the property under the valuation criteria outlined in the report are as follows:

EFFECTIVE DATE: February 11, 1988

	Market Value	Present Value, Two Years	Future Sale, Four Years
1. Casa Grande Tract, at its market supported Highest and Best Use (Land Value)	$1,350,000	$1,100,000	$ 850,000
2. Casa Grande Tract, as a congregate care retirement facility			
Non-Profit	$ 400,000	$ 325,000	$ 250,000
For-Profit	$ 350,000	$ 275,000	$ 225,000
3. Las Placitas Tract, at its market supported Highest and Best Use (Land Value)	$1,275,000	$1,000,000	$ 800,000

SUMMARY OF SALIENT FACTS

Property:	Plaza del Monte Retirement Community
Location:	417 Paseo de Peralta
Client:	Board of Pensions Presbyterian Church (USA)
Land Area:	9.146 acres
Net Usable Land Area:	
Casa Grande Tract	2.826 acres
Las Placitas Tract	5.802 acres
Present Use:	Retirement Community
Highest and Best Use:	
Casa Grande Tract	Speculative holding for commercial development
Las Placitas Tract	Residential development, interim use as residential rental compound
Date of Valuation:	February 11, 1988
Value Conclusions:	
Casa Grande Tract	$1,350,000
Las Placitas Tract	$1,275,000
Total Property (Plaza del Monte)	$2,625,000

Neighborhood Development

Neighborhood development is mixed. Two fraternal organizations, the Scottish Rite Temple and Masonic Lodge, front on Paseo de Peralta. A large local law office occupies a converted school dormitory on the north side of the Masonic Lodge. The Plaza del Monte retirement community, a mix of a congregate living facility, freestanding dwellings, and apartments, borders Fort Marcy Park on the north and fronts on Paseo de Peralta and Old Taos Highway on the southwest. There are several single family residences fronting on Bishop's Lodge Road between the Scottish Rite Temple and Plaza del Monte.

Development immediately south of Paseo de Peralta is a Federal Office complex including the Federal Courthouse, Post Office and other federal government offices. Development in the northwest quadrant of Paseo de Peralta and Old Taos Highway consists of small professional offices in the BCD zoning district. Fort Marcy Park, a large City operated recreational complex approximately 27 acres in size, includes playing fields, a swimming pool/gymnasium complex, a small ampitheater, tennis courts, jogging trails and open space, and a City fire station. North of Fort Marcy Park, east of Bishop's Lodge Road, and northwest of the neighborhood is a mix of single and multiple family residential development.

Zoning

Zoning in the neighborhood is RM-2, Multiple Family Residential District, and C-1, Office and Related Commercial District. The zoning of the 2.697± acre parcel currently occupied by the Masonic Lodge and the White, Koch, Kelly and McCarthy law offices was changed in 1984 from RM-2 to C-1.

Zoning south of Paseo de Peralta and west of Old Taos Highway is BCD, Business Capitol District, Marcy Subdistrict. Zoning west of Bishop's Lodge Road is RM-1, Multiple Family Residential District. Zoning north and northwest of the neighborhood is Single and Multiple Family Residential (R-3, R-4, R-5 and RM-1).

Community Services

All community services are available and adequate. Utility suppliers are discussed in the Santa Fe Profile. Police and fire protection are typical for Santa Fe.

Conclusions

The subject neighborhood is a mixed-use area on the northern fringe of the Santa Fe Central Business District. The area is well located and accessible and no detrimental influences have been observed. Please refer to the Santa Fe and Central Business District profiles in the addenda to the report for additional information.

Detrimental Influences

The primary detriment to development is the drainage easement for Arroyo Mascaras in the northwest corner of the site. The arroyo is four or more feet below street grade of Old Taos Highway and the drainage is supported by a stone retaining wall. Although we have not been able to document the drainage easement, according to Ormand Earp, City Engineer, the easement was acquired in the original 1901 U.S. patent to the City of Santa Fe and/or by a proscriptive easement as a natural drainageway. The drainage is maintained by the City and we assume the easement to be legally supported. The calculated area of the easement is .519 acres, or 22,608± sq.ft., leaving a net usable area of 8.627± acres. All of the encumbered area is in the Las Placitas tract. Net usable area of Las Placitas tract is 5.802 acres (6.321 - .519), or 252,735± sq.ft.

With the exception of the drainage channel, there are no known detrimental influences on the property. There have been no problems with soil or subsoil conditions on the subject or adjacent properties and the site is assumed to have adequate load bearing capability for the existing or any proposed development. Drainage is adequate. There are no other known restrictive or atypical easements. The property is in an architecturally controlled historic district.

Zoning

The property is zoned RM-2, Multiple Family Residential District. The intent of the zoning ~~is to~~ provide for single-family, two-family and multiple-family residences and related developments. The existing improvements are in conformance with the zoning. Zoning and potential zoning changes are discussed more fully in the Highest and Best Use section of the report.

Utilities

All public utilities are available and in place on the site.

Conclusions

The subject site is a well located property on the northern fringe of the downtown Central Business District of Santa Fe. The site has access and visibility from three arterial streets. With the exception of the previously discussed drainage easement, the site is not affected by any known nuisances or hazards.

IMPROVEMENT DESCRIPTION

At the time of inspection, the subject property was improved with the Plaza del Monte retirement community. The complex consists of Casa Grande, a congregate living facility in the southwest portion of the site, and Las Placitas, a residential compound of 41 dwelling units in the northern portion of the site. Please refer to the reduced copies of construction plans and photographs in the addenda to the report for visual representation of the improvements. Improvement features are briefly outlined as follows:

Casa Grande

Architecture:	Pueblo style, stuccoed masonry construction.
Building Area:	Gross heated building area has been calculated at 28,428 sq.ft. from the building plans.
Floor Plan:	The floor plan consists of one main common use facility and four residential wings. Common use facilities include a lobby/reception area, lounge, shop, kitchen and dining room, employee lounge and sleeping quarters, public restrooms, and manager's office. There are three dormitory-style dwelling wings with one and two bedroom units. One wing has been converted to four two-bedroom apartments.
Foundation:	Reinforced concrete.
Floors:	Concrete slab on steel joists. There is a crawl space under the majority of the building.
Walls:	All interior and exterior load-bearing walls are concrete block. Interior portions are steel frame and drywall.
Roof:	Three-inch concrete on steel joists. Roofing is built-up and graveled asphalt over one-half inch rigid insulation.

IMPROVEMENT DESCRIPTION

At the time of inspection, the subject property was improved with the Plaza del Monte retirement community. The complex consists of Casa Grande, a congregate living facility in the southwest portion of the site, and Las Placitas, a residential compound of 41 dwelling units in the northern portion of the site. Please refer to the reduced copies of construction plans and photographs in the addenda to the report for visual representation of the improvements. Improvement features are briefly outlined as follows:

Casa Grande

Architecture:	Pueblo style, stuccoed masonry construction.
Building Area:	Gross heated building area has been calculated at 28,428 sq.ft. from the building plans.
Floor Plan:	The floor plan consists of one main common use facility and four residential wings. Common use facilities include a lobby/reception area, lounge, shop, kitchen and dining room, employee lounge and sleeping quarters, public restrooms, and manager's office. There are three dormitory-style dwelling wings with one and two bedroom units. One wing has been converted to four two-bedroom apartments.
Foundation:	Reinforced concrete.
Floors:	Concrete slab on steel joists. There is a crawl space under the majority of the building.
Walls:	All interior and exterior load-bearing walls are concrete block. Interior portions are steel frame and drywall.
Roof:	Three-inch concrete on steel joists. Roofing is built-up and graveled asphalt over one-half inch rigid insulation.

Interior Finish:	Floor covering is a mix of carpeting and vinyl asbestos tile. Walls are painted and stuccoed. Ceilings are painted drywall and acoustic tile. There are ceramic tile floors and wall covering in the kitchen and wainscotting in the baths is ceramic tile. The ceilings in the dining room and lounge are exposed beams.
Electrical:	Assumed to be adequate and to code. Fluorescent and incandescent lighting fixtures.
Plumbing:	The dormitory style dwelling wings have one toilet and lavatory per room. Seven units have been remodeled to add bath or shower facilities. The dormitory style wings also have common bath, shower and laundry facilities. The remodeled apartment wing has one full bath, two half baths and kitchen facilities per apartment. The common use facility has men's and women's public restrooms, men's and women's employee baths, and the kitchen is plumbed for commercial food preparation. The employee lounge and sleeping rooms have full baths.
Mechanical Systems:	Heat is from a gas-fired hot water baseboard system. The heating system was separated from the domestic hot water system in 1987. Domestic hot water is now heated by six 100-gallon gas water heaters. There is no air conditioning system. A new kitchen ventilating system was installed in 1987.
Site Improvements:	Site improvements associated with Casa Grande include extensive landscaping, concrete walks, paved parking and drives, a 378± sq.ft. greenhouse adjacent to the north residential wing, and covered parking from a six-car carport, one two-car garage and one one-car garage.

Comments:
The original Casa Grande structure was built in 1962. The north residential wing was built in 1973 and was converted to two-bedroom apartments in 1977. The improvements are well maintained and in good condition. No deferred maintenance was observed.

Changes not shown on the attached plans include:

* Two of the dormitory style apartments in the north-central wing have been converted to an activity room.
* Showers have been added to four dormitory style rooms and baths have been added to an additional three rooms.
* Interior doors have been added to convert four sets of adjacent one bedroom units to two-room units.
* The greenhouse, six-car carport and two-car garage have been added.
* A walk-in cooler was added to the kitchen in March, 1988.

An energy conservation study was prepared for the building in 1986. Improvements made pursuant to the study have been:

* The heating and domestic hot water systems are now independent. A new heating system boiler and six 100-gallon domestic hot water heaters were installed in 1986.
* Storm windows were installed in 1986.
* A new kitchen ventilation system was installed in 1987.

The study also called for a tempered fresh air system for the apartments. The system was scheduled for 1989.

The main common use building is functional in design and of average appeal. The kitchen is a well designed and equipped commercial quality facility. The dining room and lounge area are of superior quality finish to the remainder of the structure.

The apartments in the remodeled north wing are average quality rental units and typical of the local rental market. The dormitory style dwelling units are somewhat institutional in design and of limited appeal by current market standards. The two bedroom apartments in the north wing contain approximately 1,070 sq.ft. apiece. The one-room dormitory style apartments contain 249± sq.ft. and the two-room apartments contain 498± sq.ft.

The Casa Grande facility is of good to average quality construction. The structure has been well maintained and is in good condition. Although there have been improvements and upgrading, the design of the structure, particularly the dormitory style apartments, is somewhat dated. Actual age of the base structure is 26 years, and the addition was built 13 years ago and remodeled four years later. We estimate effective age of the improvements to be approximately 25 years.

Las Placitas

The Las Placitas Compound consists of 37 dwelling units in 25 structures. The unit mix is 19 single-family dwellings, three duplexes, and three fourplexes. Five of the residences were existing at the time the project was dedicated. The remainder of the dwellings were built over the approximate time frame of 1962 to 1972. The existing dwellings have all been renovated and/or remodeled. Following is a chart briefly outlining the major design features. (NOTE: The I.D. number refers to the numbering system used on the site plan in the addenda).

As of 1988

IMPROVEMENT SUMMARY CHART
LAS PLACITAS RESIDENTIAL COMPOUND
PLAZA DEL MONTE

I.D.	Street Address	Type of Dwelling	Area (Sq.Ft.)	Room Count (Total-Bedrooms-Baths)	Age (Yrs.)	Comments
R-1	104 Camino Matias	Single-Family	944	4-2-1.5	26	
R-2	102 Camino Matias	Single-Family	944	4-2-1.5	26	
R-3	106 Camino Matias	Single-Family	944	4-2-1.5	26	
R-4	118 Camino Santiago	Single-Family	1,141	5-2-2	16	
R-5a	110 Camino Matias	Duplex	897	5-2-1	26	
R-5b	112 Camino Matias	Duplex	839	4-1-1	26	Addition 1968
R-6	111 Camino Matias	Single-Family	1,433	6-3-2	Unknown	Remodeled/Renovated 1962
R-7a	116 Camino Matias	Duplex	1,072	4-2-2	Unknown	Renovated 1967, Remodeled 1986
R-7b	120 Camino Matias	Duplex	1,099	4-2-2	Unknown	Renovated 1962, Remodeled 1986
R-8	109 Camino Matias	Single-Family	1,095	5-2-1	Unknown	Remodeled/Renovated 1962
R-9	107 Camino Matias	Single-Family	932	4-2-1	Unknown	Remodeled/Renovated 1962
R-10	105 Camino Matias	Single-Family	932	5-2-1	Unknown	Remodeled/Renovated 1962
R-11	101 Camino Santiago	Single-Family	1,163	4-2-1	20	
R-12	103 Camino Santiago	Single-Family	1,064	5-2-2	20	
R-14a	105a Camino Santiago	Fourplex	926	4-2-1	26	
R-14b	105b Camino Santiago	Fourplex	699	3-2-1	26	
R-14c	105c Camino Santiago	Fourplex	699	3-2-1	26	
R-14d	105d Camino Santiago	Fourplex	926	4-2-1	26	
R-15	109 Camino Santiago	Single-Family	1,029	4-2-2	25	
R-16	111 Camino Santiago	Single-Family	1,082	4-2-2	25	
R-17a	115a Camino Santiago	Duplex	1,052	4-2-2	18	
R-17b	115b Camino Santiago	Duplex	1,179	4-2-2	18	
R-18	117 Camino Santiago	Single-Family	1,356	6-2-2	Unknown	Estimated effective age 20-25 yrs.
R-19	119 Camino Santiago	Single-Family	1,105	5-2-1	25	
R-20	121 Camino Santiago	Single-Family	1,152	5-2-2	18	
R-21a	125a Camino Santiago	Fourplex	944	4-2-1	19	
R-21b	125b Camino Santiago	Fourplex	676	3-2-1	19	~ 1969
R-21c	125c Camino Santiago	Fourplex	676	3-2-1	19	
R-21d	125d Camino Santiago	Fourplex	944	4-2-1	19	
R-22	122 Camino Santiago	Single-Family	1,218	5-2-2	Unknown	Estimated effective age 20-25 yrs.
R-23	124 Camino Santiago	Single-Family	1,153	4-2-2	21	
R-24a	126a Camino Santiago	Fourplex	690	3-1-1	21	
R-24b	126b Camino Santiago	Fourplex	690	3-1-1	21	
R-24c	126c Camino Santiago	Fourplex	690	3-1-1	21	
R-24d	126d Camino Santiago	Fourplex	690	3-1-1	21	
R-25	120 Camino Santiago	Single-Family	1,259	5-2-2	18	
R-26	114 Camino Santiago	Single-Family	1,318	4-2-2	17	

Site Improvements:

Site improvements to Las Placitas include landscaped common area, landscaped yards for the individual residences, walks and drives, and two privately owned single-lane paved streets, Camino Matias and Camino Santiago, approximately 20 to 25 feet in width.

Comments:
All of the dwellings are of average quality concrete block or frame stucco construction. The dwellings have been well maintained and are in good condition. No deferred maintenance was observed. In general, the quality and type of construction of the dwellings is more typical of tract housing than northside Santa Fe development comparable in age and location. The landscaping of the compound is well cared for and has strong visible appeal.

NOTE: Area calculations, actual age and room counts are from drawings provided by our client and the project architect, Phillipe Register. We assume these drawings to be accurate. Also, we have not inspected the interiors of all of the units. We assume that the units inspected are representative of the quality and condition of the compound.

* Interviews with the City Planner's Office as well as the property owner and lessee of the adjacent property to the east.
* The recent zoning change on the adjacent property to the east.

The most desirable zoning for the property in terms of development options would be Business Capital District, or BCD. Zoning west of Old Taos Highway and south of Paseo de Peralta is presently BCD, Marcy Subdistrict. C-1, or Office and Related Commercial District, would allow for development with professional offices or compatible uses. The zoning of the adjacent property to the east was recently changed from RM-2 to C-1.

Although in our opinion a zone change for the La Casa Grande tract is a reasonable expectation, it should be emphasized that there is risk involved in any zone change application. Zoning change applications, even with support of city staff, have been denied due to public opposition and other political factors.

It is also our opinion that there is substantially higher risk involved in a zone change for the Las Placitas tract (estimated 6.321 acres). This tract does not have access or visibility from Paseo de Peralta and development to the east and west is residential. Development to the north is a city park zoned residentially and north of the park is residential development. Opposition to a zone change for the Las Placitas tract could also be expected from city staff.

At present, there is an oversupply of office and retail space, as well as multi-family and high end ($300,000+) residential property in Santa Fe in general and the downtown area in particular. Vacancy rates are substantial and the market is highly competitive.

Development of an office, retail, or mixed use project on the Casa Grande tract could be economic with a strong anchor tenant and significant pre-construction lease commitments. Otherwise, an investor can expect excessive vacancy rates and/or rent concessions with an office or retail development. Another development option for this location, depending on the scope of a potential zone change, is some sort of lodging and/or tourism industry project (hotel/motel, restaurant, gallery, shops, etc.). Even with the risks associated with a zoning change and the competitive commercial real estate market, however, the Casa Grande tract will support a higher land value than a strictly residential parcel. We therefore conclude highest and best use of the Casa Grande tract, if vacant, to be a speculative holding.

The dwellings on the Las Placitas tract are physically and legally adaptable as rental housing and there is a demand for rental housing particularly in this area of Santa Fe. We have investigated the possibility of subdividing Las Placitas and marketing the individual units. According to the City Subdivision Engineer, it is unlikely the tract could be legally subdivided due to the lot size, setback, and street width and right of way requirements. The individual units could be marketed, however as a condominium or planned unit development (PUD) project with the streets and common areas the responsibility of a homeowner's association. The income producing capacity of Las Placitas as a rental compound or PUD housing development will support value close to or slightly above the value of the underlying land.

Although the improvements to the Las Placitas tract have a limited contributory value, we have concluded that the highest return to this portion of the property would be from more intensive development. In our opinion, highest and best use of the Las Placitas tract is future high density residential development with an interim use as a residential rental compound.

MARKET RENT PROJECTION
LAS PLACITAS RESIDENTIAL COMPOUND

ID	Address	Monthly Rent
R-1	104 Camino Matias	$600
R-2	102 Camino Matias	$600
R-3	106 Camino Matias	$600
R-4	118 Camino Santiago	$650
R-5a	110 Camino Matias	$550
R-5b	112 Camino Matias	$525
R-6	111 Camino Matias	$700
R-7a	116 Camino Matias	$625
R-7b	120 Camino Matias	$625
R-8	109 Camino Matias	$600
R-9	107 Camino Matias	$550
R-10	105 Camino Matias	$550
R-11	101 Camino Santiago	$600
R-12	103 Camino Santiago	$625
R-14a	105a Camino Santiago	$550
R-14b	105b Camino Santiago	$450
R-14c	105c Camino Santiago	$450
R-14d	105d Camino Santiago	$550
R-15	109 Camino Santiago	$625
R-16	111 Camino Santiago	$625
R-17a	115a Camino Santiago	$600
R-17b	115b Camino Santiago	$600
R-18	117 Camino Santiago	$650
R-19	119 Camino Santiago	$600
R-20	121 Camino Santiago	$625
R-21a	125a Camino Santiago	$550
R-21b	125b Camino Santiago	$450
R-21c	125c Camino Santiago	$450
R-21d	125d Camino Santiago	$550
R-22	122 Camino Santiago	$650
R-23	124 Camino Santiago	$600
R-24a	126a Camino Santiago	$450
R-24b	126b Camino Santiago	$450
R-24c	126c Camino Santiago	$450
R-24d	126d Camino Santiago	$450
R-25	120 Camino Santiago	$650
R-26	114 Camino Santiago	$650
Total Monthly Rent		$21,075
Total Annual Rent (PGI)		$252,900

DONNEL DONNEL AND ASSOCIATI

PRESENT VALUE STUDY

Under a phased marketing strategy, sale proceeds may not be received until a future date. A prudent investor would therefore most likely discount future income (sale proceeds) to reflect lost income generating capacity until the income is received (the time value of money). A payment can be discounted to present value by calculating the amount that should be invested now to grow with compound interest at a satisfactory rate to equal the future payment.

From review of real estate industry publications, interviews with real estate investors and other real estate professionals, and comparison with alternative investments considered comparable in terms of risk, liquidity and other investment criteria, in our opinion the most reasonable discount rate for future sale of the property is in the 12% to 13% range. Future sales will therefore be discounted to present value at a 12% interest rate. No appreciation or depreciation is projected over the proposed time frame. Our discounting analysis is summarized on the following chart.

Also:

* The property has been inspected by the undersigned.
* Facts cited or used are deemed accurate.
* We have no present or anticipated interest, neither do we have any other personal bias.
* Our compensation in no way depends on the reported conclusions.
* All limiting conditions are presented within.
* We have prepared this report in conformity with the professional standards of the organizations to which we subscribe.
* The use of this report is subject to the requirements of the American Institute of Real Estate Appraisers relating to review by its duly authorized representatives.
* No one provided significant professional assistance to the person signing this report.
* The analyses, conclusions, and opinions are ours.

Respectfully,

DONNELL, DONNELL & ASSOCIATES



John T. Donnell, MAI

The American Institute of Real Estate Appraisers conducts a voluntary program of continuing education for its designated members. MAI's and RM's who meet the minimum standards of this program are awarded periodic education certification. John T. Donnell is certified under this program.

DONNELL DONNELL & ASSOCIATES
Page 809 of 1144

CERTIFICATION

This certifies that effective February 11, 1988, the estimated values ot the subject of this report are:

	Market Value	Present Value, Two Years	Future Sale, Four Years
1. Casa Grande Tract, at its market supported Highest and Best Use (Lahd Value)	$1,350,000	$1,100,000	$ 850,000
2. Casa Grande Tract, as a congregate care retirement facility			
Non-Profit	$ 400,000	$ 325,000	$ 250,000
For-Profit	$ 350,000	$ 275,000	$ 225,000
3. Las Placitas Tract, at its market supported Highest and Best Use (Land Value)	$1,275,000	$1,000,000	$ 800,000
4. Las Placitas Tract, as a residential rental compound	$1,200,000	$ 950,000	$ 775,000
5. Entire Property (Plaza del Monte), at its market supportable Highest and Best Use (Land Value)	$2,625,000	$2,100,000	$1,675,000
6. Plaza del Monte as a retirement community			
Non-Profit	$1,500,000	$1,200,000	$ 950,000
For-Profit	$1,300,000	$1,050,000	$ 825,000

DONNELL DONNELL AND ASSOCIATES

City of Santa Fe, New Mexico

memo

DATE: September 8, 2026

TO: Historic Districts Review Board Members

VIA: Heather Lamboy, AICP, Planning & Land Use Department Director
Maggie Moore, Assistant Land Use Director, MM

FROM: Lani McCulley, Senior Planner, Historic Preservation Division, LGM

2026-012976-HDRB. 338 Orchard Dr., Downtown & Eastside Historic District. Contributing. Osage Design Studio, agent for Anita Alarid, owner, requests a historic status review with primary facade(s) designation, if applicable, for a residential structure.

REFERENCE ATTACHMENTS (Sequentially):

CITY SUBMITTALS

____ **District Standards & yard wall & fence standards.**

__x__ **Historic Inventory Form**

__x__ **Zoning Review Sheet**

__x__ **Other**: [area aerials]

APPLICANT SUBMITTALS

__x__ **Proposal Letter**

__x__ **Site Plan/Floor Plan**

__x__ **Elevations**

__x__ **Photographs**

__x__ **Other:** [2026 HCPI]

STAFF RECOMMENDATION:

Staff recommends the historic status of the structure be maintained as contributing, with the north and west elevations (R1 and R7), including the portal, as the primary façades, per 14-4.6(C) Designation of Significant, Contributing or Noncontributing Status Within Historic Districts.

Sample motions:

a. In case 2026-012976-HDRB, for 338 Orchard Drive, retain/designate the main residence as contributing and designate facades (R1 and R7) as primary façades.

Figure 1: Property Location

BACKGROUND & SUMMARY:

Site Description:

The property at 338 Orchard Drive has been under several addresses, including 338 ½ Orchard Drive and 338 ½ East De Vargas Street. The 1984 Historic Cultural Properties Inventory shows the residence as the East De Vargas Street address. The residence sits just south of the Alarid house to the north at 338 East De Vargas Street and was once part of that property, which may explain the addressing issues.

The property reaches from Orchard Drive to Paseo de Peralta. The eastern portion of the property is currently a parking area with a parking agreement. The entire lot was originally a portion of an orchard that belonged to the Chapman family and reached much further than its current space. The land was slowly subdivided and sold off throughout the years.

Figure 2: The Residence Northwest Corner

The 1931 Adobe territorial-style residence is currently listed as contributing to the Downtown and Eastside Historic District. The residence is known as the Constanct and Ruby Chapman House. The roof is flat with a three-course brick coping.

The windows of the residence are primarily double-hung, three-over-one above a single-lite sash with separate window screens. There is a non-historic vinyl window on the south that is not typical of the residence and was installed at an unknown date. The exterior doors are wood with glazing. The doors and windows are painted in a turquoise color.

A portal sits on the north elevation. The portal is supported by painted wood columns, a wood header, exposed roof vigas, and corbels. The floor of the portal is high concrete with two sets of concrete steps. There is a visible dip in the roof line from the floor slab settling. The original porch had masonry columns on either corner with a header, a wood column, and corbels in the center. The design is evident in the 1984 Historic Cultural Properties Inventory image.

Figure 3: Portal Columns 1930s and 2026

The screened porch on the east elevation is not original to the house but was constructed by 1958. It appears on aerials to change in size over time. It is currently constructed of vertical wood siding with framed fixed screened windows, a sloped shed roof with galvanized metal drip edge.

The west elevation houses a low stuccoed chimney stack, and on the south elevation, a small basement window at grade is visible and is the only indication that there is a partial cellar under the residence.

The property is lined with a coyote fence on the east, which separates the residence from the commercial parking lot, and a wood and chain link fence along the south property line. A board fence lines the north and west property lines.

The property has been in the Chapman/Alarid family since its construction in 1931 by Ruby Gonzales Chapman and Constant R. Chapman. Their daughters Anita Chapman Alarid and her younger sister Adalida Chapman were raised in the house. Anita's granddaughter, Christina Martinez, is the current owner and resident, raising her daughter Sofie in the house. The house has continually been in the family for eighty years.

PREVIOUS CASE SUMMARIES:

ARC:

No archaeological clearance has been issued for the property.

HDRB:

No cases from the Historic District Review Board were found for the property.

ADMINISTRATIVE:

A re-roof was approved administratively in 2023 under case 2023-007294-ADMIN.


Figure 4: North Elevation Image from 1984 HCPI

APPLICANT'S REQUEST:

The applicant proposes the following exterior alterations:

1) Status Review with primary façade designation, if applicable, for a residential structure.

The house has retained its historic footprint, main design features, and openings from its construction date. It continues to convey its historic period and original design. Though it is associated with four generations of the family, it is not enough to define a status of significance. Therefore, staff recommends the residence remain with a contributing status. Though the portal on the north has changed slightly, it is the strongest architectural feature of the structure. The portal is documented in period photographs and reflects the family's use of the residence. The west elevation is the most publicly visible and retains the original window openings and continues to express the historic character of the structure. Therefore, staff would recommend the north and west elevations as primary facades, including the north portal.



Figure 5: Façade Diagram

RELEVANT CODE CITATIONS:

14-4.6 HISTORIC DISTRICTS

A. General Provisions

1. Purpose

In order to promote the economic, cultural, and general welfare of the people of Santa Fe and to ensure the harmonious, orderly, and efficient growth and development of the City, the Governing Body deems it essential to preserve the qualities relating to the history and culture of Santa Fe, maintain a harmonious outward appearance in order to preserve property values, and attract residents and tourists alike. The specific purposes of this section are to preserve qualities relating to the history of Santa Fe, such as the following:

I. Continue the existence and preservation of historic areas and buildings;

II. Continued construction of buildings in Santa Fe's historic styles; and

III. General harmony as to architectural style, form, color, height, proportion, texture, and material between buildings of historic design and those of more modern design.

B. Buildings with Significant or Contributing Historic Status

I. Purpose

Historic designation is intended to address the following:

I. Recognizing each structure as a physical record of its time, place, and use.

II. Preventing changes that create a false sense of historical development, such as the addition of conjectural features or architectural elements from other buildings;

III. Preserving and retaining changes to structures that have acquired historic importance in their own right, recognizing that most structures change over time;

IV. Preserving distinctive features, finishes, and construction techniques or examples of craftsmanship that characterize a structure; and

V. Avoiding making new additions and related or adjacent new construction in such a manner that, if removed in the future, the original form and integrity of the historic property and its environment would be unimpaired.

2. Designation of Significant, Contributing, or Noncontributing Status

I. Status Designation

Structures within historic districts may be designated a status of "significant," "contributing," or "noncontributing," as defined in Section 14-9.3, *General Definitions.* Staff shall maintain a record of the current status of structures located in the historic districts.

II. HDRB Authority to Review Status Designation

a. The HDRB may change the status of a structure or designate a status for a structure that has no status designated.

b. A change in status or the designation of a status shall be based upon an evaluation of data provided through survey or other relevant sources of information and the definitions of "significant," "contributing," or "noncontributing."

c. When the HDRB designates a structure as contributing, it shall also specify which facades of the structure are primary.

III. Initiation of Review of Status Designation

The Board may review the status designation in response to the following:

a. An application for construction or demolition as set forth in Section 14-5.2 as follows:

1. Prior to the application being placed on a board agenda or prior to issuance of a construction permit, if Board approval is not required, staff shall determine whether the board should review the status of the structure. Staff's determination shall be made within thirty days of submitting the application. If staff's determination is not completed within thirty days, the application shall be forwarded to the board. Review by the board as to the structure's status shall be made at the earliest practicable date. The board or staff (as applicable) may consider the application immediately following the determination of

status. The application shall be reviewed based upon the status of the structure following the determination of status.

2. Prior to action by the board on the application, the board itself may decide to review the status of the structure. The board's determination as to the status shall be made within forty-five days of the decision of the board to review the status. The board or staff (as applicable) may consider the application immediately following the determination of the status. The application shall be reviewed based upon the status of the structure following the determination of status.

b. Request from the property owner;

c. A request initiated by the city. Staff shall notify the property owner prior to initiating the request.

IV. Notice of HDRB's Review of Status

a. Unless the review is requested by the property owner, staff shall mail notice to the property owner of the subject property no less than 15 days prior to the HDRB's review of a change in or designation of status.

b. In addition, staff shall send notice, by first-class mail, to all property owners within one hundred (100) feet of the subject property no less than fifteen days prior to the board's review of a change in or designation of status if the review may result in the lowering of the structure's status. Staff shall retain an affidavit of mailing.

c. With the consent of the property owner, the city shall have posted on the property a poster obtained from the planning and land use department. Otherwise, the city shall post the poster at the nearest place available to the city. Such poster shall be securely posted, prominently displayed, and visible from a public street, at least fourteen days prior to the scheduled board hearing. The posting shall indicate the nature of the application, identification of the property affected, and the time, date, and place of the hearing. The poster shall be removed within thirty days of final action. Failure to do so may result in the city removing the sign at the applicant's expense. A civil fee of fifty dollars ($50.00) will be charged.

NONCONTRIBUTING STRUCTURE

A structure, located in a historic district, that is less than 50 years old, or that does not exhibit sufficient historic integrity to establish and maintain the character of the Historic district.

CONTRIBUTING STRUCTURE

A structure, located in a historic district, approximately 50 years old or older that helps to establish and maintain the character of that historic district. Although a contributing structure is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The contributing structure may have had minor alterations, but its integrity remains.

SIGNIFICANT STRUCTURE

A structure located in a historic district that is approximately 50 years old or older, and that embodies distinctive characteristics of a type, period, or method of construction. For a structure to be designated as significant, it must retain a high level of historic integrity. A structure may be designated as significant for its association with events or persons that are important on a local, regional, national, or global level; or if it is listed on or is eligible to be listed on the State Register of Cultural Properties or the National Register of Historic Places.

PRIMARY FACADE

One or more principal faces or elevations of a building with features that define the character of the building's architecture.

G. Additional District-Specific Design Standards

2. **Downtown and Eastside Historic District**

The governing body recognizes that a style of architecture has evolved within the city from the year 1600 to the present characterized by construction with adobe, hereafter called "old Santa Fe style", and that another style has evolved, hereafter called "recent Santa Fe style", which is a development from, and an elaboration of the old Santa Fe style, with different materials and frequently with added decorations.

I. Old Santa Fe Style

Old Santa Fe style, characterized by construction with adobe, is defined as including the so-called "pueblo" or "pueblo-Spanish" or "Spanish-Indian" and "territorial" styles and is more specifically described as follows:

a. With rare exception, buildings are of one story, few have three stories, and the characteristic effect is that the buildings are long and low. Roofs are flat with a slight slope and surrounded on at least three sides by a firewall of the same color and material as the walls or of brick. Roofs are never carried out beyond the line of the walls except to cover an enclosed portal or porch formed by setting back a portion of the wall or to form an exterior portal, the outer edge of the roof being supported by wooden columns.

Two-story construction is more common in the territorial than in other sub-styles, and is preferably accompanied by a balcony at the level of the floor of the second story. Façades are flat, varied by inset portales, exterior portales, projecting vigas or roof beams, canales or water-spouts, flanking buttresses and wooden lintels, architraves and cornices, which, as well as doors, are frequently carved, and the carving may be picked out with bright colors. Arches are almost never used except for nonfunctional arches, slightly ogival, over gateways in freestanding walls;

b. All exterior walls of a building are painted alike. The colors range from a light earth color to a dark earth color. The exception to this rule is the protected space under portales, or in church-derived designs, inset panels in a wall under the roof, in which case the roof overhangs the panel. These spaces may be painted white or a contrasting color, or have mural decorations;

c. Solid wall space is always greater in any façade than window and door space combined. Single panes of glass larger than thirty (30) inches in any dimension are not permissible except as otherwise provided in this section;
d. The rules as to flat roofs shall not be constructed to prevent the construction of skylights or installation of air conditioning devices, or any other necessary roof structures, but such structures other than chimneys, flues, vents and aerials, shall be so placed as to be concealed by the firewall from the view of anyone standing in the street on which the building fronts;
e. True old Santa Fe style buildings are made of adobe with mud plaster finish. Construction with masonry blocks, bricks, or other materials with which the adobe effect can be simulated is permissible; provided that the exterior walls are not less than eight (8) inches thick and that geometrically straight façade lines are avoided. Mud plaster or hard plaster simulating adobe, laid on smoothly, is required; and
f. It is characteristic of Old Santa Fe style commercial buildings to place a portal so that it covers the entire sidewalk, the columns being set at the curb line.

II. Recent Santa Fe Style

Recent Santa Fe style intends to achieve harmony with historic buildings by retention of a similarity of materials, color, proportion, and general detail. The dominating effect is to be that of adobe construction, prescribed as follows:

a. No building shall be over two stories in height in any façade unless the façade shall include projecting or recessed portales, setbacks, or other design elements;
b. The combined door and window area in any publicly visible façade shall not exceed forty percent of the total area of the façade except for doors or windows located under a portal. No door or window in a publicly visible façade shall be located nearer than three (3) feet from the corner of the façade;
c. No cantilevers shall be permitted except over projecting vigas, beams, or wood corbels, or as part of the roof treatment described below;
d. No less than eighty percent of the surface area of any publicly visible façade shall be adobe finish, or stucco simulating adobe finish. The balance of the publicly visible façade, except as above, may be of natural stone, wood, brick, tile, terra cotta, or other material, subject to approval as hereinafter provided for building permits;
e. The publicly visible façade of any building and of any adjoining walls shall, except as otherwise provided, be of one color, which color shall simulate a light earth or dark earth color, matte or dull finish and of relatively smooth texture. Façade surfaces under portales may be of contrasting or complementary colors. Windows, doors and portals on publicly visible portions of the building and walls shall be of one of the old Santa Fe styles; except that buildings with portals may have larger plate glass areas for windows under portals only. Deep window recesses are characteristic; and
f. Flat roofs shall not have more than thirty (30) inches overhang.

NEW MEXICO HISTORIC BUILDING INVENTORY FORM H1577.1 6.27.1 DB

building threatened? yes	surveyed date by HMW	county SANTA FE	ID no. 05161
field map number SFHD #4		UTM reference zone 12 13 easting	northing

location description: 338 ½ E. DE VARGAS

city/town: SANTA FE

land grant/reservation:

building name:

legal description: tnsp ___ N S range ___ E W sec ___ ¼ ¼

film roll by HMW no. SFHD 21	negative nos. 31	loc. of neg. HPB



plan shape



date of construction: 1930's. estimate ___ actual

source:

use
present: residential
other:
historic: residential
other:

condition
✓ excellent ___ good
___ fair ___ deteriorating

degree of remodeling
✓ minor ___ moderate ___ major
describe:

surroundings: COMM.

relationship to surroundings
✓ similar ___ not similar

district potential
___ yes ___ no

significance
___ eligible ___ of interest ___ none
if eligible, why?

associated buildings? ___ yes
what type?

if inventoried, list ID nos.

see back? ___ yes

style: T. R. / S. P. REV.

UNK. (CONC?)
wall material/surface

architectural features
RF DRAINS TO MTL. CANALES AT REAR.
STRAIGHT BRK COPING: S/DENTIL. R.H./S ↓.
3/1 D.H. WD WDWS, RECESS'D W/ CONC. LUG SILLS, SGLS & TANDEMS. FRONT DOOR: SGL-LEAF WD PANEL W/ 3 VERT. TALL LIGHTS, W/ SCREEN.
FRONT PORCH: ROUND WD POSTS & CORNER PIERS CARRY EXT'D WD LINTELS ON ZAPATAS & CORBELS W/ STRAIGHT-CUT PROJ.

comments VIGAS & TWO MTL & WD CANALES.
E PORCH: SCREENED-IN FRAME PORCH ON CONC. PAD, T&G WD WALLS.
ALL WD IS AQUA RT'D.

1975



1957 Scanlon Map

1957

1951

1942
Scanlon



1936-1937

Osage Design Studio
Richard Woodbury
1216 Vitalia Street
Santa Fe, NM 87505
505.629.5948
osagedesignstudio@yahoo.com

August 10, 2026

Historic Preservation Division
Planning and Land Use Department
City Hall
200 Lincoln Avenue
Santa Fe, NM 87501

Address:	338 Orchard Drive, Santa Fe NM 87501
Owners:	Anita Alarid
Building Status:	Contributing – To be determined
UPC:	1-054-099-379-007
Parcel No.:	10438784

On behalf of the applicant Anita Alarid, I am submitting a **Request for Status Review** for 338 Orchard Drive. The property is located within the Downtown and Eastside Historic District.

The lot contains an existing single-story single-family residence constructed in the early 1930s. It has been in family possession and occupancy since its construction. The Owner Applicant intends to construct a bedroom addition to the existing residence for their growing family. It would be located on the south and east side of the existing structure. The historic status needs to be confirmed so that the applicant knows the full range of code rules to the addition.

The property is currently considered "**Contributing**." Based on my own observations and that of the current HCPI, I do not see any reasons to either upgrade or downgrade the existing status. In fact, this project is a clear example of the intent of historic districts preservation as noted in the city code, "*Strengthen the unique heterogeneous character of the City by providing a full range of design options to* ***ensure that residents can continue to reside within the historic districts****."* If the structure was upgraded to "significant", it is likely that the applicant would not be able to add to the structure and might have to vacate the property. If the status is maintained at "contributing", the HCPI is recommending that the north façade be designated as "primary" with the possibility of the west, street facing, façade also being considering "primary." This is an acceptable to the applicant as this would protect the building's historic residential character while allowing for the applicant's intended addition.

The most current Historic Cultural Properties Inventory (HCPI) dated 8/7/26 prepared by John W. Murphey, Architectural History Services is attached.

Please contact me if you have any questions or require additional information.

Sincerely,

Richard Woodbury

Richard Woodbury
Osage Design Studio

Attachments: HCPI

Osage Design Studio
Richard Woodbury
1216 Vitalia Street
Santa Fe, NM 87505
505.629.5948
osagedesignstudio@yahoo.com

April 19, 2026

Lani McCulley
Historic Preservation Division
Planning and Land Use Department
City Hall
200 Lincoln Avenue
Santa Fe, NM 87501

Re: 338 Orchard Drive, Santa Fe NM 87501
Historic Narrative of Single-Family Residence

Lani:

338 Orchard Drive is the site of a historic single-story single-family residence. The site is a rectangle with the long axis running east-west. The residence is sited on the west end of the lot. The east end of the lot has been leased for parking to a commercial property at 1000 Paseo de Peralta. A fence separates the parking from the residence.

The exact date of construction is inexact, likely 1931 or 1932. The house was constructed as the primary residence of Constance and Ruby Chapman.

The structure is Territorial Style, approximately 12'-0" in height. The structure is roughly square with a roofed portal on the north and a sloped screened porch on the east. The structure has a "flat roof" with territorial style brick coping (horizontal top band, vertical soldier course mid band, and horizontal course bottom band) and stucco wall finish. The exterior walls are adobe with wood framed interior walls. The brick coping appears weathered with missing mortar and some spalling brick. At minimum, repointing the mortar is recommended.

The north portal has the same parapet height. It is supported with painted wood columns, corbels, primary wood header beam, and vigas exposed as the portal ceiling. The raised portal floor has deteriorating stucco on the face of the portal edge and a deteriorating concrete flooring. It is accessed with two sets of deteriorating concrete steps at the north and west. The roof line is noticeably dipping toward the north façade. The owners had a structural engineer assessment approximately 5 years ago (Vince Dimmer, GB and Jim Hands PE, retired). The assessment determined that the portal slab has likely settled, producing the dip in the parapet. Otherwise, the portal appears to be structurally sound.

The existing windows are primarily double hung with a three lite upper sash (3/1) over a single lite lower sash (1/1) with separate window screens. The windows are painted turquoise. A least one window on the south façade has been replaced at an unknown date with a non-historic composite window unit. The typical window unit appears original, historic at the minimum. The windows are not fully functional

and are not weather tight. However, it appears that the windows can be restored. The majority of the window frames and mutins appear to be intact without significant rot damage.

The front door is painted wood with 3/1 upper glazing over a single recessed wood panel. The screen door with wood with a single upper screen panel over a lower 2/2 screen panel. Based on historic photos, the door is not original to the house. The screen door is of a similar design but not likely original to the house. The door is likely historic but its exact age is unknown.

The roof is drained with a combination of painted metal canales on the main house and metal lined stained wood canales on the portal. Historic photos indicate that the portal was originally drained with half round metal canales. These were replaced with the wood canales at an unknown date. Thus, it is likely that all the canales have been replaced at an unknown date.

A screened porch is located on the east façade, southeast corner. Historic photos show that a porch was located here. The construction date is unknown but likely 15 years or less of the house construction. Based on the photo, it appears that the original porch has been significantly altered in size and materials at an unknown date. The existing porch would likely be considered "historic" due to its age but not original to the house. The current porch sits on a badly deteriorated concrete foundation, has vertical wood siding with framed fixed screen windows, and a shallow single slope shed roof with exposed galvanized metal drip edge. Based on the deteriorated slab, it is recommended that the structure be replaced as the foundation cannot be easily repaired without removal of the structure.

A deteriorated coyote fence on the east side of the residence separates the structure from the commercial parking lot. A mix of wood and chain link fencing is located on the south property line. The fence is deteriorated. The structure to the south has been past used as a residence and a business. A relatively new painted wood board fence is located on the west property line. A deteriorated wood board fence is located on the north property. Replace is recommended for the north fence and east coyote fence.

In summary, it appears that the primary residential structure with the attached portal are original. The windows are historic but it cannot be determined if original to the house. The canales have likely been replaced. The screened porch is historic but not original to the house.

The residential structure at 338 Orchard Drive lies within the Downtown and Eastside Historic District. The structure is currently designated "Contributing". This author finds no compelling reasons to upgrade the designation to "Significant" nor downgrade it to "Non-contributing."

The residence has been in continual ownership by the original builders and their descendants. A select list of family members:

- Ruby Gonzales Chapman and Constance R. Chapman, wife and husband, both deceased. Original builders.
- Anita Chapman Alarid, born 1929, daughter of Ruby and Constance. Raised in house.
- Adalida Chapman, younger sister of Anita. Born & raised in house. Lived in house her entire live.
- Elizabeth Alarid, born 1956, daughter of Anita.
- Christina Martinez, daughter of Elizabeth. Current resident.
- Sofie aged 2 ½ years old. Daughter of Christina. Current resident.

Anita Alarid was raised at the 338 Orchard house. She noted that her grandparents built the house at what is currently addressed as 1000 Paseo de Peralta. The 1000 PdP house has a historic plaque designating it as the "Jose Alarid House." The structure was incorporated into the commercial development that long housed Santa Fe Properties. The location of the 338 Orchard house (primary entrance and portal) to the north was primarily to orient it to the Jose Alarid House. Anita noted that the surrounding area was rich with fruit orchards including what is now the parking lot for state office complex at 1120 Paseo de Peralta. The family owned additional land in the immediate area that was sold off over time. Anita's grandmother was a pioneer. The grandmother worked with Adolph Bandelier, was a state librarian, and organist at the Cathedral Basilica of St. Francis of Assisi. The Chapman / Alarid family has long ties in Santa Fe including interests and ownership in multiple properties including what is now known as El Zaguan. Anita is the current title holder of the 338 Orchard property.

Elizabeth Alarid was raised in the Casa Alegre neighborhood of Santa Fe. She attended the St. Francis Catholic School. She spent many afternoons visiting her Gramma Ruby at the Orchard house. Christina and Sofie currently reside in the residence with Sofie's father Dan. They would like to construct an addition to the residence to accommodate their growing family.

Please contact me if you have any questions or require more detailed information.

Sincerely,

Richard Woodbury

Richard Woodbury
Osage Design Studio

Osage Design Studio experience summary. Mr. Woodbury received an architectural degree. He has over thirty years working primarily for architects, but also engineers, general contractors, and architectural product manufacturers. As an employee of Architectural Alliance Inc., he was involved in historic projects such as the Colonial Arts Society Museum (Nuevo Mexicano Heritage Arts Museum), Manderfield School, and the Loretto Chapel. In addition, Mr. Woodbury has worked on other projects such as the Rio Arriba County Courtyard in Tierra Amarilla and county courthouse renovation projects in central Texas.

Historic Photos (exact dates unknown, approximate dates provided)

Original North Façade, circa early 1940's

Original North Façade, circa 195 0's
Constance R. Chapman with grandson

North Façade Entry Portal after stucco work circa 1930's
Ruby Gonzales Chapman

South façade, date unknown

Anita Chapman Alarid, circa 1950's

Anita Chapman Alarid, circa early 1940's
East façade showing original porch

Contemporary Photos (circa 2026)

North Façade Entry Portal

West Façade

South Façade

East Façade

East Facade

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Department of Cultural Affairs

Date of Form: August 7, 2026

For HPD Office use only:
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID: N/A
Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	4. County: Santa Fe Parcel # 10438784

5. Property Type:
_x Buildings: 1, house
_x Structures: fences
__ Site __ Object

6. Date of Survey: July 22, 2026

7. Previous Survey Date(s):
x Yes: undated, c.1984-85, Harry Weiss
_ No:

8. Name of Project:
HDRB Status Evaluation

9. Lat/Long:
35.6826959,-105.9343651

10. Photo Information: Jim Rodman, photographer. Photo 1: View of west and south elevations. Camera facing northeast.

11. Brief Description of the Property:

Constructed in 1931, the Constant and Ruby Chapman House occupies an isolated remnant of former residential properties between Paseo de Peralta and the parking lot of the PERA Building. Constructed of adobe, the house presents a modest expression of the then-popular Territorial Revival style, particularly along its north elevation which is distinguished by an elevated portal. The building retains much of its original design, although a historic frame porch extending across part of the east elevation represents a later alteration. The property contains no other historic-age resources. The house is designated Contributing to the Downtown and Eastside Historic District, although no earlier building survey or Historic Districts Review Board case has been identified documenting or formally establishing that status.

Continued on Page 5.

12. Who uses the property? Residence

13. Construction Date:
Date: 1931
_x_Known __Estimated Source: publication of building permit and city directory entry

14. Setting:
__ Suburban __ Rural __ Village __ Urban If Urban: _x_ Commercial __ Industrial __ Residential __ Public

15. Relationship to Surroundings: _x_ Similar __ Dissimilar
Comments: N/A

16. Additional Perspective: (Photos, drawing, footprint, etc., indicate north arrow when possible)

Source: Office of the Santa Fe County Assessor
parcel lines may not be accurate

17. Surveyor:
(your name, address, telephone number, and any group affiliation)

John W. Murphey
Architectural Historian
Architectural History Services
w/ Jim Rodman

For: Christina Martinez

18. Owner (if known) and other knowledgeable people:

Current owner: Anita Alarid

19. Is Property Endangered? _x_ Unknown __ No __ Yes How?

20. Significance to Current Community: _x_ Unknown __ None __ Low __ Moderate __ High
Describe: Unknown

21. Other Significance or Information of Interest: (such as historical, legendary, structural, former ownership, etc.)
See Historical Overview.

22. National or State Register:

Is this property individually listed on a historic register? __ Unknown _x_ No __Yes
If yes: __ State __ National
If 'no' or unknown, do you think this property is eligible for listing? _x_ No __Yes
Why? See Evaluation of Historical Status

23. National or State Historic District: City of Santa Fe

Is this property in a historic district? __ Unknown __ No _x_ Yes
If yes: __ Significant _x_ Contributing: primary house ___ Non-contributing: ___No Status:
Per City of Santa Fe official designation map:

If 'yes', what is the name of the district? __ State __ National _x_ City of Santa Fe:
Downtown and Eastside Historic District

24. Supplemental Forms:

__ None _x_ HCPI Detail Form (FORM 2) __ Continuation Sheets, # pages: _____

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2*
HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D

1. Name of property:	2. Location:	3. Local Reference Number: Santa Fe ID: N/A
Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	4. County: Santa Fe
		5. Date of Survey: July 22, 2026

ARCHITECTURAL AND CONSTRUCTION DETAILS:

6. Visible Construction Material:

_x_Adobe _x_ Brick __ Composition __ Concrete: Block

__ Concrete: Cast Stone __Concrete: Poured __ Earth Plaster __ Masonry: Simulated

__ Metal: Corrugated __ Metal: Structural Siding __ Metal: V-Crimp __ Stone: Random Ashlar

Stone:
__ Random Coursed __Stone: River Rock __Stone: Rusticated __ Stone: Tabular

_x_Stucco: __ Tile: Clay __ Vinyl Siding __ Wood: Board and Batten

Wood:
__ Horizontal Siding __ Wood: Jacal __ Wood: Log __ Wood: Shingle

__ Wood: Tongue and Groove _x_ Other: wood frame and beadboard panels

7. Number of Stories: __ N/A
Number: _x_1 __11/2 __ 2
__ 21/2 Other: over partial basement

8. Foundation: __ N/A
_x_ Not visible __ None
__ At Grade __Raised:
Materials: _x_ Concrete: __Stone
Other:
Notes

9. Roof: __ N/A

Shape: _x_Flat __Gabled
__ Hipped __ Pyramidal
_x_ Shed:porch Other:
Pitch: __ None __ Low
__ Medium __ Steep
Features: __ Eave:
_x_ Parapets
Materials: _x_Asphalt
__ Earth
__ Composition shingle __ Metal: Pressed
__ Composition Roll __ Metal: Corrugated
__ Metal: Standing Seam__ Metal: V- Crimp: Red Panel
__ Tile: Terra Cotta __ Wood: Shingle
Other:

10. Window Types Primary House and Guesthouse (Casita)

Operation	Material	Glazing	Number
Hung-Sash	Wood	3/1	13
Hung-Sash	Vinyl	1/1	1

Note: Based on visibility and access during survey

11. Door Types Primary House and Guesthouse (Casita)

Type	Style	Material	Number
Single-Leaf	3-light & panel	Wood	1
Single-Leaf	4-light & panel	Wood	1

12. Chimneys _1_: west elevation at parapet line

13. Porches _x_ N/A
Type: __ Entry _x_Partial-Width __ Full-Width __ Wrap _
x_Screen porch addition

14. Other Significant Features N/A

15. Modifications: x __ No known modifications

#1 Date: pre-1958; addition of east frame screen porch; aerial photograph and different construction material and design.
#2 Date: Post-1985; repair and modification of north portal, including removal of solid masonry end walls and installation of wood posts, removal of viga ends, replacement of canales, replacement of wood components; historic photographs, HBI survey, and visual and material evidence.
#3 Date: Unknown, recent past; installation of vinyl bathroom window on south elevation; historic photographs and visual and material evidence.

16. Primary Architectural Style __ Not Applicable

__ Art Deco/Streamline Moderne	__ Gothic Revival	__ Mission Revival	__ Pueblo	__Spanish-Pueblo Revival
__ Bungalow/Craftsman	__ International	__ Neo-Classical	__ Queen Anne	__ Territorial
__ Colonial Revival	__ Italianate	__ Northern NM	__ Ranch	_x_Territorial Revival
__ Folk Victorian	__ Mediterranean	__ Prairie	__ Spanish-Colonial	__ Tudor Revival

Notes: __ Other: Vernacular

17. Documents Available and Their Locations

Historic Preservation Division
Land Use Department
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87504
(505) 955-6605
https://www.santafenm.gov/land-use/historic-preservation

Archaeological Records Management Section
Laboratory of Anthropology
708 Camino Lejo
Santa Fe, NM 87501
(505) 476-1320
https://nmhistoricpreservation.org/arms.html

SITE:

18. Attached or Associated Properties

Are associated properties eligible for listing: N/A

19.Site Plan: 2026 site plan. Courtesy of Osage Design Studio.



For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

Architectural Description Continued

Setting

The property is located on the west side of Paseo de Peralta, roughly opposite the Gerald Peters Gallery. The dwelling occupies the western portion of the roughly 0.3-acre rectangular lot. Approximately 7,640 square feet (about 58 percent) of the parcel has been removed from residential use and is leased for commercial parking (Photo 2). Historic aerial photographs indicate that this portion of the property formerly contained an informal entry drive, lawn, and other landscaping.

The remaining residential portion of the property retains a small lawn along the north frontage facing the former Santa Fe Properties building, together with a side yard and a gravel parking area west of the house. Several mature trees survive on the lot, including what appears to be a cultivated pear tree. In addition to the coyote fence along the east frontage, the property is enclosed by a combination of chain-link and wood-board fencing, none of which dates from the historic period.

House

Constructed in 1931, the house is built primarily of adobe, with a limited number of interior lath-and-plaster partition walls and a frame porch along the east elevation. The building retains its original rectangular plan and encompasses approximately 1,520 square feet, exclusive of the portal and porch. The compact plan contains five principal rooms: a living room, dining room, kitchen, bedroom, and bathroom. Beneath the kitchen is a partial basement, historically used for food storage and accessible only from the interior.

Architecturally, the house exhibits a restrained interpretation of the Territorial Revival style, characterized by its squared massing, brick coping, and originally light-colored plaster finish. The coping consists of a simplified stretcher-rowlock-stretcher brick pattern. The fenestration is typical of the period, utilizing standardized Craftsman-style wood windows commonly available through lumberyards such as Sanbusco. The exterior adobe walls are coated with a thick cementitious plaster that appears to have been painted originally. Today, the exterior displays a combination of painted and

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

unpainted stucco surfaces in several shades, reflecting successive campaigns of maintenance and repair.

North (Front) Elevation

The north (front) elevation is the most distinctive façade, owing to its raised portal. The façade begins at the east end with a pair of three-over-one hung sash windows (Photo 3). Extending approximately 24 feet along the western portion of the elevation, the portal provides the principal entrance to the house (Photo 4).

Period photographs indicate that the portal was originally framed by stout masonry columns that formed closed end walls (Fig. 2). Historically, it featured 10 projecting vigas and round galvanized-steel or sheet-metal canales (Fig. 3). The masonry columns and end walls remained in place through at least 1985 (Fig. 9) but were subsequently removed and replaced with smaller wood posts, leaving the ends of the portal open. Around the same time, the projecting viga ends were also cut flush with the wall plane, and the original metal canales were replaced with wider modern wood trough drains (Photo 5).

The portal shelters a concrete-floored outdoor living area that was historically used by the Chapman family for relaxation and informal gatherings. It originally overlooked the Chapman family's parent residence immediately to the north, reinforcing the close relationship between the two houses. Concrete steps approach the portal from both the north and west.

Near the center of the elevation is a three-light wood entry door flanked by windows (Photo 6). The windows are uniformly sized three-over-one double-hung wood sash, representing the simplified Craftsman-type units. The windows are arranged in paired groups separated by an engaged mullion. Most retain their original removable wood-framed insect screens, which are attached to the exterior window casing with metal clips (Photo 7). They are terminated with straight cement sills.

West Elevation

The west elevation overlooks the property's gravel parking area and, beyond it, the large asphalt-paved parking lot serving the PERA Building (Photo 8). The elevation is

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

functional in appearance, punctuated by a limited number of three-over-one double-hung wood windows arranged both singly and in pairs. Near the north end of the roofline, the brick coping is interrupted by a low, stuccoed chimney stack that projects above the parapet. This elevation is the only side of the building directly visible from a public right of way.

South Elevation

The south elevation faces a side yard now devoted primarily to gravel. The otherwise unarticulated wall contains a single three-over-one double-hung wood window near the west end and a smaller one-over-one vinyl window serving the bathroom (Photos 9 & 10). A period family photograph indicates that the bathroom opening originally contained a Craftsman-style wood window, likely with a three-over-one light configuration (Fig. 4). At grade is a small basement window that provides natural light to the partial cellar. Three older galvanized-steel punch-through canales project through the parapet. These are visible in the same historic photograph of the house (Fig. 4) and appear to be original features.

Attached to the east end of the elevation is the screened porch. Based on its design and materials, it appears to be a later addition. A structure in this location is first visible in a 1958 aerial photograph (Fig. 6).

Enclosing approximately 168 square feet, the porch is clad with weathered beadboard siding and characterized by a continuous horizontal band of screened openings (Photo 11). Historically, the Chapman family used it for summer meals and as a secondary entrance to the house. Access is provided by a four-light wood door, adjacent to a window matching the three-over-one wood sash used elsewhere on the dwelling.

East Elevation

The east elevation originally looked toward the gardens of the Bandelier estate. The gardens were removed with extension of Castillo Street and the development of Paseo de Peralta. This façade is dominated by the screened porch (Photo 12). The structure, with its vertical sheathing and shed-roof form, is not sympathetic with the home's Territorial Revival mode. Near the north edge of the building is a single three-over-one sash window, matching the other units of the house (Photo 13).

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

Interior

The interior was not visited during the site visit, but after speaking to family members, it is understood to be mostly original with respect to room layout and finishes.

Historical Overview

Introduction

Erected in 1931 on family property, the Constant and Ruby Chapman House is a four-room Territorial-style dwelling that has remained in continuous family ownership for more than eighty years. Through four generations of occupancy, it embodies the long history of the Chapman-Alarid family.

Constant Johnson Chapman

Its builder and first owner, Constant Johnson Chapman, was born in Santa Fe in August 1886. He spent his childhood on nearby East De Vargas Street, where his maternal grandmother maintained a small orchard. His mother, Anita (Ana) Johnson, was the eldest daughter of James Lewis Johnson and Jesusa (Jesúsita) Montoya Johnson.

Through the Johnson family, Constant descended from one of Santa Fe's established mercantile families. His grandfather, James Lewis Johnson, came to New Mexico from Maryland in the mid-nineteenth century. He helped establish the mercantile firm of Johnson, Koch & Wesche, and later acquired the property now known as El Zaguán.[1]

Constant's father, Albert A. Chapman, hailed from Oswego County, New York. He arrived in Santa Fe in the early 1880s and established a business on the Plaza.[2] In June 1884 he married Anita Johnson. Two years later, Constant was born.[3] Albert was unrelated to the

[1] Corinne P. Sze, *El Zaguan: The James L. Johnson House, 545 Canyon Road: A Social History* (Santa Fe, NM: Historic Santa Fe Foundation, 1997), 1 and 7; Elizabeth A. Comer, email communication to John W. Murphey, July 21, 2026.
[2] This is based on census data and early newspaper accounts after his arrival in Santa Fe.
[3] "Round About Town," *New Mexican Review,* July 1, 1884, 4.

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

other Chapman families of Santa Fe, including the anthropologist and artist Kenneth Chapman.[4]

By 1900 the marriage had ended in divorce after Albert deserted the family.[5] Anita subsequently established her household on a property along what is now East De Vargas Street, acquiring it from Manuel Delgado in 1911.[6] The family occupied the nineteenth-century residence known as the José Alarid House, which was later converted to commercial use and expanded by Gerald Peters during the late 1980s.[7] There Constant spent his youth overlooking the family's orchard—planted with apple, apricot, and pear trees—along with a strawberry patch.[8]

Constant attended local schools through the twelfth grade. Although relatively little is known about his early adult life, newspaper accounts indicate that, like his father, he moved comfortably within Santa Fe's social circles and enjoyed hunting excursions into the surrounding mountains.[9]

At the age of thirty-one, Constant enlisted in the United States Army on June 22, 1917,[10] serving as a wagoner with Company B, 115th Ammunition Train, 40th Division.[11] He transported ammunition and supplies by horse- and mule-drawn wagon, a vital logistical function within the Army's divisional supply system. After many of its original troops were transferred to other units in late 1917, the 40th Division was reorganized, brought

[4] Anita Alarid, Elizabeth Alarid, and Elizabeth Martinez, FaceTime interview by John W. Murphey, July 31, 2026.
[5] James H. Purdy, "José Alarid House," *Santa Fe Historic Foundation Bulletin* 1, no. 1 (1974): 2. Anita Chapman is shown as divorced in the 1900 federal census.
[6] Ibid.
[7] The house had converted to office/gallery space earlier but was intensified by Gerald Peters with the construction of the c.1987 addition.
[8] Alarid, Alarid, and Martinez, FaceTime interview.
[9] This is based on newspaper coverage from the early 1900s.
[10] Ancestry.com. *U.S., World War I Draft Registration Cards, 1917-1918* [database on-line]. Provo, UT, USA: Ancestry.com Operations Inc, 2005.
[11] Cemetery marker information at Santa Fe National Cemetery.

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

back to strength, and deployed to France during the summer of 1918. [12] According to family, he did not talk about his service.[13]

Following his return to Santa Fe, Constant married Ruby Maria Gonzales in 1924. Ruby had been raised on nearby Ortiz Street.[14] Constant established himself as a house painter, specializing in residential interiors, doors, and window trim. The couple initially rented homes on Ortiz Street and Canyon Road, but by the early 1930s, with two young children, they sought a permanent home of their own.[15]

Building a Home

In early 1931, the Chapman family property, which extended along a lane south of East De Vargas Street (Fig. 1), was divided into two tracts: one containing Constant's mother's house (A) and the other, immediately to the south (B), conveyed to Constant by his sister, Lola (Lolita) Chapman.[16] Lola had acquired the larger property in 1920 after their mother lost it through a mortgage foreclosure.[17]

Later that year, Constant obtained a building permit to erect a four-room house valued at $1,000.[18] The 1932 city directory indicates the dwelling had been completed by that year and was addressed as "rear 338" East De Vargas Street, reflecting its location behind and south of his mother's residence.[19]

[12] Historical Section, Army War College, *Order of Battle of the United States Land Forces in the World War: American Expeditionary Forces. Divisions* (Washington, DC: Government Printing Office, 1931), 254–61.
[13] Chapman, Alarid, and Martinez, FaceTime interview.
[14] Ibid.
[15] This is based on tracing their renting pattern in Santa Fe city directories.
[16] Warranty Deed, Lola Chapman to Constant J. Chapman, recorded April 23, 1931, Book 10, Page 281, Instrument # 41653, Santa Fe County, New Mexico; Corrected Warranty Deed, Lola Chapman de Alarid to Constant J. Chapman, recorded October 17, 1932, Book 10, Page 561, Instrument # 44194, Santa Fe County, New Mexico.
[17] Purdy, "José Alarid House," 2.
[18] "Depression Little Felt in Santa Fe," *Santa Fe New Mexican*, Dec. 31, 1931, 4. This article is an end-of-year roundup of building permits issued during 1931; the permit for the Chapman House could have been issued at any point during the year.
[19] Hudspeth Directory Company, *Hudspeth Directory Company*, *Santa Fe City Directory, 1932* (El Paso: Hudspeth Directory Company, 1932), 53.

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

The 1940 census is the first to document the family at the property, by then identified as 338½ East De Vargas Street. Although Constant had taken on a variety of jobs during the Great Depression, including work as a bartender, he had returned to his trade as a house painter. Ruby, meanwhile, opened a small downtown lunch counter known as the Red Chile Bowl, which closed at the outset of World War II.[20]

The household consisted of Constant and Ruby and their three children—Constant Jr., Anita, and Adelaide ("Lida")—who ranged in age from eight to sixteen. The house and land were valued at $4,000.[21] In 1943, Constant Jr. entered the U.S. Army, with his mother accompanying him to Fort Bliss for basic training.[22]

By the 1950 census, Constant, then sixty-two, had retired. The household consisted of Constant, Ruby, and their youngest daughter, Adelaide, then eighteen years old.[23] As throughout much of his life, Constant remained surrounded by members of his extended family. Nearby households were headed by his mother, Anita, and his nephew, Bernie Chapman. Anita J. Chapman—the family matriarch, longtime librarian of the New Mexico Supreme Court Library, and organist at St. Francis Cathedral—died four years later.[24]

Family Challenges

Constant Johnson Chapman died on February 24, 1956, at St. Vincent Hospital, apparently of a heart condition. He was sixty-nine years old. His estate was settled later that year in Probate Case No. 2786.[25] An inventory valued the house and property at

[20] Alarid, Alarid, and Martinez, FaceTime interview. This business is not listed in contemporaneous city directories.
[21] U.S. Census Bureau, Year: 1940; Census Place: Santa Fe, Santa Fe, New Mexico; Roll: m-t0627-02452; Page: 62A; Enumeration District: 25-6.
22 "In Uniform," *Santa Fe New Mexican*, July 6, 1943, 2.
23 U.S. Census Bureau, National Archives at Washington, DC; Washington, D.C.; Seventeenth Census of the United States, 1950; Year: 1950; Census Place: Santa Fe, Santa Fe, New Mexico; Roll: 3578; Page: 4; Enumeration District: 26-20.
[24] "Mrs. Chapman Dies at 91," Santa Fe New Mexican, August 9,1954, 1.
[25] *In the Matter of the Estate of Constant J. Chapman, Deceased*, Probate Case No. 2786, Probate Court, Santa Fe County, New Mexico [multiple documents].

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

$4,000 and the household furnishings at $200. The estate, however, was burdened by unpaid medical expenses owed to St. Vincent Hospital, some dating to 1945.[26]

Despite these obligations, ownership of the property remained within the Chapman family. The probate court awarded a five-eighths undivided interest in the house to Constant's widow, Ruby G. Chapman, while each of their three children—Constant R. Chapman, Anita Chapman Alarid, and Lida Chapman—received a one-eighth undivided interest.[27]

The resulting tenancy in common carried the property collectively into the next generation, marking another chapter in the family's determination to retain the house despite repeated episodes of over mortgaging[28] and financial setbacks. It was around this time that the property was first captured in an aerial photograph.

Area Change

A flyover image taken on November 10, 1958, documents the Chapman family compound in its original configuration (Fig. 6). At the north end of the lane later known as Orchard Drive[29] stood Anita Chapman's long, gable-roofed residence, the former José Alarid House. Immediately to the south stood Constant's house, then occupied by his widow, Ruby.

The dwelling comprised a modestly size, generally rectangular structure with porches extending across portions of its north and east elevations. To the west stretched open

[26] Ibid.
[27] Ibid.
[28] Purdy, "José Alarid House," 6.
[29] The renaming of the street is tied to a subdivision that never fully materialized. Although the Chapman family occupied the property years before the Orchard Park Addition was platted in 1939, their land eventually became surrounded by the proposed subdivision. A 1955 *Consent to and Waiver of Breach of Building Restriction* illustrates this transition. In that case, neighboring property owners, including members of the Chapman family, waived enforcement of the subdivision's private building restrictions after an improvement was constructed within a required setback. The document demonstrates that, by the mid-1950s, the former family lane serving the Chapman homes had become incorporated into the Orchard Park Addition and would later be known as Orchard Drive.

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

land owned by St. Michael's High School, holding the site of a former cemetery deconsecrated in 1914; to the east were the remnant gardens associated with the former Kaune estate.

This open, almost rural setting changed dramatically during the 1960s. To relieve downtown traffic congestion, Castillo Street was extended southward to East Manhattan Avenue, creating a bypass that later became part of Paseo de Peralta. The new four-lane roadway transformed the neighborhood, requiring the demolition of nearby houses[30] while fundamentally altering the setting of the Chapman properties, even though the family homes themselves remained intact.

At nearly the same time, the PERA Building was completed in 1968, and its expansive parking lot occupied much of the former St. Michael's Cemetery. The new government complex replaced the open landscape west of the house and largely eliminated its views toward the Jemez Mountains.[31] An aerial photograph from the same period illustrates the extent of these changes (Fig. 7).

Adelaide Chapman and Family Resilience

In 1962, Ruby Chapman conveyed the property to her daughter, Adelaide Chapman,[32] who had remained in the house with her parents and continued to live there after her mother's death in September 1977.

During those years, Paseo de Peralta accelerated the commercialization of the surrounding neighborhood, with many nearby residences converted to offices, galleries, and other commercial uses. Adelaide witnessed this transformation from the family home, where she continued to reside throughout her life. She also benefited from the changing neighborhood, taking a position with the PERA from which she enjoyed a short commute from her home.[33]

[30] John W. Murphey, *1075 Paseo de Peralta, Fenn Galleries/Nedra Matteucci Galleries, Santa Fe, Santa Fe County, New Mexico*, New Mexico Historic Cultural Properties Inventory 1 & 2, prepared for Jenkins-Gavins, July 2, 2022, 10.
[31] Alarid, Alarid, and Martinez, FaceTime interview.
[32] Warranty Deed, Ruby Gonzales Chapman to Adelaide Chapman, recorded February 7, 1980, Book 384, Page 860, Instrument # 453487, Santa Fe County, New Mexico.
[33] Ibid.

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

As redevelopment pressure mounted, developer Gerald Peters repeatedly sought to acquire the property for expansion of his Santa Fe Properties complex to the north. According to family members, however, Adelaide was "very stubborn and strong willed," steadfastly refusing to sell and thereby ensuring that the house remained in Chapman-Alarid family ownership.[34]

Adelaide (Lida) Lorraine Chapman died in 2018. The house remained vacant while her estate was settled in probate, which concluded in 2019.[35] In 2022, title passed by Personal Representative's Deed to her sister, Anita Alarid, a Santa Fe resident.[36]

Today the house is occupied by Anita's granddaughter, Christina Martinez, together with her partner and their child, representing the fourth generation of the Chapman family to call the property home. Under Anita's estate plan, ownership will ultimately pass to Chirstina, with the intention she will deed the property to her children, ensuring that the house remains in Chapman family ownership for yet another generation.[37]

Evaluation of Historical Status

The house has largely retained its historic footprint, principal design features, and fenestration from the period of its construction. As such, it continues to convey its historic period and original design intent. The property also possesses important associative value through its long-term ownership and occupancy by the Chapman and Alarid families, who have maintained a continuous presence on the property for four generations. While this continuity of ownership enriches the property's history and interpretation, it is not, in itself, the basis for historic significance under the Historic Districts Ordinance.

[34] Christina Martinez, Ibid.
[35] Santa Fe County Probate Case No. D-101-PB-2019-00172; Special Warranty Deed, Elizabeth Ann Alarid to Anita Alarid, representative of the Adelaide (Lida L.) Chapman estate, recorded October 29, 2019, Instrument # 1900511, Santa Fe County, New Mexico.
[36] Personal Representative's Deed, Anita Alarid, representative of the Adelaide (Lida L.) Chapman estate to Anita Alarid, recorded May 5, 2022, Instrument # 1987752, Santa Fe County, New Mexico.
[37] Christina Martinez, email communication to John W. Murphey, August 5, 2026.

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

For these reasons, the house is recommended as Contributing to the Downtown and Eastside Historic District.

Recommended Primary Facades

The north elevation, with its portal, is recommended as a primary façade. Although somewhat altered, it retains the building's strongest architectural expression of the Territorial Revival style and, as documented in period photographs, best reflects the family's historic use and occupation of the home. The west elevation is also recommended as a primary façade because of its high degree of public visibility and the number of original window openings that continue to express the building's historic residential character. The south elevation contains two openings, with one altered, while the east elevation has been substantially altered by a stylistically incompatible addition. Accordingly, the south and east elevations are not recommended as primary façades.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

Illustrations

Figure 1: 1912 King's "Official Map of Santa Fe," showing Anita J. Chapman, owning Lot 7. Chapman and her family lived in the José Alarid House.

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

Figure 2: c.1944-46 photograph of Ruby G. Chapman. Note east stuccoed column of portal. Courtesy of the Alarid family.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026



Figure 3: Undated photograph. Note presence of viga ends and rounded galvanized canales. Courtesy of the Alarid family.

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

Figure 4: c. 1944-46 photograph of south elevation. Note wood multi-light window at bathroom. Courtesy of the Alarid family.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

Figure 5: October 25, 1948, aerial photograph. Assumed subject house circled.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026



Figure 6: November 10, 1958, aerial photograph. Note presence of screened porch.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

Figure 7: February 2, 1968, aerial photograph.

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

Figure 8: September 11, 1978, aerial photograph.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

Figure 9: c.1984-85 HBI survey photo. Harry Weiss.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

Survey Photographs

(All images taken by Jim Rodman on July 22, 2026, unless otherwise noted)

Photo 2: Setting from leased parking lot. Camera facing west.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

Photo 3: East section of north elevation. Camera facing southwest.

The north elevation cannot be photographed as a full façade because of the shallow side yard and the presence of a mature pear tree in front of the portal.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

Photo 4: Portal. Camera facing east.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

Photo 5: Elements that have been altered across the portal. Camera facing up.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

Photo 6: North elevation. Camera facing southwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

Photo 7: North elevation. Window detail. Camera facing south.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

Photo 8: West elevation. Camera facing southeast.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

Photo 9: South elevation. Camera facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

Photo 10: South elevation. Detail of replacement window.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

Photo 11: South elevation. Frame screen porch. Camera facing northwest.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

Photo 12: East elevation. Camera facing west.

Historic Cultural Properties Inventory (HCPI) Detail Form (FORM 2)

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: *Please complete HCPI FORM 1 before completing FORM 2* HCPI No._____ District No._____ ___NRHP ___SRCP Criteria __A __B __C __D		
1. Name of property: Constant and Ruby Chapman/ Adelaide L. Chapman/ Christina Martinez House	2. Location: 338 ½ (338) Orchard Drive Downtown and Eastside Historic District – Santa Fe	3. Local Reference Number: Santa Fe ID: N/A 4. County: Santa Fe 5. Date of Survey: July 22, 2026

Photo 13: East elevation, north end. Camera facing northwest.

City of Santa Fe Historic Preservation Division
Preliminary Application Request Submittal
April 18, 2026



Existing Site Plan

Scale: 1" = 20'-0"

Drawing formatted to print to scale on 11x17 paper

Alarid Residence
338 Orchard Drive
Santa Fe, NM 87501

1

Santa Fe County Tax Parcel Viewer

4/5/2026, 8:46:26 AM

Tax Parcels

Roads

City of Santa Fe Address Points

Santa Fe County Boundary

1:282

0 12.5 25 50 ft

0 4.25 8.5 17 m

2024/25 EagleView Pictometry - Santa Fe County



1902 Sanborn Map

1951 Aerial

1960 Aerial structure is present

Kings Map 1912

City of Santa Fe

Land Use Department | Historic Preservation Division

Administrative Approval

THIS IS NOT A CONSTRUCTION PERMIT

DO NOT BEGIN WORK WITHOUT A PERMIT. SUBMIT THIS FORM WITH YOUR CONSTRUCTION PERMIT APPLICATION AND RETAIN A COPY AT THE JOB

Date: August 31, 2023

To: Building Permit Division

From: Ramon Sarason

Be advised that per §14-5.2 SFCC 1987 the work described below at the referenced address does NOT require Historic Districts Review Board approval and is hereby staff-approved as described below. Please allow the applicant to submit for a construction permit(s) for this work if required.

Project Address: 338 ORCHARD DR 1/2, Santa Fe, NM 87501

Case Number: 2023-007294--ADMIN

Contact Name: Travis Dixon

Phone Number: 505-501-4457 **Email:** nmtrstravis@gmail.com

Approved Scope of Work: *Re-roof for the flat sections only. This current roof will be removed, and replacing it with a Polyurethane foam and gravel system. The UV coating color will be Santa Fe Tan.*

Conditions of Approval: *Re-roof structure as submitted with the conditions that there shall be no publicly visible rooftop appurtenances and that no roofing material shall be on the top of the parapets and shall be flashed on interior of parapets.*
There shall be no changes to existing mechanical, line sets, or other rooftop appurtenances at this time.
No other work approved at this time

FURTHER ACTIONS REQUIRED: **PERMIT or PERMIT REVISION**

FINAL HISTORIC INSPECTION

New Mexico Total Roofing Solutions
***P O Box 23229**, Santa Fe, NM 87502*
Phone 505.501.4457

Date: 8/16/2023

City of Santa Fe - Historic Preservation Division:

NM Total Roofing Solutions is requesting an administrative approval for a re-roof at 338 Orchard Drive This re-roof is just for the flat sections only. This current roof needs to be removed, we will be replacing it with a Polyurethane foam and gravel system. The UV coating color will be Santa Fe Tan. The roof we are installing will not be visible. No further work will be done at this time.

Thank you,

If you have any questions please call me
(505)501-4457
Travis Dixon, Owner
New Mexico Total Roofing Solutions, LLC



CITY OF SANTA FE HISTORIC PRESERVATION DIVISION
HISTORIC DISTRICTS APPLICATION

Applicant Information (to be completed by the Applicant)

Date: 8/16/2023 Location of Project: 338 Orchard Drive

Applicant

Name: New Mexio Total Roofing Solutions

Phone: (505) 501-4457 Email: NMTRS Travis@gmal.com

Property Owner

Name: Liz Alarid

Phone: 505-6606609 Email: _____

Proposed Work:

New Roof

At a minimum these materials will be required in addition to this application form:

- Proposal letter stating the details of the scope of work.
- Site plan or map of the project area with the location of the work noted on the map.
- Photos of the current condition of the areas of work.
- Scaled floor plan and elevations if appropriate to your project.

Provide all information digitally to mgsargent@santafenm.gov . See the HPD webpage for detailed instruction. https://www.santafenm.gov/land-use/historic-preservation/hpd-procedures

Examples of Maintenance and Repair Requests:

Re-roof	*Solar	Concrete	Stucco and Paint
Skylights	Brick Coping	Hardscaping	*Windows and Doors
Canales	*Fences, Walls, and Gates	Exterior Lights	Mechanical Equipment

*May require HDRB approval.

Examples of HDRB Requests:
Demolition, Status Review, Removal of Historic Material, Additional Square Footage**, Remodel**, Window and Door Replacement**
**District dependent

Project Details Section (to be completed by Applicant)

Projects may require HDRB approval. Please submit this application form in addition to the list of materials and requirements for HDRB approval, whic can be found at https://www.santafenm.gov/land-use/historic-preservation/hdrb-hearings-and-cases .

New Construction ☐

Sq. Ft. of project: _____

Remodel (Re roof) ☐

Sq. Ft. of project: 724

Construction Cost: $10,500.00

AFIDAVIT AUTHORIZING AGENT/APPLICANT

As the Owner and holder of title of the above listed property I/we authorize the Agent/Applicant to act on my/our behalf to execute this application.

Print Name Elizabeth A/Arid

Signature Elizabeth Arid

NEW MEXICO HISTORIC BUILDING INVENTORY FORM

1+1577

building threatened? yes	surveyed date 5/3/85 by HMW	county SANTA FE	ID no. 051610627
field map SFHD #4	number 627	UTM reference zone 12 13 easting	northing

location description: 338 E. DE VARGAS.

city/town: SANTA FE

land grant/reservation:

building name: JOSÉ ALARID HOUSE

legal description: tnsp___ N S range___ E W sec___ ¼ ¼

film roll by HMW no. SFHD 13	negative nos.	loc. of neg. HPB

plan shape





date of construction: 1835 + estimate _____ actual

source

use
present: residential
other: ART GALLERY
historic: residential
other:

condition
x excellent ___good
___fair ___deteriorating

degree of remodeling
___minor ___moderate ___major
describe:

SPAN. COL. / TERR.

UNK. (STONE ?)

wall material/surface: DBL ADOBE / STUCCO

architectural features

HIPPED RF, MTL STANDING SEAM. BRK CHIMNEYS.

S SIDE: SHED RF PORCH W/ CHAMF'D SQ POSTS RAISED ON CONC. PIERS, STRAIGHT LINTEL DECOR'D W/ MOULDING IN SEG. ARC.

SHED RF ADD. AT SE CORNER: 2 6/6 D.H. WD WDWS, 1 2/2 SLIDING WD WDW, 1 4-LIGHT WD PANEL SGL-LEAF DOOR, ALL W/ WD SURR. & STRAIGHT TERR. LINTELS.

UNDER S PORCH: 1 3/1 TAND. DBL HUNG WD WDW GROUP W/ WD ~~CURRICTES~~ SURR & TERR STRAIGHT LINTEL; 2 2/2 D.H. WD W/ WD SURR & STRAIGHT TERR. LINTEL; 1 SGL-LEAF MOD. WD DOOR IN OLD FRAME - WD SURR. & LINTEL; 1 15-LIGHT WD DOOR W/ 10-LIGHT SIDELIGHTS, STRAIGHT LINTEL.

SHED RF ADD AT SW CORNER: 2 TAND & 1 SGL HD CAS'MT 6-LIGHT, WD SURR & TERR. LINTEL; MOD SGL-LEAF DOOR.

SHED RF ADD ON W SIDE: EXP'D RAFTER ENDS W/ MTL FLASHING, MOD. SGL-LEAF WD DOOR W/ CARVED JAMBS.

surroundings: COMMERCIAL / GOV'T

relationship to surroundings
___similar x not similar

district potential
___yes ___no

significance
x eligible ___of interest ___none

if eligible, why? PRIMARY: AGE, TYPE

associated buildings? ___yes
what type?

if inventoried, list ID nos.

see back? x yes

FEATURES –

N SIDE: STONE BUTTRESS AT NW CORNER OF PRIMARY VOLUME.

4 3/1 TAND D.H. WD WDW GROUPS W/ WD SURR. & TERR. LINTELS.

1 9-LIGHT MTL CASM'T WD W/ WD SURR & LINTEL. 3X3, OUTER TIERS OPEN.

CROSS GABLE W/ 2/2 D.H. WD WDW, WD SURR.

WD FRIEZE BD UNDER GUTTER.

PORCH: STONE FDN, ~~SHED~~ HIP RF MTL STANDING SEAM, SLIM TURNED WD POSTS W/ ENGAGED POSTS ON WALL & DEC. LINTEL & BRKTS W/ CIRCLE CUTOUTS, BRK FLOOR W/ COPING TILE EDGE.

DOOR: SGL. LEAF SGL-LIGHT WD PANEL W/ TURNED BELL RING, WD SURR. & TERR. LINTEL.

CONC. COVING LIP AT WALL BASE.

2 STONE BUTTRESSES AT NE CORNER.

E SIDE: WD GABLE DORMER W/ WD DOOR INSTEAD OF WDW.

1 1/1 D.H. WD WDW W/ WD SURR & TERR. LINTEL.

1 2/2 CASM'T WD.

W SIDE HAS GABLE DORMER TOO W/ 4-LIGHT OPAQUE CASM'T, SIDES CLAD IN MTL SHEET TILES.

COMMENTS: S PORCH ADDED CA. 1972, DESIGNED BY LUMPKINS WHO ALSO ADDED THE LARGE STRAIGHT LINTELS ON MOST WDWS.

PHOTO CA 1910 SHOWS N SIDE W/ 2/2 D.H. W/ SIMPLE FLAT PED. WD LINTELS. CURRENT 3/1 WDWS PROB. CA. 1925; 1910 PHOTO ALSO SHOWS CURRENT N PORCH. ADDS ON S SIDE PROB. CA 1900, INTERIORS HAVE T & G SIDING.

THE ONE 2/2 D.H. IN S SIDE IS EARLIEST WDW – THE NEW LUMPKINS PED. NAIL OVER ORIG FLAT PED.

FEATURES –

N SIDE: STONE BUTTRESS AT NW CORNER OF PRIMARY VOLUME.

4 3/1 TAND D.H. WD WDW GROUPS W/ WD SURR. & TERR. LINTELS.

1 9-LIGHT MTL CASM'T WD W/ WD SURR & LINTEL. 3X3, OUTER TIERS OPEN.

CROSS GABLE W/ 2/2 D.H. WD WDW, WD SURR.

WD FRIEZE BD UNDER

PORCH: STONE FDN, 4 ENGAGED POSTS ON WD FLOOR W/ COPING TILE EI DOOR: SGL. LEAF SG & TERR. LINTEL.

CONC. COVING LIP AT 2 STONE BUTTRESSES



E SIDE: WD GABLE DORMER W/ 1 1/1 D.H. WD WDW. W/ 1 2/2 CASM'T WD.

W SIDE HAS GABLE DR. IN MTL SHEET TILES.

COMMENTS: S PORCH ADDED CA. 1972, DESIGNED BY LUMPKINS WHO ALSO ADDED THE LARGE STRAIGHT LINTELS ON MOST WDWS. & SHUTTERS

PHOTO CA 1910 SHOWS N SIDE W/ 2/2 D.H. W/ SIMPLE FLAT TED. WD LINTELS.

CURRENT 3/1 WDWS PROB. CA. 1925; 1910 PHOTO ALSO SHOWS CURRENT N PORCH.

ADDS ON S SIDE PROB. CA 1900, INTERIORS HAVE T & G SIDING.

THE ONE 2/2 D.H. ON S SIDE IS EARLIEST WDW – THE NEW LUMPKINS TED. IS NAIL OVER ORIG FLAT TED.

3

Bulletin...

The Historic Santa Fe Foundation

Vol #1 1974



JOSÉ ALARID HOUSE
338 E. De Vargas Street

Owned during its history by many prominent Santa Fe residents, the José Alarid House was constructed sometime prior to 1854. On December 20, 1835, José Alarid, a disabled veteran of the Sanat Fe Company, purchased a section of farmland from Francisco Campos, a sergeant in the San Miguel del Vado Company. The heirs of Alarid sold this property and a house containing 61 vigas to José Hersch ("El Polaco") for 245 pesos and two reales on May 4, 1854. Little is known about Hersch except that on August 19, 1868 he married Rosalia Herschberg of Prussia in a civil ceremony performed by Joab Houghton, associate justice of the territorial Supreme Court.

Hersch conveyed the property to Bishop John B. Lamy on February 26, 1859; what use he made of the house is not known. On June 19, 1864, Bishop Lamy transferred ownership of the property to the son of Donaciano Vigil, Epifanio Vigil. During Mexican rule, Donaciano Vigil served first in the presidial company of Santa Fe and then commanded the San Miguel del Vado Company. He was also military secretary to Governor Manuel Armijo and after U.S. occupation in 1846 was appointed secretary of the territory by Brigadier-General

Stephen Watts Kearny. In 1847, he became acting civil governor of New Mexico following the assassination of Governor Charles Bent. From 1848 to 1850, Vigil continued as secretary of the territory and register of land titles. The Donaciano Vigil House at 518 Alto Street has been plaqued by the Foundation.

Also active in public affairs, Epifanio Vigil served as territorial auditor from 1865 to 1869. In 1867, Secretary of the Territory and interim Governor W.F.M. Arny appointed Anastacio Sandoval to hold this post. When Governor Robert B. Mitchell returned to New Mexico from a trip to Washington, he removed Sandoval, along with other Arny appointees, and reappointed Epifanio. Because of this action the territorial legislature on January 14, 1868 passed a joint resolution requesting Congress to remove Mitchell. This action was not taken, however, and he served until 1869. On October 1, 1868, Mitchell also appointed Epifanio to fill the position of official interpreter. The 1870 federal census lists Epifanio as being 36 years of age and owning property valued at $1,500. He was married to Cesaria Garcia and two sons, Melisendro and Donaciano, resulted from this union. After leaving public office, Epifanio engaged in printing.

Melisendro, his wife Gabriela, and Donaciano, who was a second grade teacher in San Miguel County, sold the property to Manuel Delgado for $1,100.00 on March 9, 1904. It is interesting to note that during the time the Vigils owned the house it was mortgaged to Henry S. Kaune who later owned the Bandelier House at 352 E. DeVargas Street.

Delgado and his wife conveyed the property to Anita J. Chapman on August 3, 1911. Anita was the eldest child of James L. and Jesusita Johnson the owners of El Zaguan in the mid 1900's. Born about 1863, she had one sister, Margarita and two brothers, Robert L. and George A. She married Bert (Lambert?) Chapman who later deserted her. One daughter, Lolita, and one son, Constant J., resulted from this marriage.

During the period 1890-1891, Anita served as translator and secretary for Adolf F. Bandelier, who became a close friend of the family. From 1905 to 1909 she was territorial librarian and was the first woman to hold that position. She was followed by Mrs. Lola C. Armijo, mother of Rough Rider Geroge Washington Armijo in 1909. After New Mexico gained statehood, Governor William C. MacDonald sought to replace Mrs. Armijo with Mrs. Mary Victory. However, this move failed and a short time later, legal action was instituted to oust Mrs. Armijo on the basis of sex. The question before the court was, could a woman hold a public office in New Mexico, there being no statute authorizing her to do so. The case reached the Supreme Court which in a two-to-one decision resolved the question in Mrs. Armijo's favor (State vs. Armijo, 18 N.M. 646, 140 Pac. 1123). The court concluded that the office was a purely ministerial one since according to a review of the then applicable laws for regulation of the library, the librarian was "not required to exercise his or her judgment in any respect," and for that reason, wrote Chief Justice Roberts, the duties of a state librarian "are not incompatible with the ability of a woman to perform." After Mrs. Armijo's retirement in 1917, Anita Chapman was reappointed and continued to hold the position until the summer of 1937.

Earlier in 1914, Anita mortgaged the property to a neighbor, J.G. Schuma[illegible] for $2,500.00 and on August 26 of the following year, he foreclosed and th[illegible] property was sold for $1,500.00. However, Anita retained an option to purchase the land and structure at that price plus 12% per annum. Alfonse Dockwiller who owned the Stone Warehouse from 1916-1926 purchased this option but was unable to exercise it. The result was civil case No. 8677 which forced Schumann to sell the house and land to Dockwiller for $1,635.00. On August 24, 1920 Dockwiller and his wife conveyed the property to Anita's daughter, Lolita.



This fine structure is presently the Garfield Apartment building located on Garfield Street. Both the three story tower and mansard roof have [illegible]en removed. Used as a private school which was incorporated as the [illegible]niversity of New Mexico on May 13, 1881, the building has also been utilized as a public high school, saw mill, Franciscan Hotel and St. Mary's Convent.



The Chapel of Our Lady of Light

The staff of the Loretta Chapel needs your help to "man" the Chapel through the winter months. Of the staff of four sisters, two leave the Chapel each winter and volunteers will be needed to take their place. The added volunteers will allow the third sister to have a day off.

The Chapel provides an inspiring atmosphere to work in. The tour of a volunteer consists of four hours per month and this amounts to approximately 24 hours for the entire winter months.

Mrs. Dorothy Warren is the Chairman of Volunteer Program for Loretta Chapel. She can be reached at 982-3233. Your willing help is needed!

Note cards of five historical buildings in Santa Fe are on sale at various local shops. The buildings are: The Chapel Of Our Lady Of Light, Francisca Hinojos House, The Borrego House, The Pinckney Tully House, and the Donaciano Vigil House. A certain percentage of the profit from the sale of these cards goes toward the Tully House Fund. Get as many boxes of cards as you can – at only $1.50/box it is an easy way to help in "funding" the Tully House project.

TULLY HOUSE FUND

The Board of Directors is pleased to announce that the initial fund drive effort of the Foundation came to a successful conclusion with the payment in full of the $60,000.00 short-term indebtedness with The First National Bank of Santa Fe. We are extremely grateful for the response, which came principally from the City of Santa Fe, illustrating the strong interest in historic preservation in our community.

In addition, a special mention must be made of the extraordinary assistance received from Mr. and Mrs. John Gaw Meem, who not only motivated the Foundation's participation in the project to save the Tully House by their personal enthusiasm for the preservation of the building and for its importance to the future of this community, but also aided substantially in meeting our first contribution goal.

There remains on the Tully House a mortgage indebtedness of $30,000.00 which must be reduced before the Foundation will be in a position to make needed repairs and restoration of the building. Accordingly, the Board of Directors shall continue the fund-raising effort until the goal of complete restoration of the building has been met.

The Pinckney R. Tully House

TULLY HOUSE FUND CONTRIBUTIONS REPORT. . . . . .
During the 1973-1974 years to October 1:
Contributions were made by:
8 out of 15 Board members
104 out of 293 other members
114 non-members
making a total of 226 contributions totaling $30,485.00 in cash plus several donations of services.

OLD SANTA FE ASSOCIATION TREASURE SALE

The Foundation gratefully acknowledges the offer of the Old Santa Fe Association to contribute a portion of the receipts from its Annual Treasure Sale, to be held in November, to the Tully House Fund Raising Effort. We have been informed by Bob Ward, Committee Chairman responsible for the Treasure Sale that donations of Indian pottery, jewelry, rugs, crafts or art goods of any description are being solicited for the sale. Any member of the Foundation interested in assisting, either by contributing an article for sale or otherwise, is urged to contact either Bob Ward or Ruth Chaban at the Association office in Santa Fe.

Lolita Chapman de Alarid also heavily mortgaged the property and on December 28, 1944 conveyed it to her son Bernie H. Chapman and his wife. Bernie H. Chapman, who had legally changed his name from Alarid, sold the house to Nicholas Woloshuk, Jr. on July 19, 1968 and on November 18, 1970 he sold the property to Harvey Mudd, a well known conservationist. The structure presently provides office space for the Central Clearinghouse which, according to the director, Sally Rogers, is a non-profit environmental research-information center.

SOURCES

Santa Fe County Deed Records: Book H, p. 274; Book A, p. 378; Book G, p. 245 & 246; Book O, p. 199; Book G-1, p. 612; Book H-1, p. 191; Book L-1, p. 106; Book L-2, p. 406; Book P-1, p. 256; Book 8, p. 115; Book 10, p. 284 and Book 26, p. 511.

Santa Fe County Mortgage Records: Book H, p. 292; Book O-1, p. 574; Book P-2, p. 158; B17, p. 198; B21, p. 265.

Miscellaneous Santa Fe County Records: Book R, p. 276.

Santa Fe County Contract Records: Book D. Contracts.

Interview by James Purdy with Constant Chapman on September 13, 1974.

The New Mexico Blue Book 1921.

Sanchez, Jane C. "Agitated, Personal and Unsound," *New Mexico Historical Review* (July, 1966), p. 221.

Book of Marriages, Santa Fe County Records, State Records Center & Archives, Santa Fe, N.M.

Epifanio Vigil Papers, State Records Center and Archives, Santa Fe, N.M.

Poldervaart, Arie. "The New Mexico Law Library – a History," *New Mexico Historical Review* (January, 1946), pp. 57-58.

1870 Federal Census for Santa Fe County, State Records Center and Archives, Santa Fe, N.M.

James H. Purdy
10-4-1974

North
Albuquerque Journal
ALBUQUERQUE, N. M.
APR 25 1987

Addition to Historic Home Questioned

SR#260
152

By Steve Terrell
JOURNAL STAFF WRITER

Santa Fe city planners are worried that a proposed addition to an old house once owned by Archbishop Jean Baptiste Lamy will detract from the building's historical significance.

Real estate and art investor Gerald Peters wants to put an addition on the front of the old Jose Alarid house on Paseo de Peralta at DeVargas Street.

The structure is more than 130 years old and has been recognized with a plaque from the Historic Santa Fe Foundation.

Linda Tigges of the city Planning Department said she feels the proposed addition wouldn't be compatible with the rest of the building, which currently houses offices for two of Peters' companies, Santa Fe Properties Co. and Sena Plaza Management.

"This is one of the few pitched-roof houses with architectural integrity remaining in the historic district," Tigges said. "We're requesting an opportunity to work with the architect to come up with something more compatible."

In a memo to the Historic Design Review Board, which is scheduled to discuss the project Monday, Tigges said, "Particularly, the staff is concerned about the incompatibility of a large flat-roofed addition parallel to a structure with a fine example of a Northern New Mexican pitched roof."

Tigges said the proposed addition meets the standards set forth in the city's Historic Design Ordinance. But, she said, "It would seem that any addition to the structure should merit careful consideration over and above those standards."

The City Council last week rejected similar arguments by city staff and Historic Design Review Board members in another case. The council overturned a historic board's decision to deny attorney Paul Gerber permission to enclose the porch of his 72-year-old Don Gaspar Avenue house.

Gerber's porch enclosure met the technical requirements of the city ordinance, though city planners and board members said more strict standards should apply because the house had been deemed "significant" in a historic architectural survey.

Peters couldn't be reached for comment Friday.

A 1974 Historic Santa Fe Bulletin said the house was built between 1835 and 1854 when the property was owned by Jose Alarid, "a disabled veteran of the Santa Fe Company."

Lamy owned the property between 1859 and 1864, though the Bulletin noted, "what use he made of the house is not known."

NEW MEXICO HISTORIC BUILDING INVENTORY FORM

building threatened? yes	surveyed date 5/3/85 by HMW	county SANTA FE	ID no. 051610627
field map SFHD #4	number 627	UTM reference zone 12 13 easting	northing

location description: 338 E. DE VARGAS.

city/town: SANTA FE

land grant/reservation:

building name: JOSÉ ALARID HOUSE

legal description: tnsp ___ N S range ___ E W sec ___ ¼ ___ ¼

film roll by HMW no. SFHD 13	negative nos.	loc. of neg. HPB



plan shape



date of construction: 1835 + estimate ___ actual

source:

use
present: residential
other: ART GALLERY
historic: residential
other:

condition
x excellent ___ good
___ fair ___ deteriorating

degree of remodeling
___ minor ___ moderate ___ major
describe:

surroundings: COMMERCIAL / GOV'T

relationship to surroundings
___ similar x not similar

district potential
___ yes ___ no

significance
x eligible ___ of interest ___ none
if eligible, why? PRIMARY: AGE, TYPE

associated buildings? ___ yes
what type?

if inventoried, list ID nos.

see back? x yes

foundation: UNK. (STONE ?)

wall material/surface: DBL ADOBE / STUCCO

roof: SPAN. COL. / TERR.

architectural features

HIPPED RF, MTL STANDING SEAM. BRK CHIMNEYS.

S SIDE: SHED RF PORCH W/ CHAMF'D SQ POSTS RAISED ON CONC. PIERS, STRAIGHT LINTEL DECOR'D W/ MOULDING IN SEG. ARC.

SHED RF ADD. AT SE CORNER: 2 6/6 D.H. WD WDWS, 1 2/2 SLIDING WD WDW, 1 4-LIGHT WD PANEL SGL-LEAF DOOR, ALL W/ WD SURR. & STRAIGHT TERR. LINTELS.

UNDER S PORCH: 1 3/6/1 TAND. DBL HUNG WD WDW GROUP W/ WD ~~CORNICES~~ SURR & TERR STRAIGHT LINTEL; 2 2/2 D.H. WD W/ WD SURR & STRAIGHT TERR. LINTEL; 1 SGL-LEAF MOD. WD DOOR IN OLD FRAME - WD SURR. & LINTEL; 1 15-LIGHT WD DOOR W/ 10-LIGHT SIDELIGHTS, STRAIGHT LINTEL.

SHED RF ADD AT SW CORNER: 2 TAND & 1 SGL WD CAS'MT 6-LIGHT, WD SURR & TERR. LINTEL; MOD SGL-LEAF DOOR.

SHED RF ADD ON W SIDE: EXP'D RAFTER ENDS W/ MTL FLASHING, MOD. SGL-LEAF WD DOOR W/ CARVED JAMBS.

FEATURES –

N SIDE: STONE BUTTRESS AT NW CORNER OF PRIMARY VOLUME.

4 3/1 TAND D.H. WD WDW GROUPS W/ WD SURR. & TERR. LINTELS.

1 9-LIGHT MTL CASM'T WD W/ WD SURR & LINTEL. 3X3, OUTER TIERS OPEN.

CROSS GABLE W/ 2/2 D.H. WD WDW, WD SURR.

WD FRIEZE BD UNDER

PORCH: STONE FDN, 4 ENGAGED POSTS ON WA FLOOR W/ COPING TILE EI

DOOR: SGL. LEAF SG & TERR. LINTEL.

CONC. COVING LIP AI

2 STONE BUTTRESSES

E SIDE: WD GABLE DORMER W/

1 1/1 D.H. WD WDW W/

1 2/2 CASM'T WD.

W SIDE HAS GABLE DO. IN MTL SHEET TILES.

COMMENTS: S PORCH ADDED CA. 1972, DESIGNED BY LUMPKINS WHO ALSO ADDED THE LARGE STRAIGHT LINTELS ON MOST WDWS. & SHUTTERS

PHOTO CA 1910 SHOWS N SIDE W/ 2/2 D.H. W/ SIMPLE FLAT PED. WD LINTELS.

CURRENT 3/1 WDWS PROB. CA. 1925; 1910 PHOTO ALSO SHOWS CURRENT N PORCH.

ADDS ON S SIDE PROB. CA 1900, INTERIORS HAVE T & G SIDING.

THE ONE 2/2 D.H. ON S SIDE IS EARLIEST WDW – THE NEW LUMPKINS PED. IS NAIL OVER ORIG FLAT PED.

ADDRESS: 338 E. de Vargas **HIST. SURVEY #:** 627

(OD = Out of District; M = Moved
DEM = Demolished; N/A = not a building)

NAME: Alarid, Jose, House

CITY SURVEY

Area #: 4 Signif. Status: S

(S = Significant; C = Contributing; NC = Noncontributing

REGISTER STATUS (Individual Nominations)

National: N State: Y State #: 354

HSFF: Y **HABS:** N

(OSFT = To be in forthcoming 4th edition of Old Santa Fe Today.
Not covered by a more detailed Bulletin article.)

DOCUMENTATION

SFHS Inventory: Y

NR Nomination: N/A SR Nomination:

HSFF Bulletin: Y HABS Data: N/A

Historic Photos: Y Museum: 1 Archives:

Modern Photos: MNM: SRC:

Surveys: Floor Plans: Elevations:

Other: AJ North 4/25/1987 re proposed addition.

Bibliography:

Comments:

City of Santa Fe, New Mexico

memo

DATE: September 8, 2026

TO: Historic Districts Review Board Members

VIA: Heather Lamboy, AICP, Planning & Land Use Department Director
Maggie Moore, Assistant Land Use Director MM

FROM: Lani McCulley, Senior Planner, Historic Preservation Division, LgM

2026-012977-HDRB. 527-A Agua Fria St., Westside-Guadalupe Historic District. Contributing. Osage Design Studio, agent for Neirika, LLC, owner, proposes to relocate the garage door opening. An exception is requested to 14-4.6(E)(4)(II)(c) for recreating a missing feature without replication.

REFERENCE ATTACHMENTS (Sequentially):

CITY SUBMITTALS

____ **District Standards & yard wall & fence standards.**

__x__ **Historic Inventory Form**

__x__ **Zoning Review Sheet**

__x__ **Other**: previous case files

APPLICANT SUBMITTALS

__x__ **Proposal Letter**

__x__ **Site Plan/Floor Plan**

__x__ **Elevations**

__x__ **Photographs**

__x__ **Other:** exception criteria

STAFF RECOMMENDATION:

Staff finds that the exception criteria to 14-4.6(E)(4)(II)(c) for recreating a missing feature without replication have not been met, and recommends denial of the exception request. Otherwise, staff recommends approval of the application as it complies with 14-4.6(E) General Design Standards for all Historic Districts, and 14-4.6(G)(5) Westside-Guadalupe Historic District Design Standards.

Sample motions:

a. In case 2026-012977-HDRB, for 527 Agua Fria Street, approve/deny the exception to 14-4.6(E)(4)(II)(c) for the recreation of an opening without replication on a contributing structure, finding that the exception criteria have/have not been met
b. In case 2026-012977-HDRB, for 527 Agua Fria Street, approve/deny the elements of the project that do not require an exception.

Should the Board deny the exception request, the applicant shall return with an alternative proposal for review and approval before proceeding to a building permit.

Figure 1: Site Location

BACKGROUND & SUMMARY:

Background:

In case 2026-011230-HDRB on January 13, 2026, the Historic Districts Review Board approved a remodel which included replacement of windows and doors, raising the lower roofs on the north, constructing a 36 sq. ft. addition, replacing chimneys, constructing fences and gates, exterior stairs, and stuccoing the residence and yard wall. An exception to 14-5.2(D)(5)(a) for replacing historic windows. The exception was approved. The garage door opening was on the north side of the residence, while the door itself was missing. As part of the remodel, the garage door opening on the north side was to be filled with French doors as part of making this section into a guest house.

Streetscape:

The streetscape for this property runs from just east of De Fouri Street to Romero Street. The street is lined with sidewalks, with properties having low stucco yard walls and a couple of rock yard walls. Some of the yard walls are topped with metal fencing. There is a single chain-link fence, and to the west of Closson Street, there are some

coyote fences. The yard walls and fences often feature wooden pedestrian gates. There are no vehicle gates. The average is forty-three inches in height, which is the maximum allowable height.

The properties tend to be narrow and long, with multiple buildings on most sites. The buildings vary in distance from the street, with some right up to the sidewalk and others set back twenty to thirty feet from the street. The buildings are a combination of residential and commercial spaces.

The buildings are a variety of Spanish Pueblo Revival, Territorial, and Vernacular style flat-roof homes, as well as a variety of pitched-roof homes. The homes are in lighter brown stucco with white, brown, and blue trim and natural wood elements. There are several properties with metal elements as well.



Figure 2: Street View of Residence

Site Description:
The 3,017 sq. ft. single-family residence sits on a 0.418-acre lot and was constructed in 1908 and is listed as contributing to the Westside-Guadalupe Historic District, with the south and east elevations designated as the primary facades.

The 1908 residence is constructed in vernacular-style architecture with thick, stucco-plastered walls, red-tiled roofs, and ornate archways, with large, symmetrical facades designed for warmth and indoor-outdoor living.

The roof is a red metal roof with gables of various heights, gable horns, and exposed rafters. The roof heights vary, with the lowest at 7'-10" and the highest at just under 20'-0". The walls are concrete and stucco in light tan; most windows are 8-lite wood casements in pairs and trios, and a few picture windows. The doors are wood, with the front south door being curved to match the curve in the portal. The south portal has a gable roof with a round arched opening. The southeast corner portal has a shed roof and stucco piers. The yard wall along the street is low stucco with a wood pedestrian gate, and the rear fencing is a 6'-0" high plank wood fence.

According to the 2025 HCPI, *"The original house was built sometime before 1908. An addition was constructed at the rear of the house (northeast side) sometime after 1908 and before 1913. A much larger addition was constructed on the west side of the house sometime after 1913 and before 1921. The new southwest corner of the house is constructed of adobe. A covered front porch was added at the southeast corner of the house. Another large addition was added to the back of the house, possibly an enclosed back porch with a lower roof. A separate garage was added to the west, and access to a cellar on the east side of the house was added sometime after 1921*

and before 1930. It is estimated that the double gable roof was added after 1930, and a small restroom addition was added at the top of the cellar stair on the northeast corner of the house." The roof was changed in 1920-1925. The diamond vents had glass installed behind them at an unknown time. The previous garage was connected to the main structure with an addition, which is understood to be the 1984 northeast addition under case H-84-343, though the file is no longer available for verification. However, it does show in the 1998 Sanborn map provided in the 2025 HCPI. The roof was approved to be replaced in 2024.

PREVIOUS CASE SUMMARIES:

ARC:
No Archaeological clearance has been issued for this property.

HDRB:
In case 2026-011230-HDRB on January 13, 2026, the Historic Districts Review Board approved a remodel which included replacement of windows and doors, raising the lower roofs on the north, constructing a 36 sq. ft. addition, replacing chimneys, constructing fences and gates, exterior stairs, and stuccoing the residence and yard wall. An exception to 14-5.2(D)(5)(a) for replacing historic windows. The exception was approved.

In case 2025-011549-HDRB, the Historic Districts Review Board reviewed the property for status. The Board designated the structure as contributing, with the south portion of the original residence and the east elevation as the primary facades.



Figure 3: Primary Facades

In case H-84-343, the Historic Districts Review Board approved the construction of an addition on the northeast side of the structure. There are no documents on file in the Historic Preservation Division.

ADMINISTRATIVE:
In case 2024-009160-ADMIN, the residence was approved for a reroof.

APPLICANT'S REQUEST:

The applicant proposes to:

1) Create a single garage door on the non-primary south façade. The door will be a wood carriage door style.



Figure 4: Previously Approved Floor Plan and the Proposed Floor Plan

This façade historically held two garage doors, which were replaced with windows.



Figure 5: The Historic Openings, Current Openings, and Planned Opening

EXCEPTION CRITERIA AND RESPONSES:

Exception to 14-4.6(E)(4)(II)(c): The applicant requests an exception to recreate a missing feature without replication.

(i) *Do not damage the character of the district*

Applicant Response: The unique character of the City will be maintained, as the primary residence would be renovated in accordance with the HDRB's conditional approval. Approval of the proposed single garage door would reflect the use of the garage but updated for modern times. In addition, the structure as a whole indicates an evolution of use and renovation evident in the historic districts. For instance, the historic photo shows two garage doors in a garage structure with a rounded stucco parapet. This has changed to a stucco wall, painted wood fascia, street-facing windows, and a rear garage door. The applicant is merely continuing this evolution.

Staff Response: Staff finds that this criterion is met. The character of the City will not be damaged by placing a garage door where there was one previously. It is obvious from the setup of the lot that this was once a garage, and the applicant is returning the space to its original use.

(ii) *Are required to prevent a hardship to the applicant or an injury to the public welfare*

Applicant Response: The Applicant considered two doors similar to the historic photo. For functionality, the Applicant would prefer a single door. Modern vehicles are often larger than historic vehicles. A wider single door would ease the maneuverability of a vehicle entering or exiting. Narrow double doors would create a hardship, as the future residents would not have free use of the garage.

Staff Response: Staff finds that this criterion is not met. There is a trade-off between parking flexibility and energy efficiency versus convenience and lower maintenance costs. Two single garage doors are more energy efficient; each door is independent, which results in higher costs for maintenance and installation. A single double garage door is usually 16-18 feet with no center post, making it easier to park large trucks, maneuver trailers, or swing car doors open. The cost of maintenance and installation is less since there is a single opening and door, but there is greater heat loss. Modern vehicles are larger and require more space for maneuvering than those that were initially parked in this garage. Therefore, the single door is the preference; however, staff does not find that this falls under a "hardship".

(iii*) Strengthen the unique heterogeneous character of the City by providing a full range of design options to ensure that residents can continue to reside within the historic districts*

Applicant Response: As noted above, a single wider door would be the most flexible option for a new garage door. This is the ideal design option for the Applicant and future residents. The Applicant has reasonable concerns that not providing a garage would limit what residents would consider residing in the residence. This was the primary reasoning for eliminating the ADU from the work scope and reconstructing the garage.

Staff Response: Staff finds that this criterion is met. The applicant worked with staff on other designs for the garage opening. There was discussion regarding the pros and cons of the two doors versus the single door. There is a trade-off, but the more practical design option is the single door for the modern vehicles and options for use of the garage space for the residents to continue to reside within the district.

RELEVANT CODE CITATIONS:

14-4.6 HISTORIC DISTRICTS

A. General Provisions

l. Purpose

In order to promote the economic, cultural, and general welfare of the people of Santa Fe and to ensure the harmonious, orderly, and efficient growth and development of the City, the Governing Body deems it essential to preserve the qualities relating to the history and culture of Santa Fe, maintain a harmonious outward appearance to preserve property values, and attract residents and tourists alike. The specific purposes of this section are to preserve qualities relating to the history of Santa Fe, such as the following:

I. Continue the existence and preservation of historic areas and buildings;

II. Continued construction of buildings in Santa Fe's historic styles; and

III. General harmony as to architectural style, form, color, height, proportion, texture, and material between buildings of historic design and those of more modern design.

C. Buildings with Significant or Contributing Historic Status

l. Purpose

Historic designation is intended to address the following:

I. Recognizing each structure as a physical record of its time, place, and use.

II. Preventing changes that create a false sense of historical development, such as the addition of conjectural features or architectural elements from other buildings;

III. Preserving and retaining changes to structures that have acquired historic importance in their own right, recognizing that most structures change over time;

IV. Preserving distinctive features, finishes, and construction techniques or examples of craftsmanship that characterize a structure; and

V. Avoiding making new additions and related or adjacent new construction in such a manner that, if removed in the future, the original form and integrity of the historic property and its environment would be unimpaired.

2. Designation of Significant, Contributing, or Noncontributing Status

I. Status Designation

Structures within historic districts may be designated a status of "significant," "contributing," or "noncontributing," as defined in Section 14-9.3, *General Definitions.* Staff shall maintain a record as to the current status of structures located in the historic districts.

II. HDRB Authority to Review Status Designation

a. The HDRB may change the status of a structure or designate a status for a structure that has no status designated.

b. A change in status or the designation of a status shall be based upon an evaluation of data provided through survey or other relevant sources of information and the definitions of "significant," "contributing," or "noncontributing."

c. When the HDRB designates a structure as contributing, it shall also specify which facades of the structure are primary.

V. Restoration of Status

If a property owner makes changes to a structure without the proper City approvals, which result in the lowering of the structure's status, staff or the Board may require the property owner to restore the structure such that its former status is restored.

3. Review by Historic Districts Review Board Required

I. Except where this chapter provides for review by staff, the HDRB shall review all applications for new construction, alteration, or demolition in the historic districts and of landmark structures throughout the city, based on the standards set forth in this section.

II. The historic board shall judge any proposed alteration or new structure for harmony with adjacent buildings, preservation of historical and characteristic qualities, and conformity to the standards for architectural style set forth in this section.

III. The HDRB may approve, deny, approve with conditions, or, with the consent of the applicant, postpone an application.
   a. For applications approved with conditions, no permit shall be issued until the HDRB conditions have been met.
   b. An application that is postponed shall be heard at a date agreed upon by the HDRB and the applicant.

IV. No permit shall be issued until the time for appeal to the Governing Body has expired.

4. Compliance with General and Specific Design Standards Required

All development located within the historic districts and subject to this section shall comply with all applicable general development standards set forth in Section 14-4.6E), *General Design Standards for All Historic Districts,* as well as any applicable specific development standards set forth in Section 14-4.6G), *Additional District-Specific Design Standards.*

E. General Design Standards for All Historic Districts

These standards shall apply to all additions or alterations to existing structures in the Historic Districts. Contributing, significant, and landmark structures may be subject to specific additional restrictions and district-specific standards in Section 14-4.6(G).

I. General

I. The historic status of a property with a historic status designation of significant, contributing, or landmark structure shall be retained and preserved. If a proposed alteration will cause a property to lose its significant, contributing, or landmark status, the application shall be denied. The removal of historic materials or alteration of architectural features and spaces that embody the status is prohibited.

II. If a proposed alteration or new construction will cause an adjacent property to lose its significant, contributing, or landmark status, the application may be denied.

III. For the regulations of this subsection, all facades of a significant structure are primary facades.

2. Building Additions

I. Design
   a. Building additions that meet the standards of Section 14-4.6G2, *Downtown and Eastside Historic District,* shall continue to meet those standards, in addition to the standards set forth in this section.
   b. Building additions shall have similar materials, architectural treatments and styles, features, and details as the existing structure, but shall be distinguishable from and not attempt to duplicate the existing structure.

II. Size and Location
   a. Building additions are not permitted on primary facades.

b. All building additions shall be set back a minimum of ten feet from the primary facade.
c. Building additions shall not exceed 50 percent of the square footage of the building's historic footprint and shall not exceed 50 percent of the historic length in linear feet of the primary facade.
d. To the extent architecturally practicable, new building additions shall be attached to any existing non-primary facade of a structure rather than attaching them to the primary facade of a structure.

III. Height

a. The maximum height of building additions to significant and landmark structures shall be at least six inches lower than the parapet or equivalent roof feature of the existing adjacent connecting facade.
b. Building additions to contributing structures shall be no more than one additional story higher than the existing structure. To the extent architecturally practicable, two-story additions shall be set to the rear or the side rear of the structure. When an additional story is to be placed upon an existing contributing structure, that footprint may be no greater than fifty percent of the footprint of the existing structure, subject to the provisions of Subsection A(1) above. For the purposes of this paragraph, an additional story shall not exceed twelve (12) feet from the existing rooftop to the highest point of that story.

IV. Remodeling to Increase Height

a. For remodeling of an existing significant or landmark structure, no increase in height of the structure is permitted.
b. For remodeling an existing contributing structure, a height increase may be permitted through approval of an exception, as described in Section 14-4.6D.

V. Rooftop Equipment

Rooftop equipment, including but not limited to solar collectors, clerestories, decks, or mechanical equipment, may only be installed on contributing and noncontributing structures and shall not be publicly visible, nor shall a parapet be raised to conceal such equipment.

3. Porches and Portals

Existing porches or portals on significant and landmark structures, and on primary facades of contributing structures, shall not be permanently enclosed.

4. Windows, Doors, and Other Architectural Features

I. For all facades of significant and landmark structures and for the primary facades of contributing structures:

a. Historic windows shall be repaired or restored wherever possible. Historic windows that cannot be repaired or restored shall be duplicated in the size, style, and material of the original. Thermal double-pane glass may be used. No window opening shall be widened or narrowed.
b. Window depth and other characteristics of window and door fenestration shall

be preserved.

c. No new opening shall be made where one presently does not exist unless historic documentation supports its prior existence.

d. No historic opening shall be closed.

II. **For all facades of contributing, significant, and landmark structures:**

a. **Architectural features, finishes, and details other than doors and windows shall be repaired rather than replaced.**

b. **In the event replacement is necessary, the use of new material may be approved. The new material shall match the material being replaced in composition, design, color, texture, and other visual qualities.**

c. **Replacement or duplication of missing features shall be substantiated by documentation, physical, or pictorial evidence.**

5. Roofs

The existing historic roof styles and materials shall be maintained or replaced in kind if necessary. The addition of dormers or other roof features should only be considered when they are an existing historic feature of the structure.

6. Surface Cleaning

The surface cleaning of structures shall employ the gentlest means possible. Chemical or physical treatments, such as sandblasting, that cause damage to historic materials are not permitted.

7. Archaeological Resources

Discovery of archaeological resources made during the development of a historic property shall be referred to the Archaeological Review Committee. See Section 14-2.1G.1.V.c, *Unexpected Discoveries.*

8. Signs

9. Murals

10. Pedestrian-Oriented Areas

F. Height, Pitch, Scale, Massing, and Floor Stepbacks.

The height, pitch, scale, and massing of any structure in a historic district, as defined in this section, shall be limited as provided for in this section, unless further restricted elsewhere within this chapter.

I. Applicability

The following sections identify specific areas and specific projects subject to this section. The Planning and Land Use Director shall determine whether or not properties are included within this section.

I. Specific Areas

The height limitations in this subsection F apply:

a. Within the following historic districts:

1. Downtown and Eastside;
2. Don Gaspar Area;
3. Historic Transition; and
4. Westside-Guadalupe.

b. In the Historic Review district, as specified herein.

II. Streetscape Standards

III. Project Location

Planning and Land Use Department staff shall determine the applicability of this section to individual projects and the applicable streetscape

2. Height

I. Official Map of Building Heights in the Historic Districts - Procedures

II. Height Limitations

The HDRB shall limit the height of structures as set forth in this section. Heights of existing structures shall be as set forth on the official map of building heights in the historic districts.

a. If a proposed building has a parapet, the façade shall not exceed two feet above the average of the height of the façades in the streetscape.
b. If the proposed building has a pitched roof, the ridge height of the proposed building shall not exceed two feet above the average of the ridge height of the pitched roofs in the streetscape.
c. Yard walls and fences shall be limited to a height that does not exceed the average of the height of other yard walls and fences in the streetscape.
d. The height of any other structure shall be limited to the allowable building height within the applicable streetscape, as defined in this section.
e. The height and dimensions of signage are as set forth in Section 14-7.61, *Sign Regulations in the Historic Districts.*
f. The HDRB may increase the allowable height for proposed buildings and additions located on a sloping site where the difference in the natural grade along the structure's foundation exceeds two feet. In no case shall the height of a façade exceed four feet above the allowable height of the applicable streetscape measured from natural or finished grade, whichever is more restrictive. This increase in height shall be constructed only in the form of building setbacks from the street.

Ill. Height Measurement

a. In historic districts, height shall be the vertical distance measured between the highest part of a structure and the existing grade or finished grade, whichever is more restrictive, at the midpoint of the street-facing facade, excluding rooftop appurtenances, the increased height of walls or fences over pedestrian and vehicular openings, and gates (either in open or closed position).
b. For structures that do not have street frontage, height shall be determined by the facade that contains the tallest vertical distance measured between the highest part of a structure and the existing grade or finished grade, whichever is more

restrictive. The height of walls and fences is measured from the street-facing side of the wall or fence.

IV. Pitch

If the determined streetscape includes over 50 percent buildings with pitched roofs, the proposed building may have a pitched roof. A pitched roof is defined as a gable, shed, or hipped roof. The pitch of the roof shall match the predominant pitch extant in the streetscape.

V. Scale

The height of a proposed building or addition, its façade length, and its roof form and pitch shall appear to be in proportion to the height, façade length, and roof form and pitch of buildings in the applicable streetscape, or the building on which the addition is proposed.

VI. Massing and Floor Stepbacks

The HDRB may require that upper floor levels be stepped back, to carry out the intent of this section; provided that the HDRB in making such determinations shall take into account whether the height of the proposed building, yard wall, fence, or proposed step back of upper floor levels is in harmony with the massing of the applicable streetscape and preservation of the historic and characteristic visual qualities of the streetscape. The HDRB shall also require that the publicly visible facades of the structure be in conformance with Section 14-4.6G), *Additional District-Specific Design Standards,* and, in meeting those requirements, may require that different floor levels be stepped back.

G. Additional District-Specific Design Standards

2. **Westside-Guadalupe Historic District**

I. District Standards

Compliance with the following structural standards shall occur whenever those exterior features of buildings and other structures subject to public view from any public street, way, or other public place are erected, altered, or demolished.

a. Slump block, stucco, brick, or stone shall be used as exterior wall materials. Wood and other materials may be used for details. Aluminum siding, metal, panels, mirrored glass, and unstuccoed concrete block or unstuccoed concrete shall not be used as exterior wall materials;

b. The color of stuccoed buildings shall predominantly be in browns, tans, local earth tones, and soft pastels. Surfaces of stone or brick shall be in the natural color. Entryways and portales or porches may be emphasized by the use of white or other colors. Painting of buildings with a color that causes arresting or spectacular effects, or with bold repetitive patterns, or using buildings as signs is prohibited. Murals, however, are permitted and may be referred to the city arts board for an advisory recommendation.

c. Roof form, slope, and shape. It is intended that the buildings be designed to be "wall-dominated". "Wall-dominated" means that the building's geometry is more defined by walls than by roofs. Buildings with flat, gabled, shed, or hipped roofs can be designed as "wall-dominated" solutions and are allowed. The height of the roof above the wall shall be no greater than the height of the wall. Folded plate, hyperbolic, or mansard roofs are not allowed;

d. The use of solar and other energy-collecting and conserving strategies is encouraged. The use of large glazed areas on south-facing walls for trombe walls or other solar collectors, direct gain, or other energy-collecting purposes is allowed. When in view from any public street, way, or other public place, solar equipment shall be screened as follows:
   1. raising the parapet;
   2. setting back from the edge of the roof;
   3. Framing the collector with wood.
   4. In the case of pitched roofs, by integrating the collector into the pitch;
   5. In the case of ground solar collectors, by a wall or vegetation;
   6. In the case of wall collectors, by enclosing or other walls;
   7. Other means that screen the collector or integrate it into the overall structure. Non-glare materials shall be used in solar collectors.

e. Mechanical, electrical, telephone equipment, microwave satellite receiving dishes, and other obstructive equipment shall be architecturally screened with opaque materials by raising the parapet, boxing in the equipment, or other appropriate means. The equipment shall be of a low profile to minimize the screening problems.

f. Walls and fences shall be of brick, adobe, masonry, rock, wood, coyote fencing, or similar materials. Wrought iron fences and slump block walls are allowed. Walls of unstuccoed concrete block, unstuccoed concrete, chain-link, metal wire, or similar materials are prohibited, except where the wall or fence is not in the street frontage.

g. Greenhouses;

h. Attached greenhouses that front on the street shall give the appearance of being integrated into the structure of the building or of being a substantive addition rather than having a lean-to effect. The use of corrugated fiberglass or rolled plastic for the external surface of attached or freestanding greenhouses that front on the street is prohibited. Greenhouses with slanting sides shall be bracketed at the ends, and greenhouses made from enclosed porches or portals shall maintain the shape of the porch or portal.

i. Porches and portales are encouraged;

j. When parking spaces are required for commercial or multi-family residential buildings, they shall be placed to the rear or side of the building.

II. Walls; Fences; Solar Collectors: Administration

Applications for the erection, alteration, or demolition of walls, fences, and solar collectors and required submittals shall be reviewed by the planning and land use department. Approval, disapproval, or referral shall be indicated by the division on the application for the building permit and on each of the required submittals, all of which shall be signed by the division staff assigned to the review. The division staff shall report approvals, disapprovals, and referrals to the board at its next regular meeting as an informational item. (Ord. No. 2007-45 § 30, Ord. No. 2020-22

HISTORIC CULTURAL PROPERTIES INVENTORY (HCPI)
BASE FORM

1. IDENTIFICATION

HCPI # NMCRIS # Project Name:527 Agua Fria Street Survey Date: November 25, 2025	Agency Number: Other #Old ID# 051613581; Santa Fe ID Number H1510 ☒Update
NAME OF PROPERTY Historic Name:243 Aqua Fria, 243/527 Agua Fria (Aqua Fria) Current Name:527 Agua Fria Street	OWNER and contact information:
SURVEYOR and contact information:Tina Reames; CSR Architects; 220 Gold Avenue SW; Albuquerque, NM 87102	
PROPERTY TYPE Category: ☒Building ☐Structure ☐Object ☐District ☐Site Subcategory: ☐Acequia/Historic Irrigation Ditch ☐Road/Trail ☐Other Linear	
LAND STATUS ☐ Federal ☐ State ☐ Local ☒ Private ☐ Other (land grant, tribal, etc.) Specify Other:	

2. LOCATION

STREET ADDRESS:527 Agua Fria Street CITY:Santa Fe, NM 87501 COUNTY:Santa Fe If no street address, describe how to locate the property:	UTM Coordinates:Hemisphere N Map-datum: NAD 83 Zone:13 E:414338.4 N:3949579.4 USGS Quad Name USGS Quad Code: Assessor Parcel #11266176 Local Reference #
SETTING	
Category: ☐Urban ☐Suburban ☐Rural ☐Village	Subcategory: ☐commercial ☐industrial ☒residential ☐public

3. PROPERTY DESCRIPTION

HISTORIC FUNCTION: Residence, Duplex (and for a time, a three-unit) residence CURRENT FUNCTION:Residence	CURRENT CONDITION: ☐intact ☒altered ☐deteriorated ☐other Describe:
CONSTRUCTION DATE: Before 1908 ☐Known ☒Estimated Source:1908 sanborn Fire Insurance Map ☒continuation	ARCHITECT/BUILDER:Unknown
BREIF DESCRIPTION OF PROPERTY:The property consists of a lot that is approximately 18,050 sf (.41 acres), located on the north side of Agua Fria Street, west of De Fouri Street. The house is located at the south end of the lot, along Agua Fria Street, and a small front yard, enclosed by a low adobe wall that has been stuccoed, is located between the front façade of the house and the sidewalk. North of the house is a small backyard surrounded by a wooden fence. A dirt and gravel drive runs along the east edge of the lot and to the north of the house. The house is a one-story, pitched roof, combination adobe and wood stud house that has been faced with a stucco finish. The back of the lot holds another single story smaller house (designated at 525 D Agua Fria Street).	

The front of the house entry is marked by a protruding front porch with arched screened front entry door. The front porch is not very visible from the street as the landscape is overgrown with evergreen trees. The rest of the south façade includes three sets of wood windows: central and nearest the front door is an 8/8/8 triple casement window, next to the west are two 8/8 double casement windows. All windows are trimmed with wood and painted a dark red/burgundy.

☐continuation

ACEQUIA/HISTORIC IRRIGATION DITCH:
Name of Acequia/Ditch Association:

HCPI #	NMCRIS #
Address of Property:527 Agua Fria Street	

ARCHITECTURAL STYLE: Check no more than 3 styles. Refer to HCPI Manual for additional style options.		
☐ Not Applicable	☐ International Style/Miesian	☐ Pueblo/Pueblo Vernacular
☐ Art deco	☐ Italiante/Bracketed	☐ Queen Anne
☐ Bungalow/Craftsman	☐ Mediterranean/Spanish Colonial Revival	☐ Ranch/Rambler
☐ Classical Revival/Neo-Classical Revival	☐ Mission Revival/California Mission Revival	☐ Southwest Vernacular
☐ Colonial Revival	☐ Modernism	☐ Spanish-Pueblo Revival
☐ Folk Victorian	☒ New Mexico Vernacular	☐ Territorial
☐ Gothic Revival/Folk Gothic	☐ Prairie School/Prairie Style	☐ Territorial Revival
☐ Other, describe:		

4. NATIONAL REGISTER/STATE REGISTER LISTING

A. National or State Register Listing:
Is the property individually listed in the State Register? ☐ Yes ☒ No
If yes, SR#
Is the property individually listed in the National Register? ☐ Yes ☒ No
Is the property part of a Register District? ☒ Yes ☐ No ☐ Unknown
If yes, is it ☒ Contributing ☐ Non-contributing
If not mentioned, in your opinion is the property: ☐ Contributing ☐ Non-contributing
District Name:Santa Fe Historic District District SR #260; District NR #73001150 in Santa Fe, the house is located within the "Westside-Guadalupe Historic District"
Is the property associated with a Multiple Property Documentation Form? ☐ Yes ☐ No ☒ Unknown
If yes: MPDF Name MPDF SR# MPDF theme

5. NATIONAL REGISTER/STATE REGISTER EVALUATION

A. Surveyor/Recorder Recommendations:
Name:Tina Reames Date:11/25/2025
National Register evaluation: ☐ eligible ☒ not eligible ☐ not sure
National Register eligibility criteria: ☐ a ☐ b ☐ c ☐ d ☒ criteria consideration: A) and B)
Research into the history of the building reveals that the house does not hold any special significance for its association with events or individuals on a local, regional, national, or global level. C) The building is a conglomeration of styles representing different periods in NM history, and therefore does not embody a particular type, period, or method of construction. Because there were so many changes to this house over the course of close to 50 years, there is not a high level of historic integrity to any specific historic period or type. D) It is unlikely that information important in history or prehistory will be yielded from this building or site.
Level of significance: ☒ local ☐ state ☐ national
Area of significance: subarea:
Is this property similar to other nearby properties? ☒ Yes ☐ No
Could it be contributing to an undefined district? ☒ Yes ☐ No
Discuss:The building is already considered to be contributing to the Santa Fe Historic District, listed on both the State and National Registers, and it is included in the Santa Fe Historic Preservation Divisions Westside-Guadalupe Historic District. If another district containing the site were defined, the building could be considered contributing.

B. Agency Determination:
Name: Date:
National Register evaluation: ☐ eligible ☐ not eligible ☐ undetermined
National Register eligibility criteria: ☐ a ☐ b ☐ c ☐ d ☐ criteria consideration:
Level of significance: ☐ local ☐ state ☐ national
Area of significance: subarea:
Could it be contributing to an undefined district? ☐ Yes ☐ No
Agency Remarks:

C. SHPO Determination:

Name: Date:

National Register evaluation: ☐ eligible ☐ not eligible ☐ undetermined

National Register eligibility criteria: ☐ a ☐ b ☐ c ☐ d ☐ criteria consideration:

Level of significance: ☐ local ☐ state ☐ national

Area of significance: subarea:

Could it be contributing to an undefined district? ☐ Yes ☐ No

SHPO Remarks:

HISTORIC CULTURAL PROPERTIES INVENTORY (HCPI)
DETAIL FORM

HCPI #	NMCRIS #
Address of Property:527 Agua Fria Street	

6. ARCHITECTURAL AND CONSTRUCTION DETAILS:

A. Visible Construction Materials

☒Adobe	☐Metal: Corrugated	☒Stucco
☐Brick	☐Masonry: Simulated	☐Tile: Clay
☐Composition Board	☐Metal: Structural Siding	☐Vinyl or Aluminum Siding
☒Concrete: Block	☐Metal: V-Crimp	☐Wood: Board & Batten
☐Concrete: Cast Stone	☐Stone: Random Ashlar	☐Wood: Horizontal Siding
☐Concrete: Poured	☐Stone: Random Coursed	☐Wood: Jacal
☐Concrete: Pre-cast	☐Stone: River Rock	☐Wood: Log
☐Curtain Wall	☐Stone: Rock Faced	☐Wood: Shingle
☐Earth Plaster	☐Stone: Tabular	☐Wood: Tongue and Groove

☒Other, describe:Wood stud, lath and plaster. Metal roofing.

B. Number of Stories

☐N/A ☒1 ☐1 ½ ☐2 ☐2 ½ ☐Other, describe:

C. Foundation

☐N/A ☒Not visible ☐None ☐At Grade ☐Raised

Materials: ☐Concrete: Poured ☐CMU ☐Stone ☐Other, describe:

Notes:

D. Roof

☐N/A Features: ☒Eave ☐Parapet

Shape: ☐Barrel ☐Butterfly ☐Flat ☒Cross Gable ☐Gable ☐Hipped ☐Pyramidal ☐Shed ☐Other, describe:

Pitch: ☐None ☒Low ☒Medium ☐Steep

Materials:

☐Asphalt	☐Metal: Corrugated	☒Tile: Metal
☐Composition Roll	☐Metal: Pressed	☐Tile:Terra Cotta
☐Composition Shingle	☒Metal: Standing Seam	☐Wood: Shingle
☐Earth	☐Metal: V-Crimp	

☒Other, describe:The original roof was a flat roof with drainage to the north. At some point, a gabled roof was added raising the elevations of the residence. It is not evident if this was a clay tile roof, but it now has a metal roof simulating a tile roof. The cross gable roof is offset. The lower metal roofs covering the front porches and side and back additions has a combination of metal tile and standing seam. The roof over the garage and connector is a low slope standing seam metal roof.

E. Chimneys

☐N/A Number Interior: Number Exterior:1

Construction Material: ☐Brick ☐Adobe ☐Stone ☒Stucco ☐Terra Cotta Tile ☒Metal Flue ☐Other, describe

F. Porches

☐N/A

Type: ☒Entry ☐Incised ☒Partial Width ☐Full-Width ☐Wrap ☐With a Gazebo

Other Details, describeAt the front entry, an extended covered area shields the front door to Suites 1 and 2. A later addition added a back enclosed porch with a low roof and large skylight.

HCPI #	NMCRIS #
Address of Property:527 Agua Fria Street	

G. Doorways

☐N/A Number of Doorways:7

Type: ☒One-leaf ☐Two-leaf

Style: ☐Diagonal Plank ☐Dutch ☐French ☐Plain ☒Panel ☐Vertical Plank
☒Other, describe:See sketches below

Components: Panels/Lights-Number and configuration
☐Sidelights - number and configuration ☐Transom

Material: ☐Aluminum ☐Fiberglass ☐Metal ☐Steel ☐Vinyl ☒Wood
☐Other, describe

Depth of Reveal:varies

Notes:



South Elevation Doors #1, #2, and #3 North Elevation Doors #4, #5, #6, and #7

H. Window Openings

☐N/A Number of Window Openings:21

Operation:	Material:	Glazing:		
☐Awning	☒Anodized Aluminum	☐1/1	☐2Pane Horizontal	☐Curtain Wall
☒Casement	☐Bare Aluminum	☐2/2	☐2 Pane Vertical	☐Glass Block
☒Double or Single Hung	☐Steel	☐3/1	☐3 Pane Vertical	☐Palladian Motif
☒Fixed	☐Vinyl	☐4/4	☐4 Pane Vertical	☐Picture Window
☐Hopper	☒Wood	☐6/6	☒Combination, describe:	☐Store Front or display
☐Louver	☐Other, describe:	☐9/9	☐Grouped, describe:	☐Other, describe:
☐Pivot		☒Other configuration, describe:The configuration of the windows varies. See elevations below.		
☒Sliding t				

Depth of Reveal: varies among the different window types

Notes:



I. Other Significant Features

Describe: On the north side of the house there is a thickened wall with decorative tile where a fountain may have been.

7. Associated Properties

Discuss:N/A
Are associated properties eligible for listing?No

8. Documents Available and Their Locations

Discuss: Sanborn Fire Insurance Maps attached (April 1908, June 1913, June 1921, January 1930); King's Official Map of the City of Santa Fe (1912); 1997 NM Historic Building Inventory forms; 2024 Santa Fe County Tax Parcel Viewer

9. Attachments

Please indicate which items are attached:
☒ Site Plan (required)
☒ Photos (required)
☒ Map or aerial photo (required)
☒ Continuation sheet (Word document), if necessary
☐ Additional detail forms for associated properties, if applicable

Historic Cultural Properties Inventory (HCPI) Continuation Sheet

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____		
1. Name of property: (historic and/or current name for property) 527 Agua Fria Street Previously 243 Aqua Fria Street; 243/527 Agua Fria (Aqua Fria) Street	2. Location: 527 Agua Fria Street Santa Fe, NM 87501	3. Local Reference Number: 4. County Santa Fe 5. Date of Survey November 25, 2025

Construction Date, Timeline of House, and Inferred Evolution of House Graphic:

There have been several additions and renovations to this building over time. Based on historic maps and the previous Historic Building Inventory forms (1997), it is estimated that there have been at least four additions to the original house.

- The original house was built sometime before 1908.
- It is estimated that the outhouse at the rear of the lot was constructed during the same timeframe (before 1908).
- An addition was constructed at the rear of the house (northeast side) sometime after 1908 and before 1913.
- A much larger addition was constructed at the west side of the house sometime after 1913 and before 1921. (Note: the new southwest corner of the house is constructed of adobe.) A covered front porch was added at the southeast corner of the house.
- Another large addition was added to the back of the house, possibly an enclosed back porch with lower roof. A separate garage was added to the west and access to a cellar on the east side of the house sometime after 1921 and before 1930. (Note: the location of the house appears to be further east.)



1908 Sanborn Map



1913 Sanborn Map



1921 Sanborn Map



1930 Sanborn Map

- It is estimated that the double gable roof was added after 1930 and a small restroom addition was added at the top of the cellar stair on the northeast corner of the house.
- The 2024 Santa Fe County Tax Parcel Viewer shows the property divided into three units.



1998 SF County Assessor Sketch



2024 SF County Tax Parcel View

- The image below is an enlarged image of the 1912 King's Official Map of the City of Santa Fe, NM indicating property ownership - Mrs. C. W. Dudrow

Historic Cultural Properties Inventory (HCPI) Continuation Sheet

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____		
1. Name of property: (historic and/or current name for property) 527 Agua Fria Street Previously 243 Aqua Fria Street; 243/527 Agua Fria (Aqua Fria) Street	2. Location: 527 Agua Fria Street Santa Fe, NM 87501	3. Local Reference Number: 4. County Santa Fe 5. Date of Survey November 25, 2025

Site Plan:



527 Agua Fria Site Plan, Drawn by Osage Design Studio, 9/1/25

-

Historic Cultural Properties Inventory (HCPI) Continuation Sheet

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____		
1. Name of property: (historic and/or current name for property) 527 Agua Fria Street Previously 243 Aqua Fria Street; 243/527 Agua Fria (Aqua Fria) Street	2. Location: 527 Agua Fria Street Santa Fe, NM 87501	3. Local Reference Number: 4. County Santa Fe 5. Date of Survey November 25, 2025

Photographs of Building and Site:

See 7 pages of exterior building photographs by Osage Design Studio; 45 pages of window assessment by RPA & Associates, LLC that follow.

North Elevation - northeast corner of house - thickened wall at exterior with decorative tile and broken spigot (remnants of a fountain)

527 Agua Fria Street
Existing Exterior Photographs
6/30/25

1 - South Façade (facing Agua Fria)

2 - South Façade showing west face of structure

3 - South Façade (facing Agua Fria)

4 - South Façade (facing Agua Fria)

5 - East Façade (southeast corner)

6 - East Façade

7 - North Façade (northeast corner)

8 – North Facade

9 - North Facade

10 - North Façade

11 - North Façade

12 - North Façade (northwest corner)



Agua Fria Street

Photo Key Plan

Plan
North

Historic Cultural Properties Inventory (HCPI) Continuation Sheet

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____		
1. Name of property: (historic and/or current name for property) 527 Agua Fria Street Previously 243 Aqua Fria Street; 243/527 Agua Fria (Aqua Fria) Street	2. Location: 527 Agua Fria Street Santa Fe, NM 87501	3. Local Reference Number: 4. County Santa Fe 5. Date of Survey November 25, 2025

Aerial Photograph:

Historic Cultural Properties Inventory (HCPI) Continuation Sheet

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____		
1. Name of property: (historic and/or current name for property) 527 Agua Fria Street Previously 243 Aqua Fria Street; 243/527 Agua Fria (Aqua Fria) Street	2. Location: 527 Agua Fria Street Santa Fe, NM 87501	3. Local Reference Number: 4. County Santa Fe 5. Date of Survey November 25, 2025

527 Agua Fria House Historic Research Synopses, Timeline of House, and Bibliography

See 12 pages of research synopses, etc. that follow.

527 Agua Fria House Research Synopses

Per King's and Sanborn Fire Insurance Maps:

243 Aqua Fria was built sometime before 1908. Based on the historic maps, the original portion of the existing building is the middle portion of the front rectangular façade that faces the street today. (Refer to building footprint graphic for more information.) The original building underwent a renovation and addition to the east and rear of the house sometime after 1912 and before 1913. An addition was added to the west sometime after 1913 and before 1921. A front porch was also added. Between 1921 and 1930, the footprint of the building moves to allow more space between the lot line and the main house. (There appears to have been an error in the original location of the dwelling.) On the 1930 Sanborn Map, the footprint of the building was changed from three simple rectangles to a blocky almost square footprint with the addition of a garage and the outhouse was removed. The address label for the building was changed from 243 Aqua Fria to 527 Agua Fria and the lot line had changed, reducing the lot size from east to west. The footprint of the building remained the same on the 1948 revision to the 1930 Sanborn Map. The current footprint of the building, which adds a restroom to the northeast corner and a connector from the main house to the garage, shows that one or more additions were constructed onto the building after 1985 but before 1998. Based on the research materials available, it is not entirely clear when the other additions were constructed, but it is inferred that all additions to the building and the garage were completed prior to 1998. Refer to the 1985 and 1997 Historic Building Inventory Forms section below.

Per the 1985 and 1997 Historic Building Inventory Forms:

The building was described in previous Historic Building Inventory forms – in 1985 and then resurveyed in 1997. There are some inconsistencies between the 1985 form and the 1997 and the Sanborn maps indicating the development of the house.

On the 1985 form, 527 Agua Fria (ID No. 051613581) is drawn with the main house separate from the garage that matches the 1930 and 1948 Sanborn Maps but with a protruding front porch addition. In addition, the surveyor of the 1997 form included a comment about the garage: "connected to the house by arched stucco gateway."[1] This gateway was not shown on either survey site plans. Based on the former survey, it is assumed that the addition joining the garage to the main house was constructed after 1985 but before 1998.

Both 1985 and 1997 forms note the “Mediterranean” style, but do not note that the original building was flat roofed. The 1985 form notes that the significance of the building is "of interest," and that the building should be eligible because it is "contributing."[2] It is to be noted that this 1985 survey form was the survey used to determine whether or not the building should be considered "contributing" in the Santa Fe Historic District (refer to the Santa Fe Historic District Section that follows).

On the 1997 form, the building is noted as being listed on the National Register of Historic Places, as being a contributing property, and as being listed on the State Register of Cultural Properties. While it is

[1] DB, “New Mexico Historic Building Inventory - Santa Fe Resurvey 1997, 527 Agua Fria,” August, 1997.
[2] HMW, “527 Agua Fria Building Survey Form,” June, 1985.

true that the building is contributing to the Santa Fe Historic District (See Santa Fe Historic District section that follows), the building is not listed individually on either the State Register of Cultural Properties or on the National Register of Historic Places. (Refer to SR-NR-Excel-Database-through-June-2016.xlsx file provided by the NM HPD for a list of individual properties and districts included on the State and National Registers).

On the 1985 form, the building is also noted as having had moderate remodeling and the 1997 form lists the degree of remodeling as minor.

Santa Fe Historic District

Per the 1973 National Register of Historic Places Inventory – Nomination Form:

The Santa Fe Historic District was added to the State Register on September 29, 1972 (State Register #260) and to the National Register on July 23, 1973 (National Register # 73001150). 527 Agua Fria is included as a contributing property in the Santa Fe Historic District, based on the 1997 survey of the property (mentioned above).

Ownership of the House:

On the 1912 King's Map, the building is marked as Block 60, Lot 34, and is attributed to Mrs. C. W. Dudrow.

From the 1985 Historic Building Inventory Form, included a comment: "A. C. Koch bought this in 1912 from C.W. Dudrow Estate. He added tile Rf in 1920-25. House has grown @ rear – N.V." [3]

Between 1913 and 1927, no information regarding the ownership of the house was found.

From 1928 through 1964, A.C. Koch or a Koch family member is listed as the owner of the property (per Santa Fe City Directories). There is also a Mrs. Dorothea K Dunakin (nurse) associated with the property either as a tenant or owner from 1944 through 1951.

- Between 1928 and 1938, the owner is listed as Koch, A. C.
- Between 1940 and 1944, the owner is listed as Koch, A. C. Mrs.
- Between 1944 and 1947, the owner is listed as Koch, A. C. Mrs. and Dunakin D. K. Mrs. nurse
- Between 1947 and 1949, the owner is listed as Koch, Alice Mrs. and Dunakin D. K. Mrs. nurse
- Between 1949 and 1951, the owner is listed as Koch, Alice Mrs. and Dunakin Dorothea K. Mrs. nurse
- Between 1951 and 1964, the owner is listed as Koch, Alice A. and Dunakin Dorothea K. Mrs. nurse
- In 1964, the owner is listed as Koch, Alice C. Mrs.

It is unknown when the Koch family sold the house.

On December 19, 2024, the house was sold.[4]

[3] HMW, "527 Agua Fria Building Survey Form," June, 1985.
[4] https://www.zillow.com/homedetails/527-Agua-Fria-St-Santa-Fe-NM-87501/6826806_zpid/

According to the Santa Fe County Tax Parcel Viewer, Neirika LLC is the owner of the house.

Review of Architectural Features and Styles of the House and Site:

The existing house is a compilation of pieces that were added on and renovated over the course of approximately ninety years. The various additions and renovations add different styles to the house.

Original Portion of the House: The original portion (pre-1908) may have followed many of the stylistic patterns of a New Mexico vernacular house. Whether Spanish Colonial or Territorial Style which was primarily in use in New Mexico during the mid to late nineteenth century, and featured flat roofs, adobe construction, new milled lumber elements and fired brick detailing, along with the inclusion of provincial Greek Revival Style elements, the original portion of the house is constructed of wood stud framed walls, which have been faced with stucco. A small outhouse was added in the rear. It is unknown when the north thickened wall and fountain were added to the house. This appears to be more Mediterranean in style. It is also unknown when the low adobe wall that wraps the front yard was added to the house.

Minor Addition #1: Between 1908 and 1913, a small addition was added to the northeast corner of the house.

Major Renovation/Addition #2: A significant renovation and addition was done at the house prior to 1921. It is assumed that part of the work of this project was completed in adobe construction, as the front southwest corner remains an 8" thick adobe constructed wall. Another part of the renovation of the house is thought to have included a front porch at the main entry. The windows and doors are typically wood units painted red. It appears that many of these units are the original ones installed when the main house and addition were built. The majority of the windows and doors have divided lites, square red wood trim, and the windows have square sills. All windows appear to be operable, inward swinging casement windows with a few double hung on the north side of the building.

Major Addition #3: It is possible that the third addition actually included more than one addition and interior remodeling over the course of approximately ten years including the addition of the pitched Mediterranean style tile roof. From what we can deduce, the third addition (post-1921) included the portion added onto the north and east side stair to a cellar, as well as the separate garage building. The rear porch addition may have been open to air or screened. The roof was a low slope. It is unknown whether the garage and porch had windows as it is apparent that the aluminum slider windows were added later.

The Garage: The garage is constructed of rusticated or split face narrow and long concrete masonry units. The roof is a flat roof and has a very low slope. It is unknown what the original material was but now is covered with a standing seam metal roof.

Major Renovation/Addition #4: It is possible that the fourth addition and renovation included the subdivision of the house into three separate dwelling units. The garage was connected to the main house and the back porch was enclosed. A small restroom was added to the northeast corner to serve

another tenant. Exterior entry doors were added for three separate entries. Metal roofs replaced the tile roofs, but simulated the look with red metal. The smaller additions have standing seam red metal roofs, while the main house and upper roofs have simulated metal tile red roofing.

Fences and Walls: There is little to no information regarding the existing fences and walls around the site. A low adobe wall (+/- 3' to 4' high) wraps the front yard. The low wall is not connected to the house on either edge, and has a break in the middle through which the front doors can be accessed. It is likely that the low adobe wall was added during either the first or the second addition to the house. On the east side of the building, the lot line is defined by a low wooden picket fence supported by square wood posts (approximately 4" x 4"). This fence was added sometime after the lot line was changed to its current position in 1930. It is adorned with a growing vine. A low adobe wall turning into a wooden coyote fence runs along much of the west edge of the site, but appears to be associated with the neighboring building. At the north side, individual back yards for the tenants are defined by a 6'-0" tall wooden picket fence. This fence was likely added much later on to provide privacy and security from vehicles parking in the rear of the lot.

Santa Fe Historic Preservation Division Definitions of Noncontributing, Contributing, and Significant Structures in a Historic District: [5]

- **NONCONTRIBUTING STRUCTURE:** A structure, located in an Historic District, which is less than fifty years old and/or does not exhibit sufficient historic integrity to establish and maintain the character of the Historic District. (Ord. No. 2004-26 §6)

- **CONTRIBUTING STRUCTURE:** A structure, located in a Historic District, approximately 50 years old or older that helps to establish and maintain the character of the Historic District. Although the structure is not unique in itself, it adds to the historic associations and/or historic architectural design qualities for which a District is significant. The structure may have had minor alterations, however, its integrity remains. (Ord. 2004-26 § 5)

- **SIGNIFICANT STRUCTURE:** A structure, located in an Historic District, that is approximately 50 years old or older, and (1) embodies distinctive characteristics of a type, period or method of construction. A structure may also be designated as significant (2) for its association with events or individuals that are important on a local, regional, national, or global level. In order for a structure to be designated as significant, (3) it must retain a high level of historic integrity. A structure may also be significant (4) if it is listed in or is eligible to be listed in the State Register of Cultural Properties or the National Register of Historic Places. (Ord. No. 2004-26 §5)[6]

[5] Santa Fe Historic Preservation Division, "Historic Preservation Definitions," City of Santa Fe Website, accessed May 5, 2017, http://www.santafenm.gov/historic_preservation_definitions.
[6] (x) Numbers in gray added for clarity of response. See "Architectural Historian Opinion" section that follows.

National Register Criteria for Evaluation (For Determination of Building's Eligibility):[7]

Per Santa Fe Historic Preservation Division definition of "Significant Structure" above, listing on either the State or National Registers is one criteria by which a structure can be considered significant within a historic district for the Santa Fe Historic Preservation Division. For that reason, we include the US Department of the Interior's Criteria for Evaluation of a historic property, along with the Criteria Considerations.

- **Criteria for Evaluation:** The quality of significance in American history, architecture, archeology, engineering, and culture is present in districts, sites, buildings, structures, and objects that possess integrity of location, design, setting, materials, workmanship, feeling, and association, and:
    A. That are associated with events that have made a significant contribution to the broad patterns of our history; or
    B. That are associated with the lives of significant persons in our past; or
    C. That embody the distinctive characteristics of a type, period, or method of construction, or that represent the work of a master, or that possess high artistic values, or that represent a significant and distinguishable entity whose components may lack individual distinction; or
    D. That have yielded or may be likely to yield, information important in history or prehistory.

- **Criteria Considerations:** Ordinarily cemeteries, birthplaces, graves of historical figures, properties owned by religious institutions or used for religious purposes, structures that have been moved from their original locations, reconstructed historic buildings, properties primarily commemorative in nature, and properties that have achieved significance within the past 50 years shall not be considered eligible for the National Register. However, such properties will qualify if they are integral parts of districts that do meet the criteria or if they fall within the following categories:
    a. A religious property deriving primary significance from architectural or artistic distinction or historical importance; or
    b. A building or structure removed from its original location but which is primarily significant for architectural value, or which is the surviving structure most importantly associated with a historic person or event; or
    c. A birthplace or grave of a historical figure of outstanding importance if there is no appropriate site or building associated with his or her productive life; or
    d. A cemetery that derives its primary importance from graves of persons of transcendent importance, from age, from distinctive design features, or from association with historic events; or
    e. A reconstructed building when accurately executed in a suitable environment and presented in a dignified manner as part of a restoration master plan, and when no other building or structure with the same association has survived; or
    f. A property primarily commemorative in intent if design, age, tradition, or symbolic value has invested it with its own exceptional significance; or

[7] Rebecca H. Shrimpton, ed., "How to Apply the National Register Criteria for Evaluation" (U.S. Department of the Interior, National Park Service, Cultural Resources, 1995), https://www.nps.gov/nr/publications/bulletins/nrb15/Index.htm.

g. A property achieving significance within the past 50 years if it is of exceptional importance.

Historic Architect's Opinion:

In response to criteria for a "Significant Structure," – see numbers in gray added to definition above:

(1) The building is a conglomeration of styles representing different periods in NM history, and therefore does not embody a particular type, period, or method of construction.

(2) Based on the research into the history of the building, including past owners, and residents of the house, the house was owned by Charles W. Dudrow, a 19th century entrepreneur in Santa Fe, who was engaged in the lumber, coal, ice, transfer and livery business. His legacy is connected to several historic locations, including the Dudrow House at 548 Agua Fria Street and an old warehouse that was later part of the Sanbusco Market, now part of the New Mexico School for the Arts complex. The house at 527 Agua Fria was part of the Dudrow Estate, but its significance is unknown for the Westside-Guadalupe Historic District "for its association with events or individuals that are important on a local, regional, national, or global level." The house was owned primarily by C. W. Dudrow for a short period of time before sold to A. C Koch in 1912.

(3) Because there were so many changes to this house over time, there is not a high level of historic integrity to any specific historic period or type.

(4) The building is not individually listed on either the State Register of Cultural Properties or on the National Register of Historic Places. While it is included as a contributing property in the Santa Fe Historic District, it is our opinion, for similar reasons to those listed in items (1) through (3) above, that the building would not be eligible for inclusion on either the State or National Registries.

Based on our findings, and on the Santa Fe Historic Preservation Division definitions included above, we recommend that the building continue to be designated as "Contributing."

Timeline for 512 Agua Fria House:

1846-1880 **Territorial Style** first appears in NM; features include traditional flat-roofed buildings, adobe construction, new milled lumber elements and fired bricks, and provincial Greek Revival style elements.

1869-1872 **Charles W. Dudrow,** came to Santa Fe. He had been a driver for the Barlow and Sanderson stage lines that ran from Pueblo, Colorado, to Santa Fe. [8]

1881 **Dudrow & Bear Ice, Transfer and Livery.** When Charles W. Dudrow arrived in Santa Fe he married Cora Bear and became a business partner with her father, Samuel Bear. The business was located near the train depot and Our Lady of Guadalupe Church. [9]

1908 The house appears on the April, 1908 Sanborn Map as three small rectangles with a smaller rectangle to the north. The house has the following markings: 1'2, D, and a small x in the right hand corners of each rectangle. The address is 243 Aqua Fria.[10]

1910 **Charles W. Dudrow – Kerr's Plaza Barber Shop** advertisement in the Santa Fe New Mexican, page 2, Tuesday, October 11, 1910. [11]

1911 **C. W. Dudrow** appears on the Fairview Cemetery Santa Fe history under Pioneer Merchants and Other Notable Businesspeople. (Approximate birth year is 1849).[12]

1912 The house appears on the 1912 Kings Map as the same three small rectangles (only shown as a polygon) with a smaller rectangle to the north. The property is listed as Block 60, Lot 34. A name is written on the lot. (Mrs. C. W. Dudrow)[13]

1913 The house appears on the June, 1913 Sanborn Map as the same three small rectangles only the top northeast corner of the third rectangle has an addition. The smaller rectangle is still located to the north. The house has the following markings: 1, D, Stucco, and a small black dot in the lower right of the two larger rectangles. The address is 243 Aqua Fria.[14]

1921 The house appears on the June, 1921 Sanborn Map as the same three small rectangles now with another larger rectangle added to the west. The smallest rectangle is still located to the north. The house has the following markings: 1, D, Stucco, and a small black dot in the lower right of the three large rectangles. A smaller dashed rectangle runs horizontally at the front of the house facing the street. The address is 243 Aqua Fria.[15]

[8] "Dudrow & Company" by Ana Pacheco, https://historyinsantafe.com/santa-fe-railyard-history/
[9] "Dudrow & Company" by Ana Pacheco, https://historyinsantafe.com/santa-fe-railyard-history/
[10] "Sanborn Fire Insurance Map, April 1908" (Santa Fe County, NM: Sanborn Map Company, 1908).
[11] "Santa Fe New Mexican", advertisement, https://files.core.ac.uk/download/pdf/217579931.pdf
[12] Fairview Cemetery Santa Fe website, https://www.fairviewcemeterysantafe.org/history/
[13] "King's Official Map of the City of Santa Fe, New Mexico" (Santa Fe, NM, 1912).
[14] "Sanborn Fire Insurance Map, June 1913" (Santa Fe County, NM: Sanborn Map Company, 1913).
[15] "Sanborn Fire Insurance Map, June 1921" (Santa Fe County, NM: Sanborn Map Company, 1921).

1928-1929 **Koch A C** is listed as owning the house (address marked as 527 Agua Fria). (o) following the name shows the occupant is owner of the home. This is given as an indication of permanency, but have not been checked by the official records. [16]

1930 The house appears on the January, 1930 Sanborn Map.[17]

- The house is now a large polygon appearing to have had a smaller rectangular addition to the east and larger area filled in to the northwest. The front dashed area has decreased at the southeast corner and an additional dashed protruding rectangle has been added. A large rectangle has been added to the west separate from the main polygon.
- The address is listed as 243, and also 527 Agua Fria (Aqua Fria).
- The markings say 1, D, small black circle in each of the small rectangular spaces. The separate rectangle has a 1, A (C.B) and three small black dots. There are black X's on the south, east, and north walls.
- The smallest rectangle to the north is now removed.
- A new lot line to the east has been drawn. There is a small adobe building and larger "r" shaped dwelling in the adjacent lot to the east.

1930-1931 **Koch A C** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following the name indicates the householder is the owner of the residence. [18]

1932-1933 **Koch A C** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following the name indicates the householder is the owner of the residence.[19]

1934-1935 **Koch A C** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following the name indicates the householder is the owner of the residence.[20]

1936-1937 **Koch A C** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following a householder's name indicates that we have received information during the canvass that the house is owned by some member of the family, but as the publisher cannot and does not guarantee the correctness of the information furnished, nor the complete absence of mistakes no responsibility for errors can be or is assumed, nor can the publisher furnish further information than that shown.[21]

---

[16] *Hudspeth Directory Company's Santa Fe City Directory, 1928-1929* (El Paso, TX: Hudspeth Directory Company, Inc., 1928).
[17] "Sanborn Fire Insurance Map, January 1930" (Santa Fe County, NM: Sanborn Map Company, 1930).
[18] *Hudspeth Directory Company's Santa Fe City Directory, 1930-1931* (El Paso, TX: Hudspeth Directory Company, Inc., 1930).
[19] *Hudspeth Directory Company's Santa Fe City Directory, 1932-1933* (El Paso, TX: Hudspeth Directory Company, Inc., 1932).
[20] *Hudspeth Directory Company's Santa Fe City Directory, 1934-1935* (El Paso, TX: Hudspeth Directory Company, Inc., 1934).
[21] *Hudspeth Directory Company's Santa Fe City Directory, 1936-1937* (El Paso, TX: Hudspeth Directory Company, Inc., 1936).

1938 **Koch A C** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following a householder's name indicates that we have received information during the canvass that the house is owned by some member of the family, but as the publisher cannot and does not guarantee the correctness of the information furnished, nor the complete absence of mistakes no responsibility for errors can be or is assumed, nor can the publisher furnish further information than that shown.[22]

1940 **Koch A C Mrs** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following a householder's name indicates that we have received information during the canvass that the house is owned by some member of the family, but as the publisher cannot and does not guarantee the correctness of the information furnished, nor the complete absence of mistakes no responsibility for errors can be or is assumed, nor can the publisher furnish further information than that shown.[23]

1942 **Koch A C Mrs** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following a householder's name indicates that we have received information during the canvass that the house is owned by some member of the family, but as the publisher cannot and does not guarantee the correctness of the information furnished, nor the complete absence of mistakes no responsibility for errors can be or is assumed, nor can the publisher furnish further information than that shown.[24]

1944 **Koch A C Mrs** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following a householder's name indicates that we have received information during the canvass that the house is owned by some member of the family, but as the publisher cannot and does not guarantee the correctness of the information furnished, nor the complete absence of mistakes no responsibility for errors can be or is assumed, nor can the publisher furnish further information than that shown.

An additional name is also listed - **Dunakin D K Mrs nurse**. It is unknown if this person is a tenant or someone living in the main residence.[25]

1947 **Koch Alice Mrs** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following a householder's name indicates that we have received information during the canvass that the house is owned by some member of the family, but as the publisher cannot and does not guarantee the correctness of the information furnished, nor the complete absence of mistakes no responsibility for errors can be or is assumed, nor can the publisher furnish further information than that shown.

An additional name is also listed - **Dunakin D K Mrs nurse**. It is unknown if this person is a tenant or someone living in the main residence.[26]

[22] *Hudspeth Directory Company's Santa Fe City Directory, 1938* (El Paso, TX: Hudspeth Directory Company, Inc., 1938).
[23] *Hudspeth Directory Company's Santa Fe City Directory, 1940* (El Paso, TX: Hudspeth Directory Company, Inc., 1940).
[24] *Hudspeth Directory Company's Santa Fe City Directory, 1942* (El Paso, TX: Hudspeth Directory Company, Inc., 1942).
[25] *Hudspeth Directory Company's Santa Fe City Directory, 1944* (El Paso, TX: Hudspeth Directory Company, Inc., 1944).

1949 **Koch Alice Mrs** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following a householder's name indicates that we have received information during the canvass that the house is owned by some member of the family, but as the publisher cannot and does not guarantee the correctness of the information furnished, nor the complete absence of mistakes no responsibility for errors can be or is assumed, nor can the publisher furnish further information than that shown.

An additional name is also listed - **Dunakin Dorothea K Mrs nurse**. It is unknown if this person is a tenant or someone living in the main residence.[27]

1951 **Koch Alice A** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following a householder's name indicates that we have received information during the canvass that the house is owned by some member of the family, but as the publisher cannot and does not guarantee the correctness of the information furnished, nor the complete absence of mistakes no responsibility for errors can be or is assumed, nor can the publisher furnish further information than that shown.

An additional name is also listed - **Dunakin Dorothea K Mrs nurse**. It is unknown if this person is a tenant or someone living in the main residence.[28]

1964 **Koch Alice C Mrs** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following a householder's name indicates that we have received information during the canvass that the house is owned by some member of the family, but as the publisher cannot and does not guarantee the correctness of the information furnished, nor the complete absence of mistakes no responsibility for errors can be or is assumed, nor can the publisher furnish further information than that shown.[29]

1972-1973 **Santa Fe Historic District**, which includes 527 Agua Fria as a contributing property, was added to the State Register of Cultural Properties and National Register of Historic Places.[30]

1985 NM Historic Preservation Division survey for 527 Agua Fria.[31]

1997 NM Historic Building Inventory – Santa Fe Resurvey form for 527 Agua Fria completed.[32]

2024 House listed and sold.

---

[26] *Hudspeth Directory Company's Santa Fe City Directory, 1947* (El Paso, TX: Hudspeth Directory Company, Inc., 1947).
[27] *Hudspeth Directory Company's Santa Fe City Directory, 1949* (El Paso, TX: Hudspeth Directory Company, Inc., 1949).
[28] *Hudspeth Directory Company's Santa Fe City Directory, 1951* (El Paso, TX: Hudspeth Directory Company, Inc., 1951).
[29] *Hudspeth Directory Company's Santa Fe City Directory, 1964* (El Paso, TX: Hudspeth Directory Company, Inc., 1964).
[30] James H. Purdy, "National Register of Historic Places Inventory - Nomination Form, Santa Fe Historic District" (NM Historic Preservation Division, July 23, 1973).
[31] HMW, "527 Agua Fria Building Survey Form," June, 1985.
[32] DB, "New Mexico Historic Building Inventory - Santa Fe Resurvey 1997, 527 Agua Fria," August, 1997.

Bibliography

"Charles W. Dudrow Burial Record." Find A Grave Memorial, November 30, 2025. https://www.findagrave.com/memorial/28979872/charles-w-dudrow

DB. "New Mexico Historic Building Inventory - Santa Fe Resurvey 1997, 527 Agua Fria," August, 1997.

"Dudrow & Company." By Ana Pacheco. https://historyinsantafe.com/santa-fe-railyard-history/

Fairview Cemetery Santa Fe website, https://www.fairviewcemeterysantafe.org/history/

HMW. "527 Agua Fria Building Survey Form," June, 1985.

Hudspeth Directory Company's Santa Fe City Directory, 1928-1929. El Paso, TX: Hudspeth Directory Company, Inc., 1928.

Hudspeth Directory Company's Santa Fe City Directory, 1930-1931. El Paso, TX: Hudspeth Directory Company, Inc., 1930.

Hudspeth Directory Company's Santa Fe City Directory, 1932-1933. El Paso, TX: Hudspeth Directory Company, Inc., 1932.

Hudspeth Directory Company's Santa Fe City Directory, 1934-1935. El Paso, TX: Hudspeth Directory Company, Inc., 1934.

Hudspeth Directory Company's Santa Fe City Directory, 1936-1937. El Paso, TX: Hudspeth Directory Company, Inc., 1936.

Hudspeth Directory Company's Santa Fe City Directory, 1938. El Paso, TX: Hudspeth Directory Company, Inc., 1938.

Hudspeth Directory Company's Santa Fe City Directory, 1940. El Paso, TX: Hudspeth Directory Company, Inc., 1940.

Hudspeth Directory Company's Santa Fe City Directory, 1942. El Paso, TX: Hudspeth Directory Company, Inc., 1942.

Hudspeth Directory Company's Santa Fe City Directory, 1944. El Paso, TX: Hudspeth Directory Company, Inc., 1944.

Hudspeth Directory Company's Santa Fe City Directory, 1947. El Paso, TX: Hudspeth Directory Company, Inc., 1947.

Hudspeth Directory Company's Santa Fe City Directory, 1949. El Paso, TX: Hudspeth Directory Company, Inc., 1949.

Hudspeth Directory Company's Santa Fe City Directory, 1951. El Paso, TX: Hudspeth Directory Company, Inc., 1951.

Hudspeth Directory Company's Santa Fe City Directory, 1964. El Paso, TX: Hudspeth Directory Company, Inc., 1964.

James H. Purdy. "National Register of Historic Places Inventory - Nomination Form, Santa Fe Historic District." NM Historic Preservation Division, July 23, 1973.

"King's Official Map of the City of Santa Fe, New Mexico." Santa Fe, NM, 1912.

Rebecca H. Shrimpton, ed. "How to Apply the National Register Criteria for Evaluation." U.S. Department of the Interior, National Park Service, Cultural Resources, 1995. https://www.nps.gov/nr/publications/bulletins/nrb15/Index.htm.

"Sanborn Fire Insurance Map, April 1908." Santa Fe County, NM: Sanborn Map Company, 1908.

"Sanborn Fire Insurance Map, January 1930." Santa Fe County, NM: Sanborn Map Company, 1930.

"Sanborn Fire Insurance Map, January 1930 Correction Reprint August 1948." Santa Fe County, NM: Sanborn Map Company, 1948.

"Sanborn Fire Insurance Map, June 1913." Santa Fe County, NM: Sanborn Map Company, 1913.

"Sanborn Fire Insurance Map, June 1921." Santa Fe County, NM: Sanborn Map Company, 1921.

"Santa Fe County 1969 Aerial Photograph." NM Department of Transportation, February 27, 1969.

"Santa Fe County Tax Parcel Viewer", https://sfcomaps.santafecountynm.gov/mapsvc/apps/webappviewer/index.html?id=212072bb5f18440f82d843a31515b714

Santa Fe Historic Preservation Division. "Historic Preservation Definitions." City of Santa Fe Website. Accessed May 5, 2017. http://www.santafenm.gov/historic_preservation_definitions.

"Santa Fe New Mexican" advertisement, https://files.core.ac.uk/download/pdf/217579931.pdf

Zillow Showcase Listing, https://www.zillow.com/homedetails/527-Agua-Fria-St-Santa-Fe-NM-87501/6826806_zpid/

Historic Cultural Properties Inventory (HCPI) Continuation Sheet

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____		
1. Name of property: (historic and/or current name for property) 527 Agua Fria Street Previously 243 Aqua Fria Street; 243/527 Agua Fria (Aqua Fria) Street	2. Location: 527 Agua Fria Street Santa Fe, NM 87501	3. Local Reference Number: 4. County Santa Fe 5. Date of Survey November 25, 2025

Historic Sanborn Maps:

See 8 pages of Sanborn Maps that follow.
Sanborn Maps includes:

- April 1908
- June 1913
- June 1921
- January 1930
- August 1948 Revision to January 1930 Map

11 SHEETS 235

1

SANBORN MAP COMPANY
POPULATION 8000
PREVAILING WINDS N & N W
WATER FACILITIES SEE NOTE
INCHAM & RO HAND ENGINE
2 INDEPENDENT HOSE CARTS
1 HOOK & LADDER TRUCK
SANTA FE.
SANTA FE COUNTY
NEW MEXICO.
SCALE 200 FT. = 1 INCH. APRIL 1908
11 BROADWAY, NEW YORK.
COPYRIGHTED 1908 BY THE SANBORN MAP COMPANY

WATER FACILITIES
Water Works established in 1882
Reservoir 24Miles East and 350 above Plaza
Capacity 2500000 Gals filled by running Stream
pressure at Plaza reduced to 60 pounds per
Square inch 2 Mains from Reservoir to City
No 13 Main Gateves of 6 to 15 W Pipe About
4 Miles of 6 to 10" W Pipe laid since 1882 250 D Hyd. Suits
as Corporation Daily consumption 1½ Million Gals in Summer

FIRE DEPT
Organized Vol total 40 members 2 Hose Cos
1st Co Rchem Plant to 2 Hose Carts 1050 ft
hose in good condition
Dept Hd Truck 100 ladders Rchem tank
55 gals 100 % hose Product Mfg Co Fire
160 rot gal pump 20 hoses cared with Bell
at Hose No No Horses
Grades-night Lights Elec-Night watchmen



INDEX

STREETS

A
Alto 102-228 9
" Don Gaspar to Galisteo 6
Aqua Fria ..... S, 9, 10

B
Bartlett 1
Bowers 1
Burro Alley 5, 8

C
Cathedral 100-210 3
Catron Ave 1
Cerrillos 100-129 7
" Road 7
Chapelle 102-206 7
College ..... 101-111 arbitrary 3
" 104 257 2

D
De Vargas 102-125 6
" ..... 138-164 arbitrary 2
Don Gaspar 5, 6
Dudrow 10

F
Federal 4

G
Galisteo, N 100-128 *8
" " 101-127 *9
" S 108-240 *9
" " 109-239 *6
Garfield Ave 201-228 9
" " Don Gaspar to Galisteo 6
Grant Ave 101-209 *4
" " 104-114 *8
" " 116-224 *7
Griffin Ave 5
Guadalupe 100-12 *10
" 101-121 *9

H
Hancock 8

I
Irving 135-214 7

J
Jefferson 8
Johnson 100-221 *8
" 101 225 *7

L
Lincoln Ave ..... 50 104 arbitrary 1
" " 100-110 5

M
Manderfield 6
Marcy 4
Metropolitan Ave 5, 6, 9
Montezuma Ave 101-217 8

O
Ortiz 100-126 5

P
Palace Ave., E 100 128 *3
" " " 101-137 *4
" " " 178-238 4
" " W 100-242 *5
" " " 101-243 *4
S
Sandoval 8
San Francisco Ave 100-122 3
" " 200-265 5
" " 300-305 *6
" " 304-309 *5
" " 310-407 8
Shelby 100-226 *5
" 101-213 *4
Sparks 5

T
Twitchell 2

W
Wagner 10
Washington Ave 100-220 *4
" " 101-247 *3
" " 300-318 *6
" " 301-317 *3
Water, E 100-111 3
" W 100-211 5
" " 301-338 8

SPECIALS

A
Allison Presbyterian Mission School 7
Armory 1

B
Blunt, G., Cement Block Mf'g 8

C
Capital Coal Co 10
Capitol Building 1
Cartwright-Davis Co. Hay Warehouse 10
Catholic Cathedral 5
Church (Negro) 8
" of the Holy Faith 1
Claire Hotel 5
Continental Oil Co 10
Cornado Hotel 5
County Court House 7
County Jail 8

D
Diaz, Dr., Sanitarium 5
D. & R. G. & S. F. R. R. Depot 10
Dudrow, C. W., Lumber Yard 10

F
Federal Building 4
Fire Department 4

G
Guadalupe Catholic Church 10

H
High School 4
Hughes, L. A., Hides & Wool 8
" Lumber Yard 8, 10

J
Janey, Mary E., Presb. School 10

L
Lemp Brewing Co. Depot 10

N
National Guard Commissary 9
New Mexico Asylum for the Deaf & Dumb 2
New Mexico Historical Society & Museum 3
New Mexico Penitentiary 11
Normandie Hotel 5

O
Opera House 5

P
Palace Hotel 2
Parochial Schools 3
Presbyterian Church 7
" Mission 3
Public School 9

S
St. John's M. E. Church 5
" Katherine's Indust'l Indian School 7
" Michael's College 3
" Vincent's Hospital 3
" " Orphanage 3
" " Sanitarium 3
Santa Fe New Mexican Printing 5
" " " Planing Mill 9
" " " Water & Light Co 5
San Miguel Church 2
Sisters of Loretto Convent 3
Skating Rink 4

U
U. S. Indian Industrial School 11

W
Womens Board of Trade Library B'T'd'g 4

NOTE— Indicates only one side of street shown.




10
APRIL 1908
SANTA FE
NEW MEX.
GUADALUPE R.C. CHURCH
PARSONAGE
MARY E. JAMES, PRESBYN MISSION SCHOOL
HEAT: STEAM, LIGHTS: ELECTRIC, CITY WATER.
WALLS FURRED INSIDE. CEMENT FLOOR BAT
Located 600' N. of Federal Bldg. See Sheet 4.
CHICKEN HO.
BRICK PIT
IRON GAS TANK NOT USED.
LOCATION OF OLD GAS PLANT
STORAGE
(CONCRETE)
VACANT
BEYOND
AQUA FRIA
WAGNER
DUDROW
GUADALUPE
C. W. DUDROW
WOOD YARD & WOOD SAWING
L. A. HUGHES, LUMBER YARD
C. W. DUDROW, LUMBER YARD
CHAPMAN-DAVIS CO.
HAY WARE HO.
CONTINENTAL OIL CO
OIL WARE HO.
PROPOSED 4" W. PIPE
LEMP BREWING CO
BOTTLING HOUSE
ICE HO.
WARE HO.
LUMBER SHED
LUMBER PILE
DRIVE
COAL BIN
COAL
SHED
A
F
ATCHISON, TOPEKA & SANTA FE R.R.
A.T. & S.F.R.R. SIDING
D.R.G.R.R. SIDING
CAPITAL COAL CO
DENVER & RIO GRANDE R.R.
SANTA FE CENTRAL R.R.
D.R.G.R.R. PASSENGER DEPOT
Scale of Feet.
50 40 30 20 10 0 50 100 150

WATER FACILITIES :–
Water Works established in 1884 - Reservoir 3 Miles E. & 390' above Plaza - capcty 450,000,000 Gals. filled by running stream - Pressure at Plaza reduced to 80 lbs. per sq. in - One 10" & One 15" main from reservoir to city - About 12 Miles 4" to 15" W. Pipe - About 4 Miles 6" to 10" W. Pipe laid since 1902 - 40 O.Hyds in corporation - Daily Consumption 1 Million gals. in summer -

FIRE DEPT.:–
Organized - Volunteer - Total 40 Members - 1 Carter Auto Hose Wagon, 1600' 2½" Hose - 1 60 Gal. Chemical on wheels - 200' Chemical Hose. Small amount of Ladders - Bell & Whistle Alarm - No fire Limits

Grades: Slight - Lights: Elec. Night Watchman -

SANBORN MAP COMPANY.
POPULATION 8000
PREVAILING WINDS S.W. & N.W.
WATER FACILITIES SEE NOTE
NO STEAM & ONE GAS ENGINE
ONE AUTO HOSE WAGON
NO HOOK & LADDER TRUCK
SANTA FE
SANTA FE COUNTY
NEW MEXICO
SCALE 50 FT. TO AN INCH
JUNE 1913
11 BROADWAY, NEW YORK.

COPYRIGHT 1913 BY THE SANBORN MAP COMPANY

1931 (12 SHEETS)

1



KEY
FIRE WALL 8 IN ABV ROOF
METAL CORNICE
FIRE WALL 12 IN ABV ROOF
WOOD CORNICE
FIRE WALL 16 IN ABV ROOF
FRAME PARTITION
OPENING WITH IRON DOOR
" " "STANDARD" IRON DOOR
WINDOWS & IRON SHUTTERS
WINDOW 1ST STORY
WINDOWS 1ST & 3RD STORIES
" 2ND & 4TH "
STABLE
BUILDINGS COLORED YELLOW ARE FRAME
" " RED BRICK
" " BLUE STONE
" " GRAY IRON
" " BROWN FIRE PROOF
(S) INDICATE RELATIVE HEIGHTS
FIRE STATION AS SHOWN ON KEY MAP
ALTERNATE STREET NUMBERS ARE ACTUAL
CONSECUTIVE STREET NOS ARE ARBITRARY

INDEX

STREETS

A

		SHEET
Aqua Fria,	S. of Water	5
" "	N. of De Vargas	9
" "	200-307	8
Aztec,	100-121	9

B

Bartlett,		11
Bowers,		2
Burro Alley,		5 & 6

C

Cathedral,		7
Catron Ave.,	100-131	2
" "	200-232	*2
Cerrillos,	100-129	9
" Road,		11 & 12
Chapelle,	100-269	2
Chavez,		10
College,		4 & 7

D

De Vargas, E. of Don Gaspar,	100-125	10
" " "	138-154, arb.	4
" W. of Don Gaspar,	100-233	9
Don Gaspar,		6 & 10
Dudrow,		8

F

Federal,		3 & 11

G

Galisteo, N. of De Vargas,	100-220	*5
" " "	101-221	*6
" S. of De Vargas,	100-224	*9
" " "	101-225	*10
" " "	226-245	10
Garfield Ave.,		9
Grant,	100-108	*5
"	101-221	*3
"	104-222	*2
"	301-311, arbitrary	3
Griffin,	100-219	2
Guadalupe,	100-230	*8
"	101-405	*9

H

Hancock,	100-409	9

I

Irvine, see McKenzie.		

J

Jefferson,		5
Johnson,	100-224	*5
"	101-225	*2
"	115-127, arbitrary	5

L

Lincoln Ave.,		3 & 6

M

McKenzie,	100-233	2
Manderfield,		10
Manhattan Ave.,		10
Marcy,		3 & 4
Metropolitan Ave.,		9
Minden (arbitrary),		11
Montezuma Ave.,		8 & 9

O

Ortiz,		6
Otero,		4

P

Palace Ave., E. of Wash'n Ave.,	100-178	*7
" " " " "	101-177	*4
" " " " "	179-264	11
" " " " "	317-334, arb.	4
" " " " "	590-603	11
" " W. of Wash. Ave.,	100-250	*6
" " " " "	101-251	*3
" " " " "	293-304½, arb.	3

S

Sandoval,		5
San Francisco Ave.,	100-133	7
" " "	200-265	6
" " "	300-308	*5
" " "	301-309	*6
" " "	310-409	5
Shelby,		6 & 7
Sheridan,		3
Sparks,		6 & 7
Staab,		2

T

Twitchell, see Marcy.		

W

Wagner,		8
Washington Ave.,	13-20, arbitrary	3
" " "	100-110	*6
" " "	101-247	*4
" " "	112-246	*3
" " "	112-114, arbitrary	3
" " "	301-317	*7
" " "	W.S., n. r. Scottish Rite Cath.	*11
Water, E. of Shelby,		7
" W. of Shelby,	100-245	6
" " "	120-223, arbitrary	6
" " "	300-361	5

SPECIALS

A

Allison Presbyterian Mission School,		2
Armory,		3
A. T. & S. F. R. R. Depot,		8

B

B. P. O. E. Building,		3

C

Capitol Building of New Mexico,		10
" Coal Co.,		8
" Hotel,		9
Cartwright-Davis Co., Hay Warehouse,		8
Chamber of Commerce,		3
Church of the Holy Faith,		11
Continental Oil Co.,		8
Coronado Hotel,		6
County Court House,		4
" Jail,		5
Cross-Kelly Co., Wholesale Grocery,		8

D

D. & R. G. R. R. Passenger Depot,		8
De Vargas Hotel,		4
Diaz, Dr., Sanitarium,		6

E

Elks' Theatre,		3

F

Federal Building,		3
Fire Department,		7
First Presbyterian Church,		2

G

Grade School, Lincoln Ave.,		3
Guadalupe Roman Catholic Church,		8

H

High School,		3
Hughes, L. A., Hides and Wool,		5

I

I. O. O. F. Hall,		6

J

James, M. E., Presbyterian Mission School,		11

L

Lemp Brewing Co., Bottling Works,		8

M

Mary E. James Presbyterian Mission School,		11
Montezuma Hotel,		6

N

National Guard Commissary,		9
New Mexican Printing Co.,		3
" Mexico Asylum for Deaf and Dumb,		11
" " Central R. R. Pass. Depot & Fy't (Ho.		8
" " " Historical Society and Museum,		3
" " " Penitentiary,		12
" " " State Capitol Building,		10
" State Lumber Co.,		8

P

Parochial Schools,		7
Post Office,		7
Presbyterian Mission,		7
Public School, Hancock Street,		9

R

Rice Chapel, A. M. E. Church,		5
Roman Catholic Cathedral,		7

S

St. John's Methodist Episcopal Church,		6
" Katherine's Industrial Indian School,		2
" Michael's College,		4
" Vincent's Sanitarium, Hospital & Orphanage		7
San Miguel Church,		4
Santa Fe Club House,		3
" Laundry,		5
" Lumber and Transfer Co.,		8
" Planing Mill,		9
" Water & Light Co., Electric Light Pl't,		6
" " " " Office,		4
Scottish Rite Cathedral,		11
Sisters of Loretto Convent of Our Lady of Light		7

T

Telephone Exchange,		6

U

United States Indian Industrial School,		12

W

Women's Board of Trade Library Building,		3

* Indicates only one side of Street shown.


8
JUNE 1913.
SANTA FE
N. MEX.
AQUA FRIA
DUDROW
WAGNER
GUADALUPE
MONTEZUMA AV.
NEW STATE LUMBER CO. PLANING MILL
SANTA FE LUMBER & TRANSFER CO.
CAPITOL COAL CO.
CARTWRIGHT-DAVIS CO. HAY WARE NO.
LEMP BREWING CO.
CONTINENTAL OIL CO. OIL WARE NO.
GUADALUPE R.C. CHURCH
Parsonage
CROSS-KELLY CO. WHSE. NO.
A.T. & S.F. R.R.
N.M.C.R.R.
D.&R.G.R.R.
Scale of Feet


JUNE 1921
SANTA FE
N. MEX.
8
9
AQUA FRIA
DE FOURE
DUDROW
WAGNER
GUADALUPE
MONTEZUMA AV.
SANTA FE BUILDERS SUPPLY CO.
LUMBER & BUILDING SUPPLIES
CAPITOL COAL CO.
CONTINENTAL OIL CO.
COCA-COLA BOTTLING CO.
GUADALUPE R.C. CHURCH
PARSONAGE
BROSS-KELLY CO. WHOL. GRO.
FREIGHT
PLATFORM
Scale of Feet.
Copyright 1921 by the Sanborn Map Co.


12
62
CLOSSON (WAGNER)
QUINTANA ST.
AGUA FRIA
ROMERO ST.
67
60A
(F)
AGUA FRIA (AQUA FRIA)
DE FOURI
DE FOURI (DE FOURE)
GUADALUPE R.C. CHURCH
60C
JAN. 1930
SANTA FE
N.MEX.
MIGUAL CHAVEZ R.C. SCHOOL
59
(A)
PLANING MILL
WIRE HO
PRIVATE GARAGE
LUMBER
GEN'L MDSE
PREMISES
SANTA FE BUILDERS SUPPLY CO
SASH
DOORS
TILE
OFF.
BUILDERS SUPPLIES
BUILDERS WAREHOUSE
PIPE
CAPITAL COAL YARDS
COAL YARD
HOUSE WHSE GOODS
MONTEZUMA AV.
BOTTLING WKS
PRODUCE
GARFIELD
19
3





65 58

SANTA FE

Santa Fe County
NEW MEXICO

SANBORN MAP CO. NEW YORK

JAN. 1930

All information contained in this map, covering properties that might be related to National Defense activities, is to be treated as strictly confidential by our subscribers and not divulged to any outside interests. The U. S. Espionage Act makes it incumbent upon possessors of information relating to National Defense to take all possible precautions to prevent it from falling into the hands of interests inimical to the United States.

ALL RIGHTS RESERVED. NO PART OF THIS MAP MAY BE REPRODUCED IN ANY FORM WITHOUT WRITTEN PERMISSION FROM THE SANBORN MAP COMPANY.

Copyright 1930 by the Sanborn Map Co.

Corrections and additions compiled to March 1942

Maps over New Mexico issue of March, 1933, which is now void. Santa Fe, N. Mex.

NEW REPORT, March, 1942

POPULATION: 20,237

Prevailing Winds:—North and Northwest.

PAVING—About 10½ miles concrete.
GRADES—Slightly rolling.

WATER FACILITIES

Supply is publicly owned. Source from 8 reservoirs located east of Town. Upper (Granite Point), capacity 580 acre feet, elevation 2,000 above Plaza; Lower, capacity 450 acre feet, elevation 850' above Plaza. Service basis, capacity 6,000,000 gallons, elevation 170' above Plaza. Gravity pressure direct into mains.

31 miles of 3" to 12" pipe. 197 double hydrants and 18 private hydrants. Average daily consumption 1,150,000 gallons. Domestic and fire pressure 80 lbs. at the Plaza.

FIRE DEPARTMENT

Volunteer. 1 (Chief) 1 assistant chief, 2 paid drivers and 21 volunteers. 1 station. 1 American-LaFrance 750 gallon pumper with 1,000' 2½" hose and 40' of ladders. 1 American-LaFrance 500 gallon pumper with 100 gallon booster tank, 1,000' 2½" hose, 100' 1½" hose and 40' of ladders. 1 American-LaFrance 500 gallon pumper with 100 gallon booster tank, 1,000' 2½" hose, 100' 1½" hose and 40' of ladders. 1 American-LaFrance 500 gallon pumper with 100 gallon booster tank with 800' 2½" hose and 40' of ladders, 600' 1½" hose and 1,000' 2½" hose in reserve.

To have one fire station corner of Hancock St. and Montezuma Ave. (Sheet 18).

Fire alarm by telephone and siren.

FIRE-RESISTIVE ROOFING ORDINANCE.

Ordinance prohibits use of wooden shingle roofs in Fire Limits only.

City Limits 3½ miles square.

KEY

CORRECTION RECORD

REVN NO.	DATE OF CORRECTION	ATTACHED BY	DATE ATTACHED
4	2/45	REPRINT	
5	7/45		

INDEX

STREETS

A

Agua Fria, ... 200-241 2
" " 300-331 13
" " 400-619 12
Alameda, The, ... 100-133 4
" " 134-273 3
" " 640-564 *10
" " 716-927 21
Allandale, ... 200-248 *21
Anita Place, ... 201-247 *17
Aqua Fria, see Agua Fria.
Arnijo, ... 10
Aztec, ... 300-341 13

B

Bartlett, see N. Castillo Ave.
" " S. Castillo Ave.
Berger, E., ... 100-131 20
" W., ... 100-161 20
Booth, E., ... 18
" W., ... 100-149 17
Bowers, ... 5 & 6
Boyle Lane, ... 15
Buena Vista Ave., E., ... 100 213 20
" " W., ... 100 161 20
" " 400-421 21
" " 422-440 *21
" " 423-531 *19
Burro Alley, ... 50 98 *3
" " 51 99 *3

C

Cannon Road, ... 400-503 10
" S. S., near Manderfield Public Grade School *11
Capitol, S., ... 100 141 14
Castillo Ave., N., ... 100 221 9
" " S., ... 9
Cathedral, see Cathedral Place.
" Place, ... 50-241 4
Catron, ... 6
Cerrillos Road, ... 400 428 *13
" " 401 435 *11
" " 430 434 *16
" " 436-607 16
" " 632 771 19
" " 772 788 *19
" " 1040 1069 11
Chapelle, ... 100-215 6
Chaves, see S. Capitol.
Cienega, ... 8
Closson, ... 12
College, ... 200 237 4
" 300-463 15
" 500-506 *18
" 501 507 *15
" 508-541 18

Coronado Road, E., ... 20
" W., ... 20 & 21

D

De Foure, see De Fouri.
De Fouri, ... 206 371 12
De Vargas, E., ... 100 135 14
" " 136-305 15
" W., ... 100 141 14
" " 200 241 13
Delgado, ... 100-120 *9
" " 230 248 10
Don Cubero, ... 700 717 19
" " 718 744 *19
" " 719 745 *21
" " 800 939 21
Don Diego Ave., ... 700 745 19
" " 801 869 *21
Don Gaspar Ave., ... 100 207 3
" " 209-431 14
" " 500 648 *17
" " 501 649 *18
" " 650 921 20

F

Federal, ... 5 & 7
" Place, ... 100 179 5

G

Galisteo, ... 100 242 *2
" " 101 241 *3
" " 244 342 *15
" " 301 459 *14
" " 400 434 *11
" " 436 440 *16
" " 501 609 *17
" " 611 659 17
" " 654 702 *20
" " 652 668 *17
" " 700 930 *21
" " 700 940 *16
" " 701 941 *13
" " 460 417 12
Gildersleeve, ... 630 801 20
Granada Place, ... 630 651 17
" " 652 667 20
Grant Ave., ... 100 116 *2
" " 101 241 *7
" " 118 326 *6
" " 301 327 *5
" " 400 521 6
Griffin, ... 138-241 6
" 400 431 6
Guadalupe, ... 300 420 *12
" 301 421 *13
" 422 440 *19
" 423 441 *16

H

Hancock, ... 200-209 2
" 210-423 13
" 424 603 16
Hickox, ... 200-335 16
" 336-351 19
" 100-107 5
" 108-241 8
" 300-409 9
Houghton, E., ... 200 241 20
" W., ... 100-151 20
" " 200-231 21

J

Jefferson, N., ... 100-210 *13
" 101-141 *2
" 201-211 *6
" S., ... 100-114 *13
" 101-211 *2
Johnson, ... 209-340 *2
" 201-339 *6

K

Kearny Ave., ... 5

L

La Vereda, ... 16
Lincoln Ave., ... 50-65 3
" 100-225 7

M

McKenzie, ... 200-341 6
Manderfield, ... 14
Manhattan Ave., E., ... 100-224 *18
" 101-121 *14
" 123-223 *16
" 300-339 15
" W., ... 100-140 *17
" 101-141 *14
" 202-347 16
" 348-351 19
Marcy, E., ... 100-229 8
" 230-325 9
" W., ... 50-145 7
Martinez, ... 100-139 9
Metropolitan Ave., see Read.
Montezuma Ave., ... 200-206 *11
" 201-207 *13
" 208-341 13
" 400-411 12

N

Nusbaum, ... 8

O

Ortiz, ... 200-249 3
Otero, ... 100-236 8

P

Palace Ave., E., ... 100-228 *4
" 101-227 *8
" 229-412 9
" 413-820 10
" W., ... 50-160 *3
" 51-159 *7
Paloma Ave., ... 400-420 *14
" 401-419 *15
Park Ave., ... 100-147 11
Pecos Road, ... 18
Public Road, Route No. 66, ... 21

Q

Quintana, ... 530-545 12

R

Read, ... 250-341 16
Reingardt Alley, ... 8 & 9
Rodriguez Road, ... 10
Romero, ... 12
Rosario, ... 5
" Road, ... 208 314 *11
Rose Ave., ... 10

S

San Doval, ... 100-123 2
San Francisco, E., ... 50 85 3
" " 100-141 4
" W., ... 100-131 3
" " 200-208 *2
" " 201-207 *3
" " 209-348 2
" " 400 527 11
Santa Fe Ave., E., ... 100 225 18
" W., ... 100 149 17
Seligman, see Shelby.
Sena, ... 200 333 21
Shelby, ... 50-230 *5
" 51 231 *4
Sheridan Ave., ... 7
Sparks, see The Alameda.
Staab, ... 200-341 6
State Highway No. 485, Route No. 66, ... 21

T

Temple Place, see Federal Place.

W

Wagner, see Closson.
Washington, see Shelby.
" Ave., ... 100-244 *7
" " 101-245 *8
" " 300-413 6
Water, E., ... 100-199 3
" " 200-241 4
" W., ... 100-141 3
Water, W., ... 200-333 2
Webber, ... 500-619 18

SPECIALS

A

Allison-James School, ... 5
" " (old) 6
Alvarado Hotel, ... 11
Armory, ... 7
" Troop "B" Stables, ... 15
A. T. & S. F. R. R. Freight Depot, ... 19
" " " Passenger Depot, ... 12

B

B. P. O. E. Building, ... 7
Big Jo Lumber Co., ... 2
Bishop's Lodge Co., Tourists Resort, ... 21
Boyle Floral Co., ... 15

C

Camp De Vargas, Tourist Camp, ... 16
Capital Coal Yards, ... 12
Capitol Hotel, ... 12
Chavez, M., Roman Catholic School, ... 12
Church of the Holy Faith (Episcopal), ... 9
City Hall, ... 8
Continental Oil Co., ... 19
Coronado Hotel, ... 3
County Court House, ... 8
" Jail, ... 2

D

De Vargas Hotel, ... 3
D. & R. G. W. R. R. Depot, ... 19

F

Federal Building, ... 5
Fire Department, ... 8
First Baptist Church, ... 14
" Methodist Episcopal Church, ... 3
" Presbyterian Church, ... 6
Fort Marcy Camp Grounds, Tourist Camp, ... 19
Franciscan Hotel, ... 16

G

Gilliland Oil Co. of New Mexico, ... 19
Grant, Public Grade School, ... 18
Gross Kelly & Co., Wholesale Grocery, ... 19
Guadalupe Roman Catholic Church, ... 12

H

Hancock Grade School, ... 13
Hotel El Fidel, ... 2

I

Ilfeld, C., Co., Wholesale Hardware and Groceries, ... 3

L

La Fonda Hotel, ... 4
Loretto Academy, R. C. School for Girls, ... 4

M

Manderfield Public Grade School, ... 11
Miguel Chavez Roman Catholic School, ... 12
Monero Fuel and Lumber Co., ... 6
Montezuma Hotel, ... 3

N

New Mexico Power Co., Sub-station, ... 3
" " School for the Deaf, ... 11
" " State Highway Warehouses, ... 19
" " Museum, Buildings, ... 7
" " Penitentiary, ... 22
Nuckolls Packing Co., Wholesale Meat Warehouse, ... 19

O

Orchard Camp, Tourist Camp, ... 15

P

Phillips Petroleum Co., ... 19
Post Office, ... 4

R

Railway Express Agency, Inc., ... 3
Renehan Apartments, ... 10

S

St. Catherine's Industrial Indian School, ... 17
" Francis R. C. Cathedral and School, ... 4
" Michel's College, ... 15
" Vincent Sanitarium, Orphans Home and Industrial School, ... 4
Santa Fe Builders Supply Co., ... 12
" " Creamery and Ice Co., ... 19
" " Electric Laundry, ... 2
" " Fuel Tank, ... 19
" " New Mexican Publish'g Corp'n, ... 7
" " Public Schools, ... 7
" " Tourist Camp, ... 11
" " Transportation Garage, ... 3
" " Women's Board of Trade and Library Ass'n, ... 7
Scottish Rite Cathedral, ... 5
Sena Plaza Offices, ... 18
Sinclair Oil Co., ... 19
State of New Mexico Capitol Buildings, ... 14
Summers Camp, Tourist Camp, ... 19
Sunmount Sanitarium, ... 18

T

Telephone Exchange Building, ... 3

U

U. S. Indian Industrial School, ... 21

* Indicates only one side of Street shown.

N. MEX. 503


12
12
GUADALUPE R.C. CHURCH
60C
JAN. 1930
SANTA FE
N.MEX.
CLOSSON (WAGNER)
POLACO
DE FOURI
AGUA FRIA
60A
(F)
AGUA FRIA (AQUA FRIA)
MIGUAL CHAVEZ R.C. SCHOOL
ROMERO
EUBANK LUMBER & SUPPLY COMPANY
DE FOURI (DE FOURE)
59
(A)
STATE HIGHWAY
GUADALUPE
MONTEZUMA AV.
CHARLES ILFELD CO.
GARFIELD
67
19
3

NEW MEXICO HISTORIC BUILDING INVENTORY - SANTA FE RESURVEY 1997

IDENTIFICATION

ADDRESS: 527 Agua Fria

OLD ID NUMBER: 0516 13581

SANTA FE ID NUMBER: H1510

UTM REFERENCE EASTING NORTHING

ZONE 12 13

LEGAL DESCRIPTION:

TNSP 17 (N) S RANGE 9 (E) W SEC 24 SW 1/4 NW 1/4

BUILDING NAME:

FIELD MAP
Santa Fe Historic Status Map 1996

DATE OF CONSTRUCTION: SOURCE(S)
by 1928 ESTIMATE city directory A C Koch ©
by 1930 ACTUAL Sanborn map

BUILDING DATA

ARCHITECTURAL STYLE:
Mediterranean

USE:

HISTORIC: (residential)

OTHER _____

PRESENT: (residential)

OTHER apartments

SURROUNDINGS:
residential/commercial

RELATIONSHIP TO HISTORIC SURROUNDINGS:

X SIMILAR ___ NOT SIMILAR

ASSOCIATED BUILDINGS ON SITE:

X YES ___ NO

WHAT TYPE? garage

IF INVENTORIED, LIST ID NUMBER(S)

H1511

DEGREE OF REMODELING:

X MINOR ___ MODERATE

___ MAJOR none evident

EXPLAIN:

OVERALL CONDITION:

___ EXCELLENT X GOOD

___ FAIR ___ DETERIORATED

BUILDING THREATENED?

___ YES X NO

PHOTO

SITE PLAN



SIGNIFICANCE

LISTED ON NATIONAL REGISTER OF HISTORIC PLACES?

X YES ___ NO ___ ELIGIBLE

X CONTRIBUTING ___ NON-CONTRIBUTING

LISTED ON STATE REGISTER OF CULTURAL PROPERTIES?

X YES ___ NO ___ ELIGIBLE

LOCAL DESIGNATION: Downtown-Eastside HISTORIC DISTRICT

X SIGNIFICANT ___ CONTRIBUTING ___ NON-CONTRIBUTING

LOCAL LANDMARK ___ YES X NO

SURVEYED 8/97 BY DB

NEGATIVES WITH NMHPD ROLL # D69 NEG # 14 TO 16

ARCHITECTURAL FEATURES: STYLE, MATERIALS, AND CONDITION

ROOFS & DRAINS	red (metal) tile roof with gables of various heights, gable horns, exposed rafters	
BUILDING WALLS	tan stucco/concrete	
FOUNDATIONS	not visible	APPROX. HEIGHT (FT.) 20
DOORS	wood french	
WINDOWS	8 light wood casements in pairs and trios; picture windows	
PORCHES OR PORTALES	SE corner - shed roof, stucco piers S - gable roof, round arched opening	
ARCHITECTURAL DETAILS		
FENCES/WALLS	low stucco wall, S; wd plank fence SE	
SITE FEATURES		
OTHER/ COMMENTS	Garage - flat roof, one overhead door, one filled w/ window, wd wall. Connected to house by arched stucco gateway.	

ADDITIONAL PHOTOGRAPHS

#16 SW

ES #14

1908 Sanborn
Aqua Fria
527

1930 Sanborn 527 Agua Fria



building threatened? yes	surveyed date 6/85 by HMW	county SANTA FE	ID no. 051613581
field map SFHD # 7	number 581	UTM reference zone 12 13	easting northing

location description: 527 AGUA FRIA

city/town: SANTA FE

land grant/reservation: ~~land grant/reservation~~

building name:

legal description: tnsp ___ N S range ___ E W sec ___ ½ ___ ½

film roll by SL no. SFHD # 20	negative nos. 35	loc. of neg. HPB

plan shape



date of construction: PRE 1912 + estimate ___ actual

source:

use
present: residential
other:
historic: residential
other:

condition: ✓excellent ___good ___fair ___deteriorating

degree of remodeling: ___minor ✓moderate ___major
describe: REAR ADDS, PORCH CLOSED.

surroundings: RES.

relationship to surroundings: ✓similar ___not similar

district potential: ___yes ___no

significance: ___eligible ✓of interest ___none
if eligible, why? CONTRIB.

associated buildings? ___yes
what type? STUCCO 2 CAR GARAGE.
if inventoried, list ID nos.

style: MED. REV.

foundation material: CONC.

wall material/surface: ADOBE/ STUCCO

architectural features
MIS MISSION TILE REF/ STABLE HUBNS., EXP'D RAFTER ENDS, DIAMOND VENTS.
CORNER PORCH W/ STUCCO'D PIERS, SEMI CIRC. SOFFIT
DOOR. IN SMALLER FRONT PORCH ENTRY.
6 LIGHT WD. CASM'TS., TRIM, TRIMS.
2 LARGE PIC WINDS ON W.
N.V. SHED ADDS @ REAR.

comments
A.C. KOCH BOUGHT THIS IN 1912 FROM C.W. DUDROW ESTATE.
HE ADDED TILE REF IN 1920-25. HOUSE HAS CROWN
@ REAR - N.V.
IT IS MED REV. FOR ITS REF, BUT OBVIOUSLY EARLIER
CORE.
(KOCH'S DAUGHTER LIVES IN BACK @ 229 POLACA).

see back? ___yes

H151

building threatened? yes	surveyed date 6/85 by HMW	county SANTA FE	ID no. 051613581
field map SFHD #7	number 581	UTM reference zone 12 13 easting	northing

location description: 527 AGUA FRIA

city/town: SANTA FE

land grant/reservation: ~~land grant/reservation~~

building name:

legal description: tnsp ___ N S range ___ E W sec ___ ½ ___ ½

film roll: by SL no. SFHD # 20 | negative nos.: 35 | loc. of neg.: HPB

plan shape



date of construction: PRE 1912 + estimate ___ actual

source:

use
present: residential
other:
historic: residential
other:

condition
✓ excellent ___ good
___ fair ___ deteriorating

degree of remodeling
___ minor ✓ moderate ___ major
describe: REAR ADDS, PORCH CHANGED.

surroundings: RES.

relationship to surroundings
✓ similar ___ not similar

district potential
___ yes ___ no

significance
___ eligible ✓ of interest ___ none
if eligible, why? CONTRIB.

associated buildings? ___ yes
what type? STUCCO 2 CAR GARAGE.
if inventoried, list ID nos.

style: MED. REV.

foundation material: CONC.

wall material/surface: ADOBE/ STUCCO

architectural features
MIS MISSION TILE REV/ STABLE HORNS, EXP'D RAFTER ENDS, DIAMOND VENTS
CORNER PORCH W/ STUCCO PIERS, SEMI CIRC. SOFFIT
DOOR IN SMALLER FRONT PORCH ENTRY.
6 LIGHT WD CASM'TS, TRANS, TRANS.
2 LARGE PIC WINDS ON W.
N.V. STUCCO ADDS @ REAR.

comments
A.C. KOCH BOUGHT THIS IN 1912 FROM C.W. DUDROW ESTATE. HE ADDED TILE RF IN 1920-25. HOUSE HAS CROWN @ REAR - N.V.
IT IS MED REV. FOR ITS RF, BUT OBVIOUSLY EARLIER CORE.
(KOCH'S DAUGHTER LIVES IN BACK @ 229 POLK).

see back? ___ yes

527 AGUA FRIA

THE ATTACHED SURVEY FORM REFLECTS HISTORIC BUILDING SURVEY WORK THAT WAS COMPLETED DURING APRIL - SEPTEMBER OF 1997. RESULTS OF THE SURVEY AS REFLECTED ON THE ATTACHED HAS NOT BEEN ADOPTED BY THE CITY COUNCIL. IT SHOULD BE CONSIDERED PRELIMINARY FOR PURPOSES OF PLANNING. THIS IS TRUE AS OF 9/97.

PLEASE SEE HEATHER OR MARY FOR MORE INFORMATION OR CLARIFICATION.

527 Agua Fria

Preliminary Zoning Review Worksheet

City of Santa Fe Land Use Department

To Be Completed By Applicant:

Date Submitted: 8/6/2025

Site Address: 527 Agua Fria

Property Owner of Record: NEIRIKA LLC

Proposed Construction Description: REMODEL

Applicant/Agent Name: Osage Design Studio / Richard Woodbury

Contact Person Phone Number: 505)629-5948

TOTAL ROOF AREA: 3,053

Zoning District: R-21

Overlay: □ Escarpment n/a
□ Flood Zone*
□ Other: _____

Submittals Reviewed with PZR:
☒ Legal Lot of Record □ Development Plan ☒ Building Plans ☒ Existing Site Plan ☒ Proposed Site Plan ☒ Elevations

Supplemental Zoning Submittals Required for Building Permit:
□ Zero Lot Line Affidavit

Access and Visibility: □ Arterial or Collector**
□ Visibility Triangle Required

Use of Structure: □ Residential
□ Commercial Type of Use: _____

Terrain: □ 30% slopes n/a

Lot Coverage : 23.6 %
□ Open Space Required: No

Setbacks:
Proposed Front: 13.3' Minimum: 7'
2nd Front? n/a
Proposed Rear: 128' Minimum: 15'
Proposed Sides: L 0.7' R 0.8' Minimum: 5'

Height: Proposed 18'-8" Existing
Maximum Height: _____ or
☒ Regulated by Historic Districts Ordinance
□ Regulated by Escarpment District

Parking Spaces:
Proposed 3 Accessible n/a
Minimum: 3

Bicycle Parking:**
Proposed: n/a Minimum: _____
** Commercial Requirement

* Requires an additional review conducted by Technical Review Division
** Requires an additional review conducted by the Traffic Engineering Division

THIS REVIEW DOES NOT GRANT ZONING APPROVAL FOR BUILDING PERMIT. FINAL ZONING REVIEW WILL BE PERFORMED AT THE TIME OF BUILDING PERMIT APPLICATION.

Richard Woodbury
PRINT NAME [□OWNER □APPLICANT ☒AGENT]

hereby certifies that the information provided for preliminary zoning review is accurate and will not be modified without consulting Land Use Department staff prior to submittal for Historic Districts Review Board review.

Richard Woodbury (electronic signature) 8/6/2025
SIGNATURE **DATE**

To Be Completed By City Staff: 2025-011022-PAR

Additional Agency Review if Applicable:
□ Escarpment Approval by _____ Date: __/__/__
□ Flood Plain Approval by _____ Date: __/__/__
□ Traffic Engineering Approval by _____ Date: __/__/__
Notes: _____

Zoning Approval:
☒ **Preliminary Approval** □ **with conditions** □ **Rejected**
Comments/Conditions: Legal lot of record provided. Significant structure in setbacks pre-existing.

REVIEWER: Rachael Harrison **DATE:** 08/15/2025

Original color form must be submitted with Historic Districts Review Board (HDRB) application packet.

Revised 20 November 2020

Osage Design Studio
Richard Woodbury
1216 Vitalia Street
Santa Fe, NM 87505
505.629.5948
osagedesignstudio@yahoo.com

August 10, 2026, revised 8/11/26, 8/13/26

Historic Preservation Division
Planning and Land Use Department
City Hall
200 Lincoln Avenue
Santa Fe, NM 87501

Project Number:	2025-011549-HDRB
Address:	527 and 527-A Agua Fria Street, Santa Fe NM 87501
Owners:	NEIRIKA LLC
Building Status:	Contributing
UPC:	1-053-099-521-161
Parcel No.:	11266176

RE: Exception Request to add new opening

On behalf of the applicant NEIRIKA LLC, I am submitting a request to add a new opening and changing the fenestrations on the non-primary portion of the south façade.

The property is located within the Guadalupe Historic District. The site has two existing residential structures. The subject structure is a tri-plex to be converted into a single family residence with attached garage located at the front of the property facing Agua Fria Street. (The rear structure is not part of the scope of this request; no work planned on the rear structure.) The subject structure is designated "contributing." The primary facades are the south façade (except for the south facing façade of the existing garage offset to the rear) and the east façade.

Per the HDRB meeting January 13, 2026, the project received conditional approval. See the attached Board Action letter.

The January 13th submittal indicated that the existing windows in the garage south façade window would remain. See the photos below for the existing windows.

The Applicant intends to eliminate the Accessory Dwelling Unit and reconstruct the existing Garage. The Applicant intends to relocate the garage door from the north to south façade. A primary reason for this change is to improve the legal access to the garage. (The existing access to the rear is through an adjacent lot without a platted access easement.) The two existing windows on the south garage façade would be removed. A new garage door will be placed on this façade in an enlarged opening.

The new garage door to be 16'-0" wide x 8'-0" tall. It will be an insulated overhead garage door with stained wood cladding. In additional, non-functioning black "wrought iron" hinges and handles will be installed to provide the illusion of carriage doors. Black exposed clavos will be installed on the wood planking of the door. The door to be stained Minwax "Special Walnut." The door would be recessed to

the interior of the wall with a stained wood surround on the inside face of the jamb and head. The exterior stucco would return with a bullnose to the trim.

Refer to the photographs attached to this letter for additional information about the garage door. A historic undated photo shows that the garage originally had two street facing doors. However, the applicant intends for a single wider door for functionality. The top colored garage door photo illustrates the intended design. The bottom photo is intended to show the proposed finish only.

On the North Façade, the 1/13/26 HDRB approved removing the existing garage door and installing new exterior doors and a window in new and enlarged openings. See the attached elevation drawings.

As the proposed garage door on the south façade is a new door in a new enlarged opening, an exception is required per Chapter 14-4.6(D). Exception requests must address the following criteria:

a. Do not damage the character of the district.
b. Are required to prevent a hardship to the applicant or an injury to the public welfare.
c. Strengthen the unique heterogeneous character of the City by providing a full range of design options to ensure that residents can continue to reside within the historic districts.

Exception Request: Install new garage door on non-primary south facade. The exception request includes removal of two existing windows, enlarging an existing opening, and installing a new garage door.

A. Do not damage the character of the district.

Response: The unique character of the City will be maintained as the primary residence would be renovated in accordance to the HDRB's conditional approval. Approval of the proposed single garage door would reflect the use of the garage but updated for modern times. In addition, the structure as a whole indicates an evolution of use and renovation evident in the historic districts. For instance, the historic photo shows two garage doors in a garage structure with a rounded stucco parapet. This has changed to a stucco wall, painted wood fascia, street facing windows, and a rear garage door. The applicant is merely continuing this evolution.

B. Are required to prevent a hardship to the applicant or an injury to the public welfare.

Response: The Applicant considered two doors similar to the historic photo. For functionality, the Applicant would prefer a single door. Modern vehicles are often larger than historic vehicles. A wider single door would ease maneuverability of a vehicle entering or exiting. Narrow double doors would create a hardship as the future residents would not have free use of the garage.

C. Strengthen the unique heterogeneous character of the City by providing a full range of design options to ensure that residents can continue to reside within the historic districts.

Response: As noted above, a single wider door would be the most flexible option for a new garage door. This is the ideal design option for the Applicant and future resident. The Applicant has reasonable concerns that not providing a garage would limit what residents would consider residing in the residence. This was the primary reasoning for eliminating the ADU from the work scope and reconstructing the garage.

Please review this request. Notify me if you have any questions or require additional information.

Sincerely,

Richard Woodbury

Richard Woodbury
Osage Design Studio

Attachments: 24x36 PDF drawings dated 8/10/26
HDRB Board Action Letter dated 1/13/26

South Façade – Western end of south facing garage structure

South Façade – Eastern end of south facing garage structure

Historic Photo of South Façade showing original garage doors
Date Uknown

Existing Garage – northeast corner

Existing Garage – north façade showing existing garage door

Proposed Garage Door Style

Proposed Garage Door Color – Minwax “Special Walnut” (refer to photo for color only, not style)

City of Santa Fe Chapter 14 Land Development Code	
Owner	NEIRIKA LLC
Address	527 Agua Fria Street, Santa Fe NM 87501
UPC	1-053-099-521-161
Tax Parcel	1126 6176
Legal	Guadalupe Neighborhood Parcel 284, T17N R9E S23
Zoning	R-21
Historic District	Westside Guadalupe Historic District
Hist. Bldg. Status	Contributing
Flood Plain	Not applicable
Archeological	Historic Downtown Archeological Review District
Escarpment	Not applicable
Mountain	Not applicable
Density	21 dwelling units per acre
Min. Lot Size	3,000 SF minimum, 2,000 SF with common open space
Existing Lot Size	0.418± acres
Max. Height	24' maximum height for residential structures, within 10' of side or rear property no portion of any story above ground level shall be higher than 14.0'. ***Maximum height might be superseded by historic***.
Existing Height	18'-8"± (no proposed change)
Setbacks (minimum yard requirements)	Front: 7' (20' for front facing garage) Side: 5' Rear: 15' or 20% of average lot depth, whichever is less
Maximum Lot Coverage:	40% maximum for single family or multi-family of fewer than 6 units. 40% maximum for multi-family with 6 or more units. May increase to 55% maximum if private open space is provided. (Lot coverage is the total area of structures on a lot in relation to lot area). For residential development, the portion of a lot occupied by easements for private roads and lot access driveways is excluded from the lot area. Lots smaller than one acre, common open space, fire access roads & other facilities intended primarily for other lots excluded from lot area.
Existing Lot Coverage:	23.4%
Proposed Lot Coverage:	23.4% (no change)
Open Space	No minimum open space required for single family residence except as provided by setbacks. Open space required to increase lot coverage per 14-7.5: Provide a minimum of 50% of total gross floor area (including 2nd floor). Minimum dimension of 12' (and not less than 4' / 40 SF for balconies. Portals, porches, roof decks, and balconies can contribute to the amount required. **NOT REQUIRED**: site meets maximum allowed lot coverage.

Accessory Structures	Generally, cannot be used as an accessory dwelling – may have a half bathroom (sink & toilet) or kitchen but not both.
Parking Residential	Dwelling Unit: 2 spaces per unit Attached Dwelling Unit (2-5 units): 2 spaces per dwelling unit Attached Dwelling Unit (over 5 units, less than 800 SF): 1 assigned space and 0.25 unassigned space per DU Attached Dwelling Unit (over 5 units, 800-1200 SF): 1 assigned space and 0.5 unassigned space per DU Attached Dwelling Unit (over 5 units, over 1200 SF): 1 assigned space and 1.0 unassigned space per DU Accessory Dwelling Unit: 1 space if ADU < 1,000 SF; otherwise 2 spaces Accessory Structures: parking not required
Required Parking Spaces	3 offstreet parking spaces
Existing Parking Spaces	6 off street parking spaces provided on lot for subject lot (1 in garage).
Parking Space Size	Standard pull in: 8.5' x 19', 23' drive aisle Small car: 7.6' x 15', 20' drive aisle. Parking lots with 10 or more spaces may have up to 20% of total req'd spaces designated as small car. Parallel: 8.5' x 23' Parking lots with less than 40 spaces may be gravel.



Vicinity Map

North



HDRB Approved Site Plan

Scale: 1" = 10'-0"

True North

0' 10' 20'

Proposed Lot Coverage:

Lot Size: 18,208 SF

Front Structure: 3,053 SF
Rear Structure: 1,250 SF

Lot Coverage: 23.63%

Parking Requirements:

Single Family Residence: 2 spaces
ADU less than 1,000 SF: 1 space

Retention Pond Calculations:

RE: City of Santa Fe Land Development Code Section 14-8.2 (E) (2)

The minimum amount of storm water to be retained on site to be the equivalent to the total amount of impervious surface (SF) multiplied by 0.16 equals the cubic feet (CF) of retention.

New impervious surface (ADU Bathroom): 36 SF

Total new impervious area: 36 SF

Total required ponding = 36 SF x 0.16 = 5.76 CF minimum
(5.76 CF x 7.48 = 43 gallons minimum)

Required retainage provided with (1) 50 gallon rain barrel

Sheet Index:

C-1 Existing Site Plan, Project Information
C-2 Proposed Site Plan
A-1 Existing Floor Plan
A-2 Proposed Remodel Floor Plan
A-3 Existing & Proposed Exterior Elevations

Scope of Work: Exterior and Interior Remodel of an existing residential structure.

Issued for City of Santa Fe Historic Division Review

Osage Design Studio
1216 Vitalia Street
Santa Fe, NM 87505
osagedesignstudio@yahoo.com
505.629.5948

Renovation of an Existing Residential Structure

NIERIKA LLC

527 Agua Fria Street, Santa Fe NM 87501

Existing Site Plan
Project Information

PRELIMINARY
Not for Construction
HDRB Review Only

8/10/26

2025-011549-HDRB

C-1



Osage Design Studio
1216 Vitalia Street
Santa Fe, NM 87505
osagedesignstudio@yahoo.com
505.629.5948

Renovation of an Existing Residential Structure

NIERIKA LLC

527 Agua Fria Street, Santa Fe NM 87501

Proposed Site Plan

PRELIMINARY
Not for Construction
HDRB Review Only

8/10/26

C-2

Sheet 2 of 6



Total Existing Floor Areas:

Heated:	2,345 SF
Non-heated (garage):	506 SF
Portals:	166 SF
Total Heated:	2,345 SF
Total Roofed:	3,017 SF

Total Proposed Floor Areas:

Heated:	36 SF
Non-heated (garage):	0 SF
Portals:	0 SF
Total Heated:	36 SF
Total Roofed:	36 SF

Total Adjusted Floor Areas:

Heated:	2,887 SF
Non-heated (garage):	0 SF
Portals:	166 SF
Total Heated:	2,887 SF
Total Roofed:	3,053 SF

Wall Legend:

- Existing wood framed construction
- New CMU / masonry construction
- New wood framed construction

Wall Types:

- 8 — 2 x 8 wood studs
- 6 — 2 x 6 wood studs
- 4 — 2 x 4 wood studs

HDRB Approved Floor Plan

Scale: 1/4" = 1'-0"

0' 5' 10'

Plan North

Osage Design Studio
1216 Vitalia Street
Santa Fe, NM 87505
osagedesignstudio@yahoo.com
505.629.5948

Renovation of an Existing Residential Structure

NIERIKA LLC

527 Agua Fria Street, Santa Fe NM 87501

Existing Floor Plan

PRELIMINARY
Not for Construction
HDRB Review Only

8/10/26

A-1

Sheet 3 of 5



Total Existing Floor Areas:

Heated:	2,345 SF
Non-heated (garage):	506 SF
Portals:	166 SF
Total Heated:	2,345 SF
Total Roofed:	3,017 SF

Total Proposed Floor Areas:

Heated:	36 SF
Non-heated (garage):	506 SF
Portals:	0 SF
Total Heated:	36 SF
Total Roofed:	542 SF

Total Adjusted Floor Areas:

Heated:	2,381 SF
Non-heated (garage):	506 SF
Portals:	166 SF
Total Heated:	2,381 SF
Total Roofed:	3,053 SF

Wall Legend:

- Existing wood framed construction
- New CMU / masonry construction
- New wood framed construction

Wall Types:

- 8 — 2 x 8 wood studs
- 6 — 2 x 6 wood studs
- 4 — 2 x 4 wood studs

Proposed Approved Floor Plan

Scale: 1/4" = 1'-0"

0' 5' 10'

Plan North

Osage Design Studio
1216 Vitalia Street
Santa Fe, NM 87505
osagedesignstudio@yahoo.com
505.629.5948

Renovation of an Existing Residential Structure

NIERIKA LLC

Guadalupe Neighborhood Parcel 284
527 Agua Fria Street, Santa Fe NM 87501

Proposed Remodel Plan

PRELIMINARY
Not for Construction
HDRB Review Only

8/10/26

A-2

Sheet 4 of 6



HDRB Approved Front (South) Elevation

Scale: 1/4" = 1'-0"



Proposed Front (South) Elevation

Scale: 1/4" = 1'-0"

Osage Design Studio
1216 Vitalia Street
Santa Fe, NM 87505
osagedesignstudio@yahoo.com
505.629.5948

Renovation of an Existing Residential Structure

NIERIKA LLC

527 Agua Fria Street, Santa Fe NM 87501

Exterior Elevations

PRELIMINARY
Not for Construction
HDRB Review Only

8/10/26

A-3

Sheet 5 of 6



Existing Rear (North) Elevation

Scale: 1/4" = 1'-0"



HDRB Approved Rear (North) Elevation

Scale: 1/4" = 1'-0"

Proposed Rear (North) Elevation

Scale: 1/4" = 1'-0"

NOTE:
No proposed changes between HDRB approved North Elevation and Proposed North Elevation.

Osage Design Studio
1216 Vitalia Street
Santa Fe, NM 87505
osagedesignstudio@yahoo.com
505.629.5948

Renovation of an Existing Residential Structure

NIERIKA LLC

527 Agua Fria Street, Santa Fe NM 87501

Exterior Elevations

PRELIMINARY
Not for Construction
HDRB Review Only

8/11/26

A-4

Sheet 6 of 6

h. **2025-011230-HDRB, 527 Agua Fria Street, Units 1, 2, and 3, Westlake-Guadalupe Historic District, contributing,** Osage Design Studio, agent for Neirika, LLC, owner, proposes to construct a 36 square foot addition, replace windows and doors, raise two sections of roofing, re-roof, stucco, and other repairs. Exceptions are requested to 14-5.2(D)(5)(a)(i)(ii)(iii) for the replacement of windows on primary facades, and to 14-5.2(D)(3)(a) for raising the roof of a contributing structure.

Ms. McCulley presented the case and staff recommendation. Staff found that the exception criteria have not been met and recommended denial of the exception to Section 14-5.2(D)(5)(a) for replacement of historic windows on primary façades (Items 1a, 1g, 1h, and 1l). Otherwise, staff recommended approval of the other elements of the application (Items 1b, 1c, 1d, 1e, 1f, 1i, 1j, 1k, and 2 through 9), as they comply with 14-5.2(D) General Design Standards for all Historic Districts, and 14-5.2(I) Westside-Guadalupe Historic District Design Standards.

Chair Rios requested that the primary façades be identified by elevation.

Ms. McCulley responded that they are the south elevation, larger sections and the entire east elevation.

Richard Woodbury, address inaudible, representing Osage Design Studio, was sworn in. He noted that the status of the project was recently downgraded from significant to contributing, which reflects the evolution of the architecture over time, as people living in homes modify them to make them more comfortable. He would like to replace the wooden windows, improve the lean-to porch to modern comfort, and improve the appearance of the structure.

Steven Vierra, co-owner, 24 Calle San Acacia, Santa Fe, was sworn in. Speaking via teleconference, he expressed an intention to restore the home so it could last another 100 years while respecting the neighborhood and its aesthetic. He noted that the home has already undergone so many changes that it no longer represents only one historical era or architectural style. The rotting wood could likely be restored rather than replaced, but this would be a short-term solution and not energy efficient.

Member Cherry asked about the vents on the front door.

Mr. Woodbury noted that the diamond gable vents could be repaired, but that there are currently two front doors. He wishes to change Door 3 to a window and replace Door 2 with a wood-panel door with lights.

Ms. McCulley clarified that Windows F, G, H, I, J, and L were on the primary façade. Staff recommended replacing Door 2 be in kind to maintain its arch. The applicant wishes to make Door 3, which is wooden, into a window, which would be smaller than the door.

Member Cherry noted that Door 3 was non-historic and asked whether the opening was historic.

Ms. McCulley responded that it was not.

Chair Rios inquired regarding the size of the proposed window.

Mr. Woodbury responded that it was three feet wide.

Mr. Ruybalid noted that the motion in progress implied that the exception criteria for raising the roof had been met.

Member Biedscheid responded that they had, as well as for converting Door 3 into a window.

Public Comment:
There was no public comment.

Board Action:

Member Biedscheid moved in case 2025-011230-HDRB at 527 Agua Fria Street, Units 1, 2, and 3, to adopt staff's recommendation, which is consistent with the window assessment report, which found that the exception criteria have not been met for the replacement of windows on the primary façades on the south and east and will require the repair of the historic windows on the primary façades, which are windows F, G, H, I, and J; to require the replacement in kind of the gable vents; to adopt staff's recommendation that Door No. 2 be replaced in kind to maintain the arch; and to approve the remaining elements of the application as submitted. Member Degnan seconded. The motion passed with the Board voting unanimously (4-0).

i. [redacted]

[redacted]

[redacted]

City of Santa Fe

Land Use Department
200 Lincoln Ave.
Santa Fe, New Mexico 87504-0909

PROJECT DESC: 2025-011230-HDRB, 527 Agua Fria St. units 1, 2, & 3, Westside-Guadalupe Historic District, Contributing, Osage Design Studio, agent for Neirika, LLC, owner, proposes to construct a 36 sq. ft. addition, replace windows and doors, raise two sections of roofing, re-roof, stucco, and other repairs. Exceptions are requested to 14-5-2(D)(5)(a)(i)(ii)(iii) for the replacement of windows on primary facades.

CASE NUMBER: 2025-011230--HDRB

PROJECT TYPE: Remodel

LOCATION: 527 AGUA FRIA ST 1
Santa Fe, NM 87501

CONTACTS:	Applicant	Osage Design Studio	1216 Vitalia Street Santa Fe, NM 87505	1216 Vitalia Street
	Property Owner	Neirika LLC		

BOARD ACTION

This is to certify that the Historic Districts Review Board (HDRB) acted on your request at their hearing on Jan 13, 2026. The decision of the Board was to approve the project items:

1) Replace windows and doors with divided lite windows as follows.

a. Window replacement in the same size opening at L, M, O, P, R, S, T, and V.
b. Window replacement with a new size at window E
c. Window Q will be infilled as part of the structural changes on the north elevation.
d. Window N will be converted to a door.
e. Two new windows where there are currently no openings will be in the addition, and on the north elevation wall.
f. A new door opening at the accessory dwelling unit.
g. Doors 1 and 3 (door 3 is on a primary façade) are to be replaced with windows.

i. Door 4 will be increased in size and replaced.
j. Doors 5 and 6, removed with reconstruction of space and addition.
k. Door 7 will be decreased in size to convert from a vehicle door to a pedestrian door.

NOTE: Applicant can use this action letter to apply for construction permit, but the permit shall not be released until the end of the appeal period which starts on the date of filing of the Findings and Conclusions in the City Clerk's office (SFCC 14-3.17(D)). Your permit will be denied if any changes on plans that were not approved by the HDRB or if conditions of approval are not met. **Please attach copies of this letter to all sets when submitting for construction permits.**

2) Raise the roof of the lower section of the north elevation, currently at 7'-10", to a height of 9'-8" and reroof to match the existing. The slope of the roof will be lessened to minimize the overall height change.
3) Construct a 36. sq. ft. addition to a height of 11'-2", where the maximum allowable height is 17'-8" on the north elevation. The addition will have a pre-finished metal gutter, downspout, and rain barrel.
4) Replace a chimney to meet current fire code and remove the metal flue for the wood stove that is currently on the northwest roof area.
5) Construct a 6'-0" high coyote fence with 6'-0" pedestrian gates on the north of the residence to replace the existing 6'-0" high wood plank fence.
6) Repair and stucco the front yard wall and replace the pedestrian gate with a new wood gate with solid wood rails and a flat wood panel, painted to match the existing fascia. The stucco shall be cementitious and will match the existing color.
7) Install a flagstone path from the front gate to the front door and replace the flagstone on the floor of the portal.
8) Install exterior steps with handrails at the exterior doors on the north elevation.
9) Stucco the residence in cementitious stucco to match the existing color.

Conditionally approve,

1. h) Replacement of Door 2 (on a primary façade) at the main entrance. The door may be replaced and the swing reversed on the condition that the arc of the door is not altered.

and to deny:
1. a) The replacement of windows F, G, H, I, and J finding the exception criteria are not met, and
1. l)The replacement of the gable diamond vents with metal louvered vents.

For further information please call 505-955-6124.

Sincerely,

Lani McCulley

NOTE: Applicant can use this action letter to apply for construction permit, but the permit shall not be released until the end of the appeal period which starts on the date of filing of the Findings and Conclusions in the City Clerk's office (SFCC 14-3.17(D)). Your permit will be denied if any changes on plans that were not approved by the HDRB or if conditions of approval are not met. **Please attach copies of this letter to all sets when submitting for construction permits.**

City of Santa Fe, New Mexico

memo

DATE: January 13, 2026

TO: Historic Districts Review Board Members

VIA: Heather Lamboy, Planning & Land Use Department Director
Maggie Moore, Assistant Land Use Director
Gary Moquino, Historic Preservation Division Manager *GM*

FROM: Lani McCulley, Senior Planner, Historic Preservation Division

---

2025-011230-HDRB, 527 Agua Fria St. units 1, 2, & 3, Westside-Guadalupe Historic District, Contributing, Osage Design Studio, agent for Neirika, LLC, owner, proposes to construct a 36 sq. ft. addition, replace windows and doors, raise two sections of roofing, re-roof, stucco, and other repairs. Exceptions are requested to 14-5-2(D)(5)(a) for the replacement of windows on primary facades.

REFERENCE ATTACHMENTS (Sequentially):

CITY SUBMITTALS

__x__ District Standards & yard wall & fence standards.

__x__ Historic Inventory Form

__x__ Zoning Review Sheet

__x__ Other: Fire code, International Existing Building Code References

APPLICANT SUBMITTALS

__x__ Proposal Letter

__x__ Site Plan/Floor Plan

__x__ Elevations

__x__ Photographs

__x__ Other: exception criteria, window assessment

STAFF RECOMMENDATION:

1. Staff finds that the exception criteria have not been met and recommends denial of the exception to section 14-5-2(D)(5)(a) for replacement of historic windows on primary facades (Items 1a, 1g, 1h, and 1l).
2. Otherwise, staff recommends approval of the other elements of the application (items 1b, 1c, 1d, 1e, 1f, 1i, 1j, 1k, and 2-9) as they comply with 14-5.2(D) General Design Standards for all Historic Districts, and 14-5.2(I) Westside-Guadalupe Historic District Design

Standards.

Sample motions:

Up to two motions will be required in this case. One motion for the exception to 14-5-2(D)(5)(a) for replacement of windows, and one for the elements of the project that do not require an exception.

a. In case 2025-011230-HDRB, for 527 Agua Fria Street, approve/deny the exception to section 14-5-2(D)(5)(a)(i)(ii)(iii) for replacement of windows on primary facades, finding that the exception criteria have/have not been met (Items 1a, 1g, 1h,,and 1l).
b. In case 2025-011230-HDRB, for 527 Agua Fria Street, approve/deny the elements of the project that do not require an exception (items 1b, 1c, 1d, 1e, 1f, 1i, 1j, 1k, and 2-9).

Should the Board deny the exception request, the applicant shall return with an alternative proposal for review and approval before proceeding with a building permit.

The property lies within the Historic Downtown Archaeological Review District. See Chapter 14, SFCC, Article 14-3.13(B)(1). There may be archaeological concerns associated with this project, and archaeological clearance may be required.

Figure 1: Site Location

BACKGROUND & SUMMARY:

Streetscape:
The streetscape for this property runs from just east of De Fouri Street to Romero Street. The street is lined with sidewalks with properties having low stucco yard walls and a couple of rock yard walls. Some of the yard walls are topped with metal fencing. There is a single chain link fence,

and to the west of Closson Street, there are some coyote fences. The yard walls and fences often feature wooden pedestrian gates. There are no vehicle gates. The average is forty-three inches in height, which is the maximum allowable height.

The properties tend to be narrow and long, with multiple buildings on most sites. The buildings vary in distance from the street, with some right up to the sidewalk and others set back twenty to thirty feet from the street. The buildings are a combination of residential and commercial spaces.

The buildings are a variety of Spanish Pueblo Revival, Territorial, and Vernacular style flat roof homes, as well as a variety of pitched roof homes. The homes are in lighter brown stuccos with white, brown, and blue trims and natural wood elements. There are several properties with metal elements as well.

Figure 2: Street View of Residence

Site Description:
The 3,017 sq. ft. multi-family residence at 527 Agua Fria units 1, 2, and 3 sits on a 0.418-acre lot and was constructed by 1908 and is listed as contributing to the Westside-Guadalupe Historic District with the south and east elevations designated as the primary facades.



Figure 3: Façade Diagram

The 1908 residence is constructed in a vernacular-style architecture with thick, stucco-plastered walls, red-tiled roofs, and ornate archways, with large, symmetrical facades designed for warmth and indoor-outdoor living.

The roof is a red metal roof with gables of various heights, gable horns, and exposed rafters. The roof heights vary, with the lowest at 7'-10" and the highest at just under 20'-0". According to the 1997 HCPI, the roof was changed to the existing tile roof in 1920-1925. According to the 2025 HCPI, *"the original roof was a flat roof with drainage to the north. At some point, a gabled roof was added, raising the elevations of the residence. It is not evident if this was a clay tile roof, but it now has a metal roof simulating a tile roof. The cross-gable roof is offset. The lower metal roofs covering the front porches and side and back additions have a combination of metal tile and standing seam. The roof over the garage and connector is a low-slope standing-seam metal roof."*

The walls are concrete and stucco in light tan, most windows are 8-lite wood casements in pairs and trios, and a few picture windows. The doors are wood, with the front south door being curved to match the curve in the portal. The south portal has a gable roof with a round arched opening. The southeast corner portal has a shed roof and stucco piers. The yard wall along the street is low stucco with a wood pedestrian gate, and the rear fencing is a 6'-0" high plank wood fence.

According to the 2025 HCPI, *"The original house was built sometime before 1908. An addition was constructed at the rear of the house (northeast side) sometime after 1908 and before 1913. A much larger addition was constructed on the west side of the house sometime after 1913 and before 1921. The new southwest corner of the house is constructed of adobe. A covered front porch was added at the southeast corner of the house. Another large addition was added to the back of the house, possibly an enclosed back porch with a lower roof. A separate garage was added to the*

west and access to a cellar on the east side of the house sometime after 1921 and before 1930. It is estimated that the double gable roof was added after 1930, and a small restroom addition was added at the top of the cellar stair on the northeast corner of the house." The roof was changed in 1920-1925. The diamond vents had glass installed behind them at an unknown time. The previous garage was connected to the main structure with an addition, which is understood to be the 1984 northeast addition under case H-84-343, though the file is no longer available for verification. However, it does show in the 1998 Sanborn map provided in the 2025 HCPI. The roof was approved to be replaced in 2024.

The residence is currently a three-unit structure that is being converted to a main residence with a guest house. It currently has an interior-only construction permit for the conversion work that is in progress. The addressing from multi-family to single-family will be changed after the conversion is complete.

PREVIOUS CASE SUMMARIES:

ARC:
No Archaeological clearance has been issued for this property.

HDRB:
In case H-84-343, the residence was approved for the construction of an addition on the northeast side of the structure. There are no documents on file in the Historic Preservation Division.

ADMINISTRATIVE:
In case 2024-009160-ADMIN, the residence was approved for a reroof.

APPLICANT'S REQUEST:
The applicant proposes to:

1) Replace windows and doors with divided lite windows as follows. An exception is requested to section 14-5-2(D)(5)(a) for replacement of windows on primary facades:
    a. Window replacement in the same size opening at F, G, H, I, J, L, M, O, P, R, S, T, and V. Windows F, G, H, I, and J are historic and restorable. Window O is historic; however, unrestorable. Windows L, M, P, R, S, T, and V are non-historic. Windows F, G, H, I, J, and L are all located on primary facades.
    b. Window replacement with a new size at window E, which is a non-historic window, and not located on a primary facade.
    c. Window Q will be infilled as part of the structural changes on the north elevation. This window is non-historic, and not located on a primary facade.
    d. Window N will be converted to a door. Window N is historic, however, not part of the original house, and not located on a primary facade.
    e. Two new windows where there are currently no openings will be in the addition, and on the north elevation wall.
    f. A new door opening at the accessory dwelling unit.
    g. Doors 1 and 3 (door 3 is on a primary façade) are to be replaced with windows; both are non-historic.

h. Door 2 (on a primary façade) is to be replaced without a size change, but the shape will be changed to rectangular with no arc, and the swing will be reversed.
i. Door 4 will be increased in size. According to the window assessment, it is historic, however, not of the original house, and is not located on a primary facade. The current unit has cut stiles and rails. The unit is lacking in structural integrity.
j. Doors 5 and 6, removed with reconstruction of space and addition, both are non-historic and are not located on a primary façade.
k. Door 7 will be decreased in size to convert from a vehicle door to a pedestrian door. This door is currently missing and is not located on a primary facade.
l. The east and south gable diamond vents are to be replaced with metal louvered vents for attic exhaust, painted white to match the facia. The east and south gable vents should open for venting; however, they have glass on the inside and do not vent to facilitate attic airflow.



Figure 3: Window Schedule

2) Raise the roof of the lower section of the north elevation, currently at 7'-10", to a height of 9'-8" and reroof to match the existing. The slope of the roof will be lessened to minimize the overall height change. This portion of the roof is not located on a primary façade.

Figure 4: Area of Roof to be Raised on North Elevation

3) Construct a 36. sq. ft. addition to a height of 11'-2", where the maximum allowable height is 17'-8" on the north elevation. The addition will have a pre-finished metal gutter, downspout, and rain barrel. The addition is not on a primary façade nor is it within 10' of a primary façade.



Figure 5: Area of Addition on North Elevation

4) Replace a chimney to meet current fire code and remove the metal flue for the wood stove that is currently on the northwest roof area. The chimney and flue are not located on primary facades.



Figure 6: Area of Chimney on North Elevation

5) Construct a 6'-0" high coyote fence with 6'-0" pedestrian gates on the north of the residence to replace the existing 6'-0" high wood plank fence.
6) Repair and stucco the unstatused front yard wall and replace the pedestrian gate with a new wood gate with solid wood rails and a flat wood panel, painted to match the existing fascia. The stucco shall be cementitious and will match the existing color. The existing color will need to be tested for confirmation of color.
7) Install a flagstone path from the front gate to the front door and replace the flagstone on the floor of the portal.
8) Install exterior steps with handrails at the exterior doors on the north elevation.
9) Stucco the residence in cementitious stucco to match the existing color. The existing color will need to be tested for confirmation of color, and the fascia will be painted white.

EXCEPTION CRITERIA AND RESPONSES:

Exception to section 14-5-2(D)(5)(a); The applicant requests an exception to replace historic windows F, G, H, I, J, and L, and doors 2 and 3 on primary facades.

(i) *Do not damage the character of the district*

Applicant Response: The structure has been designated "contributing," and the south and east facades are considered "primary". However, in the opinion of the Applicant, changes to the street-facing public façade should take precedence. On the street-facing façade, the changes involve window & door replacement in existing openings. No size changes are requested. No new openings or infilled openings are requested. Thus, the character of the district will be maintained. The most extensive work is proposed for the rear. This work will be hidden from public view. Hence, the character of the district will be maintained.

Staff Response: Staff finds that this criterion is not met for items Items 1a, 1g, 1h, and 1l. The windows are deemed as repairable per the window assessment. Replacing historic windows when unnecessary does damage the character of the historic district.

(ii) *Are required to prevent a hardship to the applicant or an injury to the public welfare*

Applicant Response: The exception request includes replacement of existing windows, replacement of doors, removal of iron grilles, replacement of the diamond gable vents, and new doors & windows in new openings on the north façade. As noted in the window assessment report, only a few of the windows are historic to the structure. The current window types vary. Many are single-pane, non-insulated units or older insulated units that do not meet the current energy code. Replacement would allow for code compliance, increasing the comfort of the inhabitants. None of the doors is historic. Replacement will allow for units that function well and have a design congruent with the overall appearance of the remodeled structure. The existing iron grilles are not historic and inhibit maintenance access to the windows. The fixed glazed diamond gable vents are non-functioning. Code requires that attics be vented, which new louvered metal vents, painted to match the fascia, will allow. As noted in the exception request below, the rear "lean-to" addition does not meet code regarding ceiling height. Replacing windows and doors in existing and new openings, as well as raising the roof,

allows for the spaces to be more efficiently utilized and provide code-required life safety egress.

Staff Response: Staff finds that this criterion is not met. Window replacement for the non-historic window L, can be considered because this window is non-historic, irreparable, and will be replaced in the same size openings. However, window replacement for the historic windows F, G, H, I, J, which can be repaired; repair is not under consideration in this application. According to the window assessment rating, these historic windows are in satisfactory condition and, therefore, are repairable. There is no hardship in retaining these windows.

Replacing the diamond vents changes the style of the home. Diamond-shaped gable vents for the side of a house were popular in the Victorian era and in Mediterranean-style buildings. They offer decorative appeal and attic ventilation, blending both aesthetic and functional purposes, particularly in architectural features. Metal louvered vents will not match the style of the residence.

Replacement of the non-historic doors can be considered. However, the front door that arcs at the top to match the portal is unique and a part of the character of the building. The door shape should be retained.

The green code does not apply to contributing, significant, or landmark properties. Therefore, the windows do not need to come into compliance with the green code.
The Green Code Reads:

> **"R501.6 Historic buildings**. Provisions of this code relating to the construction, repair, alteration, restoration and move-ment of structures, and change of occupancy shall not be mandatory for historic buildings provided that a report has been submitted to the code official and signed by the owner, a registered design professional, or a representative of the State Historic Preservation Office or the historic preservation authority having jurisdiction, demonstrating that compliance with that provision would threaten, degrade or destroy the historic form, fabric or function of the building."

There is no hardship in retaining the windows F, G, H, I, J, or the diamond attic vents.

(iii*) Strengthen the unique heterogeneous character of the City by providing a full range of design options to ensure that residents can continue to reside within the historic districts*

Applicant Response: The unique character of the City will be maintained as the proposed window & door replacement will provide a fresh, consistent, harmonious appearance. While it is common for individual structures to have different window and door sizes, configurations, finishes, etc., it is not pleasing for these structures to have units in varying degrees of maintenance.

Staff Response: Staff finds that this criterion is not met. Replacement of all windows, including those that are repairable, damages the status of the building and therefore the district and the city.

RELEVANT CODE CITATIONS:

14-5.2 HISTORIC DISTRICTS

(A) **General Provisions**

(1) General Purpose

In order to promote the economic, cultural, and general welfare of the people of the *city* and to ensure the harmonious, orderly and efficient growth and *development* of the *city*, it is deemed essential by the *governing body* that the qualities relating to the history of Santa Fe, and a harmonious outward appearance, which preserve *property* values and attract tourists and residents alike, be preserved, some of these qualities being:

(a) The continued existence and *preservation* of historical areas and *buildings*;

(b) The continued construction of *buildings* in the historic styles; and

(c) A general harmony as to style, form, color, height, proportion, texture, and material between *buildings* of historic design and those of more modern design.

(C) **Regulation of Significant and Contributing Structures in the Historic Districts**

(Ord. No. 2004-26)

(1) Purpose and Intent

It is intended that:

(a) Each *structure* to be recognized as a physical record of its time, place, and use. Changes that create a false sense of historical *development*, such as the addition of conjectural features or architectural elements from other *buildings*, shall not be undertaken.

(b) Changes to *structures* that have acquired historic *significance* in their own right shall be retained and preserved, recognizing that most *structures* change over time;

(c) Distinctive features, finishes, and construction techniques or examples of craftsmanship that characterize a *structure* be preserved; and

(d) New additions and related or adjacent new construction be undertaken in such a manner that if removed in the future, the original form and integrity of the historic *property* and its environment would be unimpaired.

(2) Designation of Significant, Contributing, or Noncontributing Status within Historic Districts

(a) Status Designation

Structures within historic districts may be designated a status of "significant," "contributing," or "noncontributing" based upon the definitions of these terms in Article 14-12. Staff shall maintain a record as to the current status of *structures* located in the Historic Districts.

(f) Restoration of Status

If a *property owner* makes changes to a *structure* without the proper *city* approvals, which result in the lowering of the *structure's* status, staff or the board may require the *property owner* to restore the *structure* such that its former status is restored.

(4) Compliance with General and Specific Design Standards Required

All *development* located within the historic districts and subject to this Section 14-5.2 shall comply with all applicable general *development* standards set forth in Subsection 14-5.2(D), as well as any applicable specific *development* standards set forth in Subsections 14-5.2(E) through (I).

14-12 Significant Structure:
A structure located in a historic district that is approximately fifty years old or older, and that embodies distinctive characteristics of a type, period, or method of construction. For a structure to be designated as significant, it must retain a high level of historic integrity. A structure may be designated as significant:

(A) for its association with events or persons that are important on a local, regional, national, or global level; or
(B) if it is listed on or is eligible to be listed on the State Register of Cultural Properties or the National Register of Historic Places.

14-12 Primary Façade:
One or more principal faces or elevations of a building with features that define the character of the building's architecture.

(D) **General Design Standards for All H Districts**

In any review of proposed additions or alterations to *structures* that have been declared significant or contributing in any historic district or a *landmark* in any part of the *city*, the following standards shall be met:

(1) General

(a) The status of a significant, contributing, or *landmark structure* shall be retained and preserved. If a proposed alteration will cause a *structure* to lose its significant, contributing, or *landmark* status, the *application* shall be denied. The removal of historic materials or alteration of architectural features and spaces that embody the status shall be prohibited.

(b) If a proposed alteration or new construction will cause an adjacent *structure* to lose its significant, contributing, or *landmark* status, the *application* may be denied.

(2) Additions

(a) Additions shall have similar materials, architectural *treatments* and styles, features, and details as the existing *structure*, but shall not duplicate those of the existing *structure* in a manner that will make the addition indistinguishable from the existing *structure*.

(b) Additions to *buildings* that meet the standards of Subsection 14-5.2(E) shall continue to meet those standards set forth in Subsection 14-5.2(E) in addition to the standards set forth in this section.

(c) Additions are not permitted to *primary façades*.

(d) Additions are not permitted to the side of the existing footprint unless the addition is set back a minimum of ten (10) feet from the primary facade. The addition shall not exceed fifty percent of the square footage of the existing footprint, and shall not exceed fifty percent of the existing dimension of the primary facade. To the extent architecturally practicable, new additions shall be attached to any existing noncontributing portion of *structures* instead of attaching them to the significant or contributing portion.

(e) The height of additions:

(i) For significant and *landmark structures* shall be a minimum of six (6) inches less than the parapet or equivalent roof-feature of the existing adjacent connecting facade.

(ii) For contributing *structures* shall be no more than one additional *story* higher than the existing *structure*. To the extent architecturally practicable, two-story additions shall be set to the rear or the side rear of the *structure*. When an additional *story* is to be placed upon an existing contributing *structure*, that footprint may be no greater than fifty percent of the footprint of the existing *structure*, subject to the provisions of Subsection A(1) above. For the purposes of this paragraph, an additional *story* shall not exceed twelve (12) feet from the existing rooftop to the highest point of that *story*.

(3) Remodeling to Increase Height; Rooftop Appurtenances

(a) For *remodeling* of existing significant and *landmark structures*, no increase in height of the *structures* is permitted. (For standards relating to additions to existing *structures*, see paragraph (2) above.)

(b) For significant and *landmark structures*, *publicly visible* rooftop appurtenances, including but not limited to solar collectors, clerestories, decks, or mechanical equipment, shall not be added, nor shall the parapet be raised to conceal the *rooftop appurtenances*. For contributing *buildings*, solar collectors, clerestories, decks, or mechanical equipment if *publicly visible* shall not be added.

(4) Porches and Portals

Existing *porches* or *portals* shall not be enclosed.

(5) Windows, Doors, and Other Architectural Features

(a) For all facades of significant and *landmark structures* and for the primary facades of contributing *structures*:

(i) Historic windows shall be repaired or restored wherever possible. Historic windows that cannot be repaired or restored shall be duplicated in the size, style, and material of the original. Thermal double pane glass may be used. No opening shall be widened or narrowed.

(ii) No new opening shall be made where one presently does not exist unless historic documentation supports its prior existence.

(iii) No existing opening shall be closed.

(b) For all façades of significant, contributing, and *landmark structures*, architectural features, finishes, and details other than doors and windows shall be repaired rather than replaced. In the event *replacement* is necessary, the use of new material may be approved. The new material shall match the material being replaced in composition, design, color, texture, and other visual qualities. *Replacement* or duplication of missing features shall be substantiated by documentation, physical, or pictorial evidence.

(6) Roofs

The existing roof styles and materials shall be maintained or replaced in kind if necessary. The addition of dormers or other roof features should only be considered when they are an existing or historical feature of the *structure*.

(8) Archaeological Resources

Discovery of archaeological resources made during the historic districts review process shall be referred to the archaeological review committee.

(9) Height, Pitch, Scale, Massing, and Floor Step backs

The height, pitch, *scale*, and massing of any *structure* in a historic district, as defined in this section, shall be limited as provided for in this section, unless further restricted within this chapter.

(a) Applicability

The following sections identify specific areas and specific *projects* subject to this section. Planning and land use department staff shall determine whether or not properties are included within this section. (Ord. No. 2007-45 § 30; Ord. #2020-22, § 16)

F. When the proposed *building*, *yard wall*, or fence is located in a *streetscape* that includes no *buildings*, *yard walls*, or fences, the height of the proposed *building* shall not exceed sixteen (16) feet. *Yard walls* and fences in this *streetscape* shall not exceed five (5) feet in height.

(c) Height

(ii) In exercising its authority under this section, the board shall limit the height of *structures* as set forth in this section. Heights of existing *structures* shall be as set forth on the official map of *building* heights in the historic districts.

A. If a proposed *building* has a parapet, the façade shall not be in excess of two (2) feet of the average of the height of the façades in the *streetscape*.

B. If the proposed *building* has a pitched roof, the ridge height of the proposed *building* shall not be in excess of two (2) feet of the average of the ridge height of the pitched roofs in the *streetscape*.

C. *Yard walls* and fences shall be limited to a height that does not exceed the average of the height of other *yard walls* and fences in the *streetscape*.

D. Pursuant to Section 14-7.4(C), the height of any other *structure* shall be limited to the allowable *building* height within the applicable *streetscape*, as defined in this section. (Ord. No. 2002-37 § 26)

E. The height and dimension of signage are set forth in Section 14-8.10(H).

F. The board may increase the allowable height for proposed *buildings* and additions located on a sloping site where the difference in the natural *grade* along the *structure's* foundation exceeds two (2) feet. In no case shall the height of a façade exceed four (4) feet above the allowable height of the applicable *streetscape* measured from natural or finished *grade*, whichever is more restrictive. This increase in height shall be constructed only in the form of *building* step-backs from the *street*.

(d) Pitch

If the determined *streetscape* includes over fifty percent of *buildings* with pitched roofs, the proposed *building* may have a pitched roof. A pitched roof is defined as a gable, shed, or *hipped roof*. The pitch of the roof shall match the predominant pitch extant in the *streetscape*.

(e) Scale

The height of a proposed *building* or addition, its façade length, and its roof form and pitch shall appear to be in proportion to the height, façade length, and roof form and pitch of *buildings* in the applicable *streetscape*, or the *building* on which the addition is proposed.

(f) Massing and Floor Step backs

The Board may require that upper floor levels be stepped back, to carry out the intent of this section; provided that the board in making such determinations shall take into account whether the height of the proposed *building*, *yard wall*, fence, or proposed step back of upper floor levels is in harmony with the massing of the applicable *streetscape* and *preservation* of the historic and characteristic visual qualities of the *streetscape*. The Board shall also require that the *publicly visible* façades of the *structure* be in conformance with Subsections 14-5.2(E) through (H), and in meeting those requirements, may require that different floor levels be stepped back.

(I) **Westside-Guadalupe Historic District**

(1) District Standards

Compliance with the following structural standards shall occur whenever those exterior features of *buildings* and other *structures* subject to public view from any public *street*, way, or other public place are erected, altered, or demolished:

(a) Slump block, stucco, brick, or stone shall be used as exterior *wall* materials. Wood and other materials may be used for details. Aluminum siding, metal panels, mirrored glass, and unstuccoed concrete block or unstuccoed concrete shall not be used as exterior *wall* materials;

(b) The color of stuccoed *buildings* shall predominantly be in browns, tans, local earth tones, and soft pastels. Surfaces of stone or brick shall be in the natural color. Entryways, and *portales* or *porches* may be emphasized by the use of white or other colors. Painting of *buildings* with a color that causes arresting or spectacular effects, or with bold repetitive patterns, or using *buildings* as signs is prohibited. Murals, however, are permitted and may be referred to the *city* arts board for an advisory recommendation.

(c) Roof form, *slope*, and shape. It is intended that *buildings* be designed to be "wall-dominated". "Wall-dominated" means that the *building's* geometry is more defined by *walls* than by roofs. *Buildings* with flat, gabled, shed, or *hipped roofs* can be designed as "wall-dominated" solutions and are allowed. The height of the roof above the *wall* shall be no greater than the height of the *wall*. Folded plate, hyperbolic, or mansard roofs are not allowed.

(d) The use of solar and other energy-collecting and conserving strategies is encouraged. The use of large, glazed areas on south-facing *walls* for trombe *walls* or other solar collectors, direct gain, or other energy-collecting purposes is allowed. When in view from any public *street*, way, or other public place, solar equipment shall be screened as follows:

(i) raising the parapet;

(ii) setting back from the edge of the roof;

(iii) framing the collector with wood;

(iv) in the case of pitched roofs, by integrating the collector into the pitch;

(v) in the case of ground solar collectors, by a *wall* or vegetation;

(vi) in the case of *wall* collectors, by enclosing by end or other *walls*;

(vii) other means that screen the collector or integrate it into the overall *structure*. Non-glare materials shall be used in solar collectors.

(e) Mechanical, electrical, telephone equipment, microwave satellite receiving dishes, and other obtrusive equipment shall be architecturally screened with opaque materials by raising the parapet, boxing in the equipment, or other appropriate means. The equipment shall be of a low profile to minimize the *screening* problems.

(f) *Walls* and fences shall be of brick, *adobe*, masonry, rock, wood, coyote fencing, or similar materials. Wrought iron fences and slump block *walls* are allowed. *Walls* of

unstuccoed concrete block, unstuccoed concrete, chain-link, metal wire, or similar materials are prohibited, except where the *wall* or fence is not in the *street* frontage.

(g) *Greenhouses*

(h) Attached *greenhouses* that front on the *street* shall give the appearance of being integrated into the *structure* of the *building* or of being a substantive addition rather than having a lean-to effect. The use of corrugated fiberglass or rolled plastic for the external surface of attached or freestanding *greenhouses* that front on the *street* is prohibited. *Greenhouses* with slanting sides shall be bracketed at the ends, and that *greenhouses* made from enclosed *porches* or *portales* maintain the shape of the *porch* or *portal*.

(i) *Porches* and *portales* are encouraged;

(j) When parking spaces are required for commercial or multi-family *residential buildings*, they shall be placed to the rear or side of the building.

(2) Walls; Fences; Solar Collectors; Administration

Applications for the erection, alteration, or demolition of *walls*, fences, and solar collectors and required submittals shall be reviewed by the planning and land use department. Approval, disapproval, or referral shall be indicated by the division on the *application* for the building *permit* and on each of the required submittals, all of which shall be signed by the division staff assigned to the review. The division shall report approvals, disapprovals, and referrals to the board at its next regular meeting as an informational item. (Ord. No. 2007-45 § 30; Ord. #2020-22, § 16)

Osage Design Studio
Richard Woodbury
1216 Vitalia Street
Santa Fe, NM 87505
505.629.5948
osagedesignstudio@yahoo.com

December 15, 2025 revised 12/30/25

Historic Preservation Division
Planning and Land Use Department
City Hall
200 Lincoln Avenue
Santa Fe, NM 87501

Project Number:	2025-011549-HDRB
Address:	527 Agua Fria Street, Santa Fe NM 87501
Owners:	NEIRIKA LLC
Building Status:	Contributing
UPC:	1-053-099-521-161
Parcel No.:	11266176

On behalf of the applicant NEIRIKA LLC, I am submitting a request for approval of an interior and exterior remodel of the subject structure and exceptions listed below. The property is located within the Guadalupe Historic District. The site has two existing residential structures. The subject structure is a tri-plex to be converted into a duplex located at the front of the property facing Agua Fria Street. The rear structure is not part of the scope of this request; no work planned on the rear structure.

Per the HDRB meeting December 9, 2025, the subject structure was designated as “contributing”. The primary facades were determined to be the south façade (except for the south facing façade of the existing garage offset to the rear) and the east façade.

Exterior work includes:

- Replacement of all of the windows and the majority of the exterior doors.
- The work includes stucco repair and a new stucco color coat.
- Removing and raising the roof along the north side (rear) of the structure.
- A 36 square foot addition in heated area.

Please see the attached plans for reference.

The roof has been recently replaced with a pre-finished red “clay tile” shaped roof system. In addition, the interior has received a non-structural demolition of interior partitions, cabinetry, and fixtures. This work was permitted with the City of Santa Fe. Interior work includes installing new interior partitions, bathroom fixtures, and kitchen fixtures & appliances.

Exception Requests

In general, per Chapter 14-5-2 (D), for all facades of contributing structures, architectural features, finishes, and details shall be repaired or restored rather than replaced. In addition, no additions are

permitted to primary facades. Exceptions are required to for multiple modifications to the primary facade. Exception requests must address the following criteria:

a. Do not damage the character of the district.
b. Are required to prevent a hardship to the applicant or an injury to the public welfare.
c. Strengthen the unique heterogeneous character of the City by providing a full range of design options to ensure that residents can continue to reside within the historic districts.

Each exception request is listed below with its corresponding response to the criteria.

1. Replace existing windows and selected exterior doors, including altering the size and location of fenestrations. The exception request includes removal of iron grilles on some of the windows and replacement of existing "diamond" gable vents. *14-5-2(D)(5)(a)(i)(ii)(iii): Historic windows shall be repaired or restored wherever possible. No new openings shall be made unless historic documentation supports its prior existence. No existing openings shall be closed*.

    a. *Do not damage the character of the district.*

        Response: The structure has been designated "contributing" and all facades are considered "primary". However, in the opinion of the Applicant, changes to the street facing public façade should take precedence. On the street facing façade, the changes involve window & door replacement in existing openings. No size changes are requested. No new openings or infilled openings are requested. Thus, the character of the district will be maintained. The most extensive work is proposed for the rear. This work will be hidden from the public view. Hence, the character of the district will be maintained.

    b. *Are required to prevent a hardship to the applicant or an injury to the public welfare.*

        Response: The exception request includes replacement of existing windows, replacement of doors, removal of iron grilles, replacement of the diamond gable vents, and new doors & windows in new openings on the north façade. As noted in the window assessment report, only a few of the windows are historic to the structure. The current window types vary. Many are single pane, non-insulated units or older insulated units that do not meet the current energy code. Replacement would allow for code compliance, increasing the comfort of the inhabitants. None of the doors are historic. Replacement will allow for units that function well and have a design congruent with the overall appearance of the remodeled structure. The existing iron grilles are not historic and inhibit maintenance access to the windows. The fixed glazed diamond gable vents are non-functioning. Code requires that attics be vented which new louvered metal vents, painted to match the fascia, will allow. As noted in the exception request below, the rear "lean to" addition does not meet code regarding ceiling height. By replacing windows and doors in existing and new openings, as well as raising the roof, allows for the spaces to be more efficiently utilized and provide code required life safety egress.

    c. *Strengthen the unique heterogeneous character of the City by providing a full range of design options to ensure that residents can continue to reside within the historic districts.*

        Response: The unique character of the City will be maintained as the proposed window & door replacement will provide a fresh, consistent, harmonious appearance. While it is common for individual structures to have different window and door sizes, configurations,

finishes, etc., it is not pleasing for these structures to have units in varying degrees of maintenance.

In summary, the proposed work, including the requested exceptions, will provide an aesthetically pleasing and modern efficient living space without any compromise to the integrity of the original structure or have any negative impact on the structure contributing to the historic fabric of the neighborhood.

Please contact me if you have any questions or require additional information.

Sincerely,

Richard Woodbury

Richard Woodbury
Osage Design Studio

Attachments: Preliminary Zoning Review Worksheet (PZR) – sent prior
24x36 drawing set, 6 sheets
Property photographs
Window Assessment – sent prior
Exterior Finish Schedule
NM Historic Building Inventory Report – sent prior

Finish Schedule:

Item / Material:	Color:	Notes:
Exterior Stucco	Match existing color	Patch & repair. New color coat.
Fascia Trim	Match existing color	Pre-finished metal and wood fascia & wood trim. Repair and repaint wood trim
Roofing	Match existing type & color	Replace at north modifications
Windows	Pella "Bright White"	New windows
Exterior Doors	"White" to match windows	New exterior doors to be either painted wood or clad units provided by window manufacturer.

Proposed Windows: The proposed replacement would be Pella wood windows with pre-finished exterior cladding and simulated divided lights. The exterior color to be "Bright White". See the Plans for window location, size, type, and grille pattern.

Bright White

7/8" Ogee Integral Light Technology

Existing wood and pre-finished metal fascia

Existing stucco

Existing pre-finished metal roofing with "clay tile" profile

Photographs of interior along rear façade (north wall). White pole set at 6’-0” (disregard numbers on pole). Per code, minimum ceiling height of a habitable space is 7’-0”

Photo on left in area of proposed Bedroom-2. Approximate bearing to beams 5’-8”.

Photo on right in area of proposed rear hallway. Approximate bearing is 6’-10”. However, finish floor will be raised approximately 6” to match floor level of remainder of residence.

527 Agua Fria Street
Existing Exterior Photographs
12/15/25

1 - South Façade (facing Agua Fria)

2 - South Façade showing west face of structure

3 - South Façade (facing Agua Fria)

4 - South Façade (facing Agua Fria)

5 - East Façade (southeast corner)

6 - East Façade

7 - North Façade (northeast corner)

8 – North Facade

9 - North Facade

10 - North Façade

11 - North Façade

12 - North Façade (northwest corner)

City of Santa Fe Chapter 14 Land Development Code	
Owner	NEIRIKA LLC
Address	527 Agua Fria Street, Santa Fe NM 87501
UPC	1-053-099-521-161
Tax Parcel	1126 6176
Legal	Guadalupe Neighborhood Parcel 284, T17N R9E S23
Zoning	R-21
Historic District	Westside Guadalupe Historic District
Hist. Bldg. Status	Contributing
Flood Plain	Not applicable
Archeological	Historic Downtown Archeological Review District
Escarpment	Not applicable
Mountain	Not applicable
Density	21 dwelling units per acre
Min. Lot Size	3,000 SF minimum, 2,000 SF with common open space
Existing Lot Size	0.418± acres
Max. Height	24' maximum height for residential structures, within 10' of side or rear property no portion of any story above ground level shall be higher than 14.0'. ***Maximum height might be superseded by historic***.
Existing Height	18'-8"± (no proposed change)
Setbacks (minimum yard requirements)	Front: 7' (20' for front facing garage) Side: 5' Rear: 15' or 20% of average lot depth, whichever is less
Maximum Lot Coverage:	40% maximum for single family or multi-family of fewer than 6 units. 40% maximum for multi-family with 6 or more units. May increase to 55% maximum if private open space is provided. (Lot coverage is the total area of structures on a lot in relation to lot area). For residential development, the portion of a lot occupied by easements for private roads and lot access driveways is excluded from the lot area. Lots smaller than one acre, common open space, fire access roads & other facilities intended primarily for other lots excluded from lot area.
Existing Lot Coverage:	23.4%
Proposed Lot Coverage:	23.4% (no change)
Open Space	No minimum open space required for single family residence except as provided by setbacks. Open space required to increase lot coverage per 14-7.5: Provide a minimum of 50% of total gross floor area (including 2nd floor). Minimum dimension of 12' (and not less than 4' / 40 SF for balconies. Portals, porches, roof decks, and balconies can contribute to the amount required. **NOT REQUIRED**: site meets maximum allowed lot coverage.

Accessory Structures	Generally, cannot be used as an accessory dwelling – may have a half bathroom (sink & toilet) or kitchen but not both.
Parking Residential	Dwelling Unit: 2 spaces per unit Attached Dwelling Unit (2-5 units): 2 spaces per dwelling unit Attached Dwelling Unit (over 5 units, less than 800 SF): 1 assigned space and 0.25 unassigned space per DU Attached Dwelling Unit (over 5 units, 800-1200 SF): 1 assigned space and 0.5 unassigned space per DU Attached Dwelling Unit (over 5 units, over 1200 SF): 1 assigned space and 1.0 unassigned space per DU Accessory Dwelling Unit: 1 space if ADU < 1,000 SF; otherwise 2 spaces Accessory Structures: parking not required
Required Parking Spaces	3 offstreet parking spaces
Existing Parking Spaces	6 off street parking spaces provided on lot for subject lot (1 in garage).
Parking Space Size	Standard pull in: 8.5' x 19', 23' drive aisle Small car: 7.6' x 15', 20' drive aisle. Parking lots with 10 or more spaces may have up to 20% of total req'd spaces designated as small car. Parallel: 8.5' x 23' Parking lots with less than 40 spaces may be gravel.



Vicinity Map

North



Existing Site Plan

Scale: 1" = 10'-0"

True North

0' 10' 20'

Existing Lot Coverage:

Lot Size: 18,208 SF

Front Structure: 3,017 SF
Rear Structure: 1,250 SF

Lot Coverage: 23 43%

Sheet Index:

C-1 Existing Site Plan, Project Information
C-2 Proposed Site Plan
A-1 Existing Floor Plan
A-2 Proposed Remodel Floor Plan
A-3 Existing & Proposed Exterior Elevations
A-4 Existing & Proposed Exterior Elevations

Scope of Work: Exterior and Interior Remodel of an existing residential structure

Issued for City of Santa Fe Historic Division Review

Osage Design Studio
1216 Vitalia Street
Santa Fe, NM 87505
osagedesignstudio@yahoo.com
505.629.5948

Renovation of an Existing Residential Structure

NIERIKA LLC

527 Agua Fria Street, Santa Fe NM 87501

Existing Site Plan
Project Information

PRELIMINARY
Not for Construction
HDRB Review Only

12/15/25

2025-011549-HDRB

C-1

Sheet 1 of 6



02 Gate Detail

Scale: 1/2" = 1'-0"



01 Coyote Fence Elevation

Scale: 1/4" = 1'-0"



Proposed Site Plan

Scale: 1" = 10'-0"

Parking Requirements:

Single Family Residence: 2 spaces
ADU less than 1,000 SF: 1 space

Retention Pond Calculations:

RE: City of Santa Fe Land Development Code Section 14-8 2 (E) (2)

The minimum amount of storm water to be retained on site to be the equivalent to the total amount of impervious surface (SF) multiplied by 0 16 equals the cubic feet (CF) of retention

New impervious surface (ADU Bathroom):	36 SF
Total new impervious area:	36 SF

Total required ponding = 36 SF x 0 16 = 5 76 CF minimum
(5 76 CF x 7 48 = 43 gallons minimum)

The project is EXEMPT from storm water retention as the projects meets the exemption criteria in COSF LDC Section 14-8 2 (B) (2): less than 250 SF of total area disturbed; no disturbed slopes greater than 10%; no change to existing site drainage patterns that would increase runoff leaving the site; and adequate erosion control provided

Proposed Lot Coverage:

Lot Size: 18,208 SF

Front Structure: 3,053 SF
Rear Structure: 1,250 SF

Lot Coverage: 23 63%

Osage Design Studio
1216 Vitalia Street
Santa Fe, NM 87505
osagedesignstudio@yahoo.com
505.629.5948

Renovation of an Existing Residential Structure

NIERIKA LLC

527 Agua Fria Street, Santa Fe NM 87501

Proposed Site Plan

PRELIMINARY
Not for Construction
HDRB Review Only

12/15/25

C-2

Sheet 2 of 6



All Dimensions Approximate and subject to field verification.

Existing Floor Areas - Unit 3:

Heated:	727 SF
Non-heated (garage):	506 SF
Portals:	51 SF
Total Heated:	727 SF
Total Roofed:	1,284 SF

Existing Floor Areas - Unit 2:

Heated:	993 SF
Non-heated (garage):	0 SF
Portals:	33 SF
Total Heated:	993 SF
Total Roofed:	1,026 SF

Existing Floor Areas - Unit 1:

Heated:	625 SF
Non-heated (garage):	0 SF
Portals:	82 SF
Total Heated:	625 SF
Total Roofed:	707 SF

Total Existing Floor Areas:

Heated:	2,345 SF
Non-heated (garage):	506 SF
Portals:	166 SF
Total Heated:	2,345 SF
Total Roofed:	3,017 SF

Existing Floor Plan

Scale: 1/4" = 1'-0"

0' 5' 10'

Plan North

Osage Design Studio
1216 Vitalia Street
Santa Fe, NM 87505
osagedesignstudio@yahoo.com
505.629.5948

Renovation of an Existing Residential Structure

NIERIKA LLC

527 Agua Fria Street, Santa Fe NM 87501

Existing Floor Plan

PRELIMINARY
Not for Construction
HDRB Review Only

12/15/25

A-1

Sheet 3 of 6



Total Existing Floor Areas:

Heated:	2,345 SF
Non-heated (garage):	506 SF
Portals:	166 SF
Total Heated:	2,345 SF
Total Roofed:	3,017 SF

Total Proposed Floor Areas:

Heated:	36 SF
Non-heated (garage):	0 SF
Portals:	0 SF
Total Heated:	36 SF
Total Roofed:	36 SF

Total Adjusted Floor Areas:

Heated:	2,345 SF
Non-heated (garage):	0 SF
Portals:	166 SF
Total Heated:	2,887 SF
Total Roofed:	3,053 SF

Wall Legend:

- Existing wood framed construction
- New CMU / masonry construction
- New wood framed construction

Wall Types:

- 8 — 2 x 8 wood studs
- 6 — 2 x 6 wood studs
- 4 — 2 x 4 wood studs

Proposed Floor Plan

Scale: 1/4" = 1'-0"

Plan North

Osage Design Studio
1216 Vitalia Street
Santa Fe, NM 87505
osagedesignstudio@yahoo.com
505.629.5948

Renovation of an Existing Residential Structure

NIERIKA LLC

Guadalupe Neighborhood Parcel 284
527 Agua Fria Street, Santa Fe NM 87501

Proposed Remodel Plan

PRELIMINARY
Not for Construction
HDRB Review Only

12/15/25

A-2



Existing Front (South) Elevation

Scale: 1/4" = 1'-0"



Proposed Front (South) Elevation

Scale: 1/4" = 1'-0"



Proposed Right Side (East) Elevation

Scale: 1/4" = 1'-0"



Existing Right Side (East) Elevation

Scale: 1/4" = 1'-0"

Osage Design Studio
1216 Vitalia Street
Santa Fe, NM 87505
osagedesignstudio@yahoo.com
505.629.5948

Renovation of an Existing Residential Structure

NIERIKA LLC

527 Agua Fria Street, Santa Fe NM 87501

Exterior Elevations

PRELIMINARY
Not for Construction
HDRB Review Only

12/15/25

A-3

Sheet 5 of 6



Existing Rear (North) Elevation

Scale: 1/4" = 1'-0"



Proposed Rear (North) Elevation

Scale: 1/4" = 1'-0"



Proposed Left Side (West) Elevation

Scale: 1/4" = 1'-0"



Existing Left Side (West) Elevation

Scale: 1/4" = 1'-0"

Osage Design Studio
1216 Vitalia Street
Santa Fe, NM 87505
osagedesignstudio@yahoo.com
505.629.5948

Renovation of an Existing Residential Structure

NIERIKA LLC

527 Agua Fria Street, Santa Fe NM 87501

Exterior Elevations

PRELIMINARY
Not for Construction
HDRB Review Only

12/15/25

A-4

Sheet 6 of 6

RPA & Associates, LLC.

PRESERVING OUR HISTORY

508 Ortega Rd NW Los Ranchos de Albuquerque, NM 87114
P.O. Box 10328 Albuquerque, NM 87184
505-379-7900
rpahistoric@gmail.com

TO Osage Design Studio
1216 Vitalia Street
Santa Fe, NM 87505
osagedesignstudio@yahoo.com

JOB	DATE
527 AGUA FRIA, SANTA FE, NM 87501	8/15/2025

LOCATION	DESCRIPTION
SOUTH	
A	63 x 61 HORIZONTAL SLIDER 1-LT CLAD – RED JELD-WEN 2009
B	63 x 61 HORIZONTAL SLIDER 1-LT CLAD – RED JELD-WEN 2009
DR #1	36 x 80 LH – FG HC/6-PANEL 2018
WEST	
C	63 x 61 HORIZONTAL SLIDER 1-LT CLAD – RED JELD-WEN 2009
D	63 x 61 HORIZONTAL SLIDER 1-LT CLAD – RED JELD-WEN 2009
E	33 x 26 – 2 LR 1W2H WOOD NON-HISTORIC/WIDER DIVIDED LITE BAR
SOUTH	
F	48 x 59 – 2 LR 2W4H INSWING CASEMENT WOOD HISTORIC (2-24")
G	48 x 59 – 2 LR 2W4H INSWING CASEMENT WOOD HISTORIC (2-24")
H	75 x 59 – 3 LSR 2W4H INSWING CASEMENT WOOD HISTORIC (3-25")
DR #2	36 x 81 LH ARCH 1-GLASS FLASH 1 ¾ SC BIRCH
EAST	
I	23 x 55 RH 2W4H INSWING CASEMENT WOOD HISTORIC
SOUTH	
DR #3	36 x 82 ½ RH 3W5H 15" BOTTOM RAIL WOOD BEAD SIMPSON DOOR

JOB	DATE
527 AGUA FRIA, SANTA FE, NM 87501	8/15/2025

LOCATION	DESCRIPTION
EAST	
J	48 x 59 – 2 LR 2W4H INSWING CASEMENT WOOD HISTORIC (2-24")
SOUTH	
K	11 x 20 1-LT FIXED STOPPED IN GLASS
EAST	
L	38 x 38 LH 3W3H INSWING CASEMENT WOOD HISTORIC
NORTH	
M	24 x 24 HORIZONTAL SLIDER WHITE VINYL PAINTED RED OBSCURE
N	34 x 81 DOUBLE HUNG 2W1H/2W1H IN SEGMENT HEAD WOOD HISTORIC
O	28 x 64 DOUBLE HUNG 2W2H/2W2H WOOD – WIDER MUTTON
EAST	
P	67 x 38 TWIN LR 3W3H INSWING CASEMENT SLANT CUT TOP SASHES (2-33 ½") HISTORIC
NORTH	
Q	15 x 36 L 2W3H INSWING CASEMENT WOOD HISTORIC
DR #4	36 x 80 RH INSWING 5-HORIZONTAL PANEL CUT DOG DOOR STRUCTURAL ISSUE SIMPSON DOOR CUT DOWN
GABLE DOOR	32 x 44 RH OUTSWING PLANK – WOOD 2 x 6
DR #5	30 x 80 LH 3W3H/2-PANEL SIMPSON WOOD DOOR NON-HISTORIC
R	24 x 24 HORIZONTAL SLIDER OBSCURE 1-LT BRONZE ALUMINUM
S	36 x 36 HORIZONTAL SLIDER 1-LT BRONZE ALUMINUM 1995
T	36 x 36 HORIZONTAL SLIDER 1-LT BRONZE ALUMINUM 1995
WEST	
U	24 x 24 AWNING 1-LT CLAD – RED JELD-WEN 2009
NORTH	
DR #6	24 x 80 LH OUTSWING 6-PANEL SIMPSON VENEER DOOR 2000
DR #7	9 x 7 GARAGE DOOR - MISSING

JOB	DATE
527 AGUA FRIA, SANTA FE, NM 87501	8/15/2025

LOCATION	DESCRIPTION
2 GABLE VENTS	
EAST	
V	4 - DIAMONDS
SOUTH	
W	4 - DIAMONDS

In closing, my professional opinion is as follows:

Windows F, G, H, I and J are historic and restorable.

Window N is historic however not part of the original house.

Window O is historic however unrestorable.

Window A, B, C, D, E, K, L, M, P, Q, R, S, T, V and north gable door are non-historic.

Doors #1, #2, #3, #5 and #6 are non-historic.

East and south gable vents should be vents however have glass on the inside and not venting to facilitate with attic air flow.

Door #7 is missing.

Door #4 is historic however not of the original house. The unit has cut stiles and rails. The unit is lacking in structural integrity.

If you have any questions, please contact me at 505-379-7900.

Assessment prepared by: *Ra N. Patterson*

RPA & ASSOCIATES, LLC | WINDOW & DOOR CONDITION AND INTEGRITY CODES

CODE	CONDITION AND INTEGRITY CODES
P = PREMIUM	EXTERIOR FINISHES AND SASH, FRAME, AND CASING MEMBER IN PREMIUM OR VERY GOOD CONDITION.
	PUTTY GLAZE INTACT.
	ONLY COSMECTIC TOUCH-UP, IF NEEDED.
S = SATISFACTORY	EXTERIOR FINISHES FADING AND WORN IN PLACES BUT STILL ADHERED TO THE WINDOW MEMBERS.
	PUTTY GLAZING CRACKING BUT INTACT AND ALL SASHES, FRAMES, AND CASING MEMBER WITH LESS THAN 30% –
	40% DETERIORATION.
F = FAIR	EXTERIOR FINISHES HAVE CRACKED & PEELED. MISSING TO BARE SURFACE.
	PUTTY GLAZING CRACKING AND MISSING IN 30% – 40% OF THE SASHES. ALL SASHES, FRAMES, AND CASINGS HAVE
	SOME MEMBERS 30% – 40% COMPLETELY DETERIORATED.
U = UNSATISFACTORY	EXTERIOR FINISHES HAVE COMPLETELY DETERIORATED.
	PUTTY GLAZING MOSTLY MISSING. ALL SASHES, FRAMES, AND CASING MEMBERS HAVE MORE THAN 30% - 40%
	DETERIORATION, BEYOND REPAIR.

NOTES:

LABEL	WINDOW & DOOR DESCRIPTION	CONDITION & INTEGRITY CODE	HISTORIC/NON-HISTORIC - AGE
A	63 x 61 HORIZONTAL SLIDER 1-LT CLAD RED/WOOD	P	**NON-HISTORIC** – JELD-WEN (2009)
B	63 x 61 HORIZONTAL SLIDER 1-LT CLAD RED/WOOD	P	**NON-HISTORIC** – JELD-WEN (2009)
DR #1	36 x 80 LH FIBERGLASS HALF CIRCLE 6-PANEL	P	**NON-HISTORIC** – THERMA TRU (2018)
C	63 x 61 HORIZONTAL SLIDER 1-LT CLAD RED/WOOD	P	**NON-HISTORIC** – JELD-WEN (2009)
D	63 x 61 HORIZONTAL SLIDER 1-LT CLAD RED/WOOD	P	**NON-HISTORIC** – JELD-WEN (2009)
E	33 x 26 – 2 LR INSWING CASEMENT ALL WOOD 1W2H (2-17")	F	**NON-HISTORIC** – DIFFERENT SILL, WIDER DIVIDED LITE BARS, SASHES MADE MECHANICALLY (1985 OR NEWER)
F	48 x 59 – 2 LR INSWING CASEMENT ALL WOOD 2W4H (2-24")	F	**HISTORIC** – RESTORABLE, SCREENS ARE NOT RESTORABLE
G	48 x 59 – 2 LR INSWING CASEMENT ALL WOOD 2W4H (2-24")	F	**HISTORIC** – RESTORABLE, SCREENS ARE NOT RESTORABLE
H	75 x 59 – 3 SLS INSWING CASEMENT ALL WOOD 2W4H (3-25")	F	**HISTORIC** – RESTORABLE, SCREENS ARE NOT RESTORABLE
DR #2	36 x 81 LH ARCH TOP W/1-PEEP GLASS 1 ¾ SC BIRCH	S	**NON-HISTORIC** – 1 ¾ SC BIRCH CUT OUT AND ARCHED VENEERED (1990)
I	23 x 55 RH INSWING CASEMENT 2W4H ALL WOOD	F	**HISTORIC** – RESTORABLE, THE SCREENS ARE NOT RESTORABLE
DR #3	36 x 82 ½ RH 3W5H ALL WOOD GLASS DOOR W/15" BOTTOM RAIL	S	**NON-HISTORIC** – SIMPSON DOOR (1995)

NOTES:

LABEL	WINDOW & DOOR DESCRIPTION	CONDITION & INTEGRITY CODE	HISTORIC/NON-HISTORIC – AGE
J	48 x 59 – 2 LR INSWING CASEMENT ALL WOOD 2W4H (2-24")	F	**HISTORIC** – RESTORABLE, THE SCREENS ARE NOT RESTORABLE **NON-HISTORIC** – WROUGHT IRON
K	11 x 20 FIXED 1-LT ARCHED GLASS STOPPED IN STUCCO	U	**NON-HISTORIC** – WROUGHT IRON
L	38 x 38 LR INSWING CASEMENT ALL WOOD 3W3H	F	**NON-HISTORIC** – SASH & JAMB HAVE SIGNS OF HINGES; ORIGINAL UNIT WAS A TWIN NOT A SINGLE SCREEN (NON-RESTORABLE) THE WROUGHT IRON IS ALSO **NON-HISTORIC**
M	24 x 24 HORIZONTAL SLIDER WHITE VINYL PAINTED RED ON THE EXTERIOR	S	**NON-HISTORIC** – (2001)
N	34 x 81 DOUBLE HUNG SEGMENT INSIDE RECTANGLE UPPER SASH WOOD 2W1H/2W1H	F	**HISTORIC** – NOT OF THE ORIGINAL HOUSE, ADDED AT A LATER DATE
O	28 x 64 DOUBLE HUNG ALL WOOD 2W2H/2W2H	U	**HISTORIC** – ROTTED BEYOND 30 TO 40%
P	67 x 38 – 2 LR INSWING CASEMENT ALL WOOD 3W3H (2-33 ½")	F	**NON-HISTORIC** – BARN SASHES CUT TO SLANT TO FOLLOW ROOF (1996)
Q	15 x 36 L INSWING CASEMENT ALL WOOD 2W3H	F	**NON-HISTORIC** – BARN SASH (1996)
DR #4	36 x 80 RH INSWING DOOR 5-HORIZONTAL PANELS ALL WOOD	U	**HISTORIC** – HOWEVER NOT PART OF THE ORIGINAL HOUSE. ALL DOORS ARE 2-PANEL CUT, ONE CROSS RAIL CUT, RESULTING IN WEAK STRUCTURAL INTEGRITY

NOTES:

LABEL	WINDOW & DOOR DESCRIPTION	CONDITION & INTEGRITY CODE	HISTORIC/NON-HISTORIC – AGE
NORTH GABLE DOOR	32 x 44 OUTSWING PLANK DOOR	F	**NON-HISTORIC** – GUN NAILS USED (1989)
DR #5	30 x 80 LH INSWING DOOR 3W3H/2-PANEL	F	**NON-HISTORIC** – SIMPSON (1989)
R	24 x 24 HORIZONTAL SLIDER BRONZE ALL ALUMINUM INSULATED GLASS OBSCURE	S	**NON-HISTORIC** – ALENCO (1995)
S	36 x 36 HORIZONTAL SLIDER BRONZE ALL ALUMINUM INSULATED GLASS OBSCURE	S	**NON-HISTORIC** – ALENCO (1995)
T	36 x 36 HORIZONTAL SLIDER 1-LT BRONZE ALUMINUM	S	**NON-HISTORIC** – ALENCO (1995)
U	24 x 24 AWNING 1-LT CLAD RED/WOOD	P	**NON-HISTORIC** – JELD-WEN (2009)
DR #6	24 x 80 LH OUTSWING 6-PANEL WOOD DOOR	S	**NON-HISTORIC** – SIMPSON DOOR (2009)
DR #7	9 x 7 GARAGE DOOR	U	DOOR IS MISSING

NOTES:

LABEL	WINDOW & DOOR DESCRIPTION	CONDITION & INTEGRITY CODE	HISTORIC/NON-HISTORIC – AGE
GABLE VENTS			
EAST			
V	4 – DIAMOND GLASS	F	**HISTORIC** – THERE IS A PLATE GLASS ON THE BACK SIDE OF CUT HOLES INTO THE STUCCO (NOT VENTS, HOWEVER THERE SHOULD BE VENTS FOR VENTING THE ATTIC)
SOUTH			
W	4 – DIAMOND GLASS		**HISTORIC** – THERE IS A PLATE GLASS ON THE BACK SIDE OF CUT HOLES INTO THE STUCCO (NOT VENTS, HOWEVER THERE SHOULD BE VENTS FOR VENTING THE ATTIC)

NOTES:



V - GABLE

W - GABLE

Existing Floor Plan

Scale: 1/8" = 1'-0"

0' 5' 10'

Plan North

Osage Design Studio
1216 Vitalia Street
Santa Fe, NM 87505
osagedesignstudio@yahoo.com
505.629.5948

Renovation of an Existing Residential Structure

NIERIKA LLC

527 Agua Fria Street, Santa Fe NM 87501



Existing Front (South) Elevation

Scale: 1/8" = 1'-0"



Existing Right Side (East) Elevation

Scale: 1/8" = 1'-0"

Osage Design Studio
1216 Vitalia Street
Santa Fe, NM 87505
osagedesignstudio@yahoo.com
505.629.5948

Renovation of an Existing Residential Structure

NIERIKA LLC

527 Agua Fria Street, Santa Fe NM 87501



Existing Rear (North) Elevation

Scale: 1/8" = 1'-0"



Existing Left Side (West) Elevation

Scale: 1/8" = 1'-0"

Osage Design Studio
1216 Vitalia Street
Santa Fe, NM 87505
osagedesignstudio@yahoo.com
505.629.5948

Renovation of an Existing Residential Structure

NIERIKA LLC

527 Agua Fria Street, Santa Fe NM 87501

South Elevation
Window
A

South Elevation
Window
B

South
Elevation
Door #1

West Elevation
Window C

West Elevation
Window D

West
Elevation
Window
E

South Elevation
Window
F

South Elevation
Window
G

South Elevation
Window H

South Elevation
Door #2

East Elevation
Window
I

South
Elevation
Door
#3

East Elevation
Window
J

Elevation
Window
K

East
Elevation
Window
L

North
Elevation
Window
M

North
Elevation
Window
N

North Elevation Window O

East
Elevation
Window
P

North
Elevation
Window
Q

North
Elevation
Door# 4

North
Elevation
Gable door

North Elevation
Window
R

North
Elevation
Door
#5

North
Elevation
Window
S

North
Elevation
Window
T

West Elevation
Window
U

North
Elevation
Door
#6

North
Elevation
Door
#7
Missing

East
Elevation
Diamond
Vent/glass
V

South
Elevation
Diamond
Gable
Vent/glass
W

527 Agua Fria
South Elevation

527 Auga Fria

2

2

3

527

527
2
527

527

527 Agua Fria
ss 9 Rael Ln.
Comments Historic

[redacted]

k. **2025-011549-HDRB, 527 Agua Fria St. Units 1, 2, & 3**, Westside-Guadalupe Historic District, Significant, Osage Design Studio, agent for Neirika, LLC, owner, requests a status review with primary façade designation, if applicable.

Ms. McCulley presented the case and staff recommendation. Staff recommended that the historic structure be maintained for its association with events or persons that are important on a local level and the historic integrity of the building, with all facades as primary, per 14-5.2(C) designation of significant, contributing, or noncontributing status within historic districts.

Zoom session went offline at 12:00AM

Delores Vigil, Santa Fe, New Mexico, was sworn in. Commented on project.

Public Comment:
Unknown of any public comment. No recording.

Board Action:
Unknown of who made the motion and seconded, no recording. The Historic Districts Review Board moved in case 2025-011549-HDRB at 527 Agua Fria St. Units 1, 2, & 3 to designate the residence as contributing with the south facades R1 and R3 and the east Facades R2, R4, R5 and R6 as primary, including the portal on the southeast corner, the alcove over the front south facing exterior, including all windows and doors, and excluding any non-historic materials. The motion passed. No recording of the vote.

[redacted]

City of Santa Fe

Land Use Department
200 Lincoln Ave.
Santa Fe, New Mexico 87504-0909

PROJECT DESC: 2025-011549-HDRB, 527 Agua Fria St. units 1, 2, & 3, Westside-Guadalupe Historic District, Significant, Osage Design Studio, agent for Neirika, LLC, owner, requests a status review with primary façade designation, if applicable.

CASE NUMBER: 2025-011549--HDRB

PROJECT TYPE: Historic Status Review

LOCATION: 527 AGUA FRIA ST 1
Santa Fe, NM 87501

CONTACTS:

Applicant	DOLORES VIGIL	P.O. BOX 1835 SANTA FE, 87504
Applicant	Osage Design Studio	1216 Vitalia Street 1216 Vitalia Street Santa Fe, NM 87505

BOARD ACTION

This is to certify that the Historic Districts Review Board (HDRB) acted on your request at their hearing on Dec 09, 2025. The decision of the Board was to designate the residence as contributing with the south façades R1 and R3 and the east façades R2, R4, R5, and R6, including the portal in the southeast corner and the alcove over the front south-facing exterior door, including all windows and doors, but excluding any non-historic materials.

For further information please call 505-955-6605.

Sincerely,

Lani McCulley



NOTE: Applicant can use this action letter to apply for construction permit, but the permit shall not be released until the end of the appeal period which starts on the date of filing of the Findings and Conclusions in the City Clerk's office (SFCC 14-3.17(D)). Your permit will be denied if any changes on plans that were not approved by the HDRB or if conditions of approval are not met. **Please attach copies of this letter to all sets when submitting for construction permits.**

Ver. 12 1/14/2020

City of Santa Fe, New Mexico

memo

DATE: December 9, 2025

TO: Historic Districts Review Board Members

VIA: Heather Lamboy, Planning & Land Use Department Director HLL
Maggie Moore, Assistant Land Use Director *MRM*
Gary Moquino, Historic Preservation Division Manager GM

FROM: Lani McCulley, Senior Planner, Historic Preservation Division LgM

2025-011549-HDRB, 527 Agua Fria St. units 1, 2, & 3, Westside-Guadalupe Historic District, Significant, Osage Design Studio, agent for Neirika, LLC, owner, requests a status review with primary façade designation, if applicable.

REFERENCE ATTACHMENTS (Sequentially):

CITY SUBMITTALS

__x__ District Standards & yard wall & fence standards.

__x__ Historic Inventory Form

__x__ Zoning Review Sheet

__x__ Other: ownership history documents

APPLICANT SUBMITTALS

__x__ Proposal Letter

__x__ Site Plan/Floor Plan

__x__ Elevations

__x__ Photographs

__x__ Other: 2025 HCPI

STAFF RECOMMENDATION:

Staff recommends the historic status of the structure be maintained as significant for its association with events or persons that are important on a local level and the historic integrity of the building, with all facades as primary, per 14-5.2(C) Designation of Significant, Contributing or Noncontributing Status Within Historic Districts.

Sample motions:

One motion for the status and primary façade designation is required.

a. In case 2025-011549-HDRB, for 527 Agua Fria Units 1, 2, and 3, to maintain status of the residence, as significant, designating all facades as primary.
b. In case 2025-011549-HDRB, for 527 Agua Fria Units 1, 2, and 3, designate/downgrade the main residence as contributing and designate facades (South (R13, R1 (including/excluding the portal, and R3 (including/excluding the east portal and R2 east façade), East (R2 (including/excluding the portal), R4, R5, R6, R8 (on the north elevation), and/or R10 (on the north elevation)), North (R7, R9, and/or R11), West (R12 (garage wall), R14 (residence wall)) as primary façade(s).
c. In case 2025-011549-HDRB, for 527 Agua Fria Units 1, 2, and 3, downgrade/designate the main residence to non-contributing.

The property lies within the Historic Downtown Archaeological Review District. See Chapter 14, SFCC, Article 14-3.13(B)(1). There may be archaeological concerns associated with this project, and archaeological clearance may be required.

Figure 1: Site Location

BACKGROUND & SUMMARY:

Streetscape:
The streetscape for this property runs along Agua Fria from just east of De Fouri Street to Romero Street. The street is lined with sidewalks with properties having low stucco yard walls and a couple of rock yard walls. Some of the yard walls are topped with metal fencing. There is a single chain link fence, and to the west of Closson Street, there are some coyote fences. The yard walls and

fences often feature wooden pedestrian gates. There are no vehicle gates. The average is forty-three inches in height, which is the maximum allowable height.

The properties tend to be narrow and long, with multiple buildings on most sites. The buildings vary in distance from the street, with some right up to the sidewalk and others set back twenty to thirty feet from the street. The buildings are a combination of residential and commercial spaces.

The buildings are a variety of Spanish Pueblo Revival, Territorial, and Vernacular style flat roof homes, as well as a variety of pitched roof homes. The homes are in lighter brown stuccos with white, brown, and blue trims and natural wood elements. There are several properties with metal elements as well.

Figure 2: Street View of Residence

Site Description:
The 3,017 sq. ft. multi-family residence at 527 Agua Fria units 1, 2, and 3 sits on a 0.418-acre lot and was constructed between 1908 and 1912. While the GIS map shows the residence as significant to the Westside-Guadalupe Historic District, the Historic Cultural Properties Inventory from 1997 states that the HCPI was not adopted, and there is no case for status on this property since then. If the property was not reviewed for status in 1997 or since, the property would be listed as contributing, as it was before 1997. Therefore, the residence is coming forward for clarification of status.

According to the 1997 HCPI, the residence has been listed on the national register since 1997 and as a contributing resource to the Guadalupe Neighborhood in the National Register of Historic Places nomination of the district in 1999. The accessory dwelling unit at the rear of the lot is listed as non-contributing, but is not subject to this case. According to the 2025 HCPI, the structure is located on a 1908 Sanborn Fire Insurance Map and is not listed on the state register or the national register.

Per the 1997 HCPI, the residence is constructed in a Mediterranean-style architecture with thick, stucco-plastered walls, red-tiled roofs, and ornate archways, with large, symmetrical facades designed for warmth and indoor-outdoor living. The 2025 HCPI calls this a New Mexico

Vernacular style; otherwise, the descriptions of the existing residence are the same. However, there are differences in the history of the structure's construction.

The roof is a red metal tile roof with gables of various heights, gable horns, and exposed rafters. The roof heights vary, with the lowest at 7'-10" and the highest at just under 20'-0". According to the 1997 HCPI, the roof was changed to the existing tile roof in 1920-1925. According to the 2025 HCPI, *"the original roof was a flat roof with drainage to the north. At some point, a gabled roof was added, raising the elevations of the residence. It is not evident if this was a clay tile roof, but it now has a metal roof simulating a tile roof. The cross-gable roof is offset. The lower metal roofs covering the front porches and side and back additions have a combination of metal tile and standing seam. The roof over the garage and connector is a low-slope standing-seam metal roof."*

The walls are concrete and stucco in light tan, most windows are 8-lite wood casements in pairs and trios, and a few picture windows. The doors are wood, with the front south door being curved to match the curve in the portal. The south portal has a gable roof with a round arched opening. The southeast corner portal has a shed roof and stucco piers. The yard wall along the street is low stucco with a wood pedestrian gate, and the rear fencing is a 6'-0" high plank wood fence.

According to the 1997 HCPI, the structure has had few alterations since its construction in 1912. The roof was changed in 1920-1925. The diamond vents had glass installed behind them at an unknown time. The previous garage was connected to the main structure with an addition, which is understood to be the 1984 northeast addition under case H-84-343, though the file is no longer available for verification. However, it does show in the 1998 Sanborn map provided in the 2025 HCPI. The roof was approved to be replaced in 2024.

According to the 2025 HCPI, *"The original house was built sometime before 1908. An addition was constructed at the rear of the house (northeast side) sometime after 1908 and before 1913. A much larger addition was constructed on the west side of the house sometime after 1913 and before 1921. The new southwest corner of the house is constructed of adobe. A covered front porch was added at the southeast corner of the house. Another large addition was added to the back of the house, possibly an enclosed back porch with a lower roof. A separate garage was added to the west and access to a cellar on the east side of the house sometime after 1921 and before 1930. It is estimated that the double gable roof was added after 1930, and a small restroom addition was added at the top of the cellar stair on the northeast corner of the house."*



Figure 3: Sanborn Maps from the 2025 HCPI

While the HCPIs do not match, they do both conclude that the residence is listed in the Santa Fe Historic District State Register from September 29, 1972 (State Register #260) and to the National Register from July 23, 1973 (National Register # 73001150), and is a contributing structure to the Westside-Guadalupe Historic listing and the additions to the structure are all historic save the connection between the garage and residence. The maps do not provide proof of a flat or pitched roof, but if the roof began as a flat roof, it was historically altered to a pitched roof historically.

Mrs. C. W. Dudrow is listed as the owner of the property on the 1912 Kings Map. The 1985 HCPI shows the residence was purchased by A. C. Koch in 1912 from the Dudrow Estate. A. C. Koch or a Koch family member is listed as the owner of the property from 1928 through 1964. Mrs. Dorothea K Dunakin, a nurse, was associated with the property from 1944 through 1951. No further information on these residents is provided by the HCPIs.

Staff researched both C.W. Dudrow and A. C. Koch to determine their contributions to the city of Santa Fe. Charles W. Dudrow came to Santa Fe between 1869 and 1872 and was involved in the lumber, coal, and transfer business in Santa Fe. He was part-owner with his wife's father of the Dudrow and Bear Ice, Transfer, and Livery in 1881. The business was located near the train depot and Our Lady of Guadalupe Church and was part of the beginning of the development of the area. The Dudrow warehouse became the Santa Fe Builders Supply Company (Sanbuso) in 1916 and is now the New Mexico School for the Arts and Sciences. Dudrow is buried in Fairview Cemetery.

Staff found that Adolphe Christian Koch (died in 1939) resided in Santa Fe with his wife Alice Broche Koch (died in 1982 at 106 years old) and their son Ferdinand Adolph Koch. Both are buried in Fairview Cemetery. Ferdinand A Koch was a prominent figure in Santa Fe's history, active in the dry cleaning business, land sales, including the Santa Fe Ski Basin, and various civic associations. He is listed in the New Mexico Ski Hall of Fame for his negotiation of the deal for the Ski Basin. He died in 1982. Jamie Koch is the son of Ferdinand Koch and is a native of the City of Santa Fe. Jamie Koch served as finance chairman for Governors Bruce King and Bill Richardson, was State Chair of the Democratic Party, and is a former state representative.

These two families were important to the establishment of Santa Fe and still represent Santa Fe with their community efforts.

The residential building is currently a three-unit structure that is being converted to a main residence with a guest house. It currently has an interior-only construction permit for the conversion work that is in progress. The addressing from multi-family to single-family will be changed after the conversion is complete.

PREVIOUS CASE SUMMARIES:

ARC:
No Archaeological clearance has been issued for this property.

HDRB:

In case H-84-343, the residence was approved for the construction of an addition on the northeast side of the structure. There are no documents on file in the Historic Preservation Division.

ADMINISTRATIVE:
In case 2024-009160-ADMIN, the residence was approved for a reroof.

APPLICANT'S REQUEST:
The applicant requests:

1. Status review with primary façade designation, if applicable for the residence.

The 2025 HCPI recommends a contributing status, while the 1997 HCPI recommends a significant status for the residence. In 1997, the residence was found to be a listed property. However, in 2025, it no longer holds that listing. The provided HCPIs do not address the people who resided in the structure. Staff did short research on the residents of the structure and found that they are of importance to Santa Fe enough that section 14-12(A) "for its association with events or persons that are important on a local, regional, national, or global level" is met. Since the residence has not been altered since 1997, when it was on the register, staff believe that it could still be listed if the listing for the residence had been maintained. All the additions and alterations to the structure are historic outside of the small addition that connects the residence to the garage. Therefore, the staff disagrees with the contributing recommendation and finds that this structure meets the requirement to be listed as significant.



Figure 4: Façade Diagram

RELEVANT CODE CITATIONS:

14-5.2 HISTORIC DISTRICTS

(A) **General Provisions**

(1) General Purpose

In order to promote the economic, cultural, and general welfare of the people of the *city* and to ensure the harmonious, orderly and efficient growth and *development* of the *city*, it is deemed essential by the *governing body* that the qualities relating to the history of Santa Fe, and a harmonious outward appearance, which preserve *property* values and attract tourists and residents alike, be preserved, some of these qualities being:

(a) The continued existence and *preservation* of historical areas and *buildings*;

(b) The continued construction of *buildings* in the historic styles; and

(c) A general harmony as to style, form, color, height, proportion, texture, and material between *buildings* of historic design and those of more modern design.

(C) **Regulation of Significant and Contributing Structures in the Historic Districts**

(Ord. No. 2004-26)

(1) Purpose and Intent

It is intended that:

(a) Each *structure* is to be recognized as a physical record of its time, place, and use. Changes that create a false sense of historical *development*, such as the addition of conjectural features or architectural elements from other *buildings*, shall not be undertaken.

(b) Changes to *structures* that have acquired historic *significance* in their own right shall be retained and preserved, recognizing that most *structures* change over time;

(c) Distinctive features, finishes, and construction techniques or examples of craftsmanship that characterize a *structure* be preserved; and

(d) New additions and related or adjacent new construction be undertaken in such a manner that if removed in the future, the original form and integrity of the historic *property* and its environment would be unimpaired.

(2) Designation of Significant, Contributing, or Noncontributing Status within Historic Districts

(a) Status Designation

Structures within historic districts may be designated a status of "significant," "contributing," or "noncontributing" based upon the definitions of these terms in Article 14-12. Staff shall maintain a record as to the current status of *structures* located in the Historic Districts.

(b) Board Authority to Review Status Designation

(i) The Board is authorized to change the status of a *structure* or to designate a status for a *structure* with no status designated.

(ii) A change in status or the designation of a status shall be based upon an evaluation of data provided through survey or other relevant sources of information and the definitions of "significant," "contributing," or "noncontributing."

14-12 Significant Structure:
A structure located in a historic district that is approximately fifty years old or older, and that embodies distinctive characteristics of a type, period, or method of construction. For a structure to be designated as significant, it must retain a high level of historic integrity. A structure may be designated as significant:

(A) for its association with events or persons that are important on a local, regional, national, or global level; or
(B) if it is listed on or is eligible to be listed on the State Register of Cultural Properties or the National Register of Historic Places.

14-12 Contributing Structure:
A structure, located in a historic district, approximately fifty years old or older, that helps to establish and maintain the character of that historic district. Although a contributing structure is not unique in itself, it adds to the historic associations or historic architectural design qualities that are significant for a district. The contributing structure may have had minor alterations, but its integrity remains.

14-12 Noncontributing Structure:
A structure, located in an H district, that is less than fifty years old, or that does not exhibit sufficient historic integrity to establish and maintain the character of the H District.

14-12 Primary Façade:
One or more principal faces or elevations of a building with features that define the character of the building's architecture.

(D) General Design Standards for All H Districts

In any review of proposed additions or alterations to *structures* that have been declared significant or contributing in any historic district or a *landmark* in any part of the *city*, the following standards shall be met:

(1) General

(a) The status of a significant, contributing, or *landmark structure* shall be retained and preserved. If a proposed alteration will cause a *structure* to lose its significant, contributing, or *landmark* status, the *application* shall be denied. The removal of historic materials or alteration of architectural features and spaces that embody the status shall be prohibited.

(b) If a proposed alteration or new construction will cause an adjacent *structure* to lose its significant, contributing, or *landmark* status, the *application* may be denied.

(2) Additions

(a) Additions shall have similar materials, architectural *treatments* and styles, features, and details as the existing *structure*, but shall not duplicate those of the existing *structure* in a manner that will make the addition indistinguishable from the existing *structure*.

(b) Additions to *buildings* that meet the standards of Subsection 14-5.2(E) shall continue to meet those standards set forth in Subsection 14-5.2(E) in addition to the standards set forth in this section.

(c) Additions are not permitted to *primary façades*.

(d) Additions are not permitted to the side of the existing footprint unless the addition is set back a minimum of ten (10) feet from the primary facade. The addition shall not exceed fifty percent of the square footage of the existing footprint, and shall not exceed fifty percent of the existing dimension of the primary facade. To the extent architecturally practicable, new additions shall be attached to any existing noncontributing portion of *structures* instead of attaching them to the significant or contributing portion.

(e) The height of additions:

(i) For significant and *landmark structures* shall be a minimum of six (6) inches less than the parapet or equivalent roof-feature of the existing adjacent connecting facade.

(ii) For contributing *structures* shall be no more than one additional *story* higher than the existing *structure*. To the extent architecturally practicable, two-story additions shall be set to the rear or the side rear of the *structure*. When an additional *story* is to be placed upon an existing contributing *structure*, that footprint may be no greater than fifty percent of the footprint of the existing *structure*, subject to the provisions of Subsection A(1) above. For the purposes of this paragraph, an additional *story* shall not exceed twelve (12) feet from the existing rooftop to the highest point of that *story*.

(3) Remodeling to Increase Height; Rooftop Appurtenances

(a) For *remodeling* of existing significant and *landmark structures*, no increase in height of the *structures* is permitted. (For standards relating to additions to existing *structures*, see paragraph (2) above.)

(b) For significant and *landmark structures*, *publicly visible* rooftop appurtenances, including but not limited to solar collectors, clerestories, decks, or mechanical equipment, shall not be added, nor shall the parapet be raised to conceal the *rooftop appurtenances*. For contributing *buildings*, solar collectors, clerestories, decks, or mechanical equipment if *publicly visible* shall not be added.

(4) Porches and Portals

Existing *porches* or *portals* shall not be enclosed.

(5) Windows, Doors, and Other Architectural Features

(a) For all facades of significant and *landmark structures* and for the primary facades of contributing *structures*:

(i) Historic windows shall be repaired or restored wherever possible. Historic windows that cannot be repaired or restored shall be duplicated in the size, style, and material of the original. Thermal double pane glass may be used. No opening shall be widened or narrowed.

(ii) No new opening shall be made where one presently does not exist unless historic documentation supports its prior existence.

(iii) No existing opening shall be closed.

(b) For all façades of significant, contributing, and *landmark structures*, architectural features, finishes, and details other than doors and windows shall be repaired rather than replaced. In the event *replacement* is necessary, the use of new material may be approved. The new material shall match the material being replaced in composition, design, color, texture, and other visual qualities. *Replacement* or duplication of missing features shall be substantiated by documentation, physical, or pictorial evidence.

(6) Roofs

The existing roof styles and materials shall be maintained or replaced in kind if necessary. The addition of dormers or other roof features should only be considered when they are an existing or historical feature of the *structure*.

(8) Archaeological Resources

Discovery of archaeological resources made during the historic districts review process shall be referred to the archaeological review committee.

(9) Height, Pitch, Scale, Massing, and Floor Step backs

The height, pitch, *scale*, and massing of any *structure* in a historic district, as defined in this section, shall be limited as provided for in this section, unless further restricted within this chapter.

(a) Applicability

The following sections identify specific areas and specific *projects* subject to this section. Planning and land use department staff shall determine whether or not properties are included within this section. (Ord. No. 2007-45 § 30; Ord. #2020-22, § 16)

F. When the proposed *building*, *yard wall*, or fence is located in a *streetscape* that includes no *buildings*, *yard walls*, or fences, the height of the proposed *building* shall not exceed sixteen (16) feet. *Yard walls* and fences in this *streetscape* shall not exceed five (5) feet in height.

(c) Height

(ii) In exercising its authority under this section, the board shall limit the height of *structures* as set forth in this section. Heights of existing *structures* shall be as set forth on the official map of *building* heights in the historic districts.

A. If a proposed *building* has a parapet, the façade shall not be in excess of two (2) feet of the average of the height of the façades in the *streetscape*.

B. If the proposed *building* has a pitched roof, the ridge height of the proposed *building* shall not be in excess of two (2) feet of the average of the ridge height of the pitched roofs in the *streetscape*.

C. *Yard walls* and fences shall be limited to a height that does not exceed the average of the height of other *yard walls* and fences in the *streetscape*.

D. Pursuant to Section 14-7.4(C), the height of any other *structure* shall be limited to the allowable *building* height within the applicable *streetscape*, as defined in this section. (Ord. No. 2002-37 § 26)

E. The height and dimension of signage are set forth in Section 14-8.10(H).

F. The board may increase the allowable height for proposed *buildings* and additions located on a sloping site where the difference in the natural *grade* along the *structure's* foundation exceeds two (2) feet. In no case shall the height of a façade exceed four (4) feet above the allowable height of the applicable *streetscape* measured from natural or finished *grade*, whichever is more restrictive. This increase in height shall be constructed only in the form of *building* step-backs from the *street*.

(d) Pitch

If the determined *streetscape* includes over fifty percent of *buildings* with pitched roofs, the proposed *building* may have a pitched roof. A pitched roof is defined as a gable, shed, or *hipped roof*. The pitch of the roof shall match the predominant pitch extant in the *streetscape*.

(e) Scale

The height of a proposed *building* or addition, its façade length, and its roof form and pitch shall appear to be in proportion to the height, façade length, and roof form and pitch of *buildings* in the applicable *streetscape*, or the *building* on which the addition is proposed.

(f) Massing and Floor Step backs

The Board may require that upper floor levels be stepped back, to carry out the intent of this section; provided that the board in making such determinations shall take into account whether the height of the proposed *building*, *yard wall*, fence, or proposed step back of upper floor levels is in harmony with the massing of the applicable *streetscape* and *preservation* of the historic and characteristic visual

qualities of the *streetscape*. The Board shall also require that the *publicly visible* façades of the *structure* be in conformance with Subsections 14-5.2(E) through (H), and in meeting those requirements, may require that different floor levels be stepped back.

(I) **Westside-Guadalupe Historic District**

(1) District Standards

Compliance with the following structural standards shall occur whenever those exterior features of *buildings* and other *structures* subject to public view from any public *street*, way, or other public place are erected, altered, or demolished:

(a) Slump block, stucco, brick, or stone shall be used as exterior *wall* materials. Wood and other materials may be used for details. Aluminum siding, metal panels, mirrored glass, and unstuccoed concrete block or unstuccoed concrete shall not be used as exterior *wall* materials;

(b) The color of stuccoed *buildings* shall predominantly be in browns, tans, local earth tones, and soft pastels. Surfaces of stone or brick shall be in the natural color. Entryways, and *portales* or *porches* may be emphasized by the use of white or other colors. Painting of *buildings* with a color that causes arresting or spectacular effects, or with bold repetitive patterns, or using *buildings* as signs is prohibited. Murals, however, are permitted and may be referred to the *city* arts board for an advisory recommendation.

(c) Roof form, *slope*, and shape. It is intended that *buildings* be designed to be "wall-dominated". "Wall-dominated" means that the *building's* geometry is more defined by *walls* than by roofs. *Buildings* with flat, gabled, shed, or *hipped roofs* can be designed as "wall-dominated" solutions and are allowed. The height of the roof above the *wall* shall be no greater than the height of the *wall*. Folded plate, hyperbolic, or mansard roofs are not allowed.

(d) The use of solar and other energy-collecting and conserving strategies is encouraged. The use of large, glazed areas on south-facing *walls* for trombe *walls* or other solar collectors, direct gain, or other energy-collecting purposes is allowed. When in view from any public *street*, way, or other public place, solar equipment shall be screened as follows:

(i) raising the parapet;

(ii) setting back from the edge of the roof;

(iii) framing the collector with wood;

(iv) in the case of pitched roofs, by integrating the collector into the pitch;

(v) in the case of ground solar collectors, by a *wall* or vegetation;

(vi) in the case of *wall* collectors, by enclosing by end or other *walls*;

(vii) other means that screen the collector or integrate it into the overall *structure*. Non-glare materials shall be used in solar collectors.

(e) Mechanical, electrical, telephone equipment, microwave satellite receiving dishes, and other obtrusive equipment shall be architecturally screened with opaque materials by raising the parapet, boxing in the equipment, or other appropriate means. The equipment shall be of a low profile to minimize the *screening* problems.

(f) *Walls* and fences shall be of brick, *adobe*, masonry, rock, wood, coyote fencing, or similar materials. Wrought iron fences and slump block *walls* are allowed. *Walls* of unstuccoed concrete block, unstuccoed concrete, chain-link, metal wire, or similar materials are prohibited, except where the *wall* or fence is not in the *street* frontage.

(g) *Greenhouses*

(h) Attached *greenhouses* that front on the *street* shall give the appearance of being integrated into the *structure* of the *building* or of being a substantive addition rather than having a lean-to effect. The use of corrugated fiberglass or rolled plastic for the external surface of attached or freestanding *greenhouses* that front on the *street* is prohibited. *Greenhouses* with slanting sides shall be bracketed at the ends, and that *greenhouses* made from enclosed *porches* or *portales* maintain the shape of the *porch* or *portal*.

(i) *Porches* and *portales* are encouraged;

(j) When parking spaces are required for commercial or multi-family *residential buildings*, they shall be placed to the rear or side of the building.

(2) Walls; Fences; Solar Collectors; Administration

Applications for the erection, alteration, or demolition of *walls*, fences, and solar collectors and required submittals shall be reviewed by the planning and land use department. Approval, disapproval, or referral shall be indicated by the division on the *application* for the building *permit* and on each of the required submittals, all of which shall be signed by the division staff assigned to the review. The division shall report approvals, disapprovals, and referrals to the board at its next regular meeting as an informational item. (Ord. No. 2007-45 § 30; Ord. #2020-22, § 16)


231
231
525
527
521
525
525
533
Westside-Guadalupe HD
517
523
527
527
507
543
533
AGUA FRIA ST
541
518

527 AGUA FRIA

THE ATTACHED SURVEY FORM REFLECTS HISTORIC BUILDING SURVEY WORK THAT WAS COMPLETED DURING APRIL - SEPTEMBER OF 1997. RESULTS OF THE SURVEY AS REFLECTED ON THE ATTACHED HAS NOT BEEN ADOPTED BY THE CITY COUNCIL. IT SHOULD BE CONSIDERED PRELIMINARY FOR PURPOSES OF PLANNING. THIS IS TRUE AS OF 9/97.

PLEASE SEE HEATHER OR MARY FOR MORE INFORMATION OR CLARIFICATION.

NEW MEXICO HISTORIC BUILDING INVENTORY - SANTA FE RESURVEY 1997

IDENTIFICATION

ADDRESS: 527 Agua Fria

OLD ID NUMBER: 0516 13581

SANTA FE ID NUMBER: H1510

UTM REFERENCE EASTING NORTHING

ZONE 12 13

LEGAL DESCRIPTION:

BUILDING NAME:

TNSP 17 (N) S RANGE 9 (E) W SEC 24 SW 1/4 NW 1/4

FIELD MAP

Santa Fe Historic Status Map 1996

DATE OF CONSTRUCTION: SOURCE(S)

by 1928 ESTIMATE city directory A C Koch ©

by 1930 ACTUAL Sanborn map

BUILDING DATA

ARCHITECTURAL STYLE: Mediterranean

USE:

HISTORIC: (residential)

OTHER _____

PRESENT: (residential)

OTHER apartments

SURROUNDINGS: residential/commercial

RELATIONSHIP TO HISTORIC SURROUNDINGS:

X SIMILAR ___ NOT SIMILAR

ASSOCIATED BUILDINGS ON SITE:

X YES ___ NO

WHAT TYPE? garage

IF INVENTORIED, LIST ID NUMBER(S)

H1511

DEGREE OF REMODELING:

X MINOR ___ MODERATE

___ MAJOR none evident

EXPLAIN:

OVERALL CONDITION:

___ EXCELLENT X GOOD

___ FAIR ___ DETERIORATED

BUILDING THREATENED?

___ YES X NO

PHOTO

SITE PLAN



SIGNIFICANCE

LISTED ON NATIONAL REGISTER OF HISTORIC PLACES?

X YES ___ NO ___ ELIGIBLE

X CONTRIBUTING ___ NON-CONTRIBUTING

LISTED ON STATE REGISTER OF CULTURAL PROPERTIES?

X YES ___ NO ___ ELIGIBLE

LOCAL DESIGNATION: Downtown-Eastside HISTORIC DISTRICT

X SIGNIFICANT ___ CONTRIBUTING ___ NON-CONTRIBUTING

LOCAL LANDMARK ___ YES X NO

SURVEYED 8/97 BY DB

NEGATIVES WITH NMHPD ROLL # D69 NEG # 14 TO 16

ARCHITECTURAL FEATURES: STYLE, MATERIALS, AND CONDITION

ROOFS & DRAINS	red (metal) tile roof with gables of various heights, gable horns, exposed rafters	
BUILDING WALLS	tan stucco/concrete	
FOUNDATIONS	not visible	APPROX. HEIGHT (FT.) 20
DOORS	wood french	
WINDOWS	8 light wood casements in pairs and trios; picture windows	
PORCHES OR PORTALES	SE corner - shed roof, stucco piers S - gable roof, round arched opening	
ARCHITECTURAL DETAILS		
FENCES/WALLS	low stucco wall, S; wd plank fence SE	
SITE FEATURES		
OTHER/ COMMENTS	Garage - flat roof, one overhead door, one filled w/ window, wd wall. Connected to house by arched stucco gateway.	

ADDITIONAL PHOTOGRAPHS

#16 SW

ES #14


10
APRIL 1908
SANTA FE
NEW MEX.
GUADALUPE R.C. CHURCH
PARSONAGE
MISSION SCHOOL
AQUA FRIA
AQUA FRIA
DUDROW
GUADALUPE
C. W. DUDROW
WOOD YARD & WOOD SAWING
L. A. HUGHES, LUMBER YARD
C. W. DUDROW, LUMBER YARD
CARTWRIGHT-DAVIS CO.
HAY WARE HO.
CONTINENTAL OIL CO.
OIL WARE HO.
PROPOSED 4" W. PIPE
LEMP BREWING CO.
BOTTLING WKS.
COAL HO
COAL BIN
LUMBER SHED
LUMBER SHED
LUMBER
LUMBER
LUMBER
LUMBER
LUMBER PILE
DRIVE
DRIVE
DRIVE
WARE HO.
WARE HO.
OFFICE
SCALES
SHEDS
SHED
GRO.
GRO.
EARTH RD.
EARTH RD.
6" W. PIPE
D. & R. G. R. R.
SANTA FE R. R.
SIDING
VACANT
F
A
A
A

1930 Sanborn 527 Agua Fria

building threatened? yes	surveyed date 6/85 by HMW	county SANTA FE	ID no. 051613581
field map SFHD # 7	number 581	UTM reference zone 12 13	easting northing

location description: 527 AGUA FRIA

city/town: SANTA FE

land grant/reservation: ~~land grant/reservation~~

building name:

legal description: tnsp ___ N S range ___ E W sec ___ ½ ___ ½

film roll by SL no. SFHD # 20	negative nos. 35	loc. of neg. HPB

plan shape



date of construction: PRE 1912 + estimate ___ actual

source:

use
present: residential
other:
historic: residential
other:

condition: ✓excellent ___good ___fair ___deteriorating

degree of remodeling: ___minor ✓moderate ___major
describe: REAR ADDS, PORCH CHANGED.

surroundings: RES.

relationship to surroundings: ✓similar ___not similar

district potential: ___yes ___no

significance: ___eligible ✓of interest ___none
if eligible, why? CONTRIB.

associated buildings? ___yes
what type? SNGL'D 2 CAR GARAGE.
if inventoried, list ID nos.

style: MED. REV.

foundation material: CONC.

wall material/surface: ADOBE/ STUCCO

architectural features
MFL MISSION TILE RF/ STABLE HORNS, EXP'D RAFTER ENDS, DIAMOND VENTS.
CORNER PORCH W/ STUCCO'D PIERS, SEMI CIRC. SOLID DOOR. IN SMALLER FRONT PORCH ENTRY.
8 LIGHT W.D. CASM'TS., TAN'D TRIMS.
2 LARGE PIC WINDS ON W.
N.V. SHED ADDS @ REAR.

comments
A.C. KOCH BOUGHT THIS IN 1912 FROM C.W. DUDROW ESTATE. HE ADDED TILE RF IN 1920-25. HOUSE HAS CROWN @ REAR - N.V.
IT IS MED REV. FOR ITS RF, BUT OBVIOUSLY EARLIER CORE.
(KOCH'S DAUGHTER LIVES IN BACK @ 229 POLACO).

see back? ___yes

H151

building threatened? yes	surveyed date 6/85 by HMW	county SANTA FE	ID no. 051613581
field map SFHD #7	number 581	UTM reference zone 12 13 easting northing	

location description: 527 AGUA FRIA

city/town: SANTA FE

land grant/reservation: ~~land grant/reservation~~

building name:

legal description: tnsp ___ N S range ___ E W sec ___ ½ ½

film roll by SL no. SFHD #20 | negative nos. 35 | loc. of neg. HPB

plan shape



date of construction: PRE 1912 + estimate ___ actual

source:

use
present: residential
other:
historic: residential
other:

condition
✓ excellent ___ good
___ fair ___ deteriorating

degree of remodeling
___ minor ✓ moderate ___ major
describe: REAR ADDS, PORCH CHANGED.

surroundings: RES.

relationship to surroundings
✓ similar ___ not similar

district potential
___ yes ___ no

significance
___ eligible ✓ of interest ___ none
if eligible, why? CONTRIB.

associated buildings? ___ yes
what type? STUCCO 2 CAR GARAGE
if inventoried, list ID nos.

style: MED. REV.

foundation material: CONC

wall material/surface: ADOBE/ STUCCO

architectural features
MTL MISSION TILE ROOF/ STABLE HORNS, EXP'D RAFTER ENDS, DIAMOND VENTS
CORNER PORCH W/ STUCCO PIERS, SEMI CIRC. SOFFIT
DOOR IN SMALLER FRONT PORCH ENTRY.
8 LIGHT WD CASM'TS, TRANS, TRIMS.
2 LARGE PIC WINDS ON W.
N.V. SHED ADDS @ REAR.

comments
A.C. KOCH BOUGHT THIS IN 1912 FROM C.W. DUDROW ESTATE. HE ADDED TILE RF IN 1920-25. HOUSE HAS CROWN @ REAR - N.V.
IT IS MED REV. FOR ITS RF, BUT OBVIOUSLY EARLIER CORE.
(KOCH'S DAUGHTER LIVES IN BAKE @ 229 POLK).

see back? ___ yes

Charles W. Dudrow Santa Fé County, New Mexico

Charles W. Dudrow, engaged in the lumber, coal and transfer business at. Santa Fé, was born in Frederick, Maryland, in 1841 and became a resident of Santa Fé in 1870. For several years he was employed by Barlow & Sanderson, the noted overland stage line men as express messenger. In 1880 he engaged in his present business and for several years has conducted a lumber and coal yard at Cerrillos. His business interests are capably conducted and guided by sound judgment, so that his efforts result successfully. He is widely known throughout the northern part of the Territory and is active in public affairs. He was twice elected sheriff but declined to serve, and for several terms he was a member of the board of county commissioners and chairman of that body.

Back | Santa Fe County Biographies

Source: History of New Mexico, Its Resources and People, Volume II, Pacific States Publishing Co., 1907.

©New Mexico American History and Genealogy Project 2011 - 2025
Created 1996 by Charles Barnum & 2016 by Judy White

https://historyinsantafe.com/santa-fe-railyard-history/

Dudrow & Company

- By Ana Pacheco



Dudrow & Bears Transfer station in Santa Fe in the 1881.

The Dudrow & Bears Transfer Corral in 1881 was a family-run business. Charles W. Dudrow, came to Santa Fe between 1869 and 1872. He had been a driver for the Barlow and

Sanderson stage lines that ran from Pueblo, Colorado, to Santa Fe. When he arrived in Santa Fe he married Cora Bear and became a business partner with her father, Samuel Bear. They opened Dudrow & Bear Ice, Transfer and Livery. The business was located near the train depot and Our Lady of Guadalupe Church.

Fairview Cemetery

The family tombstone of Charles Dudrow at Fairview cemetery.

Long before the Dudrow transfer station Our Lady of Guadalupe mission church dominated the area. Originally built in 1777 on the banks of the Santa Fe River, the church closed in 1826 when it fell into disrepair. A new 575-pound bell complimented the church remodel in the 1850s. The altar screen included a replica of Our Lady of Guadalupe. The painting came to Santa Fe by ox train in 1783. The Santuario de Guadalupe is the oldest continuously standing shrine to Our Lady of Guadalupe in the United States.

Our Lady of Guadalupe is the patron saint of Mexico.

A hundred years after the original structure was completed, the old mission-style building was radically changed. After its alteration it resembled a typical east-coast church, with a steeple painted bright orange. The spire was centered above the entry instead of at the southeast corner where the bell tower once stood. Gothic-style windows were built into the walls and a white picket fence was erected to enclose the churchyard. One reason given for these drastic changes was the arrival of many English-speaking Catholics from the east, who brought their building style with them.

Railroad Comes to Santa Fe

The eastern edge of the Santuario grounds has also withstood many changes. In 1889, the Denver and Rio Grande Railroad offered narrow-gauge rail service between Santa Fe and Denver out of a nearby depot. The line closed its service in 1941. Once it closed the train rails and ties were torn from the Santuario's property line along Guadalupe Street.

- Categories: Santa Fe History
- Tags: Dudrow & Bear Company, Fairview Cemetery, Our Lady of Guadalupe, Santa Fe Historical Walking Tour, Santa Fe railyard

Please support Ana Pacheco's work at:

Buy Me a Coffee

Adolphe Christian Koch

8 February 1873–21 December 1939 • GMQY-XLS

Brief Life History of Adolphe Christian

When Adolphe Christian Koch was born on 8 February 1873, in Dunkirk, Chautauqua, New York, United States, his father, Karl Ernest Theodor Koch, was 37 and his mother, Dorothea Zimmerman, was 31. He had at least 1 son and 1 daughter with Alice Broche. He lived in Santa Fe, Santa Fe, New Mexico, United States for about 10 years. He died on 21 December 1939, in Albuquerque, Bernalillo, New Mexico, United States, at the age of 66.

MORE

Spouse and Children

Adolphe Christian Koch
1873–1939

Alice Broche
1875–1982

Children (2)

Ferdinand Adolph Koch Sr
1898–1982

Dorthea Koch

Photos and Memories (0)

Do you know Adolphe Christian? Do you have a story about him that you would like to share? Sign In or Create a FREE Account

Parents and Siblings

Karl Ernest Theodor Koch
1835–1913

Dorothea Zimmerman
1841–1878

Siblings (6)

August Albert Cook
1862–1941

Family Time Line

Spouse and Children | Parents and Siblings

Sources (3)

Adolph Koch, "United States Census, 1920"

Adolph Christian Koch, "Find A Grave Index"

A C Koch, "United States Census, 1930"

VIEW ALL

Alice Broche

12 December 1875–September 1982 • GS7L-6JP

Brief Life History of Alice

When Alice Broche was born on 12 December 1875, in District of Columbia, United States, her father, Gustave Broche, was 26 and her mother, Judith Villroy, was 15. She had at least 1 son and 1 daughter with Adolphe Christian Koch. She lived in Washington, District of Columbia, United States in 1880. She died in September 1982, in Santa Fe, Santa Fe, New Mexico, United States, at the age of 106, and was buried in Santa Fe, Santa Fe, New Mexico, United States.

MORE

Parents and Siblings

Gustave Broche
1849–1900

Judith Villroy
1860–1879

Siblings (2)

Alice Broche
1875–1982

Gustave Broche Jr

Photos and Memories (0)

Do you know Alice? Do you have a story about her that you would like to share? Sign In or Create a FREE Account

Spouse and Children

Adolphe Christian Koch
1873–1939

Alice Broche
1875–1982

Children (2)

Ferdinand Adolph Koch Sr
1898–1982

Family Time Line



Sources (4)

Alice Koch in household of Adolph Koch, "United States Census, 1920"

Alice Broche Koch, "Find A Grave Index"

Alice Koch in household of A C Koch, "United States Census, 1930"

VIEW ALL

STATE New Mexico
COUNTY Santa Fe

P—127

DEPARTMENT OF COMMERCE—BUREAU OF THE CENSUS

FOURTEENTH CENSUS OF THE UNITED STATES: 1920—POPULATION

[D1—078]

SUPERVISOR'S DISTRICT NO. 211 | SHEET NO. 7 B
ENUMERATION DISTRICT NO. 129

* TOWNSHIP OR OTHER DIVISION OF COUNTY Precinct 4 | NAME OF INCORPORATED PLACE Santa Fe City | WARD OF CITY 2 Precinct 4 (Part of)

NAME OF INSTITUTION | ENUMERATED BY ME ON THE 6 DAY OF Jan 1920. | Lula B. Hinder ENUMERATOR.

PLACE OF ABODE.			NAME of each person whose place of abode on January 1, 1920, was in this family. Enter surname first, then the given name and middle initial, if any. Include every person living on January 1, 1920. Omit children born after January 1, 1920.	RELATION. Relationship of this person to the head of the family.	HOME.	PERSONS ENUMERATED.				CITIZENSHIP.			EDUCATION.			NATIVITY AND MOTHER TONGUE. Place of birth of each person and parents of each person enumerated. If born in the United States, give the state or territory. If of foreign birth, give the place of birth now, in addition, the mother tongue. (See instructions.)					OCCUPATION.				
																PERSONS.		FATHER.		MOTHER.					
Street, avenue, road, etc.	Number in order of visitation.	Number of dwelling house in order of visitation.			Number of families in this house, counting this family as one.	Sex.	Color or race.	Age at last birthday.	Single, married, widowed, or divorced.	Year of naturalization, if foreign born.	Whether naturalized or alien.	If alien, whether declared intention.	Attended school any time since Sept. 1, 1919.	Cannot read.	Cannot write.	Place of birth.	Mother tongue.	Place of birth.	Mother tongue.	Place of birth.	Mother tongue.	Whether able to speak English.	Trade, profession, or particular kind of work done, as spinner, salesman, laborer, etc.	Industry, business, or establishment in which at work, as cotton mill, shoe factory, farm, etc.	Employer, salary or wage worker, or working on own account.	Whether home owned or rented.
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29
	306	118		Probst Elda	wife			F	W	32	M					yes	yes	Colorado		Missouri		Colorado		yes	none			
	306	118	139	Otero Cecilia	Head	1	R	F	W	66	Wd					yes	yes	New Mexico		New Mexico		New Mexico		yes	seamstress	At Home		O
				— Filipi	son			M	W	28	S					yes	yes	New Mexico		New Mexico		New Mexico		yes	Painter	Newspaper	W	
				— Herman	son			M	W	28	S					yes	yes	New Mexico		New Mexico		New Mexico		yes	Cook	Hotel	W	
				— Amelia	daughter			F	W	20	S					yes	yes	New Mexico		New Mexico		New Mexico		yes	Clerk	Drygoods Store	W	
	304	119	140	Cantana Alejandro	Head	1	R	M	W	35	M					yes	yes	New Mexico		New Mexico		New Mexico		yes	Jeweler	Store	Employer	O
				— Josefita	wife			F	W	30	M					yes	yes	New Mexico		New Mexico		New Mexico		yes	none			
				— Flora	daughter			F	W	13	S					yes	yes	New Mexico		New Mexico		New Mexico		yes	none			
				— Pete	son			M	W	9	S					yes	yes	New Mexico		New Mexico		New Mexico		yes	none			
				— Carleton	daughter			F	W	7	S					yes	yes	New Mexico		New Mexico		New Mexico		yes				
				— Joe	son			M	W	4	S					yes	yes	New Mexico		New Mexico		New Mexico		yes				
				— Anany	daughter			F	W	2	S					yes	yes	New Mexico		New Mexico		New Mexico		yes				
	308	120	141	Martinez Pedro	Head	1	R	M	W	45	M					yes	yes	New Mexico		New Mexico		New Mexico		yes	Butcher	meat market	W	
				— Sharon	wife			F	W	45	M					no	no	New Mexico		New Mexico		New Mexico		no	none			
				Saddie Maggie	daughter			F	W	23	M					yes	yes	New Mexico		New Mexico		New Mexico		yes	none			
				— Maximo	son			M	W	38	M					yes	yes	New Mexico		New Mexico		New Mexico		yes	Clerk	Drygoods	W	
				Martinez	son			M	W	16	S					yes	yes	New Mexico		New Mexico		New Mexico		yes	none			
				— Adelada	mother			F	W	60	Wd					no	no	New Mexico		New Mexico		New Mexico		no	none			
	246	121	142	Lujan Viviana	Head	1	R	F	W	26	S					no	no	New Mexico		New Mexico		New Mexico		no	none			
				— Fedelia	friend			F	W	13	S					yes	yes	New Mexico		New Mexico		New Mexico		yes	none			
	245	121	143	Romero Ignacio	Head	?	R	M	W	44	Wd					no	no	New Mexico		New Mexico		New Mexico		no	Weaver	woolen	W	
	247	122	144	Muller Alfred	Head	1	R	M	W	36	M					yes	yes	New Mexico		Wisconsin	German	New Mexico		yes	Agent	Oil Company	W	
				— Mary Hays	wife			F	W	28	M					yes	yes	New Mexico		Missouri		Virginia		yes				
	248	123	145	Stinger Isidor M	Head	1	R	M	W	59	M					yes	yes	New York		New York		Indiana		yes	Painter	Newspaper	W	
				— Louisa	wife			F	W	58	M					yes	yes	Kansas		Germany	German	New York		yes	none			
				Burlington Mary E	Sister			F	W	66	Wd					yes	yes	Kansas		Scotland	Scotch	New York		yes	Cashier	Theatre		
	249	124	146	Hannah Mayflower	Head	1	R	M	W	58	Wd					yes	yes	Kansas		Iowa		Pennsylvania		yes	none			
				— Claral	daughter			F	W	23	S					yes	yes	New Mexico		Missouri		Kansas		yes	none			
				— Norman	son			M	W	22	S					yes	yes	New Mexico		Missouri		Kansas		yes	Real Estate	Agent	W	
				— E Theresa	daughter			F	W	14	S					yes	yes	New Mexico		Missouri		Kansas		yes	none			
	251	125	147	Hogle Fred	Head	1	W	M	W	38	M					yes	yes	New Mexico		Iowa		Iowa		yes	Plumber	Hardware Store	W	
				— Emma	wife			F	W	37	M					yes	yes	New Mexico		Pennsylvania		Wales		yes	none			
				— Adaline	daughter			F	W	11	S					yes	yes	New Mexico		New Mexico		New Mexico		yes				
				— Owen	son			M	W	9	S					yes	yes	New Mexico		New Mexico		New Mexico		yes				
				— William B	son			M	W	1	S							New Mexico		New Mexico		New Mexico						
	241	126	148	Smith Jr. E.	Head	1	R	M	W	40	M					yes	yes	Pennsylvania		Pennsylvania		Pennsylvania		yes	Contractor	House building	W	
				— Alice	wife			F	W	32	M					yes	yes	Iowa		Pennsylvania		Pennsylvania		yes	none			
				— E. W.	son			M	W	9	S					yes	yes	Iowa		Pennsylvania		Iowa		yes	Carpenter	House building		
	240	127	149	Koch Adolph	Head	1	R	M	W	44	M					yes	yes	New York		Germany	German	Germany	German	yes	Owner	Laundry	Rent	
				— Alice	wife			F	W	44	M					yes	yes	Kansas		Switzerland	German	France	French	yes	none			
				— Ferdinand	son			M	W	23	S					yes	yes	Colorado		Washington		New York		yes	Laundryman	Helper	W	
				— Sterlice	daughter			F	W	19	S					yes	yes	Colorado		Washington		New York		yes	none			
	243	128	150	Ortiz Pete Jr.	Head	1	R	M	W	24	Wd					yes	yes	New Mexico		New Mexico		New Mexico		yes	Jeweler	Repairer	W	
				— Ruby	daughter			F	W	3	S					yes	yes	New Mexico		New Mexico		New Mexico		yes	Teacher	Hotel	W	
				— Ruth	son			M	W	2	S					yes	yes	New Mexico		New Mexico		New Mexico		yes	none			
				— Clotilda	daughter			F	W	1	S					yes	yes	New Mexico		New Mexico		New Mexico		yes	none			
	242	129	151	— J. B	Head	1	R	M	W	77	M					yes	yes	New Mexico		New Mexico		New Mexico		yes	none			
				— Nicholas	wife			F	W	79	M					yes	yes	New Mexico		New Mexico		New Mexico		yes	none			
				Prater James P	Head			M	W	19	S					yes	yes	New Mexico		New Mexico		New Mexico		yes	Carpenter	House building	W	
				— Sirid	Head			F	W	16	S					yes	yes	New Mexico		New Mexico		New Mexico		yes	Clerk			

Form 15-6

DEPARTMENT OF COMMERCE—BUREAU OF THE CENSUS

FIFTEENTH CENSUS OF THE UNITED STATES: 1930

POPULATION SCHEDULE

State: New Mexico Incorporated place: City of Santa Fe Enumeration District No. 25-6 Sheet No. 10 B

County: Santa Fe Ward of city: 2 (pt) Block No.

Township or other division of county: Unincorporated place: Institution:

Enumerated by me on April 10th, 1930. Rafael A. Ortiz, Enumerator.

PLACE OF ABODE	NAME	RELATION	HOME DATA	PERSONAL DESCRIPTION	EDUCATION	PLACE OF BIRTH	MOTHER TONGUE (OR NATIVE LANGUAGE) OF FOREIGN BORN	CITIZENSHIP, ETC.	OCCUPATION AND INDUSTRY	EMPLOYMENT	VETERANS	
Dwelling house number in order of visitation	Name of each person whose place of abode on April 1, 1930, was in this family. Enter surname first, then the given name and middle initial, if any. Include every person living on April 1, 1930. Omit children born after April 1, 1930	Relationship of this person to the head of the family	Home owned or rented; Value of home, if owned, or monthly rental, if rented; Radio set	Sex; Color or race; Age at last birthday; Marital condition	Attended school or college any time since Sept. 1, 1929; Age at first birthday	Person; Father; Mother	Language spoken in home before coming to the United States	Year of immigration to the United States; Naturalization; Whether alien (A) or citizen (C)	Occupation; Industry; Code; Class of worker	Unemployment (Weeks); Veterans		
1 2 3 4	5	6	7 8 9 10	11 12 13 14 15 16	17 18	19 20 21	22	23 24 25	26 27 28	29 30	31 32	33 34
516	James Williams C	Head	R 30	M W 25 M	No	Florida Florida Florida			Brick Layer Building	0381 W	Yes	No
	Rosada	Wife		M W 20 M	No	New Mexico Germany New Mexico			None			
517 216 235	Lopez, E. B.	Head	R 30 R	M W 37 M	No Yes	Old Mexico Old Mexico Old Mexico	Spanish	1919	Draftsman Engineer	2448 W	Yes	No
	Dominila	Wife		M W 27 M	No Yes	Texas Texas Texas			None			
	Eva	Daughter		S W 9	Yes	New Mexico Old Mexico Texas			None			
	Lazo	Daughter		S W 8	Yes	New Mexico Old Mexico Texas			None			
	Helen	Daughter		S W 6	Yes	New Mexico Old Mexico Texas			None			
	Virginia	Daughter		S W 4	No	New Mexico Old Mexico Texas			None			
511 217 226	Mrs. Trimmers Stuart	Head	R 26 R	M W 44 M	No Yes	Missouri Scotland Scotland			Bookkeeper Garage 6773 W	Yes	No	
	Florence M	Wife		M W 40 M	No Yes	New Mexico Missouri Kansas			None			
517 218 227	Hoyle, Enoch B.	Head	O 2000 R	M W 47 M	No Yes	New Mexico Pennsylvania Iowa			Plumber Plumbing shop 3081 O	yes	No	
	Emma B	Wife		M W 48 M	No Yes	New Mexico Pennsylvania Pennsylvania			None			
	William B.	Son		M W 11 S	yes	New Mexico New Mexico New Mexico			None			
525 219 228	Healy, Thomas A.	Head	O 3500 R	M W 64 M	No Yes	Illinois Indiana Indiana			Proprietor Furniture 7288 W	Yes	No	
	Alice	Wife		M W 39 M	No Yes	England Scotland Scotland	English	1918	None			
	Alice R	Daughter		S W 3 S	No	New Mexico Illinois England			None			
	Josephine	Daughter		S W 8m S	No	New Mexico Illinois England			None			
526 220 229	Hoot, James A.	Head	R 30 R	M W 28 M	No Yes	Pennsylvania United States Pennsylvania			Building Mgr Const Co 7720 W	Yes	Yes W&S	
	Wilvonne	Wife		M W 28 M	No Yes	New Mexico France Germany			None			
	Albert B.	Son		S W 6 S	Yes	New Mexico Pennsylvania New Mexico			None			
	Bobbie R.	Son		S W 4m S	No	New Mexico Pennsylvania New Mexico			None			
527 221 230	Koch, Aug. C.	Head	O 4500 R	M W 48 M	No Yes	New York Germany Germany			Laundry Prop Laundry 7297 W	Yes	No	
	Alice	Wife		M W 35 M	No Yes	Washington D.C. France France			None			
	Jonathon	Daughter		S W 3 S	No	Colorado New York Washington D.C.			None			
529 222 231	Leuchars, August L.	Head	R 35 R	M W 34 M	No Yes	Michigan Belgium Belgium			Fire Lngr Building 6381 W	yes	yes W&S	
	Helen C.	Wife		M W 27 M	No Yes	New Mex New York Missouri			None			
528 223 232	Bowker, Jorge	Head	R 33	M W 26 S	No Yes	Missouri Kansas Kansas			Bell Hop Hotel 4694 W	Yes	No	
	Hennings, Frances	Roomer		S W 23 S	No Yes	Texas Iowa Arkansas			None			
541 224 233	Roach, Ramona M.	Head	R 15	M W 48 Wd	No Yes	New Mexico New Mexico New Mexico			Clerk Shoe Store 1390 W	yes	No	
	Norman Johnny	Son		S W 2 S	No Yes	New Mexico New Mexico New Mexico			None			
	Andrew C Adelbert	Niece		S W 5 S	No	New Mexico New Mexico New Mexico			None			
544 225 234	Pino, Apolonio	Head	O 2500 R	M W 40 M	No Yes	New Mexico New Mexico New Mexico			Dealer Cannies 2791 O	yes	No	
	Manuelita R	Wife		M W 42 M	No Yes	New Mexico New Mexico New Mexico			None			
	Lizzie	Daughter		S W 14 S	No Yes	New Mexico New Mexico New Mexico			Clerk Grocery Store 2390 W	yes	No	
	Mary	Daughter		S W 12 S	No Yes	New Mexico New Mexico New Mexico			None			
	Apolonio Jr.	Son		S W 10 S	No Yes	New Mexico New Mexico New Mexico			None			
542 226 235	Lucero, Abel G.	Head	R 20	M W 21 M	No Yes	New Mexico New Mexico New Mexico			Weaver Blanket Mfr 7769 O	yes	7753 No	
	Nicolasa M.	Wife		M W 18 M	No Yes	New Mexico New Mexico New Mexico			None			
	Camilo	Son		S W 2m S	No Yes	New Mexico New Mexico New Mexico			Miner Gravel Work 7848 W	yes	No	
	Alfredo	Son		S W 1 S	No Yes	New Mexico New Mexico New Mexico			Shoe Shop Shoemaker 9969 W	yes		
	Elicio	Son		S W 10m S	No Yes	New Mexico New Mexico New Mexico			None			
	Lucy	Son		S W 1m S	No Yes	New Mexico New Mexico New Mexico			None			
	Amelia	Daughter		S W 10 S	Yes	New Mexico New Mexico New Mexico			None			
	Delfina	Daughter		S W 7 S	Yes	New Mexico New Mexico New Mexico			None			
	Olivia	Daughter		S W 6 S	No	New Mexico New Mexico New Mexico			None			
543 227 236	Rodriguez Gilberto	Head	R 15	M W 37 M	No Yes	New Mexico New Mexico New Mexico			Laborer General Work 7599 W	yes	yes W&S	
	Lucrecia	Wife		M W 32 M	No Yes	New Mexico New Mexico New Mexico			None			
	Felipe	Son		S W 11 S	yes	New Mexico New Mexico New Mexico			None			
	Salvador	Daughter		S W 8 S	yes	New Mexico New Mexico New Mexico			None			
	Rosa	Son		S W 7 S	yes	New Mexico New Mexico New Mexico			None			

ABBREVIATIONS TO BE USED IN COLUMNS INDICATED:

ENTRIES ARE REQUIRED IN THE SEVERAL COLUMNS AS FOLLOWS:

Ferdinand Adolph Koch Sr

28 January 1898–11 October 1982 • GSVD-3L5

Brief Life History of Ferdinand Adolph

When Ferdinand Adolph Koch Sr was born on 28 January 1898, in Denver, Colorado, United States, his father, Adolphe Christian Koch, was 24 and his mother, Alice Broche, was 22. He had at least 5 sons with Annie Kathleen Long. He lived in Election Precinct 28 Santa Fe, Santa Fe, New Mexico, United States in 1940. He died on 11 October 1982, in Santa Fe, Santa Fe, New Mexico, United States, at the age of 84, and was buried in Santa Fe, Santa Fe, New Mexico, United States.

MORE

Spouse and Children

Ferdinand Adolph Koch Sr
1898–1982

Annie Kathleen Long
1896–1982

Children (5)

Ferdinand Adolph Koch Jr
1924–2001

Robert Koch

Photos and Memories (0)

Do you know Ferdinand Adolph? Do you have a story about him that you would like to share? Sign In or Create a FREE Account

Sources (11)

Ferdinand A Koch, "United States, Census, 1950"

Ferdinand Adolph Koch, "New Mexico, World War II Draft Registration Cards, 1940-1945"

Ferdinand A Koch, "United States, Obituary

Family Time Line

Spouse and Children | Parents and Siblings

Parents and Siblings

Adolphe Christian Koch
1873–1939

Alice Broche
1875–1982

Siblings (2)

Ferdinand Adolph Koch Sr

4-17

REGISTRATION CARD—(Men born on or after February 17, 1897 and on or before December 31, 1921)

SERIAL NUMBER T 601 | 1. NAME (Print) FERDINAND (First) ADOLPH (Middle) KOCH. (Last) | ORDER NUMBER T 10248.

2. PLACE OF RESIDENCE (Print)
326 CORONADO RD. (Number and street) SANTA FE (Town, township, village, or city) SANTA FE (County) N.M. (State)

[THE PLACE OF RESIDENCE GIVEN ON THE LINE ABOVE WILL DETERMINE LOCAL BOARD JURISDICTION; LINE 2 OF REGISTRATION CERTIFICATE WILL BE IDENTICAL]

3. MAILING ADDRESS
P.O. BOX 129 SANTA FE, N. MEX.
[Mailing address if other than place indicated on line 2. If same insert word same]

4. TELEPHONE
743 (Exchange) (Number)

5. AGE IN YEARS 44
DATE OF BIRTH 1 (Mo.) 28 (Day) 1898 (Yr.)

6. PLACE OF BIRTH
DENVER (Town or county)
COLORADO (State or country)

7. NAME AND ADDRESS OF PERSON WHO WILL ALWAYS KNOW YOUR ADDRESS
MRS ALICE KOCH. 527 AGUA FRIA. SANTA FE.

8. EMPLOYER'S NAME AND ADDRESS
SELF.

9. PLACE OF EMPLOYMENT OR BUSINESS
SANTA FE ELECTRIC LAUNDRY. SANTA FE
(Number and street or R. F. D. number) (Town) (County) (State)

I AFFIRM THAT I HAVE VERIFIED ABOVE ANSWERS AND THAT THEY ARE TRUE.
Ferdinand Adolph Koch
(Registrant's signature)

D. S. S. Form 1 (Revised 1-1-42) (over) ☆ GPO 16—21630-2

REGISTRAR'S REPORT

DESCRIPTION OF REGISTRANT

RACE		HEIGHT (Approx.)		WEIGHT (Approx.)		COMPLEXION	
White	✓	6-		200		Sallow	
		EYES		HAIR		Light	✓
Negro		Blue		Blonde		Ruddy	
		Gray	✓	Red		Dark	
Oriental		Hazel		Brown		Freckled	
		Brown		Black		Light brown	
Indian		Black		Gray		Dark brown	
				Bald		Black	
Filipino				MIXED			

Other obvious physical characteristics that will aid in identification
SCAR R. ARM PIT.

I certify that my answers are true; that the person registered has read or has had read to him his own answers; that I have witnessed his signature or mark and that all of his answers of which I have knowledge are true, except as follows:

J. E. Doak
(Signature of registrar)

Registrar for Local Board 2. (Number) SANTA FE. (City or county) N. M. (State)

Date of registration 2-16-1942

Local Board No. 2 Santa Fe County
83 049
FEB 16 1942 002
Supreme Court Bldg. Santa Fe, New Mexico
(STAMP OF LOCAL BOARD)
(The stamp of the Local Board having jurisdiction of the registrant shall be placed in the above space)

16—21630-2



Osage Design Studio
Richard Woodbury
1216 Vitalia Street
Santa Fe, NM 87505
505.629.5948
osagedesignstudio@yahoo.com

November 7, 2025

Historic Preservation Division
Planning and Land Use Department
City Hall
200 Lincoln Avenue
Santa Fe, NM 87501

Address:	527 Agua Fria Street, Santa Fe NM 87501
Owners:	NEIRIKA LLC
Building Status:	Significant – To be determined
UPC:	1-053-099-521-161
Parcel No.:	11266176

On behalf of the applicant NEIRIKA LLC, I am submitting a **Request for Status Review** for 527 Agua Fria Street. The property is located within the Guadalupe Historic District. The site has two existing residential structures. The subject structure is a tri-plex to be converted into a duplex located at the front of the property facing Agua Fria Street. The rear structure is not part of the scope of this request; no work planned on the rear structure.

The project was originally submitted July 15, 2025 with an October 14, 2025 HDRB hearing scheduled. However, your division determined that the status of the subject building required a new review. I am requesting that the status review be placed on the December 9, 2025 HDRB hearing.

In addition, the most current Historic Cultural Properties Inventory (HCPI) dates from 1997. We were informed by your division that a new HCPI is required. A new HCPI is being prepared.

Per your email 11/6/25, you stated that if your division received this status request letter by 11/10/25 and the new HCPI by 11/30/25, the status review can be placed on the December 9, 2025 HDRB hearing agenda.

Please contact me if you have any questions or require additional information.

Sincerely,

Richard Woodbury

Richard Woodbury
Osage Design Studio

Attachments: 24x36 drawing set, existing site plan, floor plan & exterior elevations
Existing Building Photographs

HISTORIC CULTURAL PROPERTIES INVENTORY (HCPI)
BASE FORM

1. IDENTIFICATION

HCPI # NMCRIS # Project Name:527 Agua Fria Street Survey Date: November 25, 2025	Agency Number: Other #Old ID# 051613581; Santa Fe ID Number H1510 ☒Update
NAME OF PROPERTY Historic Name:243 Aqua Fria, 243/527 Agua Fria (Aqua Fria) Current Name:527 Agua Fria Street	OWNER and contact information:
SURVEYOR and contact information:Tina Reames; CSR Architects; 220 Gold Avenue SW; Albuquerque, NM 87102	
PROPERTY TYPE Category: ☒Building ☐Structure ☐Object ☐District ☐Site Subcategory: ☐Acequia/Historic Irrigation Ditch ☐Road/Trail ☐Other Linear	
LAND STATUS ☐ Federal ☐ State ☐ Local ☒ Private ☐ Other (land grant, tribal, etc.) Specify Other:	

2. LOCATION

STREET ADDRESS:527 Agua Fria Street CITY:Santa Fe, NM 87501 COUNTY:Santa Fe If no street address, describe how to locate the property:	UTM Coordinates:Hemisphere N Map-datum: NAD 83 Zone:13 E:414338.4 N:3949579.4 USGS Quad Name USGS Quad Code: Assessor Parcel #11266176 Local Reference #
SETTING	
Category: ☐Urban ☐Suburban ☐Rural ☐Village	Subcategory: ☐commercial ☐industrial ☒residential ☐public

3. PROPERTY DESCRIPTION

HISTORIC FUNCTION: Residence, Duplex (and for a time, a three-unit) residence CURRENT FUNCTION:Residence	CURRENT CONDITION: ☐intact ☒altered ☐deteriorated ☐other Describe:
CONSTRUCTION DATE: Before 1908 ☐Known ☒Estimated Source:1908 sanborn Fire Insurance Map ☒continuation	ARCHITECT/BUILDER:Unknown
BREIF DESCRIPTION OF PROPERTY:The property consists of a lot that is approximately 18,050 sf (.41 acres), located on the north side of Agua Fria Street, west of De Fouri Street. The house is located at the south end of the lot, along Agua Fria Street, and a small front yard, enclosed by a low adobe wall that has been stuccoed, is located between the front façade of the house and the sidewalk. North of the house is a small backyard surrounded by a wooden fence. A dirt and gravel drive runs along the east edge of the lot and to the north of the house. The house is a one-story, pitched roof, combination adobe and wood stud house that has been faced with a stucco finish. The back of the lot holds another single story smaller house (designated at 525 D Agua Fria Street).	

The front of the house entry is marked by a protruding front porch with arched screened front entry door. The front porch is not very visible from the street as the landscape is overgrown with evergreen trees. The rest of the south façade includes three sets of wood windows: central and nearest the front door is an 8/8/8 triple casement window, next to the west are two 8/8 double casement windows. All windows are trimmed with wood and painted a dark red/burgundy.

☐continuation

ACEQUIA/HISTORIC IRRIGATION DITCH:
Name of Acequia/Ditch Association:

HCPI #	NMCRIS #
Address of Property:527 Agua Fria Street	

ARCHITECTURAL STYLE: Check no more than 3 styles. Refer to HCPI Manual for additional style options.		
☐ Not Applicable	☐ International Style/Miesian	☐ Pueblo/Pueblo Vernacular
☐ Art deco	☐ Italiante/Bracketed	☐ Queen Anne
☐ Bungalow/Craftsman	☐ Mediterranean/Spanish Colonial Revival	☐ Ranch/Rambler
☐ Classical Revival/Neo-Classical Revival	☐ Mission Revival/California Mission Revival	☐ Southwest Vernacular
☐ Colonial Revival	☐ Modernism	☐ Spanish-Pueblo Revival
☐ Folk Victorian	☒ New Mexico Vernacular	☐ Territorial
☐ Gothic Revival/Folk Gothic	☐ Prairie School/Prairie Style	☐ Territorial Revival
☐ Other, describe:		

4. NATIONAL REGISTER/STATE REGISTER LISTING

A. National or State Register Listing:
Is the property individually listed in the State Register? ☐ Yes ☒ No
If yes, SR#
Is the property individually listed in the National Register? ☐ Yes ☒ No
Is the property part of a Register District? ☒ Yes ☐ No ☐ Unknown
If yes, is it ☒ Contributing ☐ Non-contributing
If not mentioned, in your opinion is the property: ☐ Contributing ☐ Non-contributing
District Name:Santa Fe Historic District District SR #260; District NR #73001150 in Santa Fe, the house is located within the "Westside-Guadalupe Historic District"
Is the property associated with a Multiple Property Documentation Form? ☐ Yes ☐ No ☒ Unknown
If yes: MPDF Name MPDF SR# MPDF theme

5. NATIONAL REGISTER/STATE REGISTER EVALUATION

A. Surveyor/Recorder Recommendations:
Name:Tina Reames Date:11/25/2025
National Register evaluation: ☐ eligible ☒ not eligible ☐ not sure
National Register eligibility criteria: ☐ a ☐ b ☐ c ☐ d ☒ criteria consideration: A) and B)
Research into the history of the building reveals that the house does not hold any special significance for its association with events or individuals on a local, regional, national, or global level. C) The building is a conglomeration of styles representing different periods in NM history, and therefore does not embody a particular type, period, or method of construction. Because there were so many changes to this house over the course of close to 50 years, there is not a high level of historic integrity to any specific historic period or type. D) It is unlikely that information important in history or prehistory will be yielded from this building or site.
Level of significance: ☒ local ☐ state ☐ national
Area of significance: subarea:
Is this property similar to other nearby properties? ☒ Yes ☐ No
Could it be contributing to an undefined district? ☒ Yes ☐ No
Discuss:The building is already considered to be contributing to the Santa Fe Historic District, listed on both the State and National Registers, and it is included in the Santa Fe Historic Preservation Divisions Westside-Guadalupe Historic District. If another district containing the site were defined, the building could be considered contributing.

B. Agency Determination:
Name: Date:
National Register evaluation: ☐ eligible ☐ not eligible ☐ undetermined
National Register eligibility criteria: ☐ a ☐ b ☐ c ☐ d ☐ criteria consideration:
Level of significance: ☐ local ☐ state ☐ national
Area of significance: subarea:
Could it be contributing to an undefined district? ☐ Yes ☐ No
Agency Remarks:

C. SHPO Determination:

Name: Date:

National Register evaluation: ☐ eligible ☐ not eligible ☐ undetermined

National Register eligibility criteria: ☐ a ☐ b ☐ c ☐ d ☐ criteria consideration:

Level of significance: ☐ local ☐ state ☐ national

Area of significance: subarea:

Could it be contributing to an undefined district? ☐ Yes ☐ No

SHPO Remarks:

HISTORIC CULTURAL PROPERTIES INVENTORY (HCPI)
DETAIL FORM

HCPI #	NMCRIS #
Address of Property:527 Agua Fria Street	

6. ARCHITECTURAL AND CONSTRUCTION DETAILS:

A. Visible Construction Materials

☒Adobe	☐Metal: Corrugated	☒Stucco
☐Brick	☐Masonry: Simulated	☐Tile: Clay
☐Composition Board	☐Metal: Structural Siding	☐Vinyl or Aluminum Siding
☒Concrete: Block	☐Metal: V-Crimp	☐Wood: Board & Batten
☐Concrete: Cast Stone	☐Stone: Random Ashlar	☐Wood: Horizontal Siding
☐Concrete: Poured	☐Stone: Random Coursed	☐Wood: Jacal
☐Concrete: Pre-cast	☐Stone: River Rock	☐Wood: Log
☐Curtain Wall	☐Stone: Rock Faced	☐Wood: Shingle
☐Earth Plaster	☐Stone: Tabular	☐Wood: Tongue and Groove

☒Other, describe:Wood stud, lath and plaster. Metal roofing.

B. Number of Stories

☐N/A ☒1 ☐1 ½ ☐2 ☐2 ½ ☐Other, describe:

C. Foundation

☐N/A ☒Not visible ☐None ☐At Grade ☐Raised

Materials: ☐Concrete: Poured ☐CMU ☐Stone ☐Other, describe:

Notes:

D. Roof

☐N/A Features: ☒Eave ☐Parapet

Shape: ☐Barrel ☐Butterfly ☐Flat ☒Cross Gable ☐Gable ☐Hipped ☐Pyramidal ☐Shed ☐Other, describe:

Pitch: ☐None ☒Low ☒Medium ☐Steep

Materials:

☐Asphalt	☐Metal: Corrugated	☒Tile: Metal
☐Composition Roll	☐Metal: Pressed	☐Tile:Terra Cotta
☐Composition Shingle	☒Metal: Standing Seam	☐Wood: Shingle
☐Earth	☐Metal: V-Crimp	

☒Other, describe:The original roof was a flat roof with drainage to the north. At some point, a gabled roof was added raising the elevations of the residence. It is not evident if this was a clay tile roof, but it now has a metal roof simulating a tile roof. The cross gable roof is offset. The lower metal roofs covering the front porches and side and back additions has a combination of metal tile and standing seam. The roof over the garage and connector is a low slope standing seam metal roof.

E. Chimneys

☐N/A Number Interior: Number Exterior:1

Construction Material: ☐Brick ☐Adobe ☐Stone ☒Stucco ☐Terra Cotta Tile ☒Metal Flue ☐Other, describe

F. Porches

☐N/A

Type: ☒Entry ☐Incised ☒Partial Width ☐Full-Width ☐Wrap ☐With a Gazebo

Other Details, describeAt the front entry, an extended covered area shields the front door to Suites 1 and 2. A later addition added a back enclosed porch with a low roof and large skylight.

HCPI #	NMCRIS #
Address of Property:527 Agua Fria Street	

G. Doorways

☐ N/A **Number of Doorways**:7

Type: ☒ One-leaf ☐ Two-leaf

Style: ☐ Diagonal Plank ☐ Dutch ☐ French ☐ Plain ☒ Panel ☐ Vertical Plank
☒ Other, describe:See sketches below

Components: Panels/Lights-Number and configuration
☐ Sidelights - number and configuration ☐ Transom

Material: ☐ Aluminum ☐ Fiberglass ☐ Metal ☐ Steel ☐ Vinyl ☒ Wood
☐ Other, describe

Depth of Reveal:varies

Notes:



South Elevation Doors #1, #2, and #3 North Elevation Doors #4, #5, #6, and #7

H. Window Openings

☐ N/A **Number of Window Openings**:21

Operation:	Material:	Glazing:		
☐ Awning	☒ Anodized Aluminum	☐ 1/1	☐ 2Pane Horizontal	☐ Curtain Wall
☒ Casement	☐ Bare Aluminum	☐ 2/2	☐ 2 Pane Vertical	☐ Glass Block
☒ Double or Single Hung	☐ Steel	☐ 3/1	☐ 3 Pane Vertical	☐ Palladian Motif
☒ Fixed	☐ Vinyl	☐ 4/4	☐ 4 Pane Vertical	☐ Picture Window
☐ Hopper	☒ Wood	☐ 6/6	☒ Combination, describe:	☐ Store Front or display
☐ Louver	☐ Other, describe:	☐ 9/9	☐ Grouped, describe:	☐ Other, describe:
☐ Pivot		☒ Other configuration, describe:The configuration of the windows varies. See elevations below.		
☒ Sliding t				

Depth of Reveal: varies among the different window types

Notes:



I. Other Significant Features

Describe: On the north side of the house there is a thickened wall with decorative tile where a fountain may have been.

7. Associated Properties

Discuss:N/A

Are associated properties eligible for listing?No

8. Documents Available and Their Locations

Discuss: Sanborn Fire Insurance Maps attached (April 1908, June 1913, June 1921, January 1930); King's Official Map of the City of Santa Fe (1912); 1997 NM Historic Building Inventory forms; 2024 Santa Fe County Tax Parcel Viewer

9. Attachments

Please indicate which items are attached:

- ☒ Site Plan (required)
- ☒ Photos (required)
- ☒ Map or aerial photo (required)
- ☒ Continuation sheet (Word document), if necessary
- ☐ Additional detail forms for associated properties, if applicable

Historic Cultural Properties Inventory (HCPI) Continuation Sheet

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____		
1. Name of property: (historic and/or current name for property) **527 Agua Fria Street** **Previously 243 Aqua Fria Street; 243/527 Agua Fria (Aqua Fria) Street**	**2. Location:** **527 Agua Fria Street** **Santa Fe, NM 87501**	**3. Local Reference Number:** **4. County** **Santa Fe** **5. Date of Survey** **November 25, 2025**

Construction Date, Timeline of House, and Inferred Evolution of House Graphic:

There have been several additions and renovations to this building over time. Based on historic maps and the previous Historic Building Inventory forms (1997), it is estimated that there have been at least four additions to the original house.

- The original house was built sometime before 1908.
- It is estimated that the outhouse at the rear of the lot was constructed during the same timeframe (before 1908).
- An addition was constructed at the rear of the house (northeast side) sometime after 1908 and before 1913.
- A much larger addition was constructed at the west side of the house sometime after 1913 and before 1921. (Note: the new southwest corner of the house is constructed of adobe.) A covered front porch was added at the southeast corner of the house.
- Another large addition was added to the back of the house, possibly an enclosed back porch with lower roof. A separate garage was added to the west and access to a cellar on the east side of the house sometime after 1921 and before 1930. (Note: the location of the house appears to be further east.)



1908 Sanborn Map



1913 Sanborn Map



1921 Sanborn Map



1930 Sanborn Map

- It is estimated that the double gable roof was added after 1930 and a small restroom addition was added at the top of the cellar stair on the northeast corner of the house.
- The 2024 Santa Fe County Tax Parcel Viewer shows the property divided into three units.



1998 SF County Assessor Sketch



2024 SF County Tax Parcel View

- The image below is an enlarged image of the 1912 King's Official Map of the City of Santa Fe, NM indicating property ownership - Mrs. C. W. Dudrow

Historic Cultural Properties Inventory (HCPI) Continuation Sheet

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____		
1. Name of property: (historic and/or current name for property) 527 Agua Fria Street Previously 243 Aqua Fria Street; 243/527 Agua Fria (Aqua Fria) Street	**2. Location:** 527 Agua Fria Street Santa Fe, NM 87501	**3. Local Reference Number:** **4. County** Santa Fe **5. Date of Survey** November 25, 2025

Site Plan:



527 Agua Fria Site Plan, Drawn by Osage Design Studio, 9/1/25

Historic Cultural Properties Inventory (HCPI) Continuation Sheet

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____		
1. Name of property: (historic and/or current name for property) 527 Agua Fria Street Previously 243 Aqua Fria Street; 243/527 Agua Fria (Aqua Fria) Street	**2. Location:** 527 Agua Fria Street Santa Fe, NM 87501	**3. Local Reference Number:** **4. County** Santa Fe **5. Date of Survey** November 25, 2025

Photographs of Building and Site:

See 7 pages of exterior building photographs by Osage Design Studio; 45 pages of window assessment by RPA & Associates, LLC that follow.

North Elevation - northeast corner of house - thickened wall at exterior with decorative tile and broken spigot (remnants of a fountain)

527 Agua Fria Street
Existing Exterior Photographs
6/30/25

1 - South Façade (facing Agua Fria)

2 - South Façade showing west face of structure

3 - South Façade (facing Agua Fria)

4 - South Façade (facing Agua Fria)

5 - East Façade (southeast corner)

6 - East Façade

7 - North Façade (northeast corner)

8 – North Facade

9 - North Facade

10 - North Façade

11 - North Façade

12 - North Façade (northwest corner)



Agua Fria Street

Photo Key Plan

Plan North

Historic Cultural Properties Inventory (HCPI) Continuation Sheet

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____		
1. Name of property: (historic and/or current name for property) 527 Agua Fria Street Previously 243 Aqua Fria Street; 243/527 Agua Fria (Aqua Fria) Street	**2. Location:** 527 Agua Fria Street Santa Fe, NM 87501	**3. Local Reference Number:** **4. County** Santa Fe **5. Date of Survey** November 25, 2025

Aerial Photograph:

Historic Cultural Properties Inventory (HCPI) Continuation Sheet

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____		
1. Name of property: (historic and/or current name for property) 527 Agua Fria Street Previously 243 Aqua Fria Street; 243/527 Agua Fria (Aqua Fria) Street	**2. Location:** 527 Agua Fria Street Santa Fe, NM 87501	**3. Local Reference Number:** **4. County** Santa Fe **5. Date of Survey** November 25, 2025

527 Agua Fria House Historic Research Synopses, Timeline of House, and Bibliography

See 12 pages of research synopses, etc. that follow.

527 Agua Fria House Research Synopses

Per King's and Sanborn Fire Insurance Maps:

243 Aqua Fria was built sometime before 1908. Based on the historic maps, the original portion of the existing building is the middle portion of the front rectangular façade that faces the street today. (Refer to building footprint graphic for more information.) The original building underwent a renovation and addition to the east and rear of the house sometime after 1912 and before 1913. An addition was added to the west sometime after 1913 and before 1921. A front porch was also added. Between 1921 and 1930, the footprint of the building moves to allow more space between the lot line and the main house. (There appears to have been an error in the original location of the dwelling.) On the 1930 Sanborn Map, the footprint of the building was changed from three simple rectangles to a blocky almost square footprint with the addition of a garage and the outhouse was removed. The address label for the building was changed from 243 Aqua Fria to 527 Agua Fria and the lot line had changed, reducing the lot size from east to west. The footprint of the building remained the same on the 1948 revision to the 1930 Sanborn Map. The current footprint of the building, which adds a restroom to the northeast corner and a connector from the main house to the garage, shows that one or more additions were constructed onto the building after 1985 but before 1998. Based on the research materials available, it is not entirely clear when the other additions were constructed, but it is inferred that all additions to the building and the garage were completed prior to 1998. Refer to the 1985 and 1997 Historic Building Inventory Forms section below.

Per the 1985 and 1997 Historic Building Inventory Forms:

The building was described in previous Historic Building Inventory forms – in 1985 and then resurveyed in 1997. There are some inconsistencies between the 1985 form and the 1997 and the Sanborn maps indicating the development of the house.

On the 1985 form, 527 Agua Fria (ID No. 051613581) is drawn with the main house separate from the garage that matches the 1930 and 1948 Sanborn Maps but with a protruding front porch addition. In addition, the surveyor of the 1997 form included a comment about the garage: "connected to the house by arched stucco gateway."[1] This gateway was not shown on either survey site plans. Based on the former survey, it is assumed that the addition joining the garage to the main house was constructed after 1985 but before 1998.

Both 1985 and 1997 forms note the “Mediterranean” style, but do not note that the original building was flat roofed. The 1985 form notes that the significance of the building is "of interest," and that the building should be eligible because it is "contributing."[2] It is to be noted that this 1985 survey form was the survey used to determine whether or not the building should be considered "contributing" in the Santa Fe Historic District (refer to the Santa Fe Historic District Section that follows).

On the 1997 form, the building is noted as being listed on the National Register of Historic Places, as being a contributing property, and as being listed on the State Register of Cultural Properties. While it is

[1] DB, “New Mexico Historic Building Inventory - Santa Fe Resurvey 1997, 527 Agua Fria,” August, 1997.
[2] HMW, “527 Agua Fria Building Survey Form,” June, 1985.

true that the building is contributing to the Santa Fe Historic District (See Santa Fe Historic District section that follows), the building is not listed individually on either the State Register of Cultural Properties or on the National Register of Historic Places. (Refer to SR-NR-Excel-Database-through-June-2016.xlsx file provided by the NM HPD for a list of individual properties and districts included on the State and National Registers).

On the 1985 form, the building is also noted as having had moderate remodeling and the 1997 form lists the degree of remodeling as minor.

Santa Fe Historic District

Per the 1973 National Register of Historic Places Inventory – Nomination Form:

The Santa Fe Historic District was added to the State Register on September 29, 1972 (State Register #260) and to the National Register on July 23, 1973 (National Register # 73001150). 527 Agua Fria is included as a contributing property in the Santa Fe Historic District, based on the 1997 survey of the property (mentioned above).

Ownership of the House:

On the 1912 King's Map, the building is marked as Block 60, Lot 34, and is attributed to Mrs. C. W. Dudrow.

From the 1985 Historic Building Inventory Form, included a comment: "A. C. Koch bought this in 1912 from C.W. Dudrow Estate. He added tile Rf in 1920-25. House has grown @ rear – N.V." [3]

Between 1913 and 1927, no information regarding the ownership of the house was found.

From 1928 through 1964, A.C. Koch or a Koch family member is listed as the owner of the property (per Santa Fe City Directories). There is also a Mrs. Dorothea K Dunakin (nurse) associated with the property either as a tenant or owner from 1944 through 1951.

- Between 1928 and 1938, the owner is listed as Koch, A. C.
- Between 1940 and 1944, the owner is listed as Koch, A. C. Mrs.
- Between 1944 and 1947, the owner is listed as Koch, A. C. Mrs. and Dunakin D. K. Mrs. nurse
- Between 1947 and 1949, the owner is listed as Koch, Alice Mrs. and Dunakin D. K. Mrs. nurse
- Between 1949 and 1951, the owner is listed as Koch, Alice Mrs. and Dunakin Dorothea K. Mrs. nurse
- Between 1951 and 1964, the owner is listed as Koch, Alice A. and Dunakin Dorothea K. Mrs. nurse
- In 1964, the owner is listed as Koch, Alice C. Mrs.

It is unknown when the Koch family sold the house.

On December 19, 2024, the house was sold.[4]

[3] HMW, "527 Agua Fria Building Survey Form," June, 1985.
[4] https://www.zillow.com/homedetails/527-Agua-Fria-St-Santa-Fe-NM-87501/6826806_zpid/

According to the Santa Fe County Tax Parcel Viewer, Neirika LLC is the owner of the house.

Review of Architectural Features and Styles of the House and Site:

The existing house is a compilation of pieces that were added on and renovated over the course of approximately ninety years. The various additions and renovations add different styles to the house.

Original Portion of the House: The original portion (pre-1908) may have followed many of the stylistic patterns of a New Mexico vernacular house. Whether Spanish Colonial or Territorial Style which was primarily in use in New Mexico during the mid to late nineteenth century, and featured flat roofs, adobe construction, new milled lumber elements and fired brick detailing, along with the inclusion of provincial Greek Revival Style elements, the original portion of the house is constructed of wood stud framed walls, which have been faced with stucco. A small outhouse was added in the rear. It is unknown when the north thickened wall and fountain were added to the house. This appears to be more Mediterranean in style. It is also unknown when the low adobe wall that wraps the front yard was added to the house.

Minor Addition #1: Between 1908 and 1913, a small addition was added to the northeast corner of the house.

Major Renovation/Addition #2: A significant renovation and addition was done at the house prior to 1921. It is assumed that part of the work of this project was completed in adobe construction, as the front southwest corner remains an 8" thick adobe constructed wall. Another part of the renovation of the house is thought to have included a front porch at the main entry. The windows and doors are typically wood units painted red. It appears that many of these units are the original ones installed when the main house and addition were built. The majority of the windows and doors have divided lites, square red wood trim, and the windows have square sills. All windows appear to be operable, inward swinging casement windows with a few double hung on the north side of the building.

Major Addition #3: It is possible that the third addition actually included more than one addition and interior remodeling over the course of approximately ten years including the addition of the pitched Mediterranean style tile roof. From what we can deduce, the third addition (post-1921) included the portion added onto the north and east side stair to a cellar, as well as the separate garage building. The rear porch addition may have been open to air or screened. The roof was a low slope. It is unknown whether the garage and porch had windows as it is apparent that the aluminum slider windows were added later.

The Garage: The garage is constructed of rusticated or split face narrow and long concrete masonry units. The roof is a flat roof and has a very low slope. It is unknown what the original material was but now is covered with a standing seam metal roof.

Major Renovation/Addition #4: It is possible that the fourth addition and renovation included the subdivision of the house into three separate dwelling units. The garage was connected to the main house and the back porch was enclosed. A small restroom was added to the northeast corner to serve

another tenant. Exterior entry doors were added for three separate entries. Metal roofs replaced the tile roofs, but simulated the look with red metal. The smaller additions have standing seam red metal roofs, while the main house and upper roofs have simulated metal tile red roofing.

Fences and Walls: There is little to no information regarding the existing fences and walls around the site. A low adobe wall (+/- 3' to 4' high) wraps the front yard. The low wall is not connected to the house on either edge, and has a break in the middle through which the front doors can be accessed. It is likely that the low adobe wall was added during either the first or the second addition to the house. On the east side of the building, the lot line is defined by a low wooden picket fence supported by square wood posts (approximately 4" x 4"). This fence was added sometime after the lot line was changed to its current position in 1930. It is adorned with a growing vine. A low adobe wall turning into a wooden coyote fence runs along much of the west edge of the site, but appears to be associated with the neighboring building. At the north side, individual back yards for the tenants are defined by a 6'-0" tall wooden picket fence. This fence was likely added much later on to provide privacy and security from vehicles parking in the rear of the lot.

Santa Fe Historic Preservation Division Definitions of Noncontributing, Contributing, and Significant Structures in a Historic District: [5]

- **NONCONTRIBUTING STRUCTURE:** A structure, located in an Historic District, which is less than fifty years old and/or does not exhibit sufficient historic integrity to establish and maintain the character of the Historic District. (Ord. No. 2004-26 §6)

- **CONTRIBUTING STRUCTURE:** A structure, located in a Historic District, approximately 50 years old or older that helps to establish and maintain the character of the Historic District. Although the structure is not unique in itself, it adds to the historic associations and/or historic architectural design qualities for which a District is significant. The structure may have had minor alterations, however, its integrity remains. (Ord. 2004-26 § 5)

- **SIGNIFICANT STRUCTURE:** A structure, located in an Historic District, that is approximately 50 years old or older, and (1) embodies distinctive characteristics of a type, period or method of construction. A structure may also be designated as significant (2) for its association with events or individuals that are important on a local, regional, national, or global level. In order for a structure to be designated as significant, (3) it must retain a high level of historic integrity. A structure may also be significant (4) if it is listed in or is eligible to be listed in the State Register of Cultural Properties or the National Register of Historic Places. (Ord. No. 2004-26 §5)[6]

[5] Santa Fe Historic Preservation Division, "Historic Preservation Definitions," City of Santa Fe Website, accessed May 5, 2017, http://www.santafenm.gov/historic_preservation_definitions.
[6] (x) Numbers in gray added for clarity of response. See "Architectural Historian Opinion" section that follows.

National Register Criteria for Evaluation (For Determination of Building's Eligibility):[7]

Per Santa Fe Historic Preservation Division definition of "Significant Structure" above, listing on either the State or National Registers is one criteria by which a structure can be considered significant within a historic district for the Santa Fe Historic Preservation Division. For that reason, we include the US Department of the Interior's Criteria for Evaluation of a historic property, along with the Criteria Considerations.

- **Criteria for Evaluation:** The quality of significance in American history, architecture, archeology, engineering, and culture is present in districts, sites, buildings, structures, and objects that possess integrity of location, design, setting, materials, workmanship, feeling, and association, and:
    A. That are associated with events that have made a significant contribution to the broad patterns of our history; or
    B. That are associated with the lives of significant persons in our past; or
    C. That embody the distinctive characteristics of a type, period, or method of construction, or that represent the work of a master, or that possess high artistic values, or that represent a significant and distinguishable entity whose components may lack individual distinction; or
    D. That have yielded or may be likely to yield, information important in history or prehistory.

- **Criteria Considerations:** Ordinarily cemeteries, birthplaces, graves of historical figures, properties owned by religious institutions or used for religious purposes, structures that have been moved from their original locations, reconstructed historic buildings, properties primarily commemorative in nature, and properties that have achieved significance within the past 50 years shall not be considered eligible for the National Register. However, such properties will qualify if they are integral parts of districts that do meet the criteria or if they fall within the following categories:
    a. A religious property deriving primary significance from architectural or artistic distinction or historical importance; or
    b. A building or structure removed from its original location but which is primarily significant for architectural value, or which is the surviving structure most importantly associated with a historic person or event; or
    c. A birthplace or grave of a historical figure of outstanding importance if there is no appropriate site or building associated with his or her productive life; or
    d. A cemetery that derives its primary importance from graves of persons of transcendent importance, from age, from distinctive design features, or from association with historic events; or
    e. A reconstructed building when accurately executed in a suitable environment and presented in a dignified manner as part of a restoration master plan, and when no other building or structure with the same association has survived; or
    f. A property primarily commemorative in intent if design, age, tradition, or symbolic value has invested it with its own exceptional significance; or

[7] Rebecca H. Shrimpton, ed., "How to Apply the National Register Criteria for Evaluation" (U.S. Department of the Interior, National Park Service, Cultural Resources, 1995), https://www.nps.gov/nr/publications/bulletins/nrb15/Index.htm.

g. A property achieving significance within the past 50 years if it is of exceptional importance.

Historic Architect's Opinion:

In response to criteria for a "Significant Structure," – see numbers in gray added to definition above:

(1) The building is a conglomeration of styles representing different periods in NM history, and therefore does not embody a particular type, period, or method of construction.

(2) Based on the research into the history of the building, including past owners, and residents of the house, the house was owned by Charles W. Dudrow, a 19th century entrepreneur in Santa Fe, who was engaged in the lumber, coal, ice, transfer and livery business. His legacy is connected to several historic locations, including the Dudrow House at 548 Agua Fria Street and an old warehouse that was later part of the Sanbusco Market, now part of the New Mexico School for the Arts complex. The house at 527 Agua Fria was part of the Dudrow Estate, but its significance is unknown for the Westside-Guadalupe Historic District "for its association with events or individuals that are important on a local, regional, national, or global level." The house was owned primarily by C. W. Dudrow for a short period of time before sold to A. C Koch in 1912.

(3) Because there were so many changes to this house over time, there is not a high level of historic integrity to any specific historic period or type.

(4) The building is not individually listed on either the State Register of Cultural Properties or on the National Register of Historic Places. While it is included as a contributing property in the Santa Fe Historic District, it is our opinion, for similar reasons to those listed in items (1) through (3) above, that the building would not be eligible for inclusion on either the State or National Registries.

Based on our findings, and on the Santa Fe Historic Preservation Division definitions included above, we recommend that the building continue to be designated as "Contributing."

Timeline for 512 Agua Fria House:

1846-1880 **Territorial Style** first appears in NM; features include traditional flat-roofed buildings, adobe construction, new milled lumber elements and fired bricks, and provincial Greek Revival style elements.

1869-1872 **Charles W. Dudrow,** came to Santa Fe. He had been a driver for the Barlow and Sanderson stage lines that ran from Pueblo, Colorado, to Santa Fe. [8]

1881 **Dudrow & Bear Ice, Transfer and Livery.** When Charles W. Dudrow arrived in Santa Fe he married Cora Bear and became a business partner with her father, Samuel Bear. The business was located near the train depot and Our Lady of Guadalupe Church. [9]

1908 The house appears on the April, 1908 Sanborn Map as three small rectangles with a smaller rectangle to the north. The house has the following markings: 1'2, D, and a small x in the right hand corners of each rectangle. The address is 243 Aqua Fria.[10]

1910 **Charles W. Dudrow – Kerr's Plaza Barber Shop** advertisement in the Santa Fe New Mexican, page 2, Tuesday, October 11, 1910. [11]

1911 **C. W. Dudrow** appears on the Fairview Cemetery Santa Fe history under Pioneer Merchants and Other Notable Businesspeople. (Approximate birth year is 1849).[12]

1912 The house appears on the 1912 Kings Map as the same three small rectangles (only shown as a polygon) with a smaller rectangle to the north. The property is listed as Block 60, Lot 34. A name is written on the lot. (Mrs. C. W. Dudrow)[13]

1913 The house appears on the June, 1913 Sanborn Map as the same three small rectangles only the top northeast corner of the third rectangle has an addition. The smaller rectangle is still located to the north. The house has the following markings: 1, D, Stucco, and a small black dot in the lower right of the two larger rectangles. The address is 243 Aqua Fria.[14]

1921 The house appears on the June, 1921 Sanborn Map as the same three small rectangles now with another larger rectangle added to the west. The smallest rectangle is still located to the north. The house has the following markings: 1, D, Stucco, and a small black dot in the lower right of the three large rectangles. A smaller dashed rectangle runs horizontally at the front of the house facing the street. The address is 243 Aqua Fria.[15]

[8] "Dudrow & Company" by Ana Pacheco, https://historyinsantafe.com/santa-fe-railyard-history/
[9] "Dudrow & Company" by Ana Pacheco, https://historyinsantafe.com/santa-fe-railyard-history/
[10] "Sanborn Fire Insurance Map, April 1908" (Santa Fe County, NM: Sanborn Map Company, 1908).
[11] "Santa Fe New Mexican", advertisement, https://files.core.ac.uk/download/pdf/217579931.pdf
[12] Fairview Cemetery Santa Fe website, https://www.fairviewcemeterysantafe.org/history/
[13] "King's Official Map of the City of Santa Fe, New Mexico" (Santa Fe, NM, 1912).
[14] "Sanborn Fire Insurance Map, June 1913" (Santa Fe County, NM: Sanborn Map Company, 1913).
[15] "Sanborn Fire Insurance Map, June 1921" (Santa Fe County, NM: Sanborn Map Company, 1921).

1928-1929 **Koch A C** is listed as owning the house (address marked as 527 Agua Fria). (o) following the name shows the occupant is owner of the home. This is given as an indication of permanency, but have not been checked by the official records. [16]

1930 The house appears on the January, 1930 Sanborn Map.[17]

- The house is now a large polygon appearing to have had a smaller rectangular addition to the east and larger area filled in to the northwest. The front dashed area has decreased at the southeast corner and an additional dashed protruding rectangle has been added. A large rectangle has been added to the west separate from the main polygon.
- The address is listed as 243, and also 527 Agua Fria (Aqua Fria).
- The markings say 1, D, small black circle in each of the small rectangular spaces. The separate rectangle has a 1, A (C.B) and three small black dots. There are black X's on the south, east, and north walls.
- The smallest rectangle to the north is now removed.
- A new lot line to the east has been drawn. There is a small adobe building and larger "r" shaped dwelling in the adjacent lot to the east.

1930-1931 **Koch A C** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following the name indicates the householder is the owner of the residence. [18]

1932-1933 **Koch A C** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following the name indicates the householder is the owner of the residence.[19]

1934-1935 **Koch A C** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following the name indicates the householder is the owner of the residence.[20]

1936-1937 **Koch A C** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following a householder's name indicates that we have received information during the canvass that the house is owned by some member of the family, but as the publisher cannot and does not guarantee the correctness of the information furnished, nor the complete absence of mistakes no responsibility for errors can be or is assumed, nor can the publisher furnish further information than that shown.[21]

---

[16] *Hudspeth Directory Company's Santa Fe City Directory, 1928-1929* (El Paso, TX: Hudspeth Directory Company, Inc., 1928).
[17] "Sanborn Fire Insurance Map, January 1930" (Santa Fe County, NM: Sanborn Map Company, 1930).
[18] *Hudspeth Directory Company's Santa Fe City Directory, 1930-1931* (El Paso, TX: Hudspeth Directory Company, Inc., 1930).
[19] *Hudspeth Directory Company's Santa Fe City Directory, 1932-1933* (El Paso, TX: Hudspeth Directory Company, Inc., 1932).
[20] *Hudspeth Directory Company's Santa Fe City Directory, 1934-1935* (El Paso, TX: Hudspeth Directory Company, Inc., 1934).
[21] *Hudspeth Directory Company's Santa Fe City Directory, 1936-1937* (El Paso, TX: Hudspeth Directory Company, Inc., 1936).

1938 **Koch A C** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following a householder's name indicates that we have received information during the canvass that the house is owned by some member of the family, but as the publisher cannot and does not guarantee the correctness of the information furnished, nor the complete absence of mistakes no responsibility for errors can be or is assumed, nor can the publisher furnish further information than that shown.[22]

1940 **Koch A C Mrs** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following a householder's name indicates that we have received information during the canvass that the house is owned by some member of the family, but as the publisher cannot and does not guarantee the correctness of the information furnished, nor the complete absence of mistakes no responsibility for errors can be or is assumed, nor can the publisher furnish further information than that shown.[23]

1942 **Koch A C Mrs** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following a householder's name indicates that we have received information during the canvass that the house is owned by some member of the family, but as the publisher cannot and does not guarantee the correctness of the information furnished, nor the complete absence of mistakes no responsibility for errors can be or is assumed, nor can the publisher furnish further information than that shown.[24]

1944 **Koch A C Mrs** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following a householder's name indicates that we have received information during the canvass that the house is owned by some member of the family, but as the publisher cannot and does not guarantee the correctness of the information furnished, nor the complete absence of mistakes no responsibility for errors can be or is assumed, nor can the publisher furnish further information than that shown.

An additional name is also listed - **Dunakin D K Mrs nurse**. It is unknown if this person is a tenant or someone living in the main residence.[25]

1947 **Koch Alice Mrs** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following a householder's name indicates that we have received information during the canvass that the house is owned by some member of the family, but as the publisher cannot and does not guarantee the correctness of the information furnished, nor the complete absence of mistakes no responsibility for errors can be or is assumed, nor can the publisher furnish further information than that shown.

An additional name is also listed - **Dunakin D K Mrs nurse**. It is unknown if this person is a tenant or someone living in the main residence.[26]

[22] *Hudspeth Directory Company's Santa Fe City Directory, 1938* (El Paso, TX: Hudspeth Directory Company, Inc., 1938).
[23] *Hudspeth Directory Company's Santa Fe City Directory, 1940* (El Paso, TX: Hudspeth Directory Company, Inc., 1940).
[24] *Hudspeth Directory Company's Santa Fe City Directory, 1942* (El Paso, TX: Hudspeth Directory Company, Inc., 1942).
[25] *Hudspeth Directory Company's Santa Fe City Directory, 1944* (El Paso, TX: Hudspeth Directory Company, Inc., 1944).

1949 **Koch Alice Mrs** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following a householder's name indicates that we have received information during the canvass that the house is owned by some member of the family, but as the publisher cannot and does not guarantee the correctness of the information furnished, nor the complete absence of mistakes no responsibility for errors can be or is assumed, nor can the publisher furnish further information than that shown.

An additional name is also listed - **Dunakin Dorothea K Mrs nurse**. It is unknown if this person is a tenant or someone living in the main residence.[27]

1951 **Koch Alice A** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following a householder's name indicates that we have received information during the canvass that the house is owned by some member of the family, but as the publisher cannot and does not guarantee the correctness of the information furnished, nor the complete absence of mistakes no responsibility for errors can be or is assumed, nor can the publisher furnish further information than that shown.

An additional name is also listed - **Dunakin Dorothea K Mrs nurse**. It is unknown if this person is a tenant or someone living in the main residence.[28]

1964 **Koch Alice C Mrs** is listed as owning the house (address marked as 527 Agua Fria). An (o within an O) following a householder's name indicates that we have received information during the canvass that the house is owned by some member of the family, but as the publisher cannot and does not guarantee the correctness of the information furnished, nor the complete absence of mistakes no responsibility for errors can be or is assumed, nor can the publisher furnish further information than that shown.[29]

1972-1973 **Santa Fe Historic District**, which includes 527 Agua Fria as a contributing property, was added to the State Register of Cultural Properties and National Register of Historic Places.[30]

1985 NM Historic Preservation Division survey for 527 Agua Fria.[31]

1997 NM Historic Building Inventory – Santa Fe Resurvey form for 527 Agua Fria completed.[32]

2024 House listed and sold.

---

[26] *Hudspeth Directory Company's Santa Fe City Directory, 1947* (El Paso, TX: Hudspeth Directory Company, Inc., 1947).
[27] *Hudspeth Directory Company's Santa Fe City Directory, 1949* (El Paso, TX: Hudspeth Directory Company, Inc., 1949).
[28] *Hudspeth Directory Company's Santa Fe City Directory, 1951* (El Paso, TX: Hudspeth Directory Company, Inc., 1951).
[29] *Hudspeth Directory Company's Santa Fe City Directory, 1964* (El Paso, TX: Hudspeth Directory Company, Inc., 1964).
[30] James H. Purdy, "National Register of Historic Places Inventory - Nomination Form, Santa Fe Historic District" (NM Historic Preservation Division, July 23, 1973).
[31] HMW, "527 Agua Fria Building Survey Form," June, 1985.
[32] DB, "New Mexico Historic Building Inventory - Santa Fe Resurvey 1997, 527 Agua Fria," August, 1997.

Bibliography

"Charles W. Dudrow Burial Record." Find A Grave Memorial, November 30, 2025. https://www.findagrave.com/memorial/28979872/charles-w-dudrow

DB. "New Mexico Historic Building Inventory - Santa Fe Resurvey 1997, 527 Agua Fria," August, 1997.

"Dudrow & Company." By Ana Pacheco. https://historyinsantafe.com/santa-fe-railyard-history/

Fairview Cemetery Santa Fe website, https://www.fairviewcemeterysantafe.org/history/

HMW. "527 Agua Fria Building Survey Form," June, 1985.

Hudspeth Directory Company's Santa Fe City Directory, 1928-1929. El Paso, TX: Hudspeth Directory Company, Inc., 1928.

Hudspeth Directory Company's Santa Fe City Directory, 1930-1931. El Paso, TX: Hudspeth Directory Company, Inc., 1930.

Hudspeth Directory Company's Santa Fe City Directory, 1932-1933. El Paso, TX: Hudspeth Directory Company, Inc., 1932.

Hudspeth Directory Company's Santa Fe City Directory, 1934-1935. El Paso, TX: Hudspeth Directory Company, Inc., 1934.

Hudspeth Directory Company's Santa Fe City Directory, 1936-1937. El Paso, TX: Hudspeth Directory Company, Inc., 1936.

Hudspeth Directory Company's Santa Fe City Directory, 1938. El Paso, TX: Hudspeth Directory Company, Inc., 1938.

Hudspeth Directory Company's Santa Fe City Directory, 1940. El Paso, TX: Hudspeth Directory Company, Inc., 1940.

Hudspeth Directory Company's Santa Fe City Directory, 1942. El Paso, TX: Hudspeth Directory Company, Inc., 1942.

Hudspeth Directory Company's Santa Fe City Directory, 1944. El Paso, TX: Hudspeth Directory Company, Inc., 1944.

Hudspeth Directory Company's Santa Fe City Directory, 1947. El Paso, TX: Hudspeth Directory Company, Inc., 1947.

Hudspeth Directory Company's Santa Fe City Directory, 1949. El Paso, TX: Hudspeth Directory Company, Inc., 1949.

Hudspeth Directory Company's Santa Fe City Directory, 1951. El Paso, TX: Hudspeth Directory Company, Inc., 1951.

Hudspeth Directory Company's Santa Fe City Directory, 1964. El Paso, TX: Hudspeth Directory Company, Inc., 1964.

James H. Purdy. "National Register of Historic Places Inventory - Nomination Form, Santa Fe Historic District." NM Historic Preservation Division, July 23, 1973.

"King's Official Map of the City of Santa Fe, New Mexico." Santa Fe, NM, 1912.

Rebecca H. Shrimpton, ed. "How to Apply the National Register Criteria for Evaluation." U.S. Department of the Interior, National Park Service, Cultural Resources, 1995. https://www.nps.gov/nr/publications/bulletins/nrb15/Index.htm.

"Sanborn Fire Insurance Map, April 1908." Santa Fe County, NM: Sanborn Map Company, 1908.

"Sanborn Fire Insurance Map, January 1930." Santa Fe County, NM: Sanborn Map Company, 1930.

"Sanborn Fire Insurance Map, January 1930 Correction Reprint August 1948." Santa Fe County, NM: Sanborn Map Company, 1948.

"Sanborn Fire Insurance Map, June 1913." Santa Fe County, NM: Sanborn Map Company, 1913.

"Sanborn Fire Insurance Map, June 1921." Santa Fe County, NM: Sanborn Map Company, 1921.

"Santa Fe County 1969 Aerial Photograph." NM Department of Transportation, February 27, 1969.

"Santa Fe County Tax Parcel Viewer", https://sfcomaps.santafecountynm.gov/mapsvc/apps/webappviewer/index.html?id=212072bb5f18440f82d843a31515b714

Santa Fe Historic Preservation Division. "Historic Preservation Definitions." City of Santa Fe Website. Accessed May 5, 2017. http://www.santafenm.gov/historic_preservation_definitions.

"Santa Fe New Mexican" advertisement, https://files.core.ac.uk/download/pdf/217579931.pdf

Zillow Showcase Listing, https://www.zillow.com/homedetails/527-Agua-Fria-St-Santa-Fe-NM-87501/6826806_zpid/

Historic Cultural Properties Inventory (HCPI) Continuation Sheet

Historic Preservation Division, New Mexico Department of Cultural Affairs

For HPD Office use only: HCPI No._____ District No._____		
1. Name of property: (historic and/or current name for property) **527 Agua Fria Street** **Previously 243 Aqua Fria Street; 243/527 Agua Fria (Aqua Fria) Street**	**2. Location:** **527 Agua Fria Street** **Santa Fe, NM 87501**	**3. Local Reference Number:** **4. County** **Santa Fe** **5. Date of Survey** **November 25, 2025**

Historic Sanborn Maps:

See 8 pages of Sanborn Maps that follow.
Sanborn Maps includes:

- April 1908
- June 1913
- June 1921
- January 1930
- August 1948 Revision to January 1930 Map















STREETS

A A A
Abbott Ave. 100 200 200 23 5 4
Acme Alley 101 400 400 40 10 4
Adams Ave. 100 200 200 23 5 4
Alley No. 1 20 20 20 20 8 4
Alley No. 2 20 20 20 20 8 4
Alley No. 3 20 20 20 20 8 4
Alley No. 4 20 20 20 20 8 4
Alley No.


8
JUNE 1913.
SANTA FE
N. MEX.
AQUA FRIA
DUDROW
WAGNER
GUADALUPE
MONTEZUMA AV.
NEW STATE LUMBER CO. PLANING MILL
SANTA FE LUMBER & TRANSFER CO.
CAPITOL COAL CO.
CARTWRIGHT-DAVIS CO.
LEMP BREWING CO.
CONTINENTAL OIL CO.
GUADALUPE R.C. CHURCH
Parsonage
CROSS-KELLY CO.
FREIGHT
PLATFORM
COAL BINS
COAL SHED
HAY SHED
LUMBER SHED
WOOD PILE 10'
A
F
Scale of Feet

888
888
888
AQUAJUA
AQUAJUA
AQUAJUA







527 Agua Fria Street
Existing Exterior Photographs
9/1/25

1 - South Façade (facing Agua Fria)

2 - South Façade showing west face of structure

3 - South Façade (facing Agua Fria)

4 - South Façade (facing Agua Fria)

5 - East Façade (southeast corner)

6 - East Façade

7 - North Façade (northeast corner)

8 – North Facade

9 - North Facade

10 - North Façade

11 - North Façade

12 - North Façade (northwest corner)

City of Santa Fe Chapter 14 Land Development Code	
Owner	NEIRIKA LLC
Address	527 Agua Fria Street, Santa Fe NM 87501
UPC	1-053-099-521-161
Tax Parcel	1126 6176
Legal	Guadalupe Neighborhood Parcel 284, T17N R9E S23
Zoning	R-21
Historic District	Westside Guadalupe Historic District
Hist. Bldg. Status	Significant (confirm with Historic Preservation Division)
Flood Plain	Not applicable
Archeological	Historic Downtown Archeological Review District
Escarpment	Not applicable
Mountain	Not applicable
Density	21 dwelling units per acre
Min. Lot Size	3,000 SF minimum, 2,000 SF with common open space
Existing Lot Size	0.418± acres
Max. Height	24' maximum height for residential structures, within 10' of side or rear property no portion of any story above ground level shall be higher than 14.0'. ***Maximum height might be superseded by historic***.
Existing Height	18'-8"± (no proposed change)
Setbacks (minimum yard requirements)	Front: 7' (20' for front facing garage) Side: 5' Rear: 15' or 20% of average lot depth, whichever is less
Maximum Lot Coverage:	40% maximum for single family or multi-family of fewer than 6 units. 40% maximum for multi-family with 6 or more units. May increase to 55% maximum if private open space is provided. (Lot coverage is the total area of structures on a lot in relation to lot area). For residential development, the portion of a lot occupied by easements for private roads and lot access driveways is excluded from the lot area. Lots smaller than one acre, common open space, fire access roads & other facilities intended primarily for other lots excluded from lot area.
Existing Lot Coverage:	23.4%
Proposed Lot Coverage:	23.4% (no change)
Open Space	No minimum open space required for single family residence except as provided by setbacks. Open space required to increase lot coverage per 14-7.5: Provide a minimum of 50% of total gross floor area (including 2nd floor). Minimum dimension of 12' (and not less than 4' / 40 SF for balconies. Portals, porches, roof decks, and balconies can contribute to the amount required. **NOT REQUIRED**: site meets maximum allowed lot coverage.

Accessory Structures	Generally, cannot be used as an accessory dwelling – may have a half bathroom (sink & toilet) or kitchen but not both.
Parking Residential	Dwelling Unit: 2 spaces per unit Attached Dwelling Unit (2-5 units): 2 spaces per dwelling unit Attached Dwelling Unit (over 5 units, less than 800 SF): 1 assigned space and 0.25 unassigned space per DU Attached Dwelling Unit (over 5 units, 800-1200 SF): 1 assigned space and 0.5 unassigned space per DU Attached Dwelling Unit (over 5 units, over 1200 SF): 1 assigned space and 1.0 unassigned space per DU Accessory Dwelling Unit: 1 space if ADU < 1,000 SF; otherwise 2 spaces Accessory Structures: parking not required
Required Parking Spaces	6 offstreet parking spaces
Existing Parking Spaces	6 off street parking spaces provided on lot for subject lot (1 in garage).
Parking Space Size	Standard pull in: 8.5' x 19', 23' drive aisle Small car: 7.6' x 15', 20' drive aisle. Parking lots with 10 or more spaces may have up to 20% of total req'd spaces designated as small car. Parallel: 8.5' x 23' Parking lots with less than 40 spaces may be gravel.



Vicinity Map

North



Site Plan

Scale: 1" = 10'-0"

True North

0' 10' 20'

Sheet Index:

C-1 Existing Site Plan, Project Information
A-1 Existing Floor Plan
A-2 Demolition Floor Plan
A-3 Existing Exterior Elevations

Scope of Work: Interior non-structural demolition

Note: no work to building exterior

Issued for Building Permit and Construction

Osage Design Studio
1216 Vitalia Street
Santa Fe, NM 87505
osagedesignstudio@yahoo.com
505.629.5948

Renovation of an Existing Residential Structure

NIERIKA LLC

527 Agua Fria Street, Santa Fe NM 87501

Site Plan
Project Information

11/7/25

C-1

Sheet 1 of 3



Existing Floor Areas - Unit 3:	
Heated:	727 SF
Non-heated (garage):	506 SF
Portals:	51 SF
Total Heated:	727 SF
Total Roofed:	1,284 SF

Existing Floor Areas - Unit 2:	
Heated:	993 SF
Non-heated (garage):	0 SF
Portals:	33 SF
Total Heated:	993 SF
Total Roofed:	1,026 SF

Existing Floor Areas - Unit 1:	
Heated:	625 SF
Non-heated (garage):	0 SF
Portals:	82 SF
Total Heated:	625 SF
Total Roofed:	707 SF

Total Existing Floor Areas:	
Heated:	2,345 SF
Non-heated (garage):	506 SF
Portals:	166 SF
Total Heated:	2,345 SF
Total Roofed:	3,017 SF

Existing Floor Plan

Scale: 1/4" = 1'-0"

0' 5' 10'

Plan North

Osage Design Studio
1216 Vitalia Street
Santa Fe, NM 87505
osagedesignstudio@yahoo.com
505.629.5948

Renovation of an Existing Residential Structure

NIERIKA LLC

527 Agua Fria Street, Santa Fe NM 87501

Existing Floor Plan

11/7/25

A-1

Sheet 2 of 3



Existing Front (South) Elevation

Scale: 3/16" = 1'-0"



Existing Left Side (West) Elevation

Scale: 3/16" = 1'-0"



Existing Right Side (East) Elevation

Scale: 3/16" = 1'-0"



Existing Rear (North) Elevation

Scale: 3/16" = 1'-0"

Osage Design Studio
1216 Vitalia Street
Santa Fe, NM 87505
osagedesignstudio@yahoo.com
505.629.5948

Renovation of an Existing Residential Structure

NIERIKA LLC

527 Agua Fria Street, Santa Fe NM 87501

Exterior Elevations

11/7/25

A-3

Sheet 3 of 3

City of Santa Fe

Land Use Department | Historic Preservation Division

Administrative Approval

THIS IS NOT A CONSTRUCTION PERMIT

DO NOT BEGIN WORK WITHOUT A PERMIT. SUBMIT THIS FORM WITH YOUR CONSTRUCTION PERMIT APPLICATION AND RETAIN A COPY AT THE JOB

Date: September 25, 2024

To: Building Permit Division

From: Paul Duran

Be advised that per §14-5.2 SFCC 1987 the work described below at the referenced address does NOT require Historic Districts Review Board approval and is hereby staff-approved as described below. Please allow the applicant to submit for a construction permit(s) for this work if required.

Project Address: 527 AGUA FRIA ST 1, Santa Fe, NM 87501

Case Number: 2024-009160--ADMIN

Contact Name: Luis Ibarra

Phone Number: 505-780-8602 **Email:** highpinesrandr@gmail.com

Approved Scope of Work: *1) Re-roof structure as submitted, (3,012 sq. ft.).*
2) There shall be no publicly visible rooftop appurtenances, no roofing material shall be on the top of the parapets and shall be flashed on interior of parapets.
3) Not approved to replace canales or skylights.
4) There shall be no changes to existing mechanical, line sets, or other rooftop appurtenances at this time.

Conditions of Approval: *1) No other work approved at this time.*

FURTHER ACTIONS REQUIRED: **PERMIT or PERMIT REVISION**

FINAL HISTORIC INSPECTION

High Pines R&R, LLC
1261 Calle de Comercio
Santa Fe, NM 87507
505-780-8602

Roof Plan

September 12, 2024

Client:

Brandon Gabel

527 Agua Fria St

Santa Fe, NM 8750

Square Ft: 2770

Re-Roof Plan

Metal Tile Roof (2512 sf)

- **Tear off down to wood deck**
- **Remove and replace rotten wood**
- **Install Ice and Water Shield**
- **Install Peel and Stick Underlayment**
- **Install 26 Gauge Metal Panels**
- **S Tile Roof Type to match existing and match color.**
- **All Metal Valley, Drip Edge and Ridge Cap Included**

Shingle Roof (500 sf)

- **Tear off down to original sheathing deck.**
- **Remove and replace Rotten Wood Deck**
- **Install Ice and Water Shield**
- **Install Peel and Stick Underlayment.**
- **Install 30 Year Owens Corning Duration Shingles to match existing and match color.**
- **All Metal Valleys, Drip Edge and Ridge Cap Included.**

High Pines R&R, LLC
1261 Calle de Comercio
Santa Fe, NM 87507
505-780-8602

Metal Tile Roof

Shingle Roof

High Pines R&R, LLC
1261 Calle de Comercio
Santa Fe, NM 87507
505-780-8602

High Pines R And R LLC

1261 Calle de Comercio
Santa Fe, NM 87507 US
+1 5057808602
highpinesrandr@gmail.com
www.highpinesrandr.com

Estimate

ADDRESS	SHIP TO		
Brandon Gabel 527 Agua Fria St Santa Fe, NM 87501	Brandon Gabel 527 Agua Fria St Santa Fe, NM 87501	ESTIMATE DATE	3822 07/30/2024

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
	Metal Tile Roof (2512 sf)			
Metal Roofing	Tear off down to wood deck Remove and replace rotten wood Install Ice and Water Shield Install Peel and Stick Underlayment Install 26 Gauge Metal Panels S Tile Roof Type to match existing and match color. All Metal Valley, Drip Edge and Ridge Cap Included **12 Year Labor Warranty- It is the homeowner's responsibility to call High Pines R&R to schedule maintenance time every three (3) years. Note: Warranty only applies to exterior of roof and workmanship mentioned above. Permit fee is not included on the estimated price. **Tear off/Debre roof to be Hauled by High Pines **Cleanup everyday after End of Day	2,512	26.25	65,940.00T
Shingles Re-roof	Tear off down to original sheathing deck. Remove and replace Rotten Wood Deck Install Ice and Water Shield Install Peel and Stick Underlayment. Install 30 Year Owens Corning Duration Shingles to match existing and match color. All Metal Valleys, Drip Edge and Ridge Cap Included. **5 Year Labor Warranty- It is the homeowner's responsibility to call High Pines R&R to schedule maintenance time every three (3) years. Note: Warranty only applies to exterior of roof and workmanship mentioned above. Permit fee is not included on the estimated price. **Tear off/Debre roof to be Hauled by High Pines **Cleanup everyday after End of Day	500	16.75	8,375.00T

By signing above, client agrees to pay a 2.9% fee to process credit or debit card payments.

Contact High Pines R And R LLC to pay.

SUBTOTAL	74,315.00
TAX	6,084.54
TOTAL	**$80,399.54**

Accepted By

Accepted Date 08/01/2024

By signing above, client agrees to pay a 2.9% fee to process credit or debit card payments.

Metal Drip Edge



TruDefinition®

DURATION®

Shingles with Patented SureNail® Technology

Tejas con tecnología patentada SureNail®

STREAKGUARD ALGAE PROTECTION

DEEP DIMENSION
OUTSTANDING PERFORMANCE

Duration® Shingles offer:

- The high-performance of SureNail® Technology
- A TruDefinition® Color Platform
- A Limited Lifetime Warranty*/‡ for as long as you own your home
- The protection of a 130-MPH* wind warranty
- StreakGuard® Protection with a 25-year Algae Resistance Limited Warranty3/§

UNA NUEVA DIMENSIÓN
DESEMPEÑO SOBRESALIENTE

Las tejas Duration® ofrecen:

- El gran desempeño de la tecnología SureNail®
- La gama de colores TruDefinition®
- Una garantía limitada de por vida*/‡ mientras sea propietario de la vivienda
- La protección de una garantía contra vientos de hasta 210 km/h (130 mph)*
- Protección StreakGuard® con una garantía limitada de 25 años de resistencia a las algas 3/§

STREAKGUARD
ALGAE PROTECTION

Don't let black streaks lower the value or curb appeal of your home.

Owens Corning blends specialized copper-lined granules, developed by 3M, a leading producer of roofing granules, into our colorful shingles. This helps resist blue-green algae growth.*

No deje que las manchas de algas afecten al valor o aspecto de su vivienda.

En sus coloridas tejas, Owens Corning añade gránulos especiales con recubrimiento de cobre, desarrollados por 3M, un productor líder de gránulos para techos. Esto ayuda a prevenir la proliferación de algas azul-verdosas.*

THE FINISHING TOUCH

OWENS CORNING® HIP & RIDGE SHINGLES

Owens Corning® Hip & Ridge Shingles are uniquely color matched to TruDefinition® Duration® Shingles. The multiple color blends are only available from Owens Corning® Roofing and offer a finished look for the roof.

EL TOQUE FINAL

TEJAS DE LIMATESA Y CUMBRERA DE OWENS CORNING®

Las tejas de limatesa y cumbrera de Owens Corning® se ofrecen en una exclusiva gama de colores para combinar con las tejas Duration® TruDefinition®. Esta gran variedad de combinaciones de colores es una exclusividad de Owens Corning® Roofing para lograr techos con un acabado único.

TruDefinition®

DURATION®

Shingles with Patented SureNail® Technology | Tejas con tecnología patentada SureNail®

Amber[1]

Not available in Service Area 8 | No se puede obtener en el área de distribución 8

Brownwood[1]



Chateau Green[1]

Colonial Slate[1]

Desert Rose[1]

Driftwood[1]

Estate Gray[1]

Harbor Blue[1]

Midnight Plum[1/5]



Onyx Black[1]

Peppercorn[1]

Shasta White[1]

Not available in Service Area 8 | No se puede obtener en el área de distribución 8

Sierra Gray[1]

Teak[1]

Terra Cotta[1]

Williamsburg Gray[1]

COLOR AVAILABILITY MAP

Disponibilidad de colores por zonas/región

COLOR DISCLAIMER

As color experts, we know getting the shingle color right is a big part of any roofing purchase. Due to printing color variations, in addition to viewing shingle literature, we suggest you request an actual shingle sample to see how it will appear on your home and with your home's exterior elements in various natural lighting conditions. Lastly, we recommend you verify your color choice by seeing it installed on an actual home; your roofing contractor or supplier can provide a sample and may be able to direct you to a local installation.

DESCARGO DE RESPONSABILIDAD SOBRE LOS COLORES

En tanto que especialistas en color, sabemos que obtener el color de teja perfecto es una parte importante en toda compra de techos. Debido a las variaciones en los colores impresos, además de mirar folletos de tejas, le sugerimos que solicite una muestra de la teja para ver como se verá en su hogar y con los elementos externos de la vivienda bajo distintas condiciones de luz natural. Finalmente, le recomendamos que para verificar su elección de colores, vea cómo lucen las tejas ya instaladas en una vivienda; su contratista de techos o su proveedor le pueden dar una muestra e incluso indicarle dónde ver un techo ya instalado.

THERE'S A LINE BETWEEN A GOOD SHINGLE AND A GREAT SHINGLE.®

It's the nailing line on your shingles. The difference between a good shingle and a great shingle is having Patented SureNail® Technology, only from Owens Corning.

HAY UNA GRAN DIFERENCIA ENTRE UNA BUENA TEJA Y UNA TEJA EXCELENTE™

Es la línea de clavado en su tejas. La diferencia entre una buena teja y una teja excelente es la tecnología patentada SureNail,® una exclusividad de Owens Corning.

1

Excellent Adhesive Power
Helps keep the shingle layers laminated.

Excelente poder adhesivo
Ayuda a conservar el laminado de las capas de las tejas.



2

Breakthrough Design
Patented SureNail® Technology is the first and only reinforced nailing zone on the face of the shingle.

Diseño innovador
La tecnología patentada SureNail® es la primera y la única que provee un área de clavado reforzada en la cara de la teja.

"No Guess" Wide Nailing Zone
This tough, engineered woven-fabric strip is embedded in the shingle to create an easy-to-see, strong, durable fastener zone.

Área de clavado ancha, sin cálculos "a ojo"
Esta banda resistente de tela mecánica tejida está incrustada en la teja para proveer un área de sujeción resistente, duradera y fácil de detectar.

3

Outstanding Grip
The SureNail® strip enhances the already amazing grip of our proprietary Tru-Bond®** sealant for exceptional wind resistance of a 130-MPH wind warranty.

Agarre excepcional
La banda SureNail® mejora el excelente agarre de nuestro sellador patentado Tru-Bond®** con una garantía de resistencia al viento excepcional de 210 km/h (130 mph).

4

Triple Layer Protection®+
A unique "triple layer" of reinforcement occurs when the fabric overlays the two shingle layers, providing increased protection against "nail pull" from the wind.

Triple Layer Protection®+
Cuando la tela cubre las dos capas de la teja, se forma una "triple capa" de refuerzo excepcional que ofrece una mayor protección ante el "arranque de clavos" debido al viento.

Double the Common Bond
SureNail® features up to a 200% wider bond between the shingle layers in the nailing zone over standard shingles.

Duplica la adherencia común
En comparación con las tejas comunes, SureNail® ofrece un área de unión hasta un 200 % más ancha entre las capas de la teja en el área de clavado.



THE PROOF IS IN THE PERFORMANCE

LA PRUEBA ESTÁ EN EL DESEMPEÑO

Up to **2.5X BETTER** NAIL PULL-THROUGH RESISTANCE

Hasta **2.5 VECES MEJOR** RESISTENCIA A LA TRACCIÓN DE LOS CLAVOS

Up to **9X BETTER** NAIL BLOW-THROUGH RESISTANCE

Hasta **9 VECES MEJOR** RESISTENCIA AL DESPRENDIMIENTO DE LOS CLAVOS

Up to **2X BETTER** DELAMINATION RESISTANCE

Hasta **2 VECES MEJOR** RESISTENCIA A LA DELAMINACIÓN

TOTAL PROTECTION SIMPLIFIED®

It takes more than just shingles to protect a home. It takes an integrated system of components and layers designed to perform in three critical areas. The Owens Corning® Total Protection Roofing System®^ gives you the assurance that all of your Owens Corning® roofing components are working together to help increase the performance of your roof.

PROTECCIÓN TOTAL SIMPLIFICADA®

Se necesita más que simplemente tejas para proteger su vivienda. Se necesita un sistema integral de componentes y capas diseñadas para desempeñarse en tres áreas críticas. El Total Protection Roofing System® de Owens Corning® le garantiza que todos sus componentes para cubiertas de Owens Corning® funcionan en conjunto para mejorar el desempeño de su techo.



REGISTER YOUR WARRANTY

Registering your Owens Corning® warranty ensures it's easily referenced should you ever need to access it. The process is easy—just have your installation date, shingle type, shingle color and number of squares ready. Then go online to www.owenscorning.com/roofingstandardwarranty or call 1-800-ROOFING (1-800-766-3464) to finish the process.

SCAN TO REGISTER YOUR WARRANTY

Escanee para registrar su garantía

REGISTRE SU GARANTÍA

Al registrar su garantía de Owens Corning® la podrá consultar rápidamente si fuera necesario acceder a ella. El proceso es simple: tenga a mano la fecha de instalación, el tipo y color de tejas y la cantidad de cuadrados. Luego, visite www.owenscorning.com/roofingstandardwarranty o llame al 1-800-ROOFING (1-800-766-3464) para completar el proceso.

Product Attributes

Warranty Length*/‡

Limited Lifetime
(for as long as you own your home)

Wind Resistance Limited Warranty*

130-MPH

Algae Resistance Limited Warranty*/§

25 Years

TRU PROtection® Non-Prorated Limited Warranty* Period

10 Years

TruDefinition® Duration® Shingles Product Specifications

Size	13¼" x 39⅜"
Application Exposure	5⅝"
Shingles per Bundle	Not less than 20
Average Shingle Count per 3 Bundles	64
Average Coverage per 3 Bundles	98.4 sq. ft.

Applicable Standards and Codes

- ASTM D3462
- ASTM D228
- ASTM D3018 (Type 1)
- ICC-ES AC438#
- ASTM D3161 (Class F Wind Resistance)
- ASTM D7158 (Class H Wind Resistance)
- ASTM E108/UL 790 (Class A Fire Resistance)
- PRI ER 1378E01
- Florida Product Approval
- Miami-Dade County Product Approval[2]

Características del producto

Período de garantía*/‡

Garantía limitada de por vida
(mientras sea propietario de la vivienda)

Garantía limitada de resistencia al viento*

210 km/h (130 mph)

Garantía limitada de resistencia a las algas*/§

25 años

Período no prorrateado de garantía limitada TRU PROtection®

10 años

Especificaciones de las tejas Duration® TruDefinition®

Tamaño	33.65 × 100 cm (13¼ × 39⅜ pulg)
Exposición de aplicación	14.3 cm (5⅝ pulg)
Tejas por paquete	20 como mínimo
Cantidad promedio de tejas por 3 paquetes	64
Cobertura promedio por 3 paquetes	9.14 m² (98.4 pies²)

Normas y códigos pertinentes

- ASTM D3462
- ASTM D228
- ASTM D3018 (Tipo 1)
- ICC-ES AC438#
- ASTM D3161 (Resistencia al viento, Clase F)
- ASTM D7158 (Resistencia al viento Clase H)
- ASTM E108/UL 790 (Resistencia al fuego Clase A)
- PRI ER 1378E01
- Aprobación del producto en el estado de Florida
- Producto aprobado por el condado de Miami-Dade[2]

* See actual warranty for complete details, limitations and requirements.

‡ 40-Year Limited Warranty on commercial projects.

† Owens Corning testing against competing products with wide, single-layer nailing zones when following manufacturers' installation instructions and nailing in the middle of the allowable nailing zone.

** Tru-Bond® is a proprietary premium weathering-grade asphalt sealant that is blended by Owens Corning Roofing® and Asphalt, LLC.

+ The amount of Triple Layer Protection® may vary on shingle-to-shingle basis.

International Code Council Evaluation Services Acceptance Criteria for Alternative Asphalt Shingles.

^ Excludes non-Owens Corning® roofing products such as flashing, fasteners, pipe boots and wood decking.

1 See Color Disclaimer information on page 3 for additional details.

2 Applies to all areas that recognize Miami-Dade Notice of Acceptance (NOA).

3 Shingles are algae resistant to control the growth of algae and discoloration.

§ This coverage is effective 1/1/2023; Installation must include use of an Owens Corning® Hip & Ridge product. See actual warranty for details.

For Patent information, please visit owenscorning.com/patents.

SureNail® Technology is not a guarantee of performance in all weather conditions.

5 Owens Corning® Midnight Plum shingle includes a patent pending design.

OWENS CORNING ROOFING AND ASPHALT, LLC
ONE OWENS CORNING PARKWAY
TOLEDO, OH 43659 USA

1-800-GET-PINK® | 1-800-438-7465
www.owenscorning.com

Pub. No. 10024195-A. Printed in U.S.A. April 2023.
THE PINK PANTHER™ & © 1964–2023 Metro-Goldwyn-Mayer Studios Inc.
All Rights Reserved. The color PINK is a registered trademark of Owens Corning.
© 2023 Owens Corning. All Rights Reserved.

(Irving, Memphis)

* Consulte la garantía para obtener una lista completa de detalles, limitaciones y requisitos.

‡ Garantía limitada de 40 años para proyectos comerciales.

† Ensayos comparativos de Owens Corning con productos de la competencia con zonas de clavado ancho de una sola capa cuando se siguen las instrucciones de instalación del fabricante y se clava en el medio de la zona de clavado permitida.

** Tru-Bond® es un sellador asfáltico patentado de calidad premium formulado por Owens Corning Roofing® and Asphalt, LLC.

+ La cantidad de Triple Layer Protection® puede variar entre una teja y otra.

Criterios de aceptación de los servicios de evaluación del Consejo Internacional de Códigos para tejas asfálticas alternativas.

^ Se excluyen productos para techos no fabricados por Owens Corning®, como tapajuntas, sujetadores, bases de tubos y estructuras de soporte de madera.

1 Para obtener más información, consulte el Descargo de responsabilidad sobre los colores, en la página 3.

2 Aplicable a todas las zonas que reconocen el Aviso de aceptación (NOA, Notice of Acceptance) del condado de Miami Dade.

3 Las tejas son resistentes a las algas para controlar su desarrollo y la decoloración.

§ Esta cobertura entra en vigor el 1 de enero de 2023; la instalación debe incluir el uso de un producto para limatesa y cumbrera de Owens Corning®.

Para información sobre la patente, visite www.owenscorning.com/patents.

La tecnología SureNail® no es una garantía de desempeño en todos los tipos de condiciones climáticas.

5 La teja Owens Corning® Midnight Plum incluye un diseño con patente pendiente.

Pub. N.º 10024195-A. Impreso en EE.UU. Abril de 2023.
THE PINK PANTHER™ y © 1964–2023 Metro-Goldwyn-Mayer Studios Inc.
Todos los derechos reservados. El color PINK es una marca registrada de Owens Corning. © 2023 Owens Corning. Todos los derechos reservados.

City of Santa Fe, New Mexico

memo

DATE: September 8, 2026

TO: Historic Districts Review Board Members

VIA: Heather Lamboy, AICP, Planning & Land Use Department Director
Maggie Moore, Assistant Land Use Director MM

FROM: Lani McCulley, Senior Planner, Historic Preservation Division

---

2026-012978-HDRB. 719 Gildersleeve St., Don Gaspar Area Historic District. Contributing. Alison Kuller, owner, proposes to replace windows in the residence and casita, construct a 100 sq. ft. addition, and stucco in the color "cottonwood". An exception is requested to 14-4.6(E)(4)(I)(a) for the replacement of historic windows.

REFERENCE ATTACHMENTS (Sequentially):

CITY SUBMITTALS

____ **District Standards & yard wall & fence standards.**

__x__ **Historic Inventory Form**

__x__ **Zoning Review Sheet**

__x__ **Other**: previous cases

APPLICANT SUBMITTALS

__x__ **Proposal Letter**

__x__ **Site Plan/Floor Plan**

__x__ **Elevations**

__x__ **Photographs**

__x__ **Other:** window assessment

STAFF RECOMMENDATION:

Staff finds that the exception criteria for section 14-4.6(E)(4)(I)(a) for replacement of historic windows have not been met, and recommends denial of the request to replace historic windows. Otherwise, the staff recommends approval of the other elements of the application as they comply with 14-4.6(E) General Design Standards for all Historic Districts, and 14-4.6(G)(1) Don Gaspar Area Historic District Design Standards.

Sample motions:

a. In case 2026-012978-HDRB, for 719 Gildersleeve Street, approve/deny the exception to 14-4.6(E)(4)(I)(a) for the replacement of historic windows, finding that the exception criteria have/have not been met.
b. In case 2026-012978-HDRB, for 719 Gildersleeve Street, approve/deny the elements of the project that do not require an exception.

BACKGROUND & SUMMARY:

Site Description:
The single-family Spanish Pueblo Revival style residence at 719 Gildersleeve is a 1,800 sq. ft. rectangular, single-story structure with a linear casita attached at the rear. The residence is designated as contributing to the Don Gaspar Area Historic District, with the south and west façades designated as the primary façades. The casita is designated as non-contributing. The front yard wall is designated as contributing.

The residence holds an inset portal on the southwest corner with entry steps facing west. The entry steps are lined with low walls, with a step down at the lower steps. The windows are symmetrical across each elevation. The west and east windows are one-over-one single-lite windows, while the remaining windows of the main residence are divided lites: four (4) verticals on top and one (1) light on the bottom. There is a mix of historic and non-historic windows. The non-historic windows replicate the historic windows with the exception of those on the west elevation. The windows are trimmed in a variety of greens or dark blue. The entry doors are non-historic wood doors. The stucco of the residence is a pebble-dashed texture in cementitious “Cottonwood” with “Colonial White” under the portal.

The casita was created by converting the previous garage and adding approximately 300 sq. ft. to the structure in 1998. The garage door was replaced with a double French door, and a new pedestrian entry was placed in the north elevation. All of the windows were replaced as part of a 1997 request. These windows are divided lite, but do not replicate the historic windows of the main residence. There is a shed attached to the east elevation of the casita. The shed is unstained wood with a corrugated metal shed roof.

A low stucco yard wall along the street includes buttress elements on either side. The yard wall is in pebble-dashed texture with cementitious stucco in “Cottonwood”. A coyote fence lines the north property line.

PREVIOUS CASE SUMMARIES:

ARC:
No archaeological clearance has been issued for the property.

HDRB:

In case H-12-088, relocation of the driveway was denied due to removal of the contributing wall. An appeal was filed for the case. The decision of the Historic Districts Review Board was upheld at the appeal hearing.

In case H-97-0106, conversion of the garage to a casita increased the rear structure by 300 sq. ft. to its existing overall size of 500 sq. ft., replaced the garage opening with French doors, replaced the doors and windows, and installed skylights was approved. There were no changes to the main residence.

ADMINISTRATIVE:
In case 2026-012304-ADMIN, re-roofing of the buildings was approved.

While there is no case on file, there is a note that in 1989, a re-stucco and insulation installation was approved.

APPLICANT'S REQUEST:
The applicant proposes the following exterior alterations:

1) Replace windows and doors. All windows are currently wood double-hung, with a window on the south and one on the north that are twin double-hung windows with divided lights: four (4) verticals on top and one (1) light on the bottom, except the west windows, which are one over one. The existing color is a variety of greens or dark blue. The proposed windows are in keeping with the existing as double-hung windows with divided lights: four (4) verticals on top and one (1) light on the bottom, including the replacements for the west elevation; however, the windows will be metal-clad over wood in an off-white called "Abalone". An exception is requested to Section 14-4.6(E)(4)(I)(a) for replacing historic windows.
    a. Windows A, B, C (111, 110, and 109 of the window schedule), and H (105 of the window schedule) are historic and restorable. These windows are listed on the window assessment as being in Fair condition, which is defined as "exterior finishes have cracked and peeling, missing to bar surface, putty glazing cracking and missing in 30% to 40% of the sashes. All sash frames and casings have some members 30% to 40% completely deteriorated."
    b. Windows G and L (104 and the window to be removed) are historic; however, they are not restorable.
    c. Windows D, E, F, I, J, and K (101, 102, 103,106, 107, 108 of the window schedule) are non-historic.
    d. None of the windows (112, 113, and 114 of the window schedule) on the casita are historic.
2) Enclose a portion of the portal on the southwest corner of the residence. This small addition will remove a historic window (window L in the window assessment) and connect the main residence to the casita. Window L is historic but is not restorable. An exterior pedestrian door will be placed on the east elevation.
3) Stucco repair of the residence and casita and stucco of the enclosure in a cementitious stucco to closely match the existing residence, which is in "Cottonwood".

EXCEPTION CRITERIA AND RESPONSES:

Exception to 14-4.6(E)(4)(I)(a): The applicant requests an exception to replace historic windows.

(i) *Do not damage the character of the district*
Applicant Response: Far from damaging the character of the district, the replacement windows will match the original style and keep the house from becoming derelict from lack of maintenance.

Staff Response: Staff finds that this criterion is met. The windows 111, 110, 109, and 105 are located so that they can be seen from the public way, but details of the windows are obscured. Since the windows are being

replicated with the four (4) verticals on top and one (1) light on the bottom, it will not damage the character of the district to replace the windows.

(ii) *Are required to prevent a hardship to the applicant or an injury to the public welfare*
Applicant Response: The hardship to the applicant lies in the fact that the windows don't function properly and can't be opened for airflow in the summer months. They leak hot air out in the winter and cooler air out in the summer, adding to the applicant's utility bills and creating drafts. They also permit pollen, dust, and smoke to enter the house; the applicant is allergic to pollen, currently requiring two air filters operating 6 months of the year in addition to her allergy medications.

Staff Response: Staff finds that this criterion is not met. Windows 109, 110, and 111 are restorable according to the window assessment. If they are properly restored, they should eliminate the draft and resulting issues and be operable.

(iii*) Strengthen the unique heterogeneous character of the City by providing a full range of design options to ensure that residents can continue to reside within the historic districts*
Applicant Response: The applicant is committed to historic preservation and lives in this neighborhood partly because of its unique architecture. Indeed, six of the windows she intends to replace are in themselves more modern replacements and will be returned to the style used when the house was built in the 1920s. She has watched as two houses on her street have been abandoned because of lack of maintenance and remain unoccupied because of the high cost of renovation and the complications of the building process in the neighborhood. She's trying to keep her own house well maintained in order to avoid the same result.

Staff Response: Staff finds that this criterion is met. The new windows will replicate the historic windows and will appear the same but in a uniform color.

RELEVANT CODE CITATIONS:

14-4.6 HISTORIC DISTRICTS

A. General Provisions

1. Purpose

In order to promote the economic, cultural, and general welfare of the people of Santa Fe and to ensure the harmonious, orderly, and efficient growth and development of the City, the Governing Body deems it essential to preserve the qualities relating to the history and culture of Santa Fe, maintain a harmonious outward appearance to preserve property values, and attract residents and tourists alike. The specific purposes of this section are to preserve qualities relating to the history of Santa Fe, such as the following:

I. Continue the existence and preservation of historic areas and buildings;
II. Continued construction of buildings in Santa Fe's historic styles; and
III. General harmony as to architectural style, form, color, height, proportion, texture, and material between buildings of historic design and those of more modern design.

C. Buildings with Significant or Contributing Historic Status

I. Purpose

Historic designation is intended to address the following:

I. Recognizing each structure as a physical record of its time, place, and use.

II. Preventing changes that create a false sense of historical development, such as the addition of conjectural features or architectural elements from other buildings;

III. Preserving and retaining changes to structures that have acquired historic importance in their own right, recognizing that most structures change over time;

IV. Preserving distinctive features, finishes, and construction techniques or examples of craftsmanship that characterize a structure; and

V. Avoiding making new additions and related or adjacent new construction in such a manner that, if removed in the future, the original form and integrity of the historic property and its environment would be unimpaired.

2. Designation of Significant, Contributing, or Noncontributing Status

I. Status Designation

Structures within historic districts may be designated a status of "significant," "contributing," or "noncontributing," as defined in Section 14-9.3, *General Definitions.* Staff shall maintain a record as to the current status of structures located in the historic districts.

II. HDRB Authority to Review Status Designation

a. The HDRB may change the status of a structure or designate a status for a structure that has no status designated.

b. A change in status or the designation of a status shall be based upon an evaluation of data provided through survey or other relevant sources of information and the definitions of "significant," "contributing," or "noncontributing."

c. When the HDRB designates a structure as contributing, it shall also specify which facades of the structure are primary.

V. Restoration of Status

If a property owner makes changes to a structure without the proper City approvals, which result in the lowering of the structure's status, staff or the Board may require the property owner to restore the structure such that its former status is restored.

3. Review by Historic Districts Review Board Required

I. Except where this chapter provides for review by staff, the HDRB shall review all applications for new construction, alteration, or demolition in the historic districts and of landmark structures throughout the city, based on the standards set forth in this section.

II. The historic board shall judge any proposed alteration or new structure for harmony

with adjacent buildings, preservation of historical and characteristic qualities, and conformity to the standards for architectural style set forth in this section.

III. The HDRB may approve, deny, approve with conditions, or, with the consent of the applicant, postpone an application.
   a. For applications approved with conditions, no permit shall be issued until the HDRB conditions have been met.
   b. An application that is postponed shall be heard at a date agreed upon by the HDRB and the applicant.

IV. No permit shall be issued until the time for appeal to the Governing Body has expired.

4. Compliance with General and Specific Design Standards Required

All development located within the historic districts and subject to this section shall comply with all applicable general development standards set forth in Section 14-4.6E), *General Design Standards for All Historic Districts,* as well as any applicable specific development standards set forth in Section 14-4.6G), *Additional District-Specific Design Standards.*

E. General Design Standards for All Historic Districts

These standards shall apply to all additions or alterations to existing structures in the Historic Districts. Contributing, significant, and landmark structures may be subject to specific additional restrictions and district-specific standards in Section 14-4.6(G).

I. General

I. The historic status of a property with a historic status designation of significant, contributing, or landmark structure shall be retained and preserved. If a proposed alteration will cause a property to lose its significant, contributing, or landmark status, the application shall be denied. The removal of historic materials or alteration of architectural features and spaces that embody the status is prohibited.

II. If a proposed alteration or new construction will cause an adjacent property to lose its significant, contributing, or landmark status, the application may be denied.

III. For the regulations of this subsection, all facades of a significant structure are primary facades.

2. Building Additions

I. Design
   a. Building additions that meet the standards of Section 14-4.6(G)(2), *Downtown and Eastside Historic District,* shall continue to meet those standards, in addition to the standards set forth in this section.
   b. Building additions shall have similar materials, architectural treatments and styles, features, and details as the existing structure, but shall be distinguishable from and not attempt to duplicate the existing structure.

II. Size and Location
   a. Building additions are not permitted on primary facades.
   b. All building additions shall be set back a minimum of ten feet from the primary facade.
   c. Building additions shall not exceed 50 percent of the square footage of the building's historic footprint and shall not exceed 50 percent of the historic length in linear feet of the primary facade.
   d. To the extent architecturally practicable, new building additions shall be attached to any existing non-primary facade of a structure rather than attaching them to the primary facade of a structure.

III. Height
   a. The maximum height of building additions to significant and landmark structures shall be at least six inches lower than the parapet or equivalent roof feature of the existing adjacent connecting facade.
   b. Building additions to contributing structures shall be no more than one additional story higher than the existing structure. To the extent architecturally practicable, two-story additions shall be set to the rear or the side rear of the structure. When an additional story is to be placed upon an existing contributing structure, that footprint may be no greater than fifty percent of the footprint of the existing structure, subject to the provisions of Subsection A(1) above. For the purposes of this paragraph, an additional story shall not exceed twelve (12) feet from the existing rooftop to the highest point of that story.

IV. Remodeling to Increase Height
   a. For remodeling of an existing significant or landmark structure, no increase in height of the structure is permitted.
   b. For remodeling an existing contributing structure, a height increase may be permitted through approval of an exception, as described in Section 14-4.6D.

V. Rooftop Equipment

Rooftop equipment, including but not limited to solar collectors, clerestories, decks, or mechanical equipment, may only be installed on contributing and noncontributing structures and shall not be publicly visible, nor shall a parapet be raised to conceal such equipment.

3. Porches and Portals

Existing porches or portals on significant and landmark structures, and on primary facades of contributing structures, shall not be permanently enclosed.

4. Windows, Doors, and Other Architectural Features

I. For all facades of significant and landmark structures and for the primary facades of contributing structures:
   a. Historic windows shall be repaired or restored wherever possible. Historic windows that cannot be repaired or restored shall be duplicated in the size, style, and material of the original. Thermal double-pane glass may be used. No

window opening shall be widened or narrowed.

b. Window depth and other characteristics of window and door fenestration shall be preserved.

c. No new opening shall be made where one presently does not exist unless historic documentation supports its prior existence.

d. No historic opening shall be closed.

II. For all facades of contributing, significant, and landmark structures:

a. Architectural features, finishes, and details other than doors and windows shall be repaired rather than replaced.

b. In the event replacement is necessary, the use of new material may be approved. The new material shall match the material being replaced in composition, design, color, texture, and other visual qualities.

c. Replacement or duplication of missing features shall be substantiated by documentation, physical, or pictorial evidence.

5. Roofs

The existing historic roof styles and materials shall be maintained or replaced in kind if necessary. The addition of dormers or other roof features should only be considered when they are an existing historic feature of the structure.

6. Surface Cleaning

The surface cleaning of structures shall employ the gentlest means possible. Chemical or physical treatments, such as sandblasting, that cause damage to historic materials are not permitted.

7. Archaeological Resources

Discovery of archaeological resources made during the development of a historic property shall be referred to the Archaeological Review Committee. See Section 14-2.1(G)(1)(V)(c), *Unexpected Discoveries.*

8. Signs

9. Murals

10. Pedestrian-Oriented Areas

F. Height, Pitch, Scale, Massing, and Floor Stepbacks.

The height, pitch, scale, and massing of any structure in a historic district, as defined in this section, shall be limited as provided for in this section, unless further restricted elsewhere within this chapter.

I. Applicability

The following sections identify specific areas and specific projects subject to this section. The Planning and Land Use Director shall determine whether or not properties are included within this section.

I. Specific Areas

The height limitations in this subsection F apply:

a. Within the following historic districts:
    1. Downtown and Eastside;
    2. Don Gaspar Area;
    3. Historic Transition; and
    4. Westside-Guadalupe.
b. In the Historic Review district, as specified herein.

II. Streetscape Standards

III. Project Location

Planning and Land Use Department staff shall determine the applicability of this section to individual projects and the applicable streetscape

2. Height

I. Official Map of Building Heights in the Historic Districts - Procedures

II. Height Limitations

The HDRB shall limit the height of structures as set forth in this section. Heights of existing structures shall be as set forth on the official map of building heights in the historic districts.

a. If a proposed building has a parapet, the façade shall not exceed two feet above the average of the height of the façades in the streetscape.
b. If the proposed building has a pitched roof, the ridge height of the proposed building shall not exceed two feet above the average of the ridge height of the pitched roofs in the streetscape.
c. Yard walls and fences shall be limited to a height that does not exceed the average of the height of other yard walls and fences in the streetscape.
d. The height of any other structure shall be limited to the allowable building height within the applicable streetscape, as defined in this section.
e. The height and dimensions of signage are as set forth in Section 14-7.61, *Sign Regulations in the Historic Districts.*
f. The HDRB may increase the allowable height for proposed buildings and additions located on a sloping site where the difference in the natural grade along the structure's foundation exceeds two feet. In no case shall the height of a façade exceed four feet above the allowable height of the applicable streetscape measured from natural or finished grade, whichever is more restrictive. This increase in height shall be constructed only in the form of building setbacks from the street.

III. Height Measurement

a. In historic districts, height shall be the vertical distance measured between the highest part of a structure and the existing grade or finished grade, whichever is more restrictive, at the midpoint of the street-facing facade, excluding rooftop appurtenances, the increased height of walls or fences over pedestrian and vehicular openings, and gates (either in open or closed position).
b. For structures that do not have street frontage, height shall be determined by the

facade that contains the tallest vertical distance measured between the highest part of a structure and the existing grade or finished grade, whichever is more restrictive. The height of walls and fences is measured from the street-facing side of the wall or fence.

IV. Pitch

If the determined streetscape includes over 50 percent buildings with pitched roofs, the proposed building may have a pitched roof. A pitched roof is defined as a gable, shed, or hipped roof. The pitch of the roof shall match the predominant pitch extant in the streetscape.

V. Scale

The height of a proposed building or addition, its façade length, and its roof form and pitch shall appear to be in proportion to the height, façade length, and roof form and pitch of buildings in the applicable streetscape, or the building on which the addition is proposed.

VI. Massing and Floor Stepbacks

The HDRB may require that upper floor levels be stepped back, to carry out the intent of this section; provided that the HDRB in making such determinations shall take into account whether the height of the proposed building, yard wall, fence, or proposed step back of upper floor levels is in harmony with the massing of the applicable streetscape and preservation of the historic and characteristic visual qualities of the streetscape. The HDRB shall also require that the publicly visible facades of the structure be in conformance with Section 14-4.6G), *Additional District-Specific Design Standards,* and, in meeting those requirements, may require that different floor levels be stepped back.

G. Additional District-Specific Design Standards

I. IDon Gaspar Area Historic District

I. District Standards

Compliance with the following structural standards shall occur whenever those exterior features of buildings and other structures subject to public view from any public street, way, or other public place are erected, altered, or demolished:

a. Slump block, stucco, brick, stone, or wood shall be used as exterior wall materials. Aluminum siding, metal panels, mirrored glass, and unstuccoed concrete block or unstuccoed concrete shall not be used as exterior wall materials. The painting of buildings with a color that causes arresting or spectacular effects, or with bold repetitive patterns, or using buildings as signs, is prohibited. Murals, however, are permitted and may be referred to the city arts board for an advisory recommendation.

b. Roof forms, including but not limited to flat, gabled, shed, and hipped roofs, are allowed. Folded plate or hyperbolic roofs are not allowed.

c. The use of solar and other energy-collecting and conserving strategies is

encouraged. The use of large, glazed areas on south-facing walls for trombe walls or other solar collectors, greenhouses, garden rooms, direct gain, or other energy-collecting purposes is allowed. When in view from any public street, way, or other public place, solar equipment shall be screened by the following methods:

1. raising the parapet;
2. setting back from the edge of the roof;
3. Framing the collector with wood.
4. In the case of pitched roofs, by integrating the collector into the pitch;
5. In the case of ground solar collectors, by a wall or vegetation;
6. In the case of wall collectors, by enclosing one end or the other of the walls.
7. Other means that screen the collector or integrate it into the overall structure. Non-glare materials shall be used in solar collectors.

d. Mechanical, electrical, telephone equipment, microwave satellite receiving dishes, and other obstructive equipment shall be architecturally screened by opaque materials by raising the parapet, framing in the equipment, or other appropriate means. The equipment shall be of a low profile to minimize the screening problems.

e. Walls and fences shall be of brick, adobe, masonry, rock, wood, coyote fencing, or similar materials. Wrought iron fences and slump block walls are allowed. Walls of unstuccoed concrete, chain-link, metal wire, or similar materials are prohibited, except where the wall or fence is not in view from any public street, way, or other public place.

f. Greenhouses. Attached greenhouses that front on the street shall give the appearance of being integrated into the structure of the building or of being a substantive addition rather than having a lean-to effect. The use of corrugated fiberglass or rolled plastic for the external surface of attached or freestanding greenhouses that front on the street is prohibited. Greenhouses with slanting sides shall be bracketed at the ends, and the greenhouses made from enclosed porches or portales shall maintain the shape of the porch or portal.

g. For residential uses, paving with asphalt or parking is not allowed in the front yard except on the sidewalk or driveway.

h. For commercial uses, zoned C-1 front yards are required to be landscaped, and no required front yard shall be used for off-street parking.

i. As a condition of any rezoning, all applicants shall provide evidence of sufficient off-street parking and an intent to maintain the architectural integrity of the existing building or to conform to the architectural style of the district if constructing a building on a vacant lot.

II. Walls; Fences; Solar Collectors; Administration

Applications for the erection, alteration, or destruction of walls, fences, and solar collectors and required submittals shall be reviewed by the planning and land use department. Approval, disapproval, or referral shall be indicated by the division on the application for the building permit and on each of the required submittals, all of which shall be signed by the division staff assigned to review. The division staff

shall report approvals, disapprovals, or referrals to the board at its next regular meeting as an informational item. (Ord. No. 2007-45 § 30; Ord. No. 2020-22, § 16)

NEW MEXICO HISTORIC BUILDING INVENTORY FORM

H 2171

building threatened? yes	surveyed date 7-82 by E.T.	county Santa Fe	ID no. 051600
field map Don Gaspar Neighborhood	number 252	UTM reference zone 12 (13)	easting	northing

location description: 719 Aldersleeve

city/town: Santa Fe

land grant/reservation:

building name:

legal description: tnsp ___ N S range ___ E W sec ___ ¼ ¼

film roll by E.T. no. 9 | negative nos. 10 | loc. of neg. City of Santa Fe



building-site plan



date of construction: 1930 estimate 1912-28 actual

source: City Directory Sanborn

use
present: (residential)
other:
historic: (residential)
other:

condition
___ excellent X good
___ fair ___ deteriorating

style: Pueblo Revival

foundation material: n/v

wall material/surface: stucco / concrete block

degree of remodeling
X minor ___ moderate ___ major
describe:

architectural features
inset porch
parapet
wd d/b 1-1
walls along steps

surroundings: RLS

relationship to surroundings
X similar ___ not similar

district potential
X yes ___ no

significance
___ significant X contributing
___ supporting ___ intrusive

comments
3' stucco wall

1926 cd - Martin CP; Harkins PM
1928 cd - vacant
ca 1930 Manahan - small addition
ca 1965 upgrade

associated buildings? ___ yes
what type?

if inventoried, list ID nos.

see back? ___ yes

1428 Sanborn

Proposal Letter for 719 Gildersleeve St Improvements
Alison Kuller

My goal is to make my 100 year old property on Gildersleeve St more comfortable, energy efficient, and practical while maintaining its historic nature. The current house and casita cover approximate 1610' of the .145 acre lot.

The proposal has two components.

The first is to **replace** the double hung **windows** throughout the house and casita with new Kolbe windows that will match the original windows, will be more energy efficient and provide better airflow through the house. The current windows are a mix of original (four verticals on top and one light on the bottom) and (primarily) replacement windows and doors. Many of the windows do not open easily (or at all). When I purchased the house 7 years ago I made a concerted effort to remove and replace old broken putty, to scrape paint from the old widow sills and mullions, and to repair it as well possible. The repairs are already peeling and breaking apart due to the extreme changes in heat and humidity that our climate and the loose single pane windows create.

The new double hung windows will match the original historic style, have off-white trim, Alabaster, by Kolbe Windows, and will be metal clad over wood. No new color will be introduced.

As you will see from the window assessor's report included in this packet, more than half of the windows are non-historic, two are not restorable and the remaining four have considerable (more than 40%) rot.

The second part of my project is to **add a 100 sq ft room** to serve as a closet and laundry room at the back of the house. It will be infill in a corner of the existing portal roof, so only two walls will need to be built, along with a new door, plumbing, and electricity. None of it is visible from the street. No new roof area will be added.

Since the house was built in the 1920s the closet space is very limited in this two bedroom house, and more is needed to bring it up to contemporary use. This room will also serve as a link between the house and casita, which I consider a safety measure. A new door will be added for better egress. Because I plan to relocate the current washer and dryer from the casita to this room it will be more efficient and accessible to everyone living here.

There will be a skylight in the room, but no new windows will be added. The new door will have a glass panel and screen door to bring in more natural light and fresh air.

The only demolition required will be to convert an existing window into a doorway between the existing corner bedroom and the new room.

Plumbing and electricity are already accessible in that corner of the house, which will make hookups fairly straight-forward. A standing room basement provides access. The existing outdoor light fixture will be relocated to the new outer wall by the door.

No new gates, patios, fences or landscaping will be built.

The new stucco will match the existing color, which is Cottonwood by El Rey.

amk 8/4/26

719 Gildersleeve Street, Santa Fe

Historic Districts and Historic Landmarks
Design Standards and Signage Exception Criteria

(i) Do not damage the character of the district

Response: **Far from damaging the character of the district, the replacement windows will match the original style and keep the house from becoming derelict from lack of maintenance.**

(ii) Are required to prevent a hardship to the applicant or an injury to the public welfare

Response: **The hardship to the applicant lies in the fact that the windows don't function properly and can't be opened for airflow in the summer months. They leak hot air out in the winter and cooler air out in the summer, adding to the applicant's utility bills and creating drafts. They also permit pollen, dust and smoke to enter the house; the applicant is allergic to pollen, currently requiring two air filters operating 6 months of the year in addition to her allergy medications.**

(iii) Strengthen the unique heterogeneous character of the City by providing a full range of design options to ensure that residents can continue to reside within the historic districts

Response: **The applicant is committed to historic preservation and lives in this neighborhood partly because of its unique architecture. Indeed six of the windows she intends to replace are in themselves more modern replacements and will be returned to the style used when the house was built in the 1920s.**
She has watched as two houses on her street have been abandoned because of lack of maintenance, and remain unoccupied because of the high cost of renovation and the complications of the building process in the neighborhood. She's trying to keep her own house well maintained in order to avoid the same result.

719 GILDERSLEEVE.

HDRB SET

PROJECT INFORMATION

SCOPE
NEW LAUNDRY ROOM OF 90 SF UNDER AN EXISTING PORTAL, AND REPLACEMENT OF WINDOWS

ADDRESS
719 GILDERSLEEVE., SANTA FE, NM

LOT AREA: 0,132 AC (5,750 SQ FT)

EXISTING:
BUILT AREA: 1,549 SQ FT
ROOFED AREA: 1,928 SQ FT
PERCENT OF LOT ROOFED: 33.53%

PROPOSED:
BUILT AREA: 90 SQ FT
ROOFED AREA: 0

TOTAL
BUILT AREA: 1,639 SQ FT
ROOFED AREA: 1,928 SQ FT
PERCENT OF LOT ROOFED: 33.53%

SHEET INDEX		
NO.	SHEET NAME	REVISION DATE
A 1.1	SITE PLANS	
A 1.2	FLOOR PLANS	
A 1.3	EXTERIOR ELEVATIONS	
A 1.4	EXTERIOR ELEVATIONS	

4



2 EXISTING / PROPOSED SITE PLAN

1/8" = 1'-0"

3 AERIAL PLAN

1/8" = 1'-0"

WINDOWS REPLACEMENT
AND SMALL ADDITION
719 GILDERSLEEVE. SANTA FE, NM 87505

WIDE ANGLE CURVE
WWW.WIDEANGLECURVE.COM
wideanglecurve@gmail.com

SITE PLANS
08/05/2026

A 1.1



1 PROPOSED OVERALL FLOOR PLAN

1/8" = 1'-0"

0' 4' 8' 16'

N

DOOR SCHEDULE								
NO.	WIDTH	HEIGHT	DOOR THICKNESS	TYPE	COMMENTS	MATERIAL	INT/EXT	ROOM
1	2' - 6"	6' - 8"	0' - 1 3/4"	LH INSWING FULL LIGHT		WOOD	EXT	LAUNDRY

WINDOW SCHEDULE									
N.O.	WIDTH	HEIGHT	SILL HEIGHT	HEAD HEIGHT	TYPE	COMMENTS	MATERIAL	ROOM	HISTORIC/NON-HISTORIC
101	3' - 0"	4' - 8"	2' - 6"	7' - 2"	DOUBLE HUNG 4W1H/1-LT		WOOD	LIVING ROOM	NON-HISTORIC
102	3' - 0"	4' - 8"	2' - 6"	7' - 2"	DOUBLE HUNG 4W1H/1-LT		WOOD	LIVING ROOM	NON-HISTORIC
103	5' - 0"	4' - 8"	4' - 2 1/2"	8' - 10 1/2"	TWIN DOUBLE HUNG 4W1H/1-LT		WOOD	LIVING ROOM	NON-HISTORIC
104	5' - 0"	4' - 8"	2' - 6"	7' - 2"	TWIN DOUBLE HUNG 4W1H/1-LT		WOOD	DINING ROOM	HISTORIC
105	2' - 6"	3' - 0"	4' - 2"	7' - 2"	DOUBLE HUNG 4W1H/1-LT		WOOD	KITCHEN	HISTORIC
106	3' - 0"	4' - 0"	3' - 1 1/4"	7' - 1 1/4"	DOUBLE HUNG 4W1H/1-LT ALL WOOD		WOOD	KITCHEN	NON-HISTORIC
107	3' - 0"	4' - 0"	2' - 6"	6' - 6"	DOUBLE HUNG 4W1H/1-LT ALL WOOD		WOOD	KITCHEN	NON-HISTORIC
108	3' - 0"	4' - 0"	2' - 6"	6' - 6"	DOUBLE HUNG 4W1H/1-LT ALL WOOD		WOOD	KITCHEN	NON-HISTORIC
109	5' - 0"	4' - 8"	2' - 6"	7' - 2"	TWIN DOUBLE HUNG 4W1H/1-LT		WOOD	BEDROOM	HISTORIC
110	2' - 6"	4' - 8"	2' - 6"	7' - 2"	DOUBLE HUNG 4W1H/1-LT		WOOD	BATH	HISTORIC
111	2' - 6"	4' - 8"	2' - 6"	7' - 2"	DOUBLE HUNG 4W1H/1-LT		WOOD	BEDROOM	HISTORIC
112	1' - 7"	2' - 1"	4' - 5"	6' - 6"	DOUBLE HUNG 4W1H/1-LT		WOOD	KITCHEN/DINING	NON-HISTORIC
113	2' - 4"	4' - 8"	1' - 10"	6' - 6"	DOUBLE HUNG 4W1H/1-LT		WOOD	BEDROOM	NON-HISTORIC
114	6' - 8"	1' - 11"	4' - 0"	5' - 11"	80" x 23" TWIN FIXED 5W1H		WOOD	BATH	NON-HISTORIC

SKYLIGHT SCHEDULE					
N.O.	WIDTH	LENGTH	MATERIAL	ROOM	NOTES
201	3' - 0"	2' - 0"			LOW PROFILE SKYLIGHT
202				NO	
203				NO	



WALL LEGEND

- EXISTING WALLS
- NEW WALLS
- DEMOLISH

2 EXISTING / DEMO FLOOR PLAN

1/4" = 1'-0"

0' 2' 4' 8'

N



3 PROPOSED FLOOR PLAN

1/4" = 1'-0"

0' 2' 4' 8'

N

MATERIAL PALETTE

STUCCO	WINDOWS & DOORS
COTTONWOOD TO MATCH EXISTING HOUSE	ABALONE - KOLBE WINDOWS & DOORS

WINDOWS REPLACEMENT AND SMALL ADDITION
719 GILDERSLEEVE. SANTA FE, NM 87505

WIDE ANGLE CURVE
WWW.WIDEANGLECURVE.COM
wideangelcurve@gmail.com

FLOOR PLANS
08/05/2026
A 1.2



1 **EXISTING WEST ELEVATION**
1/4" = 1'-0"

0' 2' 4' 8'

4 **PROPOSED WEST ELEVATION**
1/4" = 1'-0"

0' 2' 4' 8'



2 **EXISTING SOUTH ELEVATION**
1/4" = 1'-0"

0' 2' 4' 8'



3 **PROPOSED SOUTH ELEVATION**
1/4" = 1'-0"

0' 2' 4' 8'

WINDOWS REPLACEMENT
AND SMALL ADDITION
719 GILDERSLEEVE. SANTA FE, NM 87505

WIDE ANGLE CURVE
WWW.WIDEANGLECURVE.COM
wideangelcurve@gmail.com

EXTERIOR ELEVATIONS
06/05/2026

A 1.3



3 **EXISTING EAST ELEVATION**
1/4" = 1'-0"
0' 2' 4' 8'



4 **PROPOSED EAST ELEVATION**
1/4" = 1'-0"
0' 2' 4' 8'

5 **EXISTING NORTH ELEVATION**
1/4" = 1'-0"
0' 2' 4' 8'



6 **PROPOSED NORTH ELEVATION**
1/4" = 1'-0"
0' 2' 4' 8'

WINDOWS REPLACEMENT
AND SMALL ADDITION
719 GILDERSLEEVE. SANTA FE, NM 87505

WIDE ANGLE CURVE
WWW.WIDEANGLECURVE.COM
wideangelcurve@gmail.com

EXTERIOR ELEVATIONS
08/05/2026

A 1.4

On Behalf Of: Sunwest Construction Spec
Address: 1254 Calle De Comerico
Santa Fe, NM 87507
Phone: 505-438-7199
Contact: Whitney Osborne
Email: whitney@sunwestconstructionspecialties.com
Phone: 480-745-0531

KOLBE
WINDOWS & DOORS
We're for the visionaries.™

Quote 1452191L: Alison Kuller
Project: 719 Gildersleeve st
Printed: 8/5/2026 8:41:48 AM

Line	Label	UOM	Quantity	Cubic Feet	List Price	Extended Price
001	LIVING RM-W	EA	(2)	7.94	$2,392.20	$4,784.40

*** Unit ***
UDH (Assy 1)

Ultra Rectangle Double Hung

*** Unit ***
Unit 1.1: #1117 VTG, EXTRD SASH, STR, SASH OPERATION: TOP & BTM ACTIVE, SQUARE BASIC JAMB PROFILE

*** Glass ***
Unit 1.1: SOLAR CONTROL LOW-E GLASS

*** Lite Divisions ***
Unit 1.1 Lower: NONE

Unit 1.1 Upper: PDL, COLONIAL, 4W1H, 1 1/8" Bars, 1 1/8" BARS, BVLD BARS - EXTERIOR

*** Hardware-Accessories ***
Unit 1.1: CLY (RUSTIC) HARDWARE, SIGNATURE LCK, BETTERVUE FG FULL SCRN, SCREEN(S) LOOSE, BLACK JAMBLINER

*** Species-Finish-Color ***
Unit 1.1: 70% FLRPOLYMR EXT SASH, 70% FLUOROPOLYMER EXTERIOR FRAME, ABLN EXT, COLORED PREFINISH INT SASH, COLORED PREFINISH INT FRAME, ABLN INT, WD WRAPPED JBLNR, BLACK VERTICAL WEATHERSTRIP

*** Casing-Jambs-Trim ***
Unit 1.1: NO CASING, NO SILL NSG, 4-9/16" JAMBS



Scaled to Fit

Rough Opening:
36 1/2" X 55 9/16"

Frame Size:
36" X 55"

Unit Dimension:
36" X 55"

002 LIVING RM-N EA (1) 14.64 $4,757.40 $4,757.40

*** Unit ***
UDH (Assy 1)

Ultra Rectangle Double Hung

*** Unit ***
Unit 1.1, 1.2: #1117 VTG, EXTRD SASH, STR, SASH OPERATION: TOP & BTM ACTIVE, SQUARE BASIC JAMB PROFILE

*** Glass ***
Unit 1.1, 1.2: SOLAR CONTROL LOW-E GLASS

*** Lite Divisions ***
Unit 1.1 Lower, 1.2 Lower: NONE

Unit 1.1 Upper, 1.2 Upper: PDL, COLONIAL, 4W1H, 1 1/8" Bars, 1 1/8" BARS, BVLD BARS - EXTERIOR

*** Hardware-Accessories ***
Unit 1.1, 1.2: CLY (RUSTIC) HARDWARE, SIGNATURE LCK, BETTERVUE FG FULL SCRN, SCREEN(S) LOOSE, BLACK JAMBLINER

*** Species-Finish-Color ***
Unit 1.1, 1.2: 70% FLRPOLYMR EXT SASH, 70% FLUOROPOLYMER EXTERIOR FRAME, ABLN EXT, COLORED PREFINISH INT SASH, COLORED PREFINISH INT FRAME, ABLN INT, WD WRAPPED JBLNR, BLACK VERTICAL WEATHERSTRIP

*** Casing-Jambs-Trim ***
Unit 1.1, 1.2: NO CASING, NO SILL NSG, 4-9/16" JAMBS



Scaled to Fit

Rough Opening:
72" X 53 9/16"

Frame Size:
71 1/2" X 53"

Unit Dimension:
71 1/2" X 53"

003 DINING RM-N EA (1) 12.57 $4,542.40 $4,542.40



Scaled to Fit

Rough Opening:
61 1/2" X 53 9/16"

Frame Size:
61" X 53"

Unit Dimension:
61" X 53"

*** Unit ***
UDH (Assy 1)

Ultra Rectangle Double Hung

*** Unit ***
Unit 1.1, 1.2: #1117 VTG, EXTRD SASH, STR, SASH OPERATION: TOP & BTM ACTIVE, SQUARE BASIC JAMB PROFILE

*** Glass ***
Unit 1.1, 1.2: SOLAR CONTROL LOW-E GLASS

*** Lite Divisions ***
Unit 1.1 Lower, 1.2 Lower: NONE

Unit 1.1 Upper, 1.2 Upper: PDL, COLONIAL, 4W1H, 1 1/8" Bars, 1 1/8" BARS, BVLD BARS - EXTERIOR

*** Hardware-Accessories ***
Unit 1.1, 1.2: CLY (RUSTIC) HARDWARE, SIGNATURE LCK, BETTERVUE FG FULL SCRN, SCREEN(S) LOOSE, BLACK JAMBLINER

*** Species-Finish-Color ***
Unit 1.1, 1.2: 70% FLRPOLYMR EXT SASH, 70% FLUOROPOLYMER EXTERIOR FRAME, ABLN EXT, COLORED PREFINISH INT SASH, COLORED PREFINISH INT FRAME, ABLN INT, WD WRAPPED JBLNR, BLACK VERTICAL WEATHERSTRIP

*** Casing-Jambs-Trim ***
Unit 1.1, 1.2: NO CASING, NO SILL NSG, 4-9/16" JAMBS

Calculated Design Pressure values of individual units will be verified upon order to Kolbe. Overall Performance Grade of mulls/assemblies may/will be less than computed values of individual units and will also be determined upon order to Kolbe.

004	KITCHEN	EA	(1)	4.32	$1,962.50	$1,962.50



Scaled to Fit

Rough Opening:
30 3/4" X 34 9/16"

Frame Size:
30 1/4" X 34"

Unit Dimension:
30 1/4" X 34"

*** Unit ***
UDH (Assy 1)

Ultra Rectangle Double Hung

*** Unit ***
Unit 1.1: #1117 VTG, EXTRD SASH, STR, SASH OPERATION: TOP & BTM ACTIVE, SQUARE BASIC JAMB PROFILE

*** Glass ***
Unit 1.1: SOLAR CONTROL LOW-E GLASS

*** Lite Divisions ***
Unit 1.1 Lower: NONE

Unit 1.1 Upper: PDL, COLONIAL, 4W1H, 1 1/8" Bars, 1 1/8" BARS, BVLD BARS - EXTERIOR

*** Hardware-Accessories ***
Unit 1.1: CLY (RUSTIC) HARDWARE, SIGNATURE LCK, BETTERVUE FG FULL SCRN, SCREEN(S) LOOSE, BLACK JAMBLINER

*** Species-Finish-Color ***
Unit 1.1: 70% FLRPOLYMR EXT SASH, 70% FLUOROPOLYMER EXTERIOR FRAME, ABLN EXT, COLORED PREFINISH INT SASH, COLORED PREFINISH INT FRAME, ABLN INT, WD WRAPPED JBLNR, BLACK VERTICAL WEATHERSTRIP

*** Casing-Jambs-Trim ***
Unit 1.1: NO CASING, NO SILL NSG, 4-9/16" JAMBS

005	NOOK	EA	(1)	5.58	$2,094.00	$2,094.00

*** Unit ***
UDH (Assy 1)

Ultra Rectangle Double Hung

*** Unit ***
Unit 1.1: #1117 VTG, EXTRD SASH, STR, SASH OPERATION: TOP & BTM ACTIVE, SQUARE BASIC JAMB PROFILE

*** Glass ***
Unit 1.1: SOLAR CONTROL LOW-E GLASS

*** Lite Divisions ***
Unit 1.1 Lower: NONE

Unit 1.1 Upper: PDL, COLONIAL, 4W1H, 1 1/8" Bars, 1 1/8" BARS, BVLD BARS - EXTERIOR

*** Hardware-Accessories ***
Unit 1.1: CLY (RUSTIC) HARDWARE, SIGNATURE LCK, BETTERVUE FG FULL SCRN, SCREEN(S) LOOSE, BLACK JAMBLINER

*** Species-Finish-Color ***
Unit 1.1: 70% FLRPOLYMR EXT SASH, 70% FLUOROPOLYMER EXTERIOR FRAME, ABLN EXT, COLORED PREFINISH INT SASH, COLORED PREFINISH INT FRAME, ABLN INT, WD WRAPPED JBLNR, BLACK VERTICAL WEATHERSTRIP

*** Casing-Jambs-Trim ***
Unit 1.1: NO CASING, NO SILL NSG, 4-9/16" JAMBS



Scaled to Fit

Rough Opening:
34 1/2" X 40 9/16"

Frame Size:
34" X 40"

Unit Dimension:
34" X 40"

006	NOOK	EA	(2)	5.58	$2,208.60	$4,417.20

*** Unit ***
UDH (Assy 1)

Ultra Rectangle Double Hung

*** Unit ***
Unit 1.1: #1117 VTG, EXTRD SASH, STR, SASH OPERATION: TOP & BTM ACTIVE, SQUARE BASIC JAMB PROFILE

*** Glass ***
Unit 1.1: SOLAR CONTROL LOW-E GLASS

Unit 1.1 Lower, 1.1 Upper: TEMP GLS

*** Lite Divisions ***
Unit 1.1 Lower: NONE

Unit 1.1 Upper: PDL, COLONIAL, 4W1H, 1 1/8" Bars, 1 1/8" BARS, BVLD BARS - EXTERIOR

*** Hardware-Accessories ***
Unit 1.1: CLY (RUSTIC) HARDWARE, SIGNATURE LCK, BETTERVUE FG FULL SCRN, SCREEN(S) LOOSE, BLACK JAMBLINER

*** Species-Finish-Color ***
Unit 1.1: 70% FLRPOLYMR EXT SASH, 70% FLUOROPOLYMER EXTERIOR FRAME, ABLN EXT, COLORED PREFINISH INT SASH, COLORED PREFINISH INT FRAME, ABLN INT, WD WRAPPED JBLNR, BLACK VERTICAL WEATHERSTRIP

*** Casing-Jambs-Trim ***
Unit 1.1: NO CASING, NO SILL NSG, 4-9/16" JAMBS



Scaled to Fit

Rough Opening:
34 1/2" X 40 9/16"

Frame Size:
34" X 40"

Unit Dimension:
34" X 40"

007	SOUTH EAST BDRM	EA	(1)	6.30	$2,219.10	$2,219.10



Scaled to Fit

Rough Opening:
29" X 54 9/16"

Frame Size:
28 1/2" X 54"

Unit Dimension:
28 1/2" X 54"

*** Unit ***
UDH (Assy 1)

Ultra Rectangle Double Hung

*** Unit ***
Unit 1.1: #1117 VTG, EXTRD SASH, STR, SASH OPERATION: TOP & BTM ACTIVE, SQUARE BASIC JAMB PROFILE

*** Glass ***
Unit 1.1: SOLAR CONTROL LOW-E GLASS

*** Lite Divisions ***
Unit 1.1 Lower: NONE

Unit 1.1 Upper: PDL, COLONIAL, 4W1H, 1 1/8" Bars, 1 1/8" BARS, BVLD BARS - EXTERIOR

*** Hardware-Accessories ***
Unit 1.1: CLY (RUSTIC) HARDWARE, SIGNATURE LCK, BETTERVUE FG FULL SCRN, SCREEN(S) LOOSE, BLACK JAMBLINER

*** Species-Finish-Color ***
Unit 1.1: 70% FLRPOLYMR EXT SASH, 70% FLUOROPOLYMER EXTERIOR FRAME, ABLN EXT, COLORED PREFINISH INT SASH, COLORED PREFINISH INT FRAME, ABLN INT, WD WRAPPED JBLNR, BLACK VERTICAL WEATHERSTRIP

*** Casing-Jambs-Trim ***
Unit 1.1: NO CASING, NO SILL NSG, 4-9/16" JAMBS

008	BATH	EA	(1)	4.41	$2,180.35	$2,180.35

*** Unit ***
UDH (Assy 1)

Ultra Rectangle Double Hung

*** Unit ***
Unit 1.1: #1117 VTG, EXTRD SASH, STR, SASH OPERATION: TOP & BTM ACTIVE, SQUARE BASIC JAMB PROFILE

*** Glass ***
Unit 1.1: SOLAR CONTROL LOW-E GLASS

Unit 1.1 Lower: 1/8" FRSTD MATTE GLS, TEMP GLS

Unit 1.1 Upper: TEMP GLS

*** Lite Divisions ***
Unit 1.1 Lower: NONE

Unit 1.1 Upper: PDL, COLONIAL, 4W1H, 1 1/8" Bars, 1 1/8" BARS, BVLD BARS - EXTERIOR

*** Hardware-Accessories ***
Unit 1.1: CLY (RUSTIC) HARDWARE, SIGNATURE LCK, BETTERVUE FG FULL SCRN, SCREEN(S) LOOSE, BLACK JAMBLINER

*** Species-Finish-Color ***
Unit 1.1: 70% FLRPOLYMR EXT SASH, 70% FLUOROPOLYMER EXTERIOR FRAME, ABLN EXT, COLORED PREFINISH INT SASH, COLORED PREFINISH INT FRAME, ABLN INT, WD WRAPPED JBLNR, BLACK VERTICAL WEATHERSTRIP

*** Casing-Jambs-Trim ***
Unit 1.1: NO CASING, NO SILL NSG, 4-9/16" JAMBS



Scaled to Fit

Rough Opening:
31 1/2" X 34 9/16"

Frame Size:
31" X 34"

Unit Dimension:
31" X 34"

009	SOUTHWEST BDRM	EA	(2)	6.30	$2,219.10	$4,438.20



Scaled to Fit

Rough Opening:
29" X 54 9/16"

Frame Size:
28 1/2" X 54"

Unit Dimension:
28 1/2" X 54"

*** Unit ***
UDH (Assy 1)

Ultra Rectangle Double Hung

*** Unit ***
Unit 1.1: #1117 VTG, EXTRD SASH, STR, SASH OPERATION: TOP & BTM ACTIVE, SQUARE BASIC JAMB PROFILE

*** Glass ***
Unit 1.1: SOLAR CONTROL LOW-E GLASS

*** Lite Divisions ***
Unit 1.1 Lower: NONE

Unit 1.1 Upper: PDL, COLONIAL, 4W1H, 1 1/8" Bars, 1 1/8" BARS, BVLD BARS - EXTERIOR

*** Hardware-Accessories ***
Unit 1.1: CLY (RUSTIC) HARDWARE, SIGNATURE LCK, BETTERVUE FG FULL SCRN, SCREEN(S) LOOSE, BLACK JAMBLINER

*** Species-Finish-Color ***
Unit 1.1: 70% FLRPOLYMR EXT SASH, 70% FLUOROPOLYMER EXTERIOR FRAME, ABLN EXT, COLORED PREFINISH INT SASH, COLORED PREFINISH INT FRAME, ABLN INT, WD WRAPPED JBLNR, BLACK VERTICAL WEATHERSTRIP

*** Casing-Jambs-Trim ***
Unit 1.1: NO CASING, NO SILL NSG, 4-9/16" JAMBS

010	CASITA -ABOVE SINK	EA	(1)	2.16	$1,427.35	$1,427.35

*** Unit ***
UAW (Assy 1)

Ultra Rectangle Awning

*** Unit ***
Unit 1.1: EXTRD SASH, CRANK OUT, VENT HINGING

*** Glass ***
Unit 1.1: SOLAR CONTROL LOW-E GLASS

*** Lite Divisions ***
Unit 1.1: PDL, COLONIAL, 2W2H, 1 1/8" Bars, 1 1/8" BARS, BVLD BARS - EXTERIOR

*** Hardware-Accessories ***
Unit 1.1: STD W/ EURO HNGS WIN HRDW, TRADITIONAL LOCK LEVER, CLY (RUSTIC) HARDWARE, E-GARD PLUS LOCKING HRDW, E-GARD PLUS OPERATING HRDW, BETTERVUE FG SCRN, SCREEN(S) LOOSE

*** Species-Finish-Color ***
Unit 1.1: 70% FLRPOLYMR EXT SASH, 70% FLUOROPOLYMER EXTERIOR FRAME, ABLN EXT, COLORED PREFINISH INT SASH, COLORED PREFINISH INT FRAME, ABLN INT, WHITE SCRN

*** Casing-Jambs-Trim ***
Unit 1.1: NO CASING, NO SILL NSG, 4-9/16" JAMBS

Individual Grille Division Type defaults may not always align with each other in certain mull/stack configurations. Please check layouts for acceptability and adjust if necessary.



Scaled to Fit

Rough Opening:
19 1/2" X 25 1/2"

Frame Size:
19" X 25"

Unit Dimension:
19" X 25"

011	CASITA - BACK BDRM	EA	(1)	7.50	$2,370.00	$2,370.00

*** Unit ***
UDH (Assy 1)

Ultra Rectangle Double Hung

*** Unit ***
Unit 1.1: #1117 VTG, EXTRD SASH, STR, SASH OPERATION: TOP & BTM ACTIVE, SQUARE BASIC JAMB PROFILE

*** Glass ***
Unit 1.1: SOLAR CONTROL LOW-E GLASS

*** Lite Divisions ***
Unit 1.1 Lower: NONE

Unit 1.1 Upper: PDL, COLONIAL, 4W1H, 1 1/8" Bars, 1 1/8" BARS, BVLD BARS - EXTERIOR

*** Hardware-Accessories ***
Unit 1.1: CLY (RUSTIC) HARDWARE, SIGNATURE LCK, BETTERVUE FG FULL SCRN, SCREEN(S) LOOSE, BLACK JAMBLINER

*** Species-Finish-Color ***
Unit 1.1: 70% FLRPOLYMR EXT SASH, 70% FLUOROPOLYMER EXTERIOR FRAME, ABLN EXT, COLORED PREFINISH INT SASH, COLORED PREFINISH INT FRAME, ABLN INT, WD WRAPPED JBLNR, BLACK VERTICAL WEATHERSTRIP

*** Casing-Jambs-Trim ***
Unit 1.1: NO CASING, NO SILL NSG, 4-9/16" JAMBS



Scaled to Fit

Rough Opening:
32" X 59 9/16"

Frame Size:
31 1/2" X 59"

Unit Dimension:
31 1/2" X 59"

012	CASITA BACK BDRM	EA	(1)	15.15	$5,189.25	$5,189.25



Scaled to Fit

Rough Opening:
38 1/8" X 83 7/32"

Frame Size:
37 5/8" X 82 23/32"

Unit Dimension:
37 5/8" X 82 23/32"

*** Unit ***
UXD3068 (Assy 1)

Ultra Rectangle Exterior Swinging Door

*** Unit ***
Unit 1.1: EXTRD SASH, ULTRA, Inswing, LT HINGING, FULL LITE PNL STYLE

*** Glass ***
Unit 1.1: SOLAR CONTROL LOW-E GLASS

Unit 1.1: TEMP GLS

*** Hardware-Accessories ***
Unit 1.1: MPT PT LCK DR HRDW, Standard Lock, EUROPEAN STYLE-DEADBOLT ON BTM, RUSTIC UMBER HARDWARE, 45 MM BACKSET, Standard Lock Height, RST UMBER HNGS, BETTERVUE FG SWG SCRN, HINGED RIGHT SCREEN OPER, SCREEN(S) LOOSE

*** Species-Finish-Color ***
Unit 1.1: 70% FLRPOLYMR EXT SASH, 70% FLUOROPOLYMER EXTERIOR FRAME, ABLN EXT, COLORED PREFINISH INT SASH, COLORED PREFINISH INT FRAME, ABLN INT

*** Casing-Jambs-Trim ***
Unit 1.1: NO CASING, 4-9/16" JAMBS

Notes / Totals / Signature

Total Quantity: 15	Total Cubic Feet: 112.27	Total Perimeter Feet: 2,548.19	Sub-Total*:	$40,382.15

Total Amount:	$40,382.15

Total Amount includes Kolbe and/or Non-Kolbe lines if applicable

Signature: _____ Date: _____

Purchase Order: _____

For warranty information please click this link or visit https://www.kolbewindows.com/resources/warranties

On Behalf Of: Sunwest Construction Spec
Address: 1254 Calle De Comerico
Santa Fe, NM 87507
Phone: 505-438-7199
Contact: Whitney Osborne
Email: whitney@sunwestconstructionspecialties.com
Phone: 480-745-0531

KOLBE
WINDOWS & DOORS
We're for the visionaries.™

Quote 1450407L: Alison Kuller
Project: 719 Gildersleeze St
Printed: 8/5/2026 8:42:41 AM

Line	Label	UOM	Quantity	Cubic Feet	List Price	Extended Price
001	CASITA	EA	(2)	3.64	$1,769.20	$3,538.40

*** Unit ***
UDHS (Assy 1)

Ultra Rectangle DH/SH Studio

*** Unit ***
Unit 1.1: #1117 VTG, EXTRD SASH, MATCH STR PROF

*** Glass ***
Unit 1.1: SOLAR CONTROL LOW-E GLASS

*** Lite Divisions ***
Unit 1.1: PDL, COLONIAL, 4W1H, 1 1/8" Bars, 1 1/8" BARS, BVLD BARS - EXTERIOR

*** Species-Finish-Color ***
Unit 1.1: 70% FLRPOLYMR EXT SASH, 70% FLUOROPOLYMER EXTERIOR FRAME, ABLN EXT, COLORED PREFINISH INT SASH, COLORED PREFINISH INT FRAME, ABLN INT

*** Casing-Jambs-Trim ***
Unit 1.1: NO CASING, NO SILL NSG, 4-9/16" JAMBS



Scaled to Fit

Rough Opening:
39" X 22 9/16"

Frame Size:
38 1/2" X 22"

Unit Dimension:
38 1/2" X 22"

Notes / Totals / Signature

Total Quantity: 2	Total Cubic Feet: 7.28	Total Perimeter Feet: 242.00	Sub-Total*:	$3,538.40

Total Amount:	$3,538.40

Total Amount includes Kolbe and/or Non-Kolbe lines if applicable

Signature: _____ Date: _____

Purchase Order: _____

Printed By: Whitney Osborne

Created: 6/15/2026

2026 Pricing

For warranty information please click this link or visit https://www.kolbewindows.com/resources/warranties

RPA & Associates LLC

PRESERVING OUR HISTORY

508 Ortega Rd NW Los Ranchos de Albuquerque, NM 87114
P.O. Box 10328 Albuquerque, NM 87184
505-379-7900
rpahistoric@gmail.com

TO Alison Kuller
719 Gildersleeve Street
Santa Fe, NM 87505
alison.kuller@gmail.com

JOB	DATE
719 Gildersleeve Street, Santa Fe, NM 87505 – MAIN HOUSE	07/02/2026

LOCATION	DESCRIPTION
SOUTH	
A	30” x 56” DOUBLE HUNG 4W1H/1-LT ALL WOOD
B	30” x 56” DOUBLE HUNG 4W1H/1-LT ALL WOOD
C	60” x 56” TWIN DOUBLE HUNG 4W1H/1-LT ALL WOOD (2-28”)
DR #1	32” x 80” RH INSWING ARCH TOP V-GROOVE ALL WOOD DOOR
WEST	
D	36” x 56” DOUBLE HUNG 1/1 ALL WOOD
E	36” x 56” DOUBLE HUNG 1/1 ALL WOOD
NORTH	
F	68” x 54” TRIPLE ALL STATS/FIXED 2W4H ALL WOOD
G	60” x 56” TWIN DOUBLE HUNG 4W1H/1-LT ALL WOOD
H	30” x 36” DOUBLE HUNG 4W1H/1-LT ALL WOOD
I	36” x 48” DOUBLE HUNG 4W1H/1-LT ALL WOOD
EAST	
J	36” x 48” DOUBLE HUNG 4W1H/1-LT ALL WOOD
DR #2	32” x 80” LH INSWING FULL LIGHT/18” BOTTOM RAIL ALL WOOD DOOR
K	36” x 48” DOUBLE HUNG 1/1 1-LT
L	28” x 56” DOUBLE HUNG 4W1H/1-LT ALL WOOD

JOB	DATE
719 Gildersleeve Street, Santa Fe, NM 87505 – CASITA	07/02/2026

LOCATION	DESCRIPTION
SOUTH	
C-A	80” x 23” TWIN FIXED 5W1H ALL WOOD
WEST	
DR #C-1	95” x 84” TRIPLE INSWING SIDELIGHT/FRENCH DOOR/SIDELIGHT FULL LIGHT ALL WOOD DOOR 15”/64”/15”
NORTH	
DR #C-2	32” x 78” LH INSWING FULL LIGHT ALL WOOD DOOR
C-B	19” x 25” FIXED INSWING STAT
DR #C-3	32” x 78” RH INSWING FULL LIGHT ALL WOOD DOOR
EAST	
C-C	29” x 56” DOUBLE HUNG 3W2H/3W2H ALL WOOD

In closing, my professional opinion is as follows:

The windows and doors on the main house are as follows:

Windows A, B, C, and H are historic and restorable however the units do have considerable rot.

Windows G and L are historic however unrestorable.

Windows D, E, F, I, J, and K are non-historic.

Doors 1 and 2 are non-historic.

If the windows and doors are replaced, they should be replaced in "like and kind" of the historic windows that are existing. With divided lights, four (4) verticals on top and one (1) light on the bottom, either in all wood or clad/wood to match the existing color. Windows such as Marvin or Kolbe will meet these requirements.

The windows and doors on the casita are as follows:

Windows C-A, C-B, and C-C are non-historic.

Doors C-1, C-2, and C-3 are non-historic.

If the windows and doors are replaced, they should be replaced in "like and kind" of the historic windows that are existing. With divided lights, four (4) verticals on top and one (1) light on the bottom, either in all wood or clad/wood to match the existing color. Windows such as Marvin or Kolbe will meet these requirements.

If you have any questions, please contact me at 505-379-7900.

Assessment prepared by: Ra N. Patterson

RPA & ASSOCIATES, LLC| WINDOW & DOOR CONDITION AND INTEGRITY CODES

CODE	CONDITION AND INTEGRITY CODES
P = PREMIUM	EXTERIOR FINISHES AND SASH, FRAME, AND CASING MEMBER IN PREMIUM OR VERY GOOD CONDITION, PUTTY GLAZE INTACT, ONLY COSMECTIC TOUCH-UP, IF NEEDED
S = SATISFACTORY	EXTERIOR FINISHES FADING AND WORN IN PLACES BUT STILL ADHERED TO THE WINDOW MEMBERS.
	PUTTY GLAZING CRACKING BUT INTACT AND ALL SASHES, FRAMES, AND CASING MEMBER WITH LESS THAN 30% – 40% DETERIORATION
F = FAIR	EXTERIOR FINISHES HAVE CRACKED & PEELED, MISSING TO BARE SURFACE
	PUTTY GLAZING CRACKING AND MISSING IN 30% – 40% OF THE SASHES. ALL SASHES, FRAMES, AND CASINGS HAVE SOME MEMBERS 30% – 40% COMPLETELY DETERIORATED
U = UNSATISFACTORY	EXTERIOR FINISHES HAVE COMPLETELY DETERIORATED
	PUTTY GLAZING MOSTLY MISSING – ALL SASHES, FRAMES, AND CASING MEMBERS HAVE MORE THAN 30% - 40% DETERIORATION, BEYOND REPAIR

NOTES:

LABEL	WINDOW & DOOR DESCRIPTION	CONDITION & INTEGRITY CODE	HISTORIC/NON-HISTORIC - AGE
SOUTH			
A	30" x 56" DOUBLE HUNG 4W1H/1-LT ALL WOOD	F	**HISTORIC** – LEFT SIDE OF TOP SASH, SILL & BOTTOM SASH ROTTED BEYOND 40 %
B	30" x 56" DOUBLE HUNG 4W1H/1-LT ALL WOOD	F	**HISTORIC** – SILL & BOTTOM RAIL OF TOP & BOTTOM SASH ROTTED BEYOND 40 %
C	60" x 56" TWIN DOUBLE HUNG 4W1H/1-LT ALL WOOD (2-28")	F	**HISTORIC** – BOTTOM RAILS & LEFT SIDE STILES ON LEFT WINDOW & RIGHT-SIDE STILE ON RIGHT WINDOW ROTTED BEYOND 40%, EXTERIOR MULL COVER IS ALSO ROTTED BEYOND 40%
DR #1	32" x 80" RH INSWING ARCH TOP V-GROOVE ALL WOOD DOOR	S	**NON-HISTORIC** – SIMPSON DOOR (2011)
WEST			
D	36" x 56" DOUBLE HUNG 1/1 ALL WOOD	S	**NON-HISTORIC** – SASHES ARE NEWER MACHINED SASHES ROUTERED/SHAPER, NON-DIVIDED LIGHTS, STUCCO SHOWS SIZE OF ORIGINAL OPENING CHANGE (1984)
E	36" x 56" DOUBLE HUNG 1/1 ALL WOOD	S	**NON-HISTORIC** – SASHES ARE NEWER MACHINED SASHES ROUTERED/SHAPER, NON-DIVIDED LIGHTS, STUCCO SHOWS SIZE OF ORIGINAL OPENING CHANGE (1984)

NOTES:

LABEL	WINDOW & DOOR DESCRIPTION	CONDITION & INTEGRITY CODE	HISTORIC/NON-HISTORIC – AGE
NORTH			
F	68" x 54" TRIPLE ALL STATS 2W4H ALL WOOD	U	**NON-HISTORIC** – SILL ROTTED & BURIED IN STUCCO ALLOWING WATER TO LEAK INTO THE WALL, WINDOW UNIT WAS A ORINGINALLY A TRIPLE DOUBLE HUNG, NON 3 BARNSASHES FROM 1980's IN THE PLACE OF THE DOUBLE HUNGS
G	60" x 56" TWIN DOUBLE HUNG 4W1H/1-LT ALL WOOD (2-28")	U	**HISTORIC** – SILLS, BOTTOM RAILS OF BOTTOM SASHES, & SIDE JAMBS GOING UP 12" ON EACH SIDE ROTTED BEYOND 40%, SHOWING SIGNS OF WATER LEAKING INTO THE WALL
H	30" x 36" DOUBLE HUNG 4W1H/1-LT ALL WOOD	F	**HISTORIC**
I	36" x 48" DOUBLE HUNG 1/1 1-LT ALL WOOD	U	**NON-HISTORIC** – SILL, BOTTOM RAIL OF BOTTOM SASH, & SIDE JAMBS ROTTED BEYOND 40%, ALLOWING WATER TO LEAK INTO THE WALL, NO DIVIDED LIGHTS (1984)
EAST			
J	36" x 48" DOUBLE HUNG 1/1 1-LT ALL WOOD	F	**NON-HISTORIC** – NO DIVIDED LIGHTS (1984)
DR #2	32" x 80" LH INSWING 1-LT ALL WOOD DOOR 18" BOTTOM RAIL	S	**NON-HISTORIC** – SIMPSON DOOR (2013)
K	36" x 48" DOUBLE HUNG 1/1 1-LT	F	**NON-HISTORIC** – NO DIVIDED LIGHTS (1984)
L	28" x 56" DOUBLE HUNG 4W1H/1-LT ALL WOOD	U	**HISTORIC** – WINDOW UNIT HAS OVER 40% ROT & BONDO ON BOTH SASHES & JAMBS

NOTES:

LABEL	WINDOW & DOOR DESCRIPTION	CONDITION & INTEGRITY CODE	HISTORIC/NON-HISTORIC – AGE
SOUTH			
C-A	80" x 23" TWIN FIXED 5W1H ALL WOOD (2-40")	U	**NON-HISTORIC** – TWO (2) DOUBLE HUNG SASHES STOPPED IN OVER 40% ROTTED HEAD & JAMB SILL THAT IS COVERED IN GALVANIZED METAL (1984)
WEST			
DR #C-1	95" x 84" LH INSWING ALL WOOD DOOR SIDE LIGHT TRIPLE/FRENCH DOOR/SIDELIGHT 1-LT FULL GLASS 15"/64" (2-32")/15"	F	**NON-HISTORIC** – SIMPSON DOOR (2011)
NORTH			
DR #C-2	32" x 78" LH INSWING ALL WOOD DOOR FULL LIGHT, CUT DOWN BOTTOM RAIL INSULATED GLASS	F	**NON-HISTORIC** – (1988)
C-B	19" x 25" FIXED INSWING STAT 2W2H ALL WOOD	F	**NON-HISTORIC** – BARN SASH (1988)
DR #C-3	32" x 78" RH INSWING ALL WOOD DOOR FULL LIGHT, CUT DOWN BOTTOM RAIL INSULATED GLASS	U	**NON-HISTORIC** – ROTTED BOTTOM RAIL (1988)
EAST			
C-C	29" x 56" DOUBLE HUNG 3W2H/3W2H ALL WOOD 3 ½" FLAT CASING EXTERIOR	U	**NON-HISTORIC** – WINDOW UNIT NOT FROM ORIGINAL ERA, LIGHT PATTERN DIFFERENT THAN THE REST OF THE HOUSE, EXTERIOR CASING HAS A DIFFERENT PROFILE

NOTES:

ALL NEW DOORS PROVIDED SHALL HAVE A MINIMUM U VALUE OF (.5 0)

ALL NEW SKYLIGHTS PROVIDED SHALL HAVE A MINIMUM U VALUE OF (.60)

ALL NEW WINDOWS PROVIDED SHALL HAVE A MINIMUM U VALUE OF (.35)

24" MIN SPACING FROM WINDOW TO DOOR. IF WINDOW IS CLOSER TO DOOR WINDOW MUST BE TEMPERED

MECHANICAL PLUMBING NOTES

1. INSULATION WITH AN R VALUE OF R-19 AND AIR SEALED SHALL BE INSTALLED TO A MINIMUM OF R-19 WALLS IN FLOOR FRAMED OF A MINIMUM OF R-19 INSULATION

2. INSULATION WITH AN R VALUE OF R-3 HOT WATER PIPING AND R-19 INSULATION FOR PIPES 4" DIAMETER SIZE

3. MAXIMUM DISCHARGE OF HOT WATER FROM SHOWERHEADS SHALL BE LIMITED TO 2.5 GALLONS PER MINUTE

Mechanical Plumbing - Electrical

All Mechanical Plumbing and Electrical To Permit All Work Shall Meet Or Exceed The Minimum Standards Set Forth In The New Mexico Residential Code

Contractors To Comply With 2018 International Residential Code and all applicable Codes and Code Books

AREA OF NEW CONSTRUCTION
PORTAL LAUNDRY ADDITION

GENERAL INFORMATION

GENERAL DESCRIPTION OF WORK

EXISTING RESIDENCE SQUARE FOOTAGE

PROPOSED ADDED SQUARE FOOTAGE

EXISTING AND PROPOSED SQUARE FOOTAGE

ADDRESS OF PROJECT

GENERAL PLAN NOTES

PROPOSED WALL LEGEND

EXISTING WALL LEGEND

EXISTING RESIDENCE
(NO CONSTRUCTION)

EXISTING FLOOR PLAN

SCALE 1/4" = 1' 0"

EXISTING RESIDENCE
(NO CONSTRUCTION)

PROPOSED FLOOR PLAN

SCALE 1/4" = 1' 0"

719 GILDERSLEEVE
SANTA FE, NM 87505

DATE

EXISTING & PROPOSED
FLOOR PLAN

SHEET NO

2



EXISTING NORTH ELEVATION

SCALE: 1/4" = 1'-0"



EXISTING WEST ELEVATION

SCALE: 1/4" = 1'-0"



EXISTING SOUTH ELEVATION

SCALE: 1/4" = 1'-0"



EXISTING EAST ELEVATION

SCALE: 1/4" = 1'-0"

719 GILDERSLEEVE
SANTA FE, NM 87505

DATE
9/28/2020

EXISTING EXTERIOR ELEVATIONS

SHEET NO
3

934 17


SANTA FE AVE.
BOOTH ST.
BUENA VISTA ST.
GILDERSLEEVE ST.
DR. GARCIA ST.
CORONADO
SURVEY LOCATION
VICINITY MAP
AFFIDAVIT
THE FOREGOING SURVEY AND LOT CONSOLIDATION WAS MADE WITH THE FREE CONSENT AND IN ACCORDANCE WITH THE DESIRES OF THE UNDERSIGNED OWNER(S), SUBJECT PROPERTIES LIE WITHIN THE PLANNING AND PLATTING JURISDICTION OF THE CITY OF SANTA FE
ALISON M. KULLER
3/26/26
DATE
STATE OF NEW MEXICO
SS
COUNTY OF SANTA FE
THE FOREGOING INSTRUMENT WAS ACKNOWLEDGED BEFORE ME THIS 26 DAY OF March 2026.
BY: Alison M. Kuller
Philip B. Vogel
MY COMMISSION EXPIRES 9/20/26
NOTARY PUBLIC
PLAT OF LOT CONSOLIDATION
FOR
ALISON M. KULLER
CONSOLIDATING LOT 3 AND LOT 4, BLOCK 10
OF THE BUENA VISTA ADDITION
OF THE CITY OF SANTA FE
INTO LOT 3-4, CITY OF SANTA FE
SANTA FE COUNTY, NEW MEXICO
PURPOSE STATEMENT: THE PURPOSE OF THIS SURVEY IS TO CONSOLIDATE TWO EXISTING LOTS.
CASE No: 2026-11885
CITY OF SANTA FE
REVIEWED:
CITY PLANNER
DATE
ENGINEER FOR LAND USE
DATE
CITY OF SANTA FE NOTES AND CONDITIONS:
1. PROPERTY DEVELOPMENT IS REQUIRED TO COMPLY WITH APPLICABLE PROVISIONS OF CHAPTER 14, LAND DEVELOPMENT CODE, SFCC 1987 AND SUBSEQUENT AMENDMENTS
2. CITY APPROVAL OF THIS PLAT DOES NOT REMOVE OR ALTER OR REMOVE ANY EASEMENTS, RESTRICTIONS OR RESERVATIONS OF RECORD PERTAINING TO THE LAND HEREON DESCRIBED.
N
SCALE: 1"=10'
LEGEND
Sewer manhole
Points found and used as noted
1/2" Capped iron pin set this survey
Power poles
Fences
Walls
Concrete
NOTES
1. BASE OF BEARINGS: GPS OBSERVATION OF FOUND MONUMENTS ON THE EAST BOUNDARY OF GILDERSLEEVE STREET, ON 9721'43" E), NAD 83, NM STATE PLANE, CENTRAL ZONE, GRID.
2. THIS SURVEY IS BASED ON A PLAT OF THE BUENA VISTA ADDITION TO THE CITY OF SANTA FE, IN PLAT BOOK 1 AT PAGE 75, RECORDS OF SANTA FE COUNTY, NM. REFERENCE PLAT OF SURVEY FOR MICHAEL WINELAND, RECORDED IN PLAT BK. 278, P. 028, RECORDS OF SANTA FE COUNTY, NM. BEARINGS AND DISTANCES IN ( ) ARE FROM SAID PLAT
3. REFERENCE DEED: INST. No. 1885470
3-A. REFERENCE DEED: BK. 28, P. 321, DATED 30 JAN. 1945.
4. a.) PROPERTY DEVELOPMENT IS REQUIRED TO COMPLY WITH APPLICABLE PROVISIONS OF CHAPTER 14, LAND DEVELOPMENT CODE, SFCC 1987 AND SUBSEQUENT AMENDMENTS.
b.) PROPERTY DEVELOPMENT IS REQUIRED TO COMPLY WITH THE PROVISIONS OF EACH CITY OF SANTA FE ORDINANCE ADOPTED PRIOR TO PLAT AND/OR DEVELOPMENT PLAN RECORDING WITH THE COUNTY CLERK OR SUBMITAL FOR A BUILDING PERMIT APPLICATION THAT MODIFIES ANY PROVISION OF CHAPTER 14, LAND DEVELOPMENT CODE, SFCC 1987 AND SUBSEQUENT AMENDMENTS
c.) BUILDABLE AREAS FOR PLATTED PARCELS WILL BE DETERMINED AT THE TIME OF BUILDING PERMIT APPLICATION AS DETAILED IN THE LAND DEVELOPMENT CODE. ANY BUILDABLE AREAS SHOWN HEREON ARE SUBJECT TO RELOCATION PER CODE REQUIREMENTS.
5. PROPERTY LIES IN FEMA FLOOD ZONE 35049C0413E ZONE X EFFECTIVE 12/4/2012.
CERTIFICATE
I, Philip B. Vogel, a duly registered Professional Surveyor in the State of New Mexico hereby certify that I conducted and am responsible for this survey, that this survey and plat represent an actual survey made in the field by me or under my direction, that it meets the Minimum Standards for Surveys in New Mexico and that the information contained herein is true and correct to the best of my knowledge, information and belief
Philip B. Vogel 8 May, 2025
Philip B. Vogel
P.S. No. 9758
P.O. Box 22773
Santa Fe, NM
PHILIP B. VOGEL
NEW MEXICO
9758
S. BARRY & DARLEEN WASHER
LOT 1 & 2 BLOCK 10
BUENA VISTA ADDITION
BK. 1974, P. 053
S 80°35'34" E
50.00'
127.12'
S 08°32'26" W
N 09°21'43" E
137.55'
N 80°40'15" W
68.83'
RESIDENCE
No. 719
2,379 sq. ft. of residence
LOT 3-4
6355.8 SQ.FT.
0.1459 ACRES±
ORIGINAL LOT 3
"OLD LOT LINE" HEREBY VACATED
ORIGINAL LOT 4
DRIVEWAY PARKING
GILDERSLEEVE STREET
50' ROW
H/T
DEBORA J. SPEYER REVOCABLE TRUST
UNIT A, CAPITOL SUMMIT COMPOUND
INST No. 1848595
H/T
JKG DEVELOPMENTS, LLC
INST. No. 1381309
PLAT BK. 564, P. 004
ADA RESIDENCE
SEWER MANHOLE
No. 81.44A/2
COUNTY OF SANTA FE
STATE OF NEW MEXICO
SANTA FE COUNTY CLERK
SANTA FE COUNTY CLERK
DATE
SANTA FE COUNTY TREASURER
3/31/2026
SANTA FE COUNTY TREASURER
DATE
INDEXING INFORMATION FOR COUNTY CLERK
BOUNDARY SURVEY
OWNER: ALISON M. KULLER
LOCATION: 719 GILDERSLEEVE ST SANTA FE
T 17 N, R 9 E, SECTION 25
PROJECTED INTO THE SANTA FE GRANT
UPC: 1-034-098-206-361
SUBDIVISION: BUENA VISTA ADDITION
SANTA FE COUNTY, N.M.
DEL RIO SURVEYS, INC.
PO BOX 22773
SANTA FE, NM
920-9200
Project No. 25040200
Dwg. PV
Chk. DV
Date: 05/08/25
REV. 3

719 Gildersleeve
West Elevation

South
Elevation
Window A.

South Elevation
Window B.

South
Elevation
Window C.

South
Elevation
Door #1.

West Elevation
Window D.

West Elevation
Window E.

North
Elevation
Window
F.

North
Elevation
Window G.

North Elevation
Window H.

North Elevation
Window I.

East Elevation
Window
J.

East Elevation
Door #2.

East Elevation
Window
K.

East
Elevation
Window L.

719
Gildersleeve
Southwest
Elevation.

719 Gildersleeve
Southwest
elevation

719.
Gildersleeve
North Elevation.

719
Gilderslee
ve
North
Elevation

719
Gildersleeve
North
Elevation.

719
Gildersleeve
North Elevation

719
Gildersleeve
East

719
Gildersleeve
Casita
West
Elevation

South
Elevation
Casita
Window
CA

West
Elevation
Casita Door #
C-1

North Elevation
Casita
Door C-2…

North Elevation
Casita
Window C-B.

North Elevation
Casita
Door # C-3.

East Elevation
Casita
Window C-C.

719
Gildersleeve
Casita
East.

719 Gildersleeve
Casita
North Elevation.

719
Gildersleeve
Casita
South
Elevation

Typical
rotted
sill.

City of Santa Fe, New Mexico

200 Lincoln Avenue, P.O. Box 909, Santa Fe, N.M. 87504-0909
www.santafenm.gov

David Coss, *Mayor*

Councilors:
Rebecca Wurzburger, Mayor Pro Tem, Dist. 2
Patti J. Bushee, Dist. 1
Chris Calvert, Dist. 1
Peter N. Ives, Dist. 2
Carmichael A. Dominguez, Dist. 3
Christopher M. Rivera, Dist. 3
Bill Dimas, Dist. 4
Ronald S. Trujillo, Dist. 4

Memorandum

To: Members of the Governing Body

From: Kelley Brennan KAB
Assistant City Attorney

Via: Geno Zamora
City Attorney

Re: Appeal of Diane Taliaferro from the
December 11, 2012 Decision of the Historic Districts Review Board
in Case #H-12-088
Driveway Relocation at 719 Gildersleeve Street
Case No. 2012-152

Date: December 31, 2012 for the January 9, 2013 Meeting of the Governing Body

The Appeal

On December 20, 2012 Diane Taliaferro[1] (Appellant) filed a Verified Appeal Petition (Petition) appealing the November 13, 2012 decision (the Decision) of the Historic Districts Review Board (HDRB) approving the application (Application) of Brian Blount and Caryli Blount (Applicants) to relocate the driveway and make related improvements (Project) to property they own at 719 Gildersleeve Street (Property). Copies of the Petition and the Application are attached as **Exhibit A** and **Exhibit B** respectively.

The Property

The Property is comprised of 0.146± acres of land improved with a single dwelling unit that fronts on Gildersleeve (Residence) and attached studio (Studio) in the rear, as well as with

[1] The Petition lists the following additional appellants: Pamela Cerosimo, 716 Gildersleeve; Marion Kassin, 714 Gildersleeve; Martha Abernathy, 718 Gildersleeve; and Sloan Cunningham, 907 Gildersleeve. As Diane Taliaferro is the sole appellant who executed the Petition, we refer to her throughout as the Appellant.

certain incidental improvements such as walls and fences. The Residence is contributing to the Don Gaspar Area Historic District (District). The Property is zoned R-21 (Residential – 21 dwelling units/acre).

History of the Case

The Project includes the relocation of the driveway from the south side of the Property to the north side, entailing, among other things, the removal of portions of an existing historic front retaining wall (Front Wall) and of an historic yard wall set back from the street to (Side Wall) to create an opening for the new driveway and infill of the existing driveway opening. A non-historic coyote fence located on the street side of the Side Wall will also be removed. The new driveway location will provide access to four parking spaces at the back of the Property to meet zoning requirements for two dwelling units. Currently, there is one parking space on the Property, with a potential for two. The additional two parking spaces provided by the Project will support the conversion of the Studio to a dwelling unit, which is permitted under applicable zoning[2]. However, the Application does not include modifications to the Residence or Studio.

The HDRB held a hearing on the Application on November 13, 2012 (the Hearing). HDRB staff provided the HDRB with a report (Staff Report) briefly describing the Application and recommending that the HDRB approve the Application and the exception for the removal of Front Wall and Side Wall historic materials. A copy of the Staff Report is attached as **Exhibit C**[3]. A copy of the minutes of the Hearing is attached as **Exhibit D**.

Findings of Fact and Conclusions of Law embodying the Decision were adopted by the HDRB on December 11, 2012 (Findings). The Findings (Item #12-102) are attached as **Exhibit E**.

Basis of Appeal

The Appellant states generally her belief that the Project will be detrimental to the historic character of the 700 block of Gildersleeve Street where it is located and expresses concern that the Project is intended as a first step to further development on the Property. She cites the following specific bases for appeal:

1. The Applicant was not the owner of the Property at the time the Application was filed (Claim 1).
2. The historic character of the Front Wall and the Side Wall has not been determined (Claim 2).
3. The Project will require the removal of two mature trees (Claim 3).
4. A prior HDRB approval required the then-owner to retain the white stucco as its historic color (Claim 4).

[2] R-21 zoning would allow for 3 dwelling units on the Property.
[3] Exhibit C does not include the material identified as "Applicant Submittals", which duplicate the material attached as ExhibitB.

5. It is difficult to determine whether an historic wire fence along the front and side of the house would be compromised (Claim 5).
6. The Application does not indicate whether the existing driveway, including the apron onto the street will be removed (Claim 6).
7. The notice of the Hearing posted on the Property gave the wrong location for the Hearing (Claim 7).

Discussion

Code §14-3.17(A)(2) provides that an appeal can only be filed if:

(1) the final action appealed from does not comply with Code Chapter 14 or §§3-21-1 through 3-21-14 NMSA[4] (the Statute);
(2) Code Chapter 14 has not been applied properly; or
(3) the decision appealed from is not supported by substantial evidence.

Pursuant to Code §14-3.17(D)(6)(a) the City Attorney's Office (CAO) has reviewed the Petition and for the reasons set forth below concurs with the determination of the Land Use Department Director that it does not conform to the requirements of Code §14-3.17 in that it does not state a valid basis for appeal under any of the foregoing provisions.

General Claims. With respect to Appellant's general statement that the Project will be detrimental to the historic character of the 700 block of Gildersleeve Street where it is located, she describes that character as including "*single family homes and several compounds all accessed by a single driveway.*" First, the Application, while stating the Applicants' intention to "*undertake improvements to [the Studio] to render it a fully functional dwelling unit*", it also states that "*[n]o modifications to the [R]esidence and [S]tudio are proposed with [the Application].*" But even if the Application did include modifications to the Residence and Studio, the HDRB does not have jurisdiction to determine whether a second dwelling unit is permitted on the Property; its jurisdiction generally is over publicly visible exterior modifications. In fact, a second dwelling unit is permitted by the underlying zoning. In addition, if and when the Studio is improved to make it a second dwelling unit, it and the Residence will be "*single-family homes...accessed by a single driveway*" consistent with how the Appellant has defined the historic character of the 700 block of Gildersleeve Street.

The Appellant's general claim does not fall within any of the three bases for appeal cited above and should be dismissed.

[4] Section 3-21-8 B. NMSA 1978 provides in pertinent part: "Any aggrieved person...affected by a decision of an administrative...commission or committee in the enforcement of Sections 3-21-1 through 3-21-14 NMSA 1978 or ordinance, resolution, rule or regulation adopted pursuant to these sections may appeal to the zoning authority. ..."

Claim 1. *The Applicants were not the owners of the Property at the time the Application was filed.*

Code §14-3.1(B)(1) provides in relevant part that applications for review and approval under Chapter 14 may be filed by the owner of the property that is the subject of the application or the owner's authorized agent with written authorization. The Application was submitted on behalf of the Applicants by JenkinsGavin Design & Development, Inc. (JGD&D) on October 17, 2012 and included the Applicants' October 8, 2012 written authorization designating JGD&D as their agent. The Application correctly listed the Estate of Jennifer A. Thompson as the owner and specifically noted at the bottom that the "*Applicant is under contract to purchase the [P]roperty.*" The Property was conveyed to the Applicants by deed dated November 2, 2012.

HDRB staff advised JGD&D at the time the Application was filed that the Applicants had to own the Property at the time the Application was heard by the HDRB, but consistent with City practice, accepted the Application on the understanding that the Applicants intended to purchase the Property.

In any event, JGD&D's failure to provide the prior owner's written authorization of agency at the time the Application was filed on October 17, 2012 was immaterial to the outcome and did not prejudice the Appellant[5]. The Applicants indisputably owned the Property at the time of the Hearing. If they had waited until November 2, 2012 to file the Application, the hearing on the Application would have occurred at a later date. There is no reason to suppose that the outcome would have differed. Nor does the failure result in any discernible prejudice to the Appellant.

Claim 1 does not fall within any of the three bases for appeal cited above and should be dismissed.

Claim 2. *The historic character of the Front Wall and the Side Wall has not been determined.*

Code §14-5.2(D)(1)(a) prohibits the removal of historic materials that embody a property's contributing status. Code §14-5.2(C)(5) authorizes the HDRB to grant an exception to Code §14-5.2 requirements. While the Applicants did not unequivocally know that the Front Wall and the Side Wall were historic, they assumed they were. As a result, they sought, and obtained, HDRB approval for an exception to permit the removal of historic materials necessary to carry out the Project. The Appellant's statements, to the extent they demonstrate that the Front Wall and the Side Wall are historic, merely support the Applicants' decision to seek an exception for any removal.

---

[5] These kinds of mistakes are identified as "harmless error". New Mexico courts have held that failure to comply with a rule of Civil Procedure does not constitute reversible error unless prejudice is shown. *Jewell v. Seidenberg*, 82 N.M. 120, 124, 477 P.2d 296, 300 (1970), citing *Martinez v. Research Park, Inc.*, 75 N.M. 672, 410 P.2d 200 (1965). Harmless error is defined as "...an error which is trivial or formal or merely academic and...not prejudicial to the substantial rights of the party..., and in no way affected the final outcome of the case." *State v. Zamora*, 91 N.M. 470, 474, 575 P.2d 1355, 1359 (Ct. App. 1978), citing *State v. Johnson*, 1 Wash.App. 553, 463 P.2d 205, 206 (1969)

Claim 2 does not fall within any of the three bases for appeal cited above and should be dismissed.

Claim 3. *The Project will require the removal of two mature trees.*

The HDRB does not have jurisdiction over trees. Code §14-5.2 regulates generally new construction, alteration and demolition of structures in the historic districts and of landmark structures outside the historic districts. Code §12-1 defines a "structure" as "*[a]nything that is constructed or erected with a fixed location on the ground or attached to something having a fixed location on the ground…*" Trees are not "structures" and the HDRB does not have jurisdiction over their removal. That jurisdiction is vested in the Land Use Department Director by Code §14-8.4(F)(5)(c), which prohibits the removal of existing deciduous trees with a 6" or greater caliper without his approval. Pursuant to Code §14-8.4(B)(2)(b), that requirement applies to the Project. In addition, in an October 30, 2012 email to JGD&D, Robert Montoya, on behalf of the City's Traffic Engineering Division, indicated that the trees in the front of the Property would not have to be removed to improve sight distance. A copy of that email is attached as **Exhibit F**.

Claim 3 does not fall within any of the three bases for appeal cited above and should be dismissed.

Claim 4. *A prior HDRB approval required the then-owner to retain the white stucco as its historic color.*

It is difficult to understand the Appellants' intent in making this claim. The Applicants have not proposed changing the stucco color. The infill of the Front Wall at the existing driveway opening must be "in kind", that is, it will match the appearance of the existing structure in style and color. JGD&D acknowledged this requirement at the Hearing, saying with respect to the Front Wall that "*...they didn't know [the composition of the wall], but they would replace aesthetically in kind if they couldn't replace the composition in kind.*" The Side Wall will be removed in its entirety and the question of stucco color does not arrive.

Claim 4 does not fall within any of the three bases for appeal cited above and should be dismissed.

Claim 5. *It is difficult to determine whether an historic wire fence along the front and side of the house would be compromised.*

It appears that the Appellant is referring in this claim to what appears to be an historic wire fence (Fence) running along the front and the side of the property to the north of the Property. The Application does not affect the Fence. As a result, the Decision does not address the Fence.

Claim 5 does not fall within any of the three bases for appeal cited above and should be dismissed.

Claim 6. *The Application does not indicate whether the existing driveway, including the apron onto the street will be removed.*

This claim is not in reality a claim; instead, it is an expression of the Appellant's ideal: "*To enhance the view of the [P]roperty [from the street,] it would be ideal if the [HDRB] recommended removal of the coyote fence to conform to the historic character of the [P]roperty…*", as well as "*…removal of the [existing] driveway apron and repair of the sidewalk and curb adjacent to the street…*"

The site plan submitted with the Application shows the Property's street-side property line running just outside and parallel to the Front Wall. Generally, the Land Use Department and the City's Traffic Engineering Division regulate infrastructure improvements and alterations. JG&DD's statement at the Hearing that "*…the City required that they close the existing driveway so they would reclaim that…*" indicates that at construction permitting the Applicants will be required to close the existing driveway opening at the street by installing curb and to restore the planting strip between curb and sidewalk and sidewalk and Front Wall.

Claim 6 does not fall within any of the three bases for appeal cited above and should be dismissed.

Claim 7. *The notice of the Hearing posted on the Property gave the wrong location for the Hearing.*

A copy of the notice of the hearing posted on the Property is attached as **Exhibit G**. The location given for the Hearing is "*City Council Chambers at City Hall, 200 Lincoln Ave.*" Due to a scheduling conflict, the Hearing was moved to the Lamy Room at the Convention Center. Notices of the change in location were posted on the Lincoln Street and Marcy Street doors to City Hall and on the City Council Chambers doors. In addition, signs were posted at the Convention Center to direct attendees to the Lamy Room. Notice of the meeting location was therefore sufficient.

In any event, the Appellant had actual notice of the Hearing location, as she and others appeared and testified at the Hearing. "'*Actual notice' refers to information that was communicated directly to or received by a party.*" Pollock v. Ramirez, 117 N.M. 187 (Ct. App. 1994). "*Actual notice... is sufficient and dispenses with statutory notice.*" Acceptance Corp. of Sante Fe v. Valencia, 70 N.M. 307, 309 (1962). *See also*, Bennett v. City Council for City of Las Cruces, 1999-NMCA-015, 126 N.M. 619, 621 ("*Our Supreme Court has held that 'substantial compliance' with notice and publication is sufficient to satisfy statutory requirements. ...stating that while 'some courts have held that even a minor defect in notice will invalidate an action taken by the zoning authority, New Mexico does not take such a strict view…'*" (*citations omitted*).

The Appellant also claims that the notice period was "extremely short" and hampered the neighbors in preparing objections to the Project. However, the notice conformed to statutory and

Chapter 14 requirements and provided the same notice given for every other application to the HDRB.

Claim 7 does not fall within any of the three bases for appeal cited above and should be dismissed.

Conclusion

The Appellant has not effectively alleged that the Decision does not comply with applicable Code or the Statute; that the Code has been improperly applied; or is not supported by substantial evidence. As a result, the Appellant has failed to state a valid basis for appeal under Code §14-3.17(A)(2). The CAO recommends that the Appellant's appeal be dismissed.

Case #2012-15

LUD Use Only

Time Filed: 3 pm
Fee paid: $ 100
Receipt attached: ☑

RECEIVED (date stamp)
DEC 20 2012
LAND USE DEPARTMENT

VERIFIED APPEAL PETITION

Two originals of this form must be filed. The Land Use Department Director or his/her designee will enter the date and time of receipt and initial both originals. See Section 14-3.17(D) SFCC 2001 for the procedure.

Appellant Information

Name: TALIAFERRO (Last) DIANE (First) M (M.I.)

Address: 716 GILDERSLEEVE STREET (Street Address) (Suite/Unit #)

SANTA FE, NM 87505 (City) (State) (ZIP Code)

Phone: (505) 983-8634 E-mail Address: LUKLA1@MSN.COM

Additional Appellant Names: SEE ATTACHED SHEET

Correspondence Directed to: ☒ Appellant ☐ Agent ☐ Both

Agent Authorization (if applicable)

I/We: _____

authorize _____ to act as my/our agent to execute this application.

Signed: _____ Date: _____

Signed: _____ Date: _____

Subject of Appeal

Project Name: _____

Applicant or Owner Name: BRIAN BLOUNT, JENKINS GAVIN, AGENT

Location of Subject Site: 719 GILDERSLEEVE STREET SANTA FE

Case Number: H-12-088 Permit Number (if applicable): _____

Final Action Appealed:

☐ Issuance of Building Permit ☐ Other Final Determination of LUD Director

Final Action of Board or Commission (specify): ☐ Planning Commission ☒ Board of Adjustment ☐ BCD-DRC ☒ HDRB

Basis of Standing (see Section 14-3.17(B) SFCC 2001):

APPELLANTS ARE PROPERTY OWNERS AND RESIDENTS OF GILDERSLEEVE ST.

Basis for Appeal: ☒ The facts were incorrectly determined ☐ Ordinances/laws were violated and/or misrepresented

Description of the final action appealed from, and date on which final action was taken:

REMOVAL OF RETAINING WALL AND YARD WALL TO CONST
AND PARKING FOR ADDITIONAL UNITS

EXHIBIT tabbies A

☐ Check here if you have attached a copy of the final action that is being appealed.

Description of Harm

Describe the harm that would result to you from the action appealed from (attach additional pages if necessary):

SEE ATTACHED

Explain the Basis for Appeal

Please detail the basis for Appeal here (be specific):

SE ATTACHED

Signature and Verification

I hereby certify that the documents submitted for review and consideration by the City of Santa Fe have been prepared to meet the minimum standards outlined in the Land Development Code, Chapter 14 SFCC 2001. Failure to meet these standards may result in the rejection or postponement of my application. I also certify that I have met with the City's Current Planning staff to verify that the attached proposal is in compliance with the City's zoning requirements.

Appellant Signature: Diane M Talia Date: 12/18/2012

Agent Signature: N/A Date: N/A

State of New Mexico)
) ss.
County of Santa Fe)

I/We Diane M Talia, being first duly sworn, depose and say: I/We have read the foregoing appeal petition and know the contents thereof and that the same are true to my/our own knowledge.

Petitioner/s:

Diane M Talia
Signature

N/A
Signature

Diane Taliaferro
Print Name

N/A
Print Name

Subscribed and sworn to before me this 18th day of December, 2012.

OFFICIAL SEAL
Olivia Ortiz
NOTARY PUBLIC
STATE OF NEW MEXICO
My Commission Expires: 07-06-13

Olivia Ortiz
NOTARY PUBLIC
My commission expires: 07-06-13

Diane Taliaferro
716 Gildersleeve St
Santa Fe, NM 87505
Appeal Case # H-12-088

Harm to the Neighborhood

Gildersleeve Street, as part of the Don Gaspar Historic District, is comprised of single family homes and several compounds, all accessed by a single driveway. The 700 block retains its original character; the appellants believe the proposed changes at 719 Gildersleeve will be detrimental to that character. We are also concerned that the current proposal is deliberately limited in scope to create access to further unspecified development on the property.

Basis for Appeal:

- Gavin-Stevens acting as agent of owner without knowledge of owner. According to Nov 13 telephone conversation with Geoffrey Thompson, as legal representative of the estate of Jennifer Thompson, the owner was not aware of the actions of buyer in reference to application to the HDRB until the date of closing, Nov 2. He stated that he signed a form at that time granting permission for this process because he was told that, though the property had closed, the deed would not be received for several days and the buyer wanted permission to bring his application to the board without waiting for the deed to be recorded. From the board's website, the schedule for the Nov 13 meeting required submission by Oct 17. Whether or not the contract for sale was contingent upon HRB approval, the owner of record had no knowledge of, nor did he approve Gavin-Stevens acting as 'agent' of the estate. On the agenda, Gavin Stevens was listed as agent for the estate of Jennifer Thompson. When this was pointed out to the members of the board, they seem to be unaware that the seller had not given permission for the firm to act as its agent.

- Determination of historic character of two property walls. The first wall in question is a retaining wall separating the front of the property from sidewalk on Gildersleeve Street, which was constructed in 1924. (Note the brass plaque embedded in the concrete in the middle of the street at the top of the 700 block) The adjacent property to the north has a similar retaining wall, topped by a historically significant wire fence. Mention was made in the Nov 13 meeting that the property line between these properties is the same wire. Because the walls follow the grade of the street, it may be argued that they are of the same time period. No sampling of the wall material was made. The use of aerial photos was reportedly inconclusive. A former resident of the block with many years' knowledge of the neighborhood has offered his testimony and has photographic evidence of a section of the retaining wall in question. The second wall is also historic at about 8 feet with a stone base as the foundation and stucco on top that

matches another wall dividing the properties. The driveway proposal will also compromise at least 2 mature trees that will have to be completely removed

- Prior Historic Board reviews of 719 Gildersleeve. The previous owner was not allowed to change the color of the stucco on the house or walls because it was deemed that the original white was indeed historic.

- No official survey, property corner determination or engineering report for the driveway. It is difficult at this time to determine whether the wire fence along the front and side of the house would be compromised, which in fact is historic as noted by the board in the meeting held on Nov. 13th.

- Original driveway location. There was no indication in the driveway proposal to rehab the original driveway or remove the concrete apron to the street. Due to the grade elevation of the current driveway this will be quite noticeable from the street despite the applicant's verbal assurances that an extension of the existing wall will be constructed across the driveway.

- View from the Street. To enhance the street view of the property it would be ideal if the board recommended removal of the coyote fence to conform to the historic character of the property. Also, removal of the driveway apron and repair of the sidewalk and curb adjacent to the street to conform to the 'one driveway per property' nature of the neighborhood. The representative from Jenkins Gavin informed us at the close of the Nov 13 meeting that there was no plan to remove any concrete from the existing drive. This was not part of the proposal; however it appears this could be an opportunity to work with the new owner to instill the goal of historic preservation.

- The original notification poster placed on the property gave the wrong meeting site and was not amended as were other posters on locations under review on Nov 13's meeting (612 Old Santa Fe Trail). This, and the extremely short notice gave the neighbors little time to prepare objections to the project. The applicant did not offer any information, verbally or in writing, (as was requested, because we were unavailable in person from Oct 29 through Nov 13). Gavin-Stevens' representative offered no information, nor did the architectural firm, which also preformed site visits prior to closing of the property on Nov 2.

Additional Appellants

Pamela Cersosimo
716 Gildersleeve

Marion Kassin
714 Gildersleeve

Martha Abernathy
718 Gildersleeve

Sloan Cunningham
907 Gildersleeve

We are totally opposed to the owners of 719 Gildersleeve Street adjacent to our property on 715 Gildersleeve Street putting a road and an additional house on the back of their property. This road would significantly change the historic character of the street. There is a reason that the drives are placed adjacent and there is a quiet space between each adjacent house. Adding a road on the north side of the 719 Gildersleeve house would eliminate this buffer quiet space and interfere significantly with the quiet enjoyment of our two homes at 715 Gildersleeve.

This is unacceptable.

We concur with the neighbors who oppose this variance.

We support every effort to stop the actions of the owners of 719 Gildersleeve Street.

Please let us know as soon as possible what the next steps are to make sure the road and additional house are not constructed.

Thank you.

Sincerely,

S. Barry Paisner and Charleen Touchette

Owners of 715 Gildersleeve Street

11/14/2012

I ATTEST THIS PICTURE WAS TAKEN OF ME WHEN I RESIDED AT 714 GILDERSLEEVE.

AS I REMEMBER THIS PICTURE WAS TAKEN OF ME SOMETIME IN THE MID-50's. MY FAMILY OWNED THE HOUSE @ 714 FROM 1943 UNTIL 2005. TO MY KNOWLEDGE, THE SAME WALL IN FRONT OF 719 GILDERSLEEVE WAS IN PLACE ALL OF THAT PERIOD.

Barbara R. Cockrell

11/14/12 witness: Marika Abernathy

City of Santa Fe
Cashiers Office
Santa Fe, NM 87504
(505)955-4333

12/20/2012 2:51:26 PM
Your cashier was LORRAINE
B002501112354 T89

Development Review
PAMELA CERSOSIMO

11001.431470	$100.00
Total	$100.00
Check 1645	$100.00
Change	$0.00

Thank you!

jenkinsgavin
DESIGN & DEVELOPMENT INC

Revised

October 17, 2012

John Murphey
Historic Preservation Division
City of Santa Fe
200 Lincoln Avenue
Santa Fe, NM 87501

RE: 719 Gildersleeve Street

Dear John:

This letter is submitted on behalf of Brian and Caryll Blount in application for an Exception for proposed modifications to existing yardwalls to accommodate a new driveway at the above named residence, for consideration by the Historic Districts Review Board on November 13, 2012. The ±0.146-acre tract is zoned R-21 and is located within the Don Gaspar Historic District. The proposed improvements are described below.

Existing Conditions

The property comprises an 1,800 square foot Contributing residence and attached studio built in the Pueblo Revival style. No modifications to the residence and studio are proposed with this application. The existing 2'6" high stucco yardwall along the street includes buttress elements on either side of the existing driveway at the south property boundary. Also existing adjacent to the north property line are a newer coyote fence and one additional rear wall barely visible from the street, and thus minimally impacting the building's façade.

Proposed Modifications

The current driveway provides only one off-street parking space. It is the applicant's intention to undertake improvements to the existing studio to render it a fully functional dwelling unit. Therefore, per SFCC §14-8.6-1, four parking spaces are required, two for each dwelling unit. To accomplish this, the applicant proposes to move the driveway to the north property boundary in order to access a proposed parking area with four parking spaces at the rear of the property.

The driveway and parking surfaces will be Santa Fe Brown gravel. Moving the driveway will entail filling in the wall at the current driveway and removing a portion of the wall at the north property boundary to allow for driveway access. This modification will create a mirror image of the current wall orientation, allowing the experience of the façade from the street to remain essentially unchanged. The additional rear wall will also have to be removed; as stated above,

130 GRANT AVENUE, SUITE 101 SANTA FE, NEW MEXICO 87501 PHONE: 505.820.7444 FACSIMILE: 505.820.

EXHIBIT
tabbies B

this will not substantially affect the building's façade. Furthermore, there will still be a substantial backyard directly behind the residence. (See attached site plan.)

Exception Request

We are requesting an Exception from the following Santa Fe City Code provisions to allow the removal of a portion of the front yardwall and replacement of the wall section currently serving the driveway.

SFCC §14-5.2(D)(1)(a) *The status of a significant, contributing, or landmark structure shall be retained and preserved. If a proposed alteration will cause a structure to lose its significant, contributing, or landmark status, the application shall be denied. The removal of historic materials or alteration of architectural features and spaces that embody the status shall be prohibited.*

SFCC §14-5.2(C)(1)(c)*Distinctive features, finishes, and construction techniques or examples of craftsmanship that characterize a structure be preserved.*

Below are our responses to the approval criteria from SFCC §14-5.2(C)(5)(c).

(i) Do not damage the character of the streetscape;

Removing a portion of the front yardwall to allow for a driveway will not damage the character of the streetscape, as the wall will be subsequently replaced on the opposite side of the property where it now breaks for the existing driveway. The result will be a mirror image that will preserve the character of the historic façade. The additional back yard wall to be removed is minimally visible from the street and will not affect the streetscape.

(ii) Prevent a hardship to the applicant or an injury to the public welfare;

The property now provides for only one off-street parking space for two potential dwelling units. This creates a hardship for the residents, as on-street parking is at a premium on this densely populated street. In order for the applicant to obtain a permit to convert the existing studio to a fully functional dwelling unit, the property must be brought into compliance with Santa Fe City Code, which calls for two off-street parking spaces for each dwelling unit. Public welfare is served by adding off-street parking to minimize on-street parking in this dense neighborhood.

(iii) Strengthen the unique heterogeneous character of the city by providing a full range of design options to ensure that residents can continue to reside within the historic districts;

Providing the opportunity to move the driveway in order to access off-street parking ensures that residents of the property will be able to comfortably and safely park within

their historic district. Maintaining a desirable residential neighborhood entails ensuring adequate off-street parking.

(iv) Are due to special conditions and circumstances which are peculiar to the land or structure involved and which are not applicable to other lands or structures in the related streetscape;

Several other residences in the related streetscape already have more than one off-street parking space in their side or back yards. The subject property has only one off-street parking space for two potential dwelling units.

(v) Are due to special conditions and circumstances which are not a result of the actions of the applicant;

The property is legal nonconforming in that it has only one off-street parking space when four will be required for the creation of an additional dwelling unit as described above. This is an existing condition that is not a result of the actions of the applicant.

(vi) Provide the least negative impact with respect to the purpose of this section as set forth in Subsection 14-5.2(A)(1).

Replacing one driveway with another, and replacing the wall to close the existing driveway, preserves the historical façade of the building and does not negatively impact the streetscape. The wall will be replaced in its current historic Pueblo Revival style.

The following documentation is submitted herewith for your review:

1. Preliminary Zoning Review Worksheet
2. HDRB Application
3. Owner Documentation
4. Letter of Authorization
5. Photographs of Existing Wall Elevations
6. Submittal Plans – one full size set and two reduced sets
7. Fees in the amount of $625.00 ($350 Exception; $250 construction; $25 poster)

Your consideration of this request is greatly appreciated. Please do not hesitate to contact us should you have any questions or need additional information. Thank you.

Sincerely,

JENKINSGAVIN DESIGN & DEVELOPMENT, INC.

Hillary Welles

Preliminary Zoning Review Worksheet

City of Santa Fe Land Use Department

To Be Completed By Applicant:	
Date Submitted: 10·16·12	Site Address: 719 Gildersleeve
Property Owner of Record: Estate of Jennifer A. Thompson	Proposed Construction Description: Relocate driveway- Modify yardwalls to accommodate driveway.
Applicant/Agent Name: Jenkins Gavin	
Contact Person Phone Number: ( )820 7444	TOTAL ROOF AREA:

NOTE: Preliminary zoning reviews are provided as a courtesy and are intended to address general zoning compliance issues. Applicants are advised to do an independent search of applicable zoning ordinances and to research documents related to property history which may affect permitting. Additionally, applicants are advised to contact appropriate City Staff with questions related to Terrain management, building, fire, water budget, Sangre de Cristo, wastewater, and other development codes which may affect permitting.

BASED ON INFORMATION PRESENTED ON APPLICATION DATE, THIS REVIEW DOES NOT GRANT ZONING APPROVAL AT THE TIME OF BUILDING PERMIT. FINAL ZONING APPROVAL WILL BE GRANTED ONCE ALL COMPLIANCE WITH ZONING HAS BEEN MET.

Hillary Welles for Jenkins Gavin / by F — 11/01/12

☐OWNER ☐APPLICANT ☒AGENT — DATE

Zoning District: R-21

Overlay:
- ☒ Historic Don Gaspar
- ☐ Arts and Crafts
- ☐ Escarpment*
- ☐ Flood Zone*
- ☐ Cerrillos Road Corridor
- ☐ Other: _____

Zoning Submittal Requirements:
- ☒ Legal Lot of Record ☐ Development Plan ☐ Building Plans
- ☒ Existing Site Plan ☒ Proposed Site Plan ☒ Elevations

Supplemental Zoning Submittals:
- ☐ Zero Lot Line Affidavit NA

Access and Visibility: ☐ Arterial or Collector*
- ☒ Visibility Triangle Required see below

Use of Structure:
- ☒ Residential
- ☐ Commercial Type of Use: _____

Terrain: ☐ 30% slopes NA

* Requires an additional review conducted by Technical Review or Traffic Engineering Division to ensure compliance.

Lot Coverage: 26 % No change
☐Open Space Required: _____

Setbacks: NA - No change
Proposed Front: ____ Minimum: ____
2nd Front? ____
Proposed Rear: ____ Minimum: ____
Proposed Sides: L ____ R ____ Minimum: ____

Height: Proposed _____ NA
Maximum Height: _____ or
☐ Regulated by Historic Districts Ordinance
☐ Regulated by Escarpment District

Parking Spaces:
Proposed 4 Accessible** ____
Minimum: 2

Bicycle Parking:**
Proposed: ____ Minimum: ____

** Commercial Requirement

To Be Completed By City Staff:

Additional Agency Review if Applicable:
- ☐ Escarpment Approval by _____ Date: __/__/__ > NA
- ☐ Flood Plain Approval by _____ Date: __/__/__
- ☒ Traffic Engineering Approval by _____ Date: 10/10/12 original approval attached.

Notes: _____

Zoning Approval:
☒ **Preliminary Approval ☐with conditions ☐ Rejected**
Comments/Conditions: _____

REVIEWER: _____ **DATE:** 11/01/12

Note: If approved, please stamp and initial each page of plan set.

Rev. 4-12

HISTORIC DISTRICTS REVIEW BOARD APPLICATION

PROJECT LOCATION: 719 Gildersleeve

HISTORIC DISTRICT: (from attached map) Downtown & Eastside [ ] Don Gaspar Area [✓] Westside-Guadalupe [ ] Historic Transition [ ] Historic Review [ ] Landmark (outside of historic districts) [ ]

PROJECT PROPOSAL: Modify existing yardwalls to accommodate a new driveway.

CONSTRUCTION COST: $ 50,000 **FEE:** $ 250 +$350 Exception +$25 Poster Cost = $ 625.00

OWNER: Estate of Jennifer A. Thompson **PHONE #:** 670-5002

*Applicant ~~OWNER~~ **ADDRESS:** Brian Blount & Caryll Blount, 1372 Santa Rosa Dr.

CITY, STATE, ZIP CODE: Santa Fe, NM 87505

Agent ~~**APPLICANT:**~~ Jenkins Gavin **PHONE #:** 820-7444

ADDRESS: 130 Grant Ave #101

CITY, STATE, ZIP CODE: Santa Fe, NM 87501

NEW CONSTRUCTION:
Single-Family Residence [ ] Commercial [ ] Multi-Family Residence [ ] one exception

OTHER CONSTRUCTION: cut in walls to create drive to rear;
Demolition [ ] Remodel [✓] Addition [ ] Residential [ ] Signs [ ]
Wall/Fence [ ] Antenna [ ]

PREAPPLICATION MEETING: Date: 09/21/12 Case Planner:

PRELIMINARY ZONING REVIEW: Date: 10/16/2012 Planner: Dan Esquibel
(You must schedule a meeting with Zoning Planner prior to the HDRB submittal deadline date. Worksheet will not be reviewed on the HDRB submittal deadline day/Preliminary Zoning Review Form must be submitted with proposal)

HEIGHT CALCULATION
Does the project include multi-story new construction, a building addition, and/or a wall or fence which will increase the height? YES [ ] NO [✓]
If yes, please provide a written request for an updated maximum allowable height calculation.
What is the proposed height of your project? _____

AFFIDAVIT TO AUTHORIZE AGENT (IF APPLICABLE)
I am,/We are the owner(s) and record title holder(s) of the property located at: _____

I/We authorize Please see attached letters of authorization. to act as my/our agent to execute this application.

Signed: _____ Date: _____

Signed: _____ Date: _____

I agree to post notice of the proposed project on the site fourteen (15) days prior to the Historic Districts Review Board hearing. I am aware that a decision of the HDRB may be appealed by any aggrieved party within fifteen (15) days of the adoption of Findings and Conclusions.

Signature of Applicant/Owner

10.17.2012
Date

* Applicant is under contract to purchase the property.

Return to First American Title Insurance Company
File No. NM04-462142-SF01 DK

WARRANTY DEED

Marcia Weese, an unmarried woman, for consideration paid, grant(s) to Jennifer A. Thompson, ~~a single woman~~ * whose address is 719 Gildersleeve, Santa Fe, NM 87501, the following described real estate in Santa Fe County, New Mexico:

Married woman as her sole and separate property

Lots 3 & 4, Block 10 of Buena Vista Addition, as shown on plat entitled "Plat of Survey for Michael L. Wineland...", filed in the office of the County Clerk, Santa Fe County, New Mexico, on June 28, 1994, in Plat Book 278, page 028, as Document No. 868,219.

Subject to patent reservations, restrictions, and easements of record and taxes for the year 2nd half 2004 and subsequent years.

with warranty covenants.

WITNESS my/our hand(s) and seal(s) this 12th day of November, 2004.

Marcia Weese

Individual Capacity

State of Illinois)
) §
County of Cook)

This instrument was acknowledged before me on the 12 day of November, 2004, by Marcia Weese.

Notary Public

My commission expires:
3-4-2007

"OFFICIAL SEAL"
GLORIA SAEZ
Notary Public, State of Illinois
My Commission Expires March 4, 2007

SFC CLERK RECORDED 11/03/2004

COUNTY CLERK
REBECCA BUSTAMANTE
SANTA FE COUNTY NEW MEXICO

COUNTY OF SANTA FE)
STATE OF NEW MEXICO) ss

WARRANTY DEED
PAGES: 1

I Hereby Certify That This Instrument Was Filed for Record On The 18TH Day Of November, A.D., 2004 at 15:22 And Was Duly Recorded as Instrument # 1355356 Of The Records Of Santa Fe County

Witness My Hand And Seal Of Office
Rebecca Bustamante
Deputy _____ County Clerk, Santa Fe, NM

STATE OF CA)
) ss.
COUNTY OF San Diego

I, Geoffrey Graeme Thompson, M.D., accept the duties of personal representative of the Estate of Jennifer A. Thompson, deceased, and do solemnly swear that I will perform, according to law, the duties of personal representative of the Estate.

5/31/11

Geoffrey Graeme Thompson, M.D.

Subscribed and sworn to before me this 31st day of May, 2011, by Geoffrey Graeme Thompson, M.D.

Notary Public

My Commission expires:
Oct 31/2014

OFFICIAL SEAL
RAMONA KHYROLOMOOR
NOTARY PUBLIC-CALIFORNIA
COMM. NO. 1906799
SAN DIEGO COUNTY
MY COMM. EXP. OCT. 31, 2014

ENDORSED
First Judicial District Court
JUN 13 2011
Santa Fe, Rio Arriba & Los Alamos Counties
PO Box 2268
Santa Fe, NM 87504-2268

FIRST JUDICIAL DISTRICT COURT
COUNTY OF SANTA FE
STATE OF NEW MEXICO

No. D-0101-PB-2011-00112

IN THE MATTER OF THE ESTATE OF
JENNIFER A. THOMPSON, Deceased

LETTERS OF ADMINISTRATION AND ACCEPTANCE

This estate having been duly filed with this Court, Geoffrey Graeme Thompson, M.D. is hereby appointed to serve as personal representative of the estate.

DATED: 6.13., 2011

STEPHEN T. PACHECO,
COURT ADMINISTRATOR/CLERK

By: _____
Deputy

I hereby certify that the foregoing pleading is a true and correct copy of same which has been filed in my office on the 13 day of JUNE 2011
Dated this 13 date of JUNE 2011

By: _____
STEPHEN T. PACHECO
Court Administrator/District Court Clerk

25

STATE OF NEW MEXICO

CERTIFICATE OF DEATH

New Mexico Vital Records and Health Statistics
State of New Mexico
United States of America

DECEDENT'S LEGAL NAME		IF FEMALE, MAIDEN NAME
<<<Jennifer Ann Thompson>>>		<<<>>>

DATE OF DEATH	TIME OF DEATH	SEX	SOCIAL SECURITY NUMBER
April 18, 2011	07:35 AM ☐ PM ☒	Female	554-02-2038

MARITAL STATUS	SURVIVING SPOUSE - If wife, maiden name
Divorced	<<<>>>

DATE OF BIRTH	BIRTH PLACE	SERVED IN U.S. ARMED FORCES
September 21, 1954	California	Yes ☐ No ☒

DECEDENT'S RACE	TRIBE	HISPANIC
White	<<<>>>	Yes ☐ No ☒

DECEDENT'S RESIDENCE COUNTY	DECEDENT'S RESIDENCE STATE
Santa Fe	New Mexico

MOTHER'S FULL MAIDEN NAME	FATHER'S FULL NAME
<<<Charlotte Lucille Ellis>>>	<<<Joseph Meacham Thompson>>>

METHOD OF DISPOSITION
☐ Burial ☐ Donation ☐ Removal from State
☒ Cremation ☐ Entombment ☐ Other (Specify): <<<>>>

DISPOSITION LOCATION: Direct Funeral Services Crematory

FUNERAL SERVICE FACILITY	COUNTY OF DEATH
Direct Funeral Services	Santa Fe

PLACE OF DEATH	TYPE OF PLACE	NAME OF PERSON CERTIFYING CAUSE OF DEATH
719 Gildersleeve Street, Santa Fe, New Mexico 87505	Decedent's Residence	<<<Karin E. Thron MD>>>

MANNER OF DEATH: ☒ Natural ☐ Accident ☐ Homicide ☐ Suicide ☐ Undetermined ☐ Pending Investigation

CAUSE OF DEATH

PART I. Events such as diseases, injuries, or complications that directly caused the death.

a. malignant metastatic breast cancer
b. <<<>>>
c. <<<>>>
d. <<<>>>

PART II. Other significant conditions contributing to death.

<<<>>>

File Number: 2011-004540
File Date: April 22, 2011
Order Number: 20110407290
2917472

Mary Anne Escudero, State Registrar

CERTIFIED COPY OF VITAL RECORD
This is a true and exact reproduction of all or part of the document officially registered and filed with the New Mexico Vital Records and Health Statistics, Public Health Division, Department of Health

Donna Dorsey
State Registrar

DATE ISSUED: Mar 25 2011

26

WARNING: IT IS ILLEGAL TO ALTER, COPY OR COUNTERFEIT THIS CERTIFICATE.
ADVERTENCIA: ES ILEGAL ALTERAR, COPIAR O FALSIFICAR ESTE CERTIFICADO.

This document is not authentic unless reproduced on safety paper displaying the Raised Seal of New Mexico

Hold at angle to view

The back of this document contains an artificial watermark

RECEIVED
NOV - 6 2012

Prepared By and Return To:
Fidelity National Title of New Mexico
8500 Menaul Blvd NE, Ste. B150
Albuquerque, NM 87112

GF# FT000114716-NM01

COUNTY OF SANTA FE }
STATE OF NEW MEXICO } ss

WARRANTY DEED
PAGES: 1

I Hereby Certify That This Instrument Was Filed for
Record On The 5TH Day Of November, A.D., 2012 at 03:34:23 PM
And Was Duly Recorded as Instrument # 1686776
Of The Records Of Santa Fe County

Witness My Hand And Seal Of Office
Valerie Espinoza
Deputy - COMONTOYA
County Clerk, Santa Fe, NM

COUNTY CLERK SANTA FE COUNTY NEW MEXICO

WARRANTY DEED
(Joint Tenants)

Geoffrey Graeme Thompson M.D. as Personal Representative of the Estate of Jennifer A. Thompson, deceased

for consideration paid, grant to

Brian Blount and Caryll Pearlman Blount , husband and wife

whose address is 1372 Santa Rosa Dive, Santa Fe, NM 87505

as joint tenants the following described real estate in County, New Mexico:

Lots 3 & 4, Block 10 of the Buena Vista Addition, as shown on "Plat of Survey for Michael L. Wineland...", filed on June 28, 1994 in Plat Book 278, page 028 as Document No. 868219, records of Santa Fe County, New Mexico.

with warranty covenants.

SUBJECT TO Patent, reservations, restrictions, and easements of record and to taxes for the year 2012, and subsequent years.

Witness my hand and seal this 2 day of November 2012

Geoffrey Graeme Thompson M.D., Personal Representative

STATE OF CA

COUNTY OF San Diego

This instrument was acknowledged before me Ramona Khyrolomoor, Notary Public
by Geoffrey Graeme Thompson

Ramona Khyrolomoor
Notary Public

My Commission Expires: Oct 31/2014

(SEAL)

OFFICIAL SEAL
RAMONA KHYROLOMOOR
NOTARY PUBLIC-CALIFORNIA
COMM. NO. 1906799
SAN DIEGO COUNTY
MY COMM. EXP. OCT. 31, 2014

Warranty Deed - Joint Tenants (4-99)
FDNM0025.rdw

PDF created with pdfFactory trial version www.pdffactory.com

October 8, 2012

RE: 719 Gildersleeve Street

To Whom It May Concern:

This letter shall serve as authorization for JenkinsGavin Design & Development, Inc. to act on my behalf with respect to the referenced property regarding land use applications to be submitted to the City of Santa Fe.

Please call should you have any questions or need additional information.

Thank you.

Sincerely,

2D0E58C1A0344C1...
Brian Blount
DocuSigned By: Brian Blount

Brian Blount

719 Gildersleeve Street



Context View



Front Elevation



Southwest Front Elevation – Existing Driveway



Northwest Front Elevation – Location of Proposed Driveway



Stone/Stucco Wall
East Elevation (View From Backyard)
63"H x 11'W x 6"D



Stone/Stucco Wall
West Elevation (View from Front)
88"H x 11'W x 6"D

719 Gildersleeve Street
Additional Wall Photographs



Coyote Fence
69 ½"H x 11'W x 5"D
Photo #1



Coyote Fence
Photo #2



N

EXISTING SITE PLAN

SCALE: 1"= 10'-0"

NOTE: INFORMATION SHOWN HAS BEEN PROVIDED BY OTHERS.



N

PROPOSED SITE PLAN

SCALE: 1"= 10'-0"

NOTE: INFORMATION SHOWN HAS BEEN PROVIDED BY OTHERS.



EXISTING WEST ELEVATION

SCALE: 1/4" = 1'-0"



PROPOSED WEST ELEVATION

SCALE: 1/4" = 1'-0"

BUILDING SQUARE FOOTAGE =	1,600 S.F.
TOTAL ROOFED AREA SQUARE FOOTAGE =	1,902 S.F.
LOT AREA =	6,377 S.F.
TOTAL LOT COVERAGE AREA =	25%

719 Gildersleeve Street
Santa Fe, New Mexico

REVISIONS:
NO. DATE

DATE: 10-15-2012
DRAWN BY: PR
CHECKED BY: PM

jenkinsgavin
DESIGN & DEVELOPMENT INC.
130 Grant Avenue, Suite 101
Santa Fe, New Mexico 87501

SHEET
A-1

City of Santa Fe, New Mexico

memo

DATE: November 13, 2012

TO: Historic Districts Review Board Members

FROM: John Murphey, Senior Planner, Historic Preservation Division
David Rasch, Supervisor Planner, Historic Preservation Division

---

CASE # H-12-088

Address: 719 Gildersleeve Street
Historic Status: Contributing
Historic District: Don Gaspar Area

REFERENCE ATTACHMENTS (sequentially):

CITY SUBMITTALS	APPLICANT SUBMITTALS
_x_ Case Synopsis	_x_ Proposal Letter
____ District Standards and Yard Wall and Fence Standards	____ Vicinity Map
_x_ Historic Inventory Form	_x_ Site Plan/Floor Plan
_x_ Zoning Review Sheet	_x_ Elevations
____ Other:	_x_ Photographs
	_x_ Other: Exception responses

STAFF RECOMMENDATION:

Staff recommends approval of this application, as it complies with Section 14-5.2 (D)(9), General Design Standards (Height, Pitch, Scale and Massing), and (H), Don Gaspar Area Historic District. Staff recommends the applicant has met the exception to remove historic material to provide additional off-street parking for a future second dwelling unit on under Section 14-5.2 (D)(1)(a).

EXHIBIT C

BACKGROUND AND SUMMARY:

Facing west and on a slight rise above the street, 719 Gildersleeve is a 1,800 sq. ft. rectangular plan, single-story dwelling with a long, linear post-1948 studio addition made to the original garage at the rear. (The current studio includes a bathroom but not a kitchen). The house's symmetrical pattern of windows is interrupted across the front façade by a cube-like inset porch. The dwelling's massing and rounded edge parapets place it in the Spanish-Pueblo Revival category. This motif additionally informs a low retaining wall trading the edge of the sidewalk. Constructed in c.1914, the house is contributing to the Don Gaspar Area Historic District.

Project

The applicant proposes to construct a new driveway along the north side of the house, thereby, replacing the existing driveway at the south end of the property.

The project will involve removing approximately 12' of the above-mentioned retaining wall at the north end and filling in the current driveway to the south with a wall of similar height and design. Essentially swapping one driveway cut for the other.

Work will include removing two additional structures along the north elevation of the house. These include a 69.5"-high recent coyote fence and an 88"-high stucco-clad stone wall farther to the east. Beyond, the driveway, paved with "Santa Fe Brown" gravel, will terminate at the east property wall with four parking spaces. In the front, low retaining walls will follow the 2% grade of the driveway.

Exception

Because the origins of the two walls are unknown, and their design and construction appear to be historic, the applicant has requested an exception to remove historic material under Section 14-5.2 (D)(1)(a).

Applicant responses:

(i) *Do not damage the character of the streetscape;*

Removing a portion of the front yardwall to allow for a driveway will not damage the character of the streetscape, as the wall will be subsequently replaced on the opposite side of the property where it now breaks for the existing driveway. The result will be a mirror image that will preserve the character of the historic façade. The additional back yard wall to be removed is minimally visible from the street and will not affect the streetscape.

Staff agrees with response.

(ii) *Prevent a hardship to the applicant or an injury to the public welfare;*

The property now provides for only one off-street parking space for two potential dwelling units. This creates a hardship for the residents, as on-street parking is at a premium on this densely populated street. In order for the applicant to obtain a permit to convert the existing studio to a fully functional dwelling unit, the property must be

brought into compliance with Santa Fe City Code, which calls for two off-street parking spaces for each dwelling unit. Public welfare is served by adding off-street parking to minimize on-street parking in this dense neighborhood.

Staff agrees with response. The current driveway is truncated by a coyote fence, reducing it to one paved parking space. The fence could be removed to provide an additional 27 linear feet of parking space to meet code for the existing dwelling unit. This configuration, however, would not provide sufficient off-street parking for a potential second unit.

(iii) *Strengthen the unique heterogeneous character of the city by providing a full range of design options to ensure that residents can continue to reside within the historic districts;*

Providing the opportunity to move the driveway in order to access off-street parking ensures that residents of the property will be able to comfortably and safely park within their historic district. Maintaining a desirable residential neighborhood entails ensuring adequate off-street parking.

Staff neither agrees nor disagrees with this response.

(iv) *Are due to special conditions and circumstances which are peculiar to the land or structure involved and which are not applicable to other lands or structures in the related streetscape;*

Several other residences in the related streetscape already have more than one off-street parking space in their side or back yards. The subject property has only one off-street parking space for two potential dwelling units.

Staff neither agrees nor disagrees with this response.

(v) *Are due to special conditions and circumstances which are not a result of the actions of the applicant;*

The property is legal nonconforming in that it has only one off-street parking space when four will be required for the creation of an additional dwelling unit as described above. This is an existing condition that is not a result of the actions of the applicant.

Staff neither agrees nor disagrees with this response. The current coyote fence could be removed to re-establish the original driveway to the former garage and provide an additional parking space.

(vi) *Provide the least negative impact with respect to the purpose of this section as set forth in Subsection 14-5.2 (A)(1).*

Replacing one driveway with another, and replacing the wall to close the existing driveway, preserves the historical façade of the building and does not negatively impact the streetscape. The wall will be replaced in its current historic Pueblo Revival style.

Staff agrees with this response. If the purpose of the request is to provide additional spaces for a future second dwelling unit, this proposal provides the least negative impact, as per the goals set forth in Section 14-5.2 (A)(1).

NEW MEXICO HISTORIC BUILDING INVENTORY FORM

H2171

building threatened? yes	surveyed date 7-82 by E.T.	county Santa Fe	ID no. 051600
field map Don Gaspar Neighborhood	number 252	UTM reference zone 12 (13) easting	northing

location description: 719 Hildersleeve

city/town: Santa Fe

land grant/reservation:

building name:

legal description: tnsp ___ N S range ___ E W sec ___ ¼ ¼

film roll by E.T. no. 9 | negative nos. 10 | loc. of neg. City of Santa Fe



building site plan



date of construction: 1930 estimate 1912-23 actual

source: City Directory Sanborn

use
present: (residential)
other:
historic: (residential)
other:

condition: ___excellent X good ___fair ___deteriorating

degree of remodeling: X minor ___moderate ___major
describe:

style: Pueblo Revival

foundation material: N/V

wall material/surface: stucco / concrete block

architectural features:
inset porch
Parapet
Wd d/B 1-1
walls along steps

surroundings: MDS

relationship to surroundings: X similar ___not similar

district potential: X yes ___no

significance: ___significant X contributing ___supporting ___intrusive

comments:
9' stucco wall

1926 cd - Martin CP; Harkins PM
1928 cd - vacant
PM 1930 - [illegible]

associated buildings? ___yes
what type?

if inventoried, list ID nos.

see back? ___yes

41


E. BERGER
E. BUENA VISTA AV.
E. HOUGHTON
E. CORONADO RD.
GILDERSLEEVE
20
97
99
125
1948 Sanborn

Preliminary Zoning Review Worksheet

City of Santa Fe Land Use Department

To Be Completed By Applicant:

Date Submitted: 10·16·12	Site Address: 719 Gildersleeve
Property Owner of Record: Estate of Jennifer A. Thompson	Proposed Construction Description: Relocate driveway- Modify yardwalls to accommodate driveway.
Applicant/Agent Name: Jenkins Gavin	
Contact Person Phone Number: ( )820 7444	TOTAL ROOF AREA:

NOTE: Preliminary zoning reviews are provided as a courtesy and are intended to address general zoning compliance issues. Applicants are advised to do an independent search of applicable zoning ordinances and to research documents related to property history which may affect permitting. Additionally, applicants are advised to contact appropriate City Staff with questions related to Terrain management, building, fire, water budget, Sangre de Cristo, wastewater, and other development codes which may affect permitting.

BASED ON INFORMATION PRESENTED ON APPLICATION DATE, THIS REVIEW DOES NOT GRANT ZONING APPROVAL AT THE TIME OF BUILDING PERMIT. FINAL ZONING APPROVAL WILL BE GRANTED ONCE ALL COMPLIANCE WITH ZONING HAS BEEN MET.

Hillary Welles for Jenkins Gavin / by F — 11/01/12

□OWNER □APPLICANT ☒AGENT — DATE

Zoning District: R-21

Overlay: ☒ Historic Don Gaspar
- □ Arts and Crafts
- □ Escarpment*
- □ Flood Zone*
- □ Cerrillos Road Corridor
- □ Other:

Zoning Submittal Requirements:
- ☒ Legal Lot of Record □ Development Plan □ Building Plans
- ☒ Existing Site Plan ☒ Proposed Site Plan ☒ Elevations

Supplemental Zoning Submittals:
- □ Zero Lot Line Affidavit NA

Access and Visibility: □ Arterial or Collector*
- ☒ Visibility Triangle Required see below

Use of Structure: ☒ Residential
- □ Commercial Type of Use:

Terrain: □ 30% slopes NA

Lot Coverage: 26 % No change
□Open Space Required:

Setbacks: NA - No change
Proposed Front: ____ Minimum: ____
2nd Front? ____
Proposed Rear: ____ Minimum: ____
Proposed Sides: L ____ R ____ Minimum: ____

Height: Proposed ____ NA
Maximum Height: ____ or
□ Regulated by Historic Districts Ordinance
□ Regulated by Escarpment District

Parking Spaces:
Proposed 4 Accessible**: —
Minimum: 2

Bicycle Parking:**
Proposed: ____ Minimum: ____

* Requires an additional review conducted by Technical Review or Traffic Engineering Division to ensure compliance. ** Commercial Requirement

To Be Completed By City Staff:

Additional Agency Review if Applicable:

□ Escarpment Approval by ____ Date: __/__/__ > NA

□ Flood Plain Approval by ____ Date: __/__/__

☒ Traffic Engineering Approval by ____ Date: 10/10/12 original approval attached.

Notes: ____

Zoning Approval:

☒ **Preliminary Approval** □ **with conditions** □ **Rejected**

Comments/Conditions: ____

REVIEWER: ____ **DATE:** 11/01/12

Note: If approved, please stamp and initial each page of plan set.

Rev. 4-12

City of Santa Fe

Agenda

CITY CLERK'S OFFICE
DATE 11/7/12 TIME 8:45
SERVED BY
RECEIVED BY

HISTORIC DISTRICTS REVIEW BOARD FIELD TRIP

TUESDAY, November 13, 2012 at 12:00 NOON

HISTORIC PRESERVATION DIVISION, 2nd FLOOR CITY HALL

HISTORIC DISTRICTS REVIEW BOARD HEARING

TUESDAY, November 13, 2012 at 5:30 P.M.

SANTA FE COMMUNITY CONVENTION CENTER

LAMY ROOM

AMENDED

A. **CALL TO ORDER**

B. **ROLL CALL**

C. **APPROVAL OF AGENDA**

D. **APPROVAL OF MINUTES: October 23, 2012**

E. **COMMUNICATIONS**

F. **FINDINGS OF FACT & CONCLUSIONS OF LAW**

Case #H-05-179	257, 259, 263, & 269 Las Colinas Drive formerly 200 Gonzales Road		
Case #H-10-012	Santa Fe River Parkway	Case #H-12-082	923 Acequia Madre
Case #H-09-012	526 Galisteo Street	Case #H-12-083	616 East Alameda, D
Case #H-12-079	556 E. Coronado Road	Case #H-12-078	545 Canyon Road
Case #H-12-080	1677 Cerro Gordo Road #9	Case #H-12-085	717 Dunlap Street

G. **BUSINESS FROM THE FLOOR**

H. **ACTION ITEMS**

1. Case #H-11-051. 250 E. Alameda. Downtown & Eastside Historic District. Duty & Germanas Architects, agent for El Castillo Retirement Residences, owners, proposes to amend a previous approval to construct a 5,370 sq. ft. addition on a non-contributing property and proposes additional remodeling. (REHEARING). (David Rasch).

2. Case #H-11-055. 1047 A Camino San Acacio. Downtown & Eastside Historic District. Richard Martinez, agent for Christopher Boghm, owner, proposes to demolish a 313 sq. ft. carport and construct 1, 372 sq. ft. of roofed additions to match existing height, 105 sq. ft. of portals, and a yardwall with pedestrian gate on a non-contributing property. (David Rasch).

3. Case #H-11-117. 621 Old Santa Fe Trail. Downtown & Eastside Historic District. Wayne Lloyd, agent for David Lamb, owner, proposes to amend a previous approval to remodel a non-contributing commercial building. (David Rasch).

4. Case #H-12-084. 447 Cerrillos Road, #6. Downtown & Eastside Historic District. Wyndham Carlisle, agent for Willow Howard, owner, proposes to alter window and door openings, stucco, and construct a 6'-high coyote fence at this contributing residence. (John Murphey).

EXHIBIT
tabbies
D

SS002 pmb-11/02

5. Case #H-12-086. 523 Calle Corvo. Downtown & Eastside Historic District. Edwin D. & Carolyn C. Jenkins, agent/owners, propose to remodel this non-contributing property, including the alteration of an existing yardwall with pedestrian gates and lowered height at the driveway. (David Rasch).

6. Case #H-12-087. 1299 Upper Canyon Road. Downtown & Eastside Historic District. Kenneth Francis & Sandra Donner, agents for Grant Hayunga, owner, propose to remove an existing addition, construct a 561 sq. ft. addition, replace windows, raise of a portion of the roof 9'-6" to 12'-0 where the maximum allowable height is 15'-0, and re-stucco this non-contributing house. (John Murphey).

7. Case #H-12-089. 613 W. San Francisco Street. Westside-Guadalupe Historic District. Martinez Architecture Studio, agent for Paul Petty, owner, requests an historic status review of this significant residential structure. (David Rasch).

8. Case #H-12-088. 719 Gildersleeve Street. Don Gaspar Area Historic District. Jenkins Gavin, agent for Estate of Jennifer A. Thompson, owner, proposes to remove a portion of an existing street retaining wall, a coyote fence and a separate yard wall to create a new driveway at this contributing residence. An exception is requested to remove historic material (Section 14-5.2 (D)(1)(a)). (John Murphey).

I. MATTERS FROM THE BOARD

J. ADJOURNMENT

Cases on this agenda may be postponed to a later date by the Historic Districts Review Board at the noticed meeting. Please contact the Historic Preservation Division at 955-6605 for more information regarding cases on this agenda.

Persons with disabilities in need of accommodation or an interpreter for the hearing impaired should contact the City Clerk's office at 955-6520 at least five (5) working days prior to the hearing date. Persons who wish to attend the Historic Districts Review Board Field Trip must notify the Historic Preservation Division by 9:00 am on the date of the Field Trip.

City of Santa Fe

Agenda

CITY CLERK'S OFFICE
DATE 10-25-12 TIME 11:00 am
SERVED BY Camille Lucero
RECEIVED BY F. Duty

HISTORIC DISTRICTS REVIEW BOARD FIELD TRIP

TUESDAY, November 13, 2012 at 12:00 NOON

HISTORIC PRESERVATION DIVISION, 2nd FLOOR CITY HALL

HISTORIC DISTRICTS REVIEW BOARD HEARING

TUESDAY, November 13, 2012 at 5:30 P.M.

SANTA FE COMMUNITY CONVENTION CENTER

LAMY ROOM

A. CALL TO ORDER

B. ROLL CALL

C. APPROVAL OF AGENDA

D. APPROVAL OF MINUTES: October 23, 2012

E. COMMUNICATIONS

F. FINDINGS OF FACT & CONCLUSIONS OF LAW

Case #H-05-179	257, 259, 263, & 269 Las Colinas Drive formerly 200 Gonzales Road		
Case #H-10-012	Santa Fe River Parkway	Case #H-12-082	923 Acequia Madre
Case #H-09-012	526 Galisteo Street	Case #H-12-083	616 East Alameda, D
Case #H-12-079	556 E. Coronado Road	Case #H-12-078	545 Canyon Road
Case #H-12-080	1677 Cerro Gordo Road #9	Case #H-12-085	717 Dunlap Street

G. BUSINESS FROM THE FLOOR

H. ACTION ITEMS

1. Case #H-11-051. 250 E. Alameda. Downtown & Eastside Historic District. Duty & Germanas Architects, agent for El Castillo Retirement Residences owners, proposes to amend a previous approval to construct a 5,370 sq. ft. addition on a non-contributing property and proposes additional remodeling. (REHEARING). (David Rasch).

2. Case #H-11-055. 1047 A Camino San Acacio. Downtown & Eastside Historic District. Richard Martinez, agent for Christopher Boghm, owner, proposes to demolish a 313 sq. ft. carport and construct 1, 372 sq. ft. of roofed additions to match existing height, 105 sq. ft. of portals, and a yardwall with pedestrian gate on a non-contributing property. (David Rasch).

3. Case #H-11-089. 420 Arroyo Tenorio. Downtown & Eastside Historic District. Tim Curry/Design Solutions, agent for Andrew Beagle and Doug Key, owners, proposes to amend a previous approval to construct two gates by constructing a trellis to 11'8" high and partially infilling the yardwall opening. (David Rasch).

4. Case #H-11-117. 621 Old Santa Fe Trail. Downtown & Eastside Historic District. Wayne Lloyd, agent for David Lamb, owner, proposes to amend a previous approval to remodel a non-contributing commercial building. (David Rasch).

5. Case #H-12-077. 1148 Camino San Acacio. Downtown & Eastside Historic District. Greg and Kay Crouch, owners, propose to remove approximately 25' of stone retaining street wall and lower another section of the same wall to create two parking spaces in front of this noncontributing house. An exception is requested to remove historic material (Section 14-5.2 (D)(1)(a)). (John Murphey).

6. Case #H-12-084. 447 Cerrillos Road, #6. Downtown & Eastside Historic District. Wyndham Carlisle, agent for Willow Howard, owner, proposes to alter window and door openings, stucco, and construct a 6'-high coyote fence at this contributing residence. (John Murphey).

7. Case #H-11-086. 523 Calle Corvo. Downtown & Eastside Historic District. Edwin D. & Carolyn C. Jenkins, agent/owners, proposes to remodel this non-contributing property including the alteration of an existing yardwall with pedestrian gates and lowered height at the driveway. (David Rasch).

8. Case #H-12-087. 1299 Canyon Road. Downtown & Eastside Historic District. Kenneth Francis & Sandra Donner, agents for Grant Hayunga, owner, proposes to remove an existing addition, construct a 561 sq. ft. addition, replace windows, raise of a portion of the roof 9'-6" to 12'-0 where the maximum allowable height is 15'-0, and re-stucco this non-contributing house. (John Murphey).

9. Case #H-12-089. 613 W. San Francisco Street. Westside-Guadalupe Historic District. Martinez Architecture Studio, agent for Paul Petty, owner, requests an historic status review of this significant residential structure. (David Rasch).

10. Case #H-12-088. 719 Gildersleeve Street. Don Gaspar Area Historic District. Jenkins Gavin, agent for Estate of Jennifer A. Thompson, owner, proposes to remove a portion of an existing street wall, a coyote fence and a separate yard wall to create a new driveway at this contributing residence. An exception is requested to remove historic material (Section 14-5.2 (D)(1)(a)). (John Murphey).

I. MATTERS FROM THE BOARD

J. ADJOURNMENT

Cases on this agenda may be postponed to a later date by the Historic Districts Review Board at the noticed meeting. Please contact the Historic Preservation Division at 955-6605 for more information regarding cases on this agenda.

Persons with disabilities in need of accommodation or an interpreter for the hearing impaired should contact the City Clerk's office at 955-6520 at least five (5) working days prior to the hearing date. Persons who wish to attend the Historic Districts Review Board Field Trip must notify the Historic Preservation Division by 9:00 am on the date of the Field Trip.

Mr. Katz was torn on this one. He also believed there was a real house under all that and would like to see it come out. The south as primary would make that much harder.

Vice Chair Rios disagreed. Even as a significant structure, an applicant could ask for exceptions. It might be more difficult but they also could prove certain things.

Mr. Rasch pointed out that the applicant could come forward to show improvements on the original dimensions that wouldn't need exceptions.

The motion passed by unanimous voice vote.

8. **Case #H-12-088. 719 Gildersleeve Street.** Don Gaspar Area Historic District. Jenkins Gavin, agent for Estate of Jennifer A. Thompson, owner, proposes to remove a portion of an existing street retaining wall, a coyote fence and a separate yard wall to create a new driveway at this contributing residence. An exception is requested to remove historic material (Section 14-5.2 (D)(1)(a)). (John Murphey)

Mr. Murphey presented the staff report for this case as follows:

BACKGROUND AND SUMMARY:

Facing west and on a slight rise above the street, 719 Gildersleeve is a 1,800 sq. ft., rectangular plan, single-story dwelling, with a long, linear post-1948 studio addition made to the original garage at the rear. (The current studio includes a bathroom but not a kitchen). Its symmetrical pattern is interrupted across the front façade by a deep inset porch at the southwest corner. The house's massing and rounded edge parapets place it in the Spanish-Pueblo Revival category. This motif additionally informs a low retaining wall tracing the edge of the sidewalk. Constructed in c.1914, it is contributing to the Don Gaspar Area Historic District.

Project

The applicant proposes to construct a new driveway along the north side of the house, thereby, replacing the existing driveway at the south end of the property.

The project will remove approximately 12' of the original retaining wall at the north, and blocking the current driveway with a wall of similar height and design.

Driveway preparation will include removing two structures along the north side of the house: a non-historic 69.5"-high coyote fence and an 88"-high stucco-clad stone wall of unknown origin.

Beyond these removed structures, the driveway will terminate at the east property wall with four parking spaces. In front, low retaining walls will follow the 2% slope of the grade. It will be paved with "Santa Fé Brown" gravel.

Exception

Because the origins of the two walls are unknown, and their design and construction appear to be historic, the applicant has requested an exception to remove historic material under Section 14-5.2 (D)(1)(a). Applicant and staff tried to find out but couldn't.

Applicant responses:

(I) Do not damage the character of the streetscape;

Removing a portion of the front yardwall to allow for a driveway will not damage the character of the streetscape, as the wall will be subsequently replaced on the opposite side of the property where it now breaks for the existing driveway. The result will be a mirror image that will preserve the character of the historic façade. The additional back yard wall to be removed is minimally visible from the street and will not affect the streetscape.

Staff agrees with response.

(ii) Prevent a hardship to the applicant or an injury to the public welfare;

The property now provides for only one off-street parking space for two potential dwelling units. This creates a hardship for the residents, as on-street parking is at a premium on this densely populated street. In order for the applicant to obtain a permit to convert the existing studio to a fully functional dwelling unit, the property must be brought into compliance with Santa Fé City Code, which calls for two off-street parking spaces for each dwelling unit. Public welfare is served by adding off-street parking to minimize on-street parking in this dense neighborhood.

Staff agrees with response. The current driveway is truncated by a coyote fence, reducing it to one paved parking space. The fence could be removed to provide an additional 27 linear feet of parking space to meet code for the existing dwelling unit. This configuration, however, would not provide sufficient off-street parking for a potential second unit.

(iii) Strengthen the unique heterogeneous character of the city by providing a full range of design options to ensure that residents can continue to reside within the historic districts;

Providing the opportunity to move the driveway in order to access off-street parking ensures that residents of the property will be able to comfortably and safely park within their historic district. Maintaining a desirable residential neighborhood entails ensuring adequate off-street parking.

Staff neither agrees nor disagrees with this response.

(iv) Are due to special conditions and circumstances which are peculiar to the land or structure involved and

which are not applicable to other lands or structures in the related streetscape;

Several other residences in the related streetscape already have more than one off-street parking space in their side or back yards. The subject property has only one off-street parking space for two potential dwelling units.

Staff neither agrees nor disagrees with this response.

(v) *Are due to special conditions and circumstances which are not a result of the actions of the applicant;*

The property is legal nonconforming in that it has only one off-street parking space when four will be required for the creation of an additional dwelling unit as described above. This is an existing condition that is not a result of the actions of the applicant.

Staff neither agrees nor disagrees with this response. The current coyote fence could be removed to re-establish the original driveway to the former garage and provide an additional parking space.

(vi) *Provide the least negative impact with respect to the purpose of this section as set forth in Subsection 14-5.2 (A)(1).*

Replacing one driveway with another, and replacing the wall to close the existing driveway, preserves the historical façade of the building and does not negatively impact the streetscape. The wall will be replaced in its current historic Pueblo Revival style.

Staff agrees with this response. As per the goals set forth in Section 14-5.2 (A)(1), this proposal provides the least negative impact to establish additional off-site parking.

STAFF RECOMMENDATION:

Staff recommends approval of this application, as it complies with Section 14-5.2 (D)(9), General Design Standards (Height, Pitch, Scale and Massing), and (H), Don Gaspar Area Historic District. Staff recommends the applicant has met the exception to remove historic material to provide additional off-street parking for a future second dwelling unit on the property, under Section 14-5.2 (D)(1)(a).

Vice Chair Rios asked if the existing driveway would remain.

Mr. Murphey said no - it would be filled in.

Ms. Walker said this motif additionally informs the retaining wall.

Mr. Acton asked what they proposed to the north of the new driveway.

Mr. Murphey said parallel retaining walls that were following grade.

Mr. Acton asked if it was a fence along the neighbor's property.

Mr. Murphey asked him to ask the applicant.

Ms. Mather concluded that the higher fence would be removed but the older would remain.

Present and sworn was Ms. Jennifer Jenkins, 130 Grant Avenue, who said the addition to the back was a little studio and had been used as a rented dwelling by previous owners but it had no functional kitchen. So the intent was to make it function as dwelling unit and that meant adequate parking was needed at 2 per dwelling unit. So this would provide for a nice dwelling. They would abandon the existing driveway for one on the north and replicate the wall as a mirror image.

Their hope was that once the work was done it would be sensitive to the character of the house. They would bring it up to code and convert the studio to a dwelling unit. There was not adequate off-street parking there on that street.

Vice Chair Rios asked for the height of the existing wall.

Ms. Jenkins said it was 2 feet.

Vice Chair Rios what its composition was.

Ms. Jenkins said they didn't know but they would replace aesthetically in kind if they couldn't replace the composition in kind.

Mr. Katz thought on the west elevation it would be better to have a gate like on the other side. He asked if that was a possibility.

Ms. Jenkins asked if he meant a vehicle gate to mirror the coyote fence.

Vice Chair Rios pointed out that neighborhood didn't use a lot of coyote in the past.

Ms. Jenkins said the coyote was really not visible from the street so it would have minimal impact on the streetscape.

Vice Chair Rios said that wall was very low.

Ms. Jenkins agreed. The other one was set back as far as the porch.

Mr. Acton asked if as a person came up the driveway there would be a stucco retaining wall on the left side.

Ms. Jenkins said it would be on both sides and as they approach the house they would use the house as retaining there.

Mr. Acton asked if it was not coyote on the north.

Ms. Jenkins agreed. If that fence was on this property they could remove it but wanted to make sure first.

Mr. Acton felt that was a stellar example of a well maintained woven wire fence.

Ms. Jenkins said the wall wouldn't function as a yard wall - just retaining.

Vice Chair Rios asked if they were disturbing the grade when opening that driveway.

Ms. Jenkins agreed. They were bringing it up to its natural grade and they had to hold up the sides on either side. The driveway would be brown gravel.

Ms. Mather asked if the tree would be retained.

Ms. Jenkins thought so.

Ms. Walker said if they had a gate it should be fenestrated.

PUBLIC COMMENT

Present and sworn was Ms. Marian Tosan, 714 Gildersleeve, who asked if Jenkins/Gavin was representing the estate of Jennifer A. Thompson as stated on the agenda.

Ms. Jenkins explained that when they submitted the application the property was under contract and has since closed so they represented the owner of record.

Ms. Tosan said she was not sure who they were representing because her statement was not the same as was on the agenda.

Vice Chair Rios thought Ms. Jenkins adequately explained who she was representing.

Ms. Tosan said this was a conflict for her because she loved that wall. The existing driveway was similar to hers. The idea of building it on the north side prompted her to ask why. She thought it was in direct conflict with preserving property. She didn't see how it contributed to historic quality of this property. The back was fairly large so she asked if it would be further subdivided and if that would improve this neighborhood. She didn't see how it could. She was very proud of having the Board give her permission to restore her home but it really disturbed her to think the owners would bastardize this property.

Vice Chair Rios asked if Ms. Jenkins would like to respond.

Ms. Jenkins agreed that the existing driveway could have two cars there but the intent in rehabilitation of the property was primarily interior work and part of it was to make that studio function as a dwelling unit and that couldn't happen unless they complied with the city code on parking. They received their driveway permit and it had met visibility standards and the City required that they close the existing driveway so they would reclaim that. Their plan would provide side by side parking in the back so it was not visible and supported the rehabilitation as it moved forward.

Present and sworn was Ms. Diane Taliaferro, 716 Gildersleeve directly across from this property. She had lived there six years and loved it and her neighbors. She had put a lot of time and energy into her house and worked with the Board on some of it. She was struggling a little to understand why they needed to put in another driveway. This particular part of Gildersleeve was one way and they have one driveway in each to accommodate 2-3 people. She was disappointed that they were talking about turning this into two houses. There were people who lived there full time and also rental units.

This house today was a house that had a garage that was converted at some time as a work space. She didn't know that it was ever rented out so some work was needed. The current driveway had room for two spaces. And the ordinance did require two per dwelling and there were rentals on the street that didn't have two per residence.

She had concerns over placement of the new driveway in that location. It was a steep grade and the wall was historic and had another stone wall in back leading into the back yard. It would require removal of two large trees. A lot of trees there in the neighborhood had already been cut down. Trees helped with watering issues and providing shade for dwellings need less air conditioning.

She and Ms. Tosan were neighbors and had driveways side by side. You have to be careful when pulling out because cars were on the street and lots of pedestrians including kids going to school. The back yard was big and you could probably park ten cars back there. There was not a lot of clearance there on the north side. Gildersleeve had also become the way to get kids to school in the mornings and the route the city uses to work on the Old Santa Fé Trail.

Another problem was that this was where they had to put their garbage and recycle containers for pickup. Two more of them would have to be put on the east side of the street so it would cram a lot of them in together and take away from parking on the street.

She said she was not clear on the ordinance if they all have to have two parking spaces each. She didn't see where it would be. She added that the next door neighbor was unaware of this meeting and not informed of this change. It came up pretty quickly but she had to wait a couple of months before she could meet with the Board.

She said she really cared about the historic neighborhoods and was on Historic Preservation board in Montana and hoped the Board members had looked at this project. She felt she had worked hard to make her

home one she could be proud of.

There were no other speakers from the public regarding this case.

Ms. Mather thought the applicant really answered a lot of questions the neighbors brought up. The ordinance did require two spaces per dwelling. She had a concern as a board member that there seemed to be some tension about this application and hoped they could get together and be neighbors. That was most important in historic neighborhoods. She hoped the tension could be dissipated in the course of the evening.

Mr. Katz understood the concern of the neighbors about having more units here. But that was not really the Board's purview. He got concerned when the regular parties came here not for historic preservation but used for another purpose to prevent someone from developing their lot. The Board needed to focus on the design factors and the parking rule should be dealt with elsewhere.

Ms. Mather moved to approve Case #H-12-088 per staff's recommendation and citing that the applicant met the exceptions. Mr. Acton seconded the motion and it passed by majority (4-1) voice vote with Dr. Kantner opposed.

I. MATTERS FROM THE BOARD

There were no matters from the Board.

J. ADJOURNMENT

Ms. Walker moved to adjourn the meeting Mr. Acton seconded the motion and it passed by unanimous voice vote.

The meeting was adjourned at 8:05 p.m.

Approved by:

_____

Sharon Woods, Chair

Submitted by:

Carl Boaz, Stenographer

ITEM # 12-102

City of Santa Fe
Historic Districts Review Board
Findings of Fact and Conclusions of Law

Case # H-12-088
Address – 719 Gildersleeve Street
Owner/Applicant's Name – Brian Blount
Agent's Name – Jenkins Gavin

THIS MATTER came before the Historic Districts Review Board (Board) for hearing on November 13, 2012, upon the application (Application) of Jenkins Gavin, agent for Brian Blount, owner.

Facing west and on a slight rise above the street, 719 Gildersleeve is a 1,800 sq. ft., rectangular plan, single-story dwelling, with a long, linear post-1948 studio addition made to the original garage at the rear. (The current studio includes a bathroom but not a kitchen). Its symmetrical pattern is interrupted across the front façade by a deep inset porch at the southwest corner. The house's massing and rounded edge parapets place it in the Spanish-Pueblo Revival category. This motif additionally informs a low retaining wall tracing the edge of the sidewalk. Constructed in c.1914, it is contributing to the Don Gaspar Area Historic District.

The applicant requested a remodeling project (Project) to remove a portion of an existing street retaining wall, a coyote fence and a separate yard wall to create a new driveway at this contributing residence. An exception was requested to remove historic material (Section 14-5.2 (D)(1)(a)).

After conducting public hearings and having heard from the Applicant and all interested persons, the Board hereby FINDS, as follows:

FINDINGS OF FACT

1. Board heard testimony from Board staff, Applicant and members of the public.
2. Zoning staff has determined the Application meets underlying zoning standards.
3. Board staff presented the case.
4. Board staff recommended approval of the application, as it complied with Section 14-5.2 (D)(9), General Design Standards (Height, Pitch, Scale and Massing), and (H), Don Gaspar Area Historic District.
5. Board staff recommended the applicant had met the exception to remove historic material under Section 14-5.2 (D)(1)(a).
6. Members of the public were sworn in and commented on the project.
7. Board responded to public comments.
8. Board concurred with staff recommendation and found the proposed project complied with applicable design standards.
9. Board additionally concurred that the applicant had met the exception to remove historic material.

EXHIBIT tabbies E

10. Property is located in the Don Gaspar Area Historic District and is subject to the requirements of the following sections of the Santa Fe Land Development Code: Section 14-5.2 (H) Don Gaspar Area Historic District.
11. Under Sections 14-5.2(A)(1)(b) and (c), 14-2.7(A)(1), and 14-2.7(A)(3), the Board has the authority to review, approve, with or without conditions, or deny, all or some of the Applicant's proposed design to assure overall compliance with applicable design standards.
12. Under Section 14-5.2(C)(3)(b), the Board has the authority to approve an application for alteration or new construction on the condition that changes relating to exterior appearance recommended by the Board be made in the proposed work, and no permit is to issue until new exhibits, satisfactory to the Board, have been submitted.

CONCLUSIONS OF LAW

Under the circumstances and given the evidence and testimony submitted during the hearing, the Board acted upon the Application as follows:

The Board concludes the project complies with Section 14-5.2 (D)(9), General Design Standards (Height, Pitch, Scale and Massing), and (H), the Don Gaspar Area Historic District. The Board additionally concludes the applicant has met the exception to remove historic material under Section 14-5.2 (D)(1)(a).

IT IS SO ORDERED ON THIS 11th DAY OF DECEMEBER 2012 THE HISTORIC DISTRICTS REVIEW BOARD OF THE CITY OF SANTA FE.

Sharon Woods
Chair

Date: 12/11/12

FILED

Yolanda Y. Vigil
City Clerk

Date: 12.20.12

APPROVED AS TO FORM

Kelley Brennan
Assistant City Attorney

Date: 12/11/12

BAER, TAMARA

From: BAER, TAMARA
Sent: Tuesday, October 30, 2012 12:06 PM
To: MONTOYA, ROBERT B.
Cc: ROMERO, JOHN J
Subject: RE: 719 Gildersleeve

Thank you so much for helping to save a tree!

Tamara Baer, ASLA
Manager, Current Planning Division
Land Use Department
City of Santa Fe
505-955-6580
tbaer@santafenm.gov

-----Original Message-----
From: MONTOYA, ROBERT B.
Sent: Tuesday, October 30, 2012 10:58 AM
To: 'Hillary Welles'; BAER, TAMARA
Cc: ROMERO, JOHN J
Subject: 719 Gildersleeve

Good Morning,

After a re-evaluation of the proposed driveway for 719 Gildersleeve the Traffic Engineering Division will not require the removal of the in front of the property to improve sight distance.

Because there is parking allowed on the street, this pushes the driving lane 8 feet back. When re-measured, the tree is outside of the sight triangle specified in City of Santa Fe Code 14.7.1(F):

"Measurements of fifteen (15) fee back from the nearest travel lane along the edge of the driveway and thirty (30) feet along the travel lane"

Please let me know if you have any questions.

Thank you,
Robert Montoya

711 Aldersleeve
NOTICE
OF PUBLIC HEARING
HISTORIC DISTRICTS REVIEW BOARD
Construction
NOT TO BE POSTED ON CITY RIGHT-OF-WAY OR UTILITY POLES
14-12-0828
POST 15 DAYS PRIOR TO MEETING
EXHIBIT
10/31/2012

Case #2012-152

LUD Use Only

Time Filed: 3 pm
Fee paid: $ 100
Receipt attached: ☑

(date stamp) RECEIVED
DEC 20 2012
LAND USE DEPARTMENT

VERIFIED APPEAL

PETITION

Two originals of this form must be filed. The Land Use Department Director or his/her designee will enter the date and time of receipt and initial both originals. See Section 14-3.17(D) SFCC 2001 for the procedure.

Appellant Information

Name: TALIAFERRO (Last) DIANE (First) M (M.I.)

Address: 716 GILDERSLEEVE STREET (Street Address) (Suite/Unit #)

SANTA FE, NM 87505 (City) (State) (ZIP Code)

Phone: (505) 983-8634 E-mail Address: LUKLA1@MSN.COM

Additional Appellant Names: SEE ATTACHED SHEET

Correspondence Directed to: ☒ Appellant ☐ Agent ☐ Both

Agent Authorization (if applicable)

I/We: _____

authorize _____ to act as my/our agent to execute this application.

Signed: _____ Date: _____

Signed: _____ Date: _____

Subject of Appeal

Project Name: _____

Applicant or Owner Name: BRIAN BLOUNT, JENKINS GAVIN, AGENT

Location of Subject Site: 719 GILDERSLEEVE STREET SANTA FE

Case Number: H-12-088 Permit Number (if applicable): _____

Final Action Appealed:

☐ Issuance of Building Permit ☐ Other Final Determination of LUD Director

Final Action of Board or Commission (specify): ☐ Planning Commission ☒ Board of Adjustment ☐ BCD-DRC ☒ HDRB

Basis of Standing (see Section 14-3.17(B) SFCC 2001):

APPELLANTS ARE PROPERTY OWNERS AND RESIDENTS OF GILDERSLEEVE ST.

Basis for Appeal: ☒ The facts were incorrectly determined ☐ Ordinances/laws were violated and/or misrepresented

Description of the final action appealed from, and date on which final action was taken:

REMOVAL OF RETAINING WALL AND YARD WALL TO CONSTRUCT DRIVEWAY. AND PARKING FOR ADDITIONAL UNITS

☐ Check here if you have attached a copy of the final action that is being appealed.

Description of Harm

Describe the harm that would result to you from the action appealed from (attach additional pages if necessary):

SEE ATTACHED

Explain the Basis for Appeal

Please detail the basis for Appeal here (be specific):

SE ATTACHED

Signature and Verification

I hereby certify that the documents submitted for review and consideration by the City of Santa Fe have been prepared to meet the minimum standards outlined in the Land Development Code, Chapter 14 SFCC 2001. Failure to meet these standards may result in the rejection or postponement of my application. I also certify that I have met with the City's Current Planning staff to verify that the attached proposal is in compliance with the City's zoning requirements.

Appellant Signature: Diane M Taliaferro Date: 12/18/2012

Agent Signature: N/A Date: N/A

State of New Mexico)
) ss.
County of Santa Fe)

I/We Diane M Taliaferro, being first duly sworn, depose and say: I/We have read the foregoing appeal petition and know the contents thereof and that the same are true to my/our own knowledge.

Petitioner/s:

Diane M Taliaferro — *Signature*

N/A — *Signature*

Diane Taliaferro — *Print Name*

N/A — *Print Name*

Subscribed and sworn to before me this 18th day of December, 2012.

OFFICIAL SEAL
Olivia Ortiz
NOTARY PUBLIC
STATE OF NEW MEXICO

Olivia Ortiz
NOTARY PUBLIC

My commission expires:

Diane Taliaferro
716 Gildersleeve St
Santa Fe, NM 87505
Appeal Case # H-12-088

Harm to the Neighborhood

Gildersleeve Street, as part of the Don Gaspar Historic District, is comprised of single family homes and several compounds, all accessed by a single driveway. The 700 block retains its original character; the appellants believe the proposed changes at 719 Gildersleeve will be detrimental to that character. We are also concerned that the current proposal is deliberately limited in scope to create access to further unspecified development on the property.

Basis for Appeal:

- Gavin-Stevens acting as agent of owner without knowledge of owner. According to Nov 13 telephone conversation with Geoffrey Thompson, as legal representative of the estate of Jennifer Thompson, the owner was not aware of the actions of buyer in reference to application to the HDRB until the date of closing, Nov 2. He stated that he signed a form at that time granting permission for this process because he was told that, though the property had closed, the deed would not be received for several days and the buyer wanted permission to bring his application to the board without waiting for the deed to be recorded. From the board's website, the schedule for the Nov 13 meeting required submission by Oct 17. Whether or not the contract for sale was contingent upon HRB approval, the owner of record had no knowledge of, nor did he approve Gavin-Stevens acting as 'agent' of the estate. On the agenda, Gavin Stevens was listed as agent for the estate of Jennifer Thompson. When this was pointed out to the members of the board, they seem to be unaware that the seller had not given permission for the firm to act as its agent.

- Determination of historic character of two property walls. The first wall in question is a retaining wall separating the front of the property from sidewalk on Gildersleeve Street, which was constructed in 1924. (Note the brass plaque embedded in the concrete in the middle of the street at the top of the 700 block) The adjacent property to the north has a similar retaining wall, topped by a historically significant wire fence. Mention was made in the Nov 13 meeting that the property line between these properties is the same wire. Because the walls follow the grade of the street, it may be argued that they are of the same time period. No sampling of the wall material was made. The use of aerial photos was reportedly inconclusive. A former resident of the block with many years' knowledge of the neighborhood has offered his testimony and has photographic evidence of a section of the retaining wall in question. The second wall is also historic at about 8 feet with a stone base as the foundation and stucco on top that

matches another wall dividing the properties. The driveway proposal will also compromise at least 2 mature trees that will have to be completely removed

- Prior Historic Board reviews of 719 Gildersleeve. The previous owner was not allowed to change the color of the stucco on the house or walls because it was deemed that the original white was indeed historic.

- No official survey, property corner determination or engineering report for the driveway. It is difficult at this time to determine whether the wire fence along the front and side of the house would be compromised, which in fact is historic as noted by the board in the meeting held on Nov. 13th.

- Original driveway location. There was no indication in the driveway proposal to rehab the original driveway or remove the concrete apron to the street. Due to the grade elevation of the current driveway this will be quite noticeable from the street despite the applicant's verbal assurances that an extension of the existing wall will be constructed across the driveway.

- View from the Street. To enhance the street view of the property it would be ideal if the board recommended removal of the coyote fence to conform to the historic character of the property. Also, removal of the driveway apron and repair of the sidewalk and curb adjacent to the street to conform to the 'one driveway per property' nature of the neighborhood. The representative from Jenkins Gavin informed us at the close of the Nov 13 meeting that there was no plan to remove any concrete from the existing drive. This was not part of the proposal; however it appears this could be an opportunity to work with the new owner to instill the goal of historic preservation.

- The original notification poster placed on the property gave the wrong meeting site and was not amended as were other posters on locations under review on Nov 13's meeting (612 Old Santa Fe Trail). This, and the extremely short notice gave the neighbors little time to prepare objections to the project. The applicant did not offer any information, verbally or in writing, (as was requested, because we were unavailable in person from Oct 29 through Nov 13). Gavin-Stevens' representative offered no information, nor did the architectural firm, which also preformed site visits prior to closing of the property on Nov 2.

Additional Appellants

Pamela Cersosimo
716 Gildersleeve

Marion Kassin
714 Gildersleeve

Martha Abernathy
718 Gildersleeve

Sloan Cunningham
907 Gildersleeve

We are totally opposed to the owners of 719 Gildersleeve Street adjacent to our property on 715 Gildersleeve Street putting a road and an additional house on the back of their property. This road would significantly change the historic character of the street. There is a reason that the drives are placed adjacent and there is a quiet space between each adjacent house. Adding a road on the north side of the 719 Gildersleeve house would eliminate this buffer quiet space and interfere significantly with the quiet enjoyment of our two homes at 715 Gildersleeve.

This is unacceptable.

We concur with the neighbors who oppose this variance.

We support every effort to stop the actions of the owners of 719 Gildersleeve Street.

Please let us know as soon as possible what the next steps are to make sure the road and additional house are not constructed.

Thank you.

Sincerely,

S. Barry Paisner and Charleen Touchette

Owners of 715 Gildersleeve Street

11/14/2012

I ATTEST THIS PICTURE WAS TAKEN OF ME WHEN I RESIDED AT 714 GILDERSLEEVE.

AS I REMEMBER THIS PICTURE WAS TAKEN OF ME SOMETIME IN THE MID-50's. MY FAMILY OWNED THE HOUSE @ 714 FROM 1943 UNTIL 2005. TO MY KNOWLEDGE, THE SAME WALL IN FRONT OF 714 GILDERSLEEVE WAS IN PLACE ALL OF THAT PERIOD.

Barbara R. Lockhart

11/14/12 witness: Marsha Abernathy

719

City of Santa Fe
Cashiers Office
Santa Fe, NM 87504
(505)955-4333

12/20/2012 2:51:26 PM
Your cashier was LORRAINE
B002501112354 T89

Development Review	
PAMELA CERSOSIMO	
11001.431470	$100.00
Total	$100.00
Check	$100.00
1645	
Change	$0.00

Thank you!

City of Santa Fe, New Mexico

200 Lincoln Avenue, P.O. Box 909, Santa Fe, N.M. 87504-0909
www.santafenm.gov

David Coss, *Mayor*

Councilors:
Rebecca Wurzburger, Mayor Pro Tem, Dist. 2
Patti J. Bushee, Dist. 1
Chris Calvert, Dist. 1
Peter N. Ives, Dist. 2
Carmichael A. Dominguez, Dist. 3
Christopher M. Rivera, Dist. 3
Bill Dimas, Dist. 4
Ronald S. Trujillo, Dist. 4

Project description: Proposes to remove a portion of an existing street retaining wall, a coyote fence and a separate yard wall to create a new driveway at this contributing residence. An exception is requested to remove historic material (Section 14-5.2(D)(1)(a)).

Project number: 12-120088
Case number: H-12-088
Project type: HDRB

PROJECT LOCATION (S): **719 Gildersleeve Street**

PROJECT NAMES:

OW – Jennifer A. Thompson
Santa Fe, NM 87505

1372 Santa Rosa Drive
505-670-5002

AP – Jenkins Gavin
Santa Fe, NM 87501

130 Grant Ave., #101
505-820-7444

BOARD ACTION

This is to certify that the Historic Districts Review Board (HDRB) at their hearing on November 13, 2012, acted on the above referenced case. The decision of the Board was to approve your application as submitted, and additionally determined that the applicant had met the one requested exception. For further information please call 955-6605.

Sincerely,

John Murphey
Senior Planner, Historic Preservation Division

NOTE: Applicant can use this action letter to apply for construction permit, but the permit shall not be released until the end of the appeal period which starts on the date of filing of the Findings and Conclusions in the City Clerks office (SFCC 14-3.17(D)). Your permit will be denied if any changes on plans that were not approved by the HDRB or if conditions of approval are not met. **Please attach copies of this letter to all sets when submitting for construction permit.**

719 Gildersleeve Street

Context View



Front Elevation

Southwest Front Elevation – Existing Driveway



Northwest Front Elevation – Location of Proposed Driveway

Stone/Stucco Wall
East Elevation (View From Backyard)
63"H x 11'W x 6"D



Stone/Stucco Wall
West Elevation (View from Front)
88"H x 11'W x 6"D

719 Gildersleeve Street
Additional Wall Photographs



Coyote Fence
69 ½"H x 11'W x 5"D
Photo #1



Coyote Fence
Photo #2

Preliminary Zoning Review Worksheet

City of Santa Fe Land Use Department

To Be Completed By Applicant:

Date Submitted: 10·16·12	**Site Address:** 719 Gildersleeve
Property Owner of Record: Estate of Jennifer A. Thompson	**Proposed Construction Description:** Relocate driveway- Modify yardwalls to accommodate driveway.
Applicant/Agent Name: Jenkins Gavin	
Contact Person Phone Number: ( )820 7444	**TOTAL ROOF AREA:**

NOTE: Preliminary zoning reviews are provided as a courtesy and are intended to address general zoning compliance issues. Applicants are advised to do an independent search of applicable zoning ordinances and to research documents related to property history which may affect permitting. Additionally, applicants are advised to contact appropriate City Staff with questions related to Terrain management, building, fire, water budget, Sangre de Cristo, wastewater, and other development codes which may affect permitting.

BASED ON INFORMATION PRESENTED ON APPLICATION DATE, THIS REVIEW DOES NOT GRANT ZONING APPROVAL AT THE TIME OF BUILDING PERMIT. FINAL ZONING APPROVAL WILL BE GRANTED ONCE ALL COMPLIANCE WITH ZONING HAS BEEN MET.

Hillary Welles for Jenkins Gavin / by F — 11 / 01 / 12

□OWNER □APPLICANT ☒AGENT — DATE

Zoning District: R-21

Overlay:
- ☒ Historic Don Gaspar
- □ Arts and Crafts
- □ Escarpment*
- □ Flood Zone*
- □ Cerrillos Road Corridor
- □ Other: _____

Zoning Submittal Requirements:
- ☒ Legal Lot of Record □ Development Plan □ Building Plans
- ☒ Existing Site Plan ☒ Proposed Site Plan ☒ Elevations

Supplemental Zoning Submittals:
- □ Zero Lot Line Affidavit NA

Access and Visibility: □ Arterial or Collector*
- ☒ Visibility Triangle Required see below

Use of Structure:
- ☒ Residential
- □ Commercial Type of Use: _____

Terrain: □ 30% slopes NA

* Requires an additional review conducted by Technical Review or Traffic Engineering Division to ensure compliance.

Lot Coverage : 26 % No change
□Open Space Required: _____

Setbacks: NA ~ No change
Proposed Front: _____ Minimum: _____
2nd Front? _____
Proposed Rear: _____ Minimum: _____
Proposed Sides: L___ R___ Minimum: ___

Height: Proposed _____ NA
Maximum Height: _____ or
□ Regulated by Historic Districts Ordinance
□ Regulated by Escarpment District

Parking Spaces:
Proposed 4 Accessible** —
Minimum: 2

Bicycle Parking:**
Proposed: _____ Minimum: _____

** Commercial Requirement

To Be Completed By City Staff:

Additional Agency Review if Applicable:

□ Escarpment Approval by _____ Date: ___/___/___ > NA

□ Flood Plain Approval by _____ Date: ___/___/___

☒ Traffic Engineering Approval by _____ Date: 10/10/12 original approval attached.

Notes: _____

Zoning Approval:

☒ **Preliminary Approval** □ **with conditions** □ **Rejected**

Comments/Conditions: _____

REVIEWER: _____ **DATE:** 11/01/12 **Rev. 4-12**

Note: If approved, please stamp and initial each page of plan set.

City of Santa Fe, New Mexico

memo

DATE: November 13, 2012

TO: Historic Districts Review Board Members

FROM: John Murphey, Senior Planner, Historic Preservation Division
David Rasch, Supervisor Planner, Historic Preservation Division

---

CASE # H-12-088

Address: 719 Gildersleeve Street
Historic Status: Contributing
Historic District: Don Gaspar Area

REFERENCE ATTACHMENTS (sequentially):

CITY SUBMITTALS	APPLICANT SUBMITTALS
_x_ Case Synopsis	_x_ Proposal Letter
___ District Standards and Yard Wall and Fence Standards	___ Vicinity Map
_x_ Historic Inventory Form	_x_ Site Plan/Floor Plan
_x_ Zoning Review Sheet	_x_ Elevations
___ Other:	_x_ Photographs
	_x_ Other: Exception responses

STAFF RECOMMENDATION:

Staff recommends approval of this application, as it complies with Section 14-5.2 (D)(9), General Design Standards (Height, Pitch, Scale and Massing), and (H), Don Gaspar Area Historic District. Staff recommends the applicant has met the exception to remove historic material to provide additional off-street parking for a future second dwelling unit on the property, under Section 14-5.2 (D)(1)(a).

BACKGROUND AND SUMMARY:

Facing west and on a slight rise above the street, 719 Gildersleeve is a 1,800 sq. ft. rectangular plan, single-story dwelling with a long, linear post-1948 studio addition made to the original garage at the rear. (The current studio includes a bathroom but not a kitchen). The house's symmetrical pattern of windows is interrupted across the front façade by a cube-like inset porch. The dwelling's massing and rounded edge parapets place it in the Spanish-Pueblo Revival category. This motif additionally informs a low retaining wall trading the edge of the sidewalk. Constructed in c.1914, the house is contributing to the Don Gaspar Area Historic District.

Project

The applicant proposes to construct a new driveway along the north side of the house, thereby, replacing the existing driveway at the south end of the property.

The project will involve removing approximately 12' of the above-mentioned retaining wall at the north end and filling in the current driveway to the south with a wall of similar height and design. Essentially swapping one driveway cut for the other.

Work will include removing two additional structures along the north elevation of the house. These include a 69.5"-high recent coyote fence and an 88"-high stucco-clad stone wall farther to the east. Beyond, the driveway, paved with "Santa Fe Brown" gravel, will terminate at the east property wall with four parking spaces. In the front, low retaining walls will follow the 2% grade of the driveway.

Exception

Because the origins of the two walls are unknown, and their design and construction appear to be historic, the applicant has requested an exception to remove historic material under Section 14-5.2 (D)(1)(a).

Applicant responses:

(i) Do not damage the character of the streetscape;

Removing a portion of the front yardwall to allow for a driveway will not damage the character of the streetscape, as the wall will be subsequently replaced on the opposite side of the property where it now breaks for the existing driveway. The result will be a mirror image that will preserve the character of the historic façade. The additional back yard wall to be removed is minimally visible from the street and will not affect the streetscape.

Staff agrees with response.

(ii) Prevent a hardship to the applicant or an injury to the public welfare;

The property now provides for only one off-street parking space for two potential dwelling units. This creates a hardship for the residents, as on-street parking is at a premium on this densely populated street. In order for the applicant to obtain a permit to convert the existing studio to a fully functional dwelling unit, the property must be

brought into compliance with Santa Fe City Code, which calls for two off-street parking spaces for each dwelling unit. Public welfare is served by adding off-street parking to minimize on-street parking in this dense neighborhood.

Staff agrees with response. The current driveway is truncated by a coyote fence, reducing it to one paved parking space. The fence could be removed to provide an additional 27 linear feet of parking space to meet code for the existing dwelling unit. This configuration, however, would not provide sufficient off-street parking for a potential second unit.

(iii) *Strengthen the unique heterogeneous character of the city by providing a full range of design options to ensure that residents can continue to reside within the historic districts;*

Providing the opportunity to move the driveway in order to access off-street parking ensures that residents of the property will be able to comfortably and safely park within their historic district. Maintaining a desirable residential neighborhood entails ensuring adequate off-street parking.

Staff neither agrees nor disagrees with this response.

(iv) *Are due to special conditions and circumstances which are peculiar to the land or structure involved and which are not applicable to other lands or structures in the related streetscape;*

Several other residences in the related streetscape already have more than one off-street parking space in their side or back yards. The subject property has only one off-street parking space for two potential dwelling units.

Staff neither agrees nor disagrees with this response.

(v) *Are due to special conditions and circumstances which are not a result of the actions of the applicant;*

The property is legal nonconforming in that it has only one off-street parking space when four will be required for the creation of an additional dwelling unit as described above. This is an existing condition that is not a result of the actions of the applicant.

Staff neither agrees nor disagrees with this response. The current coyote fence could be removed to re-establish the original driveway to the former garage and provide an additional parking space.

(vi) *Provide the least negative impact with respect to the purpose of this section as set forth in Subsection 14-5.2 (A)(1).*

Replacing one driveway with another, and replacing the wall to close the existing driveway, preserves the historical façade of the building and does not negatively impact the streetscape. The wall will be replaced in its current historic Pueblo Revival style.

Staff agrees with this response. If the purpose of the request is to provide additional spaces for a future second dwelling unit, this proposal provides the least negative impact, as per the goals set forth in Section 14-5.2 (A)(1).

RECEIVED
NOV - 6 2012

Prepared By and Return To:
Fidelity National Title of New Mexico
8500 Menaul Blvd NE, Ste. B150
Albuquerque, NM 87112

GF# FT000114716-NM01

COUNTY OF SANTA FE } WARRANTY DEED
STATE OF NEW MEXICO } ss PAGES: 1

I Hereby Certify That This Instrument Was Filed for
Record On The 5TH Day Of November, A.D., 2012 at 03:34:23 PM
And Was Duly Recorded as Instrument # 1686776
Of The Records Of Santa Fe County

Witness My Hand And Seal Of Office
Valerie Espinoza
Deputy - COMONTOYA County Clerk, Santa Fe, NM

COUNTY CLERK SANTA FE COUNTY NEW MEXICO

WARRANTY DEED
(Joint Tenants)

Geoffrey Graeme Thompson M.D. as Personal Representative of the Estate of Jennifer A. Thompson, deceased

for consideration paid, grant to

Brian Blount and Caryll Pearlman Blount , husband and wife

whose address is 1372 Santa Rosa Dive, Santa Fe, NM 87505

as joint tenants the following described real estate in County, New Mexico:

Lots 3 & 4, Block 10 of the Buena Vista Addition, as shown on "Plat of Survey for Michael L. Wineland...", filed on June 28, 1994 in Plat Book 278, page 028 as Document No. 868219, records of Santa Fe County, New Mexico.

with warranty covenants.

SUBJECT TO Patent, reservations, restrictions, and easements of record and to taxes for the year 2012, and subsequent years.

Witness my hand and seal this 2 day of November 2012

Geoffrey Graeme Thompson M.D., Personal Representative

STATE OF CA

COUNTY OF San Diego

This instrument was acknowledged before me Ramona Khyrolomoor, Notary Public
by Geoffrey Graeme Thompson

Ramona Khyrolomoor
Notary Public

My Commission Expires: Oct 31/2014

(SEAL)

OFFICIAL SEAL
RAMONA KHYROLOMOOR
NOTARY PUBLIC-CALIFORNIA
COMM. NO. 1906799
SAN DIEGO COUNTY
MY COMM. EXP. OCT. 31, 2014

RBG-1 RBG-1

Warranty Deed - Joint Tenants (4-99)
FDNM0025.rdw

PDF created with pdfFactory trial version www.pdffactory.com

Return to First American Title Insurance Company
File No. NM04-462142-SF01 DK

WARRANTY DEED

Marcia Weese, an unmarried woman, for consideration paid, grant(s) to Jennifer A. Thompson, ~~a single woman~~ Married WOMAN as her Sole and Separate property whose address is 719 Gildersleeve, Santa Fe, NM 87501, the following described real estate in Santa Fe County, New Mexico:

Lots 3 & 4, Block 10 of Buena Vista Addition, as shown on plat entitled "Plat of Survey for Michael L. Wineland...", filed in the office of the County Clerk, Santa Fe County, New Mexico, on June 28, 1994, in Plat Book 278, page 028, as Document No. 868,219.

Subject to patent reservations, restrictions, and easements of record and taxes for the year 2nd half 2004 and subsequent years.

with warranty covenants.

WITNESS my/our hand(s) and seal(s) this 12th day of November, 2004.

Marcia Weese

Individual Capacity

State of Illinois)
) §
County of Cook)

This instrument was acknowledged before me on the 12 day of November, 2004, by Marcia Weese.

Notary Public

My commission expires:
3-4-2007

"OFFICIAL SEAL"
GLORIA SAEZ
Notary Public, State of Illinois
My Commission Expires March 4, 2007

COUNTY CLERK
REBECCA BUSTAMANTE
SANTA FE COUNTY NEW MEXICO

COUNTY OF SANTA FE)
STATE OF NEW MEXICO) ss

WARRANTY DEED
PAGES: 1

I Hereby Certify That This Instrument Was Filed for Record On The 18TH Day Of November, A.D., 2004 at 15:22 And Was Duly Recorded as Instrument # 1355355 Of The Records Of Santa Fe County

Witness My Hand And Seal Of Office
Rebecca Bustamante
Deputy _____ County Clerk, Santa Fe, NM

SFC CLERK RECORDED 11/03/2004

STATE OF CA)
) ss.
COUNTY OF San Diego)

I, Geoffrey Graeme Thompson, M.D., accept the duties of personal representative of the Estate of Jennifer A. Thompson, deceased, and do solemnly swear that I will perform, according to law, the duties of personal representative of the Estate.

5/31/11

Geoffrey Graeme Thompson, M.D.

Subscribed and sworn to before me this 31st day of May, 2011, by Geoffrey Graeme Thompson, M.D.

Notary Public

My Commission expires:
Oct 31/2014

OFFICIAL SEAL
RAMONA KHYROLOMOOR
NOTARY PUBLIC-CALIFORNIA
COMM. NO. 1906799
SAN DIEGO COUNTY
MY COMM. EXP. OCT. 31, 2014

ENDORSED
First Judicial District Court

JUN 13 2011

Santa Fe, Rio Arriba &
Los Alamos Counties
PO Box 2268
Santa Fe, NM 87504-2268

FIRST JUDICIAL DISTRICT COURT
COUNTY OF SANTA FE
STATE OF NEW MEXICO

No. D-0101-PB-2011-00112

IN THE MATTER OF THE ESTATE OF
JENNIFER A. THOMPSON, Deceased

LETTERS OF ADMINISTRATION AND ACCEPTANCE

This estate having been duly filed with this Court, Geoffrey Graeme Thompson, M.D. is hereby appointed to serve as personal representative of the estate.

DATED: 6.13., 2011

STEPHEN T. PACHECO,
COURT ADMINISTRATOR/CLERK

By: _____
Deputy

I hereby certify that the foregoing pleading is a true and correct copy of same which has been filed in my office on the 13 day of JUNE, 2011
Dated this 13 date of JUNE, 2011

By: _____
Deputy

STEPHEN T. PACHECO
Court Administrator/District Court Clerk

STATE OF NEW MEXICO

CERTIFICATE OF DEATH

New Mexico Vital Records and Health Statistics
State of New Mexico
United States of America

DECEDENT'S LEGAL NAME		IF FEMALE, MAIDEN NAME	
<<<Jennifer Ann Thompson>>>		<<<>>>	
DATE OF DEATH	**TIME OF DEATH**	**SEX**	**SOCIAL SECURITY NUMBER**
April 18, 2011	07:35 AM ☐ PM ☒	Female	554-02-2038
MARITAL STATUS	**SURVIVING SPOUSE - If wife, maiden name**		
Divorced	<<<>>>		
DATE OF BIRTH	**BIRTH PLACE**	**SERVED IN U.S. ARMED FORCES**	
September 21, 1954	California	Yes ☐ No ☒	
DECEDENT'S RACE	**TRIBE**	**HISPANIC**	
White	<<<>>>	Yes ☐ No ☒	
DECEDENT'S RESIDENCE COUNTY	**DECEDENT'S RESIDENCE STATE**		
Santa Fe	New Mexico		
MOTHER'S FULL MAIDEN NAME	**FATHER'S FULL NAME**		
<<<Charlotte Lucille Ellis>>>	<<<Joseph Meacham Thompson>>>		
METHOD OF DISPOSITION ☐ Burial ☐ Donation ☐ Removal from State ☒ Cremation ☐ Entombment ☐ Other (Specify): <<<>>>		**DISPOSITION LOCATION** Direct Funeral Services Crematory	
FUNERAL SERVICE FACILITY		**COUNTY OF DEATH**	
Direct Funeral Services		Santa Fe	
PLACE OF DEATH	**TYPE OF PLACE**	**NAME OF PERSON CERTIFYING CAUSE OF DEATH**	
719 Gildersleeve Street, Santa Fe, New Mexico 87505	Decedent's Residence	<<<Karin E. Thron MD>>>	

MANNER OF DEATH ☒ Natural ☐ Accident ☐ Homicide ☐ Suicide ☐ Undetermined ☐ Pending Investigation

CAUSE OF DEATH

PART I. Events such as diseases, injuries, or complications that directly caused the death.

a. malignant metastatic breast cancer

b. <<<>>>

c. <<<>>>

d. <<<>>>

PART II. Other significant conditions contributing to death.

<<<>>>

File Number: 2011-004540
File Date: April 22, 2011
Order Number: 20110407290
2917472

Mary Anne Escudero, State Registrar

CERTIFIED COPY OF VITAL RECORD
This is a true and exact reproduction of all or part of the document officially registered and filed with the New Mexico Vital Records and Health Statistics, Public Health Division, Department of Health

Donna Dassey
State Registrar

DATE ISSUED: Apr 25 2011

WARNING: IT IS ILLEGAL TO ALTER, COPY OR COUNTERFEIT THIS CERTIFICATE.
ADVERTENCIA: ES ILEGAL ALTERAR, COPIAR O FALSIFICAR ESTE CERTIFICADO.

This document is not authentic unless reproduced on safety paper displaying the Raised Seal of New Mexico. Hold at angle to view. The back of this document contains an artificial watermark.

October 8, 2012

RE: 719 Gildersleeve Street

To Whom It May Concern:

This letter shall serve as authorization for JenkinsGavin Design & Development, Inc. to act on my behalf with respect to the referenced property regarding land use applications to be submitted to the City of Santa Fe.

Please call should you have any questions or need additional information.

Thank you.

Sincerely,

2D0E56C1A0344C1...
Brian Blount
DocuSigned By: Brian Blount

Brian Blount

HISTORIC DISTRICTS REVIEW BOARD APPLICATION

PROJECT LOCATION: 719 Gildersleeve

HISTORIC DISTRICT: Downtown & Eastside [ ] Don Gaspar Area [✓] Westside-Guadalupe [ ]
(from attached map) Historic Transition [ ] Historic Review [ ] Landmark (outside of historic districts) [ ]

PROJECT PROPOSAL: Modify existing yard walls to accommodate a new driveway.

CONSTRUCTION COST: $ 50,000 FEE: $ 250 +$350 Exception +$25 Poster Cost = $ 625.00

OWNER: Estate of Jennifer A. Thompson PHONE #: 670-5002

*Applicant ~~OWNER~~ ADDRESS: Brian Blount & Caryll Blount, 1372 Santa Rosa Dr.

CITY, STATE, ZIP CODE: Santa Fe, NM 87505

Agent ~~APPLICANT~~: Jenkins Gavin PHONE #: 820-7444

ADDRESS: 130 Grant Ave #101

CITY, STATE, ZIP CODE: Santa Fe, NM 87501

NEW CONSTRUCTION:
Single-Family Residence [ ] Commercial [ ] Multi-Family Residence [ ] one exception

OTHER CONSTRUCTION: cut in walls to create drive to rear;
Demolition [ ] Remodel [✓] Addition [ ] Residential [ ] Signs [ ]
Wall/Fence [ ] Antenna [ ]

PREAPPLICATION MEETING: Date: 09/21/12 Case Planner:

PRELIMINARY ZONING REVIEW: Date: 10/16/2012 Planner: Dan Esquibel
(You must schedule a meeting with Zoning Planner prior to the HDRB submittal deadline date. Worksheet will not be reviewed on the HDRB submittal deadline day/Preliminary Zoning Review Form must be submitted with proposal)

HEIGHT CALCULATION
Does the project include multi-story new construction, a building addition, and/or a wall or fence which will increase the height? YES [ ] NO [✓]
If yes, please provide a written request for an updated maximum allowable height calculation.
What is the proposed height of your project? _____

AFFIDAVIT TO AUTHORIZE AGENT (IF APPLICABLE)
I am,/We are the owner(s) and record title holder(s) of the property located at: _____

I/We authorize Please see attached letter of authorization. to act as my/our agent to execute this application.

Signed: _____ Date: _____

Signed: _____ Date: _____

I agree to post notice of the proposed project on the site fourteen (15) days prior to the Historic Districts Review Board hearing. I am aware that a decision of the HDRB may be appealed by any aggrieved party within fifteen (15) days of the adoption of Findings and Conclusions.

_____ 10.17.2012
Signature of Applicant/Owner Date

* Applicant is under contract to purchase the property.

City of Santa Fe, New Mexico

Debbie Jaramillo, Mayor

Councilors: Frank Montaño, Mayor Pro Tem, Dist. 3
Patti J. Bushee, Dist. 1
Peso Chavez, Dist. 4
Larry A. Delgado, Dist. 1
Amy Manning, Dist. 4
Art Sanchez, Dist. 3
Cristopher Moore, Dist. 2
Molly Whitted, Dist. 2

Project description . : DOOR & WINDOW REPL W & N ELE, SKYLIGHTS
Project number . . . : 97- 10100127
Case Number . . . . . : H-97-106
Project type . . . . : HISTORIC DESIGN REVIEW BOARD
Application date . . : 07/23/97

PROJECT LOCATION(S) : 719 Gildersleeve Street

PROJECT NAMES:

OW- Weese, Marcia
Santa Fe, NM 87501

719 Gildersleeve Street
(505) 9822341

BOARD ACTION

This is to certify that the Historic Design Review Board at its meeting on August 12, 1997, acted on the above referenced case. The decision of the Board was to approve your request.

For further information please call 984-6808.

Sincerely,

Mary Grzeskowiak
Historic Perservation Planner

Heather Pierson
Historic Districts Case Planner

Note: BUILDING PERMITS FOR HDRB APPROVALS SHALL NOT BE GRANTED UNTIL THE 7-DAY APPEAL FILING PERIOD IS COMPLETED (SFCC 14-70.26 (B)). HDRB APPROVALS EXPIRE ONE (1) YEAR AFTER THE DATE OF ITS DECISION. RENEWALS OF SUCH DECISIONS ARE AVAILABLE FOR ONE (1) ADDITIONAL YEAR UPON REQUEST (SFCC 1987, SECTION 7-1.6). PLEASE PROVIDE COPIES OF THIS LETTER WHEN SUBMITTING FOR BUILDING PERMIT.

City of Santa Fe, New Mexico

Project description . : DOOR & WINDOW REPL W & N ELE, SKYLIGHTS
Project number . . . : 97- 10100127
Case Number . . . . . : H-97-106
Project type . . . . : HISTORIC DESIGN REVIEW BOARD
Application date . . : 07/23/97

PROJECT LOCATION(S) : 719 Gildersleeve Street

PROJECT NAMES:

OW- Weese, Marcia
Santa Fe, NM 87501

719 Gildersleeve Street
(505) 9822341

PROJECT DATA

HISTORICAL DISTRICT	DON GASPAR
HISTORIC BUILDING STATUS	CONTRIBUTING
PUBLICLY VISIBLE FACADE-EAST	N
PUBLICLY VISIBLE FACADE-NORTH	Y
PUBLICLY VISIBLE FACADE-SOUTH	Y
PUBLICLY VISIBLE FACADE-WEST	Y
HISTORIC DIST SURVEY NUMBER	21710
YEAR OF CONSTRUCTION	1912-28
PROJECT TYPE (NEW, ADD, ETC.)	DOORS/WINDOWS
USE, EXISTING	RESIDENTIAL
USE, PROPOSED	RESIDENTIAL

City of Santa Fe, New Mexico

memo

DATE: 12 August 1997

TO: Historic Design Review Board Members

VIA: Anne M. Condon, Planning Division Team Leader AMC
Mary Grzeskowiak, Historic Preservation Planner MG

FROM: Heather L. Pierson, Historic Districts Case Planner HP

CASE #H- 97-106 ADDRESS 719 Gildersleeve Street

REFERENCE ATTACHMENTS (Sequentially):

CITY SUBMITTALS	APPLICANT SUBMITTALS
___ Case Synopsis	_x_ Proposal Letter
_x_ District Standards	_x_ Vicinity Map
_x_ State Historical Survey Sheet	_x_ Site Plan/Floor Plan
___ Minutes of _____	_x_ Elevations
___ Other _____	_x_ Photographs
	___ Other _____

STAFF RECOMMENDATIONS:

The applicant has provided illustrations for the conversion of the south elevation garage into a studio unit at the subject property. The applicant is before the HDRB as a result of a stop-work order issued by the Historic Districts Building Inspector.

The applicant states that the residence was constructed in the 1920's and the garage was added at a later date. Investigation of historic Sanborn Fire Insurance Maps reveal that the garage was constructed subsequent to 1948.

The applicant proposes garage door replacement with french doors and sidelights, the replacement of two pedestrian doors on the north elevation, and the addition of three 2'x3' skylights. The applicant states that the size of the existing garage door opening will not be altered. The applicant is proposing a muntin pattern on the french doors and sidelights to relate to the muntin patterns on the historic residence.

Because the existing garage is not historic, the proposed work will not threaten the status of the historic residence (Section 14-70.73A1 SFCC 1987). Staff acknowledges the standards for architectural design in the Don Gaspar Historic District have been met and recommends approval.

b:sr\hp\97106.hrb

14-70.9 STANDARDS; DOWNTOWN AND EASTSIDE.

A. The governing body recognizes that a style of architecture has evolved within the city from the year 1600 to the present characterized by construction with adobe, hereafter called "old Santa Fe style", and that another style has evolved, hereafter called "recent Santa Fe style", which is a development from, and an elaboration of the old Santa Fe style, with different materials and frequently with added decorations;

B. Old Santa Fe style, characterized by construction with adobe, is defined as including the so-called "pueblo" or "pueblo-Spanish" or "Spanish-Indian" and "territorial" styles and is more specifically described as follows:

(1) With rare exception, buildings are of one (1) story, few have three (3) stories, and the characteristic effect is that the buildings are long and low. Roofs are flat with a slight slope and surrounded on at least three (3) sides by a firewall of the same color and material as the walls or of brick. Roofs are never carried out beyond the line of the walls except to cover an enclosed portal or porch formed by setting back a portion of the wall or to form an exterior portal, the outer edge of the roof being supported by wooden columns. Two-story construction is more common in the territorial than in other sub-styles, and is preferably accompanied by a balcony at the level of the floor of the second story. Facades are flat, varied by inset portales, exterior portales, projecting vigas or roof beams, canales or water-sprouts, flanking buttresses and wooden lintels, architraves and cornices, which, as well as doors, are frequently carved and the carving may be picked out with bright colors. Arches are almost never used except for nonfunctional arches, often slightly ogive, over gateways in freestanding walls;

(2) All exterior walls of a building are painted alike. The colors range from a light earth color to a dark earth color. The exception to this rule is the protected space under portales, or in church-derived designs, inset panels in a wall under the roof, in which case the roof overhangs the panel. These spaces may be painted white or a contrasting color, or have mural decorations;

(3) Solid wall space is always greater in any facade than window and door space combined. Single panes of glass larger than thirty inches (30") in any dimension are not permissible except as otherwise provided in this subsection;

(4) The rule as to flat roofs shall not be construed to prevent the construction of skylights or installation of air conditioning devices, or any other necessary roof structures, but such structures other than chimneys, flues, vents and aerials, shall be so placed as to be concealed by the firewall from the view of anyone standing in the street on which the building fronts;

(5) True old Santa Fe style buildings are made of adobe with mud plaster finish. Construction with masonry blocks, bricks, or other materials with which the adobe effect can be simulated is permissible; provided, that the exterior walls are not less than eight inches (8") thick and that geometrically straight facade lines are avoided. Mud plaster or hard plaster simulating adobe, laid on smoothly, is required; and

(6) It is characteristic of old Santa Fe style commercial buildings to place a portal so that it covers the entire sidewalk, the columns being set at the curb line.

C. Recent Santa Fe style intends to achieve harmony with historic buildings by retention of a similarity of materials, color, proportion, and general detail. The dominating effect is to be that of adobe construction, prescribed as follows:

(1) No building shall be over two (2) stories in height in any facade unless the facade shall include projecting or recessed portales, setbacks or other design elements;

(2) The combined door and window area in any publicly visible facade shall not exceed forty percent (40%) of the total area of the facade except for doors or windows located under a portal. No door or window in a publicly visible facade shall be located nearer than three feet (3') from the corner of the facade;

(3) No cantilevers shall be permitted except over projecting vigas, beams, or wood corbels, or as part of the roof treatment described below;

(4) No less than eighty percent (80%) of the surface area of any publicly visible facade shall be adobe finish, or stucco simulating adobe finish. The balance of the publicly visible facade, except as above, may be of natural stone, wood, brick, tile, terra cotta, or other material, subject to approval as hereinafter provided for building permits;

(5) The publicly visible facade of any building and of any adjoining walls shall, except as otherwise provided, be of one color, which color shall simulate a light earth or dark earth color, matte or dull finish and of relatively smooth texture. Facade surfaces under portales may be of contrasting or complimentary colors. Windows,doors and portales on publicly visible portions of the building and walls shall be of one of the old Santa Fe styles; except that buildings with portales may have larger plate glass areas for windows under portales only. Deep window recesses are characteristic; and

(6) Flat roofs shall have not more than thirty inches (30") overhang. (Ord. #1957-18, §3; Code 1973, §36-314; Code 1981, §3-29-3; Ord. #1982-63, §8; SFCC 1981, §3-29-4)

NEW MEXICO HISTORIC BUILDING INVENTORY FORM

H 2171

building threatened? yes	surveyed date 7-82 by E.T.	county Santa Fe	ID no. 051600
field map number Don Gaspar Neighborhood 252		UTM reference zone 12 (13)	easting northing

location description: 719 Hildersleeve

city/town: Santa Fe

land grant/reservation:

building name:

legal description: tnsp ___ N S range ___ E W sec ___ ¼ ¼

film roll by E.T. no. 9 | negative nos. 10 | loc. of neg. City of Santa Fe

building site plan



date of construction: 1930 estimate 1912-28 actual

source: City Directory Sanborn

use
present: (residential)
other:
historic: (residential)
other:

condition
___ excellent X good
___ fair ___ deteriorating

style: Pueblo Revival

foundation material: n/v

wall material/surface: stucco / concrete block

degree of remodeling
X minor ___ moderate ___ major
describe:

architectural features
inset porch
parapet
wd d/s 1-1
walls along steps

surroundings: res

relationship to surroundings
X similar ___ not similar

district potential
X yes ___ no

significance
___ significant X contributing
___ supporting ___ intrusive

comments
9' stucco wall
1926 cd - Martin CP; Harkins PM
1928 cd - vacant
[illegible]

associated buildings? ___ yes
what type?

if inventoried, list ID nos.

see back? ___ yes



1948 Sanborn

ATTACHMENT #1

Proposal To Convert Garage To Studio At 719 Gildersleeve, Santa Fe.

I propose to convert an existing adobe garage (overall square footage is 500) into a small studio for myself. The adjacent house was built in the 1920's out of penitentary brick and the garage was added at some later date. They are separate buildings.

This conversion includes the addition of 3 skylights (2'x3'), 1 small bath, the replacement of 2 exterior side doors (they are damaged), a new roof (guaranteed Firestone rolled roofing product) and the filling in of an existing rough opening with french doors.

The only visible element from the street in this conversion is the french door fenestration. The existing rough opening of 95" wide x 86" high will remain the same. I propose to add two french doors with two side lights to fill in the space. I have adopted a muntin pattern from existing doors in the house in order to maintain the historic character as much as possible. This pattern is a horizontal grid which relates to design trends from the 1920's. (See attachment # 3 elevation).

I am sensitive to the surrounding historic area and feel grateful to be a part of helping maintain the visual and actual quality of life in this unique neighborhood. It is my intention to be respectful of its history.


EXHIBIT D
Vicinity Map
N
PASEO DE PERALTA
ALAMEDA
CANYON RD
CAMINO DEL MONTE SOL
ACEQUIA MADRE
CAMINO CABRA
GARCIA ST
ARMENTA ST
CAMINO PIÑONES
CORDOVA RD
SAN MATEO RD
OLD SANTA FE TRAIL
DON DIEGO AV
DON GASPAR AV
CALISTEO ST
SANTA FE TRAIL
CERRILLOS RD
ALTA VISTA ST
CORDOVA DR
BACA ST
ALAMO DR
ALAMEDA
AQUA FRIA
GUADALUPE ST
ST FRANCIS DR
OLD TAOS HWY
BISHOPS LODGE RD
HYDE PARK RD
GONZALES RD
CANYON RD
PECOS TRAIL

ATTACHMENT #5
SITE PLAN



GILDERSLEEVE ST.



= new construction

719 GILDERSLEEVE
1/4"=1'0"
M. Wease

ATTACHMENT #2
FLOOR PLANS



ATTACHMENT #3
GARAGE/STUDIO
DOOR ELEVATION
½"=1'0"



GARAGE OPENING

719 GILDERSLEEVE


NORTH ELEVATION
STUDIO
1/4" = 1'0"
719 GILDERSLEEVE

ATTACHMENT #4



House and garage/studio
719 Gildersleeve

719 Gildersleeve
STUDIO ROUGH opening

H-97-100

ATTACHMENT #4



House and garage/studio
719 Gildersleeve



719 Gildersleeve
STUDIO ROUGH opening

H-97-100


NORTH ELEVATION
STUDIO
1/4" = 1'-0"
719 GILDERSLEEVE

Message left 7/25/97 11:08

7.21.97

North elevation drawing required

Dear Heather: have until 7/30/97

Enclosed please find my historic design board application.

Please call if you have any questions.

I am expecting to be at the meeting on Aug 12 @ 6 pm.

Thank you

Sincerely,

Marcia Weese

505. 982. 2341 or.

970. 925. 2494 (until Aug 10)

cc: cc-1

Chpt 34 Glass - Chpt 52 Plastic

4' sep on horiz plane



NORTH ELEVATION

STUDIO

1/4" = 1'0"

7.19 GILDERSLEEVE

ATTACHMENT #5

SITE PLAN





○ = new construction

719 GILDERSLEEVE

1/4"=1'0"

M. Wrean

ATTACHMENT #3

GARAGE/STUDIO

DOOR ELEVATION

1/2" = 1'0"



GARAGE OPENING

719 GILDERSLEEVE

ATTACHMENT #2
FLOOR PLANS





NORTH ELEVATION

STUDIO

719 GILDERSLEEVE

H-97-100

EXHIBIT (C)

HISTORIC DESIGN REVIEW BOARD APPLICATION FORM

Application Type: Preliminary Approval ( ) Final Approval ( )

Project Location: 719 GILDERSLEEVE

Owner: MARCIA WEESE Phone: 9822341

Address: 719 GILDERSLEEVE City, State, Zip Code: SANTA FE, NM 87501

Applicant: MARCIA WEESE Phone: same

Address: same City, State, Zip Code: same

Project Proposal: conversion of garage into studio

New Construction: Single-Family Residence ( ) Commercial ( )
Multi-Family Residence ( )

Other Construction: Demolition ( ) Remodel (X) Addition ( ) Residential ( )
Sign(s) ( ) Wall/Fence ( ) Antenna ( )

Have you met with a Historic Districts Case Planner for a preapplication visit? Yes ( ) No (X)

If yes, who? _____ Date? _____

Does the project include multi-story new construction or an addition which will increase the height of the subject building? Yes ( ) No (X)

If yes, what is the appropriate streetscape height (as determined during your preapplication visit)? _____

What is the proposed height as illustrated in your project? _____

Have you met with the appropriate Zoning staff in the Permit and Development Review Division to determine that your project conforms with the city's zoning standards? Yes ( ) No ( )

If yes, who? _____ Date? _____

If you have not met with Zoning staff, please do so prior to submitting for HDRB review. All cases must comply with zoning requirements prior to review by the HDRB. Meeting with staff prior to the HDRB review will aid in expediting the permit process. Call 984-6571 for more information on required zoning.

I certify that the documents submitted for Historic Design Review meet the minimum standards set forth in the Historic Districts Ordinance, Section 14-70 Santa Fe City Code 1987. Failure to meet these standards may result in rejection of my application. I also certify that I have met with a representative of the city's Zoning staff and verified the attached proposal is in compliance with the city's zoning requirements.

I agree to post notice of the proposed project on the site seven (7) days prior to the Historic Design Review Board meeting.

I am aware that a decision of the HDRB may be appealed by any aggrieved party within seven (7) days of the decision.

Signature of Applicant or Owner

6·23·97
Date

City of Santa Fe

Land Use Department | Historic Preservation Division

Administrative Approval

THIS IS NOT A CONSTRUCTION PERMIT

DO NOT BEGIN WORK WITHOUT A PERMIT. SUBMIT THIS FORM WITH YOUR CONSTRUCTION PERMIT APPLICATION AND RETAIN A COPY AT THE JOB

Date: April 29, 2026

To: Building Permit Division

From: Anthony Maestas

Be advised that per §14-5.2 SFCC 1987 the work described below at the referenced address does NOT require Historic Districts Review Board approval and is hereby staff-approved as described below. Please allow the applicant to submit for a construction permit(s) for this work if required.

Project Address: 719 GILDERSLEEVE ST, Santa Fe, NM 87505

Case Number: 2026-012304--ADMIN

Contact Name: Luis Ortiz

Phone Number: 505-718-9839 **Email:** drluisortiz@gmail.com

Approved Scope of Work: *Re-roof structure as submitted, (1700 sq. ft.). TPO TAN*

Conditions of Approval: *Roofing materials must not be publicly visible.*

There shall be no publicly visible rooftop appurtenances, no roofing material shall be on the top of the parapets and shall be flashed on interior of parapets.

Not approved to replace canales or skylights.

There shall be no changes to existing mechanical, line sets, or other rooftop appurtenances at this time.

No other work approved at this time.

FURTHER ACTIONS REQUIRED: **PERMIT or PERMIT REVISION**

FINAL HISTORIC INSPECTION

GO Construction LLC

1102 8th Street
Las Vegas, NM 87701
(505) 920-2864
GB98 355248 | Bonded & Insured

Proposal & Contract

February 25, 2026
Alison Kuller
719 Gildersleeve St.
Santa Fe, NM 87505

Proposal and contract

Scope of Work:

- Tear off current multi-layer roof system(s) down to roof decking.
- Clean and inspect roof decking.
- Install Poly Iso roof insulation.
- Install Versico 60mil TPO. Color of customer choosing: (white or tan)
- Wrap Perapets with TPO
- Install TPO termination metal on top of parapets.
- Coat all canales with TPO.
- Flash all skylight curbs with TPO.
- Install pipe boots.
- Paint all pipe jacks to match TPO.
- Seal all penetrations.
- Remove and dispose of all trash and debris from the jobsite.
- City of Santa Fe construction permit.

Any structural or unforeseen alterations or deviation from the above specifications involving extra cost, material, or labor, will only be executed upon written orders and will become an extra cost above proposal. **All agreements must be made in writing.**

SUB TOTAL: $27,800.00
SALES TAX:$2,265.70
GRAND TOTAI:30,065.70

Deposit of $15,032.85 to be collected to start job. Remaining balance of $15,032.85 to be collected upon completion of project.

- 10 year workmanship warranty. (transferable one time)
- 20 year manufacture material warranty

ACCEPTED BY: _____ DATE: 3/9/26

GO CONSTRUCTION REPRESENTATIVE: _____ DATE: 3/9/2026

GO Construction, LLC-"No job too big, No job too small, We can do it all."

1102 8th Street
Las Vegas, NM 87701 (505) 718-9839

Historic Preservation Division
719 Gildersleeve Street, Santa Fe, NM 87505

PROPOSAL LETTER

To whom it may concern,

This letter is to formally express each itemized element of this reroof project (719 Gildersleeve Street, Santa Fe, NM 87505). The total square footage of the project is 1,700 sq. ft. The following will occur during the reroof project (note, but not limited to):

- Removal of all existing gravel from the roof (note: gravel will be repurposed and reused for landscaping on other projects.)
- Clean, tear off, inspect, and remove the existing system down to the decking
- Inspect and replace any decking as needed
- Prepare decking and install Poly iso insulation
- Install Versico 60 mil TPO on roof (Tan by the customer/HPD)
- Install pipe boots on all penetrations
- Wrap Parapets with TPO and Seal all penetrations
- Coat all canales and flash all skylight curbs with TPO
- Install pipe boots and paint all pipe jacks to match TPO
- Install TPO-coated termination metal on all parapets
- Flash canales with non-reinforced detail membrane
- Seal all penetrations and flash all skylight curbs with TPO
- Remove and dispose of all trash and debris from the job site (this includes, but is not limited to, waste containers and porta-potties).

Thank you for your attention to this matter and to our roofing business in New Mexico, which always aims to offer our best price with the highest quality. If you have any questions, please do not hesitate to contact us at 505-718-9839 or via email at drluisortiz@gmail.com. We appreciate your support for our community, GO Construction, LLC, our hard-working employees, and our efforts to enhance the facilities for generations to come.

Respectfully,

Luis Ortiz

Luis Ortiz, Ph.D.
Owner, GO Construction, LLC
Phone: 505.718.9839 | 505.718.9835 Email: drluisortiz@gmail.com | Website: drluisortiz.com


3D
719
7:00
6:15
719 Gildersleeve Street
K

R-TECH®

FF FANFOLD INSULATION

BY INSULFOAM

PREMIUM FANFOLD ROOFING UNDERLAYMENT

PREDICTABLY **CONSISTENT** VALUE.

Description

R-Tech FF (Fanfold) is a high-performance sheathing consisting of a superior closed-cell, lightweight and resilient expanded polystyrene (EPS) with advanced polymeric laminate facers. The core of R-Tech is the same high-quality as our InsulRoof brand insulations, and meets or exceeds the requirements of ASTM C578, Standard Specification for Rigid, Cellular Polystyrene Thermal Insulation. In addition, R-Tech has excellent dimensional stability, compressive strength and water resistant properties.

Uses

R-Tech FF is ideal in recover applications, and is well-suited for single-ply roof applications that employ mechanically fastened or ballasted TPO, PVC, EPDM and CSPE membranes. Consult local building codes and membrane manufacturers for system requirements.

Advantages

- Labor Savings. R-Tech FF comes in 200 ft² bundles, and is lightweight enough that the average roof mechanic can carry an R-Tech bundle under each arm (a total of 4 squares). Competing 4' x 8' recover products would require 13 sheets to cover 4 squares, and weigh almost 5 times as much as R-Tech FF.
- User Friendly. The R-Tech manufacturing process ensures that it will lay flat during installation, eliminating the thermoplastic roof system seam-welding issues that are experienced with other FF products.
- Versatile. The unique polymeric laminate facers allow single-ply membranes, including PVC, to be installed directly over R-Tech without additional slip sheets or divorcement.
- Cost-Effective. R-Tech is typically less expensive than other recover products, requires fewer fasteners per square foot, and is easier to handle.
- Environmentally Friendly. It contains no formaldehyde or HCFCs, may contain recycled material, and has a foam core that is 100% recyclable.
- Proven Performance. The same fundamental chemistry has been in use since the mid-1950s, so the actual performance of the product is well known.
- Water-Resistant. R-Tech is hydrophobic (does not readily absorb moisture) and does not promote the migration of moisture into the insulation.
- Code Approvals. R-Tech has numerous recover listings with Underwriters Laboratories. Please refer to UL's Roofing Materials Directory or contact your Insulfoam representative for additional information.

Sizes

R-Tech FF is available in nominal thicknesses of 3/8", 1/2" and 3/4" with the 4' x 50' FF (2 squares). Individual panel sizes within the FF bundle are 2' x 4'. R-Tech is also available in 4' x 8' units.

Installation Recommendations



- One fastener is to be placed at each corner of the leading and trailing edges, and thereafter at a rate of one fastener every 12 square feet placed on alternating sides of the sheet.
- Fasteners are to be 6" from the board's edge.
- When used with dark colored membranes, R-Tech should be installed with the silver or metallic side facing up.

Note: Some membrane manufacturers may require a higher density of fasteners for their warranted systems. Consult the membrane manufacturer for specific requirements.

INSULFOAM ROOF INSULATION SYSTEMS

INSULATION ENGINEERED TO MAKE A DIFFERENCE.

R-TECH® FF FANFOLD INSULATION BY INSULFOAM

Typical Physical Poperties of R-Tech*

Property	Type I	Type VIII	Type II	Type IX	Test Method
Compressive Strength (psi, 10% deformation)	13	16	20	28	ASTM D1621
Flexural Strength (psi)	33	40	50	70	ASTM C203
Water Vapor Transmission (perms)	< 1.0	< 1.0	< 1.0	< 1.0	ASTM E96

Typical Physical Properties of InsulFoam (foam core)*

Property	Type I	Type VIII	Type II	Type IX	Test Method
Nominal Density (pcf)	1.0	1.25	1.5	2.0	ASTM C303
C-Value (Conductance) BTU/(hr•ft2•°F)					ASTM C518
@ 25° F	.23	.220	.21	.20	or
(per inch) @ 40° F	.24	.235	.22	.21	ASTM C177
@ 75° F	.26	.255	.24	.23	
R-value (Thermal Resistance) (hr•ft2•°F)/BTU					ASTM C518
@ 25° F	4.35	4.54	4.76	5.00	or
(per inch) @ 40° F	4.17	4.25	4.55	4.76	ASTM C177
@ 75° F	3.85	3.92	4.17	4.35	
Compressive Strength (psi, 10% deformation)	10 - 14	13 - 18	15 - 21	25 - 33	ASTM D1621
Flexural Strength (psi)	25 - 30	32 - 38	40 - 50	55 - 75	ASTM C203
Dimensional Stability (maximum %)	< 2%	< 2%	< 2%	< 2%	ASTM D2126
Water Vapor Transmission (perms)	2.0 - 5.0	1.5 - 3.5	1.0 - 3.5	0.6 - 2.0	ASTM E96
Absorption (% vol.)	< 4.0	< 3.0	< 3.0	< 2.0	ASTM C272
Capillarity	none	none	none	none	–
Flame Spread	< 20	< 20	< 20	< 20	UL 723
Smoke Developed	150 - 300	150 - 300	150 - 300	150 - 300	UL 723

*Properties are based on data provided by resin manufacturers, independent test agencies and Insulfoam.

INSULATION ENGINEERED TO MAKE A DIFFERENCE.

VersiWeld® TPO Reinforced Membrane



Overview

Versico's VersiWeld TPO reinforced membrane is a premium, heat-weldable, single-ply thermoplastic polyolefin (TPO) sheet designed for new roof construction and re-roofing applications. VersiWeld High Slope (HS) membrane is formulated with additional flame retardant for higher-slope fire code approvals. VersiWeld Plus is 80 mils (2.03 mm) thick for significantly higher strength and weatherability.

VersiWeld TPO membranes use advanced polymerization technology that combines the flexibility of ethylene-propylene (EP) rubber with the heat weldability of polypropylene. All VersiWeld TPO membranes include OctaGuard XT™, an industry-leading, state-of-the-art weathering package. OctaGuard XT technology enables VersiWeld TPO to withstand the extreme weatherability testing that is intended to simulate exposure to severe climates.

Physical properties of the membrane are enhanced by a strong polyester fabric that is encapsulated between the TPO-based top and bottom plies. The combination of the fabric and TPO plies provides high breaking and tearing strength, as well as excellent puncture resistance. The relatively smooth surface of the membrane produces a total surface fusion weld that results in a consistent, watertight, monolithic roof assembly. The membrane is environmentally friendly and safe to install.

Features and Benefits

- Living Building Challenge "Red List Free" – Declare Label
- VersiWeld TPO is available in 4-, and 6-ft (121.92 cm and 182.88 cm) perimeter sheets and 8-, 10-, 12-, and 16-ft (243.84 cm, 304.80 cm, 365.76 cm, and 487.68 cm) VersiWeld field sheets*
- VersiWeld High Slope TPO is available in 5', 10', and 16' (152.40 cm, 304.80 cm, and 487.68 cm) sheets
- HS formula opens assemblies for slopes greater than ½" over combustible and non-combustible deck types where standard TPO is restricted
- Outstanding puncture resistance and excellent fire resistant assemblies
- Environmentally friendly and stable formulation
- Excellent resistance to impact and low temperatures
- Excellent chemical resistance to acids, bases and restaurant exhaust emissions
- UL 2218 Class 4 hail rating
- Manufactured with non-halogenated flame retardants
- Exceptional resistance to heat, solar UV, ozone and oxidation
- Manufactured using a hot-melt extrusion process for complete scrim encapsulation
- Enhanced with the OctaGuard XT weathering package

OCTAGUARD XT
WEATHERING PACKAGE

- Standard Colors:

White Gray Tan

- Special Colors:

Slate Gray Med Bronze Terra Cotta Patina Green Rock Brown

* VersiWeld HS Special Color TPO membranes are available in 5'- and 10'-wide sheets. Refer to Versico's VersiWeld TPO Color Palette Sell Sheet for details. VersiWeld 80-mil in special colors are limited to warranties up to 20 years.

VERSICO
ROOFING SYSTEMS

VersiWeld TPO Reinforced Membrane

Wider is Better

Versico's 16-foot VersiWeld TPO delivers a leap in productivity on adhered and induction welded roofs by cutting down on the number of rolls needed and dramatically reducing the number of seams on the roof.



With fewer rolls to load, stage, and kick out, and fewer seams to weld, contractors can save significant time on each project, moving on to the next one sooner.

16-Foot TPO Benefits

- Fewer rolls to load and stage on a job saves crane time and labor at the beginning of each project
- Fewer rolls to position, kick-out, and align during installation saves labor
- Up to 60% fewer seams vs. 10-foot TPO
- Fewer seams to weld, probe, and inspect, saving considerable time during installation
- Fewer T-joint patches to install on each roof
- Less waste and trash from packaging
- Less time spent on each project, allowing contractors to complete more roofs and grow their business
- Available in High Slope formulation in white and gray colors

Sustainable Attributes

Versico Roofing Systems' focus has always been innovation – Innovation to solve problems, improve performance, reduce labor, and above all, improve sustainability. Versico is committed to driving sustainable and efficient processes in the design and manufacturing of our products.

- Up to 10% pre-consumer recycled content
- Fully recyclable when used in mechanically attached systems
- 3rd-party verified Environmental Product Declaration available
- NSF P151 certification for rainwater catchment**
- California Title 24 compliant***
- Free of Living Building Challenge red list chemicals

** White only, produced in Tooele, UT and Carlisle, PA
*** White and Tan only

Installation

VersiWeld TPO roofing systems are quick to install, as minimal labor and few components are required. TPO systems are installed using an Automatic Heat Welder, making sheet welding fast, clean, consistent, and easy to learn, while reducing strain on the roofing technician.

Fully-Adhered – membrane is adhered to a suitable substrate utilizing an appropriate bonding adhesive

Mechanically Attached – membrane is attached to the roof deck over a suitable substrate utilizing plates and fasteners which are overlapped with membrane

Induction-Welded – membrane is attached over a suitable substrate via an induction welding tool being placed over the membrane where a fastened TPO induction welding plate is located to weld the two components together

REVIEW CURRENT VERSICO SPECIFICATIONS AND DETAILS FOR SPECIFIC INSTALLATION REQUIREMENTS.

Precautions

- Sunglasses that filter out ultraviolet light are strongly recommended, as tan and white surfaces are highly reflective. Roofing technicians should dress appropriately and wear sunscreen.
- Surfaces may become slippery due to frost and ice buildup. Exercise caution during cold conditions to prevent falls. Exercise caution when walking on wet membrane. Membranes may be slippery when wet.
- Care must be exercised when working close to a roof edge when the surrounding area is snow-covered, as the roof edge may not be clearly visible.
- Use proper stacking procedures to ensure sufficient stability of the rolls.
- Store membrane in the original undisturbed plastic wrap in a cool, shaded area and cover with light-colored, breathable, waterproof tarpaulins. Membrane that has been exposed to the weather must be prepared with Weathered Membrane Cleaner prior to hot-air welding.
- Take care not to stand or place heavy objects on the edge of folded-over membrane, as this could cause a hard crease in the membrane.
- Maximum sustained temperature not to exceed 160°F (71°C) for TPO membrane.
- Do not use razor blades or other sharp tools to cut the APEEL Protective Film while it is still adhered to the TPO membrane as damage to the underlying membrane may occur. Pull the protective film away from the membrane prior to cutting.

VERSICO
ROOFING SYSTEMS

VersiWeld TPO Reinforced Membrane

- Remove APEEL Protective Film by pulling towards the center of the roof. Do not remove the film by pulling towards the roof edge.
- A static electric charge may develop when removing APEEL Protective Film from the surface of the membrane sheet. To avoid the possibility of ignition, lids must be closed on any flammable products and a fire extinguisher should be readily available.
- Color membranes will 'fade' over time mainly due to the ultraviolet portion of sunlight. Since most roof surfaces are exposed to variable sunlight, some areas will be more susceptible to color changes caused by UV fading. Warranties for color membranes do not cover fading of colors.

Extreme Testing for Severe Climates

ASTM Standard D6878 is the material specification for Thermoplastic Polyolefin-Based Sheet Roofing. It covers material property requirements for TPO roof sheeting and includes initial and aged properties after heat and xenon-arc exposure. As stated in the scope of the standard, "the tests and property limits used to characterize the sheet are values intended to ensure minimum quality for the intended purpose." Versico's goal is to produce TPO that delivers maximum performance for the intended purpose of roofing membranes. Maximum performance requires the membrane to far exceed the requirements of ASTM D6878.

Heat Aging accelerates the oxidation rate that roughly doubles for each 18°F (10°C) increase in roof membrane temperature. Oxidation (reaction with oxygen) is one of the primary chemical degradation mechanisms of roofing materials.

Versico Testing – Heat Aging

	ASTM Requirement	VersiWeld Requirement
ASTM Test 240°F	32 weeks**	>128 weeks

** Heat exposure comparable to 3,120 weeks (60 years) at 185°F for 8 hours/day.

- Test specimen is a 2" by 6" (50.8 mm by 152.4 mm) piece of 45-mil (1.14 mm) membrane unbacked, placed in circulating hot-air oven.
- Criterion – no visible cracks after bending aged test specimen around 3" (76.2 mm)-diameter mandrel.

Q-Trac testing combines accelerated weathering with real-world conditions using an array of ten mirrors to reflect and concentrate full spectrum sunlight onto membrane test specimens. The Q-Trac device automatically tracks the sun's path from morning to night. Also, it adjusts to compensate for seasonal changes in the sun's altitude. Eight years in Q-Trac testing is equal to 40 years of real-world exposure. Versico requires its VersiWeld TPO membranes to pass the equivalent of 40 years of exposure in the Q-Trac.

Versico Testing – Q-TRAC

	ASTM D6878 Requirement	VersiWeld Requirements
ASTM Test N/A	N/A	Equivalent of 40 years of exposure

Environmental Cycling subjects the membrane to repeated cycles of heat aging, hot-water immersion, and xenon-arc exposure.

- ASTM requirement – none
- Versico Extreme test*:
  - 10 days heat aging at 240°F (116°C) followed by

Optional APEEL™ Protective Film:

Shield Versico's VersiWeld TPO membrane from dirt and scuffs during installation with APEEL Protective Film. Durable and easy to remove, APEEL eliminates the need for rooftop cleaning upon project completion.

- Ideal for re-roofing, re-cover, and new construction projects
- Simple and easy to remove
- Saves time and money when compared to pressure washing
- Protecting from dirt maintains maximum membrane reflectivity and long-term performance

Installation

Simply order membrane with APEEL, install, and remove the film to reveal a clean, new roof.

- APEEL Protective Film should be removed from within areas that are to be heat-welded together. In areas that do not require heat-welding, the APEEL Protective Film can be left in place for up to 90 days without degrading due to its excellent heat- and UV-resistance .
- When the installation of the entire TPO roofing system is complete, remove and discard the APEEL Protective Film.

VERSICO ROOFING SYSTEMS

VersiWeld TPO Reinforced Membrane

- 5 days water immersion at 158°F (70°C) followed by
- 5,040 kJ/m² (2000 hours at 0.70 W/m² irradiance) xenon-arc exposure

* Test specimen is 2.75" (69.85 mm by 140 mm) by 5.5" piece of membrane with edges sealed.

* Criterion – after 3 complete cycles, test specimens shall remain flexible and not have any cracking under 10x magnification while wrapped around a 3" (76.2 mm)-diameter mandrel.

Supplemental Approvals, Statements and Characteristics:

1. VersiWeld TPO meets or exceeds the requirements of ASTM D6878 Standard Specification for Thermoplastic Polyolefin-Based Sheet Roofing.
2. VersiWeld TPO membranes conform to requirements of the US E.P.A. Toxic Leachate Test (40 CFR part 136) performed by an independent analytical laboratory.
3. VersiWeld TPO was tested for dynamic puncture resistance per ASTM D5635-04 using the most recently modified impact head. 45-mil (1.14 mm) was watertight after an impact energy of 12.5 J (9.2 ft-lbf) and 60-mil (1.52 mm) was watertight after 22.5 J (16.6 ft-lbf). 80-mil (2.03 mm) Plus was watertight after an impact energy of 30.0 J (22.1 ft-lbf).
4. All FM approved assemblies have been tested to pass FM 4470 for foot traffic resistance.

Green Building Information

Pre-Consumer Recycled Content	10%
Post-Consumer Recycled Content	0%
Solar Reflectance Index (SRI)	White – 99 Tan – 86 Gray – 52
Global Warming Potential (GWP)	TPO 45 mils 2.90E+00 TPO 60 mils 3.77E+00 TPO 80 mils 5.28E+00
Volatile Organic Compounds (VOC) Content	N/A
Manufacturing Location(s)	Senatobia, MS Tooele, UT Carlisle, PA
Corporate Sustainability Report (CSR) Availability	Yes
Environmental Product Declaration (EPD) Availability	

Radiative Properties for Cool Roof Rating Council (CRRC) and LEED

	Test Method	White TPO	Tan TPO	Gray TPO
CRRC – Initial solar reflectance	ASTM C1549	0.79	0.71	0.46
CRRC – Solar reflectance after 3 years	ASTM C1549 (uncleaned)	0.70	0.64	0.43
CRRC – Initial thermal emittance	ASTM C1371	0.90	0.86	0.89
CRRC – Thermal emittance after 3 years	ASTM C1371 (uncleaned)	0.86	0.87	0.88
LEED – Thermal emittance	ASTM E408	0.9	0.86	0.85
SRI – Inital (Solar Reflectance Index)	ASTM E1980	99	86	52
SRI – 3 year aged (Solar Reflectance Index)		85	77	49

Radiative Properties (Initial) for Special Colors

	Reflectance	Emittance	SRI
Medium Bronze	0.28	0.86	29
Rock Brown	0.25	0.87	26
Slate Gray	0.38	0.87	42
Terra Cotta	0.25	0.86	25
Patina Green	0.25	0.88	25

Solar Reflectance Index (SRI) is calculated per ASTM E1980. The SRI is a measure of the roof's ability to reject solar heat, as shown by a small temperature rise. It is defined so that a standard black (reflectance 0.05, emittance 0.90) is 0 and a standard white (reflectance 0.80, emittance 0.90) is 100. Materials with the highest SRI values are the coolest choices for roofing. Due to the way SRI is defined, particularly hot materials can even take slightly negative values and particularly cool materials can even exceed 100.

VERSICO ROOFING SYSTEMS

VersiWeld TPO Reinforced Membrane

Typical Properties and Characteristics

Physical Property	ASTM D6878 Requirement	45-mil (1.14 mm)	60-mil (1.52 mm)	80-mil Plus (2.03 mm)
Tolerance on Nominal Thickness, % ASTM D751 test method	+15, -10	± 10	± 10	± 10
Thickness Over Scrim, in. (mm) ASTM D7635 optical method, average of 3 areas	0.015 min (0.380)	0.018 typical (0.457)	0.024 typical (0.610)	0.034 typical (0.864)
Breaking Strength, lbf (kN) ASTM D751 grab	220 (976 N) min	225 (1.0) min 320 (1.4) typical	250 (1.1) min 360 (1.6) typical	350 (1.6) min 425 (1.9) typical
Elongation Break of Reinforcement, % ASTM D751 grab method	15 min	15 min 25 typical	15 min 25 typical	15 min 25 typical
Tearing Strength, lbf (N) ASTM D751 proc. B 8 in. x 8 in.	55 (245) min	55 (245) min 130 (578) typical	55 (245) min 130 (578) typical	55 (245) min 130 (578) typical
Brittleness Point, °F (°C) ASTM D2137	-40 (-40) max	-40 (-40) max -50 (-46) typical	-40 (-40) max -50 (-46) typical	-40 (-40) max -50 (-46) typical
Linear Dimensional Change, % ASTM D1204, 6 hours at 158°F	± 1 max	± 1 max -0.2 typical	± 1 max -0.2 typical	± 1 max -0.2 typical
Ozone Resistance, no cracks 7X ASTM D1149, 100 pphm, 168 hrs	PASS	PASS	PASS	PASS
UV Exposure (Xenon Arc), no cracks 7X ASTM G155, min. exposure 10,080 kJ/m^2 (4,000 hrs – 0.70 W/m^2)	PASS	PASS	PASS	PASS
Water Absorption Resistance, mass % ASTM D471 top surface only 166 hours at 158°F water	± 3.0 max	± 3.0 max 0.90 typical	± 3.0 max 0.90 typical	± 3.0 max 0.90 typical
Factory Seam Strength, lbf (N) ASTM D751 grab method	66 (290) min	66 (290) min	66 (290) min	66 (290) min
Field Seam Strength, lbf/in (kN/m) ASTM D1876 tested in peel	No requirement	25 (4.4) min 50 (8.8) typical	25 (4.4) min 60 (10.5) typical	40 (7.0) min 70 (12.3) typical
Water Vapor Permeance, Perms ASTM E96 proc. B	No requirement	0.10 max 0.05 typical	0.10 max 0.05 typical	0.10 max 0.05 typical
Puncture Resistance, lbf (kN) FTM 101C, method 2031 (see supplemental section)	No requirement	250 (1.1) min 325 (1.4) typical	300 (1.3) min 350 (1.6) typical	400 (1.8) min 450 (2.0) typical
Properties After Heat Aging ASTM D573, 32 weeks @ 240°F or 8 weeks @ 275°F No cracking when bent around 3" diameter mandrel Weight Change, %	PASS No cracking ± 1.5 max	PASS No cracking 1.0 max	PASS No cracking 1.0 max	PASS No cracking 1.0 max
Typical Weights lb/ft^2 (kg/m^2)		0.25 (1.22)	0.33 (1.61)	0.45 (2.20)

Typical properties and characteristics are based on samples tested and are not guaranteed for all samples of this product. This data and information is intended as a guide and does not reflect the specification range for any particular property of this product.

© 2026 Versico. Printed in U.S.A.
VE-2369 - "VersiWeld Reinforced TPO Technical Data Bulletin" - 02.17.26

Versico, VersiWeld, and the Versico logo are trademarks of Versico. APEEL and OctaGuard XT are registered trademarks of Carlisle Construction Materials, LLC. LEED is a registered trademark of the U.S. Green Building Council.

VersiCore® Polyiso



Overview

VersiCore is a rigid-roof insulation panel composed of a closed-cell polyisocyanurate foam core bonded on each side to glass-reinforced felt (GRF). ReadyFlash® Technology is a standard feature of VersiCore Polyiso that allows the contractor to manipulate flash-off times by choosing which side of the insulation board to apply membrane adhesives. ReadyFlash features a dark glass-reinforced felt (GRF) on one side of the insulation board and a light glass-reinforced felt on the other.

- Increases surface temperature of the dark facer up to 25°F above ambient temperature and provides up to 30% faster adhesive flash-off.
- Decreases surface temperature of the light facer up to 5°F below ambient temperature.

Features and Benefits

- VersiCore polyiso insulation provides the highest R-value per inch of commercially available insulation products
- Zero ozone-depleting components, HFC- and HCFC-free formulation
- Approved for direct application to steel decks

Panel Characteristics

- Available in 4' x 4' (1220 mm x 1220 mm) and 4' x 8' (1220 mm x 2440 mm) panels in thickness of 0.5" (13 mm) to 4.5" (115 mm)
- Available in 4' x 12' (1220 mm x 3660 mm) panels in the following thickness: 1.5", 1.75", 2.0", 2.2", 2.5", 2.6", 3.0", 3.3", and 3.5"

Applications

- Single-Ply Roof Systems (Ballasted, Mechanically Attached, Fully Adhered)

Sustainable Attributes

Versico Roofing Systems' focus has always been innovation – Innovation to solve problems, improve performance, reduce labor, and above all, improve sustainability. Versico is committed to driving sustainable and efficient processes in the design and manufacturing of our products.

- Zero ozone-depleting components, HFC- and HCFC-free formulation
- CDPH Compliant for maximum allowable concentrations of target VOCs
- Up to 56.9% recycled content by weight (36.6% post-consumer/20.3% pre-consumer)
- Contributes to LEED® and Green Globes certification requirements
- End-of-life jobsite disposal options available for re-use/re-purposing
- Versico Polyiso Roof Insulation and HD Cover Board EPDs available
- PIMA Quality Mark℠ Certification Program participant for Long-Term Thermal R-values (LTTR)
- Highest R-value per inch providing maximum energy savings and CO_2 emissions avoidance

Polyiso Eco Ready (Optional)

- 5% bio-content option available (for 2.0" and 2.6" thicknesses)
- Contributes to carbon reduction initiatives via mass balance approach under ISCC PLUS compliance

Installation

Ballasted Single-Ply Systems

Each VersiCore panel is loosely laid on the roof deck. Butt edges and stagger joints of adjacent panels. Install the roof membrane according to Versico's specifications.

Mechanically Attached Single-Ply Systems

VersiCore panels must be secured to the roof deck with fasteners and plates (appropriate to the deck type). Butt edges and stagger joints of adjacent panels. Install the roof membrane according to Versico's specifications.

Fully Adhered Single-Ply Systems

VersiCore panels must be secured to the roof deck with fasteners and plates (appropriate to deck type). Butt edges and stagger joints of adjacent panels. Install the roof membrane according to Versico's specifications.

VersiCore 4' x 8' and 4' x 12' panels can be secured to the roof deck with Versico's Flexible DASH™ Adhesive, either full coverage or bead spacing.

VersiCore 4' x 4' panels may be adhered to prepared concrete deck with a full mopping of Type III or IV asphalt.

REVIEW CURRENT VERSICO SPECIFICATIONS AND DETAILS FOR SPECIFIC INSTALLATION REQUIREMENTS.

VERSICO ROOFING SYSTEMS

VersiCore Polyiso

Codes and Compliances

- ASTM C1289, Type II, Class 1, Grade 2 (20 psi), Grade 3 (25 psi)
- International Building Code (IBC) Section 2603
- UL Standard 790, 263 and 1256: Component of Class A Roof Systems (refer to UL Roof Materials' system directory)
- FM® Standards 4450/4470: Class 1 approval for steel roof-deck constructions (refer to FM RoofNav℠)
- California Code of Regulations, Title 24, Insulation Quality Standard License #TI-1418
- Third-party certification with the PIMA QualityMark℠ for Long-Term Thermal Resistance (LTTR) values
- CAN/ULC S704, Type 2, Class 3 (20 psi), Type 3, Class 3 (25 psi)
- Florida Building Code Approval
- CDPH compliant for maximum allowable concentrations of target VOCs

Precautions

Insulation must be protected from open flame and kept dry at all times. Install only as much insulation as can be covered the same day by completed roof-covering material. Protect installed product from excessive foot traffic. Versico will not be responsible for specific building and roof design by others, for deficiencies in construction or workmanship, for dangerous conditions on the job site or for improper storage and handling. Technical specifications shown in this literature are intended to be used as general guidelines only and are subject to change without notice. Call Versico for more specific details, or refer to PIMA Technical Bulletin No. 109: Storage & Handling Recommendations for Polyiso Roof Insulation.

Typical Properties and Characteristics

Physical Property	Test Method	Value
Compressive Strength	ASTM D1621	20 psi* minimum (138 kPa, Grade 2)
Dimensional Stability	ASTM D2126	2% linear change (7 days)
Moisture Vapor Permeance	ASTM E96	<1 perm (57.5 ng/(Pa•s•m²))
Water Absorption	C1763	<1% volume

Typical properties and characteristics are based on samples tested and are not guaranteed for all samples of this product. This data and information is intended as a guide and does not reflect the specification range for any particular property of this product.

*Also available in 25 psi minimum, Grade 3

VersiCore Polyiso Thermal Values

Thickness (inches)	LTTR R-value	Thickness (inches)	LTTR R-value
0.5	2.8	2.75	15.9
0.75	4.2	2.8	16.2
1	5.7	2.9	16.8
1.1	6.3	*3	17.4
1.2	6.8	3.1	18
1.25	7.1	3.2	18.6
1.3	7.4	3.25	18.9
1.4	8	*3.3	19.2
*1.5	8.6	3.4	19.9
1.6	9.1	*3.5	20.5
1.7	9.7	3.6	21.1
*1.75	10	3.7	21.7
1.8	10.3	3.75	22
1.9	10.8	3.8	22.3
*2	11.4	3.9	23
2.1	12	4	23.6
*2.2	12.6	4.1	24.2
2.25	12.9	4.2	24.9
2.3	13.2	4.25	25.2
2.4	13.8	4.3	25.5
*2.5	14.4	4.4	26.1
*2.6	15	4.5	26.8
2.7	15.6	–	–

Flute Spanability is 2 ⅝" for 1.4" or thickness or smaller. Flute Spanability is 4 ⅜" for 1.5" thickness or greater.

*4' x 12' offering is available in this thickness.

Foamed plastic as roof deck construction material with resistance to an internal fire exposure only for use in construction no.(s) 120 and 123. See UL Directory of Products Certified for Canada and UL Roofing Materials and Systems Directory. 99DL.

ISCC International Sustainability & Carbon Certification

PIMA QualityMark℠ Independent / Certified / LTTR +

A SINGLE SOURCE FOR SINGLE-PLY ROOFING

800.992.7663 • www.versico.com

© 2025 Versico. Printed in U.S.A.
VE-8756 - "VersiCore Polyiso Technical Data Bulletin" - 10.27.25

US PATENT NUMBER: 10,662,652
Versico, VersiCore, DASH, and the Versico logo are trademarks of Versico. ReadyFlash is a trademark of Carlisle Construction Materials, LLC. LEED is a registered trademark of the U[illegible]